

JARDINE

INS. CASE OWNER:

Peter

CC 4/AXA1900

1071, A16639

LKK

IDAC:

Surveyor:

Admin

DOI:

ASSIGNMENT

W/1/19

Date / Time:

12/1/19

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

SLU 54306

Name of Insured:

NEW MYNK VWV

Insured Tel No.:

HP:

Excess Sec II :SS

D.O.A.:

15/1/19

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

GOM 56W YOW

Driver Tel No.:

(V/L: YES / NO)

Claim No.:

8901422/92958

Policy No.:

Make / Model:

MERLEDES

Place of Accident:

WATERLOO ST TRNG KHAMMM
THUNG

OI GIA REPORT: YES / NO : TP GIA REPORT: YES / NO

Insured Liability:

Final ? Yes / No



INSRS:

WSP:

Tel:

Liability:

RMKS:

Chew motor



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/ Time

1/1/19

WZ

SFJ 71673

SLU 54306-7

STAGE

DATE / PIC

Non-Reporting Itr (1st):

Non-Reporting Itr (2nd):

Non-Reporting Itr (Final):

Notification Itr (if non-pickup):

Call OI:

After call Itr to OI:

Documentation Check List: Handler Typist

Notification Itr (if non-pickup)

After call Itr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA :

Medical Bill:

PDR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

24/01/19

AXA NOTIFIED TO RESORT TO CLAIM
BASED ON POLY 26.- GUMU TO TP TO RESORT CLAIM
- OPERATED IA.
- TO CLOSE.

Reject Cases

V/L

WZ

PRELIMINARY ADVICE Date/Time:

Sent By:

012-17

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

L19

SS 1,100.00

(2 days) Reduction:

63 %

Email

Call

FINAL SETTLEMENT

Date/Time:

Confirm with:

Email

Call

Final Liability:

SS

0

(Agreed / Assessed) BOLA S/N No.:

26

If NO or B 28, Ass. Lia:

(TP OPEN BOOK)

Repair Cost:

SS

—

Loss of Rental (LOR):

SS

—

(days)

Loss of Use (LOU):

SS

—

(5 x days)

Loss of Income (LOI):

SS

—

(5 x days)

LOR only

LOU only

SS

—

LOR + LOU

LOR + LO

(Tick only one)

GIA/LTA Search

SS

—

Medical:

SS

—

Disbursement:

SS

—

(e.g. Tow/ Independent)

Legal Cost

SS

—

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:

4350.00

Total:

SS

—

Global Sum SS:

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

SS

—

Name 1:

—

Payee 2: (Strike if N.A.)

SS

—

Name 2:

—

Payee 3: (Strike if N.A.)

SS

—

Name 3:

—

COPY SENT
11/1/19NO SETTLEMENT
RESORT TO CLAIM

Adrian

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No: _____

Claims No: _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 2 days Res.: Yes or NoLum Sum: 20 % J Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Vehicle: IN / OUT

Person Contacted: _____

Veh No: SKJ7167Z Yr Regn: 2009, NovType: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toyota Allion cc 1496Colour: White A/C: Insured / Std / NI / NASp. Reading 192008 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: NZT2603036343Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 185/70R14R: 185/70R14

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Habibeed

Front

Rear

R/Bal. 06 mm R/Bal. 06 mmL/Bal. 06 mm L/Bal. 06 mmD.O.A. _____ D.O.I. 22/01/19Survey held at Chew MotorDes. of Damages: Frt / Rear / O/S / NIS / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

TPAXAL/G \$1,100.00CRIP: \$1,881.30 (63%)MV: 17KPV: 10.7KNett: 6.3K

Date/Time, File Pass to?

Date/Time, File Return to?

1)

2)

3)

4)

5)

6)

Prel. Report:

Final Report:

Part Prices Check:

IN

OUT

Survey Fee:

Date:

Basic & Add.

S + RS, SI

Photos

Others

TOTAL



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AXA INSURANCE PTE LTD

Ref : CC4/ASM19001071/Ahb3

8 SHENTON WAY #24-01
AXA TOWERS SINGAPORE 068811

Date : 17-01-2019



Code : ASM

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SLU 5430G	Veh. Inspected	SKJ 7167Z
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	17/01/2019

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	15/01/2019	Inspection Date
Survey held at	CHEW MOTOR PTE LTD BLK 1 KAKI BUKIT AVE 6 #01-41 AUTOBAY @ KAKI BUKIT SINGAPORE 417883	

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

[> Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Company
Owner ID: 4540N

Vehicle Details

Vehicle No.: SKJ7167Z
Vehicle to be Exported: No
Intended Deregistration Date: 16 Jan 2019
Vehicle Make: TOYOTA
Vehicle Model: ALLION 1.5 A
Primary Colour: White
Manufacturing Year: 2009
Engine No.: 1NZZ268652
Chassis No.: NZT2603036343
Maximum Power Output: 81.0 kW (108 bhp)
Open Market Value: \$18,607.00
Original Registration Date: 12 Nov 2009
First Registration Date: 12 Nov 2009
Transfer Count: 3
Actual ARF Paid: \$18,607.00

Intended PARF Rebate Details

PARF Eligibility: Yes
PARF Eligibility Expiry Date: 11 Nov 2019
PARF Rebate Amount: \$9,303.00

Intended COE Rebate Details

COE Expiry Date: 11 Nov 2019
COE Category: A - Car (1600cc & below)
COE Period(Years): 10
QP Paid: \$16,747.00
COE Rebate Amount: \$1,374.00
Total Rebate Amount: \$10,677.00

The information contained herein is correct as at 16 Jan 2019

OK

AXA-Adrian LKK



CHEW MOTOR PTE. LTD.

1 Kaki Bukit Avenue 6, Blk A #01-11 Autobay@Kaki Bukit Singapore 417883

Tel: 6509 5545

Fax: 6509 5567

Website: www.chewmotor.com

Registration No.: 201718369R

22/01/2019

Blk 1 Kaki Bukit Ave 6
01-43
Singapore 417883

TP AXA.
Vic.

NZT2603036343

Accident date: 15/01/2019

Estimated repair cost for vehicle no: SKJ7167Z TOYOTA ALLION 1.5 A '09

S/n	Qty	Items	U/price	Amount
1	1	Rear R/H Door <i>Derred</i>		\$1,183.40 ✓
2	2	Rear R/H Door Frame Sticker <i>new</i>	\$132.25	\$264.50 60(SN)
3	1	Rear R/H Door Inner Lock Assy <i>3M</i>		\$387.00 ✓
4	1	Rear R/H Door Inner Rubber <i>1 new</i>		\$166.40 ✓

1183.40

Subtotal :-

\$2,001.30

887.55

SN: 60

Labour charges

To remove & refit rear R/H door, glass, lock, rubber, gear motor, frame sticker & trim board

~~\$180.00~~ 20.

To check wiring

\$50.00 ✓

Panel beating

780

~~\$350.00~~ 20

Spray painting

~~\$400.00~~ 20

Subtotal :-

\$980.00

Total:-

\$2,981.30

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Total 1427.55

4/5: 11K. ✓
020 days.



Pls reject claim based on Bola

Type

🔗 Question

Message

Pls also get OI LOA

Reply

Vic (LKKAUTO)

From: Vic (LKKAUTO)
Sent: Friday, 1 February, 2019 4:16 PM
To: Chew Motor Pte. Ltd.
Cc: Admin A; Vic (LKKAUTO)
Subject: Your Ref: SKJ 7167Z_ACCIDENT INVOLVING VEHICLES SLU 5430G AND SKJ 7167Z ON 15/01/2019 LKK REF CC4/ASM19001071/Ahb3
Attachments: STATEMENT.pdf

Without Prejudice

Dear Sukyi,

We refer to the subject matter.

Please be informed that our principal had further reviewed the matter and based on the available information provided, our principal is in the view that our Insured is not liable of this accident.

Our Insured reported that he was driving along the driveway when your client's vehicle passenger door open and knocked onto his vehicle. Please see attached statement.

As such, we have our principal's instruction and we are unable to look into your client's claim unless proven otherwise.

Thank you.

Best Regards,

Vic Alpeh | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6841-2096 | email: vicalpeh@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Auto
Consultants
Pte Ltd

Save the Earth. Print only when necessary.

This e-mail contain confidential and privileged material, and are for the sole use of the intended recipient. Use or distribution by an unintended recipient is prohibited, and may be a violation of law. If you believe that you received this e-mail in error, please do not read this e-mail or any attached items. Please delete the e-mail and all attachments, including any copies thereof, and inform the sender that you have deleted the e-mail, all attachments and any copies thereof. Thank you.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No. 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD		Ref : CC4/ASM19001071/Ahb3q2		
8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811 ATTN:PETER		Date : 11-02-2019		
		Code : ASM		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SLU 5430G	Veh. Inspected	SKJ 7167Z	
Policy No.	GA316589/1	Coverage (\$)	0.00	
Claim No.	S9M01AQZ	Excess (\$)	0.00	
Assign From		Assign Date	17/01/2019	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA ALLION	c.c	1496	
Engine No.	HIDDEN	Year of Reg.	2009	
Chassis No.	NZT2603036343	Colour	WHITE	
Odometer	192008	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	185/70 R14	HABILEAD	6 mm	
L/H Front Tyre	185/70 R14	HABILEAD	6 mm	
R/H Rear Tyre	185/70 R14	HABILEAD	6 mm	
L/H Rear Tyre	185/70 R14	HABILEAD	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	15/01/2019	Inspection Date	22/01/2019	
Survey held at	CHEW MOTOR PTE LTD BLK 1 KAKI BUKIT AVE 6 #01-41 AUTOBAY @ KAKI BUKIT SINGAPORE 417883			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		2 Working Days		

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKJ 7167Z

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	REAR R/H DOOR (CONSISTENT)	DENTED	1,183.40	1,183.40
1	REAR R/H DOOR INNER LOCK ASSY(CONSISTENT)	NOT NECESSARY	387.00	-
1	REAR R/H DOOR INNER RUBBER(CONSISTENT)	NOT NECESSARY	166.40	-
	LESS 25% DISCOUNT		-	-295.85
			1,736.80	887.55
	<u>SPECIAL NETT ITEMS</u>			
2	REAR R/H DOOR FRAME STICKER @\$132.25 (SN) (CONSISTENT)	NECESSARY	264.50	60.00
			264.50	60.00
	<u>LABOUR</u>			
	TO REMOVE & REFIT REAR R/H DOOR, GLASS, LOCK, RUBBER, GEAR MOTOR, FRAME STICKER & TRIM BOARD.		180.00	80.00
	TO CHECK WIRING.	NOT NECESSARY	50.00	-
	PANEL BEATING.		350.00	200.00
	SPRAY PAINTING.		400.00	200.00
			980.00	480.00
	GRAND TOTAL		2,981.30	1,427.55
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			1,100.00

Report Ref No. CC4/ASM19001071/Ahb3q2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.

