

## 新盛机械工程服务

### SIN SHENG ENGINEERING SERVICES

REGISTRATION NO: 312029/00D

No 3, Tech Park Crescent, Tuas Tech Park, Singapore 638129 Tel: 6863 9595 Fax: 6863 6477 Email: sinsheng1981@gmail.com

5-Mar-19

LKK Auto Consultants Pte Ltd 51 Ubi Ave 1, #02-25 Paya Ubi Industrial Park Singapore 408933

Our ref: SSES/L2019/0087 Your ref:S7M0025CMC/RA

Fax: 6741 4108

Tel: 6256 3561

Attn: Ms Vic

Dear Sir,

VEHICLE: XD8417Z (DoA: 09/06/2016)

We refer to the above and append herewith our costings for your perusal: -

Final Repair Bill : 4,654.50

Loss of Use: 5 days @ S\$ 250/day : 1250.00

(including 2 day for PRI)

Survey Fee : N/A

Third Party Vehicle Insurance Search Fee

Total

Search Fee

5,904.50

Thank You

Yours faithfully

Susan Tan OPERATIONS EXECUTIVE

**Encl** 

### SIN SHENG ENGINEERING SERVICES

3 TECH PARK CRESCENT SINGAPORE 638129

Tel No.: 6863-9595 Fax No.: 6863-6477

E-Mail: sinsheng1981@gmail.com Buss. Reg. No.: 312029/00D

C & P LEASING PTE LTD 41 PANDAN ROAD SINGPAORE 609283

Attention: Motor Claim Department

Contact: 6349 3836

Tax Invoice: TI002707

Date: 05/03/2019 Vehicle Num.: XD8417Z

Make/Model: NISSAN GKB45-2013 Chassis/Eng#: GKB5E00172/GH11715851

Accident Date: 09/06/2016 Claim No.: S7M0025CMC/RA Reference: XD2448Z

Policy No.: SD15V01265/VCZ/R02

Amount S\$

4,350.00

ACCIDENT LUMP SUM REPAIR

Total S\$:

GST @ 7% S\$:

Amount Due S\$:

4,350.00

304.50 4.654.50

SIN SHENG ENGINEERING SERVICES

M9-0010014-J

Your Insured's vehicle: XD2448Z

Our customer's vehicle: XD8417Z

Date : 9-Jan-19

#### AXA INSURANCE PTE LTD

Dear Sirs,

DATE OF ACCIDENT: 9-Jun-16

#### NOTICE TO INSURER TO CONDUCT PRE-REPAIR INSPECTION/SURVEY & SEEK ATTENTION

We have been appointed by C & P Leasing Pte Ltd repair their vehicle no. XD8417Z Please be informed that the said vehicle can be inspected at:

Workshop: Sin Sheng Engineering Services

Address : 3 Tech Park Crescent, Tuas Tech Park, Singapore 638129

Contact : Ms Susan

Tel / Fax : 6863 9595 / 6863 6477

Pursuant to ePractice Direction No 2 of 2011, we hereby give you notice to conduct the pre-repair inspection within the next 2 working days excluding any intervening Saturday, Sunday and/or Public Holiday failing which we will commence repairs thereafter without any futher notice or refrence to you. Kindly acnowledge upon inspection in the acknowledgement box below, Alternatively kindly inform us in writing if you are waiving your rights to an inspection of our customer's vehicle.

NB. Any settlement of offer is on the express condition that this settlement is in respect of our client's claim for property-related damage only and shall not preclude client's driver/passanger from claiming injury-related damage arising from this accident.

Your sincerely,

Busan
<i>Susan</i>

	Acknowledgement	
This is to confirm that I	Tayla	\[Full Name of Surveyor]
of	Llell	\[Surveyor's Company]
have completed the pre-repa	ir inspection on .Ve.	.(
ofhave completed the pre-repa at\f\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\	ne of Inspection)	į.
D. April		Susan
Signature of Appointed Surv	veyor Wi	tnessed By:
oignature of Tippointed Dar (		
Company Stamp	Da	te



We waive our rights to an inspection/survey of the above vehicle.				
Signature				
Name:				
Date:				

Allowed As C

# SIN SHENG ENGINEERING SERVICES

3 TECH PARK CRESCENT SINGAPORE 638129

Tel No.: 6863-9595 Fax No.: 6863-6477 E-Mail: sinsheng1981@gmail.com

Buss. Reg. No.: 312029/00D

C & P LEASING PTE LTD 41 PANDAN ROAD SINGPAORE 609283

Attention: Motor Claim Department

Contact: 6349 3836

Estimate: ES002707

Date: 09/01/2019

Vehicle Num.: XD8417Z Make/Model: NISSAN GKB45-2013

Chassis/Eng# : GKB5E00172/GH11715851

Accident Date: 09/06/2016

Claim No.:

Reference : XD2448Z

Policy No.: SD15V01265/VCZ/R02

S/N	Quantity	Particular	Unit Price Amount S\$
1. 2. 3. 4. 5.	1 21 21 1	LIST ITEMS : DIESEL TANK DIESEL TANK BRACKET DIESEL TANK BELT AD-BLUE TANK INSULATOR EXHAUST MUFFLER	7585.40 4 4,685.20 7585.40 4 1,170.80 7195.20 390.40 70 × 6,982.50 798.20
		List TotalSS: 30.00% Discount SS:	6 246.4614,027.10 4,208.13  4372.48 9,818.97
1.	1	NETT ITEMS : STEP BRACKET	H 380.00
		Nett Total S\$ : 10.00% Discount S\$ :	380.00 38.00 
		LABOUR : TO PANEL BEAT/REPAIR RH BODY TO DISMANTLE/REPLACE ABOVEMENTIONED PARTS	ξυ <sub>0</sub> 950.00

CONTINUE / ...

## SIN SHENG ENGINEERING SERVICES

3 TECH PARK CRESCENT SINGAPORE 638129

Tel No.: 6863-9595 Fax No.: 6863-6477

E-Mail: sinsheng1981@gmail.com

Buss. Reg. No.: 312029/00D

C & P LEASING PTE LTD 41 PANDAN ROAD SINGPAORE 609283

Attention: Motor Claim Department

Contact: 6349 3836

Estimate: ES002707

Date : 09/01/2019 Vehicle Num. : XD8417Z

Make/Model: NISSAN GKB45-2013 Chassis/Eng#: GKB5E00172/GH11715851

Accident Date: 09/06/2016

Claim No.:

Reference: XD2448Z

Policy No.: SD15V01265/VCZ/R02

S/N Quantity Particular

Unit Price Amount S\$

SPRAY PAINTING

LOSS OF USE: 4 DAYS @ \$ 250/DAY

Labour Total S\$:

250.00

1,200.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- · Parts prices are subject to confirmation
- . Third party survey is on a "Without Prejudice" basis
- · No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from insurance Company

Acknowledged by Repairer

Signature:

Cale:

Surolkhurtum.

Total S\$ :

11,360.97

W

SIN SHENG ENGINEERING SERVICES