Interview (\$

Tech, Invs (\$

Weekend (\$

Report Format:

Lump Sum / I.B.I: (\$

Prel.

) Photos

Shirley Hiew (LKK Auto)

From:

Claims <claims@premiumauto.com.sg>

Sent:

Saturday, 23 February 2019 10:57 AM

To:

'NORA'; 'Shirley Hiew (LKK Auto)'

Cc:

'Adrian Ling (LKKAuto)'; 'SUR'

Subject:

RE: OD Claim Veh No SLN 3634 K

Dear Shirley,

Owner of the mentioned vehicle have decided not to continue with own damage claims, we will make the necessary closure for this case on our end.

Kindly proceed to close this case on your end.

Thank You.

Best Regards, Sheila M Ismail Claims Advisor

Premium Automobiles Pte Ltd (Reg No 199902271W)

55 Ubi Road 1 Road Singapore 408699

p. +65 6388 2323 d. +65 6768 9828 f. +65 6841 1183



http://www.audi.com.sg/sea/brand/sg/audi promotions/promotions/car promotions/new-audi-q2-

2017.html Email Disclaimer

This email, including any attachment, is confidential and may also be privileged.

If you have received it in error, please notify us immediately by reply email and then delete this message from your system.

Please do not copy it or use it for any purpose, or disclose its contents or any attachment to any other person. Thank you

From: NORA [mailto:nora.khai@premiumauto.com.sg]

Sent: Monday, 21 January 2019 4:25 PM

To: 'Shirley Hiew (LKK Auto)'

Cc: 'Adrian Ling (LKKAuto)'; 'Claims'; 'SUR' Subject: RE: OD Claim Veh No SLN 3634 K

Dear Shirley,

Noted with thanks.

Best regards,

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.

Any false reporting may be referred to the Police for investigation.

- This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available

aforesaid.		
	ACCIDENT STATEMENT	
Date Of Report	12/01/2019 14:02	
Date Of Accident	12/01/2019 09:30	
Exact Location Of Accident	CLEMENTI ROAD	
Country/State of Loss	SINGAPORE	
	DETAILS OF OWN VEHICLE	
Vehicle Registration Number	SLN3634K	
Insured/Policyholder		
Name Of Registered Owner	ARVIND KUMAR SAXENA	

NRIC No S2721126G

Email Address SAXENA.ETKA@YAHOO.COM

Mobile Phone No (LOCAL) +65-96657454

Alternative Phone No OFFICE-63240500

Vehicle Particulars

Manufacturer AUDI

Model A4 SEDAN 1.4 TFSI

Exact Purpose for which vehicle was being used at

time of accident

PRIVATE USE

Are you claiming under your own insurance policy

for repair to your vehicle?

YES

If No. Please state action to be taken

Vehicle Category PRIVATE CAR

Insurance Company

Name of Insurance Company AIG ASIA PACIFIC INSURANCE PTE. LTD.

Type Of Coverage COMPREHENSIVE

Fleet Policy NO

Policy Number 2100508416-01

Cover Note Number

Driver

Name of Driver ARVIND KUMAR SAXENA

 NRIC No
 \$2721126G

 Date Of Birth
 22/08/1962

 Occupation
 INDOOR

 Date Of Driving Pass
 29/07/2004

Driving Experience 14 YEARS AND 5 MONTHS

Gender MALE

Mobile Number (LOCAL) +65-96657454

Fax Number

Contact Number OFFICE-63240500

EMail Address SAXENA.ETKA@YAHOO.COM

Address

41 HINDHEDE WALK #05-02

Postcode

587972

... ..

Was driver an employee of the Insured's Company NO

If No, Relationship of the Driver with the Insured

OWNER

Vehicle Registration Number of Driver's Own

Vehicle

(+)

Insurance Company of Driver's Own Vehicle

.

General Information of the Accident

Type Of Accident

COLLISION - HEAD TO REAR

Weather Conditions

CLEAR

Road Surface

DRY

Other Information

Was any foreign vehicle involved in this accident?

NO

Number of vehicles (including own vehicle)

45

involved in the accident

2 NO

Was any body injured in the Accident?

Was any injured conveyed to hospital by

ambulance?

NO

Was any other material or property damaged?

YES

I have been approached by unknown person(s) soliciting/offering accident claims assistance.

NO

Number of Passengers (Including Driver)

1

Details of Police Action

Was the accident reported to the police?

NO

If Yes, Please state which Police Station

Was notice of intended Prosecution given?

NO

If Yes, against whom?

Circumstances of Accident

I WAS DRIVING THE VEHICLE SLN 3634 K, I STOPPED MY VEHICLE AT A RED LIGHT. MY VEHICLE WAS NO. 3 (THERE WAS ONE SMALL PASSENGER TRUCK IN FRONT, FOLLOWING THAT WAS THE VEHICLE SKW 7727 P AND FOLLOWING THIS WAS MY VEHICLE. ALL THESE VEHICLE WAS STOPPED AT RED LIGHT & THEN THE LIGHT TURNED GREEN. I MOVED THE CAR IN FRONT OF MY VEHICLE ALSO MOVED BUT THE PASSENGER TRUCK RIGHT IN FRONT SUDDENLY STOPPED & I COULD NOT STOP MY VEHICLE. MY VEHICLE WAS MOVING VERY SLOW (MAY BE 5-10KM/HR) & HIT THE REAR BUMPER OF SKW 7727 P.

Attachment(s)

Are accident photos available for attachment?

YES

Was there any video captured by Car Camera?

NO

Was there any audio recorded?

NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number

SKW7727P

Vehicle Make/Model/Colour

MITSUBISHI LANCER / GREY

Details Of Properties

Vehicle Category

PRIVATE CAR

Name of Driver

NOR HARMAYA BINTE KAMIS

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

- Please report correctly the details of the accident to speed up the claims process.
- Isis form must be completed by the Policyholder and/or the Authorised Driver.
- Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance. Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- 7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8. Consent under the Personal Data Protection Act (PDPA)

Lunderstand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s)
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims:
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes"
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclused:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders

Policyholder's Signature

Date & Time

1245mm 2019 @

Driver's Signature (If driver is not the policyholder)


Date & Time:

Reporting Centre Personnel's Signature Name: White Extends Stanfo, Guye

NRIC/FIN NO.: 040 C 299143>

Sketch Plan #2

SKET	TCH	PI	AN
21/4		-	~



	IRCUMSTANCES OF THE ACCIDENT
2 N	no driving the vehicle SLN 3634K, 9 Stepped
my	vehicle at a red light. My Vehicle was
NB13	(there was one small passanger truck in
how	t, following that was the vehicle SKW 7727P
	following this was my vehicle).
ALL	three vehicles were stopped at realight &
then	there was the light turned green. I moved
-lhe	car in front of my vehicle also moved but
the	parsayer truck hight in front froderly
Cremi	is I I could not stop my vehicle. My
vehic	de was moving very slow (may be sololim) his
8 hi	it the rear bumper of SKN 7727P.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature

Date & Time | 2019(01350) Date & Time:

Driver's Signature

Reporting Centre Porsonnel's Signature Name hand bottom Stank Many NRIC/FIN NO: GUTET HIS X

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	SI NDC
Owner ID Type:	Singapore NRIC
Owner ID:	1126G
Vehicle Details	SLN3634K
Vehicle No.:	No.
Vehicle to be Exported:	18 Jan 2019
Intended Deregistration Date:	
Vehicle Make:	AUDI
Vehicle Model:	A4 1.4 TFSI S TRONIC
Primary Colour:	Grey
Manufacturing Year:	2017
Engine No.:	CVN032207
Chassis No.:	WAUZZZF42HA121501
Maximum Power Output:	110.0 kW (147 bhp)
Open Market Value:	\$32,086.00
Original Registration Date:	28 Apr 2017
First Registration Date:	28 Apr 2017
Transfer Count:	0
Actual ARF Paid: Intended PARF Rebate Details	\$26,921.00
	Yes
PARF Eligibility: PARF Eligibility Expiry Date:	27 Apr 2027
PARF Rebate Amount: Intended COE Rebate Details	\$20,190.00
COE Expiry Date:	27 Apr 2027
	B - Car above 1600cc or 97kW (130bhp)
COE Category:	10
COE Period(Years): QP Paid:	\$54,406.00
COE Rebate Amount:	\$45,020.00
Total Rebate Amount:	\$65,210.00
IOIAI REDALE AMOUNT.	(3·7-1/2

The information contained herein is correct as at 18 Jan 2019



CERTIFICATE OF INSURANCE

AUDI AUTO PROTECTOR PRIVATE VEHICLE

Name of Policyholder

: ARVIND KUMAR SAXENA

Period of Insurance Engine No.

: 28 Apr 2018 To 27 Apr 2019

Chassis No.

: CVN032207 : WAUZZZF42HA121501 Vehicle No.

: SLN3634K

: 2100508416-01

Policy No.

Endorsement No. Issued Date

: 10 Apr 2018

ABOUT THE COVER

Make/Model

: AUDI A4 1.4 TFSI S tronic

Engine Capacity/Tonnage : 1,395.00 CC Driver Restriction : NA

Sum Insured : Market Value Off Peak Car : No

First Year of Registration : 2017

Insuring with COE/PARF : Yes

Person or Classes of Persons Entitled to Drive* :

a) The Policyholder b) Any other person who is driving on the Policyholder's order or with his/her permission. This Policy will indemnify the Policyholder or any authorised driver only if he/she meets the specified age condition. You have to pay an additional sum of \$3,000 as "Young and/or inexperienced Driver Excess" ("YIDR") If You are or Your Authorised Driver (named or unnamed) is under the age of 23 and/or has less than 2 years' driving experience.

Age Condition

: All Age Condition

Limitation as to use*

Use only for social, domestic and pleasure purposes and for the Policyholder's business. This Policy does not cover use for hire or reward, driving tuition, driving test, racing, pace-making, reliability trial or speed-testing, the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with Motor Trade.

Loss of Use 1800cc - 2000cc Optional

* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Cap. 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

EXCESS

Section 1

Fire - \$0 Own Demage - \$600 Theft - \$0 Flood Cover - \$0

Section 2

Property Damage - \$0

Windscreen: \$100

Named Driver and Excess (where applicable)

ARVIND KUMAR SAXENA - \$600 (Own Damage)

APPROVED REPORTING CENTRES/AUTHORISED REPAIRERS (FOR CLAIMS RELATED REPAIRS)

1.Audi Customer Service Center Add: 55 Ubi Road 1 Singapore 408699 63662323

For other Approved Reporting Centres/AIG Authorised Repairers, please contact our 24-hour accident emergency hotins at +65 6338 6200. Alternatively, you may refer to AIG website www.sig.com.sg or AIG SG Mobile App, Simply search and download "AIG SG" from lTunes or Google Play.

IMPORTANT NOTES

Hire Purchase Company/Employer's Loan: DBS BANK LTD

I/We hereby certify that the policy to which this Certificate of Insurance relates is issued in accordance with the provisions of the Motor Vehicles (Third Party Risks and Compensation) Act (Cep. 189), Part IV of the Road Transport Act, 1987 (Malaysia) and Motor Vehicles (Third Party Risks) Rules, 1959 (Malaysia).

0504125219

PREMIUM LEASING - KATL

281 ALEXANDRA ROAD AUDI CUSTOMER SERVICE CENTRE

SINGAPORE 159938

Underwritten by AIG Asia Pacific Insurance Pte. Ltd.

AIG Asia Pacific Insurance Pte. Ltd. AUTHORISED REPRESENTATIVE

24-HOUR AIG AUTO HOTLINE: +65 6338 6200

IMPORTANT: KEEP THIS DOCUMENT IN YOUR CAR AT ALL TIMES.

What can the 24-hour AIG Auto Emergency Hotline provide for you?

- Immediate assistance after an accident
- Emergency breakdown service
- Towing service (accident or non-accident related)
- Advice on Motor Claims procedures
- Medical Referral Assistance

What should I do in the event of an accident?

- Keep calm and move your car to a safe place.
- Do not admit or discuss fault or blame with the other party(les).

 Report the accident to us with your accident vehicle (whether damaged or not) via our approved reporting centres or authorised repairers within 24 hours or the next working day of the accident.
- Submit Whit/Summons/Correspondences from third party(ies) to AJG immediately.

If no one is injured in the accident:

- You are not required to make any police report
- Record vehicle number, name and address, insurance company and policy number of the other driver(s) and vehicle(s).
- Collect details (name, address and contact number) of witnesses and/or try to take photographs of the scene of the accident
- Report the accident to us with your accident vehicle (whether damaged or not) via our approved reporting centres or authorised repairers within 24 hours or the next working day of the accident.

If the accident involves injuries or damage to government property & vehicles, foreign registered vehicles or non-injury hit & run case:

- Report the accident to the police, providing full details of the circumstances of the accident
- Record vehicle number, name and address, insurance company and policy number of the other driver(s) and vehicle(s), if applicable. Collect details (name, address and contact number) of witnesses and/or try to take photographs of the scene of the accident.
- Report the accident to us with your accident vehicle (whether damaged or not) via our approved reporting centres or authorised repairers within 24 hours or the next working day of the accident.

LOSS OF USE CAR REPLACEMENT BENEFIT

Applicable only if this benefit is included in your motor insurance. Please refer to your Policy Schedule for details. Policy terms and conditions apply. Please call our customer service hotline number (65) 6419-3000 for assistance.

The Certificate of Insurance (CI) should be produced without demand when collecting the Rental Car and the Rental Car Company reserves the right to verify the identity of the holder. The CI is the property of AIG and its use is subject to the terms and conditions contained in the Loss of Use Endorsement under the policy issued to the policyholder.

Steps to activate Loss of Use Car Replacement Benefit and Important Information

- 1. To activate your loss of use car replacement, please contact the Rental Car Company (listed below) after filing/reporting your accident claim.
- Your rental car will be made available within 5 working hours of activation with the Rental Car Company.
- 3. At the time of collection of the Rental Car, the original insurance policy and schedule issued by AIG, a copy of the Accident Report from Audi Customer Service Centre must be produced.
- 4. The number of days is based on the period your vehicle is in the repair workshop unless the number of days of loss of use entitlement is stated in the Policy.
- 5. Rental cars are strictly for use in Singapore only.
- 6. Extension of rental beyond repair period approved by AIG surveyor will be chargeable by the Rental Car Company on per day basis.
- Upgrade of Rental Car is available upon request subject to additional charges by the Rental Car Company.

Rental Car Company: Popular Rent A Car Pte. Ltd.

Activation Hotline: 67428888

501 Guillemard Road Singapore 399840

Operation Hours: Monday to Friday: 9am to 6pm Saturday (Half Day): 9am to 4pm

*The Rental Car Company's Terms & Conditions apply (i.e., refundable security deposit, excess liability for the Rental Car, Collision Damage Walver, etc).

IMPORTANT NOTICE

If you sell your motor vehicle, this Notice is IMPORTANT and MUST be complied with. Policyholders are hereby warned that under the Motor Vehicles (Third Party Risks and Compensation) Act (Cap.99), it shall be unlawful for any person to use or cause or permit any other person to use a motor vehicle without a valid policy of insurance under the Act.

The Policyholder is further warned that on the sale of a motor vehicle, they must surrender the Certificate of Insurance and the Policy to the insurance company. If the Certificate of Insurance has been lost or destroyed, a Statutory Declaration to that effect must be made. Failure to comply with this obligation is an offence under the Motor Vehicles (Third Party Risks and Compensation) Act (Cap.88).

This Policy will cease to be valid once the motor vehicle has been sold to another person unless the transfer of interest has been duly notified to and agreed to by the insurance company concerned. If the insurance company agrees to cover the new owner, they will issue a new Certificate of Insurance in the new owner's name. The premium chargeable may vary according to the new owner's profile.

REPUBLIC OF SINGAPORE IDENTITY CARD NO. \$2721126G



Name

ARVIND KUMAR SAXENA


A 11

INDIAN
Date of birth
22-08-1962
Country/Piece of birth

INDIA

Sex M

\$2/21126G



47842



HMC No. S2721126G



INDIAN Des et less 15-03-2018

41 HINDHEDE WALK #05-02 SINGAPORE 587972 YOU ARE UCENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASSIES)

PASE DA

Dess 28 Molorcycles of Dess 3 Molor Cers of 3000 kg with a

telercycles not exceeding 200 cc leter Cars of unladen weight not exceeding 000 kg with not more than 7 pessengers, actuative of the driver; and Motor Tractors and other Motor Vehicles of unladen weight of exceeding 2500 kg

Licence No: 52721126G

NP 428A

ď

55 Ubi Road 1, Singapore 408699 Tel: 6366 2323 Fax: 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323

Fax No : 6841 1183

Reference : PA/OD/0066/2019/NK

Date : 16-Jan-19

Vehicle NOT in workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way #07-16 AIG Building Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Mr. Arvind Kumar Saxena

Address : 41 Hindhede Walk

#05-02

Singapore 587972

 Telephone
 : Hp:+65 96657454

 Type of Claim
 : Own Damage Claims

 Policy No.
 : 2100508416-01

 Vehicle No
 : SLN 3634 K

Model Code : Audi A4 SEDAN 1.4 TFSI

 Model / Year
 : Apr-17

 Engine No
 : CVN 032207

Chassis No : WAUZZZF42HA121501

Mileage : Date In :
Liability : -

Excess Cost : -

Estimated By : Allan Wu
Accident Date : 12-Jan-19
Place of Accident : Clementi Road

Premium Automobiles 55 Ubi Road 1, Singapore 408699 Tel: 6366 2323 Fax: 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SLN 3634 K

S/N	Nature of Jobs		Estimated Charges
1	To remove and transfer front wire harness for headlights, horns, fog lamps, outside temperature sensor and headlight washer assy.	S/N	\$ 360.00
2	To dismantle and renew front bumper and both headlights. Re-organise crash management components. Reinstall all parts removed.		\$ 1,809.00 500
3	To respray front bumper.		\$ 800,06 550
4	To carry out diagnostic check.	S/N	\$ 192.00
	TOTAL LABOUR CHARGES	:	\$ 3,152.00

55 Ubi Road 1, Singapore 408699 Tel: 6366 2323 Fax: 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLN 3634 K

dese	620 W 320 W 320			- V-S S [MASS N DV [M] 1	e Parts & Price
5/N	Parts Description		S	/NETT	REMARKS
1	FRONT BUMPER Rejic		\$	1,946	.00 ×
2	FRONT BUMPER FIXING SETS	-	\$	258	.00+
3	FRONT BUMPER SECURING STRIPS	2	\$	64	.00 -
4	FRONT BUMPER CENTRE GRILLE CMC	d	\$	178	.00
5	FRONT BUMPER CENTRE CLOSING ELEMENT	me cu	\$	191	.00 *
6	FRONT BUMPER AIR GUIDE GRILLE LH / RH	Ma 2	\$	112	.00 4.
7	RADIATOR GRILLE and		\$	1,666	.00
8	AIR GUIDE GRILLE LH / RH Ne u	2	\$	666	.00 ₹ .
9	FRONT BUMPER REINFORCEMENT ?		\$	733	.00 ".
11	FRONT BUMPER GUIDE SECTION LH / RH	Yen 2	\$	67	.00 🖛
12	FRONT BUMPER TOP COVER KHE L		\$	116	.00 🐣
13	FRONT BUMPER FOAM		\$	113	.00 ?
14	FRONT BUMPER SUPPORT LH / RH	_ 2	\$	52	.00+
15	FRONT BUMPER LOCK CARRIER BRACKET 🏃	r ~	\$	125	.00~
16	SIGN "CAUTION "		\$	13	.00 *
17	STICKER FOR AIRCONDITIONER		\$	7	.00*
18	FANFARE HIGH TONE LH		\$	37	4,00
19	FANFARE LOW TONE RH		\$	262	.00 ×
20	SPRING SHACKLE LH / RH	2	\$	52	.00 ⊀
	SUB SPARE PARTS	:	\$	6,658.	00

All charges are not inclusive of GST.

Legend:

Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

55 Ubi Road 1, Singapore 408699 Tel: 6366 2323 Fax: 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLN 3634 K

S/N	Parts Description		Damage Parts & Prices S/NETT REMARKS
21	LED HEADLIGHT LH / RH PNE an	2	\$ 14,174.00 %
22	LIFT CYLINDER LH / RH	2	\$ 384.00
23	FRONT NO PLATE BENT	S/N	\$ 25.00
24	SUNDRIES ?		\$ 500.00 ?
	TOTAL SPARE PARTS		\$ 21,741.00
	TOTAL LABOUR CHARGES	10	\$ 3,152.00
	GRAND TOTAL	2	\$ 24,893.00

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

55 Ubi Road 1, Singapore 408699 Tel: 6366 2323 Fax: 6841 1183

Telefax

Name

Surveyed Date **Authorised Date**

Excess Cost

Liability

Remarks

LKK Auto Consultants hence notify the Repairer of the following:

- . To resurvey before/after spray painting
- . To display damaged part(s) during resurvey
- · Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- . No illegal modification(s) is allowed
- · Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Please Note

This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly. For inspection of vehicle, please refer to Ms Norah Khai at Tel:6768 9828 for appointment.

Anthorised Repairs, 03 Days.

Yours faithfully, Premium Automobiles Pte Ltd

Johnny Boo Body Repair Manager Allan Wu Claims Consultant

...CLAIM SUBFOLDER...(Pending for Survey Report)

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt		Adj Subr	mitted	Ins Auth'ed	Status	
Main	17 Jan 2019 Edit Reg		17 Jan 2019 00:00 Edit Adj Rpt	S\$3,471.0 Edit Estima		\$\$3,47	Spiret .		Pending for S Report Cancel Case	urvey
1	Main	Re	eference		Claim I	Details		Document	s	Show All
CLAIM SU	BFOLDER DE	TAILS	Sept of the Service Service of the	The state of the s	The Marie Co	Security Print	[Created	by adjuster]	To the party of the state of th	S STATE OF THE SECOND
Insured:	ARVIND	KUMAR SAXENA,	ID: S27211260	3						
Vehicle Reg No.:	SLN363	4K			Date	of Loss:		19 09:00 - :59 hs and 15 Days Fr	om LTA Reg Date	(Man Yr)]
Claim Type:	OD / 865	54592075SG				y/Cover No.:	2100508416 (Comprehensive)			
					Exce	ss:	S\$600.00			
Repairer:	Premium	Automobiles Pt	e Ltd (UBI) 55 L	Jbi Road 1, 4	08699	Ubi - Tel:	67689828	/9827/9911		
Handling Insurer:	AIG Asia	Pacific Insuranc	e Pte. Ltd. (Exp	oress) - Tel:	65-641	9-3000 .	[Handled	by Loo, Tong Sh	ing] TongShing.l	.oo@aig.con
Adjuster:	LKK Auto	Consultants Pte	Ltd (HQ) - Tel:	6256-3561	[Har	dled by A	DRIAN LI	NG] [Final R	pt due 28/01/	2019]
ASSOCIAT	ED MAIL RE	CEIVED			All I Comme			V	iew All Compo	se Case Mail
 AIG_SG 	(18/01/2019)	SLN3634K / O	0 / 12/01/2019	9 / Coverag	je & Ex	cess upo	date			
ALL ASSO	CIATED TAS	KS⊡					View All	Search Tasks	Create New Task	Complete
Due Date No results.	e Priority	Type Task	Group Subj	ect Han	dler	Assign	ed By	Completed On	Created O	n Done

Claim Documents

*SLN3634K (8654592075SG) OD Jan 12 2019 9:00AM [ARVIND KUMAR SAXENA] Premium Automobiles Pte Ltd

Up	load Documents Uplo	and Photos Compose New Letter Upload Video Upload Audio	View	View in Brow	vser ▼
Pho	tos/Images		3 per	page 🔻	•
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	18/01/19 09:20	General View	0	Load JPG	•
2	18/01/19 09:20	Chassis Number	0	Load JPG	•
3	18/01/19 09:20	General View	0	Load JPG	2
4	18/01/19 09:20	General View	0	Load JPG	•
5	18/01/19 09:20	General View	0	Load JPG	•
6	18/01/19 09:20	General View	0	Load JPG	•
7	18/01/19 09:20	General View	0	Load JPG	•
8	18/01/19 09:20	General View	0	Load JPG	•
9	18/01/19 09:20	General View	0	Load JPG	•
10	18/01/19 09:20	General View	0	Load JPG	•
11	18/01/19 09:20	General View	0	Load JPG	•
12	18/01/19 09:20	General View	0	Load JPG	•
13	18/01/19 09:20	General View	0	Load JPG	•
14	18/01/19 09:20	General View	0	Load JPG	•
15	18/01/19 09:20	General View	0	Load JPG	•
Doc	umentation		1 per	page 🔻	•
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	-
1	18/01/19 09:18	DRIVING & INS. CERT.pdf	0	Load PDF	
2	18/01/19 09:18	ESTIMATE .pdf	0	Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset Save Print
There are no document checklists configured.	
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)	
Show Remarks To: Handling Insurer Note: Remarks are private unless you show it to other parties.	

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Pava Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.

AIG Building, 78 Shenton Way #07-16

Singapore 079120

Our File No:

CC3/AIG19001081/ASD3S2

Date:

27/02/2019

REFERENCE

Date of Loss:

Insured/Claimant:

ARVIND KUMAR SAXENA

Policy No:

Nature of Claim:

2100508416

OD

Engine No:

Chassis No:

Odometer:

Claim No: 8654592075SG

CVN032207

27569 km

WAUZZZF42HA121501

DESCRIPTION & IDENTIFICATION OF VEHICLE

12/01/2019

Reg No:

Reg. Date:

SLN3634K

Make & Model:

AUDI A4, 1.4 (A)

28/04/2017 (Man. Year: 2017)

Colour: Grey

Engine Capacity:

Market Value/New Car Price: S\$113,000.00

Sum Insured (S\$):

1395 cc

Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:

Good

Steering (Serviceable):

No

Footbrake (Serviceable): Pre-accident Condition:

Yes

CONDITION OF TYRES

Handbrake (Serviceable):

Yes

Engine Modification:

Front Left Side:

Front Tyre Size:

205/60R16 Continental 6 mm

Rear Tyre Size: Rear Left Side:

205/60R16

Front Right Side:

Continental 6 mm

Rear Right Side:

Continental 6 mm Continental 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS		Repairer's	Adjuster's	Difference	Diff %
Parts		21,741.00	1,869.00	19,872.00	91.40
Miscellaneous Items		0.00	0.00	0.00	
Labour		3,152.00	1,602.00	1,550.00	49.18
Paintwork Labour		0.00	0.00	0.00	
Towing		0.00	0.00	0.00	
	Calculated Gross Total (S\$)	24,893.00	3,471.00	21,422.00	86.06
	- Excess (S\$)	600.00	600.00	0.00	0.00
	(\$\$)	24,293.00	2,871.00	21,422.00	88.18
	+ GST 7.00/7.00% (S\$)	1,700.51	200.97	1,499.54	88.18
	Nett Amount (S\$)	25,993.51	3,071.97	22,921.54	88.18

INSPECTION

Date of Assignment:

17/01/2019

Date Inspected:

17/01/2019

Inspected At:

Premium Automobiles Pte Ltd (UBI)

55 Ubi Road 1 Singapore 408699

Estimated Period of Repair: 3.0 days

Adjuster: ADRIAN LING

Manager:

Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

(REPAIR COST NOT CONCLUDE) (EXCLUDE CHECK ITEMS S\$1,346.00 NETT)

REPAIR DETAILS

Recommended	Parts
-------------	-------

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Repair	1,946.00 FS	*-FS
2	1		*FRONT BUMPER FIXING PARTS	Not Necessary	258.00 FS	*-FS
3	2		*FRONT BUMPER SECURING STRIPS	Not Necessary	64.00 FS	*-FS
4	1		*FRONT BUMPER CENTRE GRILLE	Cracked	178.00 FS	*178.00 FS
5	1		*FRONT BUMPER CENTRE CLOSING ELEMENT	Not Necessary	191,00 FS	*-FS
6	2		*FRONT BUMPER AIR GUIDE GRILLE LH/RH	Not Necessary	112.00 FS	*-FS
7	1		*RADIATOR GRILLE	Cracked	1,666.00 FS	*1,666.00 FS
8	2		*AIR GUIDE GRILLE LH / RH	Not Necessary	666.00 FS	*-FS
9	1		*FRONT BUMPER REINFORCEMENT	*Check	733.00 FS	*-FS
10	2		*FRONT BUMPER GUIDE SECTION LH /RH	Not Necessary	67.00 FS	*-FS
11	1		*FRONT BUMPER TOP COVER	Not Necessary	116.00 FS	*-FS
12	1		*FRONT BUMPER FOAM	*Check	113.00 FS	*- FS
13	2		*FRONT BUMPER SUPPORT LH / RH	Not Necessary	52.00 FS	*-FS
14	1		*FRONT BUMPER LOCK CARRIER BRACKET	Not Necessary	125.00 FS	*-FS
15	1		*SIGN CAUTION	Not Necessary	13.00 FS	*- FS
16	1		*STICKER FOR AIRCONDITIONER	Not Necessary	7.00 FS	*-FS
17	1		*FANFARE HIGH TONE LH	Not Necessary	37.00 FS	*-FS
18	1		*FANFARE LOW TONE RH	Not Necessary	262.00 FS	*- FS
19	2		*SPRING SHACKLE LH / RH	Not Necessary	52.00 FS	*-FS
20	2		*LED HEADLIGHT LH / RH	Not Necessary	14,174.00 FS	*-FS
21	2		*LIFT CYLINDER LH / RH	Not Necessary	384.00 FS	*-FS
22	1		*FRONT NO PLATE	Bent	25.00 FS	*25.00 FS
23	1		*SUNDRIES	*Check	500.00 FS	*-FS
F=Fra	nchise	part. S=SpcN	ett.	-	000.0010	-13
				Total Parts (S\$)	21,741.00	1,869.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

OVE AND TRANSFER FRONT WIRE HARNESS FOR GHTS, HORNS, FOG LAMPS, OUTSIDE TEMPERATURE SENSOR ADLIGHT WASHER ASSY. ANTLE AND RENEW FRONT BUMPER AND BOTH HEADLIGHTS. ANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL	New	360.00 1.800.00	360.00
GHTS, HORNS, FOG LAMPS, OUTSIDE TEMPERATURE SENSOR ADLIGHT WASHER ASSY. ANTLE AND RENEW FRONT BUMPER AND BOTH HEADLIGHTS.	0.025000		
	New	1.800.00	500.00
		1,000.00	500.00
PRAY FRONT BUMPER.	New	800.00	550.00
RY OUT DIAGNOSTIC CHECK.	New	192.00	192.00
Gross Labour	Cost (S\$)	3,152.00	1,602.00
	REMOVED. PRAY FRONT BUMPER. RY OUT DIAGNOSTIC CHECK. Gross Labour	PRAY FRONT BUMPER. New	PRAY FRONT BUMPER. RY OUT DIAGNOSTIC CHECK. RY OUT DIAGNOSTIC CHECK.

< END OF ESTIMATES >