

ASS. REC. BY: _____ REF: CS3/CTI19001082/Ecd37 Special Instruction: _____

Surveyor: Steve ASSIGNMENT (Office)

From (Person): Irene Tay of CI Date/Time: 17/11/2019 @ 2:24pm

Estimated Cost: _____ Bill to: _____

OD (TP) WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SMF8487R Insured: GBB 2246K

at Workshop n/s: platinum Werkz Tel: 67410610

of 53 ubi Ave 1 # 01-25

Policy No: DMVSN30748318011 Claim No: SNM19 D2 00313C02

Sum Insured: _____ Excess: _____

Make of Veh: _____ D.O.A. 11/01/2019
(Client's Record)

CA / REV / REP. / REV 24 HRS lap H.O.D. Endorsement: _____

Date/Time: 2:53pm 17/11/19 Person Contacted: Dora Vehicle IN / OUT

Date/Time	Action/Instruction (X) Estimate
	<u>SMF8487R-X</u>
	<u>GBB 2246K-X</u>
	<u>Dismantle: 18/11/2019</u>

Steve

REF: CTE

PRS (Meinmen)

ASSIGNMENT

From: _____ Date: 17/10/19

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: SMF 8487R

at Workshop m/s: Platinum Werkz

of: 53 ubi Ave. #01-25

Insured: _____

Policy No: _____

Claims No: _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

Veh No: SMF 8487R Yr Regn: 27/11/2018

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
Truck / Trailer or _____

Make: Honda Vezel X C.C: 1496

Colour: Blue A/C: Insured / Std / NI / NA

Sp Reading: 2054 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: RU11303 704

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or _____

Brake: Inorder / Jammed / Leaked / Burnt or _____

Modi: Nil / S/Rim / STD A/Rim or _____

Tyre Size: F: 215/60R16
R: 215/60R16

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or _____



(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 6 days Res: Yes or No

Lum Sum: _____ % 3 Val: Yes or No

CA / REV / REP. / 24 HRS up

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Front 6 mm R/Bal. 6 mm

Rear 6 mm L/Bal. 6 mm

D.O.A. 11/1/2019 D.O.I. 17/1/2019

Survey held at Platinum WREKZ

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
front o/s

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	<u>Repair done 6K-7K 6 days repair</u>
	<u>[Signature]</u>
	<u>22/11/2019</u>

Date/Time, File Pass to? Preli. Report Final Report

1) _____

Date/Time, File Return to? _____

2) _____

Report Format: PRS

Lump Sum / I.B.I.: (\$ _____)

Days Of Repair: 6

Resurvey No. of Trip: 1

Survey Fee: _____

Transportation: _____

Add Fee: Site Insp (\$ _____) S + RS \$ _____

Interview (\$ _____) Photos _____

Tech Invs (\$ _____) Other: _____

Weekend (\$ _____) _____

TOTAL _____

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	17 Jan 2019		17 Jan 2019 14:24 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents						
Show All									
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:									
Main Claimant:	TAN CHENG KIM								
Vehicle Reg. No.:	SMF8487R	Date of Loss:	11/01/2019 22:00 - :59						
Claim Type:	TP / SNM19D200313C02	Policy/Cover Note No.:	DMCVSN30748318011						
Vehicle Reg. No. (Insured):	GBB2246K	Policy No. (Claimant):							
		Excess:	S\$0.00						
Repairer:	Platinum Werkz Pte Ltd (HQ) 53 Ubi Ave 1 01-25 Paya Ubi Industrial Park, 408934 Ubi - Tel: 6741 610								
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Irene Tay Hui Ping - 638986192]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 28/01/2019]								
Adj Asg. Remarks:	PLEASE SURVEY AND REVERT								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Nivitha (LKK Auto)

From: Irene Tay <irene.tay@sg.cntaiping.com>
Sent: Thursday, 17 January 2019 2:16 PM
To: Sophia Tan
Cc: assignments; Admin A
Subject: CTP REF NO. SNM19D200313C02 AL REF NO. SMF8487R - ACCIDENT INVOLVING GBB2246K AND SMF8487R ON 11 JANUARY 2019
Attachments: REQUEST FOR PRS.pdf

WITHOUT PREJUDICE

Dear Sir/Mdm,

We refer to the above matter and our telephone conversation a moment ago.

We will appoint LKK to conduct PRS.

Aside to LKK:

Please assist to liaise with Advance Law.

Thank you.

Regards,

Irene Tay
Executive
Claims Department (Motor Division)

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road #16-00 Springleaf Tower Singapore 079909
Direct (65) 6389 6192
Fax (65) 62247478/62247175
Email: claimsdept@sg.cntaiping.com
www.sg.cntaiping.com



Disclaimer :

This message is confidential; its contents do not constitute a commitment by China Taiping Insurance (Singapore) Pte. Ltd. except where provided for in a written agreement between you and China Taiping Insurance (Singapore) Pte. Ltd. Any unauthorized disclosure, use or dissemination, either in whole or partial, is prohibited. If you are not the intended recipient of the message, please notify the sender immediately.

From: Irene Tay
Sent: Thursday, 17 January, 2019 12:04 PM
To: 'Sophia Tan' <sophia.tan@advlawllc.com>
Subject: CTP REF NO. SNM19D200313C02 AL REF NO. SMF8487R

Without Prejudice

Dear Sirs

We intend to conduct a pre-repair survey of the damage to your client's vehicle jointly with your client/your motor workshop. We propose to use one of the following motor surveyors to conduct the joint pre-repair survey as a single joint expert.

ADRIAN LING
Kelvin Ang
SEE CHEW SENG
MOHD FADHILAH BIN OSMAN
XING QUO QIANG
KENNETH KONG
SIMON HO
CHUA WEIJIE
MARCUS CHUA
HENRY NG

Please let us know within two(2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert.

You may select one of the listed motor surveyors and we will bear the cost of the pre-repair survey carried out by the single joint expert.

Thank you.

Irene Tay

Executive
Claims Department (Motor Division)

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road #16-00 Springleaf Tower Singapore 079909
Direct (65) 6389 6192
Fax (65) 62247478/62247175
Email: claimsdept@sg.cntaiping.com
www.sg.cntaiping.com



Disclaimer :

This message is confidential; its contents do not constitute a commitment by China Taiping Insurance (Singapore) Pte. Ltd. except where provided for in a written agreement between you and China Taiping Insurance (Singapore) Pte. Ltd. Any unauthorized disclosure, use or dissemination, either in whole or partial, is prohibited. If you are not the intended recipient of the message, please notify the sender immediately.

Disclaimer :

This message is confidential; its contents do not constitute a commitment by China Taiping Insurance (Singapore) Pte. Ltd. except where provided for in a written agreement between you and China Taiping Insurance (Singapore) Pte. Ltd. Any unauthorized disclosure, use or dissemination, either in whole or partial, is prohibited. If you are not the intended recipient of the message, please notify the sender immediately.

Evon Char

From: Sophia Tan <sophia.tan@advlawllc.com>
Sent: Tuesday, January 15, 2019 5:12 PM
To: Claims Dept of CTI
Cc: 'Platinum Werkz'
Subject: PRI NOTICE - SMF 8487R

GRB 2246/2

AMR/PRS

Dm CUSN

30748318011

Dear Sir

NOTICE TO INSURER TO CONDUCT PRE-REPAIR INSPECTION WITHIN 2 WORKING DAYS PURUSANT TO PARAGRAPH 6.2 OF PRE-ACTION PROTOCOL FOR NIMA CASES

We act for PLATINUM WERKZ PTE LTD who has been instructed with motorcar no. SMF 8487R with instructions to repair the same.

Please be informed that the said vehicle can be inspected at:-

T8938

Venue : PLATINUM WERKZ PTE LTD
53 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408934
Tel : 6 7410610

Contact: Ms Dora

(9N000577
SNM19D206313
↓
T 9008

If you fail to conduct the pre-repair inspection within the next 2 working days excluding any intervening Saturday, Sunday or Public Holiday, the said workshop will commence repairs thereafter without further reference to you.

Yours faithfully
Sophia Tan
Advance Law LLC

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>

16 JAN 2019

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	12/01/2019 16:10
Date Of Accident	11/01/2019 22:00
Exact Location Of Accident	KALLANG WAY T-JUNCTION FROM PIE
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SMF8487R
Insured/Policyholder	
Name Of Registered Owner	TAN CHENG KIM
NRIC No	S1697960J
Email Address	GOHYANTONG@HOTMAIL.COM
Mobile Phone No	(LOCAL) +65-82882875
Alternative Phone No	OTHERS-63798263

Vehicle Particulars

Manufacturer	HONDA
Model	VEZEL
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5105788613
Cover Note Number	

Driver

Name of Driver	GOH YAN TONG
NRIC No	S9642186I
Date Of Birth	18/11/1996
Occupation	INDOOR
Date Of Driving Pass	16/09/2015
Driving Experience	3 YEARS AND 3 MONTHS
Gender	FEMALE
Mobile Number	(LOCAL) +65-82882875
Fax Number	
Contact Number	OTHERS-63798263
EMail Address	GOHYANTONG@HOTMAIL.COM

Address	33 BISHAN STREET 21 #07-11
Postcode	579801
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	CHILDREN
Vehicle Registration Number of Driver's Own Vehicle	- - -
Insurance Company of Driver's Own Vehicle	- - -

General Information of the Accident

Type Of Accident	COLLISION - CHANGE/CROSS LANE
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER ATTACHED

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	VIDEO WITH OWNER
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GBB2246K
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	RAZZAQUE ABDUR
NRIC/Passport Number	
Contact Number	87981620
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

Sketch Plan Pg. 1

SKETCH PLAN

IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all Insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:

Driver's Signature
(if driver is not the policyholder)
Date & Time: 12/11/2019
10:16

Reporting Centre Personnel's Signature
Name:
MRIC/FIN No.:

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Vehicle A was at the junction waiting for the green light. When the traffic light turned green, both cars, in their own lane, moved to turn left.

While turning, Vehicle B cut into the leftmost lane. The back of vehicle B hit the front right of the vehicle A. Only ~~in~~ Vehicle A was damaged in the process. No visible damage can be seen on ~~at~~ vehicle B.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time: 12/1/2017

Driver's Signature
(If driver is not the policyholder)
Date & Time: 12/1/2017

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

ACCIDENT REPORT 11 JAN 2018. 2215HRS


KALLANG WAY / INTERSECTION (T-JUNCTION)

VEH A

CAR MAKE: SMF 8487R

DRIVER BY:

OWNED BY:



VEH B

CAR MAKE: CBB2246K

DRIVER BY: ABDUR RAZZARQUE


OR PHONE: 06336252

187981620 PH

STATEMENT OF FAULT

ALL DAMAGES TO VEHICLE SMF 8487R
AS A RESULT OF THIS ACCIDENT WILL BE CLAIMED
FROM THE INSURANCE OF VEHICLE CBB2246K


ABDUR RAZZARQUE
CBB 2246K


GOH YAN TONG
SMF 8487R

A'ZONE

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	7960J
Vehicle Details	
Vehicle No.:	SMF8487R
Vehicle to be Exported:	No
Intended Deregistration Date:	17 Jan 2019
Vehicle Make:	HONDA
Vehicle Model:	VEZEL 1.5X CVT
Primary Colour:	Blue
Manufacturing Year:	2018
Engine No.:	L15B5553711
Chassis No.:	RU11303704
Maximum Power Output:	96.0 kW (128 bhp)
Open Market Value:	\$21,536.00
Original Registration Date:	27 Nov 2018
First Registration Date:	27 Nov 2018
Transfer Count:	0
Actual ARF Paid:	\$12,151.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	26 Nov 2028
PARF Rebate Amount:	\$9,113.00
Intended COE Rebate Details	
COE Expiry Date:	26 Nov 2028
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$28,199.00
COE Rebate Amount:	\$27,799.00
Total Rebate Amount:	\$36,912.00

The information contained herein is correct as at 17 Jan 2019

OK

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	17 Jan 2019		17 Jan 2019 14:24 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	-, Co. Reg. No.: -		
Main Claimant:	TAN CHENG KIM		
Vehicle Reg. No.:	SMF8487R	Date of Loss:	11/01/2019 22:00 - :59 [1 Months and 15 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / SNM19D200313C02	Policy/Cover Note No.:	DMCVSN30748318011
Vehicle Reg. No. (Insured):	GBB2246K	Policy No. (Claimant):	
		Excess:	S\$0.00
Repairer:	Platinum Werkz Pte Ltd (HQ) 53 Ubi Ave 1 01-25 Paya Ubi Industrial Park, 408934 Ubi - Tel: 6741 610		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Irene Tay Hui Ping - 638986192]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by CHEN TSUE YEE] ... [Final Rpt due 28/01/2019]		
Adj Asg. Remarks:	PLEASE SURVEY AND REVERT		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SMF8487R (SNM19D200313C02)**
[GBB2246K]
TP
TAN CHENG KIM
Jan 11 2019 10:00PM
[-]
Platinum Werkz Pte Ltd

Upload Documents Upload Photos Compose New Letter

View View in Browser ▼

Photos/Images			3 per page ▼	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	21/01/19 11:57	General View	 Load PDF	
2	21/01/19 11:57	Photographs of Damaged Parts	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: Handling Insurer
 Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/CT119001082/ECD3S2
Date: 23/01/2019

REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMCVSN30748318011
 Claimant Vehicle No: SMF8487R Insured Vehicle No: GBB2246K
 Date of Loss: 11/01/2019 Nature of Claim: TP Claim No: SNM19D200313C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SMF8487R**
 Make & Model: HONDA VEZEL HYBRID, 1.5 RS (A) Engine No: L15B5553711
 Reg. Date: 27/11/2018 (Man. Year: 2018) Chassis No: RU11303704
 Colour: Blue Odometer: 2054 km
 Engine Capacity: 1496 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Good Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/60R16 Rear Tyre Size: 215/60R16
 Front Left Side: Dunlop 6 mm Rear Left Side: Dunlop 6 mm
 Front Right Side: Dunlop 6 mm Rear Right Side: Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 17/01/2019
 Date Inspected: 17/01/2019 Inspected At: Platinum Werkz Pte Ltd (HQ)
 53 Ubi Ave 1 01-25 Paya Ubi Industrial Park
 Singapore 408934
 Estimated Period of Repair: 6.0 days

Adjuster: CHEN TSUE YEE

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$6,000.00 - \$7,000.00

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 23 Jan 2019)

Parts: M1-SUV HONDA VEZEL HYBRID 1.5 RS (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SMF8487R)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >