TAX-INVOICE NUMBER: TP0219/010



(Please quote our reference number TP013012019 for payment)

Lim Mui Chin

Date: 19/02/2019

Vehicle No: SH 2338X

Model: TOYOTA COROLLA AXIO

Description Amount

To lump sum repair as recommended by surveyor.

\$1,650.00

Sub Total	\$1,650.00
Add 7% GST	\$115.50
Total	\$1,765.50

Tan Lim Motor Pte Ltd

No. 1 Defu Lane 6 Singapore 539365

No. 51 Defu Lane 10 Singapore 539216


Tel: 6858 5151 (24 hours) Fax: 6858 0877 email@tlmotor.com.sg www.tlmotor.com.sg

Co. Reg. No.: 199503965M GST Reg. No.: M2-8922054-2

AUTHORIZATION TO ACT (AXA Third Party Claim)

of Block 462 Tampines Street 44 #03-38 Singipore 520462 (address), owner of 9H 2338X (vehicle no.) hereby authorize Tan Um Modor Pte Ud
("the workshop") to act for me with respect to my claim for
repair costs and/or rental and/or loss of use ("claim") for my vehicle no. $\frac{6H2338X}{}$ that was damaged pursuant to the accident which occurred on $\frac{16/01/2019}{}$ (date) along
accident which occurred on(date) along
PIE fowards Changi Air purf (location) involving vehicle no/s SHC 5910 E ("the accident"). I further authorize the workshop to settle my above mentioned
claim in a manner that they deem fit and the workshop is further authorized to receive payment further to settlement of my claim with payment cheque/s being made in favour of the workshop.
I further acknowledge that any settlement the workshop may reach on my behalf is on a without prejudice and without admission of liability basis insofar as the driver/owner/insurers of the other vehicle/s is concerned.
Dated this 16 day of January (month) 20 19 (year)
Signed by "the third party claimant" Signed by "the workshop" (with chop)

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

DESCRIPE SINCOMOTANCES OF THE ACCIDENT
on 16/01/2019 at about 0055 hrs 1 was
driving my vehicle (A: SH2338X) along PIE toward Airport
on the centre. The vehicles infrom of me slowed down
and Stop due to work road whead and I followed suit.
and Stop Ive to work paud whead and I followed suit. Suddenly I felt an impact from my retricle's loft rear
purflux and realised that vehicle (B: 5HC 5910 F) had hif
onto my volicle's left your purlian when swerved loff caused
the uphicle B hit anto the vahicle (C:GBE 4422P) which
was driving on the extreme left lane and the vehicle c driver alighted and check. Three vehicles have no passengers on bould
alighted and check. Three vehicles have no possengers on bank

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature Date & Time:

(If driver is not the policyholder)

16/01/19 01/30h Date & Time:

Reporting Centre Personnel's Signature

CAM WES Shan 10: G GY6 4052 N2 NRIC/FIN No.: