

ASS. REC. BY:

REF:

CS3/MSG19001086/Gcd342

Special Instruction:

Surveyor  
Meimen

Guo Ching

ASSIGNMENT (Office)

From (Person):

Jung Tay

of

MSG

Date/Time:

17/1/2019 @ 2:27pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SMF 9734X

Insured:

SKU 8721J

at Workshop m/s

Guoch Motor

Tel:

9388 4210

of

Blk 7 Sin Ming Ind. Est sec. C #01-80/82

Policy No:

80410706

Claim No:

582322

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

13/01/2019

CA / REV / REP. / REV 24 HRS

22/1/19 @ after 12pm

H.O.D. Endorsement:

Date/Time:

2:45pm 17/1/19

Person Contacted:

Jocky

Vehicle IN / OUT

Date/Time

Action/Instruction (X) Estimate

SMF 9734X-X

SKU 8721J - CC3/A1/G1702/669 / Gea 342

D.O.A: 7/1/17

18/1/19 -

Vehicle not in

Dismantle: 23/1/2019

B 1158

## 120

10

130

## ...CLAIM SUBFOLDER...(New Assignment)

### CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	16 Jan 2019		17 Jan 2019 14:27 <a href="#">Assign</a>				<b>New Assignment</b> <a href="#">Cancel Case</a>

<a href="#">Main</a>	<a href="#">Reference</a>	<a href="#">Claim Details</a>	<a href="#">Documents</a>	<a href="#">Show All</a>
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

### CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	<b>LIM YEE FON DAVID( LIN YIFENG)</b> , ID: S7143846E, Tel: +6594885400		
Main Claimant:	<b>THE CARHUB</b> , Co. Reg. No.: 53331158J		
Vehicle Reg. No.:	<b>SMF9734X</b>	Date of Loss:	13/01/2019 17:00 - :59 [1 Months and 14 Days From LTA Reg Date (Man Yr)]
Claim Type:	<b>TP / 582322</b>	Policy/Cover Note No.:	80410706 (Comprehensive) Coverage: 20/08/2018 - 19/08/2019
Vehicle Reg. No. (Insured):	<b>SKU8721J</b>	Policy No. (Claimant):	
		Excess:	S\$500.00
Repairer:	<b>Guan Auto Service (Sin Ming)</b> Block 7 Sin Ming Industrial Estate Sector C, #01-80/ # 01-82, 575642 Sin Ming - Tel: 93884210		
Handling Insurer:	<b>MSIG Insurance (Singapore) Pte. Ltd. (HQ)</b> - Tel: +65 6827 7888 ... [Handled by <b>Jowyn Tay Mei Ling</b> - 6643 1307]		
Adjuster:	<b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [Imm.Advice due 18/01/2019]		
Driver/Custodian (Insured):	LIM YEE FON DAVID( LIN YIFENG) (47 / Male), NRIC: S7143846E, Tel: +6594885400		
Adj Asg. Remarks:	SJE : DISAGREED / LIABILITY 100% Please appoint LKK AUTO to conduct the survey . Kindly contact MR JACKY FONG @ 9388 4210 to arrange for survey.		

### ASSOCIATED MAIL RECEIVED

There are no mail for this case.

[View All](#)

[Compose Case Mail](#)

### ALL ASSOCIATED TASKS

[View All](#)

[Search Tasks](#)

[Create New Task](#)

[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
----------	----------	------	------------	---------	---------	-------------	--------------	------------	-------

No results.

## &gt; Back to OneMotoring

## Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Business
Owner ID:	1158J
Vehicle Details	
Vehicle No.:	SMF9734X
Vehicle to be Exported:	No
Intended Deregistration Date:	23 Jan 2019
Vehicle Make:	TOYOTA
Vehicle Model:	VIOS 1.5 E (AUTO)
Primary Colour:	Silver
Manufacturing Year:	2018
Engine No.:	2NR5292027
Chassis No.:	MR2B23F3901155333
Maximum Power Output:	79.0 kW (105 bhp)
Open Market Value:	\$13,781.00
Original Registration Date:	30 Nov 2018
First Registration Date:	30 Nov 2018
Transfer Count:	0
Actual ARF Paid:	\$13,781.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	29 Nov 2028
PARF Rebate Amount:	\$10,335.00
Intended COE Rebate Details	
COE Expiry Date:	29 Nov 2028
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$28,457.00
COE Rebate Amount:	\$28,030.00
<b>Total Rebate Amount:</b>	<b>\$38,365.00</b>

The information contained herein is correct as at 23 Jan 2019

OK

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	14/01/2019 15:20
Date Of Accident	13/01/2019 17:40
Exact Location Of Accident	PIE > JALAN EUNOS EXIT > UBI
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SMF9734X
<b>Insured/Policyholder</b>	
Name Of Registered Owner	THE CARHUB
Co Reg No	53331158J
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-93884210

### Vehicle Particulars

Manufacturer	TOYOTA
Model	VIOS 1.5 E (AUTO)

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY

Vehicle Category PRIVATE HIRE

### Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5105640421
Cover Note Number	

### Driver

Name of Driver	PEK SOON HUAT(BAI SHUNFA)
NRIC No	S7244336E
Date Of Birth	22/11/1972
Occupation	OUTDOOR
Date Of Driving Pass	16/03/2001
Driving Experience	17 YEARS AND 9 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-91512679
Fax Number	
Contact Number	
EMail Address	NOEMAIL

Address	BLK 453 TAMPINES STREET 42 #06-208
Postcode	520453
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

#### Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

THE INCIDENT TOOK PLACE ON THE ABOVEMENTIONED LOCATION. STATIONERY WAITING FOR ONCOMING VEHICLE TO CLEAR. WHILE WAITING, THAT IS WHEN VEHICLE B UNABLE TO REACT ON TIME AND THUS THE COLLISION TOOK PLACE.

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SKU8721J
Vehicle Make/Model/Colour	VOLKSWAGEN GOLF A7 1.4 TSI AT 5G13GZ SR HID
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

## Accident Sketch Plan Pg. 1

### SKETCH PLAN

#### IMPORTANT NOTICE



1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:


14 JAN 2018

IDAC KAKI BUKIT (VAC)

Reporting Centre  
Name: 23 Kaki Bukit Ave 4  
Singapore 415933  
Tel: 67416697 Fax: 67492305  
Email: [vackb@singnet.com.sg](mailto:vackb@singnet.com.sg)

# Accident Sketch Plan Pg. 1

## SKETCH PLAN



## DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Refer e-file

## DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature

Date & Time:

Driver's Signature

(If driver is not the policyholder)

Date & Time:

14 JAN 2018

IDAC KAKI BUKIT (VAC)

23 Kaki Bukit Ave 4

Singapore 415933

Reporting Centre Personnel

Name:

NRIC/FIG No.:

Tel: 67416697 Fax: 67492305

Email: [vackb@singnet.com.sg](mailto:vackb@singnet.com.sg)



## ...CLAIM SUBFOLDER...(Pending for Survey Report)



































CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	16 Jan 2019		17 Jan 2019 14:27 <a href="#">Edit Adj Rpt</a>	<b>S\$0.00</b> <a href="#">Edit Estimates</a>	<b>S\$0.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>























  

Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b> <span style="float: right;">[Created by insurer]</span>									
Insured:	<b>LIM YEE FON DAVID( LIN YIFENG)</b> , ID: S7143846E, Tel: +6594885400								
Main Claimant:	<b>THE CARHUB</b> , Co. Reg. No.: 53331158J								
Vehicle Reg. No.:	<b>SMF9734X</b>	Date of Loss:	13/01/2019 17:00 - :59 [1 Months and 14 Days From LTA Reg Date (Man Yr)]						
Claim Type:	<b>TP / 582322</b>	Policy/Cover Note No.:	80410706 (Comprehensive) Coverage: 20/08/2018 - 19/08/2019						
Vehicle Reg. No. (Insured):	<b>SKU8721J</b>	Policy No. (Claimant):							
		Excess:	S\$500.00						
Repairer:	<b>Guan Auto Service (Sin Ming)</b> Block 7 Sin Ming Industrial Estate Sector C, #01-80/ # 01-82, 575642 Sin Ming - Tel: 93884210								
Handling Insurer:	<b>MSIG Insurance (Singapore) Pte. Ltd. (HQ)</b> - Tel: +65 6827 7888 ... [Handled by <b>Jowyn Tay Mei Ling</b> - 6643 1307]								
Adjuster:	<b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [Handled by <b>XING GUO QIANG</b> ] ... [Imm.Advice due 18/01/2019]								
Driver/Custodian (Insured):	LIM YEE FON DAVID( LIN YIFENG) (47 / Male), NRIC: S7143846E, Tel: +6594885400								
Adj Asg. Remarks:	SJE : DISAGREED / LIABILITY 100% Please appoint LKK AUTO to conduct the survey . Kindly contact MR JACKY FONG @ 9388 4210 to arrange for survey.								
<b>ASSOCIATED MAIL RECEIVED</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Compose Case Mail</a></span>									
There are no mail for this case.									
<b>ALL ASSOCIATED TASKS</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a></span>									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## Claim Documents

**\*SMF9734X (582322)**  
**[SKU8721J]**  
**TP**  
**THE CARHUB**  
**Jan 13 2019 5:00PM**  
**[LIM YEE FON DAVID( LIN YIFENG)]**  
**Guan Auto Service**

<a href="#">Upload Documents</a> <a href="#">Upload Photos</a> <a href="#">Compose New Letter</a>			<b>View</b> <a href="#">View in Browser</a>	
<b>Assessment Reports</b>			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	17/01/19 08:29	<b>Accident Statement</b> <small>From: SC - Reg. No: SKU8721J, Claimant: LIM YEE FON DAVIDLIN YIFENG)</small>	 <a href="#">Load HTM</a>	
<b>Photos/Images</b>			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	25/01/19 11:59	General View	 <a href="#">Load JPG</a>	<input checked="" type="checkbox"/>
2	25/01/19 11:59	General View	 <a href="#">Load JPG</a>	<input checked="" type="checkbox"/>
3	25/01/19 11:59	General View	 <a href="#">Load JPG</a>	<input checked="" type="checkbox"/>
4	25/01/19 11:59	General View	 <a href="#">Load JPG</a>	<input checked="" type="checkbox"/>
5	25/01/19 11:59	General View	 <a href="#">Load JPG</a>	<input checked="" type="checkbox"/>
6	25/01/19 11:59	General View	 <a href="#">Load JPG</a>	<input checked="" type="checkbox"/>
7	25/01/19 11:59	General View	 <a href="#">Load JPG</a>	<input checked="" type="checkbox"/>
8	25/01/19 11:59	General View	 <a href="#">Load JPG</a>	<input checked="" type="checkbox"/>
9	25/01/19 11:59	General View	 <a href="#">Load JPG</a>	<input checked="" type="checkbox"/>
10	25/01/19 11:59	General View	 <a href="#">Load JPG</a>	<input checked="" type="checkbox"/>
11	25/01/19 11:59	General View	 <a href="#">Load JPG</a>	<input checked="" type="checkbox"/>
12	25/01/19 11:59	General View	 <a href="#">Load JPG</a>	<input checked="" type="checkbox"/>
13	25/01/19 11:59	General View	 <a href="#">Load JPG</a>	<input checked="" type="checkbox"/>
14	25/01/19 11:59	General View	 <a href="#">Load JPG</a>	<input checked="" type="checkbox"/>
15	25/01/19 11:59	General View	 <a href="#">Load JPG</a>	<input checked="" type="checkbox"/>
16	25/01/19 11:59	General View	 <a href="#">Load JPG</a>	<input checked="" type="checkbox"/>
17	25/01/19 11:59	General View	 <a href="#">Load JPG</a>	<input checked="" type="checkbox"/>
18	25/01/19 11:59	General View	 <a href="#">Load JPG</a>	<input checked="" type="checkbox"/>
19	25/01/19 11:59	General View	 <a href="#">Load JPG</a>	<input checked="" type="checkbox"/>
20	25/01/19 11:59	General View	 <a href="#">Load JPG</a>	<input checked="" type="checkbox"/>
21	25/01/19 11:59	General View	 <a href="#">Load JPG</a>	<input checked="" type="checkbox"/>
22	25/01/19 11:59	General View	 <a href="#">Load JPG</a>	<input checked="" type="checkbox"/>
23	25/01/19 11:59	General View	 <a href="#">Load JPG</a>	<input checked="" type="checkbox"/>
24	25/01/19 11:59	General View	 <a href="#">Load JPG</a>	<input checked="" type="checkbox"/>
25	25/01/19 11:59	General View	 <a href="#">Load JPG</a>	<input checked="" type="checkbox"/>
26	25/01/19 11:59	General View	 <a href="#">Load JPG</a>	<input checked="" type="checkbox"/>
27	25/01/19 11:59	General View	 <a href="#">Load JPG</a>	<input checked="" type="checkbox"/>
28	25/01/19 11:59	General View	 <a href="#">Load JPG</a>	<input checked="" type="checkbox"/>
29	25/01/19 11:59	General View	 <a href="#">Load JPG</a>	<input checked="" type="checkbox"/>
30	25/01/19 12:00	Photographs of Damaged Parts	 <a href="#">Load JPG</a>	<input checked="" type="checkbox"/>
31	25/01/19 12:00	Photographs of Damaged Parts	 <a href="#">Load JPG</a>	<input checked="" type="checkbox"/>
32	25/01/19 12:00	Photographs of Damaged Parts	 <a href="#">Load JPG</a>	<input checked="" type="checkbox"/>
33	25/01/19 12:00	Photographs of Damaged Parts	 <a href="#">Load JPG</a>	<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
34	25/01/19 12:00	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
35	25/01/19 12:00	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
36	25/01/19 12:00	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
37	25/01/19 12:00	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
38	25/01/19 12:00	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
39	25/01/19 12:00	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
40	25/01/19 12:00	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
41	25/01/19 12:00	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
42	25/01/19 12:00	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
43	25/01/19 12:00	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
44	25/01/19 12:00	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
45	25/01/19 12:00	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
46	25/01/19 12:00	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
47	25/01/19 12:00	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
48	25/01/19 12:00	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
49	25/01/19 12:00	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
50	25/01/19 12:00	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
51	25/01/19 12:00	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
52	25/01/19 12:00	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	17/01/19 08:29	TPD SMF9734X GIA REPORT From: SC - Reg. No: SKU87211, Claimant: LIM YEE FON DAVIDLIN YIFENG)	 Load PDF	
2	17/01/19 08:35	TPD SMF9734X - PRI	 Load PDF	
3	17/01/19 09:53	Reject email to TP Lawyer & appoint LKK AUTO	 Load PDF	

## Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
<b>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</b> <div style="border: 1px solid black; height: 100px; margin-top: 5px;"></div>			
<b>Show Remarks To:</b> <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/MSG19001086/GCD3E2

Date: 25/01/2019

## REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: 80410706

Claimant Vehicle No : SMF9734X

Insured Vehicle No : SKU8721J

Date of Loss: 13/01/2019

Nature of Claim: TP

Claim No: 582322

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No: SMF9734X

Make &amp; Model: TOYOTA VIOS, 1.5 E (A)

Engine No: 2NR5292027

Reg. Date: 30/11/2018 (Man. Year: 2018)

Chassis No: MR2B23F3901155333

Colour: Silver

Odometer: 6999 km

Engine Capacity: 1496 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

## CONDITION OF TYRES

Front Tyre Size: 185/60 R15

Rear Tyre Size: 185/60 R15

Front Left Side: Yokohama 9 mm

Rear Left Side: Yokohama 9 mm

Front Right Side: Yokohama 9 mm

Rear Right Side: Yokohama 9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Nett Amount (S\$)</b>	<b>0.00</b>	<b>0.00</b>	<b>0.00</b>	

## INSPECTION

Date of Assignment: 17/01/2019

Date Inspected: 22/01/2019 Inspected At:

Guan Auto Service (Sin Ming)  
Block 7 Sin Ming Industrial Estate Sector  
C, #01-80/ # 01-82  
Singapore 575642

Estimated Period of Repair: 4.0 days

Adjuster: XING GUO QIANG

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.  
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$2,000.00 - \$3,000.00

## REPAIR DETAILS

<b>Reference</b>		
<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 25 Jan 2019)
<b>Parts:</b>	143	TOYOTA VIOS 1.5 E (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SMF9734X)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

## Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.
---

< END OF ESTIMATES >