

2/03/2002

ASS. REC. BY:

REF:

083/MSG19001090/Bcd30

Special Instruction:

Surveyor

Mr. Jim

Menmen

ASSIGNMENT (Office)

From (Person): Chhia Nyuk Pui

of

MSIG

Date/Time: 17/1/19 @ 2.59pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLE9472T

Insured:

SJC 7425C

at Workshop m/s

Xin Yun Auto

Tel: 98391555

of

8 kaki Bukit Ave 4 # 05-23 premier

Policy No:

80455031

Claim No:

582324

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 13/01/2019

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

345pm @ 17/1/19

Person Contacted:

Yi Xin

Vehicle IN/OUT

Date/Time	Action/Instruction (X) Estimate
	SLE9472T-X
	SJC7425C-X
	Dismantle: 21/1/2019

REF: MSIG

ASSIGNMENT

From: Date: 18/01/2019

Estimated Cost:

OD/TP WS/TP RES/OD RES/EVA/INV/MV

To Inspect Vehicle No: SLE 9472T
 at Workshop m/s Xin Yun Auto
 of 8 kaki Bukit Ave 4 # 05-23
 Insured premier

Policy No.

Claims No.


Sum Insured: Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
 repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 4 days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS (up)

Vehicle: IN / OUT

Date: Person Contacted:

Veh No: SLE 9472T Yr Regn: 8/8/2016

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: TOYOTA SIENTA

C.C 1496

Colour: YELLOW

A/C: Insured / Std / NI / NA

Sp. Reading: 62552

T/Radio: Insured / Std / NI / NA

Eng/No: 2NR8651637

C/No: NSP1707044930

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 185/60/15

R: 185/60/15

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 6 mm

R/Bal. 6 mm

L/Bal. 6 mm

L/Bal. 6 mm

D.O.A. 13/1/19

D.O.I. 18/1/19

Survey held at XIN YUN AUTO

Des. of Damages: In / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction
 Range 4,000/- - 5,000/-

[Signature] 21/1/2019

MV 69,000/-

PV 53,189/-

NV 15,811/-

Tellim
 18/1/19

Date/Time, File Pass to?

☐ : Preli. Report

Days Of Repair: 4

1)

☐ : Final Report

Resurvey No. of Trip: 1

Survey Fee:

Date/Time, File Return to?

Transportation:

2)

Add Fee: ☐ : Site Insp (\$)

) S + RS SI

☐ : Interview (\$)

) Photos

☐ : Tech. Invs (\$)

) Others

☐ : Weekend (\$)

) ..

Report Format: PRS

Lump Sum / I.B.I: (\$)

TOTAL

130

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	16 Jan 2019		17 Jan 2019 14:59 Assign				New Assignment Cancel Case

[Main](#)
[Reference](#)
[Claim Details](#)
[Documents](#)
[Show All](#)

CLAIM SUBFOLDER DETAILS

[\[Created by insurer\]](#)

Insured:	SRIKANTH PARTHASARATHY, ID: S6984608D, Tel: +6591461845, Email: SHREEKCAN@GMAIL.COM		[Created by insurer]
Main Claimant:	TAN CHENG GUAN, ID: S0114937G		
Vehicle Reg. No.:	SLE9472T	Date of Loss:	13/01/2019 20:00 - :59 [29 Months and 5 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 582324	Policy/Cover Note No.:	80455031 (Comprehensive) Coverage: 09/03/2018 - 08/03/2019
Vehicle Reg. No. (Insured):	SJC7425C	Policy No. (Claimant):	
		Excess:	
Repairer:	Xin Yun Auto Pte Ltd (HQ) BLK 8 KAKI BUKIT AVE 4 #05-23 PREMIER @KAKI BUKIT, 415675 Kaki Bukit - Tel:		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Chhia Nyuk Pui - 6594 2521]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 18/01/2019]		
Driver/Custodian (Insured):	SRIKANTH PARTHASARATHY (49 / Male), NRIC: S6984608D, Tel: +6591461845		
Adj Asg. Remarks:	SURVEY DISAGREE ON SJE - ASSIGN LKK. LIABILITY:100% CONTACT: MS YI XIN 9839 1555		

ASSOCIATED MAIL RECEIVED

There are no mail for this case.

[View All](#)
[Compose Case Mail](#)

ALL ASSOCIATED TASKS

[View All](#)
[Search Tasks](#)
[Create New Task](#)
[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	4937G
Vehicle Details	
Vehicle No.:	SLE9472T
Vehicle to be Exported:	No
Intended Deregistration Date:	18 Jan 2019
Vehicle Make:	TOYOTA
Vehicle Model:	SIENTA 1.5G A
Primary Colour:	Yellow
Manufacturing Year:	2016
Engine No.:	2NR8651637
Chassis No.:	NSP1707044930
Maximum Power Output:	80.0 kW (107 bhp)
Open Market Value:	\$25,888.00
Original Registration Date:	08 Aug 2016
First Registration Date:	08 Aug 2016
Transfer Count:	0
Actual ARF Paid:	\$18,244.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	07 Aug 2026
PARF Rebate Amount:	\$13,683.00
Intended COE Rebate Details	
COE Expiry Date:	07 Aug 2026
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$52,301.00
COE Rebate Amount:	\$39,506.00
Total Rebate Amount:	\$53,189.00

The information contained herein is correct as at 18 Jan 2019

OK

Dep 8,690/yr

MV 69,000/2
PV 53,189/2
NV 15,811/2

CHEAPEST CAR INSURANCE RENEWAL



Fr Choice of bfe
\$0 excess

Option of any
workshop

GET A CHEAPER QUOTE NOW!

Post an Advertisement
Sell it yourself! Advertise it at just
\$58 until it's SOLD!

[Post an Ad](#)
[Advertiser Login](#)
[Ways of Selling](#)

2015 Toyota Camry 2.5A At \$82,380.



One Owner, Low Mileage, High
CDE Value, Fully Maintained By
Agent.
Direct Owner StarAd



Browse by Category ▼

32 vehicles

Toyota Sienta

Sort by Date Posted ▼

100 results/page ▼

Advanced Search 🔍

Make

Model

Price

Depreciation

Reg Date

Eng Cap

Mileage

Veh Type

Status

Search Selection

Toyota Sienta

Any

Any

2016

Any

Any

Any

All



Toyota Sienta 1.5A G

\$70,800

\$8,690 /yr

18-Aug-2016

1,496 cc

-

MPV

Available

G Model. Dual Power Doors And Led Front Info Display! Fast And Easy Approval! In House Loan Or Bank Loan Available! Easy And Flexible 100% Loan We Are sgCarMart Premium Dealer! Buy With Confidence! Al...

88 Motor Trading

Posted: 18-Jan-2019

Tags: 2016 Toyota Sienta, 2016 toyota sienta, Toyota Sienta, toyota sienta, Toyota, Sienta, sienta, Used Toyota



Toyota Sienta 1.5A G

\$68,800

\$8,780 /yr

26-Jan-2016

1,496 cc

46,300 km

MPV

Available

Elegant White MPV, One Owner Only, Low Mileage Done, With Power Sliding Door, Low Maintenance Cost, Very Well Maintained, Flexible In House Loan Packages Available.

Prime Motor & Leasing

Posted: 15-Jan-2019

Tags: 2016 Toyota Sienta, 2016 toyota sienta, Toyota Sienta, toyota sienta, Toyota, Sienta, sienta, Used Toyota



Toyota Sienta 1.5A G

\$67,800

\$8,660 /yr

26-Jan-2016

1,496 cc

55,585 km

MPV

Available

\$0 Downpayment Available With Terms Apply. \$1500 Of Pricing Incentive. High Loan Available. One Owner Only. 160 Point Assurance Check Done. No Repair Needed. Beautiful Interior With Elegance Black Ext...

Inchcape Pre-Owned

Posted: 14-Jan-2019

Tags: 2016 Toyota Sienta, 2016 toyota sienta, Toyota Sienta, toyota sienta, Toyota, Sienta, sienta, Used Toyota



Toyota Sienta 1.5A X

\$68,800

\$8,270 /yr

01-Nov-2016

1,496 cc

-

MPV


Available

Low Interest Rate From 1.99% And In-House Available! 1 Owner! Superb Condition And Very Well Maintained, Like New Car Condition, Extended Warranty Provided, High Trade In, Monthly At \$600 Plus Only! P...

Dickson Automobile

Posted: 13-Jan-2019

Tags: 2016 Toyota Sienta, 2016 toyota sienta, Toyota Sienta, toyota sienta, Toyota, Sienta, sienta, Used Toyota



Toyota rolls out P4 automated test vehicle

The bright lights of Las Vegas will once again shine on the Toyota Research Institute when it introduces the TRI-P4 automated driving test vehicle at CES.

Read this article



Toyota Sienta 1.5A G

\$68,800

\$8,170 /yr

30-Nov-2016

1,496 cc

51,000 km

MPV

Available

One Owner! Low Mileage! Flexible Loan Monthly From \$46X Onwards! High Approval Rate! Call The Assign Sales Person To Find Out More!

AL Autocar Pte Ltd

Posted: 13-Jan-2019

Tags: 2016 Toyota Sienta, 2016 toyota sienta, Toyota Sienta, toyota sienta, Toyota, Sienta, sienta, Used Toyota



Toyota Sienta 1.5A X

\$66,800

\$8,290 /yr

28-Jul-2016

1,496 cc

42,000 km

MPV

Available

Promotional 1.98% Interest Rate! 1 Owner. Well Maintained. Pristine Pearl White Paintwork, Fitted With Black Leather With Orange Trims. Most Economical MPV In The Market Right Now. Enough Seats For Yo...

Auto Zoom Enterprise Pte Ltd

Posted: 13-Jan-2019

Tags: 2016 Toyota Sienta, 2016 toyota sienta, Toyota Sienta, toyota sienta, Toyota, Sienta, sienta, Used Toyota

Toyota Sienta 1.5A G

\$66,800

\$8,290 /yr

03-Jun-2016

1,496 cc

61,000 km

MPV

Available

Loan Available, Monthly From \$550, High Approval Rate, Careful Owner, No Repairs Needed, Comes With 1 Year Engine And Gearbox Protection View To Appreciate, High Trade In, Please Call Or ...

Compare

[Compare](#)

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	14/01/2019 12:07
Date Of Accident	13/01/2019 20:00
Exact Location Of Accident	252 JURONG EAST ST 24 CARPARK
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLE9472T
Insured/Policyholder	
Name Of Registered Owner	TAN CHENG GUAN
NRIC No	S0114937G
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-96328559
Alternative Phone No	OTHERS-96328559

Vehicle Particulars

Manufacturer	TOYOTA
Model	SIENTA-1.5 G (A)
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	LIBERTY INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	SD18V07940/VPC/R00
Cover Note Number	

Driver

Name of Driver	TAN CHENG GUAN
NRIC No	S0114937G
Date Of Birth	05/09/1954
Occupation	INDOOR
Date Of Driving Pass	08/06/1976
Driving Experience	42 YEARS AND 7 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-96328559
Fax Number	
Contact Number	OTHERS-96328559
EMail Address	NOEMAIL

Address	BLK 201 CLEMENTI AVE 6 #01-23
Postcode	120201
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	HIT AND RUN / VANDALISM / DAMAGED WHILST PARKED
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	NO
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	0

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	CLEMENTI N.P.C
Police Station Address	ROAD: 20 CLEMENTI AVE 5 , POSTCODE: 129858 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: - FAX NO:
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

ON 13/01/2019 ABOUT 8PM AT 252 JURONG EAST ST 24 CARPARK, MY CAR SLE9472T WAS STATIONARY AT CAR PARK. THE VEHICLE SJC7425C REVERSING AND HIT MY VEHICLE SLE9472T FRONT BUMPER AND LIGHT. I HAVE 2 WITNESS FOR THIS ACCIDENT WITH VIDEO. PLEASE REFER TO POLICE REPORT ATTACHED.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SJC7425C
Vehicle Make/Model/Colour	TOYOTA WISH
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d), above may be shared / disclosed:
 - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:

14/1/19 @ 12:00
GIA Form 1 (Rev. 11/13)

Driver's Signature
(If driver is not the policyholder)
Date & Time:


14/1/19 @ 12:00



Reporting Centre Personnel's Signature
Name: Melody Teoh
NRIC/FIN No.:

S8526524E

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 13/01/2019 about 8:00 pm at 252 Jurong East St 24 carpark. My car was stationary at car park. the vehicle SSC 7425C reversing and hit my vehicle SLE 9472T front bumper & light.

I have 2 witness for this accident with video.

please refer to police report attached.

Name: <u>Tan Cheng Guan</u>	
(Driver / In-Charge / Owner)	
NRIC no: <u>S0114937G</u>	
Vehicle No: <u>SLE 9472T</u>	Company Stamp for Company registered vehicle
I/We hold my/their vehicle damaged vehicle as	
Company name: <u>Xin Yun Auto</u>	
For my vehicle damage repairs and insurance claim.	
GAE had clearly informed me on new GAE rules.	
I accept the conditions and discharge GOLDBELL Engineering Pte Ltd. from all accident claimant report.	

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time: 14/1/19
@ 12:00

Driver's Signature
(If driver is not the policyholder)
Date & Time: 14/1/19 @
12:00

GOLDBELL ENGINEERING PTE LTD
Reporting Centre Personnel's Signature
Name: Melody Teoh
NRIC/FIN No.: S8526524E



































...CLAIM SUBFOLDER...(Pending for Survey Report)



























CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	16 Jan 2019		17 Jan 2019 14:59 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured: SRIKANTH PARTHASARATHY , ID: S6984608D, Tel: +6591461845, Email: SHREEKCAN@GMAIL.COM									
Main Claimant: TAN CHENG GUAN , ID: S0114937G									
Vehicle Reg. No.: SLE9472T		Date of Loss: 13/01/2019 20:00 - :59 [29 Months and 5 Days From LTA Reg Date (Man Yr)]							
Claim Type: TP / 582324		Policy/Cover Note No.: 80455031 (Comprehensive) Coverage: 09/03/2018 - 08/03/2019							
Vehicle Reg. No. (Insured): SJC7425C		Policy No. (Claimant): Excess:							
Repairer: Xin Yun Auto Pte Ltd (HQ) BLK 8 KAKI BUKIT AVE 4 #05-23 PREMIER @KAKI BUKIT, 415675 Kaki Bukit - Tel:									
Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Chhia Nyuk Pui - 6594 2521]									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by Lim Teow Guan] ... [Imm.Advice due 18/01/2019]									
Driver/Custodian (Insured): SRIKANTH PARTHASARATHY (49 / Male), NRIC: S6984608D, Tel: +6591461845									
Adj Asg. Remarks: SURVEY DISAGREE ON SJE - ASSIGN LKK. LIABILITY:100% CONTACT: MS YI XIN 9839 1555									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SLE9472T (582324)**
[SJC7425C]
TP
TAN CHENG GUAN
Jan 13 2019 8:00PM
[SRIKANTH PARTHASARATHY]
Xin Yun Auto Pte Ltd

Upload Documents Upload Photos Compose New Letter			View View in Browser	
Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	16/01/19 16:00	Accident Statement From: SC - Reg. No: SJC7425C, Claimant: SRIKANTH PARTHASARATHY	 Load HTM	
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	23/01/19 11:31	General View	 Load JPG	<input checked="" type="checkbox"/>
2	23/01/19 11:31	General View	 Load JPG	<input checked="" type="checkbox"/>
3	23/01/19 11:31	General View	 Load JPG	<input checked="" type="checkbox"/>
4	23/01/19 11:31	General View	 Load JPG	<input checked="" type="checkbox"/>
5	23/01/19 11:31	General View	 Load JPG	<input checked="" type="checkbox"/>
6	23/01/19 11:31	General View	 Load JPG	<input checked="" type="checkbox"/>
7	23/01/19 11:31	General View	 Load JPG	<input checked="" type="checkbox"/>
8	23/01/19 11:31	General View	 Load JPG	<input checked="" type="checkbox"/>
9	23/01/19 11:31	General View	 Load JPG	<input checked="" type="checkbox"/>
10	23/01/19 11:31	General View	 Load JPG	<input checked="" type="checkbox"/>
11	23/01/19 11:31	General View	 Load JPG	<input checked="" type="checkbox"/>
12	23/01/19 11:31	General View	 Load JPG	<input checked="" type="checkbox"/>
13	23/01/19 11:31	General View	 Load JPG	<input checked="" type="checkbox"/>
14	23/01/19 11:31	General View	 Load JPG	<input checked="" type="checkbox"/>
15	23/01/19 11:31	General View	 Load JPG	<input checked="" type="checkbox"/>
16	23/01/19 11:31	General View	 Load JPG	<input checked="" type="checkbox"/>
17	23/01/19 11:31	General View	 Load JPG	<input checked="" type="checkbox"/>
18	23/01/19 11:31	General View	 Load JPG	<input checked="" type="checkbox"/>
19	23/01/19 11:31	General View	 Load JPG	<input checked="" type="checkbox"/>
20	23/01/19 11:31	General View	 Load JPG	<input checked="" type="checkbox"/>
21	23/01/19 11:31	General View	 Load JPG	<input checked="" type="checkbox"/>
22	23/01/19 11:31	General View	 Load JPG	<input checked="" type="checkbox"/>
23	23/01/19 11:31	General View	 Load JPG	<input checked="" type="checkbox"/>
24	23/01/19 11:31	General View	 Load JPG	<input checked="" type="checkbox"/>
25	23/01/19 11:31	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
26	23/01/19 11:31	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
27	23/01/19 11:31	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
28	23/01/19 11:31	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
29	23/01/19 11:31	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
30	23/01/19 11:31	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
31	23/01/19 11:31	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
32	23/01/19 11:31	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
33	23/01/19 11:31	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
34	23/01/19 11:31	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
35	23/01/19 11:31	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
36	23/01/19 11:31	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
37	23/01/19 11:31	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
38	23/01/19 11:31	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
39	23/01/19 11:31	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
40	23/01/19 11:31	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
41	23/01/19 11:31	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
42	23/01/19 11:31	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
43	23/01/19 11:31	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
44	23/01/19 11:31	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
45	23/01/19 11:31	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
46	23/01/19 11:31	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
47	23/01/19 11:31	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
48	23/01/19 11:31	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
49	23/01/19 11:31	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
50	23/01/19 11:31	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
51	23/01/19 11:31	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
52	23/01/19 11:31	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
53	23/01/19 11:31	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
54	23/01/19 11:31	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
55	23/01/19 11:31	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
56	23/01/19 11:31	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	16/01/19 16:00	SLE9472T TP E-FILE REPORT From: SC - Reg. No: SJC7425C, Claimant: SRIKANTH PARTHASARATHY	 Load PDF	
2	16/01/19 16:01	EMAIL FROM TP TO ARRANGE SURVEY	 Load PDF	
3	17/01/19 13:42	SURVEY DISAGREE ON SJE - ASSIGN LKK	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/MSG19001090/BCD3E2

Date: 23/01/2019

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: 80455031

Claimant Vehicle
No : SLE9472T

Insured Vehicle No : SJC7425C

Date of Loss: 13/01/2019

Nature of Claim: TP Claim No: 582324

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SLE9472T

Make & Model: TOYOTA SIENTA, 1.5 G (A)

Engine No: 2NR8651637

Reg. Date: 08/08/2016 (Man. Year: 2016)

Chassis No: NSP1707044930

Colour: Yellow

Odometer: 62552 km

Engine Capacity: 1496 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 185/60 R15

Rear Tyre Size: 185/60 R15

Front Left Side: Michelin 6 mm

Rear Left Side: Michelin 6 mm

Front Right Side: Michelin 6 mm

Rear Right Side: Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 17/01/2019

Date Inspected: 18/01/2019 Inspected At:

Xin Yun Auto Pte Ltd (HQ)
BLK 8 KAKI BUKIT AVE 4 #05-23
PREMIER @KAKI BUKIT
Singapore 415675

Estimated Period of Repair: 4.0 days

Adjuster: Lim Teow Guan

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$4,000.00 - \$5,000.00

REPAIR DETAILS

Reference

Part Source: MRM-SG **Version:** 1.0 (Last Synchronised: 23 Jan 2019)

Parts: M1-MPV TOYOTA SIENTA 1.5 G (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SLE9472T)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >