



Your Ref: DM18HO01795-JG

Date: 22nd January 2019

Our Ref: CS1/EQI19001094/Eqd3s2

M/s EQ Insurance Company Ltd

5 Maxwell Road
#17-00 Tower Block
MND Complex
Singapore 069110
(The Motor Claims Department)

Dear Sir / Madam,

EVALUATION REPORT (PAPER SURVEY) OF ACCIDENT VEHICLE NO:

SJJ 3282L

INSURED VEHICLE: SJF 3924P

ACCIDENT DATE: 16/07/2018

We thank you for your instruction on 17/01/2019.

We acknowledge receipt of the following documents:-

- a) Automobile Inspection Report of SJJ 3282L from M/s Automax Survey.
- b) Singapore Accident Statement of Vehicles SJJ 3282L and SJF 3924P.
- c) Colour damaged vehicle photographs of SJJ 3282L.

Based on the documents received from you, we have evaluated the damages of the vehicle and have the following comments:-

1. Information Recorded: -

Registration Number	: SJJ 3282L
Make & Model	: Toyota Wish 1.8A
Year of Registration	: 2009
Chassis Number	: JTDER12W603002451
Engine Capacity	: 1794 cc

2. We recommend that the repairs of the entire damage require about 3 (Three) working days to complete.
3. We hereby provide our recommendations on the cost of repair to the damaged vehicle as stated in the following page.