



Your Ref: MC20182880

Date: 21st January 2019

Our Ref: CS1/III19001105/Esd3s2

M/s India International Insurance Pte Ltd

64 Cecil Street

#05-02 IOB Building

Singapore 049711

(The Motor Claims Department)

Dear Sir / Madam,

EVALUATION REPORT (PAPER SURVEY) OF ACCIDENT VEHICLE NO:

SLG 6634C

INSURED VEHICLE: XD 5563D

ACCIDENT DATE: 01/11/2018

We thank you for your instruction on 17/01/2019.

We acknowledge receipt of the following documents:-

- a) Automobile Inspection Report of SLG 6634C from M/s NTUC Income Co-Operative Ltd.
- b) Final Repair Bill of SLG 6634C from M/s Hwa Seng Spray Painting Co.
- c) Singapore Accident Statement of Vehicles SLG 6634C and XD 5563D.
- d) Colour damaged vehicle photographs of SLG 6634C.

Based on the documents received from you, we have evaluated the damages of the vehicle and have the following comments:-

1. Information Recorded: -

Registration Number	: SLG 6634C
Make & Model	: Toyota Corolla Altis
Year of Registration	: 2016
Chassis Number	: MR053REH104558648

2. We recommend that the repairs of the entire damage require about 7 (Seven) working days to complete.
3. We hereby provide our recommendations on the cost of repair to the damaged vehicle as stated in the following page.