Surveyor: Tanjin | REF: ALH | 1114/216

ASSIGNMENT

From: | Date: 01/02/2019

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SMG 7446K

at Workshop m/s: Performance

of: 303 Alexandra Rd

Insured:

Policy No.

Claims No.

Sum Insured: | Excess:

(Client's Record)

Make of Veh: Gary

(Policy Condition)

N/S	O/S
	X

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rport: | Consistent? : Yes or No

GIA / PR Seen: | Consistent? : Yes or No

Est. Repairs: days | Res.: Yes or No

Lum Sum: % | 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: | Person Contacted:

Veh No: SMG 7446K. | Yr Regn: 2018 Nov.

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer or

Make: BMW 520I | c.c: 1998.

Colour: Black. | A/C: Insured / Std / NI / NA

Sp.Reading: 1276. | T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: WBAJA12000BJ20788

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi : Nil / S/Rim / STD A/Rim or

Tyre Size: F: 275/40R18

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front		Rear	
R/Bal.	6 mm	R/Bal.	6 mm
L/Bal.	6 mm	L/Bal.	6 mm
D.O.A.		D.O.I.	01/02/19 @ 230pm

Survey held at: DML

Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction

Date/Time, File Pass to?

1)

Date/Time, File Return to?

2)

☐ : Preli. Report

☐ : Final Report

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

Add Fee: ☐ : Site Insp ($) ___S + RS___SI

☐ Interview ($) Photos

☐ Tech. Invs ($) Others

☐ Weekend ($)

TOTAL

Report Format :

Lump Sum / I.B.I: ($)