

INS. CASE OWNER:

CC 3, AG 1900

1114, Tihay

LKK:  
IDAC:

Surveyor:

TAUMIKH

DOI:

ASSIGNMENT

01102/19

Date / Time:

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

SKA 4404G

Name of Insured:

CHEE CHEE SENG

Insured Tel No.:

HP:

Excess Sec II :SS

D.O.A:

16/1/19

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

Driver Tel No.:

(V/L: YES / NO)

Claim No.:

Policy No.:

Make / Model:

Place of Accident:

198

OI GIA REPORT: YES / NO : TP GIA REPORT: YES / NO

Insured Liability: %

Final ? Yes / No



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/ Time

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

S\$ 3,988.80 ( 3 days) Reduction: 42 %

Email ☐ Call ☐

FINAL SETTLEMENT

Date/Time:

Confirm with:

Email ☐ Call ☐

Final Liability:

% 100 (Agreed / Assessed) BOLA S/N No.:

If NO or B 28, Ass. Lia:

Repair Cost:

S\$ 4,268.02

COI (KARL-ROBERT TP)

Loss of Rental (LOR):

S\$ - ( days)

Loss of Use (LOU):

S\$ 360.00 (\$120 x 3 days) - 1998.00

Loss of Income (LOI):

S\$ - (\$ x days)

LOR only ☐ LOU only ☒LOR + LOU ☐ LOR + LOI ☐ [Tick only one]

GIA/LTA Search

S\$ 2.00

Medical:

S\$ -

Disbursement:

S\$ -

(e.g. Tow/ Independent)

Legal Cost

S\$ -

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:

\$320.00

Total:

S\$ 4,630.02

Global Sum S\$:

FINAL PAYMENT

Date/Time:

Confirm with:

Email ☐ Call ☐

Payee 1:

S\$ 4,630.02

Name 1:

PERFORMANCE MOTORS LIMITED

Payee 2: (Strike if N/A)

S\$ -

Name 2:

Payee 3: (Strike if N/A)

S\$ -

Name 3:

Tanpin

REF: ALH

114/110

# ASSIGNMENT

Form: Date: 01022019

Estimated Cost:

OD: TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: 9MG 7446K  
at Workshop no: Performance  
of: 303 Alexandra Rd

Insured:

Policy No:

Claims No:

Sum Insured: Excess:


(Client's Record)

Make of Veh:

Gary

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Report: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 3 days Res: Yes or No

Lump Sum: % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Vehicle IN / OUT

Date: Person Contacted:

Veh No: 9MG 7446K- Ty Reg: 2018 NSW

Type: M/C / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: BMW 520i CC: 1998

Colour: Black A/C: Insured / Std / NI / NA

Sp Reading: 1276 T/Ratio: Insured / Std / NI / NA

Eng/No:

C/Nr: WBAJA120005320788

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / STD / STD A/Rim or

Tyre Size F: 275/40R18 R: 275/40R18

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal: 6 mm R/Bal: 6 mm

L/Bal: 6 mm L/Bal: 6 mm

D.O.A.

D.O.A.

Survey held at:

PM L

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time: Action / Instruction:

P/P \$3,988.80  
(Exp: \$2,912.75 / 42%)

Date/Time: File Pass to:

☐ : Prel. Report  
☐ : Final Report

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

1. 3 x R100

2. 1 x R100

3. 1 x R100

4. 1 x R100

5. 1 x R100

6. 1 x R100

7. 1 x R100

8. 1 x R100

9. 1 x R100

Report Format:

Lump Sum / LB F/S

Add Fee: ☐ Site Insp. \$5  
☐ Interview \$5  
☐ Tech. Insp. \$5  
☐ Weekend \$5

## Performance Motors Limited

A member of the Sime Darby Group

Co. Reg. No. 197401335W GST Reg. No. M2-0020081-X

303, Alexandra Road  
Sime Darby Performance Centre  
Singapore 159941  
Tel. 63190100 (Sales & Admin)  
63190111 (AfterSales)  
Fax. 64747770

280, Kampong Arang Road  
East Coast Centre  
Singapore 438180  
Tel. 63190888 (AfterSales)  
Fax. 63449773

315, Alexandra Road  
Sime Darby Business Centre  
Singapore 159944  
Tel. 63190518 (AfterSales)  
63190533/330 (Motorrad)  
Fax. 64796601 (AfterSales)  
64796624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

## ESTIMATE

16 JAN 2019

Estimate No. : b1 49783  
Date Estimated : 16/01/2019  
Prepared By : Gary Poh Chai Hoon

Page No. : 1 of 5

- ESTIMATE REPAIR FOR -  
Performance Premium Selection Ltd  
280 Kampong Arang Road  
East Coast Centre

Singapore 438180

- ACCOUNT - 40000  
Cash Sales - Service  
Singapore

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SMG7446K	BJ20788	30/11/2018	520i	0

## DESCRIPTION

To replace rear bumper and attachment cause by the accident.

Painting rear bumper

To check electrical wiring systems and lightings at the rear section for proper function.

Sundries. *nu*

## VALUE

850 1,700.00 ✓

934 1,038.00 ✓

150 177.00 ✓

? 80.00 ✓

Total Labour 1: 2,995.00

## DESCRIPTION

REAR BUMPER CARRIER  
REAR BUMPER TOWING EYE FLAP (M)  
EXHAUST SUPPORT  
REAR BUMPER COVER (M)  
REAR BUMPER LH GUIDE (M)  
REAR BUMPER RH GUIDE (M)  
REAR BUMPER CENTRE GUIDE (M)  
REAR BUMPER PANEL PRIMED (M)  
UNDERBODY PANELLING REAR  
REAR RH REAR REFLECTOR  
Ultrasonic s  
DECOUPING RING PDC TORQUE CONVERTER

## QTY PRIC

1 857.75  
1 81.55  
1 48.65  
1 187.95  
1 55.75  
1 55.75  
1 61.55  
1 1,691.65  
1 41.30  
1 37.90  
2 380.65  
4 5.05

## VALUE

unx 857.75

unx 81.55

de 48.65

de 187.95

X unx 55.75

X 55.75

X 61.55

de 1,691.65

de 41.30

unx 37.90

unx 761.30

unx 20.20

Total Parts : 3,901.30

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM \_\_\_\_\_

**AIG THIRD PARTY EXPRESS SETTLEMENT**  
**FOR ACCIDENTS ON OR AFTER 1ST JUNE 2008**  
**(PAYMENT BREAKDOWN)**

Vehicle No:	SMG 7446K	Model:	
Date of Accident:	16-1-2019		

Global Sum Settlement	: <input type="checkbox"/> Yes	: <input type="checkbox"/> No	
Repair Estimate	: \$	7379.04	
Final Repair Cost	: \$	4268.02	
Loss of Use	: \$	360.00	3 days at \$ 120 per day
Rental (if any)	: \$		days
LTA / GIA Search Fee	: \$	2.00	
Others:	: \$		
	: \$		
Final Settlement Sum	: \$	4630.04	
Is Third Party Workshop GIA Registered? <input type="checkbox"/> YES <input type="checkbox"/> NO (Kindly indicate below)			
A) For Non GIA Registered Workshop: Agreed Liability _____ (%)			
B) For GIA Registered Workshop: BOLA Applicable: Yes/ No			
BOLA Scenario No: _____			
BOLA Liability: _____ (%)		Assessed Liability (*): _____ (%)	
* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.			
Remarks			

Payment Instruction: Payee's Breakdown			
1)	Performance Motors Ltd	: \$	4268.02
2)	Performance Motors Ltd	: \$	360.00
3)	Performance Motors Ltd	: \$	2.00

Signed by appointed surveyor \_\_\_\_\_

Date \_\_\_\_\_

Please attach all the supporting documents to the form.  
 (Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act;  
 Survey Report; Medical Report/ Bill (if any))



**SINGAPORE  
POLICE FORCE**

TRAFFIC POLICE  
SINGAPORE POLICE FORCE  
10, UBI AVENUE 3  
SINGAPORE 408865  
Tel : 65470000  
[www.police.gov.sg](http://www.police.gov.sg)



*class 3 - 15/DEC/2008*

**Private & Confidential**

NEOH WEE LEE

APT BLK 288A COMPASSVALE CRESCENT #12-371  
SINGAPORE 541288

You will receive your photocard driving licence by registered post within 10 to 14 working days from the date of application unless you made a special request to collect at Traffic Police at the time of application

You can drive while awaiting the delivery of your photocard driving licence

Please turn overleaf for important notes.

**YOU CAN DRIVE WHILE AWAITING THE  
DELIVERY OF YOUR PHOTOCARD  
DRIVING LICENCE**

S7864613F  
(3)

C001455316

\$25/-

(Please do not detach)

16/01/2019

### IMPORTANT NOTES

1. To check the delivery status of your photocard driving licence, you may visit the following webpage

<http://www.police.gov.sg/e-services>

### FOR NEW DRIVING LICENCE HOLDER

2. Your driving licence is now placed on one-year probation.
3. Please be reminded that your driving licence will be revoked for a period of one-year if you fail to display the P-plate sign twice or accumulated 13 or more demerit points within the first 12 months from the date your driving licence was issued.
4. If your driving licence is revoked, you are required to pass the prescribed tests of competency (theory and practical) before you can be issued with a new driving licence.

(Please do not detach)

**AUTHORISATION TO ACT**  
**(AIG Express Third Party Claim)**


I, PERFORMANCE MOTORS LIMITED (the third party claimant) of 303 ALEXANDRA ROAD  
PERFORMANCE CENTRE S 159941 (address), owner of SMG 7446K (vehicle no.)  
hereby authorize PERFORMANCE MOTORS LIMITED ("the workshop") to act for me  
with respect to my claim for repair costs and/or rental and/or loss of use ("claim") for my vehicle  
no. SMG 7446K that was damaged pursuant to the accident which occurred on 16/1/14  
(date) along 10PE TOWARDS MCE NMR PIE EXIT (location) involving vehicle no/s  
SKA 4404 G ("the accident").


I further authorize the workshop to settle my above mentioned claim in a manner that they deem fit  
and the workshop is further authorized to receive payment further to settlement of my claim with  
payment cheque/s being made in favour of the workshop.

I further acknowledge that any settlement the workshop may reach on my behalf is on a without  
prejudice and without admission of liability basis insofar as the driver/owner/insurers of the other  
vehicle/s is concerned.

Dated this \_\_\_\_\_ (day) of \_\_\_\_\_ (month) 20\_\_\_\_ (year)

PERFORMANCE MOTORS LIMITED  
303 Alexandra Road  
Sinas Dairy Performance Centre  
Singapore 159941  
TEL: 63162100 (Sales)  
63162111 (Afternoon)

  
Signed by "the third party claimant"  
(with chop if applicable)

  
Signed by "the workshop"  
(with chop)





Auto  
Consultants  
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

28 JANUARY 2019

**SHEK CHEE SENG  
143 DUCHESS AVENUE  
SINGAPORE 269167**

**By Post and By Email**

Dear Sir/Madam,

**OUR REF : CC3/AIG19001114/ha3  
YOUR REF : SKA 4404G  
ACCIDENT INVOLVING SKA 4404G AND SMG 7446K ALONG KPE TOWARDS PIE  
ON 16.01.2019**

We refer to the above subject matter. We write to inform you that we are the loss adjuster appointed by your motor insurer, AIG Asia Pacific Insurance Pte Ltd to deal with the third party claim against your policy.

We have received a claim from Body Repairer/Workshop acting on behalf of the owner of SMG 7446K against your motor insurance policy.

Based on the accident report and accident scenario, it was reported that your vehicle had collided to the Third-Party vehicle SMG 7446K. As such, liability may not be on your favour.

Please be informed that your No Claim Discount (NCD – if any) may be affected as a result of the claim against your policy.

We shall proceed to deal with the claim(s) subject to the merits of the case and according to the rights afforded under the policy. Should you not be seeking the protection of your policy and seek to take conduct of third party claim(s) arising from this incident, at your own cost and defense, please reply to us within 10 days from the date of this letter.

Your full co-operation in the handling of the claim is required and kindly submit the following to [vicalpeh@lkkauto.com](mailto:vicalpeh@lkkauto.com) within 10 days from the date of this letter **if not provided at AIG's reporting centre**. The list below is not all inclusive and further document may be required:

- Police report, Police Investigation result, appeal against the Traffic Police offence and status (if any)
- Driver's driving license or foreign driving license (if any)
- Coloured photographs of accident scene (if any)
- Coloured photographs of damage to all vehicles involved (If any)
- Video footage of accident (if any)





Auto  
Consultants  
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

- Statement and/or police report from independent witness(es) (if any)
- If you or your passenger(s) are filing a claim against any of the involved Third Party(s), you are to keep us informed of your legal representative(s) and the status of the claim

To protect your interest(s) in the handling of this claim, please do not discuss liability with any of the Third Party(s) and/or their legal representatives, or make any compromise or settlement without AIG's prior knowledge and consent.

This letter should **not** be regarded as a waiver by AIG of their rights to repudiate any claim because of any breach of policy terms and conditions you and/or your authorised driver may have committed.

In the event of receiving and handling of any third party injury claim(s), AIG shall keep you informed of the final indemnity upon conclusion of the matter(s).

If you need any clarification, please do not hesitate to contact us at 6256 3561 or email us at [vicalpeh@lkkauto.com](mailto:vicalpeh@lkkauto.com).

Please quote the claim reference when you contact us that we can assist you more effectively.

Yours sincerely,



Vic Alpeh  
Case Handler  
DID: 6841 2096  
FAX: 6741 4108  
Email: [vicalpeh@lkkauto.com](mailto:vicalpeh@lkkauto.com)

c.c. AIG Asia Pacific Insurance Pte Ltd  
(Motor Claims Dept)

[shekcheeseng@hotmail.com](mailto:shekcheeseng@hotmail.com)  
(Email)

## Vic (LKKAUTO)

---

**From:** Vic (LKKAUTO)  
**Sent:** Monday, 28 January, 2019 1:46 PM  
**To:** shekcheeseng@hotmail.com  
**Cc:** Admin A; Vic (LKKAUTO)  
**Subject:** YOUR REF: SKA 4404G\_ACCIDENT INVOLVING SKA 4404G AND SMG 7446K ALONG KPE TOWARDS PIE ON 16.01.2019



51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

28 JANUARY 2019

**SHEK CHEE SENG  
143 DUCHESS AVENUE  
SINGAPORE 269167**

**By Post and By Email**

Dear Sir/Madam,

**OUR REF : CC3/AIG19001114/ha3**

**YOUR REF : SKA 4404G**

**ACCIDENT INVOLVING SKA 4404G AND SMG 7446K ALONG KPE TOWARDS PIE ON 16.01.2019**

We refer to the above subject matter. We write to inform you that we are the loss adjuster appointed by your motor insurer, AIG Asia Pacific Insurance Pte Ltd to deal with the third party claim against your policy.

We have received a claim from Body Repairer/Workshop acting on behalf of the owner of SMG 7446K against your motor insurance policy.

Based on the accident report and accident scenario, it was reported that your vehicle had collided to the Third-Party vehicle SMG 7446K. As such, liability may not be on your favour.

Please be informed that your No Claim Discount (NCD – if any) may be affected as a result of the claim against your policy.

We shall proceed to deal with the claim(s) subject to the merits of the case and according to the rights afforded under the policy. Should you not be seeking the protection of your policy and seek to take conduct of third party claim(s) arising from this incident, at your own cost and defense, please reply to us within 10 days from the date of this letter.

Your full co-operation in the handling of the claim is required and kindly submit the following to [vicalpeh@lkkauto.com](mailto:vicalpeh@lkkauto.com) within 10 days from the date of this letter **if not provided at AIG's reporting centre**. The list below is not all inclusive and further document may be required:

- Police report, Police Investigation result, appeal against the Traffic Police offence and status (if any)
- Driver's driving license or foreign driving license (if any)
- Coloured photographs of accident scene (if any)
- Coloured photographs of damage to all vehicles involved (if any)
- Video footage of accident (if any)
- Statement and/or police report from independent witness(es) (if any)

- If you or your passenger(s) are filing a claim against any of the involved Third Party(s), you are to keep us informed of your legal representative(s) and the status of the claim

To protect your interest(s) in the handling of this claim, please do not discuss liability with any of the Third Party(s) and/or their legal representatives, or make any compromise or settlement without AIG's prior knowledge and consent.

This letter should **not** be regarded as a waiver by AIG of their rights to repudiate any claim because of any breach of policy terms and conditions you and/or your authorised driver may have committed.

In the event of receiving and handling of any third party injury claim(s), AIG shall keep you informed of the final indemnity upon conclusion of the matter(s).

If you need any clarification, please do not hesitate to contact us at 6256 3561 or email us at [vicalpeh@lkkauto.com](mailto:vicalpeh@lkkauto.com).

Please quote the claim reference when you contact us that we can assist you more effectively.

Best Regards,

**Vic Alpeh** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6841-2096 | email: [vicalpeh@lkkauto.com](mailto:vicalpeh@lkkauto.com) | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Auto  
Consultants  
Pte Ltd

*Save the Earth. Print only when necessary.*

This e-mail contain confidential and privileged material, and are for the sole use of the intended recipient. Use or distribution by an unintended recipient is prohibited, and may be a violation of law. If you believe that you received this e-mail in error, please do not read this e-mail or any attached items. Please delete the e-mail and all attachments, including any copies thereof, and inform the sender that you have deleted the e-mail, all attachments and any copies thereof. Thank you.

**RELEASE VOUCHER**  
**(AIG Express Third Party Claim)**

"We/I, Performance Motors Ltd ("the workshop") hereby confirm that we/I have reached an agreement with the appointed surveyor of AIG Asia Pacific Insurance Pte Ltd LKK AUTO CONSULTANTS PTE LTD (name of surveyor) with respect to the amount claimed for SS 4268.00 (Repair Cost), SS 360.00 (Loss of ~~rental~~/use), SS 2.00 (Disbursement), for vehicle no. SMG7446K that was damaged pursuant to the accident which occurred on 16.1.19 (date) along KPE towards MCE near PIE Exit (location) involving vehicle no/s SKA4404G. This is pursuant to the inspection conducted on 1.2.19 (date) at "the workshop".

We/I confirm that we/I are/am authorized by the owner Performance Motors Ltd ("the third party claimant") of vehicle no. SMG7446K make the claim as set out in the above paragraph and we/I have full authority to settle the matter on his/her behalf in a manner that we/I deem fit. We/I enclose herein the letter of authority given by "the third party claimant".

We/I further confirm that we/I will indemnify AIG Asia Pacific Insurance Pte Ltd for all damages, loss and/or expense that they will or have already incurred in the event that "the third party claimant" after the above said agreement lodges a further claim against the former for any loss and expenses suffered pertaining to costs of repairs and/or rental and/or loss of use pursuant to the damage to SMG7446K (vehicle no.) as a result of the accident.

We/I confirm that the agreement reached above is in full and final settlement of any claim of "the third party claimant" pursuant to the accident and that further this settlement is reached on a without prejudice and without admission of liability basis.

This agreement is subject to the application of Singapore law and the Singapore Courts have exclusive jurisdiction over any dispute arising out of the same.

Dated this 10 (day) of 04 (month) 2019 (year)



Signed by appointed surveyor

Signed by "the workshop" (with chop)

## Performance Motors Limited

A member of the Sime Darby Group  
Co. Reg. No. 197401559W GST Reg. No. M2-0920081-X



103, Alexandra Road  
Sime Darby Performance Centre  
Singapore 159941  
Tel. 63190100 (Sales & Admin)  
63190111 (AfterSales)  
Fax. 64747770

280, Kampong Arang Road  
East Coast Centre  
Singapore 438180  
Tel. 63180886 (AfterSales)  
Fax. 63449773

115, Alexandra Road  
Sime Darby Business Centre  
Singapore 159944  
Tel. 63190538 (AfterSales)  
63190533/535 (Motorrad)  
Fax. 64794601 (AfterSales)  
64794624 (Motorrad)

## SERVICE TAX INVOICE

Repair Order No. : B1 1335878

Date IN : 08/02/2019

Cust. Svc. Advisor: Gary Poh Chai Hoon

Page No. : 1 of 2

Invoice Number : 2081865 / WSB

Invoice Date : 28/03/2019

Payment Terms : 30 Days From Invoice

Invoice By : Sharon Heng

## - CUSTOMER INFORMATION -

Performance Premium Selection Ltd  
280 Kampong Arang Road  
East Coast Centre  
  
Singapore 438180

## - INVOICE TO - 121

AIG Asia Pacific Insurance Pte. Ltd.  
78 Shenton Way  
#08-16 Chartis Building  
Singapore 079120

REGN. NO.  
SMG7446K

CHASSIS NO.  
BJ20788

REGN. DATE  
30/11/2018

MODEL  
520I

MILEAGE  
1276

## - - - - LABOUR 1 - - - -

To replace rear bumper and attachments including to  
remove and install body parts in order to carry out painting  
job.

To respray rear bumper.

To check electrical wiring systems and lightings at the  
rear section for proper function.

Sundries.

INS CLAIMS : ACCIDENT REPAIR. DIRECT SETTLEMENT.

DATE OF ACCIDENT : 16.1.2019. 3RD PARTY CAR :SKA4404G.

YOUR REF NO : NIL.

VEHICLE WAS SURVEYED BY MR TAUFIKH FROM LKK AUTO  
CONSULTANTS PTE LTD ON 1.2.2019 AT 2.40 PM. AUTHORISED  
REPAIR BY MR VIC ALPEH FROM LKK AUTO CONSULTANTS PTE  
LTD ON 28.1.2019 VIA E-MAIL.

PROPOSE LOSS OF USE = \$120X3. THE AMOUNT IS SUBJECTED  
TO INSURANCE COMPANY CONFIRMATION.

GIA SEARCH FEE = \$2.00.

NETT

850.00

934.00

150.00

80.00

0.00

0.00

0.00

Total Labour 1: 2,014.00

## - - - - PARTS - - - -

EXHAUST SUPPORT

REAR BUMPER COVER (M)

REAR BUMPER PANEL PRIMED (M)

UNDERBODY PANELLING REAR

EXPANDING RIVET D=8MM

Qty Retail  
Price

1 48.65

1 187.95

1 1,691.65

1 41.30

5 1.05

NETT

48.65

187.95

1,691.65

41.30

5.25

Total Parts : 1,974.80

**Performance Motors Limited**

A member of the Sime Darby Group  
Co. Reg. No. 197401559W GST Reg. No. M2-0020081-9



303, Alexandra Road  
Sime Darby Performance Centre  
Singapore 159941  
Tel. 63190100 (Sales & Admin)  
63190111 (AfterSales)  
Fax. 64747770

290, Sempang Arang Road  
East Coast Centre  
Singapore 438100  
Tel. 63190888 (AfterSales)  
Fax. 63449773

118, Alexandra Road  
Sime Darby Business Centre  
Singapore 159944  
Tel. 63190528 (AfterSales)  
63190533/330 (Motorrad)  
Fax. 64794601 (AfterSales)  
64794624 (Motorrad)

**SERVICE TAX INVOICE**

Repair Order No. : <b>B1 1335878</b>	Page No. : <b>2 of 2</b>
Date IN : <b>08/02/2019</b>	Invoice Number : <b>2081865 / WSB</b>
Cust. Svc. Advisor: <b>Gary Poh Chai Hoon</b>	Invoice Date : <b>28/03/2019</b>
	Payment Terms : <b>30 Days From Invoice</b>
	Invoice By : <b>Sharon Heng</b>

Labour Charges : <b>1,934.00</b>	Total Labour & Parts Charges : <b>S\$ 3,988.80</b>
Parts Charges : <b>1,974.80</b>	Less Insurance Excess : <b>S\$ 0.00</b>
Lubricant/Misc : <b>80.00</b>	Invoice Total Amount Exclude GST : <b>S\$ 3,988.80</b>
	GST @ 7% : <b>S\$ 279.22</b>
	Invoice Total Amount Include GST : <b>S\$ 4,268.02</b>

Computer generated invoice. No signature is required.

Amount Payable Include GST : **S\$ 4,268.02**

All amounts are in Singapore Dollars.

Work was carried out subject to the Company's Terms and Conditions of Service.

No complaints will be entertained unless reported within seven (7) days of the date of this invoice.

For credit purchases, interest @1% per month will be debited on overdue amounts.





RECORDS MANAGEMENT CENTRE

**GENERAL INSURANCE ASSOCIATION OF SINGAPORE  
RECORDS MANAGEMENT CENTRE**

6 Raffles Quay #18-00, Singapore 048580  
Phone: +65 6224 0010 Fax: +65 6224 0030  
Operating Hours: Monday to Friday 9am to 5pm  
GST Registration No: M400017735

**Third Party Insurer Enquiry**

Our Ref No: GR-19-008857

Date of Request: 16/01/2019

Your Ref No:

Online Purchase

Performance Motors Limited  
303 Alexandra Road  
Sime Darby Performance Centre  
Singapore 159941

Dear Sir/Madam,

Enquiry Date 16/01/2019  
Enquiry By Melanie Setiawati  
TP Vehicle No. SKA4404G  
Accident Date 16/01/2019

**Enquiry Result**

TP Vehicle No.	Insurer	Period of Insurance	Insurer Tel. No.
SKA4404G	AIG Asia Pacific Insurance Pte. Ltd.	28/02/2018-27/02/2019	65-6419-3000

Thank You.

The images provided to you are taken from the original reports forwarded to the centre by the members of the General Insurance Association of Singapore and we take no responsibility for their accuracy or contents and shall be under no liability whatsoever for any loss or damage arising out of or in connection with the reports or their images.

This is a computer generated document and requires no signature.





RECORDS MANAGEMENT CENTRE

**GENERAL INSURANCE ASSOCIATION OF SINGAPORE  
RECORDS MANAGEMENT CENTRE**

6 Raffles Quay #18-00, Singapore 048580  
Phone: +65 6224 0010 Fax: +65 6224 0030  
Operating Hours: Monday to Friday 9am to 5pm  
GST Registration No: M400017735

**TAX INVOICE**

Our Ref No: GR-19-008857

Date of Request: 16/01/2019

Your Ref No:

Online Purchase

Performance Motors Limited  
303 Alexandra Road  
Sime Darby Performance Centre  
Singapore 159941

Dear Sir/Madam,

Enquiry Date 16/01/2019  
Enquiry By Melanie Setiawati  
TP Vehicle No. SKA4404G  
Accident Date 16/01/2019

DESCRIPTION	AMOUNT (S\$)
TP Insurer Enquiry	1.87
GST Amount	0.13
Total Amount Due (GST Inclusive)	2.00

Thank You.

This is a computer generated document and requires no signature.

For GIARMC Official use:

Date:

☒ [X] GIRO ☐ [ ] Cash ☐ [ ] Cheque

## ...CLAIM SUBFOLDER...(Pending for Survey Report)

Express

## CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	17 Jan 2019 <a href="#">Edit Reg</a>		01 Feb 2019 00:00 <a href="#">Edit Adj Rpt</a>	<b>S\$3,988.80</b> <a href="#">Edit Estimates</a>	<b>S\$3,988.80</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b> <span style="float: right;">[Created by adjuster]</span>									
Insured:	<b>Shek Chee Seng</b> , ID: S1553235A								
Main Claimant:	<b>PERFORMANCE MOTORS LTD.</b> , Co. Reg. No.: 197401559W								
Vehicle Reg. No.:	<b>SMG7446K</b>	Date of Loss:	16/01/2019 09:00 - :59 [1 Months and 17 Days From LTA Reg Date (Man Yr)]						
Claim Type:	<b>TP / 4489456069SG</b>	Policy/Cover Note No.:	2100249418 (Comprehensive)						
Vehicle Reg. No. (Insured):	<b>SKA4404G</b>	Policy No. (Claimant):	13203868						
		Excess:							
Repairer:	<b>Performance Motors Limited (Alexandra)</b> 303 Alexandra Road, Sime Darby Performance Centre, 159941 Alexandra - Tel: 63190172/63190174								
Handling Insurer:	<b>AIG Asia Pacific Insurance Pte. Ltd. (Express)</b> - Tel: 65-6419-3000 ... [Handled by <b>MdNoor, Norsiah</b> ] Norsiah.MdNoor@aig.com								
Claimant's Insurer:	<b>MSIG Insurance (Singapore) Pte. Ltd. (HQ)</b> - Tel: +65 6827 7888								
Adjuster:	<b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [Handled by <b>MOHD TAUFIKH BIN HAMID</b> ] ... [Final Rpt due 28/01/2019]								
<b>ASSOCIATED MAIL RECEIVED</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Compose Case Mail</a></span>									
There are no mail for this case.									
<b>ALL ASSOCIATED TASKS</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a></span>									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## Claim Documents

\*SMG7446K (4489456069SG)  
[SKA4404G]  
TP  
PERFORMANCE MOTORS LTD  
Jan 16 2019 9:00AM  
[Shek Chee Seng]  
Performance Motors Limited

Upload Documents			Upload Photos			Compose New Letter			Upload Video			Upload Audio			View			View in Browser		
Letters/Correspondences															1 per page		<input type="checkbox"/>		<input checked="" type="checkbox"/>	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)												Thumbnail		Print				
1	(Draft)	Third Party Express Settlement – Payment Breakdown												1		Edit				
Photos/Images															3 per page		<input type="checkbox"/>		<input checked="" type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)												Thumbnail		Print				
1	28/03/19 13:45	Odometer Reading												1		Load JPG		<input checked="" type="checkbox"/>		
2	28/03/19 13:45	Chassis Number												1		Load JPG		<input checked="" type="checkbox"/>		
3	28/03/19 13:45	General View												1		Load JPG		<input checked="" type="checkbox"/>		
4	28/03/19 13:45	General View												1		Load JPG		<input checked="" type="checkbox"/>		
5	28/03/19 13:45	General View												1		Load JPG		<input checked="" type="checkbox"/>		
6	28/03/19 13:45	General View												1		Load JPG		<input checked="" type="checkbox"/>		
7	28/03/19 13:45	General View												1		Load JPG		<input checked="" type="checkbox"/>		
8	28/03/19 13:45	General View												1		Load JPG		<input checked="" type="checkbox"/>		
9	28/03/19 13:45	General View												1		Load JPG		<input checked="" type="checkbox"/>		
10	28/03/19 13:45	General View												1		Load JPG		<input checked="" type="checkbox"/>		
11	28/03/19 13:45	General View												1		Load JPG		<input checked="" type="checkbox"/>		
12	28/03/19 13:45	General View												1		Load JPG		<input checked="" type="checkbox"/>		
13	28/03/19 13:45	General View												1		Load JPG		<input checked="" type="checkbox"/>		
14	28/03/19 13:45	General View												1		Load JPG		<input checked="" type="checkbox"/>		
15	28/03/19 13:45	General View												1		Load JPG		<input checked="" type="checkbox"/>		
16	28/03/19 13:45	General View												1		Load JPG		<input checked="" type="checkbox"/>		
17	28/03/19 13:45	General View												1		Load JPG		<input checked="" type="checkbox"/>		
18	28/03/19 13:45	General View												1		Load JPG		<input checked="" type="checkbox"/>		
19	28/03/19 13:45	General View												1		Load JPG		<input checked="" type="checkbox"/>		
20	10/04/19 13:42	Reinspection Photo												1		Load JPG		<input checked="" type="checkbox"/>		
21	10/04/19 13:42	Reinspection Photo												1		Load JPG		<input checked="" type="checkbox"/>		
22	10/04/19 13:42	Reinspection Photo												1		Load JPG		<input checked="" type="checkbox"/>		
23	10/04/19 13:42	Reinspection Photo												1		Load JPG		<input checked="" type="checkbox"/>		
24	10/04/19 13:42	Reinspection Photo												1		Load JPG		<input checked="" type="checkbox"/>		
Documentation															1 per page		<input type="checkbox"/>		<input checked="" type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)												Thumbnail		Print				
1	17/01/19 17:33	TP ESTIMATE + DOCS												1		Load PDF				
2	17/01/19 17:33	TP GIA REPORT												1		Load PDF				
3	28/01/19 13:48	EMAIL TO OI												1		Load PDF				
4	28/01/19 13:48	LETTER TO OI												1		Load PDF				
5	12/02/19 17:58	TP ESTIMATE - MARKED												1		Load PDF				
6	15/04/19 14:47	WORKSHOP INVOICE												1		Load PDF				
7	15/04/19 14:47	Release Voucher												1		Load PDF				
8	15/04/19 14:47	GIA SEARCH												1		Load PDF				
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)												Thumbnail		Print				

Letters/Correspondences			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	18/01/19 09:14	OI GIA REPORT	 Load PDF	

## Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM \_\_\_\_\_

### THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SKA4404G (Insd veh)	Model:	BMW 520i 2.0 LED NAV
	SMG7446K (TP veh)		MSPT (A)
Date of Accident:	16/01/2019		

Global Sum Settlement	:	<input type="checkbox"/> Yes	<input checked="" type="checkbox"/> No	
Repair Estimate	: \$	7,384.66		
Final Repair Cost	: \$	4,268.02		
Loss of Use	: \$	360.00		3.00 days at \$120.00 per day
Rental (if any)	: \$	0.00		days
LTA / GIA Search Fee	: \$	2.00		
Others:	: \$	0.00		
	: \$			
Final Settlement Sum	: \$	4,630.02		

**Is Third Party Workshop GIA Registered?**    ☒ YES    ☐ NO    (Kindly indicate below)

**A) For Non GIA Registered Workshop:**    Agreed Liability \_\_\_\_\_ (%)

**B) For GIA Registered Workshop:**    BOLA Applicable: Yes/ No    BOLA Scenario No: \_\_\_\_\_

BOLA Liability: \_\_\_\_\_ 100 \_\_\_\_\_ (%)    Assessed Liability (\*): \_\_\_\_\_ (%)

\* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.

Remarks \_\_\_\_\_

Payment Instruction: Payee's Breakdown			
1)	Performance Motors Limited	: \$	4,630.02
2)		: \$	
3)		: \$	

JOANNE LEE KHANG MIN

15 Apr  
2019

LKK Auto Consultants Pte Ltd

Date

Please attach all the supporting documents to the form.

(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

# LKK Auto Consultants Pte Ltd

(Co. Reg. No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/AIG19001114/T1HA3Q2

Date: 15/04/2019

### REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100249418  
**Claimant Vehicle No :** SMG7446K **Insured Vehicle No :** SKA4404G  
**Date of Loss:** 16/01/2019 **Nature of Claim:** TP **Claim No:** 4489456069SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

**Reg No:** SMG7446K  
**Make & Model:** BMW 520I, 2.0 LED NAV MSPT (A) **Engine No:** 14885385B48B20A  
**Reg. Date:** 30/11/2018 (Man. Year: 2018) **Chassis No:** WBAJA12000BJ20788  
**Colour:** Black **Odometer:** 1276 km  
**Engine Capacity:** 1998 cc  
**Market Value/New Car Price:** N/A  
**Sum Insured (S\$):** Market Value/New Car Price

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

**General Condition:** Steering (Serviceable): Yes **Footbrake (Serviceable):** Yes  
**Handbrake (Serviceable):** Yes **Engine Modification:** No **Pre-accident Condition:**

### CONDITION OF TYRES

**Front Tyre Size:** 275/40 R18 **Rear Tyre Size:** 275/40 R18  
**Front Left Side:** Pirelli 6 mm **Rear Left Side:** Pirelli 6 mm  
**Front Right Side:** Pirelli 6 mm **Rear Right Side:** Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,986.55	2,054.80	1,931.75	48.46
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,915.00	1,934.00	981.00	33.65
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>6,901.55</b>	<b>3,988.80</b>	<b>2,912.75</b>	<b>42.20</b>
<b>+ GST 7.00/7.00% (S\$)</b>	<b>483.11</b>	<b>279.22</b>	<b>203.89</b>	<b>42.20</b>
<b>Nett Amount (S\$)</b>	<b>7,384.66</b>	<b>4,268.02</b>	<b>3,116.64</b>	<b>42.20</b>
<b>+ Loss of Use (3.0 x S\$120.00/day) (S\$)</b>		<b>360.00</b>		
<b>+ Doc/Search Fee (S\$)</b>		<b>2.00</b>		
<b>Nett Liability (S\$)</b>		<b>4,630.02</b>		

### INSPECTION

**Date of Assignment:** 01/02/2019  
**Date Inspected:** 01/02/2019 Inspected At: Performance Motors Limited (Alexandra)  
303 Alexandra Road, Sime Darby  
Performance Centre  
Singapore 159941  
**Estimated Period of Repair:** 3.0 days

---

**Adjuster:** MOHD TAUFIKH BIN HAMID**Manager:** VIC ALPEH

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*



## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SUNDRIES	Necessary	80.00 FS	*80.00 FS
2	1		*REAR BUMPER CARRIER	Not Necessary	857.75 FS	*- FS
3	1		*REAR BUMPER TOWING EYE FLAP (M)	Not Necessary	81.55 FS	*- FS
4	1		*EXHAUST SUPPORT	Deformed	48.65 FS	*48.65 FS
5	1		*REAR BUMPER COVER (M)	Deformed	187.95 FS	*187.95 FS
6	1		*REAR BUMPER LH GUIDE (M)	Not Necessary	55.75 FS	*- FS
7	1		*REAR BUMPER RH GUIDE (M)	Not Necessary	55.75 FS	*- FS
8	1		*REAR BUMPER CENTRE GUIDE (M)	Not Necessary	61.55 FS	*- FS
9	1		*REAR BUMPER PANEL PRIMED (M)	Deformed	1,691.65 FS	*1,691.65 FS
10	1		*UNDERBODY PANELLING REAR	Deformed	41.30 FS	*41.30 FS
11	1		*REAR RH REAR REFLECTOR	Not Necessary	37.90 FS	*- FS
12	2		*ULTRASONIC S	Not Necessary	761.30 FS	*- FS
13	4		*DECOUPING RING PDC PDC TORQUE CONVERTER	Not Necessary	20.20 FS	*- FS
14	5		*EXPANDING RIVET D=8MM	Necessary	5.25 FS	*5.25 FS
Total Parts (S\$)					3,986.55	2,054.80

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REPLACE REAR BUMPER AND ATTACHMENT CAUSE BY THE ACCIDENT	New	1,700.00	850.00
2	PAINTING REAR BUMPER	New	1,038.00	934.00
3	TO CHECK ELECTRICAL WIRING SYSTEMS AND LIGHTINGS AT THE REAR SECTION FOR PROPER FUNCTION	New	177.00	150.00
Gross Labour Cost (\$\$)			2,915.00	1,934.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >