



MSG (WINNER) = 12/2/19

* SCENE VIDEO *

Letter of Claims Request for direct settlement.

We are submitting a claim on behalf of our customer TD ZHENGCONG JEREMY
NRIC 58850922F insured of vehicle SKP 894.4 against
your insured vehicle number SLV 46659 (AIG)
On the accident dated on 16-1-19 (ddmmyyyy) along 205 KALLANG
BAHRU Rd.

Dated this 17 JAN 2019 (day) of _____ (month) 2018 .

Charmaine Kong
Volkswagen Group Singapore
Accident Claims Dept.
charmaine.kong@vw.com.sg
DID : 63057176/ 63057299
HP: 92361399

VGS Singapore
247
Alexandra Road
159934 Singapore

Phone No. +65 6305 7299
Fax No. +65 6474 3643
E-Mail service@vw.com.sg

VGS Singapore, 247, 159934 Singapore

TEO ZHENGCONG, JEREMY
Mr
43 SHANGRILA WALK
568214

VAT Registration No. M20098505-2
Tax No. 199101494Z

Service Quote

Customer No. S8850922F
Quote No. SER/QUO/1900097
QuoteDate 16/01/19
Salesperson Angie Tan
Page 1

THIS IS NOT AN OFFICIAL TAX INVOICE

Make	Model Description	Mileage	Service Advisor
Volkswagen Passeng	GOLF A7 1.4 TSI (DSG)RECAT EQP	43,270	Kong Charmaine
License No.	VIN	Initial Registration	Sales Advisor
SKP8940U	WVWZZZAUZFW048343	17/10/14	Angie Tan
Engine Code	Labor Type	Engine No.	Model Code
	1T	CXS 207764	5G13GZ

No.	Description	Qty.	UoM	Unit Price	Amount
P B&P ALEX LABOUR	LABOUR	4	Labor		3,360.00
P B&P ALEX PAINT	SPRAY PAINT	4	Labor		3,200.00
P B&P DIAG	PROGRAMMING & CALIBRATION COMPULSORY TO DO AFTER AC	1	Time Un		480.00
P B&P MECH	CHECK WIRE HARNESS, ECU, S Nett	1	Time Un		280.00
	Sum Labor				7,320.00
P 5G0807050A	BUMPER BRACKET RH	1	Pieces		23.25
P 5G0807109H	BEAM Use Predecessor 5G0807109B	1	Pieces		501.17
P 5G0807217BPGRU	FRT BUMPER COVER	1	Pieces		1,093.66
P 5G0807248F	FOAM INSERT Use Predecessor 5G0807248D	1	Pieces		47.16
P 5G0807724D	BUMPER GUIDE RH	1	Pieces		61.62
P 5G0853212E 9B9	COVER PART RH	1	Pieces		30.91
P 5G0853666 9B9	GRILL RH LOWER	1	Pieces		134.08
P 5G0853677 9B9	GRILLE RH	1	Pieces		146.51
P 5G0919493	SENSOR BRACKET	1	Pieces		16.26
P 5G0919493A	SENSOR BRACKET	2	Pieces		32.52
P 5G0919494	SENSOR BRACKET	1	Pieces		16.26
P 5G0998399 GRU	SNEOSR Bracket	1	Pieces		29.28
P 5Q0919133 9B9	SENSOR O RING	1	Pieces		1.79
P 5Q0919275B GRU	SENSOR Use Predecessor 5Q0919275 GR	1	Pieces		151.58

Sum carried forward 9,606.05

Payments to: - BBN: - Acc.-No.:

VGS Singapore, 247, 159934 Singapore

TEO ZHENGCONG, JEREMY
Mr
43 SHANGRILA WALK
568214

VGS Singapore
247
Alexandra Road
159934 Singapore

Phone No. +65 6305 7299
Fax No. +65 6474 3643
E-Mail service@vw.com.sg

VAT Registration No. M20098505-2
Tax No. 199101494Z

Service Quote

Customer No. S8850922F
Quote No. SER/QUO/1900097
QuoteDate 16/01/19
Salesperson Angie Tan
Page 2

THIS IS NOT AN OFFICIAL TAX INVOICE

Make	Model Description	Mileage	Service Advisor
Volkswagen Passeng	GOLF A7 1.4 TSI (DSG)RECAT EQP	43,270	Kong Charmaine
License No.	VIN	Initial Registration	Sales Advisor
SKP8940U	WVWZZZAUZFW048343	17/10/14	Angie Tan
Engine Code	Labor Type	Engine No.	Model Code
	1T	CXS 207764	5G13GZ

		Continued	9,606.05
P D 180KU2A1	2KADHESIVE	1 Pieces	94.32
P D 822150A1	BONDAGENT	1 Pieces	67.49
	Sum Item		2,447.86

Sum Labor	7,320.00
Sum Item	2,447.86

Total SGD	9,767.86
7% GST	9,767.86 683.75
Total SGD Incl. GST	10,451.61

Explanations

P = Proportionately Charged

Payment Terms No Credit

Payments to: - BBN: - Acc.-No.: