Surveyor Pasan | REF: ASM(AXA) | 1197/R/(R) 46116

ASSIGNMENT

From: Date: 21.01.2019

Estimated Cost:

OD / (TP) / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SKW 4588T

at Workshop m/s: ComfortDelgro

of: 45 Pandan Rd.

Insured:

Policy No.:

Claims No.:

Sum Insured: Excess:

(Client's Record)

Make of Veh:

(Policy Condition) 5pm owner waiting

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: 70k.

IDAC Accident Rport: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: Person Contacted:

Veh No: SKW 4588T Yr Regn: 2015 / OCT

Type: (M.Car) / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer or

Make: Subaru Forester 2.0L c.c 1995

Colour: BLUE A/C: Insured / Std / NI / NA

Sp.Reading: 086815 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: JF1SJ5KC5FG058723

Gen. Cond: Good / Fair / Poor / Burnt

Steering: (In order) / Jammed / Leaked / Burnt or

Brake: (In order) / Jammed / Leaked / Burnt or

Modi: Nil / (S/Rim) / STD A/Rim or

Tyre Size: F: 225/60R17

R: "

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / (YOKO) or

Front		Rear	
R/Bal.	6 mm	R/Bal.	6 mm
L/Bal.	6 mm	L/Bal.	6 mm

D.O.A. 11/01/19 D.O.I. 21/01/19

Survey held at: COMFORT PANDAN

Des. of Damages: Frt / Rear / (O/S) / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction

Date/Time. File Pass to? (1) ☐ : Preli. Report ☐ : Final Report

Date/Time, File Return to? (2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation: ( ) G + RS. SI

Add Fee: ☐ : Site Insp ($) Photos

☐ : Interview ($) Others

☐ : Tech Invs ($)

☐ : Weekend ($)

TOTAL

Report Format :

Lump Sum / I.B.I: ($)