

22/03/2002

ASS. REC. BY:

REF:

C83/AIG19001252/Ecd301

Special Instruction:

Surveyor
Mention

Steve

ASSIGNMENT (Office)

From (Person):

Chin lee Ying

of

AIG

Date/Time:

21/11/19 @ 9.26am

Estimated Cost:

Bill to:

OD / ~~TP~~ / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SKU 4845L

Insured:

SGT 775J

at Workshop m/s

My Car Consultant

Tel:

8 8 6 6 8 8 3 2

of

53 ubi Ave 1 #01-25

Policy No:

2100504641

Claim No:

0852755147SG

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

14/1/19

CA / REV / REP. / REV 24 HRS

up

H.O.D. Endorsement:

Date/Time:

9.44am @ 21/1/19

Person Contacted:

Huiqin

Vehicle

IN OUT

Date/Time

Action/Instruction (X) Estimate

#01-33

SKU 4845L-X

SGT 775J - NA/AIG19000905/24

D.O.A: 14/01/2019

Dismantle: 22/1/2019.


PRS

ASSIGNMENT

From _____ Date: 21/01/19
 Estimated Cost _____
 OD ☒ TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: SKU 4845L
 at Workshop n/s My Car Consultant
 of 53 Ubi Ave 1 # 01-25 33
 Insured _____
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
 repair at the time of inspection.



Bal. or Market Value: _____
 IDAC Accident Rpt: _____ Consistent?: Yes or No
 GIA / PR Seen: _____ Consistent?: Yes or No
 Est. Repairs: 9 days Res.: Yes or No
 Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS (up)

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SKU 4845L Yr Regn: 30/05/2006
 Type: ☒ M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or _____
 Make: Toyota Lexus 1S250 C.C. 2.5
 Colour: White A/C: _____ Insured / Std / NI / NA
 Sp. Reading: 145482 T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: JTHBK262 X0 2014143
 Gen. Cond: Good ☒ Fair / Poor / Burnt
 Steering: ☒ Order / Jammed / Leaked / Burnt or
 Brake: ☒ Order / Jammed / Leaked / Burnt or
 Modi: Nil ☒ S/Rim / STD A/Rim or
 Tyre Size: F: 225/45R17
 R: 225/45R17
 BS / DUN / EXNOVA / GY / FS / LIZA / ☒ MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or _____
 Front _____ Rear _____
 R/Bal. 5 mm R/Bal. 5 mm
 L/Bal. 5 mm L/Bal. 5 mm
 D.O.A. 14/1/19 D.O.I. 21/1/19
 Survey held at My Car Consultant
 Des. of Damages ☒ Frt / ☒ Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	MV - 52,000
	PV - 33,867
	NV - 18,133

Date/Time, File Pass to? ☐ : Preli. Report
☐ : Final Report
 1) _____
 Date/Time, File Return to? _____

Days Of Repair: 9
 Resurvey No. of Trip: 1

Add Fee: ☐ : Site Insp (\$)
☐ : Interview (\$)
☐ : Tech Invs (\$)
☐ : Weekend (\$)

Survey Fee: 180
 Transportation: _____
) \$ + RS. \$
) Photos
) Others

Report Format: DAR
 Lump Sum / I.B.I. (\$) _____

TOTAL

190

- PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURE...

From: Chin, Lee-Ying
To: assignments, Admin A
Cc: Fong, Andy-SY
Sent: 21/1/2019 9:26:22 AM
Attachments:  SKU4845L.PDF

Hi LKK,

Kindly assist to survey, vehicle in workshop.

Thanks.

Best Regards
Lee Ying, Chin
AIG
Claims | AIG Asia Pacific Insurance Pte. Ltd.
78 Shenton Way #08-16 Singapore 079120
Tel +(65) 6419 1947
Lee-Ying.Chin@aig.com | www.aig.sg

From: Nur Ardiilah Ramli [mailto:ardiilah@apl.com.sg]
Sent: Friday, January 18, 2019 3:34 PM
To: Hor, Yinrul; Enquiry
Cc: Fong, Andy-SY; Chin, Lee-Ying; Abu Kassim, Noor Mariesa; Azlan, Syazairdina; Chan, Yoke Shi; Lim, Sheng Yang; Md Ishak, Mohd Imran; Mithoosingh, Aashweenjeetkaur; admin@mycar.sg; Armelia Binte Abdul Wahab; Charles Hoon
Subject: RE: PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SGT775J AND SKU4845L ON 14/01/2019

Dear Sir,

Our clients vehicle can be inspected at:

My Car Consultant
53 Ubi Ave 1
#01-25 Paya Ubi Industrial Park
Singapore 408934

Contact person: Huiqin
Tel: 88668832

Please note that our clients' vehicle will only be available for pre-repair survey within the next two (2) working days. Our clients shall proceed to repair their vehicle thereafter without further notice or reference to you.

All our clients' rights are reserved.

Ardiilah

Secretary to Mr Charles Hoon

A P Law Practice

9 Temasek Boulevard #09-01 Suntec Tower 2 Singapore 038989

T: 64071429 F: 64071427 E: ardiilah@aplp.com.sg

Singapore UEN No.: 53380739E

=====

This email transmission is confidential and intended only for the addressee(s). It may contain information which is privileged as between solicitor and client or protected by litigation privilege. If you are not the intended recipient, please delete this message and all attachments and inform us by return email. No part of this message should be disclosed to any party, copied or used for any purpose. Thank you for your co-operation.

=====

From: Hor, Yinrul <Yinrul.Hor@aig.com>

Sent: Thursday, January 17, 2019 11:05 PM

To: Nur Ardiilah Ramli <ardiilah@aplp.com.sg>; Enquiry <enquiry@aplp.com.sg>

Cc: Fong, Andy-SY <Andy-SY.Fong@aig.com>; Chin, Lee-Ying <Lee-Ying.Chin@aig.com>; Abu Kassim, Noor Mariesa <NoorMariesa.AbuKassim@aig.com>; Azlan, Syazairdina <Syazairdina.Azlan@aig.com>; Chan, Yoke Shi <yokeshi.chan@aig.com>; Lim, Sheng Yang <ShengYang.Lim@aig.com>; Md Ishak, Mohd Imran <Imran.Ishak@aig.com>; Mithoosingh, Aashweenjeetkaur <Aashweenjeetkaur.Mithoosingh@aig.com>

Subject: RE: PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SGT775J AND SKU4845L ON 14/01/2019



This is a secure, encrypted message. To read it, open the attachment.

这是安全加密信息。如要阅读此信息，请开启附件。

นี่คือการรักษาความปลอดภัยข้อความที่เข้ารหัสลับ เพื่ออ่านมันให้เปิดไฟล์ที่แนบมา

이것은 안전하고 암호화된 메시지입니다. 그것을 읽으려면 첨부 파일을 엽니다.

Ini adalah pesan, aman terenkripsi. Untuk membacanya, membuka attachment.

[Click here](#) by 2019-01-25 15:05 +08 to read your message.
After that, open the attachment.

[More Info](#)

Disclaimer: This email and its content are confidential and intended solely for the use of the addressee. Please notify the sender if you have received this email in error or simply delete it.

Secured by Proofpoint Encryption, Copyright © 2009-2017 Proofpoint, Inc. All rights reserved.

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

AP Law Practice
(UEN No. 53380739E)

9 Tamasek Boulevard
#09-01 Suntec Tower 2
Singapore 038989

T: +65 6407 1429
F: +65 6407 1427
E: enquiry@aplp.com.sg

We do not accept service of Court documents by fax

Our ref: AP/2019/000688

Lambert Aldino Rumambi Kamaldin
Blk 437 Fajar Road
#08-378
Singapore 670437

By Certificate of Posting

AIG Asia Pacific Insurance Pte Ltd
Insurer of SGT775J
78 Shenton Way
#07-16
Singapore 079120
Attn: Motor Claim Department
(your ref: to be advised)

By Post & Fax: 6415 3727

Date: 18 January 2019

Dear Sirs,

PROPERTY DAMAGE CLAIM ARISING FROM A ROAD TRAFFIC ACCIDENT ON 14 JANUARY 2019 AT ABOUT 09:40HRS INVOLVING MOTOR VEHICLES NO(S). SKU4845L & SGT775J ALONG BKE/PIE BEFORE DAIRY FARM

We refer to the above matter,

We act for Sun Ren Han , the owner of SKU4845L.

We are instructed by our clients to notify you of a road traffic accident on 14 January 2019 at about 09:40hrs along BKE/PIE before dairy farm involving our client's vehicle and your vehicle bearing registration number SGT775J. A copy of our client's Singapore accident statement is enclosed.

As a result of the accident, our clients' vehicle has been damaged. Before our client proceeds to repair the damaged vehicle, please let us know within two (2) working days of your receipt of this notice whether you or your insurer would like to conduct a pre-repair survey of our clients' vehicle. If we do not receive any reply from you within the stipulated timeline, our client shall proceed to repair his vehicle without further reference to you.

Please revert to us via email: ardilah@aplp.com.sg

Yours faithfully,



Charles Hoon
enc.

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	6258F
Vehicle Details	
Vehicle No.:	SKU4845L
Vehicle to be Exported:	No
Intended Deregistration Date:	21 Jan 2019
Vehicle Make:	TOYOTA
Vehicle Model:	LEXUS IS250 AUTO STD
Primary Colour:	White
Manufacturing Year:	2006
Engine No.:	4GR0191969
Chassis No.:	JTHBK262X02014143
Maximum Power Output:	153.0 kW (205 bhp)
Open Market Value:	\$36,638.00
Original Registration Date:	30 May 2006
First Registration Date:	30 May 2006
Transfer Count:	3
Actual ARF Paid:	\$40,302.00
Intended PARF Rebate Details	
PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	29 May 2026
COE Category:	B - Car (1601cc & above)
COE Period(Years):	10
PQP Paid:	\$46,048.00
COE Rebate Amount:	\$33,867.00
Total Rebate Amount:	\$33,867.00

The information contained herein is correct as at 21 Jan 2019

OK



Post an Advertisement
Sell it yourself! Advertise it at just
\$58 until it's SOLD!

Post an Ad

Advertiser Login

Ways of Selling



Up To 90% Loan! Low Interest!
Low Rental! 5 Yrs Warranty & 10
Yrs Engine Warranty
Autobest Traders - Standard

Free VTC evaluation
Free grooming and 6 months maintenance
In-house workshop ensures quality service
Members of SVTA and have purchase association
100% deposit refund for unapproved loan

YONG LEE SENG MOTOR PTE LTD

Browse by Category

Back (1 2 3) Next

Sort by Date Posted

20 results/page

51 vehicles

Lexus IS250

Advanced Search

Image	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
Search Selection	Lexus IS250	Any	Any	Any	Any	Any	Any	Available
	Lexus IS250 (New 10-yr COE)	\$60,800	\$6,080 /yr	24-Mar-2009	2,500 cc	-	Luxury	Available
Low Monthly From \$900! Low Interest Rate From 3.18%! Excellent Recondition, call Now								
Posted: 18-Dec-2018 Tags: 2009 Lexus IS250, 2009 Lexus IS250, Lexus IS250, Lexus IS250, Lexus IS250, Lexus IS250, Used Lexus								
	Lexus IS250C	\$45,800	\$16,630 /yr	05-Feb-2010	2,500 cc	91,000 km	Sports	Available
Bidded Carplate Number. Cheap Depreciation With Rare Convertible Unit, Elegant Colour And Perfect Paint Condition. Smooth Engine And Transmission, Accident Free. Well Maintained Without Accident. Very...								
Prem Roy Motoring								
Posted: 15-Dec-2018 Tags: 2010 Lexus IS250C, 2010 Lexus IS250C, Lexus IS250C, Lexus IS250C, Lexus IS250C, Lexus IS250C, Used Lexus								
	Lexus IS250 Luxury (COE till 10/2028)	\$68,800	\$7,090 /yr	03-Oct-2008	2,500 cc	-	Luxury	Available
\$8K Driveaway. IS250 Facelift Unit! Optional 5/10 Years COE Available! AA Trust Certified Quality Pre-Owned Vehicle! Extremely Well Maintained By Previous Owner! Beautifully Maintained Beige Leather L...								
AA Trust Automotive								
Posted: 15-Dec-2018 Tags: 2008 Lexus IS250, 2008 Lexus IS250, Lexus IS250, Lexus IS250, Lexus IS250, Lexus IS250, Used Lexus								
	Lexus IS250 Luxury (New 10-yr COE)	\$68,800	\$6,870 /yr	08-May-2009	2,500 cc	89,000 km	Luxury	Available
AA Trust Certified Quality 1 Owner Vehicle! Extremely Well Maintained By Previous Owner! Brand New Beige Leather Interior With Grey Exterior Paintwork! Luxury Sedan Comfort With The Performance Of A S...								
AA Trust Automotive								
Posted: 14-Dec-2018 Tags: 2009 Lexus IS250, 2009 Lexus IS250, Lexus IS250, Lexus IS250, Lexus IS250, Lexus IS250, Used Lexus								
	Alliance Auto Pte Ltd - Specialty Workshops							
A Lexus specialise workshop with an extensive investment in the manpower, equipment and genuine parts for Lexus.								
More info about this shop								
	Lexus IS250C	\$77,800	\$16,370 /yr	18-Jan-2012	2,500 cc	78,000 km	Sports	Available
Consignment Unit, Call For Arrange Viewing!								
Car Search								
Posted: 09-Dec-2018 Tags: 2012 Lexus IS250C, 2012 Lexus IS250C, Lexus IS250C, Lexus IS250C, Lexus IS250C, Lexus IS250C, Used Lexus								
	Lexus IS250	\$62,800	\$14,480 /yr	18-Jan-2012	2,500 cc	62,000 km	Luxury	Available
New 6 Months Road Tax. Multiple Ownership Is Due To Retention Of Number And Transfer Within Family Member. Genuine Mileage With Agent's Record. Hardly Use And Very Well Kept Engine And Interior, Orig...								
Posted: 08-Dec-2018 Tags: 2012 Lexus IS250, 2012 Lexus IS250, Lexus IS250, Lexus IS250, Lexus IS250, Lexus IS250, Used Lexus								
	Lexus IS250 (New 5-yr COE)	\$58,800	\$11,750 /yr	14-Nov-2008	2,500 cc	125,945 km	Luxury	Available
Options To Renew COE 10 Years At \$65800! Own A Luxury Car At A Affordable Price, Well Maintained, Low Mileage! Reliable And Smooth Drive. Flexible Bank/ In House Loan Package With Attractive Interest ...								
Posted: 07-Dec-2018 Tags: 2008 Lexus IS250, 2008 Lexus IS250, Lexus IS250, Lexus IS250, Lexus IS250, Lexus IS250, Used Lexus								
	Lexus IS250	\$46,888	\$15,330 /yr	11-Nov-2010	2,500 cc	121,000 km	Luxury	Available
Immaculate Condition, Car Just Serviced On 100k Km Mileage, 1 Careful Owner, Low Mileage, High PARF Rebate, Regularly Serviced At Reputable Workshop Using XADO Premium Grade Engine Oil. New Tires And ...								
Posted: 02-Dec-2018 Tags: 2010 Lexus IS250, 2010 Lexus IS250, Lexus IS250, Lexus IS250, Lexus IS250, Lexus IS250, Used Lexus								
	Lexus IS250 Luxury (COE till 11/2023)	\$48,800	\$10,140 /yr	14-Nov-2008	2,500 cc	160,000 km	Luxury	Available
Immaculate Condition And Easy To Maintained. All Wear And Tare Parts Has Been Replaced, Got Receipts And Warranty For All Work Done. Lowest Depreciation For Such A Luxury Sedan, High Trade In And Flex...								
Posted: 16-Nov-2018 Tags: 2008 Lexus IS250, 2008 Lexus IS250, Lexus IS250, Lexus IS250, Lexus IS250, Lexus IS250, Used Lexus								
	Lexus IS250 (COE till 09/2027)	\$65,800	\$7,590 /yr	21-Sep-2007	2,500 cc	-	Luxury	Available
COE Renewed Car. One Of The Most Popular Luxury Car In The Market. Interior Of The Car Well Maintained. Car Well Maintained By Fussy Owner. Comfort And Quiet, Smooth And Powerful. Don't Miss This Chan...								
Prem Roy Motoring								
Posted: 12-Nov-2018 Tags: 2007 Lexus IS250, 2007 Lexus IS250, Lexus IS250, Lexus IS250, Lexus IS250, Lexus IS250, Used Lexus								
	Free Valuation by sgCarMart Quotz							
Trading-in your Car? Make a better informed decision by getting your Car accurately valued with Quotz, based on SG's largest car database, sgCarMart. Get notified via Phone, SMS, Email. Sell your Car for more - Get your Free Valuation Today.								
Find out more!								
Compare	Lexus IS250	\$52,800	\$14,420 /yr	24-May-2011	2,500 cc	66,500 km	Luxury	Available

Used Lexus IS250 Car & Used Cars & Vehicles Singapore - sgCarMart



Flexible Finance Package Available. Powerful, Smooth V6 Eng...

Posted: 20-Jan-2019 Tags: 2011 Lexus IS250, 2011 lexus is250, Lexus IS250, lexus is250, Lexus, IS250, is250, Used Lexus



Lexus IS250 Luxury (COE till 07/2028) **\$63,800** **\$6,750 /yr** **03-Jul-2008** **2,500 cc** **113,800 km** **Luxury** **Available**

100% Flexible Loan Options Available! Rare Luxury Model! Guaranteed At Lowest Market Price! Superb Condition! Please View To Believe, Not A Leasing Or Rental Scheme! No Gimmicks! We Only Put Up The Goo...

Posted: 20-Jan-2019 Tags: 2008 Lexus IS250, 2008 lexus is250, Lexus IS250, lexus is250, Lexus, IS250, is250, Used Lexus

**The best car deals without the hassle!**

We have over a thousand consignment cars available for sale at highly attractive prices. All without the need to do paperwork. Pick out your favourite car today.

Find out more!



Lexus IS250 Premium **\$47,800** **\$12,920 /yr** **15-Dec-2010** **2,500 cc** **-** **Luxury** **Available**

Premium Model, 100% Accident Free, Service And Maintained By Borneo Motor, Recently Service In Dec, Road Tax Till Jun'19, Clean & Neat Interior.

Posted: 19-Jan-2019 Tags: 2010 Lexus IS250, 2010 lexus is250, Lexus IS250, lexus is250, Lexus, IS250, is250, Used Lexus



Lexus IS250 Luxury (COE till 01/2029) **\$65,800** **\$6,610 /yr** **02-Jan-2009** **2,500 cc** **124,000 km** **Luxury** **Available**

Car House Pte Ltd

Posted: 19-Jan-2019 Tags: 2009 Lexus IS250, 2009 lexus is250, Lexus IS250, lexus is250, Lexus, IS250, is250, Used Lexus



Lexus IS250 (New 10-yr COE) **\$61,500** **\$6,140 /yr** **26-Mar-2009** **2,500 cc** **93,000 km** **Luxury** **Available**

No Gimmicks, Honest Dealing, Low Mileage Clock, Car In Good Condition, \$46000 For 5 Years COE. High Loan Available, 100% Approval. Trade In Welcome, Bank Loan Available. Call Us For An Appointment At ...

Posted: 19-Jan-2019 Tags: 2009 Lexus IS250, 2009 lexus is250, Lexus IS250, lexus is250, Lexus, IS250, is250, Used Lexus



Lexus IS250C (New 10-yr COE) **\$73,800** **\$7,370 /yr** **23-Jul-2009** **2,500 cc** **136,300 km** **Sports** **Available**

High Loan And Trade In All Available, Interested Please Call For Viewing, Viewing By Appointment Only.

Boeki Auto & Marine

Posted: 19-Jan-2019 Tags: 2009 Lexus IS250C, 2009 lexus is250c, Lexus IS250C, lexus is250c, Lexus, IS250C, is250c, Used Lexus



Lexus IS250 (COE till 04/2026) **\$53,900** **\$7,420 /yr** **28-Apr-2006** **2,500 cc** **-** **Luxury** **Available**

Elegant Silver, Powerful Drive, Low Mileage Done, Very Well Maintained, Low Maintenance Cost, Flexible In-house Loan Packages Available.

Prime Motor & Leasing

Posted: 18-Jan-2019 Tags: 2006 Lexus IS250, 2006 lexus is250, Lexus IS250, lexus is250, Lexus, IS250, is250, Used Lexus



Lexus IS250 **\$37,800** **\$13,990 /yr** **21-May-2010** **2,500 cc** **129,891 km** **Luxury** **Available**

(Perfect Conditions With NEW Dashboard And Door Panel). Beautiful Paintwork! Highest OMV \$38495. Low Mileage Done! Fully Maintained And Serviced By Lexus From Day 1 With Records. 100% Accident-Free. ...

Posted: 18-Jan-2019 Tags: 2010 Lexus IS250, 2010 lexus is250, Lexus IS250, lexus is250, Lexus, IS250, is250, Used Lexus



Lexus IS250 (New 10-yr COE) **\$66,800** **\$6,670 /yr** **27-Feb-2009** **2,500 cc** **105,948 km** **Luxury** **Available**

Fully Agent Serviced Since Day 1. Low Mileage Vehicle With No Expenses Spared, Servicing Records Available, Beautifully Maintain By Owner Who Actually Wanted To Renew The Vehicle. Perfect Condition, V...

Posted: 18-Jan-2019 Tags: 2009 Lexus IS250, 2009 lexus is250, Lexus IS250, lexus is250, Lexus, IS250, is250, Used Lexus



Lexus IS250 **\$43,800** **\$14,660 /yr** **21-Sep-2010** **2,500 cc** **-** **Luxury** **Available**

Well Maintained Very Good Condition Lexus! Tom's Exhaust (LTA Compliant), Tanabe NF Lowering Spring, Joe Z Intake Pipe/Tom's Drop In Filter, ISF Rear Camber Arms. Call Now For Viewing Appointment! Tra...

Posted: 17-Jan-2019 Tags: 2010 Lexus IS250, 2010 lexus is250, Lexus IS250, lexus is250, Lexus, IS250, is250, Used Lexus



Lexus IS250 (New 10-yr COE) **\$93,800** **\$9,370 /yr** **20-Jan-2009** **2,500 cc** **86,622 km** **Luxury** **Available**

10 Years COE Renewal At \$65800. Only 2 Owners! Genuine Low Mileage! Agent Maintained! 100% Loan Available! Highest Offer For All Trade In! Very Good Condition! Stock Paintwork! Accident Free! Very Wel...

Car Search

Posted: 17-Jan-2019 Tags: 2009 Lexus IS250, 2009 lexus is250, Lexus IS250, lexus is250, Lexus, IS250, is250, Used Lexus



Lexus IS250C **\$42,500** **\$15,740 /yr** **29-Jan-2010** **2,500 cc** **141,000 km** **Sports** **Available**

Rare IS250 Convertible For Sale. The IS250, Known For It's Bulletproof Reliability And Low Maintenance Costs Is Now Yours At A Price Cheaper Than A Standard Sedan. Assured Worry Free Drive Till Jan Or...

Posted: 16-Jan-2019 Tags: 2010 Lexus IS250C, 2010 lexus is250c, Lexus IS250C, lexus is250c, Lexus, IS250C, is250c, Used Lexus

Save this search criteria, to get email alerts whenever a match is found.

Make Model Price Depreciation Reg Date Eng Cap Mileage Veh Type Status

Compare

5, view Expired ads

Back (1 2 3) Next »

20 results/page

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	14/01/2019 15:51
Date Of Accident	14/01/2019 09:40
Exact Location Of Accident	BKE / PIE BEFORE DAIRY FARM
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKU4845L
Insured/Policyholder	
Name Of Registered Owner	SUN REN HAN
NRIC No	S8376258F
Email Address	SUNRENHAN@GMAIL.COM
Mobile Phone No	(LOCAL) +65-87879989
Alternative Phone No	OTHERS-87879989

Vehicle Particulars

Manufacturer	LEXUS
Model	IS 250
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	GA196414
Cover Note Number	

Driver

Name of Driver	SUN REN HAN
NRIC No	S8376258F
Date Of Birth	15/05/1983
Occupation	INDOOR
Date Of Driving Pass	23/06/2008
Driving Experience	10 YEARS AND 6 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-87879989
Fax Number	
Contact Number	OTHERS-87879989
EMail Address	SUNRENHAN@GMAIL.COM

Address	52 CHOA CHU KANG NORTH 7 #06-22
Postcode	689528
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	CHAIN COLLISION
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	4
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	3
Passenger 1	NAME: : FENG JINYAN GENDER: : FEMALE
Passenger 2	NAME: : SUN YUANQI GENDER: : MALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO ATTACHED STATEMENT RECORDED BY LILY - PROGRESSIVE CAR CARE PTE LTD 67415336

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SKM2213R
Vehicle Make/Model/Colour	MERZ E250
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	VEHICLE B
NRIC/Passport Number	
Contact Number	
Address	
Postcode	

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number

SGT775J

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category

PRIVATE CAR

Name of Driver

VEHICLE C

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 3

Vehicle Registration Number

WA4296E

Vehicle Make/Model/Colour

MYVI

Details Of Properties

Vehicle Category

PRIVATE CAR

Name of Driver

VEHICLE D

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. The Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be listed outside of Singapore, for one or more of the above purposes;
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims;
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated; or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

14/1/19.

Sketch Plan #2

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On the stated time and date, I was travelling on vehicle A bearing carplate number SKU484SL on BRE PIE towards Dairy Farm, vehicle B (SKM2213R) who was in front of me stopped suddenly and I managed to brake on time, however shortly after I felt an impact from the rear. I alighted from my vehicle and realise that vehicle C (SBT775J) had collided head to rear of my vehicle that caused me to hit vehicle A. I wish to state that it is a 4 car chain collision where it also involves vehicle D (WA4296K).

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/AFIN No.:

14/1/19.

Vehicle No. SKU484SL

22/1/2019

NAC	INC	Item	CON	AC	DRY
1071	992205	Fuse Box			
1072	994011	Relay Box			
1073	995053	Wiper Washer Tank			
1074	995052	Wiper Washer Tank Motor			
1075	990159	Alternator Assy			
1076	990160	Alternator Belt			
1077	992688	Power Steering Pump			
1078	992669	Power Steering Belt			
1079	994431	Power Steering Cooler Pipe			
1080	992692	Power Steering Hose			
1081	990010	ABS Pump Control Unit			
1082	990427	Brake Master Pump Assy			
1083	990403	Brake Booster Pump Assy			
1084	991005	Engine Top Cover			
1085	991011	Engine Under Cover			
1086	990946	Engine Mounting			
1087	990949	Engine Mounting Frt			
1088	990950	Engine Mounting LH			
1089	990952	Engine Mounting RH			
1090	990951	Engine Mounting Rear			
1091	992234	Gear Box Mounting			
1092	991520	Frt LH Chassis Member			
1093	991520	Frt RH Chassis Member			
1094	990728	Frt Vertical Cross Member			
1095	991863	Frt Lower Cross Member			
1096	995070	Frt LH Fender	BT	R	
1097	995072	Frt LH Fender Inner Panel			
1098	995147	Frt LH Fender Lamp			
1099	995148	Frt LH Fender Protector			
1100	991740	Frt LH Fender Inner Shield			
1101	995179	Frt LH Mudflap			
1102	995170	Frt LH Wheel Rim			
1103	994025	Frt LH Rim Cover			
1104	995065	Frt LH Tyre			
1105	995071	Frt RH Fender	BT	R	
1106	991739	Frt RH Fender Inner Panel			
1107	991744	Frt RH Fender Lamp			
1108	991752	Frt RH Fender Protector			
1109	991740	Frt RH Fender Inner Shield			
1110	991884	Frt RH Mudflap			
1111	992087	Frt RH Wheel Rim			
1112	994025	Frt RH Rim Cover			
1113	995065	Frt RH Tyre			
1114	992093	Frt Windscreen Glass			
1115	992117	Frt Windscreen Rubber			
1116	992108	Frt Windscreen Moulding			
1117	992098	Frt Windscreen Sealant			
1118	991019	ERP Bracket			
1119	991020	ERP Unit			
1120	992140	Frt Wiper Arm			
1121	992142	Frt Wiper Blade			
1122	995045	Wiper Panel Garnish			
1123	991126	Firewall Panel			
1124	990753	Dashboard Assy			
1125	992282	Glove Box Cover			
1126	992281	Glove Box Compartment			
1127	994433	Steering Wheel Airbag			
1128	994485	Steering Wheel Airbag Sensor			
1129	996749	Dashboard Airbag			
1130	999750	Dashboard Airbag Sensor			
1131	990029	Airbag Control Unit			
1132	990864	Rt Driver Seat			
1133	991922	Frt RH Seat Belt Assy			
1134	991399	Frt Passenger Seat			
1135	995182	Frt LH Seat Belt Assy			
1136	990247	Shocker			

(01) Bent (2) Denied (3) Distorted (4) Cracked (5) Cut (6) Scratched
(07) Deformed (08) Shifted (09) Buckled (10) Broken (11) Necessary
(12) Missing (13) Torn (14) Unconfirmed (15) Not Working

MOTORCAR (Rear)

ACTION (AC)

(1) Replace (✓) (2) Repair (X) (3) Check (0)
(4) Not Consistent (NC)

Aug 2005

2082

Rear Portion

Vehicle No:

SKY 4845L

NAC	INC	Item	CON	AC	Qty
1137	993626	Rear Number Plate			
1138	993627	Rear Number Plate Base			
1139	993630	Rear Number Plate Garnish			
1140	993632	Rear Number Plate Lamp			
1141	992958	Rear Bumper	BR	✓	
1142	993085	Rear Bumper Upper			
1143	993017	Rear Bumper Lower			
1144	993054	Rear Bumper Side			
1145	993103	Rear Bumper Tow Cover			
1146	992341	Rear Bumper Clips	NEC	✓	
1147	992976	Rear Bumper Bracket			
1148	993068	Rear Bumper Side Retainer	BR	✓	
1149	993045	Rear Bumper Reinforcement	BT	✓	
1150	992970	Rear Bumper Beam			
1151	993077	Rear Bumper Sponge	CPM	✓	
1152	992999	Rear Bumper Damper			
1153	993040	Rear Bumper Protector			
1154	993036	Rear Bumper Pad			
1155	993026	Rear Bumper Moulding			
1156	993044	Rear Bumper Reflector	BR	✓	
1157	993023	Rear Bumper Lower Spoiler			
1158	994023	Reverse Sensor	BR	✓	2
1159	993327	Rear End Panel	BT	R	
1160	993339	Rear End Panel Top Garnish	CRU	✓	
1161	993333	Rear End Panel Inner Trim			
1162	990333	Boot Compartment Inner Trim			
1163	993851	Rear LH Taillamp			
1164	993853	Rear LH Taillamp Garnish			
1165	993859	Rear LH Taillamp Panel			
1166	995116	Rear RH Taillamp			
1167	993853	Rear RH Taillamp Garnish			
1168	993859	Rear RH Taillamp Panel			
1169	993554	Rear Apron Panel			
1170	992895	Bootlid	RT	R	
1171	991328	Bootlid Emblem	NEC	✓	3
1172	990356	Bootlid Handle			
1173	995250	Bootlid Moulding			
1174	990376	Bootlid Reflector			
1175	995222	Bootlid Lamp LH	BR	✓	
1176	992899	Bootlid Lamp RH	BR	✓	
1177	995243	Bootlid Lock	BT	✓	
1178	990377	Bootlid Rubber	TN	✓	
1179	990382	Bootlid Hinge			
1180	993877	Bootlid Spoiler garnish	BR	✓	
1181	994543	Tailgate			
1182	991328	Tailgate Emblem			
1183	994643	Tailgate Outer Handle			
1184	994640	Tailgate Moulding			
1185	994545	Tailgate Garnish			
1186	994648	Tailgate Reflector			
1187	994549	Tailgate Lamp			
1188	994646	Tailgate Protector			
1189	994676	Tailgate Wiper Arm			
1190	994677	Tailgate Wiper Blade			
1191	994679	Tailgate Wiper Nozzle			
1192	994555	Tailgate Wiper Motor			
1193	994602	Tailgate Glass			
1194	994606	Tailgate Glass Rubber			
1195	994604	Tailgate Glass Moulding			
1196	994607	Tailgate Glass Sealant			
1197	994629	Tailgate Lock			
1198	994651	Tailgate Rubber			
1199	994611	Tailgate Hinge			
1200	994594	Tailgate Damper			

NAC	INC	Item	CON	AC	Qty
1202	993784	Spare Tyre Board			
1203	994328	Spare Tyre Panel			
1204	995065	Spare Tyre			
1205	994326	Spare Tyre Lock Screw			
1206	993787	Spare Tyre Cover			
1207	995323	Triangle Breakdown Sign			
1208	990507	CD Changer Assy			
1209	990164	Antenna			
1210	990534	Centre Exhaust Pipe Assy			
1211	990532	Centre Exhaust Mounting			
1212	993364	Rear Exhaust Pipe			
1213	993357	Rear Exhaust Chrome Pipe			
1214	993361	Rear Exhaust Mounting			
1215	993358	Rear Exhaust Heat Shield			
1216	995223	Rear LH Chassis Member			
1217	993165	Rear RH Chassis Member			
1218	993436	Rear LH Fender			
1219	993449	Rear LH Fender Protector			
1220	993420	Rear LH Fender Inner Panel			
1221	993431	Rear LH Fender Inner Trim			
1222	993415	Rear LH Fender Inner Garnish			
1223	993425	Rear LH Fender Inner Shield			
1224	993621	Rear LH Mudflap			
1225	993933	Rear LH Wheel Rim			
1226	994025	Rear LH Rim Cover			
1227	995065	Rear LH Tyre			
1228	993456	Rear RH Fender			
1229	993450	Rear RH Fender Protector			
1230	993420	Rear RH Fender Inner Panel			
1231	993431	Rear RH Fender Inner Trim			
1232	993415	Rear RH Fender Inner Garnish			
1233	993425	Rear RH Fender Inner Shield			
1234	993622	Rear RH Mudflap			
1235	993934	Rear RH Wheel Rim			
1236	994025	Rear RH Rim Cover			
1237	995065	Rear RH Tyre			
1238	995162	Rear Fender Extension Panel LH			
1239	993401	Rear Fender Extension Panel RH			
1240	993430	Rear Fender Inner Top Garnish			
1241	993673	Rear Fender 1/4 Glass			
1242	993452	Rear Fender 1/4 Glass Rubber			
1243	993453	Rear Fender 1/4 Glass Sealant			
1244	993949	Rear Windscreen Glass			
1245	993976	Rear Windscreen Rubber			
1246	993961	Rear Windscreen Moulding			
1247	993955	Rear Windscreen Sealant			
1248	994729	Third Brake Light			
1249	993385	Rear Fender Air Grille			
1250	992167	Fuel Lid			
1251	992168	Fuel Neck			
1252	992179	Fuel Tank			
1253	992184	Fuel Tank Bracket			
1254	992191	Fuel Tank Float			
1255	990247	Sticker			






































...CLAIM SUBFOLDER...(Pending for Survey Report)


















































CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	22 Jan 2019 Edit Reg		21 Jan 2019 00:00 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case














































Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured:	Lambert Aldino Rumambi Kamaldin , ID: S80208661								
Main Claimant:	SUN REN HAN , ID: S8376258F								
Vehicle Reg. No.:	SKU4845L	Date of Loss:	14/01/2019 09:00 - :59 [151 Months and 15 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 0852755147SG	Policy/Cover Note No.:	2100504641 (Comprehensive)						
Vehicle Reg. No. (Insured):	SGT775J	Policy No. (Claimant):							
		Excess:							
Repairer:	My Car Consultant Pte Ltd (Ubi) 53 Ubi Ave 1, #01-24, Paya Ubi Industrial Park, 408934 Ubi - Tel:								
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Syed-Yusoff, Saliha] Saliha.Syed-Yusoff@aig.com								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by CHEN TSUE YEE] ... [Final Rpt due 30/01/2019]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
<ul style="list-style-type: none"> AIG_SG (22/01/2019): Request To Upload TP GIA Report 									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									


Claim Documents

***SKU4845L (0852755147SG)**
[SGT775J]
TP
SUN REN HAN
Jan 14 2019 9:00AM
[Lambert Aldino Rumambi Kamaldin]
My Car Consultant Pte Ltd

Upload Documents			Upload Photos			Compose New Letter			Upload Video			Upload Audio			View		View in Browser	
Photos/Images															3 per page		<input checked="" type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)													Thumbnail	Print		
1	23/01/19 08:58	General View														Load JPG	<input checked="" type="checkbox"/>	
2	23/01/19 08:58	General View														Load JPG	<input checked="" type="checkbox"/>	
3	23/01/19 08:58	General View														Load JPG	<input checked="" type="checkbox"/>	
4	23/01/19 08:58	General View														Load JPG	<input checked="" type="checkbox"/>	
5	23/01/19 08:58	General View														Load JPG	<input checked="" type="checkbox"/>	
6	23/01/19 08:58	General View														Load JPG	<input checked="" type="checkbox"/>	
7	23/01/19 08:58	General View														Load JPG	<input checked="" type="checkbox"/>	
8	23/01/19 08:58	General View														Load JPG	<input checked="" type="checkbox"/>	
9	23/01/19 08:58	General View														Load JPG	<input checked="" type="checkbox"/>	
10	23/01/19 08:58	General View														Load JPG	<input checked="" type="checkbox"/>	
11	23/01/19 08:58	General View														Load JPG	<input checked="" type="checkbox"/>	
12	23/01/19 08:58	General View														Load JPG	<input checked="" type="checkbox"/>	
13	23/01/19 08:58	General View														Load JPG	<input checked="" type="checkbox"/>	
14	23/01/19 08:58	General View														Load JPG	<input checked="" type="checkbox"/>	
15	23/01/19 08:58	General View														Load JPG	<input checked="" type="checkbox"/>	
16	23/01/19 08:58	General View														Load JPG	<input checked="" type="checkbox"/>	
17	23/01/19 08:58	General View														Load JPG	<input checked="" type="checkbox"/>	
18	23/01/19 08:58	General View														Load JPG	<input checked="" type="checkbox"/>	
19	23/01/19 08:58	General View														Load JPG	<input checked="" type="checkbox"/>	
20	23/01/19 08:58	General View														Load JPG	<input checked="" type="checkbox"/>	
21	23/01/19 08:58	General View														Load JPG	<input checked="" type="checkbox"/>	
22	23/01/19 08:58	General View														Load JPG	<input checked="" type="checkbox"/>	
23	23/01/19 08:58	General View														Load JPG	<input checked="" type="checkbox"/>	
24	23/01/19 08:58	General View														Load JPG	<input checked="" type="checkbox"/>	
25	23/01/19 08:58	General View														Load JPG	<input checked="" type="checkbox"/>	
26	23/01/19 08:58	General View														Load JPG	<input checked="" type="checkbox"/>	
27	23/01/19 08:58	General View														Load JPG	<input checked="" type="checkbox"/>	
28	23/01/19 08:58	General View														Load JPG	<input checked="" type="checkbox"/>	
29	23/01/19 08:58	General View														Load JPG	<input checked="" type="checkbox"/>	
30	23/01/19 08:58	General View														Load JPG	<input checked="" type="checkbox"/>	
31	23/01/19 08:58	General View														Load JPG	<input checked="" type="checkbox"/>	
32	23/01/19 08:58	General View														Load JPG	<input checked="" type="checkbox"/>	
33	23/01/19 08:58	General View														Load JPG	<input checked="" type="checkbox"/>	
34	23/01/19 08:58	General View														Load JPG	<input checked="" type="checkbox"/>	
35	23/01/19 08:58	General View														Load JPG	<input checked="" type="checkbox"/>	
36	23/01/19 08:58	General View														Load JPG	<input checked="" type="checkbox"/>	
37	23/01/19 08:58	General View														Load JPG	<input checked="" type="checkbox"/>	

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/ Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
38	23/01/19 08:58	General View	 Load JPG	<input checked="" type="checkbox"/>
39	23/01/19 08:58	General View	 Load JPG	<input checked="" type="checkbox"/>
40	23/01/19 08:58	General View	 Load JPG	<input checked="" type="checkbox"/>
41	23/01/19 08:58	General View	 Load JPG	<input checked="" type="checkbox"/>
42	23/01/19 08:58	General View	 Load JPG	<input checked="" type="checkbox"/>
43	23/01/19 08:58	General View	 Load JPG	<input checked="" type="checkbox"/>
44	23/01/19 08:58	General View	 Load JPG	<input checked="" type="checkbox"/>
45	23/01/19 08:58	General View	 Load JPG	<input checked="" type="checkbox"/>
46	23/01/19 08:58	General View	 Load JPG	<input checked="" type="checkbox"/>
47	23/01/19 08:58	General View	 Load JPG	<input checked="" type="checkbox"/>
48	23/01/19 08:58	General View	 Load JPG	<input checked="" type="checkbox"/>
49	23/01/19 08:58	General View	 Load JPG	<input checked="" type="checkbox"/>
50	23/01/19 08:58	General View	 Load JPG	<input checked="" type="checkbox"/>
51	23/01/19 08:58	General View	 Load JPG	<input checked="" type="checkbox"/>
52	23/01/19 08:58	General View	 Load JPG	<input checked="" type="checkbox"/>
53	23/01/19 09:02	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
54	23/01/19 09:02	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
55	23/01/19 09:02	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
56	23/01/19 09:02	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
57	23/01/19 09:02	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
58	23/01/19 09:02	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
59	23/01/19 09:02	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
60	23/01/19 09:02	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
61	23/01/19 09:02	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
62	23/01/19 09:02	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
63	23/01/19 09:02	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
64	23/01/19 09:02	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
65	23/01/19 09:02	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
66	23/01/19 09:02	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
67	23/01/19 09:02	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
68	23/01/19 09:02	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
69	23/01/19 09:02	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
70	23/01/19 09:02	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
71	23/01/19 09:02	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
72	23/01/19 09:02	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
73	23/01/19 09:02	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
74	23/01/19 09:02	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
75	23/01/19 09:02	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
76	23/01/19 09:02	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
77	23/01/19 09:02	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
78	23/01/19 09:02	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
79	23/01/19 09:02	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
80	23/01/19 09:02	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
81	23/01/19 09:02	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
82	23/01/19 09:02	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
83	23/01/19 09:02	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
84	23/01/19 09:02	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
85	23/01/19 09:02	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
86	23/01/19 09:02	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
87	23/01/19 09:02	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/ Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
88	23/01/19 09:02	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
89	23/01/19 09:02	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
90	23/01/19 09:02	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
91	23/01/19 09:02	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
92	23/01/19 09:02	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
93	23/01/19 09:02	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
94	23/01/19 09:02	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
95	23/01/19 09:02	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
96	23/01/19 09:02	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
97	23/01/19 09:02	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
98	23/01/19 09:02	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
99	23/01/19 09:02	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
100	23/01/19 09:02	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
101	23/01/19 09:02	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
102	23/01/19 09:02	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
103	23/01/19 09:02	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
104	23/01/19 09:02	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
105	23/01/19 09:02	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
106	23/01/19 09:02	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
107	23/01/19 09:02	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
108	23/01/19 09:02	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
109	23/01/19 09:02	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
110	23/01/19 09:02	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
111	23/01/19 09:02	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
112	23/01/19 09:02	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
113	23/01/19 09:02	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
114	23/01/19 09:02	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
115	23/01/19 09:02	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
116	23/01/19 09:02	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
117	23/01/19 09:02	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
118	23/01/19 09:03	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
119	23/01/19 09:03	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
120	23/01/19 09:03	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
121	23/01/19 09:03	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
122	23/01/19 09:03	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
123	23/01/19 09:03	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
124	23/01/19 09:03	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
125	23/01/19 09:03	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
126	23/01/19 09:03	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
127	23/01/19 09:03	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
128	23/01/19 09:03	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
129	23/01/19 09:03	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
130	23/01/19 09:03	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
131	23/01/19 09:03	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
132	23/01/19 09:03	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
133	23/01/19 09:03	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
134	23/01/19 09:03	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	22/01/19 12:55	OI GIA REPORT	Load PDF	

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
				

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)
<div></div>
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AIG19001252/ECD3E2

Date: 28/01/2019

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.

Policy No: 2100504641

Claimant Vehicle No : SKU4845L

Insured Vehicle No : SGT775J

Date of Loss: 14/01/2019

Nature of Claim: TP

Claim No: 0852755147SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SKU4845L

Make & Model: LEXUS IS, 250 (A)

Engine No: 4GR0191969

Reg. Date: 30/05/2006 (Man. Year: 2006)

Chassis No: JTHBK262X02014143

Colour: White

Odometer: 145482 km

Engine Capacity: 2500 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes

Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/45 R17

Rear Tyre Size:

225/45 R17

Front Left Side: Michelin 5 mm

Rear Left Side:

Michelin 5 mm

Front Right Side: Michelin 5 mm

Rear Right Side:

Michelin 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 21/01/2019

Date Inspected: 21/01/2019 Inspected At:

My Car Consultant Pte Ltd (Ubi)

53 Ubi Ave 1, #01-24, Paya Ubi Industrial Park

Singapore 408934

Estimated Period of Repair: 9.0 days

Adjuster: CHEN TSUE YEE

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT NUMBER PLATE	Broken	0.00 F	*- F
2	1		*FRT NUMBER PLATE BASE	Cut	0.00 F	*- F
3	1		*FRT NUMBER PLATE GARNISH	Broken	0.00 F	*- F
4	1		*FRT BUMPER	Broken	0.00 F	*- F
5	1		*FRT BUMPER CLIPS	Necessary	0.00 F	*- F
6	2		*FRT BUMPER SIDE RETAINER	Broken	0.00 F	*- F
7	1		*FRT BUMPER SPONGE	Broken	0.00 F	*- F
8	1		*FRT GRILLE	Broken	0.00 F	*- F
9	1		*FRT GRILLE EMBLEM	Necessary	0.00 F	*- F
10	1		*FRT GRILLE CHROME MOULDING	Broken	0.00 F	*- F
11	1		*FRT SUPPORT PANEL	Bent	0.00 F	*- F
12	1		*FRT BRACE PANEL	Bent	0.00 F	*- F
13	1		*FRT LH HEADLAMP ASSY	Broken	0.00 F	*- F
14	1		*FRT RH HEADLAMP ASSY	Broken	0.00 F	*- F
15	1		*BONNET	Dented	0.00 F	*- F
16	1		*BONNET LOCK	Bent	0.00 F	*- F
17	1		*AIR CON CONDENSER	Bent	0.00 F	*- F
18	1		*RADIATOR	Bent	0.00 F	*- F
19	1		*RADIATOR FAN ASSY	Broken	0.00 F	*- F
20	1		*AIR DUCT	Cut	0.00 F	*- F
21	1		*AIR CLEANER ASSY	Broken	0.00 F	*- F
22	1		*AIR CLEANER HOSE	Distorted	0.00 F	*- F
23	1		*FRT LH FENDER	Repair	0.00 F	*- F
24	1		*FRT RH FENDER	Repair	0.00 F	*- F
25	1		*REAR BUMPER	Broken	0.00 F	*- F
26	1		*REAR BUMPER CLIPS	Necessary	0.00 F	*- F
27	1		*REAR BUMPER SIDE RETAINER	Broken	0.00 F	*- F
28	1		*REAR BUMPER REINFORCEMENT	Bent	0.00 F	*- F
29	1		*REAR BUMPER SPONGE	Crumpled	0.00 F	*- F
30	1		*REAR BUMPER REFLECTOR	Broken	0.00 F	*- F
31	2		*REVERSE SENSOR	Broken	0.00 F	*- F
32	1		*REAR END PANEL	Repair	0.00 F	*- F
33	1		*REAR END PANEL TOP GARNISH	Crumpled	0.00 F	*- F
34	1		*BOOTLID	Repair	0.00 F	*- F
35	3		*BOOTLID EMBLEM	Necessary	0.00 F	*- F
36	1		*BOOTLID LAMP LH	Broken	0.00 F	*- F
37	1		*BOOTLID LAMP RH	Broken	0.00 F	*- F
38	1		*BOOTLID LOCK	Bent	0.00 F	*- F
39	1		*BOOTLID RUBBER	Torn	0.00 F	*- F
40	1		*BOOTLID GARNISH	Broken	0.00 F	*- F

F=Franchise part.

Total Parts (S\$)	0.00	0.00
--------------------------	-------------	-------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >