

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	21/01/2019 12:14
Date Of Accident	20/01/2019 17:20
Exact Location Of Accident	TAMPINES ST 44 BLK 463 OPEN SPACE CARPARK
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SJV6282D
<b>Insured/Policyholder</b>	
Name Of Registered Owner	NG BOON CHWEE
NRIC No	S8338656H
Email Address	JOHNSON09115@GMAIL.COM
Mobile Phone No	(LOCAL) +65-97973898
Alternative Phone No	OTHERS-97973898

### Vehicle Particulars

Manufacturer	MITSUBISHI
Model	LANCER EX
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	REPORTING ONLY
Vehicle Category	PRIVATE CAR

### Insurance Company

Name of Insurance Company	MSIG INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	A 80454444 QMX
Cover Note Number	

### Driver

Name of Driver	NG BOON CHWEE
NRIC No	S8338656H
Date Of Birth	15/12/1983
Occupation	OUTDOOR
Date Of Driving Pass	06/04/2004
Driving Experience	14 YEARS AND 9 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-97973898
Fax Number	
Contact Number	OTHERS-97973898
Email Address	JOHNSON09115@GMAIL.COM

Address	BLK 463 TAMPINES ST 44 #02-86
Postcode	520463
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	- - -
Insurance Company of Driver's Own Vehicle	- - -

#### General Information of the Accident

Type Of Accident	SIDE SWIPE
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	4
Passenger 1	NAME: : ADRIAN GENDER: : MALE
Passenger 2	NAME: : ASHLEY GENDER: : FEMALE
Passenger 3	NAME: : EVELYN GENDER: : FEMALE

#### Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	TAMPINES NORTH NPP
Police Station Address	<b>ROAD:</b> 461 TAMPINES ST 44 #01-56 , <b>POSTCODE:</b> 520461 , <b>COUNTRY:</b> SINGAPORE
Police Station Contact	<b>TEL NO:</b> - <b>FAX NO:</b>
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

PLS REFER TO THE POLICE REPORT: T/20190120/2098

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SMG2096U
Vehicle Make/Model/Colour	

Details Of Properties

Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

### SKETCH PLAN

(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:

- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
- (ii) investigating the accident and/or my claims;
- (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
- (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
- (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")

(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and

(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

(d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.

(e) the information so collected under (d) above may be shared / disclosed:

- (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
- (ii) for complying with requirements under any regulations, laws or court orders.

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

## Accident Sketch Plan

### SKETCH PLAN

A - SSV62820  
B - SMG20964

TAMPINES ST 44 BLK 463  
OPEN SPACE CARPARK

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

1. A Blue Sedan was following me very closely at a high speed when I enter the carpool
2. While I was doing a reverse parking the car tried to overtake me from behind my blind spot resulting in a collision
3. No damage was observe from the Blue Sedan and no government property was damage and no passenger was injured.

## DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature  
Date & Time:

Driver's Signature \_\_\_\_\_  
(If driver is not the policyholder)  
Date & Time: \_\_\_\_\_

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

## Individual Statement



**SINGAPORE  
POLICE FORCE**



T/20190120/2098

Police Station Of Origin:  
Tampines North NPP  
461 Tampines Street 44 #01-56 SINGAPORE  
520461  
Tel No: 1800-7818999

2 of 3

Report No. T/20190120/2098

### CONTINUATION OF REPORT

#### **Brief Details.**

On 20/01/2019 at about 1720hrs, I was in my Black Mitsubishi (Reg No: SJV6282D) at the carpark of B/463 Tampines St 44 and was about reverse my vehicle into vehicle lot no: 266 when my vehicle side swipe a white (Blue SG Car) (Reg No: SMG2096U) driven by a male driver.

I did make a check on both side and rear mirrors before reversing to ensure that there was no vehicle. I reviewed my CCTV dash board camera which able to view from the front and rear of my vehicle and observed that the White SG Car Mark was at my blindspot area when I was reversing.

Both the driver and myself alighted from the vehicle to assess the damaged however I managed to handover my contact detail but the male driver refused to give his details. I observed that there were no damages to the white (Blue SG Car) and photo was taken as evidence.

No parties were injured during the incident

I managed to take down the white (Blue SG Car) registration number and lodging this report for insurance claims.

Damaged sustained:  
SJV6282D - slight dent on my left side front fender.



Accident Photo



Accident Photo





Accident Photo



Accident Photo



Accident Photo





Accident Photo





Accident Photo



Accident Photo



Accident Photo



Accident Photo





Accident Photo



Accident Photo



Accident Photo



# Police Report



**SINGAPORE  
POLICE FORCE**



T/20190120/2098

1 of 3

Police Station Of Origin:  
Tampines North NPP  
461 Tampines Street 44 #01-56 SINGAPORE  
520461  
Tel No: 1800-7818999

Report No. T/20190120/2098

## REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 20/01/2019 18:22			Vide Report No.:		Station Diary No.: 31
<b>Informant's Particulars</b>					
Name of Informant: NG BOON CHWEE			Address: APT BLK 463 TAMPINES STREET 44 #02-86 SINGAPORE 520463		
ID Type / ID No.: NRIC NO / S6338858H			Contact No.: Home/Office: Mobile: 97973898		
Nationality: SINGAPORE CITIZEN			Email:		
Sex: Male	Age: 35	Date of Birth: 15/12/1983	Type of Informant: Driver		
Race: Chinese			Language: English		Institution / School Name:
Occupation: Real estate agent			Driving Licence Information: Class: 2B,2A,2,3 Date of Expiry:		

## General Information of the Accident

Type of Accident:	Non-Injury Others	Drink Drive: No	Date/Time of Accident: 20/01/2019 17:20	Type of Location: Car Park
Location: Along Road 1 TAMPINES STREET 44 B/463 Tampines Street 44 Carpark				
Weather: Clear		Road Surface: Dry	Road Speed Limit:	
Traffic Flow:		Traffic Control: Not Controlled	Traffic Volume: No Traffic	
Type of Collision: Between Moving Vehicles - Side Swipe - Same Direction				Anyone conveyed by ambulance: No

## Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
SJV6282D	Car	MITSUBISHI	LANCER 1.5 MIVEC SPORTS AT ABS D/AB	Black	Slightly Damaged	1
SMG2098U	Car	BLUECAR	BLUECAR	White	No Damage	1



## Police Report



**SINGAPORE  
POLICE FORCE**



T/20190120/2096

Police Station Of Origin:  
Tampines North NPP  
461 Tampines Street 44 #01-56 SINGAPORE  
520461  
Tel No: 1800-7818999

2 of 3

Report No. T/20190120/2096

### CONTINUATION OF REPORT

#### Brief Details.

On 20/01/2019 at about 1720hrs, I was in my Black Mitsubishi (Reg No: SJV6282D) at the carpark of B/463 Tampines St 44 and was about reverse my vehicle into vehicle lot no: 266 when my vehicle side swipe a white (Blue SG Car) (Reg No: SMG2096U) driven by a male driver.

I did make a check on both side and rear mirrors before reversing to ensure that there was no vehicle. I reviewed my CCTV dash board camera which able to view from the front and rear of my vehicle and observed that the White SG Car Mark was at my blindspot area when I was reversing.

Both the driver and myself alighted from the vehicle to assess the damaged however I managed to handover my contact detail but the male driver refused to give his details. I observed that there were no damages to the white (Blue SG Car) and photo was taken as evidence.

No parties were injured during the incident

I managed to take down the white (Blue SG Car) registration number and lodging this report for insurance claims.

Damaged sustained:

SJV6282D - slight dent on my left side front fender.

## Police Report



**SINGAPORE  
POLICE FORCE**



T/20190120/2098

Police Station Of Origin:  
Tampines North NPP  
461 Tampines Street 44 #01-68 SINGAPORE  
520461  
Tel No: 1800-7818999

3 of 3

Report No. T/20190120/2098

CONTINUATION OF REPORT

### Sketch Plan

Informant is not able to provide sketch plan

**IMPORTANT:** Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report:

G /

Staff Sgt MUHAMMAD FIRDAUS BIN MISWAN

Signature Of Informant:

Signature Of Interpreter:

Not applicable

Date/Time:

20/01/2019 18:22

Officer In Charge Of Case:

TP / GIA /

Staff Sgt WONG SIEU LUI

Contact No.: 65476151

Classification Of Case:

Authentication Stamp

NP168

SIGNATURE

# Identification Card

