

ASS. REC. BY:

REF:

CS3/CTI19001260/Ged312

Special Instruction:

Surveyor:

Mirmir

Gao Qiang

ASSIGNMENT (Office)

From (Person)

Chong Boun Sen

of

CTE

Date/Time:

21/11/19 @ 9:11am

Estimated Cost:

Bill to:

OD (TP) WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SIF 69337

Insured:

SGD 2744U

at Workshop m/s

Sheng Ji Tai

Tel:

9111 9222

of

2 kaki Bukit Ave 2 # 01-36

Policy No:

Claim No:

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

15/01/19

CA / REV / REP. / REV 24 HRS

lwp

H.O.D. Endorsement:

Date/Time:

9:38am @ 21/1/19

Person Contacted:

Mr. Low

Vehicle

IN OUT

Date/Time

Action/Instruction (X) Estimate

SIF 69337 - X

SGD 2744U - X

Demantle: 23/1/2019

PRs

ASSIGNMENT

From: Date: 21/01/19

Veh No: SJF 6933T Yr Regn: 1591

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

Truck / Trailer or

To Inspect Vehicle No: SJF 6933T

Make: Hyundai Avante

at Workshop n/s Sheng Hi Jee

Colour: white

A/C: Insured / Std / NI / NA

of 2 Kaki Bukit Ave 2 # 01-36

Sp. Reading: 185 805

T/Radio: Insured / Std / NI / NA

Insured

Eng/No:

C/No: KM1101-41 BR 74434884

Policy No.

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Claims No.

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Sum Insured: Excess:

Tyre Size: F: 205/50 R16

(Client's Record)

R: 4

Make of Veh:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Achilles

(Policy Condition)

Front

Rear

R/Bal. 5 mm

R/Bal. 5 mm

Remark: The veh had commenced its repair at the time of inspection.

L/Bal. 5 mm

L/Bal. 5 mm

Bal. or Market Value: \$22k

D.O.A.

D.O.I. 21-01-19

IDAC Accident Report: Consistent?: Yes or No

Survey held at W/S 5pm

Des. of Damages: Front / Rear / O/S / N/S / U/C / Rooftop or

GIA / PR Seen: Consistent?: Yes or No

The U/C / Chassis frame / Body Structure affected due to collision.

Est. Repairs: 14 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS (up)

Date: Person Contacted: Vehicle: IN / OUT

Date / Time Action / Instruction

~~\$6000~~ \$7000 - \$8000

Date/Time, File Pass to?

Days Of Repair: 14

Resurvey No. of Trip: 1

1) ☐ : Preli. Report

Survey Fee: 150

2) ☐ : Final Report

Transportation: S + RS SI

Date/Time, File Return to?

Add Fee: ☐ : Site Insp (\$)

Photos

Others

Report Format: PRs

Lump Sum / I.B.I: (\$)

Weekend (\$)

TOTAL 150

Nivitha (LKK Auto)

From: Shu Pei (LKKAuto) <shupe@lkkauto.com>
Sent: Monday, 21 January 2019 9:11 AM
To: assignments
Subject: FW: [PRI] YOUR REF: EAL.2019.6146.MK.ya / OUR REF:SNM19D200322c02

Best Regards,

Shu Pei | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366-0055 | email: shupe@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Yvonne <yvonne@ealc.com.sg>
Sent: Friday, 18 January 2019 3:56 PM
To: Chong Boon Sen <boonsen.chong@sg.cntaiping.com>
Cc: Admin A <admin-a@lkkauto.com>
Subject: [PRI] YOUR REF: EAL.2019.6146.MK.ya / OUR REF:SNM19D200322c02

Our ref : 2019.6146.MK.ya - **SJF6933T(2ND)**
Your ref : **SGD2744U(3RD)**

PLEASE REPLY VIA EMAIL (yvonne@ealc.com.sg)

China Taiping Insurance
(Singapore) Pte. Ltd.
No. 3 Anson Road,
#16-00 Springleaf Tower,
Singapore 079909
Attn: Motor Claims Department
2 DAYS' PRE-REPAIR NOTICE

Surveyor from M/s China Taiping Insurance (Singapore) Pte. Ltd. Vehicle SJF6933T(2ND) inspected as follows by Name:		
Before repair	Parts removed	After repair
_____	_____	_____
Signature	Signature	Signature
Date/ Time:	Date/ Time:	Date/ Time:

Dear Sir/Madam,

NOTICE TO THIRD PARTY INSURERS FOR PRE-REPAIR NOTICE

CLAIMANT: FUCHI PTE LTD

ACCIDENT INVOLVING SJF6933T(2ND) & SGD2744U(3RD) & SFY8890S(1ST) ON 15 JANUARY 2019 ALONG PIE TOWARDS TUAS
AFTER TOA PAYOH LORONG 6 EXIT AT ABOUT 1350 HOURS

We refer to the above matter wherein we are instructed to act for **FUCHI PTE LTD**, the owner of vehicle no. **SJF6933T(2ND)**.

There is no agreement to the surveyors proposed by parties.

Our client's vehicle **SJF6933T(2ND)** is available as follows, please call prior appointment for the pre-repair inspection:

M/s Sheng Li Lai
No. 2 Kaki Bukit Ave 2,
#01-36 Autohub Kaki Bukit,
Singapore 417921.

Tel: 91119222 (Mr Low)

Please arrange for the pre-repair inspection on the damaged vehicle within 2 working days from the time of notification, excluding Saturdays, Sundays and public holidays.

Regards,
Yvonne Ang

East Asia Law Corporation
No. 133 New Bridge Road, #10-02 Chinatown Point, Singapore 059413
Tel: 63232565 Fax: 63232373

Confidentiality Notice: This e-mail is confidential. It may also be legally privileged.

If you are not the addressee or to whom it is intended, you may not copy, forward, disclose or use any part of it.

If you have received this message in error, please delete the message and all copies from your system and notify the sender immediately by return e-mail.

From: Chong Boon Sen <boonsen.chong@sg.cntaiping.com>
Sent: Friday, 18 January 2019 2:18 PM
To: Yvonne <yvonne@ealc.com.sg>
Cc: Admin A <admin-a@lkkauto.com>
Subject: YOUR REF: EAL.2019.6146.MK.ya / OUR REF:SNM19D200322c02

Without Prejudice
Save as to costs

Dear Yvonne,

We will use LKK. Can you kindly assist to provide workshop details pls.

Dear LKK,

Pls pri.

Regards,
Chong Boon Sen
Claims Executive
Claims

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #16-00 Springleaf Tower
Singapore 079909
Co. Reg. No. 200208384E
DID: 63896171
Fax: 62247175
Email: boonsen.chong@sg.cntaiping.com
Website: www.sg.cntaiping.com

Disclaimer :

This message is confidential; its contents do not constitute a commitment by China Taiping Insurance (Singapore) Pte. Ltd. except where provided for in a written agreement between you and China Taiping Insurance (Singapore) Pte. Ltd. Any unauthorized disclosure, use or dissemination, either in whole or partial, is prohibited. If you are not the intended recipient of the message, please notify the sender immediately.

[> Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	0925K
Vehicle Details	
Vehicle No.:	SJF6933T
Vehicle to be Exported:	No
Intended Deregistration Date:	22 Jan 2019
Vehicle Make:	HYUNDAI
Vehicle Model:	HD AVANTE 1.6 A
Primary Colour:	White
Manufacturing Year:	2008
Engine No.:	G4FC8U381812
Chassis No.:	KMH DU41BR7U434884
Maximum Power Output:	89.7 kW (120 bhp)
Open Market Value:	\$13,010.00
Original Registration Date:	07 Jun 2008
First Registration Date:	07 Jun 2008
Transfer Count:	3
Actual ARF Paid:	\$13,010.00
Intended PARF Rebate Details	
PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	31 May 2023
COE Category:	A - Car (1600cc & below)
COE Period(Years):	5
PQP Paid:	\$19,096.00
COE Rebate Amount:	\$16,642.00
Total Rebate Amount:	\$16,642.00
Message	
Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 22 Jan 2019

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	15/01/2019 15:06
Date Of Accident	15/01/2019 13:50
Exact Location Of Accident	PIE TOWARDS TUAS AFTER TOA PAYOH LORONG 6 EXIT
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SJF6933T
Insured/Policyholder	
Name Of Registered Owner	FUCHI PTE LTD
Co Reg No	200720925K
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-67470251

Vehicle Particulars

Manufacturer	HYUNDAI
Model	AVANTE-1.6 HD (A)

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY
Vehicle Category COMMERCIAL VEHICLE

Insurance Company

Name of Insurance Company	EQ INSURANCE COMPANY LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	DMPPHQ18-003128
Cover Note Number	07/06/2018 TO 06/06/2019

Driver

Name of Driver	CHENG ZHIXIANG
NRIC No	S7780923F
Date Of Birth	05/09/1977
Occupation	INDOOR
Date Of Driving Pass	08/07/2005
Driving Experience	13 YEARS AND 6 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-92385260
Fax Number	
Contact Number	
E-Mail Address	JASONCHENG@FUCHI.COM.SG

Address	APT BLK 335 SERANGOON AVE 3 #04-327 (S) 550335
Postcode	
Was driver an employee of the Insured's Company	YES
If No, Relationship of the Driver with the Insured	
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

refer with attach.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SGD2744U
Vehicle Make/Model/Colour	PROTON WAJA
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	THAN HUANG KWEE
NRIC/Passport Number	S6973187B
Contact Number	93677123
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	1

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number	SFY8890S
-----------------------------	----------

Vehicle Make/Model/Colour	MAZDA
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

Accident Sketch Plan Pg. 1

SKETCH PLAN


IMPORTANT NOTICE


1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


Policyholder's Signature
Date & Time:


Driver's Signature
(If driver is not the policyholder)
Date & Time: 15.01.2019, 15:16


Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Accident Sketch Plan Pg. 1

SKETCH PLAN



A: SJF6933T

B: SHD2744U

C: SFY8890S

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Cars in front of me stop moving, I follow to stop. car behind hit the back of my car. I am not sure whether my car had any contact with the car in front. The owner of car in front alighted and checked his car before moving off. However, there is no exchange of contact or particulars.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time: 15.01.2019, 15:16

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:



...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	18 Jan 2019		25 Jan 2019 16:39 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	----------

CLAIM SUBFOLDER DETAILS		[Created by insurer]
Insured:	-, Co. Reg. No.: -	
Main Claimant:	FUCHI PTE LTD , Co. Reg. No.: 200720925K	
Vehicle Reg. No.:	SJF6933T	Date of Loss: 15/01/2019 13:00 - :59 [127 Months and 8 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / SNM19D200322C02	Policy/Cover Note No.: DMPCSN17102718011
Vehicle Reg. No. (Insured):	SGD2744U	Policy No. (Claimant): DMPPHQ18-003128
		Excess: S\$0.00
Repairer:	Sheng Li Hai (HQ) BLK 1067 EUNOS AVE 4 #01-210, 409801 Eunos - Tel: 68420302	
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Chong Boon Sen]	
Claimant's Insurer:	EQ Insurance Company Ltd (HQ) - Tel: 6223 9433	
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Final Rpt due 07/02/2019]	



















































ASSOCIATED MAIL RECEIVED	View All	Compose Case Mail
There are no mail for this case.		



















































ALL ASSOCIATED TASKS										View All	Search Tasks	Create New Task	Complete
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?				
No results.													




































Claim Documents

*SJF6933T (SNM19D200322C02)
[SGD2744U]
TP
FUCHI PTE LTD
Jan 15 2019 1:00PM
[-]
Sheng Li Hai

Upload Documents			Upload Photos		Compose New Letter		View		View in Browser	
Video							1 per page		<input checked="" type="checkbox"/>	
No	Finalized On	Kan Fook Sing Motor Workshop (Defu)						Thumbnail	Print	
1	15/01/19 17:13	Video - Accident [Linked Accident Report Documents]						Load MP4		
Assessment Reports							1 per page		<input checked="" type="checkbox"/>	
No	Finalized On	Kan Fook Sing Motor Workshop (Defu)						Thumbnail	Print	
1	15/01/19 17:14	Accident Statement						Load HTM		
Photos/Images							3 per page		<input checked="" type="checkbox"/>	
No	Finalized On	Kan Fook Sing Motor Workshop (Defu)						Thumbnail	Print	
1	15/01/19 17:04	Accident Photo [Linked Accident Report Documents]						Load JPG	<input checked="" type="checkbox"/>	
2	15/01/19 17:04	Accident Photo [Linked Accident Report Documents]						Load JPG	<input checked="" type="checkbox"/>	
3	15/01/19 17:04	Accident Photo [Linked Accident Report Documents]						Load JPG	<input checked="" type="checkbox"/>	
4	15/01/19 17:04	Accident Photo [Linked Accident Report Documents]						Load JPG	<input checked="" type="checkbox"/>	
5	15/01/19 17:04	Accident Photo [Linked Accident Report Documents]						Load JPG	<input checked="" type="checkbox"/>	
6	15/01/19 17:04	Accident Photo [Linked Accident Report Documents]						Load JPG	<input checked="" type="checkbox"/>	
7	15/01/19 17:04	Accident Photo [Linked Accident Report Documents]						Load JPG	<input checked="" type="checkbox"/>	
8	15/01/19 17:04	Accident Photo [Linked Accident Report Documents]						Load JPG	<input checked="" type="checkbox"/>	
9	15/01/19 17:04	Accident Photo [Linked Accident Report Documents]						Load JPG	<input checked="" type="checkbox"/>	
10	15/01/19 17:04	Accident Photo [Linked Accident Report Documents]						Load JPG	<input checked="" type="checkbox"/>	
11	15/01/19 17:04	Accident Photo [Linked Accident Report Documents]						Load JPG	<input checked="" type="checkbox"/>	
12	15/01/19 17:04	Accident Photo [Linked Accident Report Documents]						Load JPG	<input checked="" type="checkbox"/>	
13	15/01/19 17:04	Accident Photo [Linked Accident Report Documents]						Load JPG	<input checked="" type="checkbox"/>	
14	15/01/19 17:04	Accident Photo [Linked Accident Report Documents]						Load JPG	<input checked="" type="checkbox"/>	
15	15/01/19 17:04	Accident Photo [Linked Accident Report Documents]						Load JPG	<input checked="" type="checkbox"/>	
16	15/01/19 17:04	Accident Photo [Linked Accident Report Documents]						Load JPG	<input checked="" type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)						Thumbnail	Print	
1	28/01/19 09:55	General View						Load JPG	<input checked="" type="checkbox"/>	
2	28/01/19 09:55	General View						Load JPG	<input checked="" type="checkbox"/>	
3	28/01/19 09:55	General View						Load JPG	<input checked="" type="checkbox"/>	
4	28/01/19 09:55	General View						Load JPG	<input checked="" type="checkbox"/>	
5	28/01/19 09:55	General View						Load JPG	<input checked="" type="checkbox"/>	
6	28/01/19 09:55	General View						Load JPG	<input checked="" type="checkbox"/>	
7	28/01/19 09:55	General View						Load JPG	<input checked="" type="checkbox"/>	

Video			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Kan Fook Sing Motor Workshop (Defu)	Thumbnail	Print
8	28/01/19 09:55	General View	 Load JPG	<input checked="" type="checkbox"/>
9	28/01/19 09:55	General View	 Load JPG	<input checked="" type="checkbox"/>
10	28/01/19 09:55	General View	 Load JPG	<input checked="" type="checkbox"/>
11	28/01/19 09:55	General View	 Load JPG	<input checked="" type="checkbox"/>
12	28/01/19 09:55	General View	 Load JPG	<input checked="" type="checkbox"/>
13	28/01/19 09:55	General View	 Load JPG	<input checked="" type="checkbox"/>
14	28/01/19 09:55	General View	 Load JPG	<input checked="" type="checkbox"/>
15	28/01/19 09:55	General View	 Load JPG	<input checked="" type="checkbox"/>
16	28/01/19 09:55	General View	 Load JPG	<input checked="" type="checkbox"/>
17	28/01/19 09:55	General View	 Load JPG	<input checked="" type="checkbox"/>
18	28/01/19 09:55	General View	 Load JPG	<input checked="" type="checkbox"/>
19	28/01/19 09:55	General View	 Load JPG	<input checked="" type="checkbox"/>
20	28/01/19 09:55	General View	 Load JPG	<input checked="" type="checkbox"/>
21	28/01/19 09:55	General View	 Load JPG	<input checked="" type="checkbox"/>
22	28/01/19 09:55	General View	 Load JPG	<input checked="" type="checkbox"/>
23	28/01/19 09:55	General View	 Load JPG	<input checked="" type="checkbox"/>
24	28/01/19 09:55	General View	 Load JPG	<input checked="" type="checkbox"/>
25	28/01/19 09:55	General View	 Load JPG	<input checked="" type="checkbox"/>
26	28/01/19 09:55	General View	 Load JPG	<input checked="" type="checkbox"/>
27	28/01/19 09:55	General View	 Load JPG	<input checked="" type="checkbox"/>
28	28/01/19 09:55	General View	 Load JPG	<input checked="" type="checkbox"/>
29	28/01/19 09:55	General View	 Load JPG	<input checked="" type="checkbox"/>
30	28/01/19 09:55	General View	 Load JPG	<input checked="" type="checkbox"/>
31	28/01/19 09:55	General View	 Load JPG	<input checked="" type="checkbox"/>
32	28/01/19 09:55	General View	 Load JPG	<input checked="" type="checkbox"/>
33	28/01/19 09:55	General View	 Load JPG	<input checked="" type="checkbox"/>
34	28/01/19 09:55	General View	 Load JPG	<input checked="" type="checkbox"/>
35	28/01/19 09:55	General View	 Load JPG	<input checked="" type="checkbox"/>
36	28/01/19 09:55	General View	 Load JPG	<input checked="" type="checkbox"/>
37	28/01/19 09:55	General View	 Load JPG	<input checked="" type="checkbox"/>
38	28/01/19 09:55	General View	 Load JPG	<input checked="" type="checkbox"/>
39	28/01/19 09:55	General View	 Load JPG	<input checked="" type="checkbox"/>
40	28/01/19 09:55	General View	 Load JPG	<input checked="" type="checkbox"/>
41	28/01/19 09:55	General View	 Load JPG	<input checked="" type="checkbox"/>
42	28/01/19 09:55	General View	 Load JPG	<input checked="" type="checkbox"/>
43	28/01/19 09:55	General View	 Load JPG	<input checked="" type="checkbox"/>
44	28/01/19 09:55	General View	 Load JPG	<input checked="" type="checkbox"/>
45	28/01/19 09:55	General View	 Load JPG	<input checked="" type="checkbox"/>
46	28/01/19 09:55	General View	 Load JPG	<input checked="" type="checkbox"/>
47	28/01/19 09:55	General View	 Load JPG	<input checked="" type="checkbox"/>
48	28/01/19 10:20	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
49	28/01/19 10:20	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
50	28/01/19 10:20	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
51	28/01/19 10:20	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
52	28/01/19 10:20	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
53	28/01/19 10:20	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
54	28/01/19 10:20	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
55	28/01/19 10:20	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
56	28/01/19 10:20	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
57	28/01/19 10:20	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>

Video			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Kan Fook Sing Motor Workshop (Defu)	Thumbnail	Print
58	28/01/19 10:20	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
59	28/01/19 10:20	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
60	28/01/19 10:20	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
61	28/01/19 10:20	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
62	28/01/19 10:20	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
63	28/01/19 10:20	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
64	28/01/19 10:20	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
65	28/01/19 10:20	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
66	28/01/19 10:20	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
67	28/01/19 10:20	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
68	28/01/19 10:20	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
69	28/01/19 10:20	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
70	28/01/19 10:20	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
71	28/01/19 10:20	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
72	28/01/19 10:20	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
73	28/01/19 10:20	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
74	28/01/19 10:20	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
75	28/01/19 10:20	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
76	28/01/19 10:20	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
77	28/01/19 10:20	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
78	28/01/19 10:20	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
79	28/01/19 10:20	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
80	28/01/19 10:20	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
81	28/01/19 10:20	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
82	28/01/19 10:20	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
83	28/01/19 10:20	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
84	28/01/19 10:20	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
85	28/01/19 10:20	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
86	28/01/19 10:20	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
87	28/01/19 10:20	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
88	28/01/19 10:20	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
89	28/01/19 10:20	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
90	28/01/19 10:20	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
91	28/01/19 10:20	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
92	28/01/19 10:20	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
93	28/01/19 10:20	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
94	28/01/19 10:20	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
95	28/01/19 10:20	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
96	28/01/19 10:20	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
97	28/01/19 10:20	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
98	28/01/19 10:20	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
99	28/01/19 10:20	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
100	28/01/19 10:20	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
101	28/01/19 10:20	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
102	28/01/19 10:20	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
103	28/01/19 10:20	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
104	28/01/19 10:20	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
105	28/01/19 10:20	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
106	28/01/19 10:20	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
107	28/01/19 10:20	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>

Video			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Kan Fook Sing Motor Workshop (Defu)	Thumbnail	Print
108	28/01/19 10:20	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
109	28/01/19 10:20	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
110	28/01/19 10:20	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
111	28/01/19 10:20	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
112	28/01/19 10:20	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
113	28/01/19 10:20	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
114	28/01/19 10:20	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
115	28/01/19 10:20	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
116	28/01/19 10:20	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
117	28/01/19 10:20	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
118	28/01/19 10:20	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
119	28/01/19 10:20	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
120	28/01/19 10:20	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
121	28/01/19 10:20	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
122	28/01/19 10:20	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
123	28/01/19 10:20	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
124	28/01/19 10:20	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
125	28/01/19 10:20	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
126	28/01/19 10:20	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
127	28/01/19 10:20	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
128	28/01/19 10:20	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
129	28/01/19 10:20	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
130	28/01/19 10:20	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
131	28/01/19 10:20	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
132	28/01/19 10:20	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
133	28/01/19 10:20	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
134	28/01/19 10:20	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
135	28/01/19 10:20	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
136	28/01/19 10:20	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Kan Fook Sing Motor Workshop (Defu)	Thumbnail	Print
1	15/01/19 17:07	Accident Sketch Plan [Linked Accident Report Documents]	 Load TIF	
2	15/01/19 17:07	Accident Sketch Plan [Linked Accident Report Documents]	 Load TIF	
3	15/01/19 17:07	certificate of insurance [Linked Accident Report Documents]	 Load TIF	
4	15/01/19 17:07	driver's nric & license [Linked Accident Report Documents]	 Load TIF	
5	15/01/19 17:07	driver's nric & license [Linked Accident Report Documents]	 Load TIF	
No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	25/01/19 16:39	PRS CONTACT	 Load PDF	

Linked Accident Report Documents

Video			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Kan Fook Sing Motor Workshop (Defu)	Thumbnail	Print
1	15/01/19 17:13	Video - Accident	 Load MP4	
Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Kan Fook Sing Motor Workshop (Defu)	Thumbnail	Print
1	15/01/19 17:14	Accident Statement	 Load HTM	

Video			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Kan Fook Sing Motor Workshop (Defu)	Thumbnail	Print
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Finalized On	Kan Fook Sing Motor Workshop (Defu)	Thumbnail	Print
1	15/01/19 17:04	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
2	15/01/19 17:04	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
3	15/01/19 17:04	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
4	15/01/19 17:04	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
5	15/01/19 17:04	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
6	15/01/19 17:04	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
7	15/01/19 17:04	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
8	15/01/19 17:04	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
9	15/01/19 17:04	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
10	15/01/19 17:04	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
11	15/01/19 17:04	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
12	15/01/19 17:04	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
13	15/01/19 17:04	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
14	15/01/19 17:04	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
15	15/01/19 17:04	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
16	15/01/19 17:04	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Kan Fook Sing Motor Workshop (Defu)	Thumbnail	Print
1	15/01/19 17:07	Accident Sketch Plan	Load TIF	
2	15/01/19 17:07	Accident Sketch Plan	Load TIF	
3	15/01/19 17:07	certificate of insurance	Load TIF	
4	15/01/19 17:07	driver's nric & license	Load TIF	
5	15/01/19 17:07	driver's nric & license	Load TIF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/CTI19001260/GCD3E2

Date: 28/01/2019

REFERENCE

Handling Insurer: China Taiping Insurance
(Singapore) Pte. Ltd.

Policy No: DMPCSN17102718011

Claimant Vehicle
No: SJF6933TInsured Vehicle
No: SGD2744U

Date of Loss: 15/01/2019

Nature of Claim: TP

Claim
No: SNM19D200322C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SJF6933T

Make & Model: HYUNDAI AVANTE, 1.6 HD (A)

Reg. Date: 07/06/2008 (Man. Year: 2008)

Colour: White

Engine Capacity: 1591 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

Engine No: G4FC8U381812

Chassis No: KMHDU41BR7U434884

Odometer: 185805 km

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/50 R16 Rear Tyre Size: 205/50 R16
Front Left Side: Achilles 5 mm Rear Left Side: Achilles 5 mm
Front Right Side: Achilles 5 mm Rear Right Side: Achilles 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 25/01/2019

Date Inspected: 21/01/2019 Inspected At:

Sheng Li Hai (HQ)
2 KAKI BUKIT AVE 2
#01-36 KAKI BUKIT AUTOHUB
SINGAPORE 417921

Estimated Period of Repair: 14.0 days

Adjuster: XING GUO QIANG

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$7,000.00 -\$8,000.00

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 28 Jan 2019)
Parts:	143	HYUNDAI AVANTE 1.6 HD (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJF6933T)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >