





Team: ARC Repair TP(CLS0)1	<b>JOB CARD</b>	Sales Order:	JO NO: 305261375
STOMER:	REGD NO: SH 8566P	MILEAGE:	
VMS: COMFORT TRANSPORTATION PTE LTD	MAKE: TOYOTA	FUEL: E 1/2 F	
STOMER NO: 7010045	MODEL: PRIUS HYBRID(G4)	DATE/TIME IN: 18.01.2019 13:30	
DRESS: 383 SIN MING DRIVE	YR OF MANU: 03.10.2017	TARGET DATE:	
Singapore SINGAPORE 575717	CHASSIS CODE: JTDKB3FU003565037	COMPLETION DATE/TIME:	
65508755			
IRI: (B)			
IP1:			
ICOUNT CARD NO:			

JOB DESCRIPTION


Accident Date: 17.01.2019

NATURE: 3P 17.01.2019

S/NO LABOR CODE

AXA - Rear

DESCRIPTION



CHECKED & PASSED OUT BY:

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

Acknowledgement Slip

Exit Pass

By

at

File No:

SH 8566P

LARRY

Vehicle No:

SH 8566P

Larry Ng

Signature of Service Advisor

Signature/Date

Name of Service Advisor

Date

I returned to Service Reception upon collection

To be kept by Security Guard

## COMFORTDELGRO ENGINEERING PTE LTD

## REPAIR ESTIMATE\*

VEHICLE NO : SH 8566P

DATE: 18. Jan. 2019

MAKE : TOYOTA

MODEL : PRIUS

DOA: 17. Jan. 2019

AXA

Qty	Parts Description/ Labour	Type	Unit Price	Amount
1	Rear Bumper ✓			\$458.60
1	Rear Bumper Beam ?			\$318.80
1	Rear Bumper Sponge ✕			\$143.40
10	Rear Bumper Clips ✓		\$2.20	\$22.00
1	Rear Bumper Undercover ✓			\$552.60
1	Rear End Panel ✕			\$602.10
	Rear Spare Tyre Panel ✕			\$667.70
2	Rear Bumper Side Retainer ✕		\$112.70	\$225.40
1	Rear Bumper Tow Cover ✓			\$82.70
SUB TOTAL				\$3,073.30
LESS 20%				\$614.66
DISCOUNTED TOTAL				\$2,458.64
1	Reverse Sensor ✓			\$135.70
				Nett
				\$135.70
Labour Charge				300
1	Panel Beating			<del>\$750.00</del>
1	Spray Painting Charge			<del>\$400.00</del>
1	Remove/refix reverse sensor			<del>\$100.00</del>
1	Tuff Kote			<del>\$100.00</del>
TOTAL LABOUR				\$1,350.00
ESTIMATE TOTAL				\$3,944.34
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.				



Kahar (16/1)

20/1/19 mark

2 by

Pir Before Part photo

Larry Ng

# COMFORTDELGRO ENGINEERING

Our Job Ref No : 305261375

Date : 23. Jan. 2019

ComfortDelGro Engineering Pte Ltd  
59 Loyang Drive, Singapore 508969  
Fax: 6546 8156

## FINALIZATION FORM

To : LKK

Fax :

Attn : KALVIN

Vehicle Reg No. : SH 8566P

Date of Accident: 17. Jan. 2019

The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-

1. The repair job shall bill to: AXA SKT3911R

2. The finalized amount shall be:

(a) Spare Parts after List discount \$1,014.00

(b) Labour Charges \$530.00

**Total for Part-By-Part Repair Cost \$1,544.00**

(c.) Lumpsum Repair (if applicable)

Total for Lumpsum repair cost after Less: \_\_\_\_\_

**Final Lumpsum Repair cost** \_\_\_\_\_

3. Estimated normal period for repairs: 2 working days.

4. We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days

5. Thank you for your assistance.

We confirm the estimates and finalized amount

Signature : 

Name : Larry Ng

Tel : 6214 8316

Fax : 6546 8156

Signature : 

Name : Kahr

Date : 23/1/19

## For Official Use Only

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid				
3. Survey Fees				
4. LTA Search Fee				
5. Medical Fees (on behalf of driver, if applicable)				
6. Overrun				

Remarks:

*Final Amount subject to Insurance Approval*

## COMFORTDELGRO ENGINEERING PTE LTD

## REPAIR ESTIMATE

Date: 23.01.2019

Time: 12:46:39

Page: 1

COMPANY : THIRD PARTY'S CLAIMS (CAS)  
CUSTOMER: 7010045  
ADDRESS : COMFORT TRANSPORTATION PTE LTD  
383 SIN MING DRIVE  
SINGAPORE SINGAPORE 575717  
65508755

JOB NO : 305261375  
REGN NO : SH 8566P  
MILEAGE : 0000000000  
MAKE : TOYOTA  
MODEL : PRIUS HYBRID(G4)  
DATE OF REGN : 03.10.2017  
DATE/TIME IN : 18.01.2019 13:30  
ACCIDENT DATE : 17.01.2019

## JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

## PART REQUISITION

0001 04-01-0302-2282-G	PRIG4 COVER REAR BUMPER	1	458.60	25.00	343.95
0002 04-01-0302-2287-G	PRIG4 GUARD-REAR BUMPER C	1	552.60	25.00	414.45
0003 04-01-0302-2267-G	PRIVC BUMPER PIECE	10	22.00	25.00	16.50
0004 04-01-0302-2288-G	PRIG4 REINFORCEMENT SUB-A	1	318.80	25.00	239.10

SUB-TOTAL : 1,014.00

## JOB NATURE

0000 L	PANEL BEATING	300.00
0001 23-502	SPRAYPAINT ON AFFECTED AREA	200.00
0002 L	REMOVE/REFIX REVERSE SENSOR	30.00

SUB-TOTAL : 530.00

TOTAL : 1,544.00

AUTHORISED : YES / NO

MVA NAME & SIGNATURE  
DATE :

SURVEYOR NAME & SIGNATURE  
DATE :

## REPAIR ESTIMATE\*

VEHICLE NO : SH 8566P

DATE: 18. Jan. 2019

MAKE : TOYOTA

MODEL : PRIUS

DOA: 17. Jan. 2019

AXA

Qty	Parts Description/ Labour	Type	Unit Price	Amount
1	Rear Bumper			\$458.60
1	Rear Bumper Beam			\$318.80
1	Rear Bumper Sponge			\$143.40
10	Rear Bumper Clips		\$2.20	\$22.00
1	Rear Bumper Undercover			\$552.60
1	Rear End Panel			\$602.10
	Rear Spare Tyre Panel			\$667.70
2	Rear Bumper Side Retainer		\$112.70	\$225.40
1	Rear Bumper Tow Cover			\$82.70
SUB TOTAL				\$3,073.30
LESS 20% <i>25%</i>				\$614.66
DISCOUNTED TOTAL				\$2,458.64
1	Reverse Sensor <i>x skc</i>			\$135.70
				Nett
				\$135.70
Labour Charge				300
1	Panel Beating			\$750.00
1	Spray Painting Charge			\$400.00 <i>200</i>
1	Remove/refix reverse sensor			\$100.00 <i>70</i>
1	Tuff Kote			\$100.00 <i>x 1</i>
TOTAL LABOUR				\$1,350.00
ESTIMATE TOTAL				\$3,944.34
<p>This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.</p>				

Larry Ng

Kahai (Kah)

20/1/19 11:58h

2 by

Pip Return Part photo

TOTAL LABOUR

ESTIMATE TOTAL

## ◀ Service Request Details

Claim

S9M01B03 ✓

Reference

None ✎

Kavin

Loss Date

January 17, 2019

Request Date

January 19, 2019

Due Date

January 25, 2019

Vendor Name

LKK AUTO CONSULTANTS PTE LTD (TP)

Type of Loss

Third Party Vehicle Damage

Services

Pending verification - Direct Settlement

### Actions

Next Step

Agree to perform service

Declined Work

Accept Work

### Vehicle Information

Incident Vehicle Registration #

SH8566P

Make

TPVD TOYOTA



## Service Address

\*\*\*

## Primary Contact/Insured

TAN SHI QI, JACINTHA

BLK 333A ANCHORVALE LINK, #16-340, 541333, Singapore

## Claim Handler

ANG Richard

richard.angbs@axa.com.sg

Additional Instructions

My Claims

Invoice

History

Documents

Assessment

Metrics

Notes

No Documents

**Catherine Chong (LKK Auto)**

---

**From:** Ng Nyuk Phin <ngnp@cdge.com.sg>  
**Sent:** Friday, 18 January, 2019 4:55 PM  
**To:** SG AXA Insurance SM AXA SGP - Motor Survey  
**Cc:** Lim Kwok Eng  
**Subject:** SH 8566P VS SKT3911R (AXA) DOA: 17.01.2019  
**Attachments:** img-118165034-0001.pdf

**Categories:** SHEKHAR

Dear Motor Claims,

Please see attached Repair Estimate and SAS. Kindly arrange to survey the taxi at 59 Loyang Drive.

The taxi is at the rooftop carpark.

Regards,  
Larry Ng  
ComfortDelGro Engineering Pte Ltd  
Loyang Taxi Crash Repairs  
6214 8316

---

**From:** ApeosPort-IV C5570 <sbs-singnalling@sbstransit.com.sg>  
**Sent:** Friday, 18 January 2019 4:50 PM  
**To:** Ng Nyuk Phin  
**Subject:** Scan Data from CDG\_LO\_AW\_A5570

Number of Images: 11  
Attachment File Type: PDF

Device Name: ApeosPort-IV C5570  
Device Location:

---

This message and any attachments may contain confidential, privileged or proprietary information. If you are not the intended recipient, kindly notify us and delete this message and its attachments immediately, and please be advised that using, copying, distributing or disclosing any contents therein is not allowed. Statements pertaining to any matter outside our business are not to be taken as endorsed by ComfortDelGro Corporation Limited or its related companies. The comments/proposals provided are for discussion purposes only and are subject to approvals. Nothing herein shall constitute a binding agreement between the parties. Neither party shall be bound in any way to any term or condition except as agreed in a written agreement signed by the duly authorised representatives of both parties.

ComfortDelGro - a Green Office certified by the Singapore Environment Council - is committed to preserving the environment. We encourage you to print this only if necessary.

---

This message and any attachments may contain confidential, privileged or proprietary information. If you are not the intended recipient, kindly notify us and delete this message and its attachments immediately, and please be advised that using, copying, distributing or disclosing any contents therein is not allowed. Statements pertaining to any matter outside our business are not to be taken as endorsed by ComfortDelGro Corporation Limited or its related companies. The comments/proposals provided are for discussion purposes only and are subject to approvals. Nothing herein shall constitute a binding agreement between the parties. Neither party shall be bound in any way to any term or condition except as agreed in a written agreement signed by the duly authorised representatives of both parties.

ComfortDelGro - a Green Office certified by the Singapore Environment Council - is committed to preserving the environment. We encourage you to print this only if necessary.

ComfortDelGro Engineering Pte Ltd [Registration No. 199506048W]

---

Our Ref : T 0119/ SH 8566P /WT(st)

Your Ref :

Date : 30-Jan-19

CDGE Taxi Claims Dept  
59 Loyang Drive 4th Flr  
Singapore 508969

ComfortDelGro Engineering Pte Ltd  
205 Braddell Road Singapore 579701

Mainline +65 6383 6280  
Facsimile +65 6280 9735

www.cdge.com.sg

Company Registration No: 199900001W

**AXA Insurance Pte Ltd**  
8 Shenton Way  
#24-01, AXA Tower  
Singapore 068811

Attn : Motor Claims Department

WITHOUT PREJUDICE

Dear Sir

**ACCIDENT INVOLVING OUR TAXI SH 8566P YOUR INSURED SKT3911R  
AND OTHER SCV6919J ON 17.01.19**

We are the authorised repair workshop for Comfort Transportation Pte Ltd, the owner of motor vehicle No : SH 8566P which was involved in the captioned accident with your insured vehicle. The vehicle owner and the taxi driver concerned have requested and authorized us to assist them in presenting their claims against the party responsible for all applicable matters arising from the damage to the vehicle.

As the accident was caused by the negligent act of your insured driving : SKT3911R we are submitting these claim for your consideration on behalf of the claimants.

#### TAXI OWNER'S CLAIM

1	Cost of Repair	\$ 1,652.08
2	<u>5</u> days Loss of Rental @ <u>\$ 125.40</u> per day	\$ 627.00
3	Survey Report Fees <i>(Surveyed by M/s LKK)</i>	\$ -
4	GIA / LTA Search Fee	\$ 7.49
5	GIA / Police Report Fees	\$ -
6	Towing Fees	\$ -
Sub Total :		\$ 2,286.57

#### HIRER'S CLAIM

7	<u>5</u> days Loss of Income @ <u>\$ 80.00</u> per days	\$ 400.00
Total Claims:		\$ 2,686.57

We enclose herewith the following documents to support the claims: -

- a) Original repair bill and photocopies of photographs 7 pcs
- b) LTA search slip/s of :
- c) GIA / Police report/s of : SH 8566P
- d) Letter of authority from owner / hirer / operator
  - ( X ) Photocopy/s of Accident Scene Photo/s ( X ) Towing receipts
  - ( ) Witness statement/s ( x ) Rental Rate letter ( x ) Downtime/Mileage record

Kindly look into the matter and let us hear from you on the settlement of the said claims as soon as possible.

Please note that it is a condition of any settlement reached that it shall be without prejudice to any personal injury claim (if any) of the taxi driver.

Yours faithfully

*William Tan*

CDGE Claims Department

Tel: 6214 8737 Fax: 6214 1843 Email : williamtan@cdge.com.sg

This is a computer generated letter. No signature is required.

#### Workshops

**Braddell**  
205 Braddell Road  
Singapore 579701

**Loyang**  
59 Loyang Drive  
Singapore 508969

**Sin Ming**  
383 Sin Ming Drive  
Singapore 575717

**Pandan**  
45 Pandan Road  
Singapore 608286

**Ubi**  
320 Ubi Road 3  
Singapore 408649

**Senoko**  
24 Senoko Loop  
Singapore 758156

**Sungei Kadut**  
7 Sungei Kadut Way  
Singapore 728791

**Yishun**  
Yishun Industrial Park A  
Singapore 768732



Auto  
Consultants  
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

29 APRIL 2019

JACINTHA TAN SHI QI (CHEN SHIQI)  
BLK 333A ANCHORVALE LINK  
#16-340  
SINGAPORE 541333

Dear Sir/Madam,

OUR REF : CC4/ASM19001298/K1ha3q2  
YOUR REF : SKT3911R  
**ACCIDENT INVOLVING SKT3911R / SH8566P/ OTHERS ALONG PIE ON 17.01.2019**

We refer to the above subject matter. We write to inform you that we are the loss adjuster appointed by your motor insurer, AXA Insurance Pte Ltd to deal with the third-party claim against your policy.

We have received a claim from M/s COMFORTDELGRO ENGINEERING PTE LTD acting on behalf of the owner of SH8566P against your motor insurance policy.

Based on the accident report and accident scenario, it was reported that your vehicle had was involved in a 3 vehicle chain collision and your vehicle was the second vehicle. Pursuant to the above said accident wherein you and/or your authorized driver had amongst other information given us your version of how the accident had occurred, we as the appointed agent of your insurers shall proceed to negotiate for an amicable settlement with third party claimant.

You are aware that your No-Claim Discount (NCD – if applicable) will be withheld for the time being pending for final allocation of liability in settlement by our principal.

We shall proceed to deal with the claim(s) subject to the merits of the case and according to the rights afforded under the policy. Should you not be seeking the protection of your policy and seek to take conduct of third party claim(s) arising from this incident, at your own cost and defence, please reply to us within 7 days from the date of this letter.

Your full co-operation in the handling of the claim is required and kindly submit the following to [khanchna@lkkauto.com](mailto:khanchna@lkkauto.com) within 7 days from the date of this letter **if not provided at AXA's reporting centre**. The list below is not all inclusive and further document may be required:

- Police report, Police Investigation result, appeal against the Traffic Police offence and status (if any)
- Authorization Letter for the Driver to drive the vehicle
- Driver's driving license or foreign driving license (if any)
- Coloured photographs of accident scene (if any)



Auto  
Consultants  
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

- Coloured photographs of damage to all vehicles involved (If any)
- Video footage of accident (if any)
- Statement and/or police report from independent witness(es) (if any)
- If you or your passenger(s) are filing a claim against any of the involved Third Party(s), you are to keep us informed of your legal representative(s) and the status of the claim

To protect your interest(s) in the handling of this claim, please do not discuss liability with any of the Third Party(s) and/or their legal representatives, or make any compromise or settlement without AXA's prior knowledge and consent.

This letter should **not** be regarded as a waiver by AXA of their rights to repudiate any claim because of any breach of policy terms and conditions you and/or your authorised driver may have committed.

In the event of receiving and handling of any third party injury claim(s), AXA shall keep you informed of the final indemnity upon conclusion of the matter(s).

If you need any clarification, please do not hesitate to contact us at 6256 3561 or email us at [khanchna@lkkauto.com](mailto:khanchna@lkkauto.com).

Please quote the claim reference when you contact us that we can assist you more effectively.

Yours sincerely,

  
KHANCHNA  
Case Handler  
DID: 6841 2360  
FAX: 6741 4108  
Email: [khanchna@lkkauto.com](mailto:khanchna@lkkauto.com)

c.c. AXA Insurance Pte Ltd (AXA)  
(Motor Claims Dept)

## LETTER OF AUTHORISATION

(NAF / PAF)

**ACCIDENT INVOLVING** **TOYOTA PRIUS SH8566P , SKT3911R , SC... ON 17-Jan-19 18:20**  
**ALONG** **ALONG PIE**

I / We **SIM SWEE HONG @NG S...** (Hirer) NRIC No.: **S1577964J**

and/or **SIM SWEE HONG** (Relief) NRIC No.: **S1577964J**

Taxi Number **SH8566P**

hereby authorise ComfortDelGro Engineering Pte Ltd(CDGE):

1. To submit my/our claims for damages, costs and expense, including loss of income, loss of rental, medical fee and legal costs.
2. To have absolute discretion to agree to any settlement or compensation amount in respect of my/our claim against third party (except personal injuries and medical claims).
3. To sign Discharge Voucher on my/our behalf.
4. To accept any payment (claim proceeds) in respect of the claim against third party and payment by cheque shall be forward directly to CDGE in accordance with CDGE's instruction and made in favour of **"ComfortDelGro Engineering Pte Ltd"**.

Date **18-Jan-2019**

Name of Hirer **SIM SWEE HONG @NG SWEE HONG**  
Hirer NRIC **S1577964J**

Signature :




Address **484A CHOA CHU KANG AVE 5 #02-24**  
**681484**

Contact No. **96573588**

Name of Relief **SIM SWEE HONG**  
Relief NRIC **S1577964J**

Signature :



Address **484A CHOA CHU KANG AVE 5 #02-24**  
**681484**

Contact No.



### AXA THIRD PARTY DIRECT SETTLEMENT

Vehicle No:	SKT 3911R	(Insd veh)	Model: TOYOTA PRIUS HYBRID 4G
	SH 8566P	(TP veh)	
Date of Accident/ Time:	17/01/2019 / 18:20		

Repair Estimate	: S	4,222.44	
Final Repair Cost	: S		
Loss of Use	: S		days at S per day
Rental (if any)	: S		days at S per day
ETA / GIA Search Fee	: S		
Others	: S		
Final Settlement Sum	: S	2,440.00	Global Sum (All In)
Payee Name : COMFORTDELORO ENGINEERING PTE LTD			
Is Third Party Workshop GIA Registered? <input checked="" type="checkbox"/> YES <input type="checkbox"/> NO (Kindly indicate below)			
A)	For Non GIA Registered Workshop:	Agreed Liability: _____ (%)	
B)	For GIA Registered Workshop:	BOLA Applicable: Yes/ <del>No</del> BOLA Scenario No: <u>38</u>	
	BOLA Liability: 100 (%)	Assessed Liability (*): <u>0</u> (%)	
* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply			
Remarks:			

#### NOTE:

- PLEASE EXPRESSLY RESERVE YOUR CLIENT'S RIGHTS IF SO REQUIRED IN THIS SETTLEMENT DOCUMENT.
- THIS SETTLEMENT IS ON A WITHOUT PREJUDICE BASIS AND SHOULD NOT CONSTRUED AS AN ADMISSION OF LIABILITY ON AXA AND THEIR CLIENT/TORTFEASOR IN ANY MANNER WHATSOEVER.
- AXA RESERVES THEIR RIGHTS UNDER THE POLICY TERMS & CONDITIONS AS WELL AS THEIR RIGHTS IN LAW.

Only applicable to rental claim - All document are to be submitted with this settlement confirmation. In the event, rental agreement / invoices are **not received within 7 days** of this signed confirmation, we will automatically revert to loss of use claim per the NIMA rates.

We/I confirmed that this is a **full and final settlement** that we and or our client have/had/has against you (AXA and their policyholder/authorised driver/tortfeasor) for any and all losses (past/present/future) arising from this accident.

We confirmed that we have the authority of our client to act for and on their behalf in this accident.

Signature of workshop representative / Workshop stamp Name of Representative: COMFORTDELORO ENGINEERING PTE LTD Date: 15.5.19  Signature of AXA's surveyor/representative: Name of AXA's surveyor / Representative: Date: 22/5/19	Signature of Witness / Workshop stamp (if applicable) Name of Witness: Date: 15.5.19 COMFORTDELORO ENGINEERING PTE LTD 38 LOYANG DRIVE SINGAPORE 508569
--	--

Please forward your cheque made payable to:  
COMFORTDELORO ENGINEERING PTE LTD

The contents of this document apply to vehicle damages only  
All personal injuries and damages arising therefrom are excluded  
from the ambit and application of this document



## TAX INVOICE

COMPANY REG. NO.: 199506048W  
Page: 1

8010010

AXA INSURANCE PTE LTD

8 SHENTON WAY AXA TOWER #24-01  
SINGAPORE SG 068811

CONTACT NO: 63387288

VEHICLE NO  
SH 8566P

INV. NO/DATE  
91422727 28.01.2019

MAKE  
TOYOTA

JOB NO.  
305261375

MODEL  
PRIUS HYBRID(G4)

ODOMETER READING

DATE OF REG  
03.10.2017

DATE/TIME IN  
18.01.2019 13:30

CHASSIS CODE  
JTDKB3FU003565037

Description : 3P 17.01.2019

S/No	Part No.		Qty	Unit Price	%Disc	Net
PART REQUISITION						
0001	04-01-0302-2282	PRIG4 COVER REAR BUMPER	1	458.60	25.00	343.95
0002	04-01-0302-2287	PRIG4 GUARD-REAR BUMPER C	1	552.60	25.00	414.45
0003	04-01-0302-2267	PRIVC BUMPER PIECE	10	2.20	25.00	16.50
0004	04-01-0302-2288	PRIG4 REINFORCEMENT SUB-A	1	318.80	25.00	239.10
SUB-TOTAL			:			1,014.00

### JOB NATURE

0001	L	PANEL BEATING	300.00	300.00
0002	23-502	SPRAYPAINT ON AFFECTED AREA	200.00	200.00
0003	L	REMOVE/REFIX REVERSE SENSOR	30.00	30.00
SUB-TOTAL			:	530.00

WE HEREBY WARRANT ALL REPAIRABLE PRECAUTIONS AGAINST THE EFFECT OF ACCIDENTAL DAMAGES. THE COMPANY ACCEPTS NO RESPONSIBILITY FOR DAMAGE OR OTHER PROBLEMS BELONGING TO CUSTOMERS WHO REPAIRS ARE DONE AND TESTED A CUSTOMER NAME.

CUSTOMERS SHALL INSPECT THEIR VEHICLES IMMEDIATELY UPON DELIVERY AND SHALL, WITHIN 7 DAYS FROM SUCH DELIVERY, ADVISE IN WRITING TO THE COMPANY OF ANY COMPLAINTS. OTHERWISE, THE VEHICLE WILL BE DEEMED TO HAVE BEEN ACCEPTED IN GOOD ORDER.

INTEREST OF 1% PER MONTH WILL BE CHARGED FOR A DAY TO DAY BASIS IN RESPECT OF ANY AMOUNT DUE AND OWING TO THE COMPANY BY THE CUSTOMER AND NOT PAID ON THE DAY DUE OF PAYMENT (I.E. AFTER 30 DAYS FROM THE INVOICE FOR THE REPAIR OF DAMAGE).

PLEASE EXAMINE THIS INVOICE IMMEDIATELY UPON RECEIPT AND ADVISE THE COMPANY OF ALL DEFECTS OR DISCREPANCIES WITHIN 15 DAYS OF RECEIPT. IF THE COMPANY DOES NOT HEAR FROM THE CUSTOMER, THE COMPANY WILL TREAT THIS INVOICE AS CORRECT AND BINDING.

ComfortDelGro Engineering Pte Ltd  
A member of COMFORTDELGRO

Head Office:  
205 Braddell Road  
Singapore 579701

Kindly note that no receipt shall be issued unless requested.

CUSTOMER'S COPY

ACCOUNT No.	INVOICE No.	AMOUNT	BANK/CHQ No.
8010010	91422727	1,652.08	

GST REG. NO. M2-8921817-3

## TAX INVOICE

COMPANY REG. NO.: 199506048W  
 Page: 2

8010010

AXA INSURANCE PTE LTD

8 SHENTON WAY AXA TOWER #24-01  
 SINGAPORE SG 068811

CONTACT NO: 63387288

VEHICLE NO  
 SH 8566P

MAKE  
 TOYOTA

MODEL  
 PRIUS HYBRID(G4)

DATE OF REG  
 03.10.2017

CHASSIS CODE  
 JTDKB3FU003565037

INV. NO/DATE  
 91422727 28.01.2019

JOB NO.  
 305261375

ODOMETER READING

DATE/TIME IN  
 18.01.2019 13:30

Items total		1,544.00
Add GST @	7.000 %	108.08
Invoice amount		1,652.08

Issued by : CHEWRELENG 28.01.2019 11:26:35  
 Repair type : CLSO/57/57  
 Payment Type/Term: /Credit 30 days

ComfortDelGro Engineering Pte Ltd  
 A member of COMFORTDELGRO

Head Office:  
 205 Braddell Road  
 Singapore 579701

Kindly note that no receipt shall be issued unless requested.

CUSTOMER'S COPY

ACCOUNT No.	INVOICE No.	AMOUNT	BANK/CHQ No.
8010010	91422727	1,652.08	

Our Ref: CT19010518

Date: 28 January 2019



**TO WHOM IT MAY CONCERN**

Dear Sir/Madam

ACCIDENT ON 17/01/2019 @ 18:20 hrs  
ALONG ALONG PIE  
INVOLVING SKT3911R, SCV6919J

We refer to the above-mentioned accident and wish to inform that **Comfort Transportation Pte Ltd** is the registered owner of the taxi bearing vehicle registration number **SH8566P** (the "Taxi"). The Taxi was hired to **SIM SWEE HONG @NG SWEE HONG IC NO S1577964J** a registered hirer-operator of **Comfort Transportation Pte Ltd** at the time of occurrence of the aforementioned accident at a rental rate **\$125.40** per day (inclusive of GST).

Please be advised that the Taxi was insured with **MS First Capital Insurance Ltd** on a third party basis at the material time of the accident.

We wish to confirm that the aforesaid hirer-operator had obtained our permission to undertake repairs for damage on the Taxi arising from the said accident with a motor workshop of his choice.

Please liaise with the said hirer-operator or his authorized workshop directly for settlement of claims with third party's insurance company in respect of the said accident.

Yours faithfully

Christine Tay  
Assistant Manager, Fleet Safety

This is a computer generated letter. No signature is required.

MILEAGE READING			MILEAGE TRAVELLED (KM)		NAME OF DRIVER	MILEAGE READING		MILEAGE TRAVELLED (KM)	HOURS OPERATED (TIME)	
									FROM	TO
39	04	2	399		305261875	14	00	1400	13:30	14:30
39	45	4	412			00	00	0000		
39	89	3	439							
40	27	7	384							
40	65	6	379							
40	87	3	217							
41	12	7	254							
41	45	2	305							
41	84	8	395							
42	24	6	398							
42	60	4	358							

Enquire Vehicle Insurer

Vehicle No.	Incident Date/Time	Search Status	Insurance Company Code	Insurance Company Name
SKT3911R	17 Jan 2019 / 18:20:00	Successful	A12	AXA INSURANCE PTE LTD

Previous OK

### THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SKT 3911R (Insd veh)	Model:	TOYOTA PRIUS
	SH 8566P (TP veh)		
Date of Accident:	17/01/2019		

Global Sum Settlement	:	<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No
Repair Estimate	:	\$	4,220.44
Final Repair Cost	:	\$	1,652.08
Loss of Token Sum	:	\$	225.00
Rental (if any)	:	\$	564.30
LTA / GIA Search Fee	:	\$	7.49

Others:	:	\$	0.00
---------	---	----	------

	:	\$	
Final Settlement Sum (Global Sum)	:	\$	2,440.00

Is Third Party Workshop GIA Registered? ☒ YES ☐ NO (Kindly indicate below)

A) For Non GIA Registered Workshop:	Agreed Liability _____ (%)
B) For GIA Registered Workshop:	BOLA Applicable: Yes/ No BOLA Scenario No: _____
BOLA Liability: _____ 100 _____ (%)	Assessed Liability (*): _____ 0 _____ (%)
* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.	

Remarks  
\_\_\_\_\_  
\_\_\_\_\_

Payment Instruction: Payee's Breakdown		
1)	COMFORTDELGRO ENGINEERING PTE LTD	\$ 2,440.00

JOANNE LEE KHANG MIN  
LKK Auto Consultants Pte Ltd

10/06/2019  
Date


Please attach all the supporting documents to the form.  
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No: 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD			Ref : CC4/ASM19001298/K1ha3q2	
8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811 ATTN:RICHARD ANG			Date : 10-06-2019	
			Code : ASM	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
Insured Veh.	SKT 3911R	Veh. Inspected	SH 8566P	
Policy No.	GA386490	Coverage (\$)	0.00	
Claim No.	S9M01B03	Excess (\$)	0.00	
Assign From		Assign Date	19/01/2019	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model	TOYOTA PRIUS	c.c	1798	
Engine No.	HIDDEN	Year of Reg.	2017	
Chassis No.	JTDKB3FU003565037	Colour	BLUE	
Odometer	142684	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	FAIR			
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre	195/65 R15	WEST LAKE	7 mm	
L/H Front Tyre	195/65 R15	WEST LAKE	7 mm	
R/H Rear Tyre	195/65 R15	WEST LAKE	7 mm	
L/H Rear Tyre	195/65 R15	WEST LAKE	7 mm	
<b>4. Description of Damages</b>				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
<b>5. General Information</b>				
Accident Date	17/01/2019	Inspection Date	21/01/2019	
Survey held at	COMFORTDELGRO ENGINEERING PTE LTD 59 LOYANG DRIVE SINGAPORE 508969			
<b>5a. Remarks</b>				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
<b>5b. Estimate Days of Repair</b>				
ESTIMATED NORMAL PERIOD FOR REPAIR:		<b>2 Working Days</b>		

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

**ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SH 8566P**

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b><u>REPLACEMENT OF PARTS</u></b>				
1	REAR BUMPER (CONSISTENT)	DEFORMED	458.60	458.60
1	REAR BUMPER BEAM (CONSISTENT)	BENT	318.80	318.80
1	REAR BUMPER SPONGE (CONSISTENT)	NOT NECESSARY	143.40	-
10	REAR BUMPER CLIPS @\$2.20 (CONSISTENT)	NECESSARY	22.00	22.00
1	REAR BUMPER UNDERCOVER (CONSISTENT)	CRACKED	552.60	552.60
1	REAR END PANEL (CONSISTENT)	SERVICEABLE	602.10	-
1	REAR SPARE TYRE PANEL (CONSISTENT)	SERVICEABLE	667.70	-
2	REAR BUMPER SIDE RETAINER @\$112.70 (CONSISTENT)	SERVICEABLE	225.40	-
1	REAR BUMPER TOW COVER (CONSISTENT)	SERVICEABLE	82.70	-
	LESS 20% DISCOUNT		-614.66	-
	LESS 25% DISCOUNT		-	-338.00
			2,458.64	1,014.00
<b><u>SPECIAL NETT ITEMS</u></b>				
1	REVERSE SENSOR (SN)(CONSISTENT)	SERVICEABLE	135.70	-
			135.70	-
<b><u>LABOUR</u></b>				
	PANEL BEATING .		750.00	300.00
	SPRAY PAINTING CHARGE.		400.00	200.00
	REMOVE/REFIX REVERSE SENSOR .		100.00	30.00
	TUFF KOTE.	NOT NECESSARY	100.00	-
			1,350.00	530.00
<b>GRAND TOTAL</b>			<b>3,944.34</b>	<b>1,544.00</b>
<b>RECOMMENDED COST OF REPAIRS</b>				<b>1,544.00</b>

Report Ref No. CC4/ASM19001298/K1ha3q2

**KALVIN ANG WEI KUN**

Automotive Assessor / Investigator

**HO LEONG CHUAN**

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.







