



ComfortDelGro Engineering Pte Ltd

205 Braddell Road Singapore 579701

T 0119/ SH 8566P /WT(st) Our Ref:

Your Ref:

Date

Dear Sir

30-Jan-19

CDGE Taxi Claims Dept

59 Loyang Drive 4th Flr Singapore 508969

AXA Insurance Pte Ltd 8 Shenton Way

#24-01, AXA Tower

Singapore 068811

Attn: Motor Claims Department

WITHOUT PREJUDICE

SH 8566P which was involved in the captioned accident with your

ON 17.01.19

www.cdge.com.sg

Facsimilie +65 6280 9755

Braddell Singapore 579701

383 Sin Ming Drive Singapore 575717

Singapore 609286

Singapore 408649

24 Senoko Loo

Sungei Kadut 7 Sungei Kadut Way Singapore 728791

Yishun Singapore 768732

As the accident was caused by the negligent act of your insured driving: SKT3911R

AND OTHER SCV6919J

of motor vehicle No:

we are submitting these claim for your consideration on behalf of the claimants. TAXI OWNER'S CLAIM

\$ 1,652.08 Cost of Repair 1 \$ 627.00 days Loss of Rental @ 125.40 per day 2 5 \$ _ 3 Survey Report Fees (Surveyed by M/s LKK) 7.49 4 GIA / LTA Search Fee \$ 5 GIA / Police Report Fees \$

ACCIDENT INVOLVING OUR TAXI SH 8566P YOUR INSURED SKT3911R

We are the authorised repair workshop for Comfort Transportation Pte Ltd, the owner

insured vehicle. The vehicle owner and the taxi driver conderned have requested and authorized us to assist them in presenting their claims against the party responsible

6 Towing Fees

\$ 2,286.57 Sub Total:

HIRER'S CLAIM

days Loss of Income @

80.00 per days

\$ 400.00

Total Claims: \$ 2,686.57

We enclose herewith the following documents to support the claims: -

for all applicable matters arising from the damage to the vehicle.

Original repair bill and photocopies of photographs a)

pcs

LTA search slip/s of: b)

c) GIA / Police report/s of : SH 8566P

Letter of authority from owner / hirer / operator

(X) Photocopie/s of Accident Scene Photo/s

(X) Towing receipts

() Witness statement/s (x) Rental Rate letter (x) Downtime/Mileage record

Kindly look into the matter and let us hear from you on the settlement of the said claims as soon as possible.

Please note that it is a condition of any settlement reached that it shall be without prejudice to any personal injury claim (if any) of the taxi driver.

Yours faithfully

William Tan

CDGE Claims Department

Tel: 6214 8737 Fax: 6214 1843 Email: williamtan@cdge.com.sg

This is a computer generated letter. No signature is required.









LETTER OF AUTHORISATION

(NAF / PAF)

ACCIDENT INVOLVING TOYOTA PRIUS SH8566P , SKT3911R , SC... ON 17-Jan-19 18:20

ALONG

ALONG PIE

I / We

SIM SWEE HONG @NG S... (Hirer) NRIC No.: S1577964J

and/or

SIM SWEE HONG

(Relief) NRIC No.: **S1577964J**

Taxi Number

SH8566P

hereby authorise ComfortDelGro Engineering Pte Ltd(CDGE):

- 1. To submit my/our claims for damages, costs and expense, including loss of income, loss of rental, medical fee and legal costs.
- 2. To have absolute discretion to agree to any settlement or compensation amount in respect of my/our claim against third party (except personal injuries and medical claims).
- 3. To sign Discharge Voucher on my/our behalf.
- 4. To accept any payment (claim proceeds) in respect of the claim against third party and payment by cheque shall be forward directly to CDGE in accordance with CDGE's instruction and made in favour of "ComfortDelGro Engineering Pte Ltd".

Date

18-Jan-2019

Name of Hirer

SIM SWEE HONG @NG SWEE HONG

Hirer NRIC

Signature: S1577964J

Address

484A CHOA CHU KANG AVE 5 #02-24

681484

Contact No.

96573588

Name of Relief

SIM SWEE HONG

Relief NRIC

Signature: S1577964J

Address

484A CHOA CHU KANG AVE 5 #02-24

681484

Contact No.



A member of COMFORIDELGRO

GST REG. NO. M2-8921817-3

TAX INVOICE

ComfortDelGro Engineering Pte Ltd

205 Braddell Road Singapore 579701 Mainline + 65 6383 6280 Facsimile + 65 6280 9755

Workshops

S9 Loyang Drive Singapore 508969 383 Sin Ming Drive Singapore 575717 45 Pandan Road Singapore 609286 320 Ubi Road 3 Singapore 408649

24 Senoko Loop Singapore 758156 7 Sungei Kadut Way Singapore 728791 501 Yishun Industrial Park A Singapore 768732

COMPANY REG. NO.: 199506048W

200.00

530.00

80100 AXA I	10 NSURANCE PTE LTD		VEHCLE SH 8566		INV. NO/DATE 91422727 28.01.2019 JOB NO. 305261375		
8 SHE SINGA	NTON WAY AXA TOWE PORE SG 068811	R #24-01	MAKE TOYOTA				
CONTA	CT NO: 63387288	MODEL PRIUS H	YBRID(G4)	ODOMETER READING			
			DATE 0		DATE/TIME IN 18.01.2019 13:30		
Descr	iption : 3P 17.01	CHASSIS CODE JTDKB3FU003565037					
S/No	Part No.		Qty	Unit Price	%Disc	Net	
PART	REQUISITION						
0001	04-01-0302-2282	PRIG4 COVER REAR BUMPER	1	458.60	25.00	343.95	
0002	04-01-0302-2287	PRIG4 GUARD-REAR BUMPER C	1	552.60	25.00	414.45	
0003	04-01-0302-2267	PRIVC BUMPER PIECE	10	2.20	25.00	16.50	
0004	04-01-0302-2288	PRIG4 REINFORCEMENT SUB-A	1	318.80	25.00	239.10	
			SUB-TOTAL	:	1,0	14.00	
JOB N	ATURE						
0001 L		PANEL BEATING	300.00)		

SPRAYPAINT ON AFFECTED AREA

REMOVE/REFIX REVERSE SENSOR

ComfortDelGro Engineering Pte Ltd A member of COMFORTDELGRO

Head Office:

205 Braddell Road Singapore 579701

0002

0003

23-502

ACCOUNT No.	INVOICE No.	AMOUNT	BANK/CHQ No.		
8010010	91422727	1,652.08			
					

200.00

30.00

SUB-TOTAL

Kindly note that no receipt shall be issued unless requested.



A member of COMFORTDELGRO

GST REG. NO. M2-8921817-3

TAX INVOICE

ComfortDelGro Engineering Pte Ltd

205 Braddell Road Singapore 579701 Mainline + 65 6383 6280 Facsimile + 65 6280 9755

59 Loyang Drive Singapore 508969 383 Sin Ming Drive Singapore 575717 45 Pandan Road Singapore 609286 320 Ubi Road 3 Singapore 408649

24 Senoko Loop Singapore 758156 7 Sungei Kadut Way Singapore 728791 501 Yishun Industrial Park A Singapore 768732

COMPANY REG. NO.: 199506048W

Page:

8010010

AXA INSURANCE PTE LTD

8 SHENTON WAY AXA TOWER SINGAPORE SG 068811 #24-01

CONTACT NO: 63387288

VEHCLE NO SH 8566P

INV. NO/DATE 91422727 28.01.2019

MAKE TOYOTA JOB NO. 305261375

MODEL PRIUS HYBRID(G4) ODOMETER READING

DATE OF REG 03.10.2017

DATE/TIME IN 18.01.2019 13:30

CHASSIS CODE JTDKB3FU003565037

Items total

1,544.00

Add GST @

7.000 %

108.08

Invoice amount

1,652.08

Issued by : CHEWBEELENG 28.01.2019 11:26:35
Repair type : CLSO/57/57
Payment Type/Term: /Credit 30 days

ComfortDelGro Engineering Pte Ltd A member of COMFORTDELGRO

Head Office: 205 Braddell Road Singapore 579701

BANK/CHQ No. ACCOUNT No. INVOICE No. **AMOUNT** 1,652.08 91422727 8010010

Kindly note that no receipt shall be issued unless requested.

CUSTOMER'S COPY

Our Ref: CT19010518

Date: 28 January 2019



TO WHOM IT MAY CONCERN

Dear Sir/Madam

ACCIDENT ON

17/01/2019 @ 18:20 hrs

ALONG

ALONG PIE

INVOLVING

SKT3911R, SCV6919J

We refer to the above-mentioned accident and wish to inform that Comfort Transportation Pte Ltd is the registered owner of the taxi bearing vehicle registration number SH8566P (the "Taxi"). The Taxi was hired to SIM SWEE HONG @NG SWEE HONG IC NO S1577964J a registered hirer-operator of Comfort Transportation Pte Ltd at the time of occurrence of the aforementioned accident at a rental rate \$125.40 per day (inclusive of GST).

Please be advised that the Taxi was insured with **MS First Capital Insurance Ltd** on a third party basis at the material time of the accident.

We wish to confirm that the aforesaid hirer-operator had obtained our permission to undertake repairs for damage on the Taxi arising from the said accident with a motor workshop of his choice.

Please liaise with the said hirer-operator or his authorized workshop directly for settlement of claims with third party's insurance company in respect of the said accident.


Yours faithfully


Christine Tay Assistant Manager, Fleet Safety

This is a computer generated letter. No signature is required.

HOURS OPERATED (TIME)	FROM TO	15:30 [4:30										
MII EAGE	TRAVELLED (KM)	W.	and the same day									
	MILEAGE READING	905261375 14 W/MW/MW										
	NAME OF DRIVER	SF\$19C508										
	DATE	18 January 3019	22. Il 22 Jameny 2019									A STATE OF THE PROPERTY OF THE PARTY OF THE
	HOURS OPERATED (TIME)	FROM TO	-	000	6.30 30 3	3 7	DC OC 00.0.	6.40 32.10	6.35 33.00	7.10 22-40	6.50 (32-5%	では 大学の 日本の 日本の 日本の 日本の 日本の 日本の 日本の 日本の 日本の 日本
	MILEAGE	TRAVELLED (KIM)	1000	1139	384	2/4	784	SOL	396	398	328	STREET, STREET
		MILEAGE READING	2904	39893	40377	40656	40077	4 67 2	41848	42246	70961	

















Insurance Particulars Enquiry By Agents Detail

https://vrl.lta.gov.sg/lta/vrl/action/insPartDetailByAA?FUNCTIO...

Enquire Vehicle Insurer

Vehicle No. Incident Date/Time

Search Status

Insurance Company Code

Insurance Company Name

SKT3911R

17 Jan 2019 / 18:20:00

Successful

A12

AXA INSURANCE PTE LTD

Previous

OK