

ASS. REC. BY:

REF:

CS3/AIG19001300/Bcd3h

Special Instruction:

Survivor
member

Mr. Jim

ASSIGNMENT (Office)

From (Person):

Chin Lee Ying

of

AIG

Date/Time:

21/1/09 @ 11:29am

Estimated Cost:

Bill to:

OD (P) WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SFW 1126Y

Insured:

SLW 7287E

at Workshop m/s

MW Brothers

Tel:

96704479

of

2 Keki Bkt Ave 2 #02-02

Policy No:

1800018423

Claim No:

209966764886

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

18/1/19

CA / REV / REP. / REV 24 HRS

lup

Morning @ 22/1/19

H.O.D. Endorsement:

Date/Time:

3:22pm @ 21/1/19

Person Contacted:

Mr. Tan

Vehicle

IN OUT

Date/Time	Action/Instruction (X) Estimate
	SFW 1126Y - CCS/AIG 07001323/RDH
	SLW 7287E - X
	Dismantle: 23/1/2019

D.O.A: 27/1/09

REF:

AIG

ASSIGNMENT

From: Date: 22/1/19

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SFW 1126 Y

at Workshop m/s MW Bros

of 2 Kaki Bukit Ave, 02-02

Insured:

Policy No.

Claims No.


Sum Insured: Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 7 days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: Person Contacted:

Vehicle: IN / OUT

Veh No: SFW 1126 Y Yr Regn: 27/6/2005

Type: ☒ M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

DAR

Make: TOYOTA Vios

C.C. 1497

Colour: RED

A/C: Insured / Std / NI / NA

Sp. Reading: 203768

T/Radio: Insured / Std / NI / NA

Eng/No: INEX 290155

C/No: MR053 HY420A139459

Gen. Cond: Good / ☒ Fair / Poor / BurntSteering: ☒ In order / Jammed / Leaked / Burnt orBrake: ☒ In order / Jammed / Leaked / Burnt orModi: Nil / S/Rim / ☒ STD A/Rim or

Tyre Size: F: 185/65/14

R: 185/65/14

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or CS TIRES

Front

Rear

R/Bal. 5 mm

R/Bal. 5 mm

L/Bal. 5 mm

L/Bal. 5 mm

D.O.A. 18/1/19

D.O.I. 22/1/19

Survey held at MW Bros

Des. of Damages ☒ Front / ☒ Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

MV 11,000/2

PV 8,322/2

NV 2,678/2

TCM line
8/2/19

Date/Time, File Pass to?

☐ : Preli. Report

Days Of Repair: 7

1)

☐ : Final Report

Resurvey No. of Trip: 1

Date/Time, File Return to?

Survey Fee: 180

2)

Add Fee: ☐ : Site Insp (\$

Transportation:

) \$ + RS. SI

☐ : Interview (\$

) Photos

☐ : Tech. Invs (\$

) Others

☐ : Weekend (\$

)

Report Format: DAR

Lump Sum / I.B.I: (\$

TOTAL

190

Your Ref : SLW 7287E

Our Ref : SFW 1126Y/MW/ca/wl

Date : 21 January 2019

Fax : 6538 3708

Tel : 3152 0983

Email : accident@kscgp.com

AIG Asia Pacific Insurance Pte. Ltd.

BY EMAIL ONLY

DATE OF ACCIDENT: 18 JANUARY 2019

NOTICE TO INSURER TO CONDUCT PRE-REPAIR SURVEY / INSPECTIONS

We refer to your email of even date.

Please be informed that our client is not agreeable to your proposed motor surveyors. Instead we propose you to choose a surveyor from our client's list of surveyors as appended below:-

S/No.	Name of Surveyor	Company Name
1.	Dennis Yap	Pal's Appraiser Pte Ltd
2.	Michael Yap	Mc-Coy Appraiser Pte Ltd
3.	Andy Yap	LCW Appraiser Pte Ltd
4.	Dixon Yeo	Treasure Appraisal Services

Please be informed that if we do not hear from you within 2 working days from the date hereof, we will assume, as per the Protocol, that you have no objections to our list of motor surveyors. You will be deemed to have agreed to any of the above motor surveyors as a "single joint expert". We will inform you who the "single joint expert" is in due course.

If you object to our client's list of motor surveyors, we will accordingly inform the client to instruct his choice of motor surveyor to conduct the pre-repair survey. Also, please let us know within 2 working days excluding any intervening Saturday, Sunday and/or Public Holiday of your receipt of this notice whether you would like to conduct a pre-repair survey of the vehicle failing which our client will commence repairs thereafter without any further notice or reference to you. Please be informed that the said vehicle can be surveyed / inspected at:

Address : MW Brothers Auto Repair
2 Kaki Bukit Avenue 2
#02-02 Kaki Bukit Autohub
Singapore 417921

Contact Person/Tel : Mr Tan / 9670 4479

Yours faithfully,

WL

Your Ref : SLW 7287E

Our Ref : SFW 1126Y/MW/ca/wl

Date : 21 January 2019

Acknowledgement

This is to confirm that I _____ *[Full Name of Surveyor]* of
_____ *[Surveyor's Company]* have completed as follows:-

(a) Pre- Repair Survey/Inspection on _____ [Date] at _____ [Time].

Name and signature of Appointed Surveyor
Company Stamp

Witnessed by:
Date:

(b) Pre- Repair Survey/Inspection (during dismantling) on _____ [Date] at _____ [Time].

Name and signature of Appointed Surveyor
Company Stamp

Witnessed by:
Date:

(c) Re-inspection of new replacement part (part by part) on _____ [Date] at _____ [Time].

Name and signature of Appointed Surveyor
Company Stamp

Witnessed by:
Date:

(d) Post – Repair Survey/Inspection on _____ [Date] at _____ [Time].

Name and signature of Appointed Surveyor
Company Stamp

Witnessed by:
Date:




- PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURE...

From: Chin, Lee-Ying

To: assignments, Admin A

Cc: Fong, Andy-SY

Sent: 21/1/2019 11:29:36 AM

Attachments:  [1st PRS.PDF](#)  [GIA.PDF](#)  [2nd PRS.PDF](#)

Hi LKK,

Kindly assist to survey, vehicle in workshop.

Thanks.

Best Regards

Lee Ying, Chin

AIG

Claims | AIG Asia Pacific Insurance Pte. Ltd.

78 Shenton Way #08-16 Singapore 079120

Tel +(65) 6419 1947

Lee-Ying.Chin@aig.com | www.aig.sg

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	2575H
Vehicle Details	
Vehicle No.:	SFW1126Y
Vehicle to be Exported:	No
Intended Deregistration Date:	08 Feb 2019
Vehicle Make:	TOYOTA
Vehicle Model:	VIOS 1.5S A
Primary Colour:	Red
Manufacturing Year:	2005
Engine No.:	1NZX290155
Chassis No.:	MR053HY4204139459
Maximum Power Output:	80.0 kW (107 bhp)
Open Market Value:	\$13,893.00
Original Registration Date:	27 Jun 2005
First Registration Date:	27 Jun 2005
Transfer Count:	0
Actual ARF Paid:	\$15,283.00
Intended PARF Rebate Details	
PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	31 May 2020
COE Category:	A - Car (1600cc & below)
COE Period(Years):	5
PQP Paid:	\$31,722.00
COE Rebate Amount:	\$8,322.00
Total Rebate Amount:	\$8,322.00
Message	
Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 08 Feb 2019

OK

Dep 7540/4r

MV 11,000/2

PV 8,322/2

NV 2,678/2

line

8/2/19



Toyota Vios 1.5A E (COE till 09/2020) **\$13,800** **\$8,440 /yr** **28-Sep-2005** **1,497 cc** **-** **Sedan** **Available**

1 Owner Car. Up To 95% Loan, Immediate Approval. Original Car Paintwork! Extremely Well Maintained! Low Mileage. Accident Free. Don't Miss This Chance. Kindly Call Our Friendly Sales Person For Viewin...

PREMIUM AD

Posted: 31-Jan-2019 Tags: 2005 Toyota Vios, 2005 toyota vios, Toyota Vios, toyota vios, Toyota, Vios, vios, Used Toyota



Toyota Vios 1.5A E (New 5-yr COE) **\$26,800** **\$5,360 /yr** **09-Jan-2009** **1,497 cc** **95,000 km** **Sedan** **Available**

CNY Offer! Up To 100% Loan, Immediate Approval! Easy To Drive And Well Maintained! Very Smooth Transmission! 1 Of The Most Highest Demand And Reliable Car. Fuel Saving Yet Powerful Drive. STA/VICOM In...

PREMIUM AD

Posted: 31-Jan-2019 Tags: 2009 Toyota Vios, 2009 toyota vios, Toyota Vios, toyota vios, Toyota, Vios, vios, Used Toyota



Toyota Vios 1.5A E (New 5-yr COE) **\$25,800** **\$5,160 /yr** **15-Jan-2009** **1,497 cc** **-** **Sedan** **Available**

2.88%P.A Lowest Interest At \$468 Monthly For Toyota Vios. \$0 Admin Fees For All GV Purchase. 2 Years Warranty For Engine And Gearbox. Add Ons Available.

PREMIUM AD

GV Credit Pte Ltd

Posted: 31-Jan-2019 Tags: 2009 Toyota Vios, 2009 toyota vios, Toyota Vios, toyota vios, Toyota, Vios, vios, Used Toyota



Toyota Vios 1.5A E (COE till 12/2023) **\$25,800** **\$5,290 /yr** **26-Dec-2008** **1,497 cc** **125,000 km** **Sedan** **Available**

Monthly Payment Of \$563. Well Kept By Previous Owner. Car Done Up To Showroom Condition With Wear And Tear Parts Fixed. New Coat Of Paint With Beautiful Leather Seats Like New. We Offer The Highest Fo...

SmartCars Boutique Pte Ltd

Posted: 31-Jan-2019 Tags: 2008 Toyota Vios, 2008 toyota vios, Toyota Vios, toyota vios, Toyota, Vios, vios, Used Toyota



Toyota Vios 1.5A E (New 5-yr COE) **\$28,800** **\$5,760 /yr** **01-Sep-2008** **1,497 cc** **108,000 km** **Sedan** **Available**

Luxury White, Low Mileages Done, Well Maintain By Owner, No Repairs Needed, Perfect And Genuine Unit Available For Viewing. 6 Months Comprehensive Warranty Provided, 24/7 Free Towing Included. Trade I...

PREMIUM AD

Posted: 30-Jan-2019 Tags: 2008 Toyota Vios, 2008 toyota vios, Toyota Vios, toyota vios, Toyota, Vios, vios, Used Toyota



Toyota Vios 1.5A E (COE till 06/2021) **-** **N.A** **19-Jul-2006** **1,497 cc** **-** **Sedan** **SOLD**

High Paper Value, Safe Buy, Smooth Engine, Gear Box, Bank/In-House Loan And Competitive Insurance Available. Call Our Sales Team Now. Well Maintained By Previous Owner! All In Good Condition! High Trad...

Posted: 30-Jan-2019 Tags: 2006 Toyota Vios, 2006 toyota vios, Toyota Vios, toyota vios, Toyota, Vios, vios, Used Toyota



Toyota Vios 1.5A J (COE till 01/2024) **\$27,888** **\$5,640 /yr** **19-Jan-2009** **1,497 cc** **115,000 km** **Sedan** **Available**

No Gimmicks! Free 1 Servicing Upon Purchase! 1 Years Warranty Engine And Gearbox! 100% Loan Approval! Good Condition On Both Interior And Exterior. Comes With 5 Years COE. Call Us Now To Book A Breezy...

PREMIUM AD

Posted: 30-Jan-2019 Tags: 2009 Toyota Vios, 2009 toyota vios, Toyota Vios, toyota vios, Toyota, Vios, vios, Used Toyota



Toyota Vios 1.5A E (COE till 01/2024) **\$26,300** **\$5,310 /yr** **23-Jan-2009** **1,497 cc** **130,000 km** **Sedan** **Available**

COE Renewal Available! Well Kept And Maintained By Previous Owner, Original Paintwork, The Perfect Car For Your Daily Commute, Contact Our Name Sales Person Now For Viewing.

PREMIUM AD

Ka-Hup Vehicles Trading

Posted: 30-Jan-2019 Tags: 2009 Toyota Vios, 2009 toyota vios, Toyota Vios, toyota vios, Toyota, Vios, vios, Used Toyota



Toyota Vios 1.5A E (COE till 01/2024) **\$25,800** **\$5,230 /yr** **14-Jan-2009** **1,497 cc** **-** **Sedan** **Available**

2.88%P.A Lowest Interest At \$468 Monthly For Toyota Vios. \$0 Admin Fees For All GV Purchase. 2 Years Warranty For Engine And Gearbox. Add Ons Available.

PREMIUM AD

GV Credit Pte Ltd

Posted: 30-Jan-2019 Tags: 2009 Toyota Vios, 2009 toyota vios, Toyota Vios, toyota vios, Toyota, Vios, vios, Used Toyota



Toyota Vios 1.5A E (COE till 10/2020) **\$12,800** **\$7,540 /yr** **21-Oct-2005** **1,497 cc** **156,000 km** **Sedan** **Available**

One Year In House Warranty, Full Loan Available, Price Above Stated Is Actual Selling Price, Company Renew COE Cars Based On Car Condition, Accident Free, STA/VICOM Evaluation Are Welcome, Wear & Tear...

nway

Posted: 30-Jan-2019 Tags: 2005 Toyota Vios, 2005 toyota vios, Toyota Vios, toyota vios, Toyota, Vios, vios, Used Toyota

Select used cars to Compare or Add to Alert

Shortlist [2]


Toyota Vios 1.5A E (COE till 09/2020)
28-Sep-2005

Toyota Vios 1.5A E (COE till 10/2020)
21-Oct-2005

To compare cars, select from the search results.

To compare cars, select from the search results.

Add to Shortlist
Compare Now
Clear All



THE SCHEDULE

Private Car Insurance Policy

This Policy sets out the terms of a contract between NTUC Income Insurance Co-operative Limited (INCOME) and you (the Policyholder named in the schedule to this Policy).
The statements, information and declaration provided by you at the time of proposal shall form the basis of this contract.
We (INCOME) will provide the insurance set out in this Policy in respect of events occurring during the Period of Insurance shown in the Schedule and any further period for which we may accept a renewal premium.
The provision of this insurance is subject to:

1. any Endorsement specified as operative in the Schedule
2. the Conditions and General Exclusions of this Policy, and
3. the payment of the premium specified in the Schedule.

This Policy, the Schedule and the Certificate of Insurance are to be read together as one document.
GST Reg No. M4-0009030-8

Policy Number	5029199965-10		
The Policyholder	LAI KIT LOONG (LI JIELONG) 87 CLOVER WAY CLOVER PARK SINGAPORE 579136		
Period of Insurance	27 Jun 2018 To 26 Jun 2019		
Sum Insured	Market Value of Insured Vehicle at Time of Loss		
Premium (inclusive GST)	S\$564.17		
Interest Insured			
Cover Type	Third Party, Fire & Theft		
Primary Driver	LAI KIT LOONG (LI JIELONG)		
Named Driver (1)	GOH SIJAY MOY		
Named Driver (2)	LAI AH CHIN		
Make/Model	TOYOTA/VIOS	Capacity	1500cc
Registration Number	SFW1126Y	Registration Year	2005
Chassis Number	1NZK290155	Off-peak Car	No
Repair at Owner's Preferred Workshop	No	Insure with COE	Yes
Excess (Section 1)	N/A	NCD Entitlement	50%
Excess (Section 2)	N/A	NCD Protection	Yes(Free)
Additional Excess	N/A	Loyalty Discount	5%
Unnamed Driver Excess	N/A		
Hire Purchase Company	N/A		
Memo A	N/A		
Endorsement Operative	M2, M4		
Agency	INCOME - ANG MO KIO BRANCH (00000600293)		
Date of Issue	01 Jun 2018 20:50 hrs		

DUTY OF DISCLOSURE

We would remind you that you must disclose to us, fully and faithfully, the facts you know or ought to know, otherwise you may not receive any benefit from your Policy.

Signed in Singapore by order of the Board of Directors

Chief Executive

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	18/01/2019 15:12
Date Of Accident	18/01/2019 12:50
Exact Location Of Accident	JALAN ANAK BUKIT
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SFW1126Y
Insured/Policyholder	
Name Of Registered Owner	LAI KIT LOONG (LI JIELONG)
NRIC No	S8132575H
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-94386687
Alternative Phone No	OTHERS-94386687

Vehicle Particulars

Manufacturer	TOYOTA
Model	VIOS-1.5 S (A)

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY

Vehicle Category PRIVATE CAR

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	NO
Policy Number	5029199965-10
Cover Note Number	27/06/2018 TO 26/06/2019

Driver

Name of Driver	TAN KAI BENG,KELVIN (CHEN KAIMING,KELVIN)
NRIC No	S8032621A
Date Of Birth	03/11/1980
Occupation	INDOOR
Date Of Driving Pass	10/12/2001
Driving Experience	17 YEARS AND 1 MONTH
Gender	MALE
Mobile Number	(LOCAL) +65-90300011
Fax Number	
Contact Number	
Email Address	WHITEDEVILKAI11@GAMIL.COM

Address APT BLK 523 BUKIT BATOK ST 32 #04-707 (S) 650523

Postcode

Was driver an employee of the Insured's Company NO

If No, Relationship of the Driver with the Insured OTHER - BROTHER-IN-LAW

Vehicle Registration Number of Driver's Own Vehicle -

Insurance Company of Driver's Own Vehicle -

General Information of the Accident

Type Of Accident CHAIN COLLISION

Weather Conditions AFTER RAIN

Road Surface WET

Other Information

Was any foreign vehicle involved in this accident? NO

Number of vehicles (including own vehicle) involved in the accident 2

Was any body injured in the Accident? NO

Was any injured conveyed to hospital by ambulance?

Was any other material or property damaged? YES

I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO

Number of Passengers (Including Driver) 2

Passenger 1 NAME: : LAI SOAK CHAN (WIFE)

GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police? NO

If Yes, Please state which Police Station

Was notice of intended Prosecution given? NO

If Yes, against whom?

Circumstances of Accident

refer with attach.

Attachment(s)

Are accident photos available for attachment? YES

Was there any video captured by Car Camera? YES

Remarks/ Reasons: VIDEO FILE SIZE IS TOO LARGE, UNABLE TO UPLOAD

Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SLW7287E

Vehicle Make/Model/Colour KIA

Details Of Properties

Vehicle Category PRIVATE CAR

Name of Driver BAO YINPING

NRIC/Passport Number S8182812A

Contact Number 82186840

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

1

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number

SLT9582E

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category

PRIVATE CAR

Name of Driver

JOO HWANSOO

NRIC/Passport Number

G1689731R

Contact Number

90617901

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

2

Passenger 1

NAME: :

GENDER: :

Accident Sketch Plan Pg. 1

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:



SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I was following behind Vehicle A SLT9582E - the front vehicle stopped at the red light. I followed to stop behind. Suddenly my vehicle got hit from behind and the impact forced my vehicle to hit the front vehicle. The driver from the behind vehicle SLW7287E alighted and said she didn't break in time.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:



MOTORCAR (Rear)

Rear Portion

NAC	INC	Item	CON	AC	Qty
1137	993626	Rear Number Plate	✓		
1138	993627	Rear Number Plate Base			
1139	993630	Rear Number Plate Garnish			
1140	993632	Rear Number Plate Lamp			
1141	992958	Rear Bumper	DD	✓	
1142	993085	Rear Bumper Upper			
1143	993017	Rear Bumper Lower			
1144	993054	Rear Bumper Side	DL	✓	2
1145	993103	Rear Bumper Tow Cover			
1146	992341	Rear Bumper Clips	NEC	✓	
1147	992976	Rear Bumper Bracket			
1148	993068	Rear Bumper Side Retainer	NEC	✓	
1149	993045	Rear Bumper Reinforcement			
1150	992970	Rear Bumper Beam			
1151	993077	Rear Bumper Sponge			
1152	992999	Rear Bumper Damper			
1153	993040	Rear Bumper Protector			
1154	993036	Rear Bumper Pad			
1155	993026	Rear Bumper Moulding			
1156	993044	Rear Bumper Reflector			
1157	993023	Rear Bumper Lower Spoiler			
1158	994023	Reverse Sensor	✓		
1159	993327	Rear End Panel	DD	✓	
1160	993339	Rear End Panel Top Garnish	DL	✓	
1161	993333	Rear End Panel Inner Trim			
1162	990333	Boot Compartment Inner Trim			
1163	993851	Rear LH Taillamp			
1164	993853	Rear LH Taillamp Garnish			
1165	993859	Rear LH Taillamp Panel			
1166	995116	Rear RH Taillamp	RR	✓	
1167	993853	Rear RH Taillamp Garnish			
1168	993859	Rear RH Taillamp Panel			
1169	993554	Rear Apron Panel			
1170	992895	Bootlid	DD	✓	
1171	991328	Bootlid Emblem	NEC	✓	4
1172	990356	Bootlid Handle			
1173	995250	Bootlid Moulding			
1174	990376	Bootlid Reflector			
1175	995222	Bootlid Lamp LH			
1176	992899	Bootlid Lamp RH			
1177	995243	Bootlid Lock	✓		
1178	990377	Bootlid Rubber	✓		
1179	990382	Bootlid Hinge	✓		
1180	993877	Bootlid Spoiler			
1181	994543	Tailgate			
1182	991328	Tailgate Emblem			
1183	994643	Tailgate Outer Handle			
1184	994640	Tailgate Moulding			
1185	994545	Tailgate Garnish			
1186	994648	Tailgate Reflector			
1187	994549	Tailgate Lamp			
1188	994646	Tailgate Protector			
1189	994676	Tailgate Wiper Arm			
1190	994677	Tailgate Wiper Blade			
1191	994679	Tailgate Wiper Nozzle			
1192	994555	Tailgate Wiper Motor			
1193	994602	Tailgate Glass			
1194	994606	Tailgate Glass Rubber			
1195	994604	Tailgate Glass Moulding			
1196	994607	Tailgate Glass Sealant			
1197	994629	Tailgate Lock			
1198	994651	Tailgate Rubber			
1199	994611	Tailgate Hinge			
1200	994594	Tailgate Damper			
1201	994613	Tailgate Inner Board			

Vehicle No: SFW 11264

NAC	INC	Item	CON	AC	Qty
1202	993784	Spare Tyre Board			
1203	994328	Spare Tyre Panel	DD	✓	
1204	995065	Spare Tyre			
1205	994326	Spare Tyre Lock Screw			
1206	993787	Spare Tyre Cover			
1207	995323	Triangle Breakdown Sign			
1208	990507	CD Changer Assy			
1209	990164	Antenna			
1210	990534	Centre Exhaust Pipe Assy			
1211	990532	Centre Exhaust Mounting			
1212	993364	Rear Exhaust Pipe			
1213	993357	Rear Exhaust Chrome Pipe			
1214	993361	Rear Exhaust Mounting			
1215	993358	Rear Exhaust Heat Shield			
1216	995223	Rear LH Chassis Member			
1217	993165	Rear RH Chassis Member			
1218	993436	Rear LH Fender			
1219	993449	Rear LH Fender Protector			
1220	993420	Rear LH Fender Inner Panel			
1221	993431	Rear LH Fender Inner Trim	DIS	✓	
1222	993415	Rear LH Fender Inner Garnish			
1223	993425	Rear LH Fender Inner Shield			
1224	993621	Rear LH Mudflap			
1225	993933	Rear LH Wheel Rim			
1226	994025	Rear LH Rim Cover			
1227	995065	Rear LH Tyre			
1228	993456	Rear RH Fender			
1229	993450	Rear RH Fender Protector			
1230	993420	Rear RH Fender Inner Panel			
1231	993431	Rear RH Fender Inner Trim	DIS	✓	
1232	993415	Rear RH Fender Inner Garnish			
1233	993425	Rear RH Fender Inner Shield			
1234	993622	Rear RH Mudflap			
1235	993934	Rear RH Wheel Rim			
1236	994025	Rear RH Rim Cover			
1237	995065	Rear RH Tyre			
1238	995162	Rear Fender Extension Panel LH			
1239	993491	Rear Fender Extension Panel RH			
1240	993430	Rear Fender Inner Top Garnish			
1241	993673	Rear Fender 1/4 Glass			
1242	993452	Rear Fender 1/4 Glass Rubber			
1243	993453	Rear Fender 1/4 Glass Sealant			
1244	993949	Rear Windscreen Glass			
1245	993976	Rear Windscreen Rubber			
1246	993961	Rear Windscreen Moulding			
1247	993955	Rear Windscreen Sealant			
1248	994729	Third Brake Light			
1249	993385	Rear Fender Air Grille			
1250	992167	Fuel Lid			
1251	992168	Fuel Neck			
1252	992179	Fuel Tank			
1253	992184	Fuel Tank Bracket			
1254	992191	Fuel Tank Float			
1255	990247	Sticker			

No of Items: 16

Assessor: TGLM

23/1/19

MOTOR CAR (Frt)

Vehicle No: **SFW 11264**

Front Portion

NAC	INC	Item	CON	AC	Qty
1001	991886	Frt Number Plate	CRAY	✓	
1002	991887	Frt Number Plate Base	CRAY	✓	
1003	991889	Frt Number Plate Garnish			
1004	991300	Frt Bumper	CRAY	✓	
1005	992341	Frt Bumper Clips	NECV	✓	
1006	991325	Frt Bumper Bracket	RT	✓	
1007	991462	Frt Bumper Side Retainer	NECV	✓	
1008	991433	Frt Bumper Reinforcement	RT	✓	
1009	991318	Frt Bumper Beam	RT	✓	
1010	991468	Frt Bumper Sponge			
1011	991427	Frt Bumper Protector			
1012	991420	Frt Bumper Pad			
1013	991363	Frt Bumper Grille			
1014	991301	Frt Bumper Moulding			
1015	991407	Frt Bumper Lower Spoiler			
1016	991438	Frt Bumper Sensor			
1017	995100	Frt LH Bumper Fog Lamp Cover			
1018	991355	Frt RH Bumper Fog Lamp Cover			
1019	995079	Frt LH Bumper Fog Lamp			
1020	995080	Frt RH Bumper Fog Lamp			
1021	991793	Frt Grille			
1022	991328	Frt Grille Emblem			
1023	991799	Frt Grille Chrome Moulding			
1024	991222	Frt Apron Panel			
1025	992013	Frt Support Panel			
1026	992025	Frt Support Panel Top Garnish Cover			
1027	992416	Horn			
1028	991277	Frt Brace Panel			
1029	995153	Frt LH Headlamp Assy	BR	✓	
1030	991821	Frt RH Headlamp Assy	BR	✓	
1031	995088	Frt LH Side Lamp			
1032	995089	Frt RH Side Lamp			
1033	990248	Bonnet			
1034	991328	Bonnet Emblem			
1035	990287	Bonnet Lock			
1036	990285	Bonnet Insulator			
1037	990273	Bonnet Hinge			
1038	990261	Bonnet Damper			
1039	990305	Bonnet Rubber			
1040	990252	Bonnet Cable			
1041	990311	Bonnet Stand			
1042	990119	Air Con Condenser			
1043	990122	Air Con Fan Assy			
1044	990134	Air Con Suction Pipe (Low Pressure)			
1045	990118	Air Con Suction Hose			
1046	990133	Air Con Discharge Pipe (High Pressure)			
1047	990114	Air Con Discharge Hose			
1048	990149	Air Con Liquid Pipe			
1049	995066	Air Con Receiver Drier			
1050	990111	Air Con Compressor Assy			
1051	995294	Air Con Belt			
1052	995074	Radiator			
1053	992738	Radiator Cowling			
1054	992742	Radiator Fan Assy			
1055	992745	Radiator Fan Clutch			
1056	992758	Radiator Hose Top			
1057	992757	Radiator Hose Bottom			
1058	992741	Radiator Expansion Tank			
1059	990151	Air Duct			
1060	990070	Air Cleaner Assy			
1061	990056	Air Cleaner Hose			
1062	990089	Air Cleaner Resonator			
1063	991712	Frt Exhaust Manifold			
1064	991713	Frt Exhaust Manifold Cover			
1065	991054	Frt Exhaust Manifold Sensor (Oxygen)			
1066	991714	Front Exhaust Pipe			
1067	990219	Battery			
1068	990224	Battery Cover			
1069	990223	Battery Bracket			
1070	990229	Battery Tray			

NAC	INC	Item	CON	AC	Qty
1071	992205	Fuse Box			
1072	994011	Relay Box			
1073	995053	Wiper Washer Tank			
1074	995052	Wiper Washer Tank Motor			
1075	990159	Alternator Assy			
1076	990160	Alternator Belt			
1077	992688	Power Steering Pump			
1078	992669	Power Steering Belt			
1079	994431	Power Steering Cooler Pipe			
1080	992692	Power Steering Hose			
1081	990010	ABS Pump Control Unit			
1082	990427	Brake Master Pump Assy			
1083	990403	Brake Booster Pump Assy			
1084	991005	Engine Top Cover			
1085	991011	Engine Under Cover			
1086	990946	Engine Mounting			
1087	990949	Engine Mounting Frt			
1088	990950	Engine Mounting LH			
1089	990952	Engine Mounting RH			
1090	990951	Engine Mounting Rear			
1091	992234	Gear Box Mounting			
1092	991520	Frt LH Chassis Member			
1093	991520	Frt RH Chassis Member			
1094	990728	Frt Vertical Cross Member			
1095	991863	Frt Lower Cross Member			
1096	995070	Frt LH Fender			
1097	995072	Frt LH Fender Inner Panel			
1098	995147	Frt LH Fender Lamp			
1099	995148	Frt LH Fender Protector			
1100	991740	Frt LH Fender Inner Shield			
1101	995179	Frt LH Mudflap			
1102	995170	Frt LH Wheel Rim			
1103	994025	Frt LH Rim Cover			
1104	995065	Frt LH Tyre			
1105	995071	Frt RH Fender			
1106	991739	Frt RH Fender Inner Panel			
1107	991744	Frt RH Fender Lamp			
1108	991752	Frt RH Fender Protector			
1109	991740	Frt RH Fender Inner Shield			
1110	991884	Frt RH Mudflap			
1111	992087	Frt RH Wheel Rim			
1112	994025	Frt RH Rim Cover			
1113	995065	Frt RH Tyre			
1114	992093	Frt Windscreen Glass			
1115	992117	Frt Windscreen Rubber			
1116	992108	Frt Windscreen Moulding			
1117	992098	Frt Windscreen Sealant			
1118	991019	ERP Bracket			
1119	991020	ERP Unit			
1120	992140	Frt Wiper Arm			
1121	992142	Frt Wiper Blade			
1122	995045	Wiper Panel Garnish			
1123	991126	Firewall Panel			
1124	990753	Dashboard Assy			
1125	992282	Glove Box Cover			
1126	992281	Glove Box Compartment			
1127	994483	Steering Wheel Airbag			
1128	994485	Steering Wheel Airbag Sensor			
1129	990749	Dashboard Airbag			
1130	990750	Dashboard Airbag Sensor			
1131	990029	Airbag Control Unit			
1132	990864	Frt Driver Seat			
1133	991922	Frt RH Seat Belt Assy			
1134	991899	Frt Passenger Seat			
1135	995182	Frt LH Seat Belt Assy			
1136	990247	Sticker			

No of Items: **10**

Accessories:

TG/LIM

28/1/05

...CLAIM SUBFOLDER...(Pending for Survey Report)

PRI

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	21 Jan 2019 Edit Reg		21 Jan 2019 00:00 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured:	TAY JIA SHENG (ZHENG JIASHENG), ID: S8032690D								
Main Claimant:	LAI KIT LOONG (LI JIELONG), ID: S8132575H								
Vehicle Reg. No.:	SFW1126Y	Date of Loss:	18/01/2019 12:00 - :59 [162 Months and 22 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 2099667648SG	Policy/Cover Note No.:	1800018423 (Comprehensive) Coverage: 28/02/2018 - 19/09/2019						
Vehicle Reg. No. (Insured):	SLW7287E	Policy No. (Claimant):							
		Excess:							
Repairer:	Mw Brothers Auto Repair (kaki Bukit) (HQ) 2 KAKI BUKIT AVENUE 2, #02-02 KAKI BUKIT AUTOHUB, 417921 Kaki Bukit - Tel: 96704479								
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Lee, Ming-Yao] MingYao.Lee@aig.com								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by Lim Teow Guan] ... [Final Rpt due 30/01/2019]								
Insurer's Solicitor:	KSCGP JURIS LLP (HQ) - Tel: 65383611 ... Incoming Assignment								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
• AIG_SG (22/01/2019): TP GIA REPORT									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents



















































***SFW1126Y (2099667648SG)**
[SLW7287E]
TP
LAI KIT LOONG (LI JIELONG)
Jan 18 2019 12:00PM
[TAY JIA SHENG (ZHENG JIASHENG)]
Mw Brothers Auto Repair (kaki Bukit)
































Upload Documents
Upload Photos
Compose New Letter
Upload Video
Upload Audio

View View in Browser

Assessment Reports				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print	
1	22/01/19 13:10	Accident Statement <small>From: OD - Reg. No: SLW7287E, Claimant: TAY JIA SHENG (ZHENG JIASHENG)</small>	 Load HTM		

Photos/Images				3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print	
1	11/02/19 16:04	General View	 Load JPG	<input checked="" type="checkbox"/>	
2	11/02/19 16:04	General View	 Load JPG	<input checked="" type="checkbox"/>	
3	11/02/19 16:04	General View	 Load JPG	<input checked="" type="checkbox"/>	
4	11/02/19 16:04	General View	 Load JPG	<input checked="" type="checkbox"/>	
5	11/02/19 16:04	General View	 Load JPG	<input checked="" type="checkbox"/>	
6	11/02/19 16:04	General View	 Load JPG	<input checked="" type="checkbox"/>	
7	11/02/19 16:04	General View	 Load JPG	<input checked="" type="checkbox"/>	
8	11/02/19 16:04	General View	 Load JPG	<input checked="" type="checkbox"/>	
9	11/02/19 16:04	General View	 Load JPG	<input checked="" type="checkbox"/>	
10	11/02/19 16:04	General View	 Load JPG	<input checked="" type="checkbox"/>	
11	11/02/19 16:04	General View	 Load JPG	<input checked="" type="checkbox"/>	
12	11/02/19 16:04	General View	 Load JPG	<input checked="" type="checkbox"/>	
13	11/02/19 16:04	General View	 Load JPG	<input checked="" type="checkbox"/>	
14	11/02/19 16:04	General View	 Load JPG	<input checked="" type="checkbox"/>	
15	11/02/19 16:04	General View	 Load JPG	<input checked="" type="checkbox"/>	
16	11/02/19 16:04	General View	 Load JPG	<input checked="" type="checkbox"/>	
17	11/02/19 16:04	General View	 Load JPG	<input checked="" type="checkbox"/>	
18	11/02/19 16:04	General View	 Load JPG	<input checked="" type="checkbox"/>	
19	11/02/19 16:04	General View	 Load JPG	<input checked="" type="checkbox"/>	
20	11/02/19 16:04	General View	 Load JPG	<input checked="" type="checkbox"/>	
21	11/02/19 16:04	General View	 Load JPG	<input checked="" type="checkbox"/>	
22	11/02/19 16:04	General View	 Load JPG	<input checked="" type="checkbox"/>	
23	11/02/19 16:04	General View	 Load JPG	<input checked="" type="checkbox"/>	
24	11/02/19 16:04	General View	 Load JPG	<input checked="" type="checkbox"/>	
25	11/02/19 16:04	General View	 Load JPG	<input checked="" type="checkbox"/>	
26	11/02/19 16:04	General View	 Load JPG	<input checked="" type="checkbox"/>	
27	11/02/19 16:04	General View	 Load JPG	<input checked="" type="checkbox"/>	
28	11/02/19 16:04	General View	 Load JPG	<input checked="" type="checkbox"/>	
29	11/02/19 16:04	General View	 Load JPG	<input checked="" type="checkbox"/>	
30	11/02/19 16:04	General View	 Load JPG	<input checked="" type="checkbox"/>	
31	11/02/19 16:04	General View	 Load JPG	<input checked="" type="checkbox"/>	
32	11/02/19 16:04	General View	 Load JPG	<input checked="" type="checkbox"/>	
33	11/02/19 16:04	General View	 Load JPG	<input checked="" type="checkbox"/>	

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
34	11/02/19 16:04	General View	 Load JPG	<input checked="" type="checkbox"/>
35	11/02/19 16:04	General View	 Load JPG	<input checked="" type="checkbox"/>
36	11/02/19 16:04	General View	 Load JPG	<input checked="" type="checkbox"/>
37	11/02/19 16:04	General View	 Load JPG	<input checked="" type="checkbox"/>
38	11/02/19 16:04	General View	 Load JPG	<input checked="" type="checkbox"/>
39	11/02/19 16:04	General View	 Load JPG	<input checked="" type="checkbox"/>
40	11/02/19 16:04	General View	 Load JPG	<input checked="" type="checkbox"/>
41	11/02/19 16:04	General View	 Load JPG	<input checked="" type="checkbox"/>
42	11/02/19 16:04	General View	 Load JPG	<input checked="" type="checkbox"/>
43	11/02/19 16:04	General View	 Load JPG	<input checked="" type="checkbox"/>
44	11/02/19 16:04	General View	 Load JPG	<input checked="" type="checkbox"/>
45	11/02/19 16:04	General View	 Load JPG	<input checked="" type="checkbox"/>
46	11/02/19 16:04	General View	 Load JPG	<input checked="" type="checkbox"/>
47	11/02/19 16:04	General View	 Load JPG	<input checked="" type="checkbox"/>
48	11/02/19 16:04	General View	 Load JPG	<input checked="" type="checkbox"/>
49	11/02/19 16:04	General View	 Load JPG	<input checked="" type="checkbox"/>
50	11/02/19 16:04	General View	 Load JPG	<input checked="" type="checkbox"/>
51	11/02/19 16:04	General View	 Load JPG	<input checked="" type="checkbox"/>
52	11/02/19 16:04	General View	 Load JPG	<input checked="" type="checkbox"/>
53	11/02/19 16:04	General View	 Load JPG	<input checked="" type="checkbox"/>
54	11/02/19 16:04	General View	 Load JPG	<input checked="" type="checkbox"/>
55	11/02/19 16:04	General View	 Load JPG	<input checked="" type="checkbox"/>
56	11/02/19 16:04	General View	 Load JPG	<input checked="" type="checkbox"/>
57	11/02/19 16:04	General View	 Load JPG	<input checked="" type="checkbox"/>
58	11/02/19 16:04	General View	 Load JPG	<input checked="" type="checkbox"/>
59	11/02/19 16:04	General View	 Load JPG	<input checked="" type="checkbox"/>
60	11/02/19 16:04	General View	 Load JPG	<input checked="" type="checkbox"/>
61	11/02/19 16:04	General View	 Load JPG	<input checked="" type="checkbox"/>
62	11/02/19 16:04	General View	 Load JPG	<input checked="" type="checkbox"/>
63	11/02/19 16:04	General View	 Load JPG	<input checked="" type="checkbox"/>
64	11/02/19 16:04	General View	 Load JPG	<input checked="" type="checkbox"/>
65	11/02/19 16:04	General View	 Load JPG	<input checked="" type="checkbox"/>
66	11/02/19 16:04	General View	 Load JPG	<input checked="" type="checkbox"/>
67	11/02/19 16:04	General View	 Load JPG	<input checked="" type="checkbox"/>
68	11/02/19 16:04	General View	 Load JPG	<input checked="" type="checkbox"/>
69	11/02/19 16:04	General View	 Load JPG	<input checked="" type="checkbox"/>
70	11/02/19 16:04	General View	 Load JPG	<input checked="" type="checkbox"/>
71	11/02/19 16:04	General View	 Load JPG	<input checked="" type="checkbox"/>
72	11/02/19 16:04	General View	 Load JPG	<input checked="" type="checkbox"/>
73	11/02/19 16:04	General View	 Load JPG	<input checked="" type="checkbox"/>
74	11/02/19 16:04	General View	 Load JPG	<input checked="" type="checkbox"/>
75	11/02/19 16:04	General View	 Load JPG	<input checked="" type="checkbox"/>
76	11/02/19 16:04	General View	 Load JPG	<input checked="" type="checkbox"/>
77	11/02/19 16:04	General View	 Load JPG	<input checked="" type="checkbox"/>
78	11/02/19 16:04	General View	 Load JPG	<input checked="" type="checkbox"/>
79	11/02/19 16:04	General View	 Load JPG	<input checked="" type="checkbox"/>
80	11/02/19 16:04	General View	 Load JPG	<input checked="" type="checkbox"/>
81	11/02/19 16:04	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
82	11/02/19 16:04	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
83	11/02/19 16:04	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
84	11/02/19 16:04	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
85	11/02/19 16:04	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
86	11/02/19 16:04	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
87	11/02/19 16:04	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
88	11/02/19 16:04	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
89	11/02/19 16:04	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
90	11/02/19 16:04	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
91	11/02/19 16:04	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
92	11/02/19 16:04	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
93	11/02/19 16:04	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
94	11/02/19 16:04	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
95	11/02/19 16:04	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
96	11/02/19 16:04	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
97	11/02/19 16:04	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
98	11/02/19 16:04	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
99	11/02/19 16:04	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
100	11/02/19 16:04	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
101	11/02/19 16:04	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
102	11/02/19 16:04	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
103	11/02/19 16:04	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
104	11/02/19 16:04	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
105	11/02/19 16:04	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
106	11/02/19 16:04	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
107	11/02/19 16:04	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
108	11/02/19 16:04	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
109	11/02/19 16:04	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
110	11/02/19 16:04	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
111	11/02/19 16:04	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
112	11/02/19 16:04	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
113	11/02/19 16:04	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
114	11/02/19 16:04	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 100px; width: 100%;"></div>
Show Remarks To: <input type="checkbox"/> Handling Insurer <input type="checkbox"/> Insurer's Solicitor <small>Note: Remarks are private unless you show it to other parties.</small>

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AIG19001300/BCD3E2

Date: 14/02/2019

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.

Policy No: 1800018423

Claimant Vehicle No : SFW1126Y

Insured Vehicle No : SLW7287E

Date of Loss: 18/01/2019

Nature of Claim: TP

Claim No: 2099667648SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SFW1126Y

Make & Model: TOYOTA VIOS, 1.5 S (A)

Engine No: 1NZX290155

Reg. Date: 27/06/2005 (Man. Year: 2005)

Chassis No: MR053HY4204139459

Colour: Red

Odometer: 203768 km

Engine Capacity: 1497 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 185/65 R14

Rear Tyre Size: 185/65 R14

Front Left Side: CST TIRE 5 mm

Rear Left Side: CST TIRE 5 mm

Front Right Side: CST TIRE 5 mm

Rear Right Side: CST TIRE 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (\$\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 21/01/2019

Date Inspected: 22/01/2019 Inspected At:

Mw Brothers Auto Repair (kaki Bukit) (HQ)
2 KAKI BUKIT AVENUE 2, #02-02 KAKI
BUKIT AUTOHUB
Singapore 417921

Estimated Period of Repair: 7.0 days

Adjuster: Lim Teow Guan

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR NUMBER PLATE	Broken	0.00 F	*- F
2	1		*REAR BUMPER	Dented	0.00 F	*- F
3	2		*REAR BUMPER SIDE	Dislodged	0.00 F	*- F
4	1		*REAR BUMPER CLIPS	Necessary	0.00 F	*- F
5	1		*REAR BUMPER SIDE RETAINER	Necessary	0.00 F	*- F
6	2		*REVERSE SENSOR	Cut	0.00 F	*- F
7	1		*REAR END PANEL	Dented	0.00 F	*- F
8	1		*REAR END PANEL TOP GARNISH	Dislodged	0.00 F	*- F
9	1		*REAR RH TAILLAMP	Broken	0.00 F	*- F
10	1		*BOOTLID	Dented	0.00 F	*- F
11	4		*BOOTLID EMBLEM	Necessary	0.00 F	*- F
12	1		*BOOTLID LOCK	Bent	0.00 F	*- F
13	1		*BOOTLID RUBBER	Cut	0.00 F	*- F
14	1		*BOOTLID HINGE	* Check	0.00 F	*- F
15	1		*SPARE TYRE PANEL	Dented	0.00 F	*- F
16	1		*REAR LH FENDER INNER TRIM	Distorted	0.00 F	*- F
17	1		*REAR RH FENDER INNER TRIM	Distorted	0.00 F	*- F
18	1		*FRT NUMBER PLATE	Cracked	0.00 F	*- F
19	1		*FRT NUMBER PLATE BASE	Cracked	0.00 F	*- F
20	1		*FRT BUMPER	Cracked	0.00 F	*- F
21	1		*FRT BUMPER CLIPS	Necessary	0.00 F	*- F
22	1		*FRT BUMPER BRACKET	Bent	0.00 F	*- F
23	1		*FRT BUMPER SIDE RETAINER	Necessary	0.00 F	*- F
24	1		*FRT BUMPER REINFORCEMENT	Bent	0.00 F	*- F
25	1		*FRT LH HEADLAMP ASSY	Broken	0.00 F	*- F
26	1		*FRT RH HEADLAMP ASSY	Broken	0.00 F	*- F
27	1		*BONNET	Dented	0.00 F	*- F
Total Parts (\$\$)					0.00	0.00

F=Franchise part.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >