Rasna | REF: | 0647H

Work INVENT

From: Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SKM 6661D

at Workshop m/s: MOVA

of: 1008, BUKIT MERAH LN 3 #01-64

Insured: AXA

Policy No:

Claims No:

Sum Insured: Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

N/S	O/S

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: 19K

IDAC Accident Rport: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: Person Contacted:

Veh No: SKM 6661D Yr Regn: 2009 Jun

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer or

Make: HONDA CIVIC TYPE R 2.0M c.c 1998

Colour: BLACK A/C: Insured / Std / NI / NA

Sp.Reading: 187631 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: FD2160057 8

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Worder / Jammed / Leaked / Burnt or

Brake: Worder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 225/45R17

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front		Rear	
R/Bal.	6 mm	R/Bal.	6 mm
L/Bal.	6 mm	L/Bal.	6 mm
D.O.A.	16/01/19	D.O.I.	27/02/19

Survey held at: MOVA (BM)

Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time | Action / Instruction

repair limit 2k. refer to email

Date/Time. File Pass to? : Preli. Report

: Final Report

Date/Time. File Return to?

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation

Add Fee: Site Insp ($) $ +RS: $

Interview ($) Photos

Tech. Invs ($) Other

Weekend ($)

TOTAL

Report Format :

Lump Sum / LR F (S