Surveyor:	ASSIGNM	ENT (Office)	
From (Person): Onlithing Won	of	Msih	Date/Time: 21012019 4.0801
Estimated Cost:)	Bill to:	
OD / WS/TP RES/ OD RE	S/EVA/INV/MV7	CS	
To Inspect Vehicle No:	SGR 74337		Insured: FBM 217A
at Workshop m/s Him	Hong		Tel: 6745 9633
of Blk 2 Kal	si Bukit Ave 2	#02-13	
Policy No: MD / YMFT /18	-3811)48		MSC /V/19-00007
Sum Insured:		Excess:	
Make of Veh: (Client's Record)			P10C10F1_A.O.D
CA / REV / REP. / REV 24 H Date/Time: 21012019 1412pm	RS Wp Person Contacted:		H.O.D. Endorsement:
Date/Time Action/Instruction	(/) Estimate	ę	
ShR 7936] -	NA/ INC1900]1	20/h4	PIO12017 : AUG
- AFIG MBT			
23/1/9 Informed (oristina pendina	n oct for	n repairer by merimen

No results.

...CLAIM SUBFOLDER...(New Assignment)

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status	
Main	21 Jan 2019 10:17		21 Jan 2019 16:08 Assign				New Assig	
	Main	F	Reference		Claim Details	Doe	cuments	Show All
	UBFOLDER DET	TAILS					[Created by	insurer1
Insured:		MUHA	AMMAD FERROZY	BIN MOHD	SANUSI, ID: S8821	284C		
Main Clair	mant:			S2047347I				
Vehicle Re	eg. No.:	SGR	79333		Date of Loss:		17/01/2019 08 [143 Months a Reg Date (Man	and 2 Days From LT
Claim Typ	e:	TP /	MSC/V/19-0000	087	Policy/Cover Note No	.:	MSD/VMFT/18- Theft) Coverage: 14/ 13/06/2019	-384298 (TP, Fire & 06/2018 -
Vehicle Re	g. No. (Insured):	FBM2	17A		Policy No. (Claimant)		13/00/2013	
					Excess:			
Repairer:		Hiap I	Hong Motor Repa	ir () 2 Kaki	Bykit Avenue 2, #02-1	3, 417921 Kaki B	ukit - Tel:	
Handling I	Insurer:	MSIG 1311]	Insurance (Sing	apore) Pte.	Ltd. (HQ) - Tel: +65	6827 7888 [H	andled by Chri	stina Wong - 6643
Adjuster:		LKK A	uto Consultants	Pte Ltd (HC	2) - Tel: 6256-3561	Imm.Advice	due 22/01/	20191
Adj Asg. R	lemarks:	Liabilit	y down. TP want t	o use LKK Au	to Consultants as the	SJE. Contact No:	6745 9633.	2025]
	TED MAIN DEC							
1000 0000000000	TED MAIL REC					Vi	ew All	Compose Case Mail
There are	no mail for this ca	ase.						
=								

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Owner ID Type:	Singapore NRIC
Owner ID:	73471
Vehicle Distalls 2	
Vehicle No.:	SGR7933J
Vehicle to be Exported:	Yes
Intended Deregistration Date:	22 Jan 2019
Vehicle Make:	TOYOTA
Vehicle Model:	COROLLA ALTIS 1.6 AUTO
Primary Colour:	Red
Manufacturing Year:	2006
Engine No.:	3ZZ4622261
Chassis No.:	MR053ZEC107138072
Maximum Power Output:	81.0 kW (108 bhp)
Open Market Value:	\$15,355.00
Original Registration Date:	15 Feb 2007
First Registration Date:	15 Feb 2007
Transfer Count:	0
Actual ARF Paid:	\$16,891.00
Intended PARF Rebate Cetalls	
PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	
PARF Rebate Amount:	\$0.00
Intended COE Rebate Distalls	
COE Expiry Date:	14 Feb 2022
COE Category:	A - Car (1600cc & below)
COE Period(Years):	5
PQP Paid:	\$25,197.00
COE Rebate Amount:	\$15,450.00
Total Rebate Amount:	\$15,450.00


Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 22 Jan 2019

No Harry	Toyota Corolla Altis 1.6A (COE till 05/2021)	\$13,900	\$5,990 /yr	19-May-2006	1,598 cc		Sedan	Available
	Come View This Popular Japanese Reliable Serious Seller. Private Hire Car Owners Wel	Work Horse, All come. Price	Servicing Done Dil	igently. Radiator Cha	nged Recently.	lew Shock Absorbe	ers. View To Offer.	ORECT OWNE
	Posted: 13-Jan-2019 Tags: 2006 Toyota	ica Corolla, 2006	toyota corolla, Toyoti	Corolla, toyota corolla	, Toyota, Corolla	corolla, Used		
- Suran	Toyota Corolla Altis 1.6A (COE till 06/2021)	\$13,899	\$5,730 /yr	26-Jun-2006	1,598 cc	128,000 km	Sedan	Available
	Low Mileage, Popular Choice For Daily Use! Owner. Clean And Neat Interior! Buy With		Efficiency With Amp	ole Space For Passen	gers And Boot S	torage. Well Maint	ained By Previous	
	Ken Garage Pte Ltd Posted: 22-Jan-2019 Tags: 2006 Toyota	ita Corolla, 2006	toyota cordila, Toyota	s Corolla, toyota corolla	, Toyota, Corolla	corolla, Used		
	Toyota Corolla Altis 1.6A (COE	\$13,899	\$5,730 /yr	27-Jun-2006	1,598 cc	123,000 km	Sedan	Availabl
	till 06/2021) Low Mileage Done, Popular Choice For Dails	y Use! Excellent	Fuel Efficiency Wit					Availabi
	Previous Owner, Clean And Neat Interior! B Ken Garage Pte Ltd	uy with Trust A	**					
	Posted 22-Jan-2019 Toyota Toyota	ta Corolla, 2006 I	toyota corolla, Toyoti	Corolla, toyota corolla	, Toyota, Corolla,	cordita, Used		
	Toyota Corolla Altis 1.6A (COE till 06/2021)	\$16,800	\$6,900 /yr	30-Jun-2006	1,598 cc		Sedan	Available
Mall Commercial Commer	100% Full Loan View At Phoenix Motor Trad	5 17		remaine institut our can	Toronto Carolla	CONTRACTOR INC.		
	Posted: 27-Dec-2018 Toyota	Kill Carollay 2016	oyota curusa, royez	i Corollà, toyota corollà	i, Toyota, Corolla,	covolia, Used		
7 01	That's a fine looking car interior							
	Customise your ride. Replace your leather s available. Each with merchant information,					choice. List of the	best workshops	
	Find out more!							
	Toyota Corolla Altis 1.6A (COE till 06/2021)	\$14,500	\$5,950 /yr	12-Jul-2006	1,598 cc		Sedan	Availabl
100	1 Careful Owner, Low Mileage Done, Popula Maintained By Previous Owner, Clean And N	ar Choice For Da Neat Interior!	ily Use! Excellent F	uel Efficiency With A	mple Space For	Passengers And B	oot Storage. Well	
	Posted 20-Jan-2019 Tags: 2006 Toyota Toyota	ta Corolla, 2006 i	oyota corolla, Toyota	Corolla, toyota corolla	, Toyota, Corolla,	corolla, Used		
	Toyota Corolla Altis 1.6A (COE till 06/2021)	\$15,800	\$6,480 /yr	21-Jul-2006	1,598 cc		Sedan	Available
NAME OF THE PARTY OF	COE Till June 2021. Well Maintained And Se	erviced. Viewing	By Appointment O	nly, Call To Arrange.				
	Singapore Automobile.com Posted 18-Jan-2019 Tags: 2906 Toyota Toyota	ta Corolla, 2006 i	zyota corolla, Toyota	Corolla, toyota corolla	, Toyota, Corolla,	corolla, Useo		
-	Toyota Corolla Altis 1.6A (COE	\$17,500	\$6,380 /yr	20-Oct-2006	1,598 cc		Sedan	Available
	till 10/2021)							Availabil
	100% Loan (2 Owner Only, Excellent Condi Accident Free! Call Now Before It's Gone!	tion And Well M	aintained By Previo	us Owner) Special H	igh Loan Packag	e Available! This C	ar Is 100%	
	Hamilton Autohub Pte Ltd Posted: 07-Jan-2019 Tegs: 2006 Toyo Toyota	ta Corolla, 2006 t	oyota corolla, Toyota	Corolla, toyota corolla	, Toyota, Corolla,	corolla, Used		
	Toyota Corolla Altis 1.6A (COE	\$18,800	\$6,780 /yr	31-Oct-2006	1,598 cc		Sedan	Available
	till 10/2021)	710,000	40,700 //	31 00 2000	1,550 cc		Sedan	Availabil
-y	COE Till 30/10/2021, Good Condition, Loan			Corolla, toyota corolla	Townty, Comilia	cocolla Userl		
	Posted 21-Jan-2019 Toyota	34. 330 30 1199, 36 3 5 5 5	N. S. C.	Profession of Lone Column	0.7509940.5403400	300 3000 3000		
	Toyota Corolla Altis 1.6A (COE till 02/2022)	\$27,388	\$8,960 /yr	12-Feb-2007	1,598 cc		Sedan	Available
00	New Arrival! Owned By A Careful, Non Smo Most Popular Sedan Among Its Class. She N		rice Regularly At 10	k Km Without Fail. C	original Paint, Be	autiful Leather And	d Accident Free.	
			oyota corolla, Toyota	Corolla, toyota corolla	, Toyota, Corolla,	corolla, Used		
	Toyota Corolla Altis 1.6A (COE till 04/2022)	\$28,800	\$8,840 /yr	26-Apr-2007	1,598 cc	143,000 km	Sedan	Available
San	Best COE Renewed Condition, View Yoursel 2017. Car Serviced On Dec 2017, Original D			Engine, Just Replace	ed Front And Re	ar Brake Pad And E	Battery On Dec	_
HITLESTED HISTORY	Prem Roy Motoring	rosn ovarú Kadi	o Pellins					CONSIGNMEN



Compare S Posted 10-Jan-2019 Tags: 2007 Toyota Corolla, 2007 toyota corolla, C



insurance. Find buy used toyota altis, toyota altis Singapore, used toyota altis Singapore, used toyota altis Singapore or even buy used toyota altis Singapore. We have new car dealers comprising parallel importers, authorised car dealers, and used car dealers on our site. Find new car price lists, new car launches and new car promotions, visit our partner sites for job openings for Singapore jobs, real estate properties for sale, mover, car performance parts, car discussion, forum discussion, commercial vehicle leasing & COE results

All prices and other information displayed on spCarMart.com are gathered from sources and based on algorithms that are believed by spCarMart.com to be reliable, but no assurance can be given that this information is accurate, complete or current, sgCarMart.com does not assume any responsibility for errors or omissions or warrant the accuracy of this information.

Follow sgCarMart.com













About Us | Careers | Contact Us | Sitemap | Terms of Service | Privacy Policy | Personal Data Protection Statement ©2004-2019 sgCarMart. All rights reserved.

View Sent Message

This mail is associated with:

*SGR7933J (MSC/V/19-000087) [FBM217A]

TP TAN CHIN LONG Jan 17 2019 8:00AM [MUHAMMAD FERROZY BIN MOHD SANUSI] Hiap Hong Motor Repair

Resend	View Recipients	Print Message	Delete Message	Forward

LKK Auto Consultants Pte Ltd (LKK_HQ), sent on 23/01/2019 10:44 AM.

To MSIG_CWSF1

TP SURVEY SGR 7933J Subject

Dear Christina,

Please be informed that we have inspected the vehicle SGR 7933J on 21/1/2019

We are pending estimate from repairer.

Best Regards,

Veron Chen on behalf of Shirley

DOCUMENTS SUMMARY

There are no documents.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

- 1. Please report <u>correctly</u> the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to reput repudiate policy ability
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- 6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore(GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

	ACCIDENT STATEMENT
Date Of Report	10/01/2012 16:15
Date Of Accident	27/12/2011 12:00
Exact Location Of Accident	ALONG LORNIE RD TWDS PIE
	DETAILS OF OWN VEHICLE
Vehicle Registration Number	GBB3088T
Insured/Policyholder	
Name Of Registered Owner	ETONG CONSTRUCTION (S) PTE LTD
Co Reg No	199701731R
Vehicle Particulars	
Manufacturer	ТОУОТА
Model	DYNA 150D-3.0 D (M)
Exact Purpose for which vehicle was being used at time of accident	COMPANY USE
Are you claiming under your own insurance policy for repair to your vehicle?	No
If No, Please state action to be taken	Reporting Only
Vehicle Category	Commercial Vehicle
Insurance Company	
Name of Insurance Company	Chartis Singapore Insurance Pte Ltd
Type Of Coverage	Comprehensive
Fleet Policy	No
Policy Number	2100105433
Cover Note Number	

Driver		BHH
Name of Driver	LUHARING	
Passport No/FIN	G6733646T	
Date Of Birth	04/07/1985	
Occupation	Indoor	
Date Of Driving Pass	22/09/2011	
Driving Experience	0 Year And 3 Month	
Gender	Male	
Mobile Number	(Local) +65-90372973	ih
Fax Number	47 Jalan 12ming	5.6.3
Contact Number	35. 8	

 EMail Address
 YZBY520LHB@163.COM

 Address
 47 JALAN PEMIMPIN #05-02

 Postcode
 577200

Was driver an employee of the Insured's Company Yes

If No, Relationship of the Driver with the Insured

MNA119008114 / National Assessment Centre Services - Ubi ENTRY DATE & TIME: 17/01/2019 17:10 SUBMITTED BY: Llow Shan Hul

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.

This Form must be completed by the Policyholder and/or the Authorised Driver.

3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to

4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies. 5. Any false reporting may be referred to the Police for Investigation.

This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.

7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available

ACCIDENT STATEMENT Date Of Report 17/01/2019 17:10 Date Of Accident 17/01/2019 08:05 Exact Location Of Accident KIM KEAT LINK SLIP RD EXIT TO LOR 6 TOA PAYOH Country/State of Loss SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number

Insured/Policyholder

Name Of Registered Owner NRIC No

Email Address

Mobile Phone No

Alternative Phone No. Vehicle Particulars

Manufacturer

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle?

If No, Please state action to be taken

Vehicle Category

Insurance Company

Name of Insurance Company

Type Of Coverage Fleet Policy

Policy Number

Cover Note Number Driver

Name of Driver NRIC No Date Of Birth Occupation

Date Of Driving Pass **Driving Experience**

Mobile Number

Gender

Contact Number

EMall Address

Fax Number

SGR7933J

TAN CHIN LONG

S20473471 NOEMAIL

(LOCAL) +65-97685436 OFFICE-97685436

TOYOTA

COROLLA ALTIS 1.6 AUTO

PRIVATE USE

THIRD PARTY

PRIVATE CAR

NTUC INCOME INSURANCE CO-OPERATIVE LTD

THIRD PARTY FIRE AND/OR THEFT NO

5025927294-10

TEO WE! YUN

S7639606Z 03/12/1976 INDOOR 20/02/2002

16 YEARS AND 10 MONTHS

FEMALE

(LOCAL) +65-97659105

NOEMAIL

Page 1 of 21

Address

BLK 322C ANCHORVALE DR #03-146

Postcode

543322

Was driver an employee of the Insured's Company NO

If No, Relationship of the Driver with the Insured

OTHER - DAUGHTER IN LAW

Vehicle Registration Number of Driver's Own

Vehicle

Insurance Company of Driver's Own Vehicle

General Information of the Accident

Type Of Accident

COLLISION - HEAD TO REAR

Weather Conditions

CLEAR

Road Surface

DRY

Other Information

Was any foreign vehicle involved in this accident?

NO

Number of vehicles (including own vehicle)

involved in the accident

Was any body injured in the Accident? Was any injured conveyed to hospital by

NO

Was any other material or property damaged? have been approached by unknown person(s)

YES NO

soliciting/offering accident claims assistance. Number of Passengers (Including Driver)

Details of Police Action

Was the accident reported to the police?

YES

If Yes, Please state which Police Station

Police Station Name

TOA PAYOH NEIGHBOURHOOD POLICE CENTRE

Police Station Address Police Station Contact

ROAD: 93 TOA PAYOH CENTRAL TOA PAYOH COMMUNITY BUILDING ,

POSTCODE: 319194, COUNTRY: SINGAPORE TEL NO: 1800-2519999 - FAX NO: 63548749

Was notice of intended Prosecution given?

If Yes, against whom?

Circumstances of Accident

PLEASE REFER TO POLICE REPORT.

Attachment(s)

Are accident photos available for attachment?

YES

Was there any video captured by Car Camera?

NO

Was there any audio recorded?

NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number

FBM217A

Vehicle Make/Model/Colour Details Of Properties

Vehicle Category

MOTORCYCLE

Name of Driver

FERROZY

NRIC/Passport Number

Contact Number Address

98894729

Postcode

Insurance Company Name

Nature Of Damage

Page 2 of 21

SKETCH PLAN

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- information provided must be as <u>truthful and accurate as possible</u>. Any wilful misrepresentation or withholding of material facts may allow insurance companies to <u>repudiate policy liability</u>.
- The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance
 Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by
 interested parties.
- 7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, involces, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature Date & Time: Driver's Signature

(If driver is not the policyholder)


Date & Time:

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No .:

		E ITALIA TANDATA
American (a)		
Lor 6 ton	Payoh.	
		A = SGR 7933 J
		B= FEM 217A
	(A)	
	1881	
	\ \\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\	
	King Kent Liv	IK THE
DESCRIBE CIRCUMSTAN		
PESCHIBE CIRCUISTAN	LES OF THE ACCIDENT	
√ 1.	Refer to Pol	
Please	Reder to Pol	ice Report
		1
	,	/
11/25		
	/	
CLARATION	tioulane are two in	,
ve acciare the foregoing par	ticulars are true in every respect.	/ /
	Your.	4
licyholder's Signature	Driver's Signature	mit
te & Time:	(If driver is not the policyholder)	Reporting Centre Personnel's Signature Name:
	Date & Time:	NRIC/FIN No.:







Police Station Of Origin:
Toa Payoh N.P.C
93 Toa Payoh Central #01-02 Toa Payoh
Community Building SINGAPORE 319194
Tel No: 1800-2519999

1 of 4 Report No. T/20190117/2122

REPORT OF A TRAFFIC ACCIDENT

17/01/2019 16:11		Made:	Vide Report No.:	Station Diary No.: 57
Informar	nt's Partic	ulars III		10.
TEO WE		4	Address: APT BLK 322C ANCHORVAL 543322	LE DRIVE #03-146 SINGAPORE
ID Type / NRIC NO	ID No.: / S76396	06Z	Contact No.: Home/Office:	Mobile: 97659105
Nationalit SINGAPO		ŒN	Email:	WOODIE: 07009100
Sex: Female	Age: 42	Date of Birth: 03/12/1976	Type of Informant: Driver	
Race: Chinese			Language:	Institution / School Name:
Occupation Technical		•	Driving Licence Information: Class:	Date of Evolution

Type of Accident:	Non-Injury Others	Drink Drive: No	Date/Time of Accident: 17/01/2019 08:05	Type of Location Bend
PAN ISLAND KIM KEAT LIN From PIE towa	Traveling Toward Roa EXPRESSWAY K Irds Kim Keat Link			
Weather: Clear		Road Surface: Dry		Road Speed Limit:
Traffic Flow:	ffic Flow: e Way Traffic Control: Not Controlled oe of Collision:			Traffic Volume: Heavy

Vehicle No.	Туре	Make	Model	Color	Condition	No of Passenger
FBM217A	Motorcycle	HONDA	GLR1251W	Black	Sacramon	1
SGR7933J	Car	TOYOTA	COROLLA ALTIS 1.6 AUTO	Red	Slightly Damaged	0

Details of Person Involved	
Any Pedestrian Involved: No	
No. of Pedestrians Injured: NIL	Use of Pedestrian Crossing: NA



T/20190117/2122

2 of

Report No. T/20190117/212

Police Station Of Origin: Toa Payoh N.P.C 93 Toa Payoh Central #01-02 Toa Payoh Community Building SINGAPORE 319194

Tel No: 1800-2519999

CONTINUATION OF REPORT

Rider	THE STATE OF THE PARTY OF THE P				件 對 (
Name	FERROZY			ID No).	NIL
Related Vehicle	FBM217A (Motorcy	rcle)		Conta	act No.	98894729
Hospital/Clinic	NIL			Class Drivin Licen Expin	ıg	Class: NIL Date of Expiry: NIL
Date Treatment	NIL		Date Disc			
No. of Days gran	ted Medical Leave	NIL	Degree of			***************************************
Driver						
Name	TEO WEI YUN			ID No		S7639606Z
Related Vehicle	SGR7933J (Car)			Conta	ct No.	97659105
Hospital/Clinic	NIL			Class Drivin Licena Expire	g	Class: NIL Date of Expiry: NIL
Date Treatment	NIL		Date Disc			
No. of Days grant	ed Medical Leave	NIL	Degree of			
Vehicle Owner						
Name	TAN CHIN LONG			ID No		S2047347I
Related Vehicle	SGR7933J (Car)	-		Conta	ct No.	97685436
Hospital/Clinic	NIL			Class Driving Licence Expiry	g e&	Class: NIL Date of Expiry: NIL
Date Treatment	NIL		Date Disch		NIL	
Vo of Days grant	ed Medical Leave	NIL	Degree of		NIL	

On 17/01/2019 at about 0805hrs, I was driving my father-in-law's vehicle SGR7933J along the bend from PIE towards Kim Keat Link. The traffic was quite heavy at that time. When approaching the stop line from PIE, I slowed down and stopped behind a stop line to wait for traffic to clear. All of a sudden, I felt an impact from the back of my vehicle. I looked into the rear view mirror and saw one motorcycle (FBM217A) have collided into my vehicle, however the rider and his pillion did not fall off.

As it was unsafe for me to alight due to the heavy traffic, I drove to the roadside near to Toa Payoh SAFRA, after the zebra crossing, to assess the damage. The motorcyclist have also stopped and I did not notice any physical injury on him except for a small cut on his finger. The pillion was also observed to be okay. I noticed a vehicle part have also fallen off from the right side of the motorcycle. Due to the impact, there are some scratches and dents on the left rear of my vehicle. I wish to state that I do not have any injury. We then exchange particulars and left for our own ways. No police or ambulance came to scene. I





Police Station Of Origin: Toa Payoh N.P.C 93 Toa Payoh Central #01-02 Toa Payoh Community Building SINGAPORE 319194 CONTINUATION OF REPORT Tel No: 1800-2519999

Report No. T/20190117/2122

am lodging a report for recording purposes and insurance claims.





Police Station Of Origin: Toa Payoh N.P.C 93 Toa Payoh Central #01-02 Toa Payoh Community Building SINGAPORE 319194 CONTINUATION OF REPORT Tel No: 1800-2519999

4 of 4 Report No. T/20190117/2122

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report/ E / Sgt 2 JASMINE LEAU WEI LIN	Signature Of Informant:
Signature Of Interpreter: Not applicable	Date/Time: 17/01/2019 16:11
Officer In Charge Of Case: TP / GIA / Staff Sgt WONG SIEU LUI Contact No.: 65476151	Classification Of Case:
Authentication Stamp NP168	IF.

	17 1	
	27933J.	Date No.
Toys	ota Altis.	Date No.
	S3ZEC107138072	
Rees	Buyer Deformed	425.90 ~
Reas	Buyer Cuips. Her	30
Reer	Buyer Side Holder F.H New	2450 ~
	Burger Impact Badat LH. XIt Ne	
	End Penel. Repir	700804
Peer	End Panel Top Garrish 2 HP	68.90 +
Reer	End Panel Top Garish 2 NA End Panel Sentent, I New	60(SN) X.
Tai	llup LH Couled	28950
Tori	llap lower Apran LH Repris	8010 4
	loup Parel LH Pepis	381.20 +.
Rev	ese Sensor sond.	250 (SN) - 200 (SN)
	769	90 S.N:200
	577	
Reen	el Beatiz	DE 250.
0	1 Pountry	800 400
	my -	50 30.
70	rende revere servor	100 50
To	rende revere servor renore upholslery,	150 X
		3743.52 730.
	LKK Auto Consultants hence notify	tolal. 1507 HZ
	• To resurvey before/affect	
	Parts prices are subject to	45: 1.2K.
	No illegal modification(a) is a "Without Prejudice" basis	1
	Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company	
	Acknowledged by Repairer	
	Signature:	

...CLAIM SUBFOLDER...(Pending for Survey Report)

LAIM SUE	BFOLDER TRAC			Communication .	T		1-	
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status	
Main	21 Jan 2019 10:17		21 Jan 2019 16:08 Edit Adj Rpt	S\$1,200.00 Edit Estimates	S\$1,200.00 View Rpt		Pending for Survey Report Cancel Case	
	Main	Ref	erence	Claim Deta	ails	Documents	Show All	
CLAIM S	UBFOLDER DET	TAILS			[Created b	y insurer]		
Insured:	MUHAMMA	D FERROZY BIN	MOHD SANUSI,	D: S8821284C				
Main Claimant:	TAN CHIN	LONG, ID: S204	73471					
Vehicle Re No.:	sgR7933	33		Date of L	[143 Month	s and 2 Days From L	TA Reg Date (Man Yr)]	
Claim Typ	e: TP / MSC,	/V/19-000087		Policy/Co Note No.		18-384298 (TP, Fire 4/06/2018 - 13/06/2		
Vehicle Re No. (Insured):	FBM217A			Policy No (Claiman				
				Excess:				
Repairer:	Hiap Hong	Motor Repair ()	2 Kaki Bykit Avenue	2, #02-13, 417921	Kaki Bukit - Tel:			
Handling Insurer:	learness reasons			ASTRO- DESPOSABLE DESPOSA		Christina Wong - 60	SOURCESS	
Adjuster:	22/01/20		.td (HQ) - Tel: 625	6-3561 [Handled	by XING GUO QI	ANG] [Imm.Ac	dvice due	
Adj Asg. Remarks:	Liability dov	vn. TP want to use	LKK Auto Consultar	nts as the SJE. Cont	act No: 6745 9633			
ASSOCIA	TED MAIL REC	EIVED				View Al	Compose Case Mai	
There are	no mail for this o	case.						
ALL ASS	OCIATED TASK	(S [□]			View All Se	earch Tasks Creat	te New Task Complete	
		1000 MINE 1000	C	Handler 4			Created On Done	
Due Da No results		Type Task (Group Subject	Handler As	ssigned By	Completed On	Created On Done	

Claim Documents

*SGR7933J (MSC/V/19-000087)

[FBM217A]

TP

TAN CHIN LONG

Jan 17 2019 8:00AM

[MUHAMMAD FERROZY BIN MOHD SANUSI]

Hiap Hong Motor Repair

			2	ge 🔽	
	otos/Images		3 per pa		V
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	0	Thumbnail Load JPG	V
1	26/02/19 15:37	General View			-
2	26/02/19 15:37	General View	0	Load JPG	<u> </u>
3	26/02/19 15:37	General View	0	Load JPG	V
4	26/02/19 15:37	General View	0	Load JPG	V
5	26/02/19 15:37	General View	0	Load JPG	<u>~</u>
6	26/02/19 15:37	General View	0	Load JPG	V
7	26/02/19 15:37	General View	0	Load JPG	✓
8	26/02/19 15:37	General View	0	Load JPG	✓
9	26/02/19 15:37	General View	0	Load JPG	✓
10	26/02/19 15:37	General View	0	Load JPG	V
11	26/02/19 15:37	General View	0	Load JPG	Y
12	26/02/19 15:37	General View	0	Load JPG	~
13	26/02/19 15:37	General View	0	Load JPG	V
14	26/02/19 15:37	General View	0	Load JPG	~
15	26/02/19 15:37	General View	0	Load JPG	V
16	26/02/19 15:37	General View	0	Load JPG	V
17	26/02/19 15:37	General View	0	Load JPG	V
18	26/02/19 15:37	Reinspection Photo	0	Load JPG	V
19	26/02/19 15:37	Reinspection Photo	0	Load JPG	~
20	26/02/19 15:37	Reinspection Photo	0	Load JPG	V
21	26/02/19 15:37	Reinspection Photo	0	Load JPG	V
22	26/02/19 15:37	Reinspection Photo	0	Load JPG	V
23	26/02/19 15:37	Reinspection Photo	0	Load JPG	V
24	26/02/19 15:37	Reinspection Photo	0	Load JPG	V
			0	Load JPG	V
25	26/02/19 15:37	Reinspection Photo	0	Load JPG	✓
26	26/02/19 15:37	Reinspection Photo		Load JPG	<u>~</u>
27	26/02/19 15:37	Reinspection Photo	0		
28	26/02/19 15:37	Reinspection Photo	0	Load JPG	<u> </u>
29	26/02/19 15:37	Reinspection Photo	6	Load JPG	V
30	26/02/19 15:37	Reinspection Photo	0	Load JPG	V
31	26/02/19 15:37	Reinspection Photo	0	Load JPG	✓
Dos	cumentation		1 per pa	age V	V
	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	- Indeed	Thumbnail	-
No 1	21/01/19 10:18	SGR79333 GIA Rpt	0	Load PDF	
2	21/01/19 10:18	FBM217A GIA Rpt	Ō	Load PDF	
3	21/01/19 10:21	PRI - Tng Soon Chye & Co	0	Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
			^
			~
Show Remarks To: Handling Insurer Note: Remarks are private unless you show it to other parties.			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25. Pava Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No:

CS/MSG19001307/AGSD3E2

Date:

01/03/2019

REFERENCE

MSIG Insurance (Singapore) Pte. Handling Insurer:

Policy No:

MSD/VMFT/18-

384298

Claimant Vehicle SGR7933J

Insured Vehicle

Nature of Claim:

FBM217A

No:

Date of Loss:

17/01/2019

No:

TP

Claim No:

MSC/V/19-000087

MR053ZEC107138072

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:

SGR7933J

Make & Model:

TOYOTA COROLLA ALTIS, 1.6 (A)

Engine No: Chassis No:

Odometer:

3ZZ4622261

239997 km

Reg. Date: Colour:

15/02/2007 (Man. Year: 2006)

Engine Capacity: Market Value/New Car Price: N/A

1598 cc

Sum Insured (S\$):

Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:

Steering (Serviceable):

Yes Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes Engine Modification:

Pre-accident Condition: No

CONDITION OF TYRES

Front Tyre Size:

195/60 R15

Rear Tyre Size:

195/60 R15

Front Left Side:

ACENDA 6 mm

Rear Left Side:

ACENDA 6 mm

Front Right Side:

ACENDA 6 mm

Rear Right Side:

ACENDA 6 mm

The above values represent the remaining tyre treads depth

Repairer's	Adjuster's	Difference	Diff %
1,843.52	777.42	1,066.10	57.83
0.00	0.00	0.00	
1,900.00	730.00	1,170.00	61.58
0.00	0.00	0.00	
0.00	0.00	0.00	
3,743.52	1,507.42	2,236.10	59.73
	1,200.00		
3,743.52	1,200.00	2,543.52	67.94
	1,843.52 0.00 1,900.00 0.00 0.00 3,743.52	1,843.52 777.42 0.00 0.00 1,900.00 730.00 0.00 0.00 0.00 0.00 3,743.52 1,507.42 1,200.00	1,843.52 777.42 1,066.10 0.00 0.00 0.00 1,900.00 730.00 1,170.00 0.00 0.00 0.00 0.00 0.00 0.00 3,743.52 1,507.42 2,236.10 1,200.00

Inspected At:

INSPECTION

Date of Assignment:

21/01/2019

Date Inspected:

21/01/2019

Hiap Hong Motor Repair

2 Kaki Bykit Avenue 2, #02-13

Singapore 417921

Estimated Period of Repair:

2.0 days

Adjuster: XING GUO QIANG

Manager:

Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Referen		Version: 1.0 (Last Synchronised: 01 Mar 2019)			
Parts: Labour:	143 Repairer's	TOYOTA COROLLA ALTIS 1.6 (A) (Catalogue:Merimen Singapore 1.0) (Price-denominated Standard List)			
Print Code:	(Unsubmitted,	no print-code for SGR7933J)			
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page				
Further Info:	Items/values r	ot in reference catalogue are prefixed with an asterisk *.			

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	425.90 FL	*425.90 FL
2	1		*REAR BUMPER CLIPS	Necessary	30.00 FL	*30.00 FL
3	1		*REAR BUMPER SIDE HOLDER LH	Necessary	24.50 FL	*24.50 FL
4	1		*REAR BUMPER IMPACT BRACKET LH	Not Necessary	43.20 FL	*-FL
5	1		*REAR END PANEL	Repair	700.80 FL	*-FL
6	1		*REAR END PANEL TOP GARNISH	Not Necessary	68.90 FL	*- FL
7	1		*REAR END PANEL SEALANT	Not Necessary	60.00 FS	*- FS
8	1		*TAILLAMP LH	Cracked	289.50 FL	*289.50 FL
9	1		*TAILLAMP LOWER APRON LH	Repair	80.70 FL	*-FL
10	1		*TAILLAMP PANEL LH	Repair	381.20 FL	*-FL
11	1		*REVERSE SENSOR	Damaged	250.00 FS	*200.00 FS
F=Fra	anchise	part. S=SpcN	lett. L=ListItemDisc.	Sub Total (S\$)	2,354.70	969.90
			- List Item Discount on L It	ems 25.00/25.00% (S\$)_	511.18	192.48
				Total Parts (S\$)	1,843.52	777.42

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			
1	PANEL BEATING	New	800.00	250.00
2	SPRAY PAINTING	New	800.00	400.00
3	WIRING	New	50.00	30.00
4	TO REMOVE REVERSE SENSOR	New	100.00	50.00
5	TO REMOVE UPHOLSTERY	New	150.00	0.00
		Gross Labour Cost (S\$)	1,900.00	730.00
	Report w	as unsubmitted during this print-out.	-	

< END OF ESTIMATES >