

ASS REC BY:

REF: CS/Smo19001317/Utd3ⁿ²

Special Instruction:

Surveyor
Muhimen

ASSIGNMENT (Office)

From (Person): Shawn Ngo of SMO Date/Time: 21/01/2019 2:37pm

Estimated Cost: Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MY / CS

To Inspect Vehicle No: SJT 3270T Insured: SJR 26736

at Workshop m/s JEC Auto Tel: 6509 6585

of Blk 1 Kaki Bukit Ave 6 #02-11

Policy No: D18MTPVD1010193 Claim No: CMTD1900249

Sum Insured: Excess:

Make of Veh: D.O.A. 18012019
(Client's Record)

CA / REV / REP. / REV 24 HRS 'wp' 23-01-2019 H.O.D. Endorsement:

Date/Time: 21-01-2019 4:18pm Person Contacted: An Xian Vehicle IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	SJT 3270T - X
	SJR 26736 - CS/Smo19001317/Utd3 OIA: 18012019
24/1/19 @ 3pm	Informed Shawn Ngo, see our parking estimate from repairer.

REF: SMO

ASSIGNMENT

From: _____ Date: 23/1/19

Estimated Cost: _____

OD: WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SJT 3270T

at Workshop m/s: JEC Auto

of BK1, kaki Bkt Ave 6 # 02-11

Insured: _____

Policy No: _____

Claims No: _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Vch: _____

Veh No: SJT 3270T Yr Regn: 4, 16

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or CA /

Make: Audi, A3 c.c. 1395

Colour: white A/C: Insured / Std / NI / NA

Sp Reading: 5244 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: WAUZZZ8V7G1088421

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 205/55 R16

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or hankook

Front: _____ Rear: _____

R/Bal. 6 mm R/Bal. 6 mm

L/Bal. 6 mm L/Bal. 6 mm

D.O.A. 18/1/19 D.O.I. 23/1/19

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear

The U/C / Chassis frame / Body Structure affected due to collision.

<input type="checkbox"/>	<input type="checkbox"/>
N/S	O/S
<input type="checkbox"/>	<input type="checkbox"/>

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rport: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: 4 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS lup

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Date / Time Action / Instruction

20/2/19 LTA 44844

H/S # 3900 confirmed with AH. Xian. (Red: 1030899, 77%)

RECEIVED 21 FEB 2019

Date/Time, File Pass to? : Preli. Report

21/2 Typist : Final Report

Date/Time, File Return to? _____

Days Of Repair: 4

Resurvey No. of Trip: 1

Add Fee: Site Insp (\$)

Interview (\$)

Tech Invs (\$)

Weekend (\$)

Survey Fee: _____

Transportation: _____

Photos: _____

Others: _____

TOTAL: _____

350
10
360

Report Format: TP

Lump Sum / I.B.I: (\$) 3900

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	19 Jan 2019		21 Jan 2019 14:37 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

CLAIM SUBFOLDER DETAILS				[Created by insurer]																				
Insured:	KUAN CHAU FOO, ID: S7863268B, Tel: +6582005229, Email: NOEMAIL																							
Main Claimant:	TAN CHEOW BOON																							
Vehicle Reg. No.:	SJT3270T	Date of Loss:	18/01/2019 12:00 - :59																					
Claim Type:	TP / CMTD1900449	Policy/Cover Note No.:	D18MTPV01010193 (Comprehensive)																					
Vehicle Reg. No. (Insured):	SJR2673G	Policy No. (Claimant):	Excess:																					
Repairer:	Jec Auto Service (HQ) 1 KAKI BUKIT AVENUE 6 #02-11, Autobay @ Kaki Bukit, 417883 Kaki Bukit - Tel: 6509 6585 / 9435 4491																							
Handling Insurer:	Sompo Insurance Singapore Pte. Ltd. (HQ) - Tel: 6461 6555 ... [Handled by NGO SAU WEI SHAWN - 6329 5202]																							
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 30/01/2019]																							
Driver/Custodian (Insured):	KUAN CHAU FOO (40 / Male), NRIC: S7863268B, Tel: +6582005229																							
ASSOCIATED MAIL RECEIVED				View All Compose Case Mail																				
There are no mail for this case.																								
<input type="checkbox"/> ALL ASSOCIATED TASKS																								
<table border="1"> <thead> <tr> <th>Due Date</th> <th>Priority</th> <th>Type</th> <th>Task Group</th> <th>Subject</th> <th>Handler</th> <th>Assigned By</th> <th>Completed On</th> <th>Created On</th> <th>Done?</th> </tr> </thead> <tbody> <tr> <td colspan="10">No results.</td> </tr> </tbody> </table>					Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?	No results.									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?															
No results.																								

Shiau Chan (LKKAuto)

From: Do-Not-Reply <do-not-reply@merimen.com>
Sent: Thursday, 24 January 2019 3:00 PM
To: do-not-reply@merimen.com
Cc: SUR
Subject: VEHICLE SJT 3270T (YOUR REF: CMTD1900449)

This mail is associated with :

***SJT3270T (CMTD1900449)**

[SJR2673G]

TP

TAN CHEOW BOON

Jan 18 2019 12:00PM

[KUAN CHAU FOO]

Jec Auto Service

Dear Shawn,

Please be informed that we have inspected the vehicle SJT 3270T on 23/01/2019.

We are pending for estimate from repairer.

Thanks & Regards,

Shiau Chan on behalf of Denise (Ms)

LKK Auto Consultants Pte Ltd

Tel: 6256 3561

This is an auto-generated email. Do not reply to this email.

Sent by : SHIAU CHAN (LKK Auto Consultants Pte Ltd)



This email has been checked for viruses by AVG antivirus software.

www.avg.com

> **Back to OneMotoring**

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	0273I
Vehicle Details	
Vehicle No.:	SJT3270T
Vehicle to be Exported:	No
Intended Deregistration Date:	25 Jan 2019
Vehicle Make:	AUDI
Vehicle Model:	A3 SEDAN 1.4 TFSI (AMBIENTE)
Primary Colour:	White
Manufacturing Year:	2016
Engine No.:	CZC537526
Chassis No.:	WAUZZZ8V7G1088421
Maximum Power Output:	92.0 kW (123 bhp)
Open Market Value:	\$22,584.00
Original Registration Date:	29 Apr 2016
First Registration Date:	29 Apr 2016
Transfer Count:	1
Actual ARF Paid:	\$13,618.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	28 Apr 2026
PARF Rebate Amount:	\$10,213.00
Intended COE Rebate Details	
COE Expiry Date:	28 Apr 2026
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$47,300.00
COE Rebate Amount:	\$34,331.00
Total Rebate Amount:	\$44,544.00

The information contained herein is correct as at 23 Jan 2019

OK

MSME19009132 / SME Motor Pte Ltd - Kaki Bukit
 ENTRY DATE & TIME: 19/01/2019 12:53
 SUBMITTED BY: Chia Pei Ying

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	19/01/2019 12:53
Date Of Accident	18/01/2019 12:35
Exact Location Of Accident	BUKIT TIMAH RD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SJT3270T
Insured/Policyholder	
Name Of Registered Owner	TAN CHEOW BOON
NRIC No	S1780273I
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-90184415
Alternative Phone No	OFFICE-90184415

Vehicle Particulars

Manufacturer	AUDI
Model	A3
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	1800070534
Cover Note Number	

Driver

Name of Driver	TAN CHEOW BOON
NRIC No	S1780273I
Date Of Birth	23/08/1966
Occupation	INDOOR
Date Of Driving Pass	25/06/1984
Driving Experience	34 YEARS AND 6 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-90184415
Fax Number	
Contact Number	OFFICE-90184415
E-Mail Address	NOEMAIL

Address 32 JALAN LANJUT SEMBAWANG HILLS ESTATE
 Postcode 577675
 Was driver an employee of the Insured's Company NO
 If No, Relationship of the Driver with the Insured OWNER
 Vehicle Registration Number of Driver's Own Vehicle -
 -
 -
 Insurance Company of Driver's Own Vehicle -
 -
 -

General Information of the Accident

Type Of Accident COLLISION - HEAD TO REAR
 Weather Conditions CLEAR
 Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
 Number of vehicles (Including own vehicle) involved in the accident 2
 Was any body injured in the Accident? NO
 Was any injured conveyed to hospital by ambulance? NO
 Was any other material or property damaged? YES
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
 Number of Passengers (Including Driver) 2
 Passenger 1 NAME: : UNKNOWN GENDER: UNKNOWN
 GENDER: : MALE

Details of Police Action

Was the accident reported to the police? NO
 If Yes, Please state which Police Station
 Was notice of intended Prosecution given? NO
 If Yes, against whom?

Circumstances of Accident

ON 18/01/2019 AT 12.33PM, I WAS DRIVING ALONG BUKIT TIMAH ROAD FROM KK HOSPITAL TOWARDS SIM LIM TOWER. I STOPPED AT THE TRAFFIC LIGHT BETWEEN TEKKA LANE AND RACE COURSE ROAD. SUDDENLY, I HEARD A LOUD NOISE AND I NOTICED MY CAR WAS HIT AT THE BACK BY ANOTHER CAR (SJR2673G)

Attachment(s)

Are accident photos available for attachment? YES
 Was there any video captured by Car Camera? NO
 Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SJR2673G
 Vehicle Make/Model/Colour
 Details Of Properties VEHICLE B
 Vehicle Category PRIVATE CAR
 Name of Driver
 NRIC/Passport Number
 Contact Number
 Address
 Postcode
 Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

Sketch Plan Pg. 1


SKETCH PLAN

IMPORTANT NOTICE


1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:


- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

x 

Policyholder's Signature
Date & Time:



Driver's Signature
(If driver is not the policyholder)
Date & Time:




Reporting Centre Personne's Signature
Name:
NRIC/FIN No.:

GIA/PA... 3/19/2019 14:35 FAX

JEC AUTO

Sketch Plan #2 Pg. 1

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 18/1/19 @ 6.33 pm, I was driving along Bukit Timah Road from K.K Hospital towards Sim Lim Tower. I stopped at the traffic light between Tekka Lane and Race course Road. Suddenly I heard a loud noise and I notice my car was hit at the back by another car SJR2673G.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

19/1/19 p 10.33AM

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

JEC AUTO SERVICE

1 Kaki Bukit Ave 6 #02-11 Autobay, Singapore 417883
 Hp: 9232 7457@Ah Xian Tel: 6509 6585 Fax: 6509 6584
 Email: jecautoservice@yahoo.com.sg

not Authorised
Hubb
L/S 3900/
23/1/19
Wh. pt. After repair
4 day.


Vehicle No.: SJT 3270 T

Model: Audi A3

Qty Description

List Items

- 1 Rear boot lid
- 2 Rear boot lamps
- 1 Rear boot lock
- 1 Rear boot logo
- 1 Rear boot rubber
- 1 Rear boot "A3" emblem *ps*
- 1 Rear boot "TFSI" emblem
- 2 Rear taillamps
- 1 Rear end panel
- 1 Rear end panel inner garnish
- 1 Rear bumper
- 2 Rear bumper side brackets
- 1 Rear bumper clip (1 set)
- 2 Rear bumper reflectors
- 1 Rear bumper reinforcement *50/*
- 2 Rear bumper side retainers
- 1 Rear bumper lower diffuser
- 4 Rear bumper PDC sensors *460*
- 1 Rear exhaust silencer
- 2 Rear exhaust mountings



Amt S(\$)

\$	<i>n</i>	2,171.00	<i>X</i>
\$	<i>nn</i>	970.00	<i>X</i>
\$	<i>nn</i>	146.00	<i>X</i>
\$	<i>nn</i>	94.00	<i>✓</i>
\$	<i>nn</i>	211.00	<i>X</i>
\$	<i>nn</i>	94.00	<i>✓</i>
\$	<i>nn</i>	68.50	<i>✓</i>
\$	<i>one</i>	1,150.00	<i>✓</i>
\$	<i>n</i>	885.00	<i>X</i>
\$	<i>nn</i>	216.00	<i>X</i>
\$	<i>nn/one</i>	1,078.80	<i>✓</i>
\$	<i>nn</i>	98.00	<i>X</i>
\$	<i>nn</i>	80.00	<i>✓</i>
\$	<i>nn</i>	210.00	<i>X</i>
\$	<i>set</i>	655.00	<i>✓</i>
\$	<i>nn</i>	98.00	<i>X</i>
\$	<i>grad/psn</i>	421.50	<i>✓</i>
\$	<i>Shuko</i>	920.00	<i>2pcs</i>
\$	<i>nn</i>	1,687.50	<i>X</i>
\$	<i>nn</i>	92.00	<i>X</i>
\$		11,346.30	<i>✓</i>
\$		567.32	<i>3938-80</i>
\$		10,778.99	<i>3741-86</i>

Less 5%

Labour Charges

1	To remove, replaced damaged lamps and check up rear wiring.	\$	80.00	<i>20</i>
2	To remove and refit inner garnishes.	\$	150.00	<i>60</i>
3	To remove and refit rear reverse sensor.	\$	150.00	<i>50</i>
4	To transfer boot lid mechanism and wiring assembly.	\$	120.00	<i>X</i>
5	To remove, refit and replace exhaust silencer and mountings.	\$	150.00	<i>X</i>
6	To apply undercoating.	\$	180.00	<i>X</i>
7	Panel beating, remove and replacing above parts.	\$	1,400.00	<i>400</i>
8	To respray painting.	\$	1,200.00	<i>600</i>
		\$	3,430.00	<i>4801-86</i>

ESTIMATE PARTS AND LABOUR TOTAL \$

\$ 14,208.99

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/SMO19001317/UTD3N2

Date: 22/02/2019

REFERENCE

Handling Insurer:	Sompo Insurance Singapore Pte. Ltd.	Policy No:	D18MTPV01010193
Claimant Vehicle No :	SJT3270T	Insured Vehicle No :	SJR2673G
Date of Loss:	18/01/2019	Nature of Claim:	TP
		Claim No:	CMTD1900449

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJT3270T	Engine No:	CZC537526
Make & Model:	AUDI A3, 1.4 SEDAN TFSI (AMBIENTE) (A)	Chassis No:	WAUZZZ8V7G1088421
Reg. Date:	29/04/2016 (Man. Year: 2016)	Odometer:	52441 km
Colour:	White		
Engine Capacity:	1395 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/55R16	Rear Tyre Size:	205/55R16
Front Left Side:	Hankook 6 mm	Rear Left Side:	Hankook 6 mm
Front Right Side:	Hankook 6 mm	Rear Right Side:	Hankook 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	10,778.98	3,741.86	7,037.12	65.29
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,430.00	1,140.00	2,290.00	66.76
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	14,208.98	4,881.86	9,327.12	65.64
Approved Total (Overridden) (S\$)		3,900.00		
Nett Amount (S\$)	14,208.98	3,900.00	10,308.98	72.55

INSPECTION

Date of Assignment:	21/01/2019	
Date Inspected:	23/01/2019	Inspected At:
		Jec Auto Service (HQ) 1 KAKI BUKIT AVENUE 6 #02-11, Autobay @ Kaki Bukit Singapore 417883
Estimated Period of Repair:	4.0 days	

Adjuster: MARCUS CHUA

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference	
Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 22 Feb 2019)
Parts: 144	AUDI A3 1.4 SEDAN TFSI (AMBIENTE) (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJT3270T)
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BOOT LID	Repair	2,171.00 FL	*- FL
2	2		*REAR BOOT LAMPS	Not Necessary	970.00 FL	*- FL
3	1		*REAR BOOT LOCK	Not Necessary	146.00 FL	*- FL
4	1		*REAR BOOT LOGO	Necessary	94.00 FL	*94.00 FL
5	1		*REAR BOOT RUBBER	Not Necessary	211.00 FL	*- FL
6	1		*REAR BOOT A3 EMBLEM	Necessary	94.00 FL	*85.00 FL
7	1		*REAR BOOT TFSI EMBLEM	Necessary	68.50 FL	*68.50 FL
8	2		*REAR TAILLAMPS	Cracked	1,150.00 FL	*1,150.00 FL
9	1		*REAR END PANEL	Repair	885.00 FL	*- FL
10	1		*REAR END PANEL INNER GARNISH	Not Necessary	216.00 FL	*- FL
11	1		*REAR BUMPER	Dented/Deformed	1,078.80 FL	*1,078.80 FL
12	2		*REAR BUMPER SIDE BRACKETS	Not Necessary	98.00 FL	*- FL
13	1		*SET REAR BUMPER CLIP	Necessary	80.00 FL	*80.00 FL
14	2		*REAR BUMPER REFLECTORS	Not Necessary	210.00 FL	*- FL
15	1		*REAR BUMPER REINFORCEMENT	Bent	655.00 FL	*501.00 FL
16	2		*REAR BUMPER SIDE RETAINERS	Not Necessary	98.00 FL	*- FL
17	1		*REAR BUMPER LOWER DIFFUSER	Grazed/Torn	421.50 FL	*421.50 FL
18	1		*REAR BUMPER PDC SENSORS (4 Pcs)	Shorted (2 Pcs only)	920.00 FL	*460.00 FL
19	1		*REAR EXHAUST SILENCER	Not Necessary	1,687.50 FL	*- FL
20	2		*REAR EXHAUST MOUNTINGS	Not Necessary	92.00 FL	*- FL

F=Franchise part. L=ListItemDisc.

Sub Total (\$\$)	11,346.30	3,938.80
- List Item Discount on L Items 5.00/5.00% (\$\$)	567.32	196.94
Total Parts (\$\$)	10,778.98	3,741.86

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE,REPLACED DAMAGED LAMPS AND CHECK UP REAR WIRING	New	80.00	30.00
2	TO REMOVE AND REFIT INNER GARNISHES	New	150.00	60.00
3	TO REMOVE AND REFIT REAR REVERSE SENSOR	New	150.00	50.00
4	TO TRANSFER BOOT LID MECHANISM AND WIRING ASSEMBLY	New	120.00	0.00
5	TO REMOVE,REFIT AND REPLACE EXHAUST SILENCER AND MOUNTINGS	New	150.00	0.00
6	TO APPLY UNDERCOATING	New	180.00	0.00
7	PANEL BEATING,REMOVE AND REPLACING ABOVE PARTS	New	1,400.00	400.00
8	TO RESPRAY PAINTING	New	1,200.00	600.00
Gross Labour Cost (S\$)			3,430.00	1,140.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >