

22/03/2002

ASS. REC. BY:

REF: CS3 / ALH19001327 / Ecd3ek

Special Instruction:

Surveyor: menjun ASSIGNMENT (Office)

From (Person): Chin Lee Ying of ALH Date/Time: 21-01-2019 2:09pm

Estimated Cost: _____ Bill to: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No.: SDL 1181T Insured: SGS 9593M

at Workshop m/s Auto Best Motor Tel: 6745 6932

of Blk 3006 Ubi Rd 1 # 01-362

Policy No: 2100504499 Claim No: 986637592586

Sum Insured: _____ Excess: _____

Make of Veh: _____ D.O.A. 16-01-2019
(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement: _____

Date/Time: 21/01/2019 4:28pm Person Contacted: Mr Lee Vehicle: IN / OUT

Date/Time	Action/Instruction (X) Estimate
	SDL 1181T - X
	SGS 9593M - X
	Dismantle: 24/1/2019

Steve

REF: AIG

PRS

ASSIGNMENT

From: Date: 22/1/19

Veh No: SDL 1181T Yr Regn: 17/01/2012

Estimated Cost:

Type: M.Car M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer or

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SDL 1181T

Make: Mercedes Benz E 250 C.C. 1796

at Workshop m/s

Colour: A/C Insured / Std / NI / NA

of

Sp. Reading: 115341 T/Radio: Insured / Std / NI / NA

Insured:

Eng/No:

Policy No.

C/No: W002120472 A537916

Claims No.

Gen. Cond: Good Fair / Poor / Burnt

Sum Insured: Excess:

Steering: Inorder Jammed / Leaked / Burnt or

(Client's Record)

Brake: Inorder Jammed / Leaked / Burnt or


Make of Veh:

Modi: Nil / S/Rim / STD A/Rim or

(Policy Condition)

Tyre Size: F: 265/352R18 R: 265/352R18

Remark: The veh had commenced its repair at the time of inspection.



BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or HABLEAD

Bal. or Market Value:

Front Rear

IDAC Accident Rpt: Consistent?: Yes or No

R/Bal. 5 mm

GIA / PR Seen: Consistent?: Yes or No

L/Bal. 5 mm

Est. Repairs: 5 days Res.: Yes or No

D.O.A. 16/1/2019 D.O.I. 22/1/2019

Lum Sum: % 3 Val.: Yes or No

Survey held at LKK

CA / REV / REP. / 24 HRS (up)

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Date: Person Contacted: Vehicle: IN / OUT

The U/C / Chassis frame / Body Structure affected due to collision.

Table with 2 columns: Date / Time, Action / Instruction. Handwritten entries: MV - 69,000, PV - 53,308, NV - 15,692.

Date/Time, File Pass to? []: Preli. Report []: Final Report

Days Of Repair: 5

Date/Time, File Return to? 1) 2)

Resurvey No. of Trip: 1

Survey Fee: 180

Add Fee: [] Site Insp (\$) [] Interview (\$) [] Tech. Invs (\$) [] Weekend (\$)

Transportation: [] S + RS [] SI [] Photos [] Others 10

Report Format: DAR

Lump Sum / I.B.I. (\$)

TOTAL 190

- PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURE...

From: Chin, Lee-Ying
To: assignments, Admin A
Cc: Fong, Andy-SY
Sent: 21/1/2019 2:09:51 PM
Attachments:  [SDL1181T.PDF](#)

Hi LKK.

Please assist to survey.

Thanks.

Best Regards
Lee Ying, Chin
AIG
Claims | AIG Asia Pacific Insurance Pte. Ltd.
78 Shenton Way #08-16 Singapore 079120
Tel +(65) 6419 1947
Lee-Ying.Chin@aig.com | www.aig.sg

From: gslimlaw@singnet.com.sg [mailto:gslimlaw@singnet.com.sg]

Sent: Friday, January 18, 2019 4:12 PM

To: Hor, Yinrul

Cc: Fong, Andy-SY; Chin, Lee-Ying; Abu Kassim, Noor Mariesa; Azlan, Syazairdina; Chan, Yoke Shi; Lim, Sheng Yang; Md Ishak, Mohd Imran; Mithoosingh, Aashweenjeetkaur; gslimlaw@singnet.com.sg

Subject: RE: - PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SGS9593M AND SDL1181T ON 09/01/2019

Our Ref : HL/ABM/11978/19/ck

Your Ref : 9866375925SG003

Dear Sirs

We refer to your email of even date.

Pursuant to State Courts Practice Directions Amendment No. 1 of 2016, our client is not agreeable to your list of surveyors. Our client's appointed surveyor is Mr Kent Ong (KTO Automobile Assessors).

Please contact and liaise with the workshop directly to arrange for the pre-repair survey of our client's damaged vehicle and obtain the requisite documents from them.

Workshop

Auto Best Motor Services

Address

Blk 3006 Ubi Road 1 #01-362 Singapore 408700

Contact Person Mr Lee

Tel No. 67456932

Thank you

Regards,

G S Lim & Partners | 150 South Bridge Road #02-30 Fook Hai Building Singapore 058727
Tel : 65324518 | Fax : 65325410 | Email gslimlaw@singnet.com.sg

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

林
錦
秀
律
師
館

G S LIM & PARTNERS

Advocates & Solicitors
Notary Public
Commissioner for Oaths

HENRY G S LIM
LLB (Hons) (London)
Barrister-at-Law (Lincoln's Inn)

DAVID YONG KHUNG LIN
LLB (Hons) (University of Bristol)

150 South Bridge Road
#02-30 Fook Hai Building
Singapore 058727
Tel 65324518 Fax 65325410
email : gslimlaw@singnet.com.sg
UEN 53131358A
GST Reg No. M90361086A

Our Reference : HL/ABM/11978/19/ck
Your Reference :

18 January 2019

M/S AIG ASIA PACIFIC INSURANCE PTE LTD
78 SHENTON WAY
#08-16
SINGAPORE 079120

BY FAX 64153727 ONLY

Attn : Motor Claims Department

Dear Sirs

**PRE-REPAIR SURVEY – NOTIFICATION OF INSPECTION
ACCIDENT AT BKE EXIT TO KJE EXIT 5 INVOLVING SJV 4017S, SDL 1181T & SGS 9593M ON
16.01.19**

We are instructed by M/s Auto Best Motor Services to notify you of a road traffic accident on 16.01.19 along BKE exit to KJE Exit 5 involving our client's vehicle registration number SDL 1181T and SGS 9593M driven by your insured at the material time. A copy of our client(s) Singapore Accident Statement is attached.

As a result of the accident, our client's vehicle has been damaged. Before our client proceed to repair the damaged vehicle, please let us know within two (2) working days of your receipt of this notice whether you would like to conduct a pre-repair survey of the vehicle. If we do not receive any reply from you within the stipulated timeline, our client shall proceed to repair the vehicle without further reference to you.

Yours faithfully



HENRY G S LIM

Encl

cc : M/s Auto Best Motor Services

> **Back to OneMotoring**

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	1181C
Vehicle Details	
Vehicle No.:	SDL1181T
Vehicle to be Exported:	No
Intended Deregistration Date:	22 Jan 2019
Vehicle Make:	MERCEDES BENZ
Vehicle Model:	E 250
Primary Colour:	Silver
Manufacturing Year:	2011
Engine No.:	27186030372029
Chassis No.:	WDD2120472A537916
Maximum Power Output:	150.0 kW (201 bhp)
Open Market Value:	\$54,036.00
Original Registration Date:	17 Jan 2012
First Registration Date:	17 Jan 2012
Transfer Count:	2
Actual ARF Paid:	\$54,036.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	16 Jan 2022
PARF Rebate Amount:	\$32,421.00
Intended COE Rebate Details	
COE Expiry Date:	16 Jan 2022
COE Category:	B - Car (1601cc & above)
COE Period(Years):	10
QP Paid:	\$70,003.00
COE Rebate Amount:	\$20,887.00
Total Rebate Amount:	\$53,308.00

The information contained herein is correct as at 22 Jan 2019

OK



AVIVA

Post an Advertisement
Sell it yourself! Advertise it at just
\$58 until it's SOLD!

Post an Ad Advertiser Login Ways of Selling

New 5 Years Coe Renewal Toyota Vios 1.5a



Driveaway \$2300(Inc:insurance & Adv) 2.88%p.a Monthly \$468
By Gv Finance
GV Credit Pte Ltd StarAd

Lake View Credit Pte Ltd [view our cars](#)

- > Low prices guaranteed
- > Specialist in Japanese cars
- > Easy loan approval
- > All terms are negotiable

Browse by Category ▼

Sort by Date Posted ▼ 20 results/page

9 vehicles

mercedes benz e250

Advanced Search 🔍

Make Model Price Depreciation Reg Date Eng Cap Mileage Veh Type Status

Search Selection mercedes benz e250 Any Any 2012 Any Any Any Available



Mercedes-Benz E-Class E250 CGI Avantgarde **\$81,888** \$14,390 /yr 05-Nov-2012 1,796 cc - Luxury Available

Ultimate Luxury Sedan Pristine Condition Well Taken Care By Meticulous Owner, Classy Black Interior Upholstery, Comfortable Drive With Power On Demand, Immaculate Condition, Up To 90% Loan And Trade I...

TTS Euroclub

Posted: 22-Jan-2019 Tags: 2012 Mercedes-Benz E250, 2012 mercedes-benz e250, Mercedes-Benz E250, mercedes-benz e250, Mercedes-Benz, E250, e250, Used Mercedes-Benz



Mercedes-Benz E-Class E250 CGI Avantgarde **\$85,800** \$15,760 /yr 06-Nov-2012 1,796 cc 29,965 km Luxury Available

(Super Low Mileage Only 29965Km), Fully Maintained By C&C, Loan Packages Available, Interest Rate, Mint Condition, Hurry Call Now.

Hamilton Autohub Pte Ltd

Posted: 22-Jan-2019 Tags: 2012 Mercedes-Benz E250, 2012 mercedes-benz e250, Mercedes-Benz E250, mercedes-benz e250, Mercedes-Benz, E250, e250, Used Mercedes-Benz



Mercedes-Benz E-Class E250 **\$69,800** \$14,430 /yr 10-Jan-2012 1,796 cc 130,000 km Luxury Available

Low Monthly Installment! Well Maintained By Previous Owner! 100% Accident Free. High Trade In Welcome! Bank Loan Or In House Loan Available! Call Me Now Before It's Sold!

Viking Motor Pte Ltd

Posted: 21-Jan-2019 Tags: 2012 Mercedes-Benz E250, 2012 mercedes-benz e250, Mercedes-Benz E250, mercedes-benz e250, Mercedes-Benz, E250, e250, Used Mercedes-Benz



Mercedes-Benz E-Class E250 CGI Cabriolet **\$89,800** \$17,590 /yr 30-Jul-2012 1,796 cc - Sports Available

Graded **B** by **STAR**

Excellent Condition! Interest From 2.78%! Buy With A Peace Of Mind From Award Accredited Company! Attractive Loan Package And Competitive Trade In Price! Call Now To Find Out More!

Autolink Holdings Pte Ltd

Posted: 19-Jan-2019 Tags: 2012 Mercedes-Benz E250, 2012 mercedes-benz e250, Mercedes-Benz E250, mercedes-benz e250, Mercedes-Benz, E250, e250, Used Mercedes-Benz



Blowing your hair in style with Mercedes

While the Mercedes-Benz Coupe was an exciting car, the Cabriolet here does not fall short. Find out just how much of a hair-dryer this car is.

Read this article

Mercedes-Benz E-Class E250 **\$68,800** \$14,050 /yr 13-Jan-2012 1,796 cc - Luxury Available

High Paper Value! Nice Bidded Number Plate 2268. Perfect Condition. Like New. Guarantee Buy Back At Only 12k Depre. Flexible Loan Scheme Available With Bank/In-House, High Loans, High Trade Ins, Low I...

Compare

Car Empire Automobiles Pte Ltd

PREMIUM



Posted: 11-Jan-2019 Tags: 2012 Mercedes-Benz E250, 2012 mercedes-benz e250, Mercedes-Benz E250, mercedes-benz e250, Mercedes-Benz, E250, e250, Used Mercedes-Benz



Mercedes-Benz E-Class E250 CGI **\$71,800** \$14,730 /yr 17-Feb-2012 1,796 cc 51,900 km Luxury **Availabl**

Classy Black Exterior, Immaculate Condition! Well Maintained Inside Out, Very Low Original Mileage, Service Records Available, View To Believe! Viewing Strictly By Appointment Only.

360 VR Cars

Posted: 01-Jan-2019 Tags: 2012 Mercedes-Benz E250, 2012 mercedes-benz e250, Mercedes-Benz E250, mercedes-benz e250, Mercedes-Benz, E250, e250, Used Mercedes-Benz



Mercedes-Benz E-Class E250 Cabriolet **\$99,800** \$19,070 /yr 12-Nov-2012 1,796 cc 97,000 km Sports **Availabl**

Elegant White With Red Interior, Owner 2nd Car And Very Much Under Utilise, Bidded Plate To Go With Car, High Loan/Bank/Finance/In House Loan Available, Trade In Welcome. Owner Consignment, PI Unit, C...

Posted: 26-Dec-2018 Tags: 2012 Mercedes-Benz E250, 2012 mercedes-benz e250, Mercedes-Benz E250, mercedes-benz e250, Mercedes-Benz, E250, e250, Used Mercedes-Benz



Mercedes-Benz E-Class E250 Coupe **\$75,000** \$15,900 /yr 12-Jan-2012 1,796 cc 130,000 km Sports **Availabl**

7 Speed E250 In Market With Newer Facelift Of Straight DRL. 1 Owner Car. Lady Driver. Nice Beautiful Condition. Well Looked After With CSII Paint Protection. LTA Approved Carlsson Exhaust System. Acci...

Posted: 19-Dec-2018 Tags: 2012 Mercedes-Benz E250, 2012 mercedes-benz e250, Mercedes-Benz E250, mercedes-benz e250, Mercedes-Benz, E250, e250, Used Mercedes-Benz

DIRECT OWN



Mercedes-Benz E-Class E250 Cabriolet **\$94,800** \$22,390 /yr 03-Jan-2012 1,796 cc 72,000 km Sports **Availabl**

C&C Unit, Super Condition, The Best E Class Cabriolet You Can Find! Why Wait? Viewing By Appointment Only For This Consignment Unit. Call Our Friendly Staffs For A No Obligations Discussion.

Car Search

Posted: 10-Dec-2018 Tags: 2012 Mercedes-Benz E250, 2012 mercedes-benz e250, Mercedes-Benz E250, mercedes-benz e250, Mercedes-Benz, E250, e250, Used Mercedes-Benz

CONSIGNME

Save this search criteria, to get email alerts whenever a match is found.

Make Model Price Depreciation Reg Date Eng Cap Mileage Veh Type Status

For old advertisements, view [Expired ads](#)

20 results/pag

[Home](#) | [New Cars](#) | [Used Cars](#) | [Sell My Car](#) | [Directory](#) | [Products](#) | [Insurance](#) | [Article](#) | [Forum](#) | [Resources](#)

sgCarMart is the number one car classifieds for parallel import cars, Toyota, Honda, Nissan, Mitsubishi & BMW. There are plenty of cars for sale, from vans, trucks, sedan cars, luxury cars, cars or stationwagons, SUV, MPV, hatchback, to COE cars & OPC cars. You can also buy from a car auction, look up car loans, financial services, low mileage cars, car brands, carpark rate insurance. Find buy used mercedes benz e250, mercedes benz e250 Singapore, used mercedes benz e250 Singapore, used mercedes benz e250, used vehicles Singapore or even buy u mercedes benz e250 Singapore. We have new car dealers comprising parallel importers, authorised car dealers, and used car dealers on our site. Find new car price lists, new car launche new car promotions. Visit our partner sites for job openings for Singapore jobs, real estate properties for sale, mover, car performance parts, car discussion, forum discussion, commercial leasing & COE results.

All prices and other information displayed on sgCarMart.com are gathered from sources and based on algorithms that are believed by sgCarMart.com to be reliable, but no assurance can be that this information is accurate, complete or current. sgCarMart.com does not assume any responsibility for errors or omissions or warrant the accuracy of this information.

Follow sgCarMart.com

[About Us](#) | [Careers](#) | [Contact Us](#) | [Sitemap](#) | [Terms of Service](#) | [Privacy Policy](#) | [Personal Data Protection Statement](#)

©2004-2019 sgCarMart. All rights reserved.

Compare

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	17/01/2019 13:33
Date Of Accident	16/01/2019 10:15
Exact Location Of Accident	BKE EXIT TO KJE AT EXIT 5
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SDL1181T
Insured/Policyholder	
Name Of Registered Owner	CHUA CHUN LENG ROLAND
NRIC No	S1791181C
Email Address	ROLCHUA@SINGNET.COM.SG
Mobile Phone No	(LOCAL) +65-93895639
Alternative Phone No	OFFICE-93895639

Vehicle Particulars

Manufacturer	MERCEDES-BENZ
Model	E250-1.8 (A)
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	TOKIO MARINE INSURANCE SINGAPORE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	MT000477
Cover Note Number	

Driver

Name of Driver	CHUA CHUN LENG ROLAND
NRIC No	S1791181C
Date Of Birth	09/12/1967
Occupation	INDOOR
Date Of Driving Pass	19/04/1985
Driving Experience	33 YEARS AND 8 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-93895639
Fax Number	
Contact Number	OFFICE-93895639
EEmail Address	ROLCHUA@SINGNET.COM.SG

Address	BLK 225B COMPASSVALE WALK #13-329
Postcode	542225
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	CHAIN COLLISION
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	3
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

STATEMENT RECORDED BY SOO - PROGRESSIVE CAR CARE PTE LTD (6741 5336)

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SGS9593M
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	CHAN LIN MING
NRIC/Passport Number	S8277104B
Contact Number	93364046
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

Sketch Plan


SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) Investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purpose")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
- (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time:




Driver's Signature
(if driver is not the policyholder)
Date & Time:



Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Sketch Plan #2

SKETCH PLAN





DESCRIBE CIRCUMSTANCES OF THE ACCIDENT


I was driving along BKE to KJE at Exit 5
 Car 'C' suddenly stop and I applied Emergency
 Brakes. I heard Bang! Bang! Car 'B' hit my
 car & I hit Car 'C'.

DECLARATION

I/We declare the foregoing particulars are true in every respect.
 Please be advised that your insurer may have a fourteen (14) days claim whereby the claim against own policy must be made within the stipulated timeframe
 from the day of occurrence. Kindly check your policy for more details.


 Policyholder's Signature
 Date & Time:


 Driver's Signature
 (If driver is not the policyholder)
 Date & Time:


 Reporting Centre Personnel's Signature
 Name:
 NRIC/FIN No.:

Condition (CON)

(01) Bent (2) Dented (3) Distorted (4) Cracked (5) Cut (6) Scratched
 (07) Deformed (08) Shifted (09) Buckled (10) Broken (11) Necessary
 (12) Missing (13) Torn (14) Unconfirmed (15) Not Working

MOTORCAR (Rear)

(1) Replace (✓) (2) Repair (X) (3) Check (P)
 (4) Not Consistent (NC)

Vehicle No:

SOL 1181T 2852

Rear Portion

NAC	INC	Item	CON	AC	Qty
1137	993626	Rear Number Plate			
1138	993627	Rear Number Plate Base			
1139	993630	Rear Number Plate Garnish			
1140	993632	Rear Number Plate Lamp			
1141	992958	Rear Bumper	DD	✓	
1142	993085	Rear Bumper Upper			
1143	993017	Rear Bumper Lower			
1144	993054	Rear Bumper Side			
1145	993103	Rear Bumper Tow Cover			
1146	992341	Rear Bumper Clips	NEC	✓	
1147	992976	Rear Bumper Bracket			
1148	993068	Rear Bumper Side Retainer	RR	✓	2
1149	993045	Rear Bumper Reinforcement	BT	✓	
1150	992970	Rear Bumper Beam			
1151	993077	Rear Bumper Sponge			
1152	992999	Rear Bumper Damper			
1153	993040	Rear Bumper Protector			
1154	993036	Rear Bumper Pad			
1155	993026	Rear Bumper Moulding	NEC	✓	3
1156	993044	Rear Bumper Reflector			
1157	993023	Rear Bumper Lower Spoiler			
1158	994023	Reverse Sensor			
1159	993327	Rear End Panel	RT	R	
1160	993339	Rear End Panel Top Garnish			
1161	993333	Rear End Panel Inner Trim			
1162	990333	Boot Compartment Inner Trim			
1163	993851	Rear LH Taillamp			
1164	993853	Rear LH Taillamp Garnish			
1165	993859	Rear LH Taillamp Panel			
1166	995116	Rear RH Taillamp			
1167	993853	Rear RH Taillamp Garnish			
1168	993859	Rear RH Taillamp Panel			
1169	993554	Rear Apron Panel			
1170	992895	Bootlid			
1171	991328	Bootlid Emblem			
1172	990356	Bootlid Handle			
1173	995250	Bootlid Moulding			
1174	990376	Bootlid Reflector			
1175	995222	Bootlid Lamp LH			
1176	992899	Bootlid Lamp RH			
1177	995243	Bootlid Lock			
1178	990377	Bootlid Rubber			
1179	990382	Bootlid Hinge			
1180	993877	Bootlid Spoiler			
1181	994543	Tailgate			
1182	991328	Tailgate Emblem			
1183	994643	Tailgate Outer Handle			
1184	994640	Tailgate Moulding			
1185	994545	Tailgate Garnish			
1186	994648	Tailgate Reflector			
1187	994549	Tailgate Lamp			
1188	994646	Tailgate Protector			
1189	994676	Tailgate Wiper Arm			
1190	994677	Tailgate Wiper Blade			
1191	994679	Tailgate Wiper Nozzle			
1192	994555	Tailgate Wiper Motor			
1193	994602	Tailgate Glass			
1194	994606	Tailgate Glass Rubber			
1195	994604	Tailgate Glass Moulding			
1196	994607	Tailgate Glass Sealant			
1197	994629	Tailgate Lock			
1198	994651	Tailgate Rubber			
1199	994611	Tailgate Hinge			
1200	994594	Tailgate Damper			

Handwritten notes:
 NEC
 25/1/2019

NAC	INC	Item	CON	AC	Qty
1202	993784	Spare Tyre Board			
1203	994328	Spare Tyre Panel			
1204	995065	Spare Tyre			
1205	994326	Spare Tyre Lock Screw			
1206	993787	Spare Tyre Cover			
1207	995323	Triangle Breakdown Sign			
1208	990507	CD Changer Assy			
1209	990164	Antenna			
1210	990534	Centre Exhaust Pipe Assy			
1211	990532	Centre Exhaust Mounting			
1212	993364	Rear Exhaust Pipe			
1213	993357	Rear Exhaust Chrome Pipe			
1214	993361	Rear Exhaust Mounting			
1215	993358	Rear Exhaust Heat Shield			
1216	995223	Rear LH Chassis Member			
1217	993165	Rear RH Chassis Member			
1218	993436	Rear LH Fender			
1219	993449	Rear LH Fender Protector			
1220	993420	Rear LH Fender Inner Panel			
1221	993431	Rear LH Fender Inner Trim			
1222	993415	Rear LH Fender Inner Garnish			
1223	993425	Rear LH Fender Inner Shield			
1224	993621	Rear LH Mudflap			
1225	993933	Rear LH Wheel Rim			
1226	994025	Rear LH Rim Cover			
1227	995065	Rear LH Tyre			
1228	993456	Rear RH Fender			
1229	993450	Rear RH Fender Protector			
1230	993420	Rear RH Fender Inner Panel			
1231	993431	Rear RH Fender Inner Trim			
1232	993415	Rear RH Fender Inner Garnish			
1233	993425	Rear RH Fender Inner Shield			
1234	993622	Rear RH Mudflap			
1235	993934	Rear RH Wheel Rim			
1236	994025	Rear RH Rim Cover			
1237	995065	Rear RH Tyre			
1238	995162	Rear Fender Extension Panel LH			
1239	993491	Rear Fender Extension Panel RH			
1240	993430	Rear Fender Inner Top Garnish			
1241	993673	Rear Fender 1/4 Glass			
1242	993452	Rear Fender 1/4 Glass Rubber			
1243	993453	Rear Fender 1/4 Glass Sealant			
1244	993949	Rear Windscreen Glass			
1245	993976	Rear Windscreen Rubber			
1246	993961	Rear Windscreen Moulding			
1247	993955	Rear Windscreen Sealant			
1248	994729	Third Brake Light			
1249	993385	Rear Fender Air Grille			
1250	992167	Fuel Lid			
1251	992168	Fuel Neck			
1252	992179	Fuel Tank			
1253	992184	Fuel Tank Bracket			
1254	992191	Fuel Tank Float			
1255	990247	Sticker			

...CLAIM SUBFOLDER...(Pending for Survey Report)

PRI

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	17 Jan 2019 Edit Reg		21 Jan 2019 00:00 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured:	Chan Lin Ming (Zeng LinMin) , ID: S8277104B								
Main Claimant:	CHUA CHUN LENG ROLAND , ID: S1791181C								
Vehicle Reg. No.:	SDL1181T	Date of Loss:	16/01/2019 10:00 - :59 [83 Months and 30 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 9866375925SG	Policy/Cover Note No.:	2100504499 (Comprehensive)						
Vehicle Reg. No. (Insured):	SGS9593M	Policy No. (Claimant):							
		Excess:							
Repairer:	Auto Best Motor Services (HQ) BLK 3006 UBI ROAD 1, #01-362, 408700 Ubi - Tel:								
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by MdNoor, Norsiah] Norsiah.MdNoor@aig.com								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by CHEN TSUE YEE] ... [Final Rpt due 30/01/2019]								
Claimant's Solicitor:	G S LIM & PARTNERS - Tel: 65324518								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
• AIG_SG (22/01/2019): Request To Upload TP GIA Report									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SDL1181T (9866375925SG)**
[SGS9593M]
TP
CHUA CHUN LENG ROLAND
Jan 16 2019 10:00AM
[Chan Lin Ming (Zeng LinMin)]
Auto Best Motor Services

Upload Documents	Upload Photos	Compose New Letter	Upload Video	Upload Audio	View View in Browser
Assessment Reports					1 per page <input type="checkbox"/>
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)		Thumbnail	Print
1	22/01/19 13:03	Accident Statement From: SC - Reg. No: SGS9593M, Claimant: CHAN LIN MING (ZENG LINMIN)	1	Load HTM	<input type="checkbox"/>
Photos/Images					3 per page <input type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	23/01/19 08:53	General View	1	Load JPG	<input checked="" type="checkbox"/>
2	23/01/19 08:53	General View	1	Load JPG	<input checked="" type="checkbox"/>
3	23/01/19 08:53	General View	1	Load JPG	<input checked="" type="checkbox"/>
4	23/01/19 08:53	General View	1	Load JPG	<input checked="" type="checkbox"/>
5	23/01/19 08:53	General View	1	Load JPG	<input checked="" type="checkbox"/>
6	23/01/19 08:53	General View	1	Load JPG	<input checked="" type="checkbox"/>
7	23/01/19 08:53	General View	1	Load JPG	<input checked="" type="checkbox"/>
8	23/01/19 08:53	General View	1	Load JPG	<input checked="" type="checkbox"/>
9	23/01/19 08:53	General View	1	Load JPG	<input checked="" type="checkbox"/>
10	23/01/19 08:53	General View	1	Load JPG	<input checked="" type="checkbox"/>
11	23/01/19 08:53	General View	1	Load JPG	<input checked="" type="checkbox"/>
12	23/01/19 08:53	General View	1	Load JPG	<input checked="" type="checkbox"/>
13	23/01/19 08:53	General View	1	Load JPG	<input checked="" type="checkbox"/>
14	23/01/19 08:53	General View	1	Load JPG	<input checked="" type="checkbox"/>
15	23/01/19 08:53	General View	1	Load JPG	<input checked="" type="checkbox"/>
16	23/01/19 08:53	General View	1	Load JPG	<input checked="" type="checkbox"/>
17	23/01/19 08:53	General View	1	Load JPG	<input checked="" type="checkbox"/>
18	23/01/19 08:53	General View	1	Load JPG	<input checked="" type="checkbox"/>
19	23/01/19 08:53	General View	1	Load JPG	<input checked="" type="checkbox"/>
20	23/01/19 08:53	General View	1	Load JPG	<input checked="" type="checkbox"/>
21	23/01/19 08:53	General View	1	Load JPG	<input checked="" type="checkbox"/>
22	23/01/19 08:53	General View	1	Load JPG	<input checked="" type="checkbox"/>
23	23/01/19 08:53	General View	1	Load JPG	<input checked="" type="checkbox"/>
24	23/01/19 08:53	General View	1	Load JPG	<input checked="" type="checkbox"/>
25	23/01/19 08:53	General View	1	Load JPG	<input checked="" type="checkbox"/>
26	23/01/19 08:53	General View	1	Load JPG	<input checked="" type="checkbox"/>
27	23/01/19 08:53	General View	1	Load JPG	<input checked="" type="checkbox"/>
28	23/01/19 08:53	General View	1	Load JPG	<input checked="" type="checkbox"/>
29	23/01/19 08:53	General View	1	Load JPG	<input checked="" type="checkbox"/>
30	23/01/19 08:53	General View	1	Load JPG	<input checked="" type="checkbox"/>
31	23/01/19 08:53	General View	1	Load JPG	<input checked="" type="checkbox"/>
32	23/01/19 08:53	General View	1	Load JPG	<input checked="" type="checkbox"/>
33	23/01/19 08:53	General View	1	Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
34	23/01/19 08:53	General View	 Load JPG	<input checked="" type="checkbox"/>
35	23/01/19 08:53	General View	 Load JPG	<input checked="" type="checkbox"/>
36	23/01/19 08:53	General View	 Load JPG	<input checked="" type="checkbox"/>
37	23/01/19 08:53	General View	 Load JPG	<input checked="" type="checkbox"/>
38	23/01/19 08:53	General View	 Load JPG	<input checked="" type="checkbox"/>
39	23/01/19 08:53	General View	 Load JPG	<input checked="" type="checkbox"/>
40	23/01/19 08:53	General View	 Load JPG	<input checked="" type="checkbox"/>
41	23/01/19 08:53	General View	 Load JPG	<input checked="" type="checkbox"/>
42	23/01/19 08:53	General View	 Load JPG	<input checked="" type="checkbox"/>
43	23/01/19 08:53	General View	 Load JPG	<input checked="" type="checkbox"/>
44	23/01/19 08:53	General View	 Load JPG	<input checked="" type="checkbox"/>
45	23/01/19 08:53	General View	 Load JPG	<input checked="" type="checkbox"/>
46	23/01/19 08:53	General View	 Load JPG	<input checked="" type="checkbox"/>
47	25/01/19 11:55	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
48	25/01/19 11:55	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
49	25/01/19 11:55	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
50	25/01/19 11:55	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
51	25/01/19 11:55	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
52	25/01/19 11:55	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
53	25/01/19 11:55	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
54	25/01/19 11:55	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
55	25/01/19 11:55	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
56	25/01/19 11:55	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
<p>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</p> <div style="border: 1px solid black; height: 40px; width: 100%;"></div>			
<p>Show Remarks To: <input type="checkbox"/> Handling Insurer</p> <p><small>Note: Remarks are private unless you show it to other parties.</small></p>			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AIG19001327/ECD3E2

Date: 25/01/2019

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2100504499
Claimant Vehicle No : SDL1181T	Insured Vehicle No :	SGS9593M
Date of Loss: 16/01/2019	Nature of Claim:	TP Claim No: 9866375925SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SDL1181T	Engine No: 27186030372029
Make & Model: MERCEDES-BENZ E250, 1.8 (A)	Chassis No: WDD2120472A537916
Reg. Date: 17/01/2012 (Man. Year: 2011)	Odometer: 115341 km
Colour: Silver	
Engine Capacity: 1796 cc	
Market Value/New Car Price: N/A	
Sum Insured (S\$): Market Value/New Car Price	

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 265/35Z R18	Rear Tyre Size: 265/35Z R18
Front Left Side: Habilead 5 mm	Rear Left Side: Habilead 5 mm
Front Right Side: Habilead 5 mm	Rear Right Side: Habilead 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment:	21/01/2019	
Date Inspected:	22/01/2019	Inspected At: Auto Best Motor Services (HQ) BLK 3006 UBI ROAD 1, #01-362 Singapore 408700
Estimated Period of Repair:	5.0 days	

Adjuster: CHEN TSUE YEE

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount	
1	1		*FRT NUMBER PLATE	Cut	0.00 F	*- F	
2	1		*FRT BUMPER	Dented	0.00 F	*- F	
3	1		*FRT BUMPER CLIPS	Necessary	0.00 F	*- F	
4	2		*FRT BUMPER MOULDING LOWER	Necessary	0.00 F	*- F	
5	1		*FRT GRILLE	Broken	0.00 F	*- F	
6	1		*FRT GRILLE EMBLEM	Broken	0.00 F	*- F	
7	1		*FRT GRILLE BRACKET	Broken	0.00 F	*- F	
8	1		*BONNET	Repair	0.00 F	*- F	
9	1		*BONNET GARNISH	Cut	0.00 F	*- F	
10	1		*REAR BUMPER	Dented	0.00 F	*- F	
11	1		*REAR BUMPER CLIPS	Necessary	0.00 F	*- F	
12	2		*REAR BUMPER SIDE RETAINER	Broken	0.00 F	*- F	
13	1		*REAR BUMPER REINFORCEMENT	Bent	0.00 F	*- F	
14	3		*REAR BUMPER MOULDING	Necessary	0.00 F	*- F	
15	1		*REAR END PANEL	Repair	0.00 F	*- F	
					Total Parts (S\$)	0.00	0.00

F=Franchise part.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >