

Diagnostic Form

REF:

337 (RTP)

44424


COG EXPIRY: 2021/Jan

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 OD / P / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: **SHJ 23064**
 at Workshop m/s **MOVA**
 of **15, TAN YONG RD**
 Insured: **111**
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

Veh No: **SHJ 23064** Yr Regn: **2006 / July**
 Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or
 Make: **MITSUBISHI LANCEA 1.6m** c.c. **1584**
 Colour: **GREY** A/C: **Insured / Std / NI / NA**
 Sp. Reading: **250465** T/Radio: **Insured / Std / NI / NA**

(Policy Condition)
 Remark: The veh had commenced its
 repair at the time of inspection.



Eng/No: _____
 C/No: **JMY SNCS 3A6U 007382**
 Gen. Cond: **Good** / Fair / Poor / Burnt
 Steering: **in order** / Jammed / Leaked / Burnt or
 Brake: **in order** / Jammed / Leaked / Burnt or
 Mod: **Nil** / S/Rim / STD A/Rim or
 Tyre Size: F: _____ R: **195/60R15**
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or

Bal. or Market Value: **17K**
 IDAC Accident Rport: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: _____ days Res.: Yes or No
 Lum Sum: _____ % 3 Val.: Yes or No

Front mm Rear mm
 R/Bal. **5** mm R/Bal. **5** mm
 L/Bal. **5** mm L/Bal. **5** mm
 D.O.A. **14/01/19** D.O.I. **21/01/19**
 Survey held at **MOVA (FY)**

CA / REV / REP. / 24 HRS _____
 Date: _____ Person Contacted: _____
 Vehicle: IN / OUT _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
Rear N/S
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	repair (mt SK . refer to email)

Date/Time, File Pass to? : Preli. Report
 : Final Report
 1) _____
 Date/Time, File Return to? _____
 2) _____
 Report Format : _____
 Lump Sum / I.B.I. (\$) _____

Days Of Repair: _____
 Resurvey No. of Trip: _____
 Add Fee: : Site Insp (\$)
 : Interview (\$)
 : Tech. Invs (\$)
 : Weekend (\$)

Survey Fee: _____
 Transportation: _____
) \$ + RS. SI _____
) Photos _____
) Others _____
) _____
 TOTAL _____

Rasul (LKKAuto)

From: Rasul (LKKAuto)
Sent: Tuesday, 22 January, 2019 2:54 PM
To: 'Alan Chng'
Subject: SGJ 2306U DOA : 14/01/19

Hi Alan,

Repair limit for this case is 5K only


Best Regards,

Rasul | Assessor

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Rasul@lkkauto.com | fax: 6841-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Save the Earth. Print only when necessary.

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	4442G
Vehicle Details	
Vehicle No.:	SGJ2306U
Vehicle to be Exported:	No
Intended Deregistration Date:	22 Jan 2019
Vehicle Make:	MITSUBISHI
Vehicle Model:	LANCER 1.6 M
Primary Colour:	Grey
Manufacturing Year:	2006
Engine No.:	4G18HJ7605
Chassis No.:	JMYSNCS3A6U007382
Maximum Power Output:	79.0 kW (105 bhp)
Open Market Value:	\$11,490.00
Original Registration Date:	04 Jul 2006
First Registration Date:	04 Jul 2006
Transfer Count:	0
Actual ARF Paid:	\$12,639.00
Intended PARF Rebate Details	
PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	30 Jun 2021
COE Category:	E - Open Category
COE Period(Years):	5
PQP Paid:	\$23,227.00
COE Rebate Amount:	\$11,329.00
Total Rebate Amount:	\$11,329.00
Message	
Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 22 Jan 2019

OK

17,000
 11,329

 5671