



### Case Details

Case Reference Number : TAX001/19/2072  
 Type of Repair : Accident Repair  
 Vehicle Registration Number : SHC4792B

Company Type : SMRT Taxi Pte Ltd  
 Estimation ID : EST-6377-ID  
 Assigned By : Taxi Claims Manager Team

Insurance Company Name : AXA Insurance Singapore Pte Ltd  
 Accident Date and Time : 14/01/2019 04:05 PM  
 Vehicle Age(In Months) : 33

### Documents / Photographs

[View Documents / Photographs](#)

Total Documents: 1

### Estimation Details

#### Spare Part's Cost Detail

BOB Type	Coating Type	Portion	Material Number	Part Name	Qty	SMRT Recommendation				Repair/Replace	Surveyor Approval		Remarks	
						Lmt Price Per Unit(S)	Lmt Price(S)	Dis(%)	Final Price(S)		Surveyor Quantity	Surveyor Final Price(S)		Repair/Replace
One Time Key In	Main			PANEL, ROOF SIDE, / LH SIDE	1	134.80	134.80	25.00	101.10	Replace	0	0	Check	X NN
One Time Key In	Main			PANEL, ROOF SIDE OUTER LH	1	134.80	134.80	25.00	101.10	Replace	0	0	Not Give	X NN
One Time Key In	Main			RAIL, ROOF SIDE LH	1	273.60	273.60	25.00	205.20	Replace	1	0	Repair	X RR
One Time Key In	Main			DOOR RRLH	1	654.30	654.30	25.00	715.88	Replace	1	0	Repair	X RR
One Time Key In	Main			DOOR LOCK RRLH	1	708.30	708.30	25.00	531.87	Replace	0	0	Not Give	X NN
One Time Key In	Main			HINGE LOWER LHR, DOOR	1	72.20	72.20	25.00	54.15	Replace	0	0	Not Give	X NN
One Time Key In	Main			HINGE UPPER LHR, DOOR	1	81.70	81.70	25.00	61.28	Replace	0	0	Not Give	X NN
One Time Key In	Main			CHECK ASSY, FR DOOR,	1	180.30	180.30	25.00	112.73	Replace	0	0	Not Give	X NN
One Time Key In	Main			TAIL LAMP BRACKET, RH	1	30.70	30.70	25.00	23.02	Replace	0	0	Not Give	X NN
One Time Key In	Main			TAIL LAMP RH	1	537.80	537.80	10.00	502.82	Replace	0	0	Not Give	X NN
Total Spare Part Cost						49,983.55					Surveyor Total		8,875.50	
Lump Sum Discount (%)						0.00					Lump Sum Dis (%)		0	
Final Spare Part Cost						49,983.55					Final Sur Total		8,875.50	

SMRT Recommendation											Surveyor Approval			
BOM Type	Coating Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
One Time Key In	Main			TROUGH, BACK DOOR	1	110.90	110.90	25.00	83.19	Replace	0	0	Check	X NH
One Time Key In	Main			FENDER RR/RH	1	768.90	768.90	25.00	575.10	Replace	0	0	Not Give	X NH
One Time Key In	Main			SMRT LOGO	1	7.90	7.90	9.00	7.80	Replace	0	0	Not Give	X NH
One Time Key In	Main			STICKER DECAL 8555 8688	1	21.80	21.80	9.00	21.80	Replace	0	0	Not Give	X NH
One Time Key In	Main			FENDER LINER RR/RH	1	141.30	141.30	25.00	105.99	Replace	0	0	Not Give	X NH
One Time Key In	Main			DUCT ASSY, QUARTER	2	70.40	140.80	25.00	105.60	Replace	2	105.60	Replace	/ GUC
One Time Key In	Main			BACK ASSY, REAR SIDE SEAT, RH	1	843.90	843.90	25.00	628.95	Replace	0	0	Not Give	X NH
One Time Key In	Main			QUARTER GLASS RR/RH	1	848.50	848.50	25.00	636.38	Replace	0	0	Not Give	X NH
One Time Key In	Main			SEALANT W/SCREEN	1	37.00	37.00	9.00	37.00	Replace	0	0	Not Give	X NH
One Time Key In	Main			DOOR RR/RH	1	954.50	954.50	25.00	715.88	Replace	1	0	Repair	X R
One Time Key In	Main			DOOR LOCK RR/RH	1	709.20	709.20	25.00	531.97	Replace	0	0	Not Give	X NH
One Time Key In	Main			HNGE LOWER RR/R, DOOR	1	42.90	42.90	25.00	32.18	Replace	0	0	Not Give	X NH
One Time Key In	Main			HNGE UPPER RR/R, DOOR	1	81.75	81.75	25.00	61.31	Replace	0	0	Not Give	X NH
One Time Key In	Main			DOOR LOCK STRIKER	1	40.50	40.50	25.00	30.38	Replace	0	0	Not Give	X NH
One Time Key In	Main			BUMPER FRT	1	482.00	482.00	25.00	361.50	Replace	1	361.50	Replace	/ OR

Total Spare Part Cost 45,983.55

Lump Sum Discount (%) 0.00

Final Spare Part Cost 45,983.55

Surveyor Total 8,975.50

Lump Sum Dis (%) 0

Final Sur Total 8,975.50

SMART Recommendation											Surveyor Approval			
BOM Type	Coating Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
One Time Key In	Main			BUMPER CLIPS	10	1.81	18.10	25.00	12.08	Replace	10	12.08	Replace	/ NCL
One Time Key In	Main			BUMPER ENERGY ABSORBER FRT	1	78.80	78.80	25.00	59.10	Replace	0	0	Check	X NAI
One Time Key In	Main			BUMPER REINFORCEMENT FRT	1	498.40	498.40	25.00	373.60	Replace	0	0	Check	X NAI
One Time Key In	Main			ARM SUB-ASSY, FR BUMPER LH	1	350.40	350.40	25.00	187.80	Replace	0	0	Check	X NAI
One Time Key In	Main			ARM SUB-ASSY, FR BUMPER RH	1	350.40	350.40	25.00	187.80	Replace	0	0	Check	X NAI
One Time Key In	Main			BUMPER GRILLE SUB-ASSY, LOWER	1	311.10	311.10	25.00	233.33	Replace	1	233.33	Replace	/ SCR
One Time Key In	Main			FOG LAMP LH	1	285.10	285.10	19.00	232.09	Replace	1	232.09	Replace	/ SCR
One Time Key In	Main			BUMPER FRT ABSORBER LOWER	1	127.70	127.70	25.00	95.78	Replace	0	0	Check	X NAI
One Time Key In	Main			COVER, FR BUMPER HOLE LH	1	18.50	18.50	25.00	13.88	Replace	1	13.88	Replace	/ SCR
One Time Key In	Main			BUMPER SUPPORT FILH	1	76.40	76.40	25.00	57.30	Replace	1	57.30	Replace	/ CRJ
One Time Key In	Main			BRACKET, FR TURN CENTER LH	1	58.20	58.20	25.00	43.65	Replace	0	0	Check	X NAI
One Time Key In	Main			BRACKET, FR TURN UPPER LH	1	34.40	34.40	25.00	18.30	Replace	0	0	Check	X NAI
One Time Key In	Main			BRACKET, FR TURN LOWER LH	1	26.00	26.00	25.00	19.50	Replace	0	0	Check	X NAI
One Time Key In	Main			LENS & BODY, FR TURN LH	1	811.80	811.80	10.00	465.82	Replace	1	465.82	Replace	/ SCR
One Time Key In	Main			GRILLE, RADIATOR	1	310.80	310.80	25.00	232.95	Replace	0	0	Check	X NAI

Total Spare Part Cost 48,903.55

Lump Sum Discount (%) 0.00

Final Spare Part Cost 48,903.55

Surveyor Total 8,975.50

Lump Sum Dis (%) 0

Final Sur Total 8,975.50

SMRT Recommendation											Surveyor Approval			
SQM Type	Coating Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
One Time Key In	Main			SUPPORT SUB-ASSEMBLY	1	1,466.40	1,466.40	25.00	1,099.30	Replace	0	0	Check	X NN
One Time Key In	Main			HEAD LAMP LH	1	943.20	943.20	10.00	838.56	Replace	1	838.56	Replace	/ CRB
One Time Key In	Main			FENDER FRTLH	1	723.40	723.40	25.00	542.55	Replace	1	542.55	Replace	/ ORF
One Time Key In	Main			NAME PLATE (HYBRID)	1	41.90	41.90	25.00	31.42	Replace	1	31.97	Replace	/ NEC
One Time Key In	Main			FENDER LINER FRTLH	1	171.70	171.70	25.00	128.77	Replace	0	0	Check	X NN
One Time Key In	Main			FENDER LINER PAD, FR WHEEL LH	1	48.30	48.30	25.00	36.22	Replace	0	0	Not Give	X NR
One Time Key In	Main			PROTECTOR, FRONT FENDER SIDE PANEL LH	1	114.50	114.50	25.00	85.87	Replace	0	0	Check	X NN
One Time Key In	Main			TYRE	1	126.74	126.74	0.00	126.74	Replace	0	0	Check	X NN
One Time Key In	Main			WHEEL DISC, FRONT	1	1,494.30	1,494.30	25.00	1,119.15	Replace	1	0	Repair	X R
One Time Key In	Main			DOOR FRTLH	1	894.40	894.40	25.00	670.80	Replace	1	0	Repair	X R
One Time Key In	Main			STICKER DECAL SMRT (DOOR)	1	60.00	60.00	0.00	60.00	Replace	1	60.00	Replace	/ MC :
One Time Key In	Main			PILLAR, FR BODY, LH	1	363.10	363.10	25.00	272.32	Replace	1	0	Repair	X R
One Time Key In	Main			SEAL, FRONT FENDER TO COWL SIDE, LH	1	11.40	11.40	25.00	8.55	Replace	1	11.40	Replace	/ NEC
One Time Key In	Main			COOLANT	1	12.32	12.32	0.00	12.32	Replace	0	0	Check	X NN
One Time Key In	Main			QUARTER GLASS FRTLH	1	234.90	234.90	25.00	176.18	Replace	0	0	Not Give	X NN

Total Spare Part Cost 49,993.30  
 Lump Sum Discount (%) 0.00  
 Final Spare Part Cost 49,993.30

Surveyor Total 6,975.50  
 Lump Sum Dis (%) 0  
 Final Sur Total 6,975.50

BOM Type	Coating Type	Partion	Material Number	EMRT Recommendation							Surveyor Approval			
				Part Name	Qty	List Price Per UHR(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
One Time Key In	Main			SEALANT WISCREEN	1	37.00	37.00	0.00	37.00	Replace	0	0	Not Give *	X NAI
One Time Key In	Main			BUMPER REAR	1	408.60	408.60	25.00	343.96	Replace	1	343.96	Replace *	/ DEF
One Time Key In	Main			BUMPER CLIPS	10	1.81	16.10	25.00	12.08	Replace	10	12.08	Replace *	/ NEG
One Time Key In	Main			BUMPER REINFORCEMENT REAR	1	206.70	206.70	25.00	154.27	Replace	1	154.27	Replace *	/ DD
One Time Key In	Main			ARM SUB-ASSY, RR BUMPER LH	1	128.80	128.80	25.00	104.70	Replace	1	104.70	Replace *	/ DD
One Time Key In	Main			ARM SUB-ASSY, RR BUMPER RH	1	128.80	128.80	25.00	104.70	Replace	1	104.70	Replace *	/ DD
One Time Key In	Main			ANTENNA, ELECTRICAL LOWER REAR	1	127.40	127.40	10.00	114.66	Replace	0	0	Check *	X NAI
One Time Key In	Main			SENSOR REVERSE	1	180.00	180.00	0.00	180.00	Replace	1	180.00	Replace *	/ Shunk
One Time Key In	Main			FUEL STICKER	2	60.00	120.00	0.00	120.00	Replace	2	120.00	Replace *	/ NEG
One Time Key In	Main			BUMPER LIP COVER RHLH	1	72.20	72.20	25.00	54.15	Replace	1	54.15	Replace *	/ DEF
One Time Key In	Main			BUMPER LIP COVER RRRH	1	116.10	116.10	25.00	86.57	Replace	0	0	Not Give *	X NAI
One Time Key In	Main			BUMPER LIP REAR	1	228.80	228.80	25.00	177.68	Replace	1	177.68	Replace *	/ DEF
One Time Key In	Main			BUMPER SEAL, RR LH	1	66.90	66.90	25.00	50.18	Replace	1	50.18	Replace *	/ NEG
One Time Key In	Main			BUMPER SEAL, RR RH	1	65.70	65.70	25.00	49.28	Replace	1	49.28	Replace *	/ NEG
One Time Key In	Main			BUMPER SIDE RETAINER RHLH	1	94.80	94.80	25.00	71.10	Replace	1	71.10	Replace *	/ c.RA
Total Spare Part Cost									49,983.50	Surveyor Total				8,875.50
Lump Sum Discount (%)									0.00	Lump Sum Dis (%)				0
Final Spare Part Cost									49,983.50	Final Sur Total				8,875.50

SMRT Recommendation											Surveyor Approval			
SCM Type	Coating Type	Portion	Material Number	Part Name	Qty	List Price	List Price(\$)	Dis(%)	Final Price(\$)	Repair/Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
One Time Key In	Main			BUMPER SIDE RETAINER RR/RH	1	94.80	94.80	25.00	71.10	Replace	0	0	Not Give	X NN
One Time Key In	Main			UNDER COVER SUBASSY, RH FLOOR	1	314.80	314.80	25.00	238.88	Replace	1	385.88	Replace	/ DEF
One Time Key In	Main			EXHAUST HEAT SHIELD, REAR	1	107.40	107.40	25.00	80.55	Replace	0	0	Check	X NN
One Time Key In	Main			EXHAUST TAIL PIPE	1	606.20	606.20	25.00	454.15	Replace	0	0	Not Give	X NN
One Time Key In	Main			EXHAUST PIPE FIT	1	4,184.70	4,184.70	25.00	3,138.52	Replace	0	0	Not Give	X NN
One Time Key In	Main			SUPPORT EXHAUST PIPE, NO.A	2	40.20	80.40	25.00	60.45	Replace	0	0	Not Give	X NN
One Time Key In	Main			SUPPORT, EXHAUST REAR	2	33.00	67.20	25.00	50.40	Replace	0	0	Not Give	X NN
One Time Key In	Main			TAILGATE ASY	1	1,007.90	1,007.90	25.00	755.92	Replace	1	755.92	Replace	/ DD
One Time Key In	Main			TAIL GATE DOOR GLASS MOULDING, LH	1	29.40	29.40	25.00	22.05	Replace	1	22.05	Replace	/ NEG
One Time Key In	Main			TAIL GATE DOOR GLASS MOULDING, RH	1	29.40	29.40	25.00	22.05	Replace	1	22.05	Replace	/ NEG
One Time Key In	Main			TAILGATE DOOR GLASS	1	1,090.90	1,090.90	25.00	818.18	Replace	1	818.18	Replace	/ CBA
One Time Key In	Main			MOULDING BACK WINDOW, LOWER NO.1	1	29.40	29.40	25.00	22.05	Replace	1	22.05	Replace	/ NEG
One Time Key In	Main			TAILGATE LOWER WINDOW GLASS	1	721.30	721.30	25.00	540.97	Replace	1	540.97	Replace	/ CBA
One Time Key In	Main			SEALANT W/SCREEN	2	37.00	111.00	0.00	111.00	Replace	2	111.00	Replace	/ NEG
One Time Key In	Main			TAILGATE DOOR HINGE L/RH	2	58.20	116.40	25.00	87.45	Replace	2	0	Check	X NN
Total Spare Part Cost									48,892.88					
Lump Sum Discount (%)									0.00					
Final Spare Part Cost									48,892.88					
											Surveyor Total		8,975.50	
											Lump Sum Dis (%)		0	
											Final Sur Total		8,975.50	

SMRT Recommendation											Surveyor Approval			
BOM Type	Coating Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
One Time Key In	Main			TAILGATE DOOR LOCK	1	444.10	444.10	25.00	333.08	Replace	0	0	Check	X NN
One Time Key In	Main			TAILGATE DOOR STAY LH	1	241.50	241.50	25.00	181.13	Replace	0	0	Check	X NN
One Time Key In	Main			TAILGATE DOOR STAY RH	1	241.50	241.50	25.00	181.13	Replace	0	0	Check	X NN
One Time Key In	Main			TAILGATE DOOR WEATHER STRIP	1	253.40	253.40	25.00	189.55	Replace	0	0	Check	X NN
One Time Key In	Main			TAILGATE LOCK COVER	1	15.70	15.70	25.00	11.78	Replace	0	0	Check	X NN
One Time Key In	Main			TAILGATE OUTSIDE GARNISH	1	304.90	304.90	25.00	229.87	Replace	1	378.48	Replace	/ DEP
One Time Key In	Main			STRIKER, BACK DOOR	1	48.90	48.90	25.00	36.68	Replace	0	0	Check	X NN
One Time Key In	Main			TAILGATE TRIM, LH	1	85.90	85.90	25.00	64.43	Replace	0	0	Check	X NN
One Time Key In	Main			TAILGATE TRIM, LOWER	1	160.70	160.70	25.00	120.53	Replace	0	0	Check	X NN
One Time Key In	Main			TAILGATE TRIM, RH	1	86.30	86.30	25.00	64.73	Replace	0	0	Check	X NN
One Time Key In	Main			TAILGATE TRIM, UPPER	1	49.80	49.80	25.00	37.35	Replace	0	0	Check	X NN
One Time Key In	Main			TAILGATE BOARD ASSY	1	246.90	246.90	25.00	185.18	Replace	0	0	Check	X NN
One Time Key In	Main			WIRE, BACK DOOR, NO.1	1	582.40	582.40	10.00	524.16	Replace	0	0	Check	X NN
One Time Key In	Main			MOTOR ASSY, RR WIPER	1	734.90	734.90	10.00	661.41	Replace	0	0	Check	X NN
One Time Key In	Main			ARM, RR WIPER	1	84.70	84.70	25.00	63.53	Replace	0	0	Check	X NN

Total Spare Part Cost 49,993.55  
 Lump Sum Discount (%) 0.00  
 Final Spare Part Cost 49,993.55

Surveyor Total 8,875.00  
 Lump Sum Dis (%) 0  
 Final Sur Total 8,875.00

SMRT Recommendation											Surveyor Approval				
SOM Type	Coating Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks	
One Time Key In	Main			BLADE ASSY, REAR WIPER	1	55.00	55.00	25.00	41.25	Replace	0	0	Check	X NN	
One Time Key In	Main			CAMERA ASSY, TELEVISION, RR	1	1,436.80	1,436.80	10.00	1,292.94	Replace	0	0	Check	X NN	
One Time Key In	Main			SWITCH ASSY, BACK DOOR OPENER	1	146.10	146.10	15.00	121.48	Replace	0	0	Check	X NN	
One Time Key In	Main			FENDER RRLH	1	766.80	766.80	25.00	575.10	Replace	1	575.10	Replace	/ BUC	
One Time Key In	Main			SMRT LOGO	1	7.80	7.80	0.00	7.80	Replace	1	7.80	Replace	/ MIEC	
One Time Key In	Main			STICKER DECAL 6555 8888	1	21.80	21.80	0.00	21.80	Replace	1	21.80	Replace	/ NEEC	
One Time Key In	Main			FENDER LINER RRLH	1	141.30	141.30	25.00	105.98	Replace	0	0	Check	X NN	
One Time Key In	Main			LID ASSY, FUEL	1	102.00	102.00	25.00	76.50	Replace	0	0	Check	X NN	
One Time Key In	Main			CABLE SUB-ASSY, FUEL LID	1	63.90	63.90	25.00	47.92	Replace	0	0	Check	X NN	
One Time Key In	Main			RETAINER, FUEL LID CABLE	1	5.80	5.80	25.00	4.35	Replace	0	0	Check	X NN	
One Time Key In	Main			CAP ASSY, FUEL TANK	1	66.10	66.10	25.00	49.57	Replace	0	0	Not Give	X NN	
One Time Key In	Main			PIPE SUB-ASSY, FUEL NECK	1	230.80	230.80	25.00	173.10	Replace	0	0	Not Give	X NN	
One Time Key In	Main			TUBE, FUEL TANK	1	36.10	36.10	25.00	27.08	Replace	0	0	Not Give	X NN	
One Time Key In	Main			TANK SUB-ASSY, FUEL	1	745.10	745.10	25.00	558.82	Replace	0	0	Not Give	X NN	
One Time Key In	Main			QUARTER GLASS RRLH	1	168.10	168.10	25.00	126.07	Replace	1	126.07	Replace	/ NEEC	
Total Spare Part Cost								48,993.50			Surveyor Total		8,975.50		
Lump Sum Discount (%)								0.00			Lump Sum Dis (%)		0		
Final Spare Part Cost								48,993.50			Final Sur Total		8,975.50		

SMRT Recommendation											Surveyor Approval					
DOB Type	Coating Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks		
One Time Key In	Main			SEALANT WSCREEN	1	27.00	27.00	0.00	27.00	Replace	1	27.00	Replace	/ NEC		
One Time Key In	Main			TYRE	1	126.74	126.74	0.00	126.74	Replace	0	0	Not Give	X NN		
One Time Key In	Main			WHEEL DISC	1	1,490.20	1,490.20	25.00	1,117.65	Replace	0	0	Not Give	X NN		
One Time Key In	Main			REINFORCEMENT, ROOF SIDE INNER LH	1	60.30	60.30	25.00	45.23	Replace	0	0	Check	X NN		
One Time Key In	Main			REINFORCE, ROOF SIDE OUTER LH	1	91.90	91.90	10.00	82.71	Replace	0	0	Check	X NN		
One Time Key In	Main			REINFORCEMENT, BACK DOOR SIDE LH	1	66.50	66.50	25.00	49.88	Replace	0	0	Check	X NN		
One Time Key In	Main			EXTENSION, QUARTER PANEL FRONT LH	1	82.90	82.90	25.00	61.68	Replace	0	0	Check	X NN		
One Time Key In	Main			EXTENSION, QUARTER PANEL REAR LH	1	108.50	108.50	10.00	97.65	Replace	0	0	Check	X NN		
One Time Key In	Main			PANEL, ROOF SIDE, INNER LH	1	134.80	134.80	25.00	101.10	Replace	0	0	Check	X NN		
One Time Key In	Main			EMBLEM REAR	1	60.30	60.30	25.00	45.23	Replace	1	45.23	Replace	/ NEC		
One Time Key In	Main			LICENSE PLATE LAMP	2	35.75	71.50	25.00	53.55	Replace	0	0	Check	X NN		
One Time Key In	Main			NUMBER PLATE	1	15.00	15.00	0.00	15.00	Replace	1	15.00	Replace	/ BUC		
One Time Key In	Main			NUMBER PLATE FRAME	1	12.00	12.00	0.00	12.00	Replace	1	12.00	Replace	/ BUC		
One Time Key In	Main			NAME PLATE (HYBRID)	1	31.90	31.90	25.00	23.93	Replace	1	23.93	Replace	/ NEC		
One Time Key In	Main			NAME PLATE (PRIUS)	1	60.80	60.80	25.00	45.60	Replace	1	45.60	Replace	/ NEC		
Total Spare Part Cost											48,993.55	Surveyor Total				8,975.50
Lump Sum Discount (%)											0.00	Lump Sum Dis (%)				0
Final Spare Part Cost											48,993.55	Final Sur Total				8,975.50

SMRT Recommendation											Surveyor Approval			
SOM Type	Coating Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
One Time Key In	Main			NAME PLATE (TOYOTA)	1	21.90	21.90	25.00	38.50	Replace	1	38.50	Replace	/ NEI
One Time Key In	Main			SPOILER REAR	1	903.70	903.70	25.00	715.28	Replace	1	0	Repair	X R
One Time Key In	Main			3RD BRAKE LAMP	1	231.20	231.20	10.00	208.17	Replace	0	0	Not Give	X NA
One Time Key In	Main			SMRT LOGO	1	7.80	7.80	0.00	7.80	Replace	1	7.80	Replace	/ NEI
One Time Key In	Main			STICKER DECAL 8035 8038	1	21.60	21.60	0.00	21.60	Replace	1	21.60	Replace	/ NEI
One Time Key In	Main			END PANEL	1	602.10	602.10	25.00	451.58	Replace	0	0	Check	X NN
One Time Key In	Main			END PANEL COVER, DECK TRIM HOLE	1	46.10	46.10	25.00	34.58	Replace	0	0	Check	X NN
One Time Key In	Main			END PANEL COVER, DECK TRIM, RR	1	121.10	121.10	25.00	90.82	Replace	0	0	Check	X NN
One Time Key In	Main			REINFORCEMENT, RR	2	34.80	69.60	25.00	51.90	Replace	0	0	Check	X NN
One Time Key In	Main			SEALANT SIKAFLEX	1	37.00	37.00	0.00	37.00	Replace	0	0	Check	X NN
One Time Key In	Main			SPARE TYRE PANEL	1	667.70	667.70	25.00	500.78	Replace	0	0	Check	X NN
One Time Key In	Main			MEMBER SUB-ASSY, RR LH	1	174.10	174.10	25.00	130.57	Replace	0	0	Check	X NN
One Time Key In	Main			MEMBER SUB-ASSY, RR RH	1	174.10	174.10	25.00	130.57	Replace	0	0	Check	X NN
One Time Key In	Main			MEMBER SUB-ASSY, REAR FLOOR CROSS NO.1	1	436.40	436.40	25.00	327.30	Replace	0	0	Check	X NN
One Time Key In	Main			MEMBER SUB-ASSY, REAR FLOOR CROSS NO.2	1	655.70	655.70	25.00	491.78	Replace	0	0	Check	X NN

Total Spare Part Cost 46,993.50

Surveyor Total 8,875.00

Lump Sum Discount (%) 0.00

Lump Sum Dis (%) 0

Final Spare Part Cost 46,993.50

Final Sur Total 8,875.00

SMART Recommendation											Surveyor Approval			
BOM Type	Coating Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
One Time Key In	Main			FLOOR PANEL RRLH	1	102.00	102.00	25.00	76.80	Replace	0	0	Check	X NN
One Time Key In	Main			FLOOR PANEL RRSH	1	209.80	209.80	25.00	157.43	Replace	0	0	Check	X NN
One Time Key In	Main			BOX, DECK FLOOR, RR	1	649.70	649.70	25.00	487.28	Replace	0	0	Check	X NN
One Time Key In	Main			BOX, RR FLOOR, BOARD	1	679.60	679.60	25.00	509.70	Replace	0	0	Check	X NN
One Time Key In	Main			BOARD, RR FLOOR	1	292.30	292.30	25.00	219.23	Replace	0	0	Check	X NN
One Time Key In	Main			BOARD ASSY, RR RR	1	379.20	379.20	25.00	284.40	Replace	0	0	Check	X NN
One Time Key In	Main			SPACER, RR FLOOR	1	130.60	130.60	25.00	97.95	Replace	0	0	Check	X NN
One Time Key In	Main			BOX, DECK FLOOR, COVER LH	1	230.10	230.10	25.00	172.57	Replace	0	0	Check	X NN
One Time Key In	Main			BOX, DECK FLOOR, LH	1	196.80	196.80	25.00	147.60	Replace	0	0	Check	X NN
One Time Key In	Main			COVER ASSY, TONNEAU	1	802.10	802.10	25.00	601.58	Replace	0	0	Check	X NN
One Time Key In	Main			CUSHION, SPARE WHEEL	1	230.80	230.80	25.00	173.10	Replace	0	0	Check	X NN
One Time Key In	Main			PROTECTOR, SPARE	1	143.70	143.70	25.00	107.77	Replace	0	0	Check	X NN
One Time Key In	Main			CARRIER, SPARE	1	19.70	19.70	25.00	14.77	Replace	0	0	Check	X NN
One Time Key In	Main			TYRE	1	126.74	126.74	0.00	126.74	Replace	0	0	Not Give	X NN
One Time Key In	Main			WHEEL, DISC	1	1,480.20	1,480.20	25.00	1,110.15	Replace	0	0	Not Give	X NN

Total Spare Part Cost 49,992.55

Surveyor Total 8,975.50

Lump Sum Discount (%) 0.00

Lump Sum Dis (%) 0

Final Spare Part Cost 49,992.55

Final Sur Total 8,975.50

SMRT Recommendation											Surveyor Approval			
BOC Type	Costing Type	Portion	Material Number	Part Name	Qty	Unit Price	Unit Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
One Time Key In	Main			BREAKDOWN SIGN	1	35.00	35.00	0.00	35.00	Replace	0	0	Check	X NA
One Time Key In	Main			PANEL ASSY, DECK LH	1	307.00	307.00	25.00	230.25	Replace	0	0	Check	X NA
One Time Key In	Main			PANEL ASSY, DECK RH	1	307.00	307.00	25.00	230.25	Replace	0	0	Check	X NA
One Time Key In	Main			GARNISH SIDE UPPER, LHR	1	281.70	281.70	25.00	196.27	Replace	0	0	Check	X NA
One Time Key In	Main			BATTERY	1	278.00	278.00	10.00	250.20	Replace	0	0	Check	X NA
One Time Key In	Main			BATTERY ASSY, HV	1	5,544.40	5,544.40	10.00	4,989.96	Replace	0	0	Check	X NA
One Time Key In	Main			BATTERY CLAMP	1	18.10	18.10	25.00	13.58	Replace	0	0	Check	X NA
One Time Key In	Main			BATTERY TRAY	1	42.80	42.80	25.00	32.10	Replace	0	0	Check	X NA
One Time Key In	Main			WIRE, FRAME	1	1,580.00	1,580.00	25.00	1,185.00	Replace	0	0	Check	X NA
One Time Key In	Main			WIRE, ENGINE, NO.3	1	74.00	74.00	10.00	66.60	Replace	0	0	Not Give	X NA
One Time Key In	Main			WIRE, FLOOR	1	1,875.00	1,875.00	10.00	1,687.50	Replace	0	0	Check	X NA
One Time Key In	Main			WIRE, FLOOR, NO.3	1	1,305.40	1,305.40	10.00	1,174.86	Replace	0	0	Check	X NA
One Time Key In	Main			RECEIVER, DOOR CONTROL	1	238.70	238.70	10.00	214.83	Replace	0	0	Check	X NA
One Time Key In	Main			PANEL SUB-ASSY, QTR	1	228.70	228.70	25.00	171.52	Replace	0	0	Check	X NA
One Time Key In	Main			PANEL SUB-ASSY, QTR	1	888.40	888.40	25.00	666.30	Replace	0	0	Check	X NA

Total Spare Part Cost 48,893.55

Lump Sum Discount (%) 0.00

Final Spare Part Cost 48,893.55

Surveyor Total 8,975.50

Lump Sum Dis (%) 0

Final Sur Total 8,975.50

SMRT Recommendation											Surveyor Approval			
SOB Type	Coating Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(S)	List Price(S)	Dis(%)	Final Price(S)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(S)	Repair/Replace	Remarks
One Time Key In	Main			PANEL SUB-ASSY, QTR WHEEL HOUSE	1	585.40	585.40	25.00	439.05	Replace	0	0	Check	X NN
One Time Key In	Main			PANEL, QUARTER WHEEL HOUSE, OUTER LH	1	226.70	226.70	25.00	170.02	Replace	0	0	Check	X NN
One Time Key In	Main			TAIL LAMP BRACKET, LH	1	22.70	22.70	25.00	17.02	Replace	0	0	Check	X NN
One Time Key In	Main			TAIL LAMP LH	1	545.40	545.40	10.00	490.86	Replace	1	493.56	Replace	✓ C.B
One Time Key In	Main			TROUGH, BACK DOOR LH	1	110.90	110.90	10.00	99.81	Replace	0	0	Check	X NN
Total Spare Part Cost									48,993.55	Surveyor Total		4,875.53		
Lump Sum Discount (%)									5.00	Lump Sum Dis (%)		0		
Final Spare Part Cost									48,993.55	Final Sur Total		4,875.53		

## Labour's Cost Detail

S.No.	Coating Type	Job Scope	SMRT Recommendation(S)	Surveyor Adjustment(S)	Remarks
1	Main	TO REPAIR FRONT LH PORTION	843.00	400	
2	Main	TO REPAIR REAR PORTION	2,026.00	600	
Total:			2,873.00	1,000.00	

## Spray Cost Detail

S.No.	Coating Type	Job Scope	SMRT Recommendation(S)	Surveyor Adjustment(S)	Remarks
1	Main	TO RESPRAY FRONT BUMPER	378.00	200	
2	Main	TO SPRAY FRONT BUMPER LOWER SUB GRILLE	180.00	0	
3	Main	TO RESPRAY FRONT SUPPORT PANEL	180.00	0	
4	Main	TO RESPRAY FRONT FENDER LH	378.00	200	
5	Main	TO RESPRAY RIM	540.00	50	
6	Main	TO RESPRAY FRONT PILLAR LH	180.00	80	
7	Main	TO RESPRAY FRONT DOOR LH	378.00	300	
Total:			2,542.00	1,710.00	

S.No.	Coating Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
8	Matn	TO RESPRAY REAR BUMPER	378.00	200	
9	Matn	TO RESPRAY TAIL GATE	378.00	200	
10	Matn	TO RESPRAY TAILGATE OUTSIDE GARNISH	180.00	80	
11	Matn	TO RESPRAY REAR SPOILER	180.00	80	
12	Matn	TO RESPRAY REAR PANEL	180.00	0	
13	Matn	TO RESPRAY REAR SPARE TYRE PANEL	180.00	0	
14	Matn	TO RESPRAY REAR FLOOR SIDE PANEL RH	180.00	0	
15	Matn	TO RESPRAY REAR FLOOR SIDE PANEL LH	180.00	0	
16	Matn	TO RESPRAY BATTERY PANEL	180.00	0	
17	Matn	TO RESPRAY REAR MEMBER,RH	180.00	0	
18	Matn	TO RESPRAY REAR MEMBER,LH	180.00	0	
19	Matn	TO RESPRAY RH REAR WHEEL HOUSE	180.00	0	
20	Matn	TO RESPRAY REAR LH WHEEL HOUSE	180.00	0	
21	Matn	TO RESPRAY FUEL LID COVER	180.00	0	
22	Matn	TO RESPRAY RH RAIL ROOF SIDE	180.00	0	
23	Matn	TO RESPRAY LH RAIL ROOF SIDE	180.00	80	
24	Matn	TO RESPRAY MEMBER SUB-ASSY, CENTER FLOOR CROSS , NO.2	180.00	0	
25	Matn	TO RESPRAY TROUGH BACK DOOR RH	180.00	0	
26	Matn	TO RESPRAY TROUGH BACK DOOR LH	180.00	0	
27	Matn	TO RESPRAY REAR FENDER LH	378.00	200	
28	Matn	TO RESPRAY REAR FENDER RH	378.00	0	
29	Matn	TO RESPRAY RH REAR DOOR	378.00	0	
30	Matn	TO RESPRAY REAR DOOR LH	378.00	200	
<b>Total:</b>			<b>7,842.00</b>	<b>1,710.00</b>	

## Other Cost Detail

S.No.	Costing Type	Job Scope	\$BRT Recommendation(2)	Surveyor Adjustment(3)	Remarks
1	Main	TOWING CHARGE	125.00	0	90 / APC
2	Main	TO CHECK WIRING AND SYSTEM FUNCTION	80.00	30	APC
3	Main	TO APPLY RUST-PROOFING ON AFFECTED AREA	300.00	100	APC
4	Main	TO DO WHEEL ALIGNMENT / TYRE BALANCING	120.00	60	APC
5	Main	TO REMOVE AND REFIT TYRE RM (SPRAYING PURPOSE)	120.00	30	APC
6	Main	TO TOP UP A/C GAS	120.00	0.00	
7	Main	TO REMOVE & REFIX FAN ENGINE & RADIATOR ASSY & INNER COOLER & AIR CON CONDENSER	120.00	0	
8	Main	TO REMOVE / REFIT SEAT	120.00	0	
9	Main	TO ALIGN CHASSIS	350.00	0	
10	Main	TO REMOVE & REFIT FUEL TANK	120.00	0	
11	Main	TO REMOVE & REFIT EXHAUST	120.00	0	
12	Main	TO TRANSFER DOOR MECHANISM	240.00	0	
13	Main	TO PROVIDE LABOUR & MATERIAL FOR SOLAR FILM (NET)	800.00	0	600 APC
14	Main	TO TRANSFER REAR TAILGATE MECHANISM	120.00	50	APC
15	Main	TO TEST AND REFIX REVERSE SENSOR SYSTEM	120.00	30	APC
16	Main	TO REMOVE AND INSTALL LUGGAGE COMPARTMENT TRIM TO FACILITATE REPAIR	120.00	40	APC
17	Main	TO INSPECT RR LIGHTING MECHANISMS & WATER TEST RR LIGHTING FOR LEAKAGE	120.00	50	APC
18	Main	TO CHECK & RESET SYSTEM FUNCTION	380.00	0	
19	Main	TO REMOVE AND REFIX REAR WINDSCREEN	240.00	120	APC
20	Main	TO REMOVE & REFIT REAR QUARTER GLASS RH	120.00	0	
21	Main	TO REMOVE & REFIT REAR QUARTER GLASS LH	120.00	50	APC
22	Main	TO REMOVE & REFIX FRONT LH/RH QUARTER GLASS	120.00	0	
23	Main	TO REMOVE AND REFIT WIRE HARNESS	250.00	0	
Total:			4,745.00		

S.No.	Coating Type	Job Scope	SMART Recommendation(E)	Surveyor Adjustment(E)	Remarks
24	Met	TO REMOVE AND REFIT BATTERY ASSY HV	120.00	0	
25	Met	TO REPLACE SUNDRY PARTS	100.00	0	
26	Met	TO WASH AND VACUUM	60.00	0	

Total: 37. To remove & refit Battery assy HV \$200 ~~1,800~~ 1449

### Summary

	Estimator Assessment(E)	Surveyor Assessment(E)
Total Spare Part Cost	48,993.55	8,875.50
Total Labour Cost	2,875.00	1,200.00
Total Spray Painting	7,542.00	1,770.00
Other	4,746.00	1,400.00
Overall Total	65,156.55	13,285.50
Lump Sum Repair Option		
Lump Sum Total	0.00	13,285.50
Surveyor Approved Amount		13,285.50
No of Repair Days*	22	7
Remarks		MP repair, photo before paint.
Surveyor Name		Howe Jc
Signature		
Survey Date	21/01/2019	Save Clear

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date:

Contractor:	WEGA ENGINEERING PTE LTD		
Accident Case Number	TAX/01/19/2072	Date of Collection	23/1/19
Vehicle No	SHC 475213	Date of Request	28/1/19
Vehicle Model	TOYOTA PRIUS	Number of Days to Extend	10 DAYS - 6 days

**REQUEST FOR SUPPLYMENT PARTS**

S/N	Number photos	Part Description	Quantity	Unit Price
1	6564, 185, 189, 90	Bumper Energy Absorber Part	1	\$78.50 / OR \$59.10
2	6591, 92, 193	Support Sub Assy	1	\$1460.40 / OR \$1095.30
3	6595, 96, 97	Antenna Electrical Lwr Rear	1	\$157.40 / OR \$141.66
4	6598, 99, 6600	Tail Gate Door Lock	1	\$444.10 / OR 333.08
5	6601, 02	Tail Gate weatherstrip	1	\$353.40 / OR \$265.05
6	6618, 19, 20	Tail Gate Board Assy	1	\$246.90 / OR \$185.18
7	6603, 04	Fender Liner RR LH	1	\$141.30 / OR \$105.98
8	6605, 06, 07	End panel	1	\$602.10 / OR \$451.58

<<<Please submit photographs for damaged parts>>>

I, (Name) CHIA

(Position) ADVISOR

Do solemnly and sincerely declare that:- Supplementary Parts are raised for replacement for the aforesaid vehicle.

Chia

Signature of person making this declaration

[To be signed in front of an authorised witness]

I acknowledge that this declaration is true and correct, and I make it with the understanding and belief that a person who makes a false declaration is liable to the damages of perjury.

Acknowledge By	ARC Executive / Supervisor / SA	
Approval By	Surveyor / In-house Staff	
Parts Ordering	SMRT Store / Contractor Supply / Form 22 / WOC	Form22 / PO / WOC / Reservation / Number
Photo Submitted		Date of submission

For SMRT Staff

①

Contractor:	WEGA ENGINEERING PTE LTD		
Accident Case Number	7AY/01/19/2072	Date of Collection	23/1/19
Vehicle No	SLC 4752R	Date of Request	28/1/19
Vehicle Model	TOYOTA PRIUS	Number of Days to Extend	

**REQUEST FOR SUPPLYMENT PARTS**

S/N	Number photos	Part Description	Quantity	Unit Price	
1	6611,12,13	End Panel Cover Deck Trim LH	1	\$46.10	1 CRU \$34.58
2	6608,09,10	End Panel Cover Deck Trim RR	1	\$121.10	1 CRU \$90.83
3	6643,44,45	Spare Tyre Panel	1	\$667.70	1 CRU \$500.78
4	6621,22	Member Sub Assy RR LH	1	\$174.10	1 CRU \$130.58
5	6625,26	Floor Panel RR LH	1	\$102.00	1 CRU \$76.50
6	6614,15,16,17	Box Deck Floor RR	1	\$649.70	1 CRU \$487.28
7	6637,38,39	Protector Spare	1	\$143.70	1 CRU \$107.78
8	6647,48,49,50	Battery Assy HV	1	\$5544.40	1 CRU \$4989.96

<<<Please submit photographs for damaged parts>>>

I, (Name) CHIA

(Position) ADVISOR

Do solemnly and sincerely declare that:- Supplementary Parts are raised for replacement for the aforesaid vehicle.

CHIA

Signature of person making this declaration

[To be signed in front of an authorised witness]

I acknowledge that this declaration is true and correct, and I make it with the understanding and belief that a person who makes a false declaration is liable to the damages of perjury.

Acknowledge By	ARC Executive / Supervisor / SA	
Approval By	Surveyor / In-house Staff	
Parts Ordering	SMRT Store / Contractor Supply / Form 22 / WOC	Form22 / PO / WOC / Reservation / Number
Photo Submitted		Date of submission

For SMRT Staff

②

Contractor:	WEGA ENGINEERING PTE LTD		
Accident Case Number	7AY/01/19/2072	Date of Collection	23/1/19
Vehicle No	SHC 4752B	Date of Request	28/1/19
Vehicle Model	TOYOTA PRIUS	Number of Days to Extend	

**REQUEST FOR SUPPLYMENT PARTS**


S/N	Number photos	Part Description	Quantity	Unit Price	
1	6623, 24, 6630 6631, 32	To Repair Member Sub Assy RR RH		\$ 150.00	100/
2	6637, 28, 29 6651, 52, 53, 54	To Repair Rear RH & LH Wheel House		\$ 500.00	400/
3	6581, 82, 183	To Repair Rear RH Fender		\$ 400.00	200/
4		To Respray Rear RH Fender		\$ 378.00	200/
5		To Respray Rear RH & LH Wheel House		\$ 250.00	200/
6		To Respray Rear Member Sub Assy RR RH		\$ 180.00	100/
7		To Respray End Panel		\$ 180.00	100/
8		To Respray Spare Tyre Panel		\$ 180.00	100/

<<<Please submit photographs for damaged parts>>>

1. (Name) CHIA

(Position) ADVISOR

Do solemnly and sincerely declare that - Supplementary Parts are raised for replacement for the aforesaid vehicle.



Signature of person making this declaration

[To be signed in front of an authorised witness]

I acknowledge that this declaration is true and correct, and I make it with the understanding and belief that a person who makes a false declaration is liable to the damages of perjury.

Acknowledge By	ARC Executive / Supervisor / SA	
Approval By	Surveyor / In-house Staff	
Parts Ordering	SMRT Store / Contractor Supply / Form 22 / WOC	Form22 / PO / WOC / Reservation / Number
Photo Submitted		Date of submission

For SMRT Staff

③

Contractor:	WEGA ENGINEERING PTE LTD		
Accident Case Number	7AY / 01 / 19 / 2072	Date of Collection	23 / 1 / 19
Vehicle No	SHC 4752 B	Date of Request	
Vehicle Model	TOYOTA PRIUS	Number of Days to Extend	

**REQUEST FOR SUPPLYMENT PARTS**

S/N	Number photos	Part Description	Quantity	Unit Price
1		To Respray Rear RH Door		\$ 378.00
2		To Request Labour And working		
3		Day For Repair & Replace		
4		Bend Panel, spare tyre panel,		
5		Member Sub Assy RR LH F.		\$ 800.00
6		To Remove & Refit Battery Assy HU		\$ 250.00
7				
8				

200/

400/

200/

<<<Please submit photographs for damaged parts>>>

I, (Name) CHIA

(Position) ADVISOR

Do solemnly and sincerely declare that - Supplementary Parts are raised for replacement for the aforesaid vehicle.

*CHIA*  
.....

Signature of person making this declaration

[To be signed in front of an authorised witness]

I acknowledge that this declaration is true and correct, and I make it with the understanding and belief that a person who makes a false declaration is liable to the damages of perjury.

Acknowledge By	ARC Executive / Supervisor / SA	
Approval By	Surveyor / In-house Staff	
Parts Ordering	SMRT Store / Contractor Supply / Form 22 / WOC	Form22 / PO / WOC / Reservation / Number
Photo Submitted		Date of submission

For SMRT Staff

(4)