

Surveyor: Kelvin

REF: CC3/TML19001397/Klgd3n2

ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OOITP / WS / TP RES / OD RES / EVA / INV / MV

To Inspected Vehicle No: \_\_\_\_\_

at Workshop m/s \_\_\_\_\_

Insured: SLD 9369P

Policy No: M1000656

Claims No: M1900474

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: \_\_\_\_\_

IDAC Accident Report: \_\_\_\_\_ Consistent?: Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent?: Yes or No

Est. Repairs: 3 days Res.: Yes or No

Lum Sum: \_\_\_\_\_ % J Val: Yes or No

CA / REV / REP: / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_ Vehicle: IN / OUT

Veh No: SHA 3892Y Yr Regn: 24 Feb, 2017

Type: M. Car / M. Cycle / Bus / Van / Lorry / T/O / Prime Mover /

Truck / Trailer of \_\_\_\_\_

Make: Hyundai 2012 cc 1500

Colour: Blk A/C: Insured / Std / NI / NA

Sp. Reading: 256033 T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: KMHC851CVH4022691

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD / Rim or

Tyre Size: F: 195/65R15

R: \_\_\_\_\_

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / DHTSU / PIR / SUMI /

TOYO / YOKO or Westlake

Front \_\_\_\_\_ Rear \_\_\_\_\_

R/Bal: 7 mm R/Bal: 7 mm

L/Bal: 7 mm L/Bal: 7 mm

D.O.A. 18/1/19 D.O.I. 21/1/19

Survey held at C.D.G.E (Loyang)

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

Front / Rear

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	SHA 3892Y - N/A / INCI 9000834 / r3 <span style="float: right;">DUPA 13012019 Tokis</span>
	SLD 9369P - x <span style="float: right;">r/r</span>
24/1/19	Chk r/r \$1893.02 / 3 Rp. (Paid @ 1018.32, 35%)

RECEIVED 24 JAN 2019

Date/Time, File Pass to?  : Prel. Report

24/1/19 Kevin  : Final Report

Date/Time, File Return to?

0)

Report Format: NER-B

Lump Sum M.S.I. @ 1893.02

Days Of Repair: 3

Resurvey No. of Trip: 1

Add Fee:  : Site Insp (\$ \_\_\_\_\_)

: Interview (\$ \_\_\_\_\_)

: Tech Invs (\$ \_\_\_\_\_)

: Weekend (\$ \_\_\_\_\_)

Survey Fee:	
Transportation:	<u>250</u>
S + RS	<u>10</u>
Photos	
Others	
	<u>260</u>

> Back to OneMotoring

## Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	3821R
Vehicle Details	
Vehicle No.:	SHA3892Y
Vehicle to be Exported:	No
Intended Deregistration Date:	24 Jan 2019
Vehicle Make:	HYUNDAI
Vehicle Model:	AE IONIQ HEV 1.6 DCT
Primary Colour:	Blue
Manufacturing Year:	2017
Engine No.:	G4LEGU327124
Chassis No.:	KMHC851CVHU022699
Maximum Power Output:	103.6 kW (138 bhp)
Open Market Value:	\$27,778.00
Original Registration Date:	24 Feb 2017
First Registration Date:	24 Feb 2017
Transfer Count:	0
Actual ARF Paid:	\$5,000.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	23 Feb 2025
PARF Rebate Amount:	\$3,750.00
Intended COE Rebate Details	
COE Expiry Date:	23 Feb 2025
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	8
PQP Paid:	\$40,316.00
COE Rebate Amount:	\$30,676.00
<b>Total Rebate Amount:</b>	<b>\$34,426.00</b>
Message	
Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 24 Jan 2019

OK

### SINGAPORE ACCIDENT STATEMENT

#### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

#### ACCIDENT STATEMENT

Date Of Report	19/01/2019 08:31
Date Of Accident	18/01/2019 09:45
Exact Location Of Accident	SLE TWDS ANG MO KIO AFT YIO CHU KANG EXIT
Country/State of Loss	SINGAPORE

#### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHA3892Y
<b>Insured/Policyholder</b>	
Name Of Registered Owner	COMFORT TRANSPORTATION PTE LTD
Co Reg No	199303821R
Email Address	FLEETSAFETY@CDGTAXI.COM.SG
Mobile Phone No	
Alternative Phone No	OFFICE-65508768

#### Vehicle Particulars

Manufacturer	HYUNDAI
Model	IONIQ HYBRID
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	TAXI

#### Insurance Company

Name of Insurance Company	INDIA INTERNATIONAL INSURANCE PTE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	YES
Policy Number	MCOM0015
Cover Note Number	

#### Driver

Name of Driver	TAN SOON LAI
NRIC No	S1598017F
Date Of Birth	24/10/1963
Occupation	OUTDOOR
Date Of Driving Pass	29/03/2016
Driving Experience	2 YEARS AND 9 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-98581198
Fax Number	
Contact Number	
EMail Address	CABTANS1@SINGNET.COM.SG

Address	BLK 544 ANG MO KIO AVENUE 10 #11-2278
Postcode	560544
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - TAXI DRIVER
Vehicle Registration Number of Driver's Own Vehicle	-
Insurance Company of Driver's Own Vehicle	-

#### General Information of the Accident

Type Of Accident	CHAIN COLLISION
Weather Conditions	RAINING
Road Surface	WET

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	3
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : - GENDER: : FEMALE

#### Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

REFER ATTACHED

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	-
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLD9369P
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	RAJENDRAN
NRIC/Passport Number	S1769120A
Contact Number	
Address	
Postcode	
Insurance Company Name	

Nature Of Damage FRONT

No. Of Passenger (Including Driver)

**DETAILS OF OTHER VEHICLE PROPERTY 2**

Vehicle Registration Number SHD4426M

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category TAXI

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage NO DAMAGED

No. Of Passenger (Including Driver)

# Sketch Plan Pg. 1

## SKETCH PLAN

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**


I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.






COMFORT TRANSPORTATION PTE LTD  
CO. REG. NO. 199303821R

Policyholder's Signature  
Date & Time:

  
Driver's Signature  
(If driver is not the policyholder)  
Date & Time: 18.01.2019  
@17:00hrs

  
Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:





**ComfortDelGro Engineering Pte Ltd** (Co Reg No:199506048W)

59 Loyang Drive  
Singapore 508969  
Tel: 6214 8300

**TP INSURER:**  
**CTPL**

**Tokio Marine Insurance Singapore Ltd (HQ)**

Jumani

Singapore

**PARTICULARS OF CLAIM**

Claim Type:	THIRD PARTY	Ref. No:	
Policy No:		Date of Loss:	18/01/2019
Vehicle Reg. No.:	SHA3892Y	Driveable?	YES
Party At Fault:	UNKNOWN		
Make/Model:	HYUNDAI IONIQ HYBRID, 1.6 GLS DCT (A)	Vehicle Reg. Date:	24/02/2017
Vehicle Colour:	BLUE	Gen Condition:	GOOD
Engine No:	G4LEGU327124	Chassis No:	KMHC851CVHU022699
Odometer:	0 KM		
Paint Type:			
List Item Discount:	20.00 %		
Total Loss?	<b>NO</b>		
Est. Duration of Repair (day)	4		
Present Location:	COMFORTDELGRO ENGINEERING PTE LTD (LOYANG)		

<b>COST OF CLAIMS</b>	<b>Amount</b>
Parts	1,585.18
Miscellaneous Items	10.00
Labour	800.00
Paintwork Labour	0.00
Towing	0.00
<b>Gross Total (S\$)</b>	<b>2,395.18</b>
<b>+ GST 7.00% (S\$)</b>	<b>167.66</b>
<b>Nett Amount (S\$)</b>	<b>2,562.84</b>

**This claim is handled by: JUMANI BIN MASUDIN**

*Generated using Merimen e-Claims Internet Estimation & Adjusting System*

29.11.38

### REPAIR DETAILS

#### Reference

Part Source: MRM-SG      Version: 1.0 (Last Synchronised: 19 Jan 2019)  
 Parts: 192      HYUNDAI IONIQ HYBRID 1.6 GLS DCT (A) (Catalogue:Merimen Singapore 1.0)  
 Labour: Repairer's      (Price-denominated Standard List)  
 Print Code: **ComfortDelGro Engineering Pte Ltd/SHA3892Y/19/01/2019 10:46**  
 Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page  
 Further Info: Items/values not in reference catalogue are prefixed with an asterisk \*.

#### Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*REAR BUMPER ASSY <i>in</i>	20.00	0.00	*459.40 FL
2	1		*REAR BUMPER REINFORCEMENT <i>you</i>	20.00	0.00	*294.80 FL
3	1		*REAR BUMPER REINFORCEMENT BRACKET LH <i>you</i>	20.00	0.00	*138.10 FL
4	1		*REAR BUMPER REINFORCEMENT BRACKET RH <i>you</i>	20.00	0.00	*138.10 FL
5	1		*REAR BUMPER CENTRE MOULDING ASSY <i>in</i>	20.00	0.00	*451.25 FL
6	1		*REAR BUMPER LOWER CENTRE MOULDING ASSY <i>x repair</i>	20.00	0.00	*47.50 FL
7	1		*REAR BUMPER STAY <i>you</i>	20.00	0.00	*138.10 FL
8	10		*REAR BUMPER COVER CLIPS <i>in</i>	20.00	0.00	*22.00 FL
9	1		*REAR BUMPER UNDER COVER <i>you</i>	20.00	0.00	*53.85 FL
10	1		*REAR NUMBER PLATE <i>in</i>	0.00	0.00	*25.00 F
11	1		*REAR NUMBER PLATE CASING <i>in</i>	0.00	0.00	*30.00 F
12	1		*REVERSE SENSOR <i>shhd</i>	0.00	0.00	*135.70 F

F=Franchise part. L=ListItemDisc.

	Sub Total (\$\$)	1,933.80
<i>Front bumper x repair</i>	List Item Discount on L Items (\$\$)	348.62
<i>Front number plate cut 355</i>		
	<b>Total Parts (\$\$)</b>	<b>1,585.18</b>

ComfortDelGro Engineering Pte Ltd/SHA3892Y/19/01/2019 10:46. Not valid without Reference section.  
 Generated using Merimen e-Claims IEAS

*Rear Fog lamp Assy in 20% \$201.50*

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
<b>Miscellaneous Items</b>			
1	1	OD/TP Case (Insurer)	10.00
<b>Sub Total (\$\$)</b>			<b>10.00</b>

Estimates on Labour

No	Particulars	Lab.Type	Amount
<b>Labour Items</b>			
1	PANEL BEATING	New	<del>350.00</del> 300
2	SPRAYPAINT	New	<del>250.00</del> 200
3	WIRING	New	<del>30.00</del> X
4	TUFF KOTE	New	<del>50.00</del> X
5	REMOVE/REFIX REVERSE SENSOR	New	<del>120.00</del> 30
<b>Gross Labour Cost (\$\$)</b>			<b>800.00</b>

ComfortDelGro Engineering Pte Ltd/SHA3892Y/19/01/2019 10:46. Not valid without Reference section.  
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

*1 car Lin 1 (1/1/19)  
20/1/19 1110h  
3 hrs  
111  
Before Part p/le*

LEK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification is allowed
- Supplementary work must be authorised and is subject to final approval from LEK Auto Consultants

Acknowledged by Repairer  
Signature:  
Date:

**ComfortDelGro Engineering Pte Ltd** (Co.Reg.No:199506048W)

59 Loyang Drive  
Singapore 508969  
Tel: 6214 8300

**(SUPPLEMENTARY)**

**TP INSURER:** **Tokio Marine Insurance Singapore Ltd (HQ)**  
**PHUA HONG LEONG**

Singapore

**PARTICULARS OF CLAIM**

Claim Type:	THIRD PARTY	Ref. No:	
Policy No:	MI000656	Date of Loss:	18/01/2019
Vehicle Reg. No.:	<b>SHA3892Y</b>	Driveable?	YES
Party At Fault:	UNKNOWN		
Make/Model:	HYUNDAI IONIQ HYBRID, 1.6 GLS DCT (A)	Vehicle Reg. Date:	24/02/2017
Vehicle Colour:	BLUE	Gen Condition:	GOOD
Engine No:	3ZZ4883031	Chassis No:	MR053ZEE106144065
Odometer:	0 KM		
Paint Type:			
List Item Discount:	20.00 %		
Total Loss?	<b>NO</b>		
Est. Duration of Repair (day)	4		
Description of Accident/Loss	ACCIDENT INVOLVING SLD9369P, SHA3892Y & SHD4426M ALONG SLE TWDS ANG MO KIO AFT YIO CHU KANG EXIT		
Present Location:	COMFORTDELGRO ENGINEERING PTE LTD (LOYANG)		

<b>COST OF CLAIMS</b>	<b>Amount</b>
Parts	216.20
Miscellaneous Items	0.00
Labour	300.00
Paintwork Labour	0.00
Towing	0.00
<b>Gross Total (S\$)</b>	<b>516.20</b>
<b>+ GST 7.00% (S\$)</b>	<b>36.13</b>
<b>Nett Amount (S\$)</b>	<b>552.33</b>
<b>+ Previous Estimates (S\$)</b>	<b>2,562.84</b>
<b>Claim Total (S\$)</b>	<b>3,115.17</b>

Generated using Merimen e-Claims Internet Estimation & Adjusting System

**REPAIR DETAILS**

**Reference**

**Part Source:** MRM-SG    Version: 1.0 (Last Synchronised: 24 Jan 2019)  
**Parts:** 192    HYUNDAI IONIQ HYBRID 1.6 GLS DCT (A) (Catalogue:Merimen Singapore 1.0)  
**Labour:** Repairer's    (Price-denominated Standard List)  
**Print Code:** ComfortDelGro Engineering Pte Ltd/SHA3892Y/24/01/2019 11:57  
**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page  
**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk \*.

**Estimates on Parts**

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*FRT NUMBER PLATE WITH CASING	0.00	0.00	*55.00 F <i>CM</i>
2	1		*LAMP ASSY - REAR FOG	20.00	0.00	*201.50 FL <i>CM</i>
<b>Sub Total (S\$)</b>						<b>256.50</b>
<b>- List Item Discount on L Items (S\$)</b>						<b>40.30</b>
<b>Total Parts (S\$)</b>						<b>216.20</b>

F=Franchise part, L=ListItemDisc.

ComfortDelGro Engineering Pte Ltd/SHA3892Y/24/01/2019 11:57. Not valid without Reference section.  
 Generated using Merimen e-Claims IEAS

## Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

## Estimates on Labour

No	Particulars	Lab.Type	Amount
<b>Labour Items</b>			
1	SPRAYPAINT - FRT	New	200 300.00
<b>Gross Labour Cost (S\$)</b>			<b>300.00</b>

ComfortDelGro Engineering Pte Ltd/SHA3892Y/24/01/2019 11:57. Not valid without Reference section.  
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >



COMFORTDELGRO ENGINEERING PTE LTD  
REPAIR ESTIMATE

Date: 23.01.2019  
Time: 17:39:10  
Page: 1

COMPANY : THIRD PARTY'S CLAIMS (CAS)  
CUSTOMER: 7010045  
ADDRESS : COMFORT TRANSPORTATION PTE LTD  
383 SIN MING DRIVE  
SINGAPORE SINGAPORE 575717  
65508755

JOB NO : 305261437  
REGN NO : SHA3892Y  
MILEAGE : 0000000000  
MAKE : HYUNDAI  
MODEL : IONIQ  
DATE OF REGN : 24.02.2017  
DATE/TIME IN : 18.01.2019 16:30  
ACCIDENT DATE : 18.01.2019

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001	04-01-0104-2282-G	IONIQVC COVER-RR BUMPER#	1	459.40	20.00	367.52
0002	04-01-0104-2360-G	IONIQV1 MOULDING ASSY-RR	1	451.25	20.00	361.00
0003	FNPS	NO PLATE(S) WITH CASING	2 N	110.00	2.00-	110.00
0004	04-01-0104-2370-G	IONIQ LAMP ASSY-REAR FOG	1	201.50	20.00	161.20
0005	09-01-9999-0068-A	HYUNDAI REVERSE SENSOR AS	1 N	135.70	2.00-	135.70
0006	04-01-0101-0111-G	HYUNDAI BUMPER COVER CLIP	10 L	22.00	20.00	17.60
						SUB-TOTAL : 1,153.02

JOB NATURE

0000 L	SPRAYPAINT - FRT	200.00
0001 L	PANEL BEATING- REAR	300.00
0002 23-502	SPRAYPAINT - REAR	200.00
0003 L	REMOVE/REFIX REVERSE SENSOR	30.00
0004 L	MERIMEN	10.00

COMFORTDELGRO ENGINEERING PTE LTD

Date: 23.01.2019

Time: 17:39:10

REPAIR ESTIMATE

Page: 2

COMPANY : THIRD PARTY'S CLAIMS (CAS)  
CUSTOMER: 7010045  
ADDRESS : COMFORT TRANSPORTATION PTE LTD  
383 SIN MING DRIVE  
SINGAPORE SINGAPORE 575717  
65508755

JOB NO : 305261437  
REGN NO : SHA3892Y  
MILEAGE : 0000000000  
MAKE : HYUNDAI  
MODEL : IONIQ  
DATE OF REGN : 24.02.2017  
DATE/TIME IN : 18.01.2019 16:30  
ACCIDENT DATE : 18.01.2019

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

SUB-TOTAL : 740.00

TOTAL : 1,893.02

\_\_\_\_\_  
MVA NAME & SIGNATURE  
DATE :

\_\_\_\_\_  
SURVEYOR NAME & SIGNATURE  
DATE : AUTHORIZED : YES / NO

# COMFORTDELGRO ENGINEERING

Our Job Ref No 305261437  
Date : 23/01/2019

ComfortDelGro Engineering Pte Ltd  
59 Loyang Drive Singapore 508969  
Fax: 6546 8156

## FINALIZATION FORM

To : LKK Fax : \_\_\_\_\_  
Attn : KALVIN  
: SHA3892Y Date of Accident : 18/01/2019


The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-

1. The repair job shall bill to: TOKIO --- SLD9369P  
###
2. The finalized amount shall be:
 

(a) Spare Parts after List discount		<u>\$1,153.02</u>
(b) Labour Charges	###	<u>\$740.00</u>
<b>Total for Part-By-Part Repair Cost</b>		<b><u>\$1,893.02</u></b>
N1		
(c) Lumpsum Repair (if applicable)		
Total for Lumpsum repair cost after Less: <u>20%</u>		<u>                    </u>
Final Lumpsum Repair cost		<u>                    </u>

3. Estimated normal period for repairs: 3 working days
4. We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days
5. Thank you for your assistance.

We confirm the estimates and finalized amount

Signature :   
Name : JUMANI  
Tel : 6214 8315  
Fax : 65468156

Signature :   
Name : Kalvin  
Date : 24/1/19

### For Official Use Only

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid		N		
3. Survey Fees				
4. LTA Search Fee	\$7.49			
5. Medical Fees (on behalf of driver, if applicable)				
6. Overrun				

Remarks:

\_\_\_\_\_

A member of COMFORTDELGRO

Team: ARC Repair TP(CLS0)1

## JOB CARD

Sales Order:

JC NO.: 305261437

STOMER: COMFORT TRANSPORTATION PTE LTD  
 VMS: 7010045  
 STOMER NO: 383 SIN MING DRIVE  
 DRESS: Singapore SINGAPORE 575717  
 65508755 (O)

REGN NO.: SHA3892Y	MILEAGE
MAKE: HYUNDAI	FUEL: E.....1/2.....F
MODEL: IONIQ	DATE/TIME IN: 18.01.2019 16:30
YR OF MANU: 24.02.2017	TARGET DATE
CHASSIS CODE: KMHC851CVHU022699	COMPLETION DATE/TIME:


SCOUNT CARD NO.

### JOB DESCRIPTION

Accident Date: 18.01.2019  
 NATURE: 3P 18.01.19 -

S/NO                      LABOR CODE

### DESCRIPTION



CHECKED & PASSED OUT BY: \_\_\_\_\_

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

Acknowledgement Slip

Exit Pass

to: SHA3892Y                      JU TOKIO LKK

Vehicle No.: SHA3892Y

Name of Service Advisor


Signature/Date

Name of Service Advisor

Date

to be returned to Service Reception upon collection

To be kept by Security Guard



**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT**

Our File No: CC3/TMI19001397/K1QD3N2  
Date: 25/01/2019

**REFERENCE**

Handling Insurer:	Tokio Marine Insurance Singapore Ltd	Policy No:	MI000656
Claimant Vehicle No :	SHA3892Y	Insured Vehicle No :	SLD9369P
Date of Loss:	18/01/2019	Nature of Claim:	TP
		Claim No:	M1900424

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No:	SHA3892Y	Engine No:	G4LEGU327124
Make & Model:	HYUNDAI IONIQ HYBRID, 1.6 GLS DCT (A)	Chassis No:	KMHC851CVHU022699
Reg. Date:	24/02/2017 (Man. Year: 2017)	Odometer:	256033 km
Colour:	Blue		
Engine Capacity:	1580 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	Average

**CONDITION OF TYRES**

Front Tyre Size:	195/65R15	Rear Tyre Size:	195/65R15
Front Left Side:	West Lake 7 mm	Rear Left Side:	West Lake 7 mm
Front Right Side:	West Lake 7 mm	Rear Right Side:	West Lake 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,801.38	1,153.02	648.36	35.99
Miscellaneous Items	10.00	10.00	0.00	0.00
Labour	1,100.00	730.00	370.00	33.64
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>2,911.38</b>	<b>1,893.02</b>	<b>1,018.36</b>	<b>34.98</b>
<b>+ GST 7.00/7.00% (S\$)</b>	<b>203.79</b>	<b>132.51</b>	<b>71.28</b>	<b>34.98</b>
<b>Nett Amount (S\$)</b>	<b>3,115.17</b>	<b>2,025.53</b>	<b>1,089.64</b>	<b>34.98</b>

**INSPECTION**

Date of Assignment:	22/01/2019	Present Location:	ComfortDelGro Engineering Pte Ltd (Loyang)
Date Inspected:	21/01/2019	Inspected At:	ComfortDelGro Engineering Pte Ltd (Loyang) 59 Loyang Drive Singapore 508969
Estimated Period of Repair:	3.0 days		

Adjuster: KALVIN ANG WEI KUN

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

## REPAIR DETAILS

### Reference

<b>Part Source:</b> MRM-SG	Version: 1.0 (Last Synchronised: 25 Jan 2019)
<b>Parts:</b> 192	HYUNDAI IONIQ HYBRID 1.6 GLS DCT (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b> Repairer's	(Price-denominated Standard List)
<b>Print Code:</b> (Unsubmitted, no print-code for SHA3892Y)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
<b>Further Info:</b> Items/values not in reference catalogue are prefixed with an asterisk *	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount	
1	1		*REAR BUMPER ASSY	Cracked	459.40 FL	*459.40 FL	
2	1		*REAR BUMPER REINFORCEMENT	Serviceable	294.80 FL	*- FL	
3	1		*REAR BUMPER REINFORCEMENT BRACKET LH	Serviceable	138.10 FL	*- FL	
4	1		*REAR BUMPER REINFORCEMENT BRACKET RH	Serviceable	138.10 FL	*- FL	
5	1		*REAR BUMPER CENTRE MOULDING ASSY	Cracked	451.25 FL	*451.25 FL	
6	1		*REAR BUMPER LOWER CENTRE MOULDING ASSY	Repair	47.50 FL	*- FL	
7	1		*REAR BUMPER STAY	Serviceable	138.10 FL	*- FL	
8	10		*REAR BUMPER COVER CLIPS	Necessary	22.00 FL	*22.00 FL	
9	1		*REAR BUMPER UNDER COVER	Serviceable	53.85 FL	*- FL	
10	1		*REAR NUMBER PLATE	Cracked	25.00 F	*25.00 F	
11	1		*REAR NUMBER PLATE CASING	Cracked	30.00 F	*30.00 FS	
12	1		*REVERSE SENSOR	Shorted	135.70 F	*135.70 FS	
13	1		*FRONT BUMPER (NPA)	Repair	-	*- FL	
<b>Supplementary #1</b>							
14	1		*FRT NUMBER PLATE WITH CASING	Cracked	55.00 F	*55.00 FS	
15	1		*LAMP ASSY - REAR FOG	Cracked	201.50 FL	*201.50 FL	
					<b>Sub Total (\$\$)</b>	<b>2,190.30</b>	<b>1,379.85</b>
					<b>- List Item Discount on L Items 20.00/20.00% (\$\$)</b>	<b>388.92</b>	<b>226.83</b>
					<b>Total Parts (\$\$)</b>	<b>1,801.38</b>	<b>1,153.02</b>

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

### Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
<b>Miscellaneous Items</b>				
1	1	OD/TP Case (Insurer)	10.00	10.00
<b>Sub Total (S\$)</b>			<b>10.00</b>	<b>10.00</b>

### Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	PANEL BEATING	New	350.00	300.00
2	SPRAYPAINT	New	250.00	200.00
3	WIRING	New	30.00	-
4	TUFF KOTE	New	50.00	-
5	REMOVE/REFIX REVERSE SENSOR	New	120.00	30.00
<b>Supplementary #1</b>				
<b>Labour Items</b>				
6	SPRAYPAINT - FRT	New	300.00	200.00
<b>Gross Labour Cost (S\$)</b>			<b>1,100.00</b>	<b>730.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >