

ASS. REC. BY:

REF: CS/MSG19001409/KSD352

Special Instruction:

Surveyor
Meinmen

Kenneth

ASSIGNMENT (Office)

From (Person):

Pauline Tham

of

MSG

Date/Time:

21/1/19 @ 4:22pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SKH1805R

Insured:

SFS 2846S

at Workshop m/s

BCC Automotive

Tel:

6552 5588

of

1 Sin Ming Ind. Est. - Sec. C #01-101

Policy No:

A290887450mx

Claim No:

582747

Sum Insured:

Excess:

Make of Veh:

D.O.A.

16/01/2019

(Client's Record)

CA / REV / REP. / REV 24 HRS (up)

H.O.D. Endorsement:

Date/Time:

9:30am 22/1/19

Person Contacted:

Christian

Vehicle IN/OUT

Date/Time

Action/Instruction (✓) Estimate

SKH1805R-NS/INC17013087/Grbe2

DUA: 3/7/2017

SFS2846S-MSG19001334/qd3

DUA: 16/1/2019.

23/1/19 @ 1:28pm revised to Pauline Tham via Meinmen.

REF: MSIG

ASSIGNMENT

From: Date: 22/1/2019

Estimated Cost:

OD / ☒ WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SKH 1805R

at Workshop n/s: BCC Automotive

of 1 Sin Ming Ind. Est & C-C # 01-101

Insured:

Policy No:

Claims No:

Sum Insured: Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: S 21k

IDAC Accident Report: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 07 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS ^{up}

Date: Person Contacted:

Vehicle: IN / OUT

Veh No: SKH 1805R / Regn: 12 09

Type: ☒ M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Volkswagen Scirocco 1390

Colour: M. Black A/C: Insured / Std / NI / NA

Sp. Reading: 157316 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: WVV 888138 AV 41083

Gen. Cond: ☒ Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / ☒ STD A/Rim or

Tyre Size: F:

R:

235/40 ZR18

BS / DUN / EXNOVA / GY / FS / LIZA / ☒ MIC / OHTSU / PIR / SUM /

TOYO / YOKO or

Front

Rear

R/Bal. 5 mm

R/Bal. 6 mm

L/Bal. 5 mm

L/Bal. 6 mm

D.O.A. 16/1/19

D.O.I. 22/1/19

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

O/S Frt burnt

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

23/1 File pass to Car

Submit preli report due to owner change workshop.

RECEIVED 31 JAN 2019

Date/Time, File Pass to?

31/01/19

1) Typist

Date/Time, File Return to?

2)

Report Format: Preli

Lump Sum / I.B.I: (\$)

Days Of Repair: 7

Resurvey No. of Trip: /

Survey Fee:

Transportation:

) S + RS, SI

) Photos

) Others

TOTAL

Add Fee: ☐ Site Insp (\$☐ Interview (\$☐ Tech. Invs (\$☐ Weekend (\$

150
10
TOTAL

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	17 Jan 2019		21 Jan 2019 16:22 Assign				New Assignment Cancel Case

[Main](#)
[Reference](#)
[Claim Details](#)
[Documents](#)
[Show All](#)

CLAIM SUBFOLDER DETAILS

[\[Created by insurer\]](#)

Insured:	KOH CHONG HEONG, ID: S25828901		
Main Claimant:	TEE YI WEI, ID: S9527218E		
Vehicle Reg. No.:	SKH1805R	Date of Loss:	16/01/2019 21:00 - :59 [109 Months From LTA Reg Date (Man Yr)]
Claim Type:	TP / 582747	Policy/Cover Note No.:	A29088745QMX (Comprehensive) Coverage: 12/07/2018 - 11/07/2019
Vehicle Reg. No. (Insured):	SFS28465	Policy No. (Claimant):	
		Excess:	S\$0.00
Repairer:	BCC Automotive Pte Ltd (Sin Ming) Blk 1 Sin Ming Industrial Estate, Sector C #01-101, 575636 Sin Ming - Tel: 6552 5588		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Pauline Tham - 6594 2545]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 22/01/2019]		
Driver/Custodian (Insured):	KOH CHONG HEONG (), NRIC: S25828901		
Adj Asg. Remarks:	Liability not clear. TP agree SJE - assign LKK Auto Consultants Pte Ltd.		

ASSOCIATED MAIL RECEIVED

There are no mail for this case.

[View All](#)
[Compose Case Mail](#)

ALL ASSOCIATED TASKS

[View All](#)
[Search Tasks](#)
[Create New Task](#)
[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Shirley Hiew (LKK Auto)

From: Pauline Tham <pauline_tham@sg.msig-asia.com>
Sent: Thursday, 31 January 2019 10:47 AM
To: Shirley Hiew (LKK Auto)
Cc: SUR
Subject: RE: SKH1805R TP / 582747

Dear Shirley

Please proceed to submit your report.

Thanks.

Pauline Tham

Senior Executive, Claims Services, Motor

D: +65 6594 2545 | F: +65 6225 7402 | pauline_tham@sg.msig-asia.com



MSIG

MSIG Insurance (Singapore) Pte Ltd 16 Raffles Quay, #24-01 Hong Leong Building, Singapore 048581 | T: +65 6220 9644 | F: +65 6225 6371 | Co. Reg. No. 200412212G | msig.com.sg



A Member of **MS&AD** INSURANCE GROUP

From: Shirley Hiew (LKK Auto) [mailto:ShirleyHiew@lkkauto.com]
Sent: Wednesday, 30 January, 2019 3:27 PM
To: Pauline Tham <pauline_tham@sg.msig-asia.com>
Cc: SUR <sur@lkkauto.com>
Subject: SKH1805R TP / 582747

Hi Pauline,

As spoken, owner of SKH 1805R went to other work shop to repair his vehicle.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Shirley Hiew (LKK Auto)

From: Admin-D (LKKAuto) <admin-d@lkkauto.com>
Sent: Friday, 25 January 2019 12:00 PM
To: christina@bcc.sg; SUR
Cc: assignments
Subject: RE: 3RD PARTY CLAIM AGAIN SFS2846S

Dear Christina,

Thank you for the email.

Dear Shirley,

Kindly assist

FYNA Our Ref : CS/MSG19001409/Ksd3

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Christina Lim [mailto:christina@bcc.sg]
Sent: Friday, 25 January 2019 11:49 AM
To: 'Admin-D (LKKAuto)' <admin-d@lkkauto.com>; 'assignments' <assignments@lkkauto.com>
Subject: RE: 3RD PARTY CLAIM AGAIN SFS2846S

Hi Nivitha,

We wish to inform you that customer went to other work shop to repair his car.

Thanks

Christina Lim | +65 6552 5588



BCC Automotive Pte Ltd | www.bcc.sg

Blk 1 Sin Ming Industrial Estate

Sector C #01-101/103/105/107/109

Singapore 575636

Tel : +65 6552 5588 (5 lines) | Fax : +65 6552 7750

Operating Hours : Mon - Fri (8:30am - 5:30pm) | Sat (8:30am - 4:00pm) | Closed on Sun and Public Holidays

From: Admin-D (LKKAuto) [mailto:admin-d@lkkauto.com]
Sent: 22 January, 2019 9:26 AM

Note: This document has not been finalised.**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Pauline Tham

Date: 23 Jan 2019

Preliminary Advice

Insured Vehicle No	: SFS2846S	Accident Date	: 16/01/2019
TP Vehicle No	: SKH1805R	Assignment Date	: 21/01/2019
Make	: VOLKSWAGEN SCIROCCO	Est. Duration of Repair	: 7.00
Date of Inspection	: 22/01/2019		
Inspection At	: BCC AUTOMOTIVE PTE LTD (SIN MING) BLK 1 SIN MING INDUSTRIAL ESTATE, SECTOR C #01-101 SINGAPORE 575636		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages o/s front portion burnt and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	9,780.50
Revised Amount	:S\$	7,839.50
Check Items (Estimated)	:S\$	120.00
Total	:S\$	7,959.50

Lump Sum Repair :S\$

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is economical/not economical for repair.
- (X) The above survey was conducted on a 'without prejudice' basis.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	17/01/2019 14:41
Date Of Accident	16/01/2019 22:50
Exact Location Of Accident	YISHUN BLK 348D OPEN SPACE CARAPRK
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKH1805R
Insured/Policyholder	
Name Of Registered Owner	TEE YI WEI
NRIC No	S9527218E
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-81391815
Alternative Phone No	OTHERS-81391815
Vehicle Particulars	
Manufacturer	VOLKSWAGEN
Model	SCIROCCO 1.4 TSI
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR
Insurance Company	
Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5098640437 (DRIVO CLASSIC)
Cover Note Number	
Driver	
Name of Driver	TEE YI WEI
NRIC No	S9527218E
Date Of Birth	03/08/1995
Occupation	OUTDOOR
Date Of Driving Pass	25/02/2016
Driving Experience	2 YEARS AND 10 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-81391815
Fax Number	
Contact Number	OTHERS-81391815
Email Address	NOEMAIL

Address	BLK 239 #23-378 JURONG EAST STREET 21
Postcode	600239
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	FIRE, EXPLOSION OR LIGHTNING
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	0

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO STATEMENT ATTACHED. *INFORMED DRIVER TO MAKE A POLICE REPORT AND SUBMIT TO INSURER.
REMARKS: POLICE CAME TO THE ACCIDENT SCENE AND I WAS GIVEN A CASE NUMBER : L/20190116/0158.
(ATTENDED BY CHRISTINA)

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SFS2846S
Vehicle Make/Model/Colour	AUDI A4
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	KOH POH HENG
NRIC/Passport Number	S9246936J
Contact Number	81995998
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:


Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:



Sketch Plan #2 Pg. 1

SKETCH PLAN



A- SKH 1805R

B- SFS 28465

DOA - 16/1/19

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

The owner of the audi A4 that burned told me when I reach the scene.

He said "When ~~he~~ he was reversing he saw smoke coming out of his bonnet when ~~he~~ my car was beside just right beside", ~~he~~ And when I am back on the scene my car was already burn ~~badly~~ on the front bumper and the sides of the car.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

17 JAN 2019

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:





**SINGAPORE
POLICE FORCE**



E/20190117/2068

1 of 2

POLICE REPORT (NP299)

Report No. E/20190117/2068

Police Station Of Origin
Thomson NPP
25 Sin Ming Road #01-180 SINGAPORE
570025
Tel No: 1800-4529999

Date/Time Report Made 17/01/2019 16:33	Vide Report No. L/20190116/0158	Station Diary No. 47
Name Of Informant TEE YI WEI	Address APT BLK 239 JURONG EAST STREET 21 #23-376 SINGAPORE 600239	
ID Type / ID No. NRIC NO / S9527218E	Contact No. Home/Office Mobile 81391815	
Nationality SINGAPORE CITIZEN	Email Address	
Occupation WORK SITE SUPERVISOR	Sex Male	Age 23
Institution/School Name	Date of Birth 03/08/1995	Race Chinese
Date/Time Of Incident 16/01/2019 22:30	Location Of Incident APT BLK 349 YISHUN AVENUE 11 YISHUN JASMINE SINGAPORE 760349 Open Space Car Park	

Brief details.

On 16/01/2019 at about 2230hrs when I was at work, I received a call from the Police. The Police officer told me that my car bearing registration number SKH1805R (Volkswagen Scirocco 1.4 TSI, Black colour) is involved in a fire incident. I immediately rushed down to scene.

Upon arrival, I noticed that my car front right driver side was already burnt. The Police told me that a

Signature Of Officer Recording The Report:
E / Sgt 2 MUHAMMAD ZULHILMI BIN ABU HASSAN

Signature Of Interpreter:
Not applicable

Officer In-Charge Of Case:
E / Tanglin Police Divisional Investigation Branch /
Insp ZHOU PAOPAO
Contact No.: 6391 0000

Authentication Stamp

Signature Of Informant:

Date/Time:
17/01/2019 16:33

Classification Of Case:



**SINGAPORE
POLICE FORCE**



E/20190117/2068

2 of 2

POLICE REPORT (NP299)

CONTINUATION OF REPORT

Report No. E/20190117/2068

vehicle SFS2846S caught fire and the fire spread to my car which was parked at the parking lot.

Due to the incident, the front right bumper, front right tyres and rim, right side mirror was severely burnt.

I wish to state that my said car had been parked at the said parking lot for about 2 weeks. I went to IDAC and I was advised to lodge a Police report to facilitate the claim. As such I am lodging this Police report for record purposes.

Signature Of Officer Recording The Report:

E / Sgt 2 MUHAMMAD ZULHILMI BIN ABU HASSAN

Signature Of Interpreter:
Not applicable

Officer In-Charge Of Case:
E / Tanglin Police Divisional Investigation Branch /
Insp ZHOU PAOPAO
Contact No.: 6391 0000

Authentication Stamp

Signature Of Informant:

Date/Time:
17/01/2019 16:33

Classification Of Case:

> [Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:

Singapore NRIC

Owner ID:

7218E

Vehicle Details

Vehicle No.:

SKH1805R

Vehicle to be Exported:

Yes

Intended Deregistration Date:

18 Jan 2019

Vehicle Make:

VOLKSWAGEN

Vehicle Model:

SCIROCCO 1.4L AT TSI 1372Q5

Primary Colour:

Black

Manufacturing Year:

2009

Engine No.:

CAV133453

Chassis No.:

WVWZZZ13ZAV419083

Maximum Power Output:

118.0 kW (158 bhp)

Open Market Value:

\$23,947.00

Original Registration Date:

16 Dec 2009

First Registration Date:

16 Dec 2009

Transfer Count:

4

Actual ARF Paid:

\$23,947.00

Intended PARF Rebate Details

PARF Eligibility:

Yes

PARF Eligibility Expiry Date:

15 Dec 2019

PARF Rebate Amount:

\$11,973.00

Intended COE Rebate Details

COE Expiry Date:

15 Dec 2019

COE Category:

A - Car (1600cc & below)

COE Period(Years):

10

QP Paid:

\$13,658.00

COE Rebate Amount:

\$1,238.00

Total Rebate Amount:

\$13,211.00

The information contained herein is correct as at 17 Jan 2019

OK

Certificate of Insurance

MOTOR VEHICLES (THIRD PARTY RISKS AND COMPENSATION) ACT (CHAPTER 189)
MOTOR VEHICLES (THIRD PARTY RISKS AND COMPENSATION) RULES, 1960
ROAD TRANSPORT ACT, 1987 (MALAYSIA)
MOTOR VEHICLES (THIRD PARTY RISKS) RULES, 1959 (MALAYSIA)

Certificate Number: 5098640437

Cover : drivo CLASSIC

1. Index mark and Registration Number of Vehicle : **SKH1805R**
Chassis Number : **WVWZZZ13ZAV419083**
2. Name of Policyholder : **TEE YI WEI**
3. Effective Date of Insurance : **09 Mar 2018**
4. Expiry Date of Insurance : **15 Jun 2019**
5. Persons or Classes of Persons entitled to drive#
(a) The Policyholder.
(b) Any other person who is driving on the Policyholder's order or with his/her permission.
Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle.
6. Limitations as to Use#
(a) Use for social domestic and pleasure purposes and in connection with the Policyholder's business or profession.

This Policy does not cover

- (a) Use for hire or reward.
- (b) Use for racing, pace-making, reliability trial or speed-testing.
- (c) Use for the carriage of goods (other than samples) in connection with any trade or business.
- (d) Use for any purpose in connection with the Motor Trade.

Limitations rendered inoperative by Section 8 of the Motor Vehicle (Third Party Risks and Compensation) Act (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

EXCESS (SECTION 1)	: S\$600
EXCESS (SECTION 2)	: N/A
WINDSCREEN EXCESS	: S\$100
ADDITIONAL EXCESS	: N/A
UNNAMED DRIVER EXCESS	: PLEASE REFER OVERLEAF
REPAIR AT OWNER'S PREFERRED WORKSHOP	: NO
INSURE WITH COE	: YES
NCD PROTECTION	: NO
TRANSPORT ALLOWANCE	: NO
EXCESS WAIVER	: NO
PRIMARY DRIVER	: TEE YI WEI
NAMED DRIVER (1)	: N/A
NAMED DRIVER (2)	: N/A
HIRE PURCHASE COMPANY	: DBS BANK LTD
SUM INSURED	: MARKET VALUE OF INSURED VEHICLE AT TIME OF LOSS

I/We hereby Certify that the Policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia)

Agency : META AGENCY PTE. LTD. (00000573430)
Date of Issue : 08 Mar 2018 15:03 hrs

For NTUC INCOME INSURANCE CO-OPERATIVE LIMITED



Countersigned By:

Authorised Officer



Chief Executive

REPUBLIC OF SINGAPORE
IDENTITY CARD NO. S9527218E



Name

TEE YI WEI

郑义伟

Race

CHINESE

Date of birth

03-08-1995

Sex

M

Country of birth

SINGAPORE



REPUBLIC OF SINGAPORE DRIVING LICENCE

Licence Number: S9527218E

Name:

TEE YI WEI



Birth Date: 03 Aug 1995
Issue Date: 25 Feb 2016



002541118C



Licence No. S9527218E



Date of issue

05-02-2010

Address

APT BLK 239 JURONG EAST STREET 21
#23-376
SINGAPORE 600239

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(S)

EFFECTIVE DATE

Class 3

Motor cars with unladen weight \leq 3000kg with \leq 7 passengers, exclusive of driver; and other motor vehicles with unladen weight \leq 2500kg



Licence No. S9527218E

NP 428A

**BCC AUTOMOTIVE PTE LTD**

BLK 1 SIN MING IND. ESTATE
SECTOR C #101/103/105/107/109
SINGAPORE 575636
Tel: +65 6552 5588 Fax: +65 6552 7750
Email: enquiry@bcc.sg Website: www.bcc.sg

QUOTATION

Company / GST Reg No : 200507063Z

Quotation No : **SMQ8333**Quotation Date : **2019-01-17**

Vehicle Reg No : SKH1805R
Name : TEE YI WEI

Make & Model : VOLKSWAGEN - SCIROCCO 1.4L AT
Chassis No : TSI 1372Q5
Mileage : WWWZZ13ZAV419083
Officer-In-Charge : 157316 KM
Page : KAHKHEE
: 1 of 2

(B) Burnt

No	Description	Unit Price	Qty	Disc (%)	Amount	
1	FRONT BUMPER	B 850.00	1.00	10.00	765.00	✓
2	FRONT BUMPER LAMP RH	B 520.00	1.00	10.00	468.00	✓
3	FRONT BUMPER BRACKET LOWER	B 145.00	1.00	10.00	130.50	✓
4	FRONT BUMPER CENTER GRILLE	B 320.00	1.00	10.00	288.00	✓
5	FRONT BUMPER CARBON FIBRE SPOILER (NETT)	B 700.00	1.00		700.00	✓
6	FRONT BONNET CARBON FIBRE STICKER (NETT)	B 100.00	2.00		200.00	✓
7	HEADLAMP RH	B 950.00	1.00	10.00	855.00	✓
8	HEADLAMP WASHER GUIDE	B 28.00	1.00	10.00	25.20	✓
9	WINDOW WEATHER STRIP RH	B 185.00	1.00	10.00	166.50	✓
10	RH WING MIRROR HOUSING	B 410.00	1.00	10.00	369.00	✓
11	RH WING MIRROR BACK COVER	B 160.00	1.00	10.00	144.00	X
12	RH HEADLAMP BULB (HID)	B 310.00	1.00	10.00	279.00	✓
13	RH HEADLAMP BALAST (HID)	B 550.00	1.00	10.00	495.00	✓
14	FOG LAMP RH	B 185.00	1.00	10.00	166.50	✓
15	FOG LAMP COVER	B 280.00	2.00	10.00	504.00	✓
16	FENDER RH	B 410.00	1.00	10.00	369.00	✓
17	FENDER SHIELD RH	B 115.00	1.00	10.00	103.50	✓
18	RETAINER RH	B 32.00	1.00	10.00	28.80	✓

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

**BCC AUTOMOTIVE PTE LTD**

BLK 1 SIN MING IND. ESTATE
SECTOR C #101/103/105/107/109
SINGAPORE 575636
Tel: +65 6552 5588 Fax: +65 6552 7750
Email: enquiry@bcc.sg Website: enquiry@bcc.sg

QUOTATION

Company / GST Reg No : 2005070632

Quotation No : **SMQ8333**Quotation Date : **2019-01-17**

Vehicle Reg No : SKH1805R
Name : TEE YI WEI

Make & Model : VOLKSWAGEN SCIROCCO 1.4L AT
Chassis No : TSI 1372Q5
Mileage : WVVZZZ13ZAV419083
Officer-In-Charge : 157316 KM
Page : KAHKHEE
2 of 2

No	Description	Unit Price	Qty	Disc (%)	Amount
19	BRACKET RH	B 35.00	1.00	10.00	31.50 ✓
20	COVER TRIM	B 55.00	2.00	10.00	99.00 ✓
21	GRILLE INNER	Sn 175.00	1.00	10.00	157.50 X
22	GRILLE OUTER	Sn 185.00	1.00	10.00	166.50 X
23	SCREW	nn 5.00	32.00	10.00	144.00 X
24	NUT	nn 5.00	30.00	10.00	135.00 X
25	MICHELIN TYRE (235/40R18) (FRONT RH) (NETT)	B 270.00	1.00		270.00 80/m
26	RESpray PAINT ROOF PANEL, FRONT BUMPER, FRONT RH FENDER, FRONT RH DOOR, REAR RH DOOR & REAR RH FENDER	1800.00	1.00	1100/	1,800.00
27	PANEL BEAT & REPLACEMENT FOR THE ABOVE REPAIR	800.00	1.00		800.00 600/
28	TOWING CHARGE (FLATBED)	120.00	1.00	(Bill)	120.00 ?

Sub-Total : 9,780.50
Add GST 7% : 684.64
Estimated Total Amt (SGD) : 10,465.14

NOTE:

1. This quotation is only the estimated cost of repair. Any additional works and parts be required during the course of repair, a supplementary quote will be submitted.
2. If you decide to terminate the repair after our diagnosis, a diagnostic fee will apply according to the job performed

CUSTOMER'S AUTHORIZATION

I agree to this quotation and hereby authorize to proceed with the above listed repairs.

CUSTOMER'S SIGNATURE _____

(& Co's Stamp, WHERE NECESSARY)

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	17 Jan 2019		21 Jan 2019 16:22 Edit Adj Rpt	S\$7,851.50 Edit Estimates	S\$7,851.50 View Rpt		Pending for Survey Report Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	KOH CHONG HEONG, ID: S2582890I		
Main Claimant:	TEE YI WEI, ID: S9527218E		
Vehicle Reg. No.:	SKH1805R	Date of Loss:	16/01/2019 21:00 - :59 [109 Months From LTA Reg Date (Man Yr)]
Claim Type:	TP / 582747	Policy/Cover Note No.:	A29088745QMX (Comprehensive) Coverage: 12/07/2018 - 11/07/2019
Vehicle Reg. No. (Insured):	SFS2846S	Policy No. (Claimant):	
		Excess:	S\$0.00
Repairer:	BCC Automotive Pte Ltd (Sin Ming) Blk 1 Sin Ming Industrial Estate, Sector C #01-101, 575636 Sin Ming - Tel: 6552 5588		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Pauline Tham - 6594 2545]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KENNETH KONG] ... [Final Rpt due 20/02/2019]		
Driver/Custodian (Insured):	KOH CHONG HEONG (), NRIC: S2582890I		
Adj Asg. Remarks:	Liability not clear. TP agree SJE - assign LKK Auto Consultants Pte Ltd.		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SKH1805R (582747)**

[SFS2846S]

TP

TEE YI WEI

Jan 16 2019 9:00PM

[KOH CHONG HEONG]

BCC Automotive Pte Ltd

Upload Documents Upload Photos Compose New Letter

View View in Browser ▼

Assessment Reports

1 per page ▼

No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	23/01/19 13:28	Adjuster Immediate Advice	Load HTM	

Photos/Images

3 per page ▼

No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	31/01/19 11:35	General View	Load JPG	<input checked="" type="checkbox"/>
2	31/01/19 11:35	General View	Load JPG	<input checked="" type="checkbox"/>
3	31/01/19 11:35	General View	Load JPG	<input checked="" type="checkbox"/>
4	31/01/19 11:35	General View	Load JPG	<input checked="" type="checkbox"/>
5	31/01/19 11:35	General View	Load JPG	<input checked="" type="checkbox"/>
6	31/01/19 11:35	General View	Load JPG	<input checked="" type="checkbox"/>
7	31/01/19 11:35	Odometer Reading	Load JPG	<input checked="" type="checkbox"/>
8	31/01/19 11:35	General View	Load JPG	<input checked="" type="checkbox"/>
9	31/01/19 11:35	General View	Load JPG	<input checked="" type="checkbox"/>
10	31/01/19 11:35	General View	Load JPG	<input checked="" type="checkbox"/>
11	31/01/19 11:35	General View	Load JPG	<input checked="" type="checkbox"/>
12	31/01/19 11:35	General View	Load JPG	<input checked="" type="checkbox"/>
13	31/01/19 11:35	General View	Load JPG	<input checked="" type="checkbox"/>
14	31/01/19 11:35	General View	Load JPG	<input checked="" type="checkbox"/>
15	31/01/19 11:35	General View	Load JPG	<input checked="" type="checkbox"/>
16	31/01/19 11:35	General View	Load JPG	<input checked="" type="checkbox"/>
17	31/01/19 11:35	General View	Load JPG	<input checked="" type="checkbox"/>
18	31/01/19 11:35	General View	Load JPG	<input checked="" type="checkbox"/>
19	31/01/19 11:35	General View	Load JPG	<input checked="" type="checkbox"/>

Documentation

1 per page ▼

No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	21/01/19 09:27	SKH1805R e-file report	Load PDF	
2	21/01/19 09:28	OI SFS2846S e-file report	Load PDF	
3	21/01/19 14:02	tp agree SJE - assign LKK	Load PDF	
4	31/01/19 10:48	TP claimant went to other workshop - LKK to submit report	Load HTM	

Documents Checklist

DOCUMENTS CHECKLIST

Reset Save Print

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)**Show Remarks To:** ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG19001409/KSD3S2

Date: 31/01/2019

REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	A29088745QMX
Claimant Vehicle No :	SKH1805R	Insured Vehicle No :	SFS2846S
Date of Loss:	16/01/2019	Nature of Claim:	TP
		Claim No:	582747

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKH1805R	Engine No:	CAV133453
Make & Model:	VOLKSWAGEN SCIROCCO, 1.4 L (A)	Chassis No:	WVWZZZ13ZAV419083
Reg. Date:	16/12/2009 (Man. Year: 2009)	Odometer:	157316 km
Colour:	Metallic Black		
Engine Capacity:	1390 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	235/40 ZR18	Rear Tyre Size:	235/40 ZR18
Front Left Side:	Michelin 5 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 5 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,060.50	6,151.50	909.00	12.87
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,720.00	1,700.00	1,020.00	37.50
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	9,780.50	7,851.50	1,929.00	19.72
+ GST 7.00/7.00% (S\$)	684.64	549.61	135.03	19.72
Nett Amount (S\$)	10,465.14	8,401.11	2,064.03	19.72

INSPECTION

Date of Assignment:	21/01/2019	
Date Inspected:	22/01/2019	Inspected At: BCC Automotive Pte Ltd (Sin Ming) Blk 1 Sin Ming Industrial Estate, Sector C #01-101 Singapore 575636
Estimated Period of Repair:	7.0 days	

Adjuster: KENNETH KONG

Manager: Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

(REPAIR COST NOT CONCLUDE)

(EXCLUDE CHECK ITEMS S\$120.00 NETT)

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 31 Jan 2019)
Parts:	144	VOLKSWAGEN SCIROCCO 1.4 L (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKH1805R)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Burnt	850.00 FL	*850.00 FL
2	1		*FRONT BUMPER LAMP RH	Burnt	520.00 FL	*520.00 FL
3	1		*FRONT BUMPER BRACKET LOWER	Burnt	145.00 FL	*145.00 FL
4	1		*FRONT BUMPER CENTER GRILLE	Burnt	320.00 FL	*320.00 FL
5	1		*HEADLAMP	Burnt	950.00 FL	*950.00 FL
6	1		*HEADLAMP WASHER GUIDE	Burnt	28.00 FL	*28.00 FL
7	1		*WINDOW WEATHER STRIP RH	Burnt	185.00 FL	*185.00 FL
8	1		*RH WING MIRROR HOUSING	Burnt	410.00 FL	*410.00 FL
9	1		*RH WING MIRROR BACK COVER	Serviceable	160.00 FL	*- FL
10	1		*RH HEADLAMP BULB (HID)	Burnt	310.00 FL	*310.00 FL
11	1		*RH HEADLAMP BALAST (HID)	Burnt	550.00 FL	*550.00 FL
12	1		*FOG LAMP RH	Burnt	185.00 FL	*185.00 FL
13	2		*FOG LAMP COVER	Burnt	560.00 FL	*560.00 FL
14	1		*FENDER RH	Burnt	410.00 FL	*410.00 FL
15	1		*FENDER SHIELD RH	Burnt	115.00 FL	*115.00 FL
16	1		*RETAINER RH	Burnt	32.00 FL	*32.00 FL
17	1		*BRACKET RH	Burnt	35.00 FL	*35.00 FL
18	2		*COVER TRIM	Burnt	110.00 FL	*110.00 FL
19	1		*GRILLE INNER	Serviceable	175.00 FL	*- FL
20	1		*GRILLE OUTER	Serviceable	185.00 FL	*- FL
21	1		*SCREW	Not Necessary	160.00 FL	*- FL
		32pcs				
22	1		*NUT	Not Necessary	150.00 FL	*- FL
		30pcs				
23	1		*FRONT BUMPER CARBON FIBRE SPOILER	Burnt	700.00 FS	*700.00 FS
24	2		*FRONT BONNET CARBON FIBRE STICKER	Burnt	200.00 FS	*200.00 FS
25	1		*MICHELIN TYRE (235/40R18) (FRONT RH) (40%)	Burnt	270.00 FS	*108.00 FS

F=Franchise part, S=SpcNett, L=ListItemDisc.

Sub Total (S\$)	7,715.00	6,723.00
- List Item Discount on L Items 10.00/10.00% (S\$)	654.50	571.50
Total Parts (S\$)	7,060.50	6,151.50

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	RESPRAY PAINT ROOF PANEL, FRONT BUMPER, FRONT RH FENDER, FRONT RH DOOR, REAR RH DOOR & REAR RH FENDER.	New	1,800.00	1,100.00
2	PANEL BEAT & REPLACEMENT FOR THE ABOVE REPAIR.	New	800.00	600.00
3	TOWING CHARGE (FLATBED) (*Check)	New	120.00	0.00
Gross Labour Cost (S\$)			2,720.00	1,700.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >