

ASS. REC. BY:

REF: es/msg19001410/UTd3

Special Instruction:

Surveyor: M. M. M. M.

ASSIGNMENT (Office)

From (Person): Katherine Wong of MSIGDate/Time: 21/11/19 @ 4:21pm

Estimated Cost: _____ Bill to: _____

OD / IT / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SKC 1774Y Insured: XE 3033Aat Workshop m/s Zoom Autowerks Tel: 94507920of 15 Kaki Bukit Rd 4 # 01-53Policy No: 28967616 MEC Claim No: 582770

Sum Insured: _____ Excess: _____

Make of Veh: _____ D.O.A. 17/01/2019
(Client's Record)

CA / REV / REP. / REV 24 HRS (up)

H.O.D. Endorsement: _____

Date/Time: 10:40am @ 20/11/19 Person Contacted: Elin Vehicle: IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	SKC 1774Y - NA / INC 19001212 / 24
	XE 3033A - NA / INC 19001212 / 24
23/11/2019: 14:03pm	revert compose mail pending estimate.

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: SKC1774

at Workshop m/s 200M

of _____

Insured: _____

Policy No: _____

Claims No: _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: 326.

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 6 days Res: Yes or No

Lum Sum: 20 % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

6948H
Vehicle: IN / OUT

Veh No: SKC1774 /r Regn: 7. 11

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prima Mover /

Truck / Trailer or CA /

Make: Volkswagen New Golf 1390

Colour: Black A/C: Insured / Std / NI / NA

Sp. Reading 145687 T/Radio: Insured / Std / NI / NA

Eng No: _____

C/Nr: WVWZZZ1K2CW001946

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 225/40 R18

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front: _____ Rear: 6

R/Bal: 6 mm R/Bal: 6 mm

L/Bal: 6 mm L/Bal: 6 mm

D.O.A. 12/1/19 D.O.I. 22/1/19

Survey held at _____

Des. of Damages: Fnt / Rear / O/S / N/S / U/C / Rooftop or

0/S Body

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	4TA 19876 2.5 yrs. 2009 net 1224
	del door 1725.17 new door 1725.17
25/1/19 4/5	\$8000 confirmed w/le Elin Cred: 10841.01 : 55%
RECEIVED 26 FEB 2019	

Date/Time, File Pass to? ☐ : Preli. Report

1) 26/2 Typst ☒ : Final Report

Date/Time, File Return to? _____

2) _____

Report Format: TP

Lum Sum / I.B.I: (\$ 8000)

Days Of Repair: 6

Resurvey No. of Trip: 1

Add Fee: ☐ : Site Insp (\$ _____) ☐ : Interview (\$ _____)

☐ : Tech. Invs (\$ _____) ☐ : Weekend (\$ _____)

Survey Fee: 100

Transportation: _____

Photos: _____

Others: _____

TOTAL: _____

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	21 Jan 2019		21 Jan 2019 16:21 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	SAMWOH CORPORATION PTE. LTD., Co. Reg. No.: 1985022022		
Main Claimant:	Mohamed Hanafiah Bin Abu Bakar, ID: S1586948H		
Vehicle Reg. No.:	SKC1774Y	Date of Loss:	17/01/2019 16:00 - :59 [89 Months and 21 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 582770	Policy/Cover Note No.:	28967616MKC (Comprehensive) Coverage: 03/06/2018 - 02/06/2019
Vehicle Reg. No. (Insured):	XE3033A	Policy No. (Claimant):	
		Excess:	
Repairer:	Zoom Autowerks Pte Ltd (HQ) 15 Kaki Bukit Road 4, #01-53, 417808 Kaki Bukit - Tel:		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Katherine Wong Chew Shong - 6594 2544]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 22/01/2019]		
Adj Asg. Remarks:	OI not reported, SJE agree - LKK, Contact : Elin Cai at 9450 7920.		

ASSOCIATED MAIL RECEIVED

There are no mail for this case.

[View All](#)

[Compose Case Mail](#)

ALL ASSOCIATED TASKS

[View All](#)

[Search Tasks](#)

[Create New Task](#)

[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

View Sent Message

This mail is associated with :

***SKC1774Y (582770)
[XE3033A]**

TP

Mohamed Hanafiah Bin Abu Bakar
Jan 17 2019 4:00PM
[SAMWOH CORPORATION PTE. LTD.]
Zoom Autowerks Pte Ltd

[Resend](#) [View Recipients](#) [Print Message](#) [Delete Message](#) [Forward](#)

From LKK Auto Consultants Pte Ltd (LKK_HQ), sent on 23/01/2019 14:03 PM.
To katherine_wong@sg.msg-asia.com
Subject SKC1774Y (582770) [XE3033A]

Dear Sir/Madam,

Please be informed that we have inspected the vehicle SKC 1774X on 22/1/2019
We are pending estimate from repairer.

Regards,

Denise Tay | Case Handler
LKK Auto Consultants Pte Ltd

DOCUMENTS SUMMARY

There are no documents.

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	6948H
Vehicle Details	
Vehicle No.:	SKC1774Y
Vehicle to be Exported:	No
Intended Deregistration Date:	19 Jan 2020
Vehicle Make:	VOLKSWAGEN
Vehicle Model:	NEW GOLF 1.4 AT 5K13G5
Primary Colour:	Black
Manufacturing Year:	2011
Engine No.:	CAX902559
Chassis No.:	WVWZZZ1KZCW001946
Maximum Power Output:	90.0 kW (120 bhp)
Open Market Value:	\$22,264.00
Original Registration Date:	27 Jul 2011
First Registration Date:	27 Jul 2011
Transfer Count:	1
Actual ARF Paid:	\$22,264.00 11132
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	26 Jul 2021
PARF Rebate Amount:	\$12,245.00
Intended COE Rebate Details	
COE Expiry Date:	26 Jul 2021
COE Category:	A - Car (1600cc & below)
COE Period(Years):	10
QP Paid:	\$50,244.00
COE Rebate Amount:	\$7,631.00
Total Rebate Amount:	\$19,876.00
Message	

The information contained herein is correct as at 23 Jan 2019

OK

New Cars

Used Cars

Sell My Car

Directory

Products

Insurance

Articles

F

RENEW
YOUR COE1.99%*P.A
ONLY

MEMBER

golf

Price Range

Depreciation

2011

Vehicle Type



Home » Used Cars » Prem Roy Motoring » Volkswagen Golf 1.4A TSI

Resources

Car Buying

Car Selling

Car Ownership

Car Aftermarket

On The Move

Lifestyle

Volkswagen Golf 1.4A TSI

Overview

Financial

Insurance

Accessories

Similar

Research

Photos

Map



COMPLETE CAR TRADE S

Add to Shortlist

Add to Compare

Add a Note

Report Error

More Actions

Share

Car Details

Price	\$31,900	
Depreciation	\$8,990 /yr View models with similar depreciation	?
Reg Date	09-May-2011 (2yrs 3mths 15days COE left)	
Manufactured	2011	?
Mileage	147,000 km (19.1k /yr)	
Transmission	Auto	
Engine Cap	1,390 cc	
Road Tax	\$620 /yr	?
Power	90.0 kW (120 bhp) View specs of the Volkswagen Golf GTI (2003-2009)	
Curb Weight	1,241 kg	?
Features	Smooth Powerful And Fuel Efficient 1.4L Twincharged Engine, 7 Speed DSG Auto Transmission, Paddle Shifters, Reverse Sensors, Push/Start Stop.	
Accessories	Leather Seats, Rear Aircon, Stock Rims And Tires, Factory MP3 Audio System With Multi Function Steering Control, Fog Lamps, Retractable Side Mirrors.	
Description	Only 50 Units Of This Rabbit Version Has Been Release By VW. Only One In The Market. Single Owner! Reliable And Problem Free Unit. No Repairs Needed. Practical And Affordable For For Daily Driving. Good Fuel Consumption. Very Sporty Paintwork Matched With Its Black Leather Interior. All Wear And Tear Replaced With Receipts To Prove. Loans N Trade In Avail, Optional Warranty Available, View By Appt!	
COE	\$40,123	?



Location Map

Price An

Seller Information

Company

Prem



» deale

» 143 v

availabl

Address

9 Tagor

Search

Location

9@Tag-

Compare

Commercial Vehicle

BRAND NEW FLEET
AVAILABLE FOR
RENT / LEASE

NISSAN NV200 \$1,200
NISSAN CASHSTAR \$1,200

CALL: 8482 3003
EMAIL: sales@panpacificleasing.com.sg

New Cars

Used Cars

Sell My Car

Directory

Products

Insurance

Articles

F

RENEW
YOUR COE1.99%*P.A
ONLYM
S/M

golf

Price Range

Depreciation

2011

Vehicle Type



Home » Used Cars » Hou Auto » Volkswagen Golf 1.4A TSI

Resources

Car Buying

Car Selling

Car Ownership

Car Aftermarket

On The Move

Lifestyle

Car Leasing

Leasing

YOUR PREFERRED CAR LEASING
OPTION IN SINGAPORE

6769 7117 8720 5000 8720 8000

Volkswagen Golf 1.4A TSI

Overview

Financial

Insurance

Accessories

Similar

Research

Photos

Map

Add to Shortlist

Add to Compare

Add a Note

Report Error

More Actions

Share

Car Details

Price	\$33,800	
Depreciation	\$8,570 /yr View models with similar depreciation	?
Reg Date	16-Sep-2011 (2yrs 7mths 23days COE left)	
Manufactured	2011	?
Mileage	85,000 km (11.6k /yr)	
Transmission	Auto	
Engine Cap	1,390 cc	
Road Tax	\$620 /yr	?
Power	90.0 kW (120 bhp) View specs of the Volkswagen Golf GTI (2003-2009)	
Curb Weight	1,241 kg	?
Features	-	
Accessories	-	
Description	Well Kept Drives Well. Lady Owner Upgrading. Loan And Trade In Welcome. Call For Viewing.	
COE	\$51,000	?
OMV	\$22,244	?
ARF	\$22,244	?
Dereg Value	\$26,844 as of today (change)	?
No. of Owners	2	?
Type of Veh	Hatchback	
Category	PARF Car	
Availability	Available	

Add to Shortlist

Add to Compare

Add a Note

Posted on: 18-Jan-2019 | Last Updated on: 22-Jan-2019



Location Map

Price An

Seller Information

Company	Hou A » deale » 4 veh
Address	1 Kaki I Search
Location	Autoba
Office No	94574!
Contact Person(s)	Black

Useful Services

Afraid of lerr
this car eval

Compare

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	18/01/2019 16:55
Date Of Accident	17/01/2019 16:50
Exact Location Of Accident	PIE (TUAS) BEFORE ANAK BUKIT FLYOVER
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKC1774Y
Insured/Policyholder	
Name Of Registered Owner	MOHAMED HANAFIAH BIN ABU BAKAR
NRIC No	S1586948H
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-97474014
Alternative Phone No	OFFICE-97474014

Vehicle Particulars

Manufacturer	VOLKSWAGEN
Model	NEW GOLF 1.4 AT 5K13G5
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5098928070
Cover Note Number	

Driver

Name of Driver	MUHAMMAD RIFDI BIN MOHAMED HANAFIAH
NRIC No	S9524467Z
Date Of Birth	08/07/1995
Occupation	INDOOR
Date Of Driving Pass	22/05/2018
Driving Experience	0 YEAR AND 7 MONTH
Gender	MALE
Mobile Number	(LOCAL) +65-97474014
Fax Number	
Contact Number	OFFICE-97474014
EMail Address	NOEMAIL

Address	BLK 702 BEDOK RESERVOIR ROAD #07-3550
Postcode	470702
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	CHILDREN
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - CHANGE/CROSS LANE
Weather Conditions	DRIZZLING
Road Surface	WET

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO STATEMENT.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	XE3033A
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	1

Accident Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to regulate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodging of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**
I understand, acknowledge, agree and consent that:
 - (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail package(s)); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes").
 - (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
 - (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agent(s) (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
 - (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
 - (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated; or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:

Driver's Signature
(if driver is not the policyholder)
Date & Time:


Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Accident Sketch Plan

SKETCH PLAN

VEHICLE A: SKC 1774Y

VEHICLE B: YE 3033A / TPD 442611.



Vehicle B, before impact, entered from the right

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On the stated date & time, I, vehicle 'A', SKC 1774Y, was travelling straight along the stated venue. Suddenly, vehicle 'B', YE 3033A, cut into my lane and collided onto my vehicle's right portion. He then continued to further went on for a couple of metres.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

[Signature]
 Policyholder's Signature
 Date & Time:

[Signature]
 Driver's Signature
 (If driver is not the policyholder)
 Date & Time:

[Signature]
 Reporting Centre Person's Signature
 Name:
 NRIC/ID No.:

21 JANUARY 2019

REG NO.: SKC 1774 Y
MAKE/MODEL: VOLKSWAGEN GOLF

Ref. Authorised
d/s = 8600/-
22/1/19
take photo. After rep-
6 day.

ESTIMATED REPAIR COST FOR THE VEHICLE MENTIONED ABOVE

QTY	DESCRIPTION	AMT(\$)
	<u>LIST ITEMS</u>	
1	Front door -R/H	1,645.50
1	Front door glass outer moulding	56.20
1	Front door inner board	835.40
1	Front door lock	304.20
1	Front door outer handle	455.00
1	Front door regulator	415.00
1	Front door regulator motor	615.00
1	Front door rubber	193.10
1	Front door side mirror	691.60
1	Rear door -R/H	1,589.60
1	Rear door glass outer moulding	86.90
2	Rear door hinges	208.00
1	Rear door lock	312.00
1	Rear door outer handle	484.00
1	Rear door regulator	558.00
1	Rear door regulator motor	615.00
1	Rear door rubber	220.00
1	Rear door inner board	932.00
1	Rear wheel rim -R/H	1,250.00
1	Rear wheel hub with bearing	677.00
1	Rear shock absorber	456.50
1	Rear knuckle arm	652.00
1	Rear upper arm	324.20
1	Rear centre arm	356.00
1	Rear lower arm	452.20
1	Tie rod end	147.00
1	Rear bumper	935.00
1	Rear bumper clip (1 set)	55.00
1	Rear bumper side retainer	68.50
1	Rear taillamp -R/H	389.00
		15,978.90
	Less 10%	1,597.89
		14,381.01

P. 882479
10%
7969.31

SPECIAL NETT ITEMS

1	Rear tyre	\$ su	450.00 X
		\$	450.00

S/N LABOUR CHARGES

2	To remove, replaced damaged lamps and check up rear wiring.	\$	80.00 30
3	To remove and refit inner garnishes.	\$	180.00 80
4	To remove and refit fuel tank assembly with all attachments.	\$	150.00 60
5	To remove and refit rear undercarriage.	\$	400.00 120
6	To conduct wheel alignment.	\$	150.00 60
7	To remove, replace doors & damaged parts, transfer all fittings to new door.	\$	350.00 120
8	To apply undercoating.	\$	200.00 80
9	Panel beating.	\$	1,600.00 800
10	To re-spray painting on the affected areas.	\$	1,500.00 1000
		\$	4,610.00

GRAND TOTAL :

1076931.
864544

\$ 19,441.01

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	21 Jan 2019		21 Jan 2019 16:21 Edit Adj Rpt	S\$8,600.00 Edit Estimates	S\$8,600.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	SAMWOH CORPORATION PTE. LTD. , Co. Reg. No.: 198502202Z								
Main Claimant:	Mohamed Hanafiah Bin Abu Bakar , ID: S1586948H								
Vehicle Reg. No.:	SKC1774Y	Date of Loss:	17/01/2019 16:00 - :59 [89 Months and 21 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 582770	Policy/Cover Note No.:	28967616MKC (Comprehensive) Coverage: 03/06/2018 - 02/06/2019						
Vehicle Reg. No. (Insured):	XE3033A	Policy No. (Claimant):							
		Excess:							
Repairer:	Zoom Autowerks Pte Ltd (HQ) 15 Kaki Bukit Road 4, #01-53, 417808 Kaki Bukit - Tel:								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Katherine Wong Chew Shong - 6594 2544]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MARCUS CHUA] ... [Imm.Advice due 22/01/2019]								
Adj Asg. Remarks:	OI not reported, SJE agree - LKK, Contact : Elin Cai at 9450 7920.								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SKC1774Y (582770)**
[XE3033A]
TP
Mohamed Hanafiah Bin Abu Bakar
Jan 17 2019 4:00PM
[SAMWOH CORPORATION PTE. LTD.]
Zoom Autowerks Pte Ltd

Upload Documents Upload Photos Compose New Letter			View View in Browser	
Assessment Reports			1 per page	☒
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	25/01/19 15:20	Accident Statement Addm. #1 From: SC - Reg. No: XE3033A, Claimant: SAMWOH CORPORATION PTE LTD	 Load HTM	
Photos/Images			3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	22/01/19 18:05	General View	 Load JPG	☒
2	22/01/19 18:05	General View	 Load JPG	☒
3	22/01/19 18:05	General View	 Load JPG	☒
4	22/01/19 18:05	General View	 Load JPG	☒
5	22/01/19 18:05	General View	 Load JPG	☒
6	22/01/19 18:05	General View	 Load JPG	☒
7	22/01/19 18:05	General View	 Load JPG	☒
8	22/01/19 18:05	General View	 Load JPG	☒
9	22/01/19 18:05	General View	 Load JPG	☒
10	22/01/19 18:05	General View	 Load JPG	☒
11	22/01/19 18:05	General View	 Load JPG	☒
12	22/01/19 18:05	General View	 Load JPG	☒
13	22/01/19 18:05	General View	 Load JPG	☒
14	22/01/19 18:05	General View	 Load JPG	☒
15	22/01/19 18:05	General View	 Load JPG	☒
16	22/01/19 18:05	General View	 Load JPG	☒
17	22/01/19 18:05	General View	 Load JPG	☒
18	22/01/19 18:05	General View	 Load JPG	☒
19	22/01/19 18:05	General View	 Load JPG	☒
20	22/01/19 18:05	General View	 Load JPG	☒
21	22/01/19 18:05	General View	 Load JPG	☒
22	22/01/19 18:05	General View	 Load JPG	☒
23	22/01/19 18:05	General View	 Load JPG	☒
24	22/01/19 18:05	General View	 Load JPG	☒
25	22/01/19 18:05	General View	 Load JPG	☒
26	22/01/19 18:05	General View	 Load JPG	☒
27	22/01/19 18:05	General View	 Load JPG	☒
28	22/01/19 18:05	General View	 Load JPG	☒
29	22/01/19 18:05	General View	 Load JPG	☒
30	22/01/19 18:05	General View	 Load JPG	☒
31	22/01/19 18:05	General View	 Load JPG	☒
32	22/01/19 18:05	General View	 Load JPG	☒
33	22/01/19 18:05	General View	 Load JPG	☒

Assessment Reports			1 per page	☒
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
34	22/01/19 18:05	General View		☒
35	22/01/19 18:05	General View		☒
36	22/01/19 18:05	General View		☒
37	22/01/19 18:05	General View		☒
38	22/01/19 18:05	General View		☒
39	22/01/19 18:05	General View		☒
40	22/01/19 18:05	General View		☒
41	22/01/19 18:05	General View		☒
42	22/01/19 18:05	General View		☒
43	22/01/19 18:05	General View		☒
44	22/01/19 18:05	General View		☒
45	22/01/19 18:05	General View		☒
46	22/01/19 18:05	General View		☒
47	22/01/19 18:05	General View		☒
48	22/01/19 18:05	General View		☒
49	22/01/19 18:05	General View		☒
50	22/01/19 18:05	General View		☒
51	22/01/19 18:05	General View		☒
52	22/01/19 18:05	General View		☒
53	22/01/19 18:05	General View		☒
54	22/01/19 18:05	General View		☒
55	22/01/19 18:05	General View		☒
56	22/01/19 18:05	General View		☒
57	22/01/19 18:05	General View		☒
58	22/01/19 18:05	General View		☒
59	22/01/19 18:05	General View		☒
60	22/01/19 18:05	General View		☒
61	22/01/19 18:05	General View		☒
62	22/01/19 18:05	General View		☒
63	22/01/19 18:05	General View		☒
64	22/01/19 18:05	General View		☒
65	22/01/19 18:05	General View		☒
66	22/01/19 18:05	General View		☒
67	22/01/19 18:05	General View		☒
68	22/01/19 18:05	General View		☒
69	22/01/19 18:05	General View		☒
70	22/01/19 18:05	General View		☒
71	23/01/19 17:13	Reinspection Photo		☒
72	23/01/19 17:13	Reinspection Photo		☒
73	23/01/19 17:13	Reinspection Photo		☒
74	23/01/19 17:13	Reinspection Photo		☒
75	23/01/19 17:13	Reinspection Photo		☒
76	23/01/19 17:13	Reinspection Photo		☒
77	23/01/19 17:13	Reinspection Photo		☒
78	23/01/19 17:13	Reinspection Photo		☒
79	23/01/19 17:13	Reinspection Photo		☒
80	23/01/19 17:13	Reinspection Photo		☒
81	23/01/19 17:13	Reinspection Photo		☒
82	23/01/19 17:13	Reinspection Photo		☒
83	23/01/19 17:13	Reinspection Photo		☒

Assessment Reports			1 per page	☒
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
84	23/01/19 17:13	Reinspection Photo		☒
85	23/01/19 17:13	Reinspection Photo		☒
86	23/01/19 17:13	Reinspection Photo		☒
87	23/01/19 17:13	Reinspection Photo		☒
88	23/01/19 17:13	Reinspection Photo		☒
89	23/01/19 17:13	Reinspection Photo		☒
90	23/01/19 17:13	Reinspection Photo		☒
91	23/01/19 17:13	Reinspection Photo		☒
92	23/01/19 17:13	Reinspection Photo		☒
93	23/01/19 17:13	Reinspection Photo		☒
94	23/01/19 17:13	Reinspection Photo		☒
95	23/01/19 17:13	Reinspection Photo		☒
96	23/01/19 17:13	Reinspection Photo		☒
97	23/01/19 17:13	Reinspection Photo		☒
98	23/01/19 17:13	Reinspection Photo		☒
99	23/01/19 17:13	Reinspection Photo		☒
100	23/01/19 17:13	Reinspection Photo		☒
101	23/01/19 17:13	Reinspection Photo		☒
102	23/01/19 17:13	Reinspection Photo		☒
103	23/01/19 17:13	Reinspection Photo		☒
104	23/01/19 17:13	Reinspection Photo		☒
105	23/01/19 17:13	Reinspection Photo		☒
106	23/01/19 17:13	Reinspection Photo		☒
107	23/01/19 17:13	Reinspection Photo		☒
108	23/01/19 17:13	Reinspection Photo		☒
109	23/01/19 17:13	Reinspection Photo		☒
110	23/01/19 17:13	Reinspection Photo		☒
111	23/01/19 17:13	Reinspection Photo		☒
112	23/01/19 17:13	Reinspection Photo		☒
113	23/01/19 17:13	Reinspection Photo		☒
114	23/01/19 17:13	Reinspection Photo		☒
Documentation			1 per page	☒
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	21/01/19 13:39	PRI from Zoom Autowerks Pte Ltd		☒
2	21/01/19 13:39	SKC1774Y E-file report		☒
3	21/01/19 13:39	Survey Agree on SJE - LKK		☒

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
Show Remarks To: ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.			

LKK Auto Consultants Pte Ltd (Co.Reg.No.199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG19001410/UTD3Q2

Date: 27/02/2019

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: 28967616MKC

Claimant Vehicle No : SKC1774Y

Insured Vehicle No : XE3033A

Date of Loss: 17/01/2019

Nature of Claim: TP

Claim No: 582770

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SKC1774Y

Make & Model: VOLKSWAGEN NEW GOLF 5K13G5, 1.4 (A)

Engine No: CAX902559

Reg. Date: 27/07/2011 (Man. Year: 2011)

Chassis No: VVWZZZ1KZCW001946

Colour: Black

Odometer: 145681 km

Engine Capacity: 1390 cc

Market Value/New Car

Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes Footbrake (Serviceable):

Yes

Handbrake (Serviceable): Yes Engine Modification:

No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/40 R18

Rear Tyre Size: 225/40 R18

Front Left Side: Pirelli 6 mm

Rear Left Side: Pirelli 6 mm

Front Right Side: Pirelli 6 mm

Rear Right Side: Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	14,831.01	8,419.31	6,411.70	43.23
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,610.00	2,350.00	2,260.00	49.02
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	19,441.01	10,769.31	8,671.70	44.61
Approved Total (Overridden) (S\$)		8,600.00		
Nett Amount (S\$)	19,441.01	8,600.00	10,841.01	55.76

INSPECTION

Date of Assignment: 21/01/2019

Date Inspected: 22/01/2019 Inspected At:

Zoom Autowerks Pte Ltd (HQ)
15 Kaki Bukit Road 4, #01-53
Singapore 417808

Estimated Period of Repair: 6.0 days

Adjuster: MARCUS CHUA

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 26 Feb 2019)
Parts:	144	VOLKSWAGEN NEW GOLF 5K13G5 1.4 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKC1774Y)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT DOOR -R/H	Badly Dented	1,645.50 FL	*1,645.50 FL
2	1		*FRONT DOOR GLASS OUTER MOULDING	Bent	56.20 FL	*56.20 FL
3	1		*FRONT DOOR INNER BOARD	Deformed / Cracked	835.40 FL	*835.40 FL
4	1		*FRONT DOOR LOCK	Twisted/ Jammed	304.20 FL	*295.30 FL
5	1		*FRONT DOOR OUTER HANDLE	Cut	455.00 FL	*267.30 FL
6	1		*FRONT DOOR REGULATOR	Bent	415.00 FL	*415.00 FL
7	1		*FRONT DOOR REGULATOR MOTOR	Serviceable	615.00 FL	*- FL
8	1		*FRONT DOOR RUBBER	Necessary	193.10 FL	*193.10 FL
9	1		*FRONT DOOR SIDE MIRROR (CRACKED)	Not Consistent With The Impact	691.60 FL	*- FL
10	1		*REAR DOOR GLASS OUTER MOULDING	Bent	86.90 FL	*86.90 FL
11	2		*REAR DOOR HINGES	Not Necessary	208.00 FL	*- FL
12	1		*REAR DOOR LOCK	Twisted / Jammed	312.00 FL	*292.30 FL
13	1		*REAR DOOR OUTER HANDLE	Cut	484.00 FL	*267.30 FL
14	1		*REAR DOOR REGULATOR	Bent	558.00 FL	*450.50 FL
15	1		*REAR DOOR REGULATOR MOTOR	Not Necessary	615.00 FL	*- FL
16	1		*REAR DOOR RUBBER	Necessary	220.00 FL	*188.50 FL
17	1		*REAR DOOR INNER BOARD	Cracked	932.00 FL	*799.40 FL
18	1		*REAR WHEEL RIM -R/H	Cut / Bent	1,125.00 FS	*450.00 FS
19	1		*REAR WHEEL HUB WITH BEARING	Damaged	677.00 FL	*453.69 FL
20	1		*REAR SHOCK ABSORBER	Not Necessary	456.50 FL	*- FL
21	1		*REAR KNUCKLE ARM	Serviceable	652.00 FL	*- FL
22	1		*REAR UPPER ARM	Not Necessary	324.20 FL	*- FL
23	1		*REAR CENTRE ARM	Not Necessary	356.00 FL	*- FL
24	1		*REAR LOWER ARM	Not Necessary	452.20 FL	*- FL
25	1		*TIE ROD END	Not Necessary	147.00 FL	*- FL
26	1		*REAR BUMPER	Cut	935.00 FL	*895.30 FL
27	1		*SET REAR BUMPER CLIP	Necessary	55.00 FL	*55.00 FL
28	1		*REAR BUMPER SIDE RETAINER	Bent	68.50 FL	*68.50 FL
29	1		*REAR TAILLAMP -R/H	Not Necessary	389.00 FL	*- FL
30	1		*REAR TYRE	Serviceable	450.00 FS	*- FS
31	1		*REAR DOOR -R/H	Badly Dented	1,589.60 FL	*1,589.60 FL

F=Franchise part. S=SpcNett. L=ListItemDisc

Sub Total (\$\$)	16,303.90	9,304.79
- List Item Discount on L Items 10.00/10.00% (\$\$)	1,472.89	885.48
Total Parts (\$\$)	14,831.01	8,419.31

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE, REPLACED DAMAGED LAMPS AND CHECK UP REAR WIRING	New	80.00	30.00
2	TO REMOVE AND REFIT INNER GARNISHES	New	180.00	80.00
3	TO REMOVE AND REFIT FUEL TANK ASSEMBLY WITH ALL ATTACHMENTS	New	150.00	60.00
4	TO REMOVE AND REFIT REAR UNDERCARRIAGE	New	400.00	120.00
5	TO CONDUCT WHEEL ALIGNMENT	New	150.00	60.00
6	TO REMOVE,REPLACE DOORS & DAMAGED PARTS ,TRANSFER ALL FITTINGS TO NEW DOOR	New	350.00	120.00
7	TO APPLY UNDERCOATING	New	200.00	80.00
8	PANEL BEATING	New	1,600.00	800.00
9	TO RE-SPRAY PAINTING ON THE AFFECTED AREAS	New	1,500.00	1,000.00
Gross Labour Cost (S\$)			4,610.00	2,350.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >