

ASS. REC. BY:

REF: 033/MSG19001411/Bcd3⁵⁷ Special InstructionSurveyor:
Mennan

Mr. Jim

ASSIGNMENT (Office)

From (Person):

Monica Chung

of

MSIG

Date/Time 22/11/19 @ 10.04am

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SKL 390E

Insured:

XD7868L

at Workshop m/s

Black Eagles

Tel:

9647 8331

of

25 kaki Bukit Rd 4 # 05-80

Policy No:

28687267

Claim No:

582604

Sum Insured:

Excess:

Make of Veh:

D.O.A.

16/01/2019

(Client's Record)

CA / REV / REP. / REV 24 HRS ^{up}

H.O.D. Endorsement:

Date/Time:

10:51am @ 22/11/19

Person Contacted:

Mr. Ng

Vehicle IN/OUT

Date/Time

Action/Instruction (X) Estimate

SKL 390E - X

XD 7868L - X

Dismantle: 28/11/19

After repair: 28/2/2019

REF:

MSIC

ASSIGNMENT

From:

Date: 22/1/19

Veh No:

SKL 320E

Yr Regn:

25/2/2013

Estimated Cost:

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

Truck / Trailer or

To Inspect Vehicle No:

SKL 320E

Make:

Toyota Hilux

C.C. 177

at Workshop m/s

25 Koki Bukit Rd 1 # 05-80

Colour:

white

A/C: Insured / Std / NI / NA

of

Black Eagles

Sp. Reading

216.725

T/Radio: Insured / Std / NI / NA

Insured:

Eng/No:

2ER1262042

Policy No.

C/No:

ZGE20016416

Claims No.

Gen. Cond: Good / Fair / Poor / Burnt

Sum Insured:

Excess:

Steering: Inorder / Jammed / Leaked / Burnt or

(Client's Record)

Brake: Inorder / Jammed / Leaked / Burnt or

Make of Veh:

Modi: Nil / S/Rim / STD A/Rim or

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

7

days

Res.: Yes or No

Lump Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Tyre Size:

F:

195/65R5

R:

195/65R5

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

BS-Front / Continental

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

16/1/19

D.O.I.

22/1/19

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Range 8,000p - 9,000p

[Signature]
8/4/2019

MV 58,000/2

PV 48,134/2

NV 3,866/2

[Signature]
8/4/19

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair: 7

Resurvey No. of Trip: 2

Survey Fee:

Transportation:

) \$ + RS.) \$

) Photos

) Others

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Invs (\$

☐

Weekend (\$

Report Format:

PRS

Lump Sum / I.B.I. (\$))

TOTAL

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	17 Jan 2019		22 Jan 2019 10:04 Assign				New Assignment Cancel Case

[Main](#)
[Reference](#)
[Claim Details](#)
[Documents](#)
[Show All](#)

CLAIM SUBFOLDER DETAILS

[\[Created by insurer\]](#)

Insured:	SAMWOH RESOURCES PTE LTD , Co. Reg. No.: 199105225W		
Main Claimant:	BLACK EAGLE RENTAL LLP , Co. Reg. No.: T17LL1043L		
Vehicle Reg. No.:	SKL390E	Date of Loss:	16/01/2019 14:00 - :59
Claim Type:	TP / 582604	Policy/Cover Note No.:	28607267 (Comprehensive) Coverage: 17/10/2018 - 16/10/2019
Vehicle Reg. No. (Insured):	XD7868L	Policy No. (Claimant):	
		Excess:	
Repairer:	Black Eagles Auto Pte Ltd (HQ) 25 Kaki Bukit Road, #05-80 Synergy Building, 417800 Kaki Bukit - Tel:		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Monica Chung Pei Zhen - 6594 2552]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 23/01/2019]		
Driver/Custodian (Insured):	YEO CHIANG TIONG (), NRIC: S2742792H, Tel: +6598928244		
Adj Asg. Remarks:	on WP. LIAB 100%. SJE DISAGREE APPOINT LKK. PLS CONTACT Mr Ng Yuze (h/p: 9647 8331)		

ASSOCIATED MAIL RECEIVED

[View All](#)
[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)
[Search Tasks](#)
[Create New Task](#)
[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	17/01/2019 12:40
Date Of Accident	16/01/2019 16:55
Exact Location Of Accident	CHANGI SOUTH AVE 4
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKL390E
Insured/Policyholder	
Name Of Registered Owner	BLACK EAGLE RENTAL LLP
Co Reg No	T17LL1043L
Email Address	NAIMOTAI9912@GMAIL.COM
Mobile Phone No	
Alternative Phone No	OFFICE-90107743

Vehicle Particulars

Manufacturer	TOYOTA
Model	WISH
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE HIRE

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	YES
Policy Number	5098750063
Cover Note Number	DRIVO CLASSIC

Driver

Name of Driver	MOHAMAD RUSDI BIN MOHAMAD ROSHSAN
NRIC No	S8942282E
Date Of Birth	29/11/1989
Occupation	OUTDOOR
Date Of Driving Pass	27/05/2009
Driving Experience	9 YEARS AND 7 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-97208544
Fax Number	
Contact Number	
Email Address	NOEMAIL


Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name	MOHAMAD RUSDI BIN MOHAMAD ROSHSAN
Approximate Age	
Injuries Sustain	
Injured person in which vehicle?	SKL390E
Were seat belts worn?	
Was this injured conveyed to hospital by ambulance?	NO
Address	
Postcode	

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Refer to police report

Declaration

I/We declare the foregoing particulars are true in every respect.



17-01-19 / 12:27

Policyholder's Signature / Date & Time

17-01-19 / 12:27

Driver's Signature (If driver is not the policyholder) / Date & Time

Alan Tang (S098825)
Customer Care Executive
Motor Service Centre

Witnessed by Reporting Centre Personnel

Police Report



**SINGAPORE
POLICE FORCE**



G/20190117/7025

2 of 3

POLICE REPORT (NP299)

CONTINUATION OF REPORT

Report No. G/20190117/7025

try to shout at the front driver to warn him that i was at the rear of him but also useless as they believe he was busy using his walkie talkie communicating with his other friends.
After the incident i decide to go out from my vehicle and talk to the driver for his mistake and ask for more details, he was so incorporate and decided to move off. Before he move off i manage to get a picture of his driving licence.

Subjects Involved			
Suspect			
Person Name	Mr yeo cheng tong		
ID Type	OTHERS / S2742792H	Gender	Male
Race	Chinese	Language	English
Mobile No	98928244		
Victim			
Person Name	MOHAMAD RUSDI BIN MOHAMAD ROSHSAN		
ID Type	NRIC NO	ID No	S8942282E
Gender	Male	Age	29
Race	Pakistani	Language	English
Occupation	Lorry driver	Address Type	
Address	APT BLK 682A EDGEDALE PLAINS #03-753 SINGAPORE 821682		Mobile No 97208544
Is Informant A Victim?	Yes		

Signature Of Officer Recording The Report:

Not applicable

Signature Of Interpreter:

Not applicable

Officer In-Charge Of Case:

Authentication Stamp

Signature Of Informant:

The identity of the person making this report has been authenticated by SingPass. No signature is required.

Date/Time:

17/01/2019 13:26

Classification Of Case:

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Limited Liability Partnership
Owner ID:	1043L
Vehicle Details	
Vehicle No.:	SKL390E
Vehicle to be Exported:	No
Intended Deregistration Date:	08 Apr 2019
Vehicle Make:	TOYOTA
Vehicle Model:	WISH 1.8X A
Primary Colour:	White
Manufacturing Year:	2013
Engine No.:	2ZR1262049
Chassis No.:	ZGE200164116
Maximum Power Output:	106.0 kW (142 bhp)
Open Market Value:	\$19,628.00
Original Registration Date:	25 Sep 2013
First Registration Date:	25 Sep 2013
Transfer Count:	2
Actual ARF Paid:	\$19,628.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	24 Sep 2023
PARF Rebate Amount:	\$13,739.00
Intended COE Rebate Details	
COE Expiry Date:	24 Sep 2023
COE Category:	E - Open Category
COE Period(Years):	10
QP Paid:	\$80,000.00
COE Rebate Amount:	\$34,395.00
Total Rebate Amount:	\$48,134.00

The information contained herein is correct as at 08 Apr 2019

OK

avg dep 11,300/yr
94.5/km

MV 58,000/2
PV 48,134/2
NV 9,866/2

Termin
by 24/13



ANNOUNCING 88 Motor Trading

as sgCarMart Premium Dealer for the 5th Consecutive Year

88 汽车贸易

MOTOR TRADING

Post an Advertisement
Sell it yourself! Advertise it at just
\$58 until it's SOLD!

Post an Ad

Advertiser Login

Ways of Selling

BMW X3 Xdrive20i



Mint Condition Flawless PML Car
Under Warranty, Only Latest
Gen X3 In Market.
Direct Owner...StarAd

PRIME MOTOR & LEASING

(CHENGLONG CREDIT ENTERPRISES PTE LTD. GROUP OF COMPANIES)

With over 200 units of vehicles to choose from, ranging from all European to Japanese Makes.








Browse by Category

Sort by Date Posted 20 results/page

6 vehicles

Toyota Wish

Advanced Search

	Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
Search Selection	Toyota Wish		Any	Any	2013	Any	Any	Any	All
	Toyota Wish	1.8A Elegance	\$60,800	\$11,760 /yr	05-Aug-2013	1,798 cc	90,000 km	MPV	Available
One Owner Only. 100% Accident-Free. With Reverse Camera, Beautiful Pearl White. Nice And Clean Interior. Well Maintained By Previous Non Smoking Owner, Most Popular Japan Make MPV In The Market. Easy ...									
Posted: 06-Apr-2019 Tags: 2013 Toyota Wish, 2013 toyota wish, Toyota Wish, toyota wish, Toyota, Wish, wish, Used Toyota									
	Toyota Wish	1.8A Elegance	\$56,800	\$10,930 /yr	22-Jul-2013	1,798 cc	110,147 km	MPV	Available
Single Owner "Elegance" Model With Full Agent Service! 100% Accident-Free. Beautiful Silver Paintwork, Most Popular Japan MPV In The Market, Ultra Reliable And Fuel Saving, Immaculate Condition, Buy W...									
Posted: 05-Apr-2019 Tags: 2013 Toyota Wish, 2013 toyota wish, Toyota Wish, toyota wish, Toyota, Wish, wish, Used Toyota									
	Toyota Wish	1.8A Elegance	-	N.A	10-Jul-2013	1,798 cc	-	MPV	SOLD
Extended Warranty Available! Immaculately Maintained By Previous Owner! Flexible Loan Schemes Available! View To Believe Condition! Buy From Trustworthy Dealer And We Will Workout A Win Win Package Fo...									
Car Times Automobile Pte Ltd									
Posted: 30-Mar-2019 Tags: 2013 Toyota Wish, 2013 toyota wish, Toyota Wish, toyota wish, Toyota, Wish, wish, Used Toyota									
	Toyota Wish	1.8A	-	N.A	03-Jul-2013	1,798 cc	-	MPV	SOLD
1 Owner! Cheapest Depreciation In Market. No Repairs Needed At All. Full Agent Maintain. Low Maintenance Cost And Cheap Spare Parts. Excellent Fuel Saver For Daily Usage And Most Suitable For Family U...									
Posted: 26-Feb-2019 Tags: 2013 Toyota Wish, 2013 toyota wish, Toyota Wish, toyota wish, Toyota, Wish, wish, Used Toyota									
	Absorb Engine Noise & Enjoy Quieter Driving Absorbs engine noise, delivering a quieter listening environment in your vehicle & delivers high acoustic absorption. More info about this product								
	Toyota Wish	1.8A	-	N.A	22-Feb-2013	1,798 cc	-	MPV	SOLD
1 Owner! Cheap! No Scratches, Tip Top Condition, Looks, Feel And Drive Like New. Pre-purchase Inspection At Your Own Workshop Or STA Evaluation Available Prior To Your Purchase For A Total Peace Of Mi...									
Posted: 31-Jan-2019 Tags: 2013 Toyota Wish, 2013 toyota wish, Toyota Wish, toyota wish, Toyota, Wish, wish, Used Toyota									
	Toyota Wish	1.8A	-	N.A	23-Aug-2013	1,798 cc	-	MPV	SOLD
Elegant Beige MPV, Agent Unit, One Owner Only, Low Maintenance Cost, Very Well Maintained, Flexible In-House Loan Packages Available.									
Prime Motor & Leasing									
Posted: 29-Jan-2019 Tags: 2013 Toyota Wish, 2013 toyota wish, Toyota Wish, toyota wish, Toyota, Wish, wish, Used Toyota									

Save this search criteria, to get email alerts whenever a match is found.

Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
------	-------	-------	--------------	----------	---------	---------	----------	--------

For old advertisements, view Expired ads

20 results/page

Compare

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	17 Jan 2019		22 Jan 2019 10:04 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	SAMWOH RESOURCES PTE LTD, Co. Reg. No.: 199105225W		
Main Claimant:	BLACK EAGLE RENTAL LLP, Co. Reg. No.: T17LL1043L		
Vehicle Reg. No.:	SKL390E	Date of Loss:	16/01/2019 14:00 - :59 [63 Months and 22 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 582604	Policy/Cover Note No.:	28607267 (Comprehensive) Coverage: 17/10/2018 - 16/10/2019
Vehicle Reg. No. (Insured):	XD7868L	Policy No. (Claimant):	
		Excess:	
Repairer:	Black Eagles Auto Pte Ltd (HQ) 25 Kaki Bukit Road, #05-80 Synergy Building, 417800 Kaki Bukit - Tel:		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Monica Chung Pei Zhen - 6594 2552]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by Lim Teow Guan] ... [Imm.Advice due 23/01/2019]		
Driver/Custodian (Insured):	YEO CHIANG TIONG (), NRIC: S2742792H, Tel: +6598928244 Email:		
Adj Asg. Remarks:	on WP. LIAB 100%. SJE DISAGREE APPOINT LKK. PLS CONTACT Mr Ng Yuze (h/p: 9647 8331)		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SKL390E (582604)**

[XD7868L]

TP

BLACK EAGLE RENTAL LLP

Jan 16 2019 2:00PM

[SAMWOH RESOURCES PTE LTD]

Black Eagles Auto Pte Ltd

[Upload Documents](#)
[Upload Photos](#)
[Compose New Letter](#)
View
[View in Browser](#)

Video

1 per page



No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail	Print
1	21/01/19 15:53	Video - AccidentTP		Load MP4	

Assessment Reports

1 per page







No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail	Print
1	21/01/19 14:54	Accident Statement From:SC - Reg. No: XD7868L, Claimant: SAMWOH RESOURCES PTE LTD		Load HTM	












Photos/Images

3 per page



No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	08/04/19 16:52	General View		Load JPG	
2	08/04/19 16:52	General View		Load JPG	
3	08/04/19 16:52	General View		Load JPG	
4	08/04/19 16:52	General View		Load JPG	
5	08/04/19 16:52	General View		Load JPG	
6	08/04/19 16:52	General View		Load JPG	
7	08/04/19 16:52	General View		Load JPG	
8	08/04/19 16:52	General View		Load JPG	
9	08/04/19 16:52	General View		Load JPG	
10	08/04/19 16:52	General View		Load JPG	
11	08/04/19 16:52	General View		Load JPG	
12	08/04/19 16:52	General View		Load JPG	
13	08/04/19 16:52	General View		Load JPG	
14	08/04/19 16:52	General View		Load JPG	
15	08/04/19 16:52	General View		Load JPG	
16	08/04/19 16:52	General View		Load JPG	
17	08/04/19 16:52	General View		Load JPG	
18	08/04/19 16:52	General View		Load JPG	
19	08/04/19 16:52	General View		Load JPG	
20	08/04/19 16:52	General View		Load JPG	
21	08/04/19 16:52	General View		Load JPG	
22	08/04/19 16:52	General View		Load JPG	
23	08/04/19 16:52	General View		Load JPG	
24	08/04/19 16:52	General View		Load JPG	
25	08/04/19 16:52	General View		Load JPG	
26	08/04/19 16:52	General View		Load JPG	
27	08/04/19 16:52	General View		Load JPG	
28	08/04/19 16:52	General View		Load JPG	

Video			1 per page ▾	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
29	08/04/19 16:52	General View	 Load JPG	<input checked="" type="checkbox"/>
30	08/04/19 16:52	General View	 Load JPG	<input checked="" type="checkbox"/>
31	08/04/19 16:52	General View	 Load JPG	<input checked="" type="checkbox"/>
32	08/04/19 16:52	General View	 Load JPG	<input checked="" type="checkbox"/>
33	08/04/19 16:52	General View	 Load JPG	<input checked="" type="checkbox"/>
34	08/04/19 16:52	General View	 Load JPG	<input checked="" type="checkbox"/>
35	08/04/19 16:52	General View	 Load JPG	<input checked="" type="checkbox"/>
36	08/04/19 16:53	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
37	08/04/19 16:53	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
38	08/04/19 16:53	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
39	08/04/19 16:53	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
40	08/04/19 16:53	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
41	08/04/19 16:53	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
42	08/04/19 16:53	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
43	08/04/19 16:53	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
44	08/04/19 16:53	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
45	08/04/19 16:53	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
46	08/04/19 16:53	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
47	08/04/19 16:53	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
48	08/04/19 16:53	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
49	08/04/19 16:53	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
50	08/04/19 16:53	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
51	08/04/19 16:53	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
52	08/04/19 16:53	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
53	08/04/19 16:53	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
54	08/04/19 16:53	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
55	08/04/19 16:53	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
56	08/04/19 16:53	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
57	08/04/19 16:53	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
58	08/04/19 16:53	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
59	08/04/19 16:53	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
60	08/04/19 16:53	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
61	08/04/19 16:53	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
62	08/04/19 16:53	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
63	08/04/19 16:53	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
64	08/04/19 16:53	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
65	08/04/19 16:53	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
66	08/04/19 16:53	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
67	08/04/19 16:53	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
68	08/04/19 16:53	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
69	08/04/19 16:53	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
70	08/04/19 16:53	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
71	08/04/19 16:53	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
72	08/04/19 16:53	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
73	08/04/19 16:53	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
74	08/04/19 16:53	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
75	08/04/19 16:53	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
76	08/04/19 16:53	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>

Video			1 per page ▼	✓
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
77	08/04/19 16:53	Photographs of Damaged Parts	 Load JPG	✓
78	08/04/19 16:53	Photo After Spray	 Load JPG	✓
79	08/04/19 16:53	Photo After Spray	 Load JPG	✓
80	08/04/19 16:53	Photo After Spray	 Load JPG	✓
81	08/04/19 16:53	Photo After Spray	 Load JPG	✓
Documentation			1 per page ▼	✓
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	21/01/19 14:54	PRI From: SC - Reg. No: XD7868L, Claimant: SAMWOH RESOURCES PTE LTD	 Load PDF	
2	21/01/19 14:54	TP SKL390E E-REPORT From: SC - Reg. No: XD7868L, Claimant: SAMWOH RESOURCES PTE LTD	 Load PDF	
3	21/01/19 15:11	SJE DISAGREE	 Load PDF	
4	21/01/19 15:18	APPOINT LKK	 Load PDF	
5	22/01/19 11:05	PHOTO 1	 Load JPG	✓
6	22/01/19 11:05	PHOTO 2	 Load JPG	✓

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/MSG19001411/BCD3S2
Date: 11/04/2019

REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	28607267
Claimant Vehicle No :	SKL390E	Insured Vehicle No :	XD7868L
Date of Loss:	16/01/2019	Nature of Claim:	TP
		Claim No:	582604

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKL390E	Engine No:	2ZR1262049
Make & Model:	TOYOTA WISH, 1.8 (A)	Chassis No:	ZGE200164116
Reg. Date:	25/09/2013 (Man. Year: 2013)	Odometer:	216725 km
Colour:	White		
Engine Capacity:	1797 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Poor	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	195/65R15	Rear Tyre Size:	195/65R15
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Continental 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Continental 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment:	22/01/2019	
Date Inspected:	22/01/2019	Inspected At: Black Eagles Auto Pte Ltd (HQ) 25 Kaki Bukit Road, #05-80 Synergy Building Singapore 417800
Estimated Period of Repair:	7.0 days	

Adjuster: Lim Teow Guan**Manager:** CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$8,000.00 - \$9,000.00

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 10 Apr 2019)
Parts:	M1-MPV	TOYOTA WISH 1.8 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKL390E)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >