

ASS. REC. BY:

REF: CSB/AIG 9001419/Bedok Special Instruction:

Surveyor  
MamenMr. Jim  
Chin Lee Ying

## ASSIGNMENT (Office)

From (Person): Chin Lee Ying of AIG Date/Time: 22/1/19 @ 11.50am

Estimated Cost: \_\_\_\_\_ Bill to: \_\_\_\_\_

OD /  TP / WS / TP RES / OD RES / EVA / INV / MV / CSTo Inspect Vehicle No: SIG 4950B Insured: SLB9412Hat Workshop m/s Green Star Spray Painting Tel: 6546 3092of Blk 3011-Bedok North Ave 4 # 01-2004Policy No: \_\_\_\_\_ Claim No: 1704810644SG

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

Make of Veh: \_\_\_\_\_ D.O.A. 17/01/2019

(Client's Record)

CA / REV / REP. / REV 24 HRS <sup>lup?</sup> H.O.D. Endorsement: \_\_\_\_\_Date/Time: 1:50pm @ 22/1/19 Person Contacted: June Vehicle  IN /  OUT

Date/Time	Action/Instruction (X) Estimate
	SIG 4950B-CC4 / III 1702412 / Upa392 DuA: 16/12/2017
	SLB9412H-X
	Dismantle: 24/1/2019



**- PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURE...**

From: Chin, Lee-Ying  
To: assignments, Admin A  
Cc: Fong, Andy-SY  
Sent: 22/1/2019 11:50:51 AM

Attachments:  [Green Star - Pre-Repair Notice \(AIG\)\(SJK4950B\).pdf](#)

---

Hi LKK,

Kindly assist to survey.

Thanks.

Best Regards  
Lee Ying, Chin  
AIG  
Claims | AIG Asia Pacific Insurance Pte. Ltd.  
78 Shenton Way #08-16 Singapore 079120  
Tel +(65) 6419 1947  
[Lee-Ying.Chin@aig.com](mailto:Lee-Ying.Chin@aig.com) | [www.aig.sg](http://www.aig.sg)

**IMPORTANT NOTICE:**

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

# CROSSBORDERS LLC

Advocates & Solicitors | Commissioner for Oaths | Notary Public

Our Ref: AJ.tk.GS (SJG4950B)  
Your Ref: SLB9412H

22 January 2019

**AIG Asia Pacific Insurance Pte Ltd**  
78 Shenton Way  
#08-16 AIG Building  
Singapore 079120  
**Attn: Motor Claims Department**

BY FAX: 6415 3727 & EMAIL

**URGENT**

MAIN OFFICE  
133 NEW BRIDGE ROAD  
#23-03/04/05  
CHINATOWN POINT  
SINGAPORE 059413  
TEL: 6438 1323  
FAX: 6438 2313

BRANCH OFFICE  
1 JALAN BERSEH  
#03-12 NEW WORLD CENTRE  
SINGAPORE 209037

PLEASE SEND ALL  
CORRESPONDENCES TO  
THE MAIN OFFICE

WE DO NOT ACCEPT  
SERVICE BY FAX

Dear Sirs

**NOTICE TO INSURER TO CONDUCT PRE-REPAIR SURVEY**  
**CLAIMANT: FAST TRACK LIMO SERVICE**  
**TRAFFIC ACCIDENT ON 17 JANUARY 2019 AT 09:40 HRS ALONG AYE (1<sup>ST</sup> LANE), 5.5KM LP 501F INVOLVING VEHICLES NO. SJG4950B & SLB9412H & SHC7028P**

We are instructed by Fast Track Limo Service to notify you of a road accident on 17 January 2019 at about 09:40 hrs along AYE (1<sup>ST</sup> Lane), 5.5KM LP 501F involving our clients' vehicle registration number SJG4950B and vehicle registration number SLB9412H driven by your insured at the material time. A copy of the Singapore accident statement/traffic police report filed is enclosed.


As a result of the accident, our clients' vehicle has been damaged. Before our clients proceeds to repair the damaged vehicle, please let us know within 2 working days (excluding any intervening Saturday, Sunday and Public Holiday) of your receipt of this notice whether you or your insurer would like to conduct a pre-repair survey of the vehicle. If we do not receive any reply from you within the stipulated timeline, our clients shall proceed to repair the vehicle without further reference to you.

Please be informed that the said vehicle can be inspected at:

Venue: Green Star Spray Painting  
Address: Blk 3011 Bedok North Avenue 4  
#01-2004 Bedok Industrial Park E  
Singapore 489977  
Contact: Jane (6546 3092)

Please liaise with the above workshop directly.

Yours faithfully

  
Crossborders LLC

Email: [corene@crossbordersllc.com](mailto:corene@crossbordersllc.com) /  
[huiting@crossbordersllc.com](mailto:huiting@crossbordersllc.com)  
encs

**PLEASE LET US KNOW THE DATE  
OF THE PRE-REPAIR INSPECTION**

.....

CONFIDENTIALITY CAUTION  
THIS DOCUMENT IS FOR THE ADDRESSEE(S) ONLY AND MAY CONTAIN CONFIDENTIAL INFORMATION AND/OR MAY BE  
SUBJECT TO LEGAL PRIVILEGE. IF YOU HAVE RECEIVED THIS IN ERROR, PLEASE CONTACT US IMMEDIATELY.

**CROSSBORDERS LLC**

A LIMITED LIABILITY CORPORATION, REGISTRATION NUMBER 201305284K  
GST REGISTRATION NUMBER 201305284K

> [Back to OneMotoring](#)

### Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Business
Owner ID:	6357C
Vehicle Details	
Vehicle No.:	SJG4950B
Vehicle to be Exported:	No
Intended Deregistration Date:	22 Jan 2019
Vehicle Make:	TOYOTA
Vehicle Model:	WISH 1.8XE A
Primary Colour:	Grey
Manufacturing Year:	2008
Engine No.:	1ZZ3099776
Chassis No.:	ZNE100409240
Maximum Power Output:	97.0 kW (130 bhp)
Open Market Value:	\$17,147.00
Original Registration Date:	01 Jul 2008
First Registration Date:	01 Jul 2008
Transfer Count:	1
Actual ARF Paid:	\$17,147.00
Intended PARF Rebate Details	
PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	30 Jun 2023
COE Category:	B - Car (1601cc & above)
COE Period(Years):	5
PQP Paid:	\$18,953.00
COE Rebate Amount:	\$16,826.00
<b>Total Rebate Amount:</b>	<b>\$16,826.00</b>
Message	
Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 22 Jan 2019

OK

Dep. 6,650/yr  
554/mth

MV 28,000/-  
PV 16,826/-  
NV 11,174/-

*[Signature]*  
24/1/19



**Toyota Wish 1.8A (COE till 08/2022)** - N.A. 02-Aug-2007 1,794 cc - MPV **SOLD**

High Loan Available With \$3000! Genuine Low Mileage Done! Vehide Still In Tip Top Condition! Beautifully Polish! Accident-Free! Very Well Kept And Maintained By Owner! Free 6 Month Road Tax! Hard To ...

Creative Auto

Posted: 20-Jan-2019 Tags: 2007 Toyota Wish, 2007 toyota wish, Toyota Wish, toyota wish, Toyota, Wish, wish, Used Toyota



**Toyota Wish 1.8A (COE till 01/2024)** \$33,800 \$6,770 /yr 20-Jan-2009 1,794 cc 150,000 km MPV **Available**

\$5K Driveaway! High Loan Available! In-House/Bank Loan Available! Major Wear & Tear Replaced! New Paintwork! Call Us Now For An Appointment! View To Believe Its Pristine Condition!

Autotruster Traders Pte Ltd

Posted: 20-Jan-2019 Tags: 2009 Toyota Wish, 2009 toyota wish, Toyota Wish, toyota wish, Toyota, Wish, wish, Used Toyota

PREMIUM AD



**Toyota Wish 1.8A Aero Tourer (New 5-yr COE)** \$35,888 \$7,170 /yr 31-Dec-2008 1,794 cc 108,000 km MPV **Available**

Bank And In House Loan Available! Up To 2 Years Warranty. Highest Trade In Value For Your Car! Priced Lowest In The Market Yet Comes With Full Accessories! Beautiful Interior! Lowest Price In The Mark...

JDM Cars

Posted: 20-Jan-2019 Tags: 2008 Toyota Wish, 2008 toyota wish, Toyota Wish, toyota wish, Toyota, Wish, wish, Used Toyota



**Toyota Wish 1.8A X (COE till 12/2023)** \$32,800 \$6,650 /yr 30-Dec-2008 1,794 cc - MPV **Available**

2.88%P.A Lowest Interest At \$638 Monthly For Toyota Wish 1.8a \$0 Admin Fees For All GV Purchase. 2 Years Warranty For Engine And Gearbox. Add Ons Available.

GV Credit Pte Ltd

Posted: 20-Jan-2019 Tags: 2008 Toyota Wish, 2008 toyota wish, Toyota Wish, toyota wish, Toyota, Wish, wish, Used Toyota

PREMIUM AD



**Toyota Wish 1.8A (New 5-yr COE)** \$33,800 \$6,760 /yr 14-Nov-2008 1,794 cc 160,000 km MPV **Available**

Benefit Auto Offer Best Deal In Market! Offer Best Price! Offer Best Price For Trade In! Offer Best Interest Rate With High Loan! Hurry Arrange Call To Our Sales For Appointment!

Benefit Auto Enterprise Pte Ltd

Posted: 20-Jan-2019 Tags: 2008 Toyota Wish, 2008 toyota wish, Toyota Wish, toyota wish, Toyota, Wish, wish, Used Toyota



**Toyota Wish 1.8A Aero Tourer (New 5-yr COE)** \$34,800 \$6,960 /yr 02-Sep-2008 1,794 cc 116,000 km MPV **Available**

Agent Car's, Comes With 6 Months Warranty From Reputable Workshop, Low Mileage.Fully Done Up With Receipts,See To Believe, Gtee Superb!

Posted: 20-Jan-2019 Tags: 2008 Toyota Wish, 2008 toyota wish, Toyota Wish, toyota wish, Toyota, Wish, wish, Used Toyota



**Toyota Wish 1.8A (New 5-yr COE)** \$35,888 \$7,170 /yr 15-Jan-2009 1,794 cc - Sedan **Available**

Bank And In House Loan Available! Up To 2 Years Warranty. Highest Trade In Value For Your Car! Priced Lowest In The Market Yet Comes With Full Accessories! Lowest Price In The Market! Call Us Now.

JDM Cars

Posted: 19-Jan-2019 Tags: 2009 Toyota Wish, 2009 toyota wish, Toyota Wish, toyota wish, Toyota, Wish, wish, Used Toyota



**Toyota Wish 1.8A (New 10-yr COE)** \$50,800 \$5,080 /yr 13-Jan-2009 1,794 cc - MPV **Available**

Low Monthly Installment \$811. Interest From 3.18%. All Wear And Tear Replaced! Checked By Our Own In-house Workshop. Option To Renew 5 Years COE. Bank Loan And In House Loan Available. Trade In Welcom...

Posted: 19-Jan-2019 Tags: 2009 Toyota Wish, 2009 toyota wish, Toyota Wish, toyota wish, Toyota, Wish, wish, Used Toyota



**Toyota Wish 1.8A (COE till 05/2026)** \$42,800 \$5,820 /yr 18-Jul-2006 1,794 cc 70,000 km MPV **Available**

Super Low Mileage Done 70000km Only, Very Well Maintained, View To Appreciate.

Posted: 19-Jan-2019 Tags: 2006 Toyota Wish, 2006 toyota wish, Toyota Wish, toyota wish, Toyota, Wish, wish, Used Toyota



**Toyota Wish 1.8A (COE till 01/2021)** \$16,800 \$8,430 /yr 21-Jan-2006 1,794 cc 113,000 km MPV **Available**

COE Specialist With 100% Immediate Loan Approval! Additional 6 Months Warranty And Road Tax For You! Priced Lowest In The Market With The Best Engine Condition! Superbly Well Maintained By One Previous...

Posted: 19-Jan-2019 Tags: 2006 Toyota Wish, 2006 toyota wish, Toyota Wish, toyota wish, Toyota, Wish, wish, Used Toyota

PREMIUM AD

Compare [ 3 ]

Select used cars to Compare or Add to Alert

Shortlist [ 3 ]

Volkswagen Scirocco 1.4A TSI  
03-May-2012

Volkswagen Passat 1.8A TSI  
28-Feb-2015

Toyota Wish 1.8A (COE till 12/2023)  
29-Dec-2008

To compare cars, select from the search results.

Add to Shortlist  
Compare Now  
Clear All

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	21/01/2019 15:48
Date Of Accident	17/01/2019 09:40
Exact Location Of Accident	ALONG AYE (1ST LANE) , 5.5 KM LP 501F
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SJG4950B
<b>Insured/Policyholder</b>	
Name Of Registered Owner	FAST TRACK LIMO SERVICE
Co Reg No	53326357C
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-92222003
Alternative Phone No	OFFICE-92222003

### Vehicle Particulars

Manufacturer	TOYOTA
Model	WISH-1.8 X (A)
Exact Purpose for which vehicle was being used at time of accident	ON DUTY
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE HIRE

### Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5089912359-01
Cover Note Number	01/07/2018 - 30/06/2019

### Driver

Name of Driver	MOHAMED JABIR S/O FAKEER
NRIC No	S8070802E
Date Of Birth	15/05/1980
Occupation	OUTDOOR
Date Of Driving Pass	10/10/2007
Driving Experience	11 YEARS AND 3 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-92222003
Fax Number	
Contact Number	
Email Address	FMJABIR@GMAIL.COM

Address	BLK 82 WHAMPOA DRIVE #12-971
Postcode	320082
Was driver an employee of the Insured's Company	YES
If No, Relationship of the Driver with the Insured	
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	CHAIN COLLISION
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	3
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	YES
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	YES
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : SUMITA T GENDER: : FEMALE

#### Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	10 UBI AVENUE 3
Police Station Address	ROAD: 10 UBI AVENUE 3 , POSTCODE: 408865 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: - FAX NO:
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

ON THE ABOVE MENTIONED TIME, DATE AND LOCATION, I WAS TRAVELLING ALONG THE 1ST OF 4 LANES AT THE MENTIONED LOCATION. AS I WAS TRAVELLING, THE VEHICLE SHC7028P (VEHICLE C) WAS AHEAD OF ME AND JAM BRAKED. THEREFORE, I JAM BRAKED AND CAME TO A COMPLETE STOP. AFTERWARDS, THE VEHICLE SLB9412H (VEHICLE B) COLLIDED INTO ME FROM BEHIND WHICH CAUSED MY VEHICLE TO MOVE FORWARD AND HIT ONTO THE VEHICLE SHC7028P (VEHICLE C). AFTER THE COLLISION, I HIT MY HEAD AGAINST THE STEERING WHEEL AND WAS SEMI CONSCIOUS, AS A RESULT I SUFFERED FROM A CONCUSSION, NECK AND BACK INJURIES. I WAS LATER CONVEYED TO TAN TOCK SENG HOSPITAL AND DISCHARGE ON 18/01/2018. I RECEIVED 7 DAYS MC. INCIDENT NUMBER: E/20190117/0061.

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLB9412H
Vehicle Make/Model/Colour	VEHICLE B
Details Of Properties	

Vehicle Category PRIVATE CAR  
Name of Driver  
NRIC/Passport Number  
Contact Number  
Address  
Postcode  
Insurance Company Name  
Nature Of Damage  
No. Of Passenger (Including Driver)

**DETAILS OF OTHER VEHICLE PROPERTY 2**

Vehicle Registration Number SHC7028P  
Vehicle Make/Model/Colour VEHICLE C  
Details Of Properties  
Vehicle Category TAXI  
Name of Driver  
NRIC/Passport Number  
Contact Number  
Address  
Postcode  
Insurance Company Name  
Nature Of Damage  
No. Of Passenger (Including Driver)

**DETAILS OF INJURED PERSON 1**

Name MOHAMED JABIR S/O FAKEER MOHAMED  
Approximate Age  
Injuries Sustain CONCUSSION, NECK AND BACK INJURIES  
Injured person in which vehicle? SJG4950B  
Were seat belts worn? YES  
Was this injured conveyed to hospital by ambulance? YES  
Address BLK 82 WHAMPOA DRIVE  
#12-971  
Postcode 320082

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.




Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

Sketch Plan Pg. 2

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT


Refer to police report T120190118/2143 and CIA report.

You had been advised by workshop that in the event that you wish to claim against your own policy (OD claim), there is a Fourteen (14) days clause whereby the claim must be made within the stipulated time-frame from the day of occurrence.	Reporting Only
	<input type="checkbox"/> Claim OD
	<input checked="" type="checkbox"/> Claim TP
	<input type="checkbox"/> Claim OD/TP at other workshop

DECLARATION

I/We declare the foregoing particulars are true in every respect.


 Policyholder's Signature  
 Date & Time:


 Driver's Signature  
 (If driver is not the policyholder)  
 Date & Time:



 Reporting Centre Personnel's Signature  
 Name:  
 NRIC/FIN No.:



**SINGAPORE  
POLICE FORCE**



T/20190118/2142

1 of 3

Police Station Of Origin:  
Traffic Police  
10 Ubi Avenue 3 SINGAPORE 408865  
Tel No: 65470000

Report No. T/20190118/2142

**REPORT OF A TRAFFIC ACCIDENT**

Date/Time Report Made: 18/01/2019 16:07		Vide Report No.:		Station Diary No.:	
<b>Informant's Particulars</b>					
Name of Informant: MOHAMED JABIR S/O FAKEER MOHAMED			Address: 82 WHAMPOA DRIVE #12-971 WHAMPOA SPRING SINGAPORE 320082		
ID Type / ID No.: NRIC NO / S8070802E			Contact No.:		Mobile: 92222003
Nationality:			Email:		
Sex: Male	Age: 38	Date of Birth: 15/05/1980	Type of Informant: Driver		
Race:		Language:		Institution / School Name:	
Occupation: PRIVATE HIRE DRIVER		Driving Licence Information: Class: 3		Date of Expiry:	

<b>General Information of the Accident</b>					
Type of Accident:	Injury Attended by Police	Drink Drive: No	Date/Time of Accident: 17/01/2019 09:40	Type of Location: Flyover	
Location: Along Road 1 CENTRAL EXPRESSWAY AYER RAJAH EXPRESSWAY 5.5KM LP 501F					
Weather: Clear		Road Surface: Dry		Road Speed Limit:	
Traffic Flow: Dual Carriage Way		Traffic Control: Not Controlled		Traffic Volume: Heavy	
Type of Collision: Between Moving Vehicles - Head To Rear				Anyone conveyed by ambulance: Yes	

<b>Details of Vehicle Involved</b>						
Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
SHC7028P	Car					1
SJG4950B	Car					1
SLB9412H	Car					1



**SINGAPORE  
POLICE FORCE**



T/20190118/2142

2 of 3

Police Station Of Origin:  
Traffic Police  
10 Ubi Avenue 3 SINGAPORE 408865  
Tel No: 65470000

Report No. T/20190118/2142

## CONTINUATION OF REPORT

Details of Person Involved			
Any Pedestrian Involved: No			
No. of Pedestrians Injured: NIL		Use of Pedestrian Crossing: NA	
Driver			
Name	MOHAMED JABIR S/O FAKEER MOHAMED	ID No.	S8070802E
Related Vehicle	SJG4950B (Car)	Contact No.	92222003
Hospital/Clinic	TAN TOCK SENG HOSPITAL	Class of Driving Licence & Expiry Date	Class: 3 Date of Expiry: NIL
Date Treatment	17/01/2019	Date Discharge	18/01/2019
No. of Days granted Medical Leave	07	Degree of Injury	NIL

**Brief Details.**

ON THE ABOVE MENTIONED TIME,DATE AND LOCATION.

I WAS TRAVELLING ALONG THE 1ST OF 4 LANES AT THE ABOVE MENTIONED LOCATION. AS I WAS TRAVELLING , THE VEHICLE SHC7028P WAS AHEAD OF ME AND JAM BRAKED. THEREFORE, I JAM BRAKED AND CAME TO A COMPLETE STOP. AFTERWARDS, THE VEHICLE SLB9412H COLLIDED INTO ME FROM BEHIND WHICH CAUSED MY VEHICLE TO MOVE FORWARD AND HIT ONTO THE VEHICLE SHC7028P. AFTER THE COLLISION , I HIT MY HEAD AGAINST THE STEERING WHEEL AND WAS SEMI CONSCIOUS , AS A RESULT I SUFFERED FROM A CONCUSSION , NECK AND BACK INJURIES. I WAS LATER CONVEYED TO TAN TOCK SENG HOSPITAL AND DISCHARGED ON 18/1/2018. I RECEIVED 7 DAYS MC.

INCIDENT NUMBER: E/20190117/0061



SINGAPORE  
POLICE FORCE



T/20190118/2142

Police Station Of Origin:  
Traffic Police  
10 Ubi Avenue 3 SINGAPORE 408865  
Tel No: 65470000

3 of 3



Report No. T/20190118/2142

CONTINUATION OF REPORT

**Sketch Plan**

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the **report number** as reference.

Signature Of Officer Recording The Report: TP / KHALED AMR HASSAN MOHSSEN 	Signature Of Informant: 
Signature Of Interpreter: Not applicable	Date/Time: 18/01/2019 16:07
Officer In Charge Of Case: TP / GIT / Staff Sgt MOHAMED SUFIAN BIN MOHAMED JUNID Contact No.: 65476247	Classification Of Case: 
Authentication Stamp NP168	 Signature: _____

(1) Deformed (2) Shifted (3) Buckled (4) Broken (5) Necessary (6) Missing (7) Torn (8) Unconfirmed (9) Not Working

### MOTORCAR (Rear)

(1) Replace (✓) (2) Repair (✓) (3) Check (✓) (4) Not Consistent (✓)

Rear Portion

Vehicle No: SJG 4950B

NAC	INC	Item	CON	AC	Qty
1137	993626	Rear Number Plate			
1138	993627	Rear Number Plate Base			
1139	993630	Rear Number Plate Garnish			
1140	993632	Rear Number Plate Lamp			
1141	992958	Rear Bumper	DD	✓	
1142	993085	Rear Bumper Upper			
1143	993017	Rear Bumper Lower			
1144	993054	Rear Bumper Side			
1145	993103	Rear Bumper Tow Cover			
1146	992341	Rear Bumper Clips			
1147	992976	Rear Bumper Bracket			
1148	993068	Rear Bumper Side Retainer	NEW		
1149	993045	Rear Bumper Reinforcement			
1150	992970	Rear Bumper Beam			
1151	993077	Rear Bumper Sponge			
1152	992999	Rear Bumper Damper	DD	✓	
1153	993040	Rear Bumper Protector			
1154	993036	Rear Bumper Pad			
1155	993026	Rear Bumper Moulding			
1156	993044	Rear Bumper Reflector	BK	✓	13
1157	993023	Rear Bumper Lower Spoiler			
1158	994023	Reverse Sensor	CUT	✓	
1159	993327	Rear End Panel	RES	✓	
1160	993339	Rear End Panel Top Garnish	DL	✓	
1161	993333	Rear End Panel Inner Trim			
1162	990333	Boot Compartment Inner Trim			
1163	993851	Rear LH Taillamp	CRA	✓	
1164	993853	Rear LH Taillamp Garnish			
1165	993859	Rear LH Taillamp Panel			
1166	995116	Rear RH Taillamp	CRA	✓	
1167	993853	Rear RH Taillamp Garnish			
1168	993859	Rear RH Taillamp Panel			
1169	993554	Rear Apron Panel			
1170	992895	Bootlid			
1171	991328	Bootlid Emblem			
1172	990356	Bootlid Handle			
1173	995250	Bootlid Moulding			
1174	990376	Bootlid Reflector			
1175	995222	Bootlid Lamp LH			
1176	992899	Bootlid Lamp RH			
1177	995243	Bootlid Lock			
1178	990377	Bootlid Rubber			
1179	990382	Bootlid Hinge			
1180	993877	Bootlid Spoiler			
1181	994543	Tailgate	DD	✓	
1182	991328	Tailgate Emblem	NEC	✓	
1183	994643	Tailgate Outer Handle			
1184	994640	Tailgate Moulding			
1185	994545	Tailgate Garnish			
1186	994648	Tailgate Reflector			
1187	994549	Tailgate Lamp	CUT	✓	
1188	994646	Tailgate Protector			
1189	994676	Tailgate Wiper Arm			
1190	994677	Tailgate Wiper Blade			
1191	994679	Tailgate Wiper Nozzle			
1192	994555	Tailgate Wiper Motor			
1193	994602	Tailgate Glass			
1194	994606	Tailgate Glass Rubber			
1195	994604	Tailgate Glass Moulding	NEC	✓	
1196	994607	Tailgate Glass Sealant	NEC	✓	
1197	994629	Tailgate Lock	BT	✓	
1198	994651	Tailgate Rubber	NEC	✓	
1199	994611	Tailgate Hinge			
1200	994594	Tailgate Damper			
1201	994613	Tailgate Inner Board	CRA	✓	

NAC	INC	Item	CON	AC	Qty
1202	993784	Spare Tyre Board			
1203	994328	Spare Tyre Panel			
1204	995065	Spare Tyre			
1205	994326	Spare Tyre Lock Screw			
1206	993787	Spare Tyre Cover			
1207	995323	Triangle Breakdown Sign			
1208	990507	CD Changer Assy			
1209	990164	Antenna			
1210	990534	Centre Exhaust Pipe Assy			
1211	990532	Centre Exhaust Mounting			
1212	993364	Rear Exhaust Pipe	BT	✓	
1213	993357	Rear Exhaust Chrome Pipe			
1214	993361	Rear Exhaust Mounting	DIS	✓	2
1215	993358	Rear Exhaust Heat Shield	DD	✓	
1216	995223	Rear LH Chassis Member			
1217	993165	Rear RH Chassis Member			
1218	993436	Rear LH Fender	SCR	✓	
1219	993449	Rear LH Fender Protector			
1220	993420	Rear LH Fender Inner Panel			
1221	993431	Rear LH Fender Inner Trim			
1222	993415	Rear LH Fender Inner Garnish			
1223	993425	Rear LH Fender Inner Shield			
1224	993621	Rear LH Mudflap			
1225	993933	Rear LH Wheel Rim			
1226	994025	Rear LH Rim Cover			
1227	995065	Rear LH Tyre			
1228	993456	Rear RH Fender			
1229	993450	Rear RH Fender Protector			
1230	993420	Rear RH Fender Inner Panel			
1231	993431	Rear RH Fender Inner Trim			
1232	993415	Rear RH Fender Inner Garnish			
1233	993425	Rear RH Fender Inner Shield			
1234	993622	Rear RH Mudflap			
1235	993934	Rear RH Wheel Rim			
1236	994025	Rear RH Rim Cover			
1237	995065	Rear RH Tyre			
1238	995162	Rear Fender Extension Panel LH			
1239	993401	Rear Fender Extension Panel RH			
1240	993430	Rear Fender Inner Top Garnish			
1241	993673	Rear Fender 1/4 Glass			
1242	993452	Rear Fender 1/4 Glass Rubber			
1243	993453	Rear Fender 1/4 Glass Sealant			
1244	993949	Rear Windscreen Glass			
1245	993976	Rear Windscreen Rubber			
1246	993961	Rear Windscreen Moulding			
1247	993955	Rear Windscreen Sealant			
1248	994729	Third Brake Light			
1249	993385	Rear Fender Air Grille			
1250	992167	Fuel Lid			
1251	992168	Fuel Neck			
1252	992179	Fuel Tank			
1253	992184	Fuel Tank Bracket			
1254	992191	Fuel Tank Float			
1193	990247	Sticker			

No of Items: 18

Assessor: T.Glim

*[Signature]*  
24/1/19

**MOTOR CAR (Frt)**

**Front Portion**

NAC	INC	Item	CON	AC	Qty
1001	991586	Frt Number Plate			
1002	991887	Frt Number Plate Base			
1003	991889	Frt Number Plate Garnish			
1004	991300	Frt Bumper	BR ✓		
1005	992341	Frt Bumper Clips	NC ✓		
1006	991325	Frt Bumper Bracket			
1007	991462	Frt Bumper Side Retainer	NE ✓		
1008	991433	Frt Bumper Reinforcement	DD ✓		
1009	991318	Frt Bumper Beam			
1010	991468	Frt Bumper Sponge	X		
1011	991427	Frt Bumper Protector			
1012	991420	Frt Bumper Pad			
1013	991363	Frt Bumper Grille	BR ✓		
1014	991301	Frt Bumper Moulding			
1015	991407	Frt Bumper Lower Spoiler			
1016	991438	Frt Bumper Sensor			
1017	995100	Frt LH Bumper Fog Lamp Cover			
1018	991355	Frt RH Bumper Fog Lamp Cover			
1019	995079	Frt LH Bumper Fog Lamp			
1020	995080	Frt RH Bumper Fog Lamp			
1021	991793	Frt Grille	BR ✓		
1022	991328	Frt Grille Emblem	NE ✓		
1023	991799	Frt Grille Chrome Moulding	DD ✓		
1024	991222	Frt Apron Panel			
1025	992013	Frt Support Panel	DD ✓		
1026	992025	Frt Support Panel Top Garnish Cover			
1027	992416	Horn			
1028	991277	Frt Brace Panel			
1029	995153	Frt LH Headlamp Assy	CRA ✓		
1030	991821	Frt RH Headlamp Assy	CRA ✓		
1031	995088	Frt LH Side Lamp			
1032	995089	Frt RH Side Lamp			
1033	990248	Bonnet	DD ✓		
1034	991328	Bonnet Emblem	NE ✓		
1035	990287	Bonnet Lock			
1036	990285	Bonnet Insulator			
1037	990273	Bonnet Hinge	X		
1038	990261	Bonnet Damper			
1039	990305	Bonnet Rubber			
1040	990252	Bonnet Cable Moulding	DD ✓		
1041	990311	Bonnet Stand			
1042	990119	Air Con Condenser	DD ✓		
1043	990122	Air Con Fan Assy	X		
1044	990134	Air Con Suction Pipe (Low Pressure)			
1045	990118	Air Con Suction Hose			
1046	990133	Air Con Discharge Pipe (High Pressure)			
1047	990114	Air Con Discharge Hose			
1048	990149	Air Con Liquid Pipe			
1049	995060	Air Con Receiver Drier			
1050	990111	Air Con Compressor Assy			
1051	995294	Air Con Belt			
1052	995074	Radiator			
1053	992738	Radiator Cowling			
1054	992742	Radiator Fan Assy			
1055	992745	Radiator Fan Clutch			
1056	992758	Radiator Hose Top			
1057	992757	Radiator Hose Bottom			
1058	992741	Radiator Expansion Tank			
1059	990131	Air Duct			
1060	990070	Air Cleaner Assy			
1061	990056	Air Cleaner Hose			
1062	990069	Air Cleaner Resonator			
1063	991713	Frt Exhaust Manifold			
1064	991713	Frt Exhaust Manifold Cover			
1065	991254	Frt Exhaust Manifold Sensor (Oxygen)			
1066	991711	Front Exhaust Pipe			
1067	990110	Battery			
1068	990224	Battery Cover			
1069	990223	Battery Bracket			
1070	990222	Battery Tray			

NAC	INC	Item	CON	AC	Qty
1071	992205	Fuse Box			
1072	994011	Relay Box			
1073	995053	Wiper Washer Tank			
1074	995052	Wiper Washer Tank Motor			
1075	990159	Alternator Assy			
1076	990160	Alternator Belt			
1077	992688	Power Steering Pump			
1078	992669	Power Steering Belt			
1079	994431	Power Steering Cooler Pipe			
1080	992692	Power Steering Hose			
1081	990010	ABS Pump Control Unit			
1082	990427	Brake Master Pump Assy			
1083	990403	Brake Booster Pump Assy			
1084	991005	Engine Top Cover			
1085	991011	Engine Under Cover			
1086	990946	Engine Mounting			
1087	990949	Engine Mounting Frt			
1088	990950	Engine Mounting LH			
1089	990952	Engine Mounting RH			
1090	990951	Engine Mounting Rear			
1091	992234	Gear Box Mounting			
1092	991520	Frt LH Chassis Member			
1093	991520	Frt RH Chassis Member			
1094	990728	Frt Vertical Cross Member			
1095	991863	Frt Lower Cross Member			
1096	995070	Frt LH Fender			
1097	995072	Frt LH Fender Inner Panel			
1098	995147	Frt LH Fender Lamp			
1099	995148	Frt LH Fender Protector			
1100	991740	Frt LH Fender Inner Shield			
1101	995179	Frt LH Mudflap			
1102	995170	Frt LH Wheel Rim			
1103	994025	Frt LH Rim Cover			
1104	995065	Frt LH Tyre			
1105	995071	Frt RH Fender			
1106	991739	Frt RH Fender Inner Panel			
1107	991744	Frt RH Fender Lamp			
1108	991752	Frt RH Fender Protector			
1109	991740	Frt RH Fender Inner Shield			
1110	991884	Frt RH Mudflap			
1111	992087	Frt RH Wheel Rim			
1112	994025	Frt RH Rim Cover			
1113	995065	Frt RH Tyre			
1114	992093	Frt Windscreen Glass			
1115	992117	Frt Windscreen Rubber			
1116	992108	Frt Windscreen Moulding			
1117	992098	Frt Windscreen Sealant			
1118	991019	ERP Bracket			
1119	991020	ERP Unit			
1120	992140	Frt Wiper Arm			
1121	992142	Frt Wiper Blade			
1122	995045	Wiper Panel Garnish			
1123	991126	Firewall Panel			
1124	990753	Dashboard Assy			
1125	992282	Glove Box Cover			
1126	992281	Glove Box Compartment			
1127	994483	Steering Wheel Airbag			
1128	994485	Steering Wheel Airbag Sensor			
1129	990749	Dashboard Airbag			
1130	990750	Dashboard Airbag Sensor			
1131	990029	Airbag Control Unit			
1132	990864	Frt Driver Seat			
1133	991922	Frt RH Seat Belt Assy			
1134	991899	Frt Passenger Seat			
1135	995182	Frt LH Seat Belt Assy			
1136	990247	Sticker			
		Headlamp Support Bracket BT			

No of items: 13

ASSASSOR: TCUM

24/1/19

**...CLAIM SUBFOLDER...(Pending for Survey Report)**

PRI

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	23 Jan 2019 <a href="#">Edit Reg</a>		22 Jan 2019 00:00 <a href="#">Edit Adj Rpt</a>	<b>S\$0.00</b> <a href="#">Edit Estimates</a>	<b>S\$0.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b> <span style="float: right;">[Created by adjuster]</span>									
Insured:	<b>LION CITY RENTALS PTE LTD</b> , Co. Reg. No.: 201624597K								
Main Claimant:	<b>FAST TRACK LIMO SERVICE</b> , Co. Reg. No.: 53326357C								
Vehicle Reg. No.:	<b>SJG4950B</b>	Date of Loss:	17/01/2019 09:00 - :59 [126 Months and 16 Days From LTA Reg Date (Man Yr)]						
Claim Type:	<b>TP / 1704810644SG</b>	Policy/Cover Note No.:	(Comprehensive)						
Vehicle Reg. No. (Insured):	<b>SLB9412H</b>	Policy No. (Claimant):							
		Excess:							
Repairer:	<b>GREEN STAR SPRAY PAINTING (HQ)</b> BLK 3011 BEDOK NORTH AVENUE 4 #01-2004 BEDOK INDUSTRIAL PARK E, 489977 Bedok - Tel:								
Handling Insurer:	<b>AIG Asia Pacific Insurance Pte. Ltd. (Express)</b> - Tel: 65-6419-3000 ... [Handled by <b>Ng, Hai-Chuan</b> ] Hai-Chuan.Ng@aig.com								
Adjuster:	<b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [Handled by <b>Lim Teow Guan</b> ] ... [Final Rpt due 31/01/2019]								
Claimant's Solicitor:	<b>CROSSBORDERS LLC</b> - Tel: 64381323								
<b>ASSOCIATED MAIL RECEIVED</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Compose Case Mail</a></span>									
<ul style="list-style-type: none"> <li>AIG_SG (23/01/2019): Request To Upload TP GIA Report</li> </ul>									
<b>ALL ASSOCIATED TASKS</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a></span>									
<b>Due Date</b>	<b>Priority</b>	<b>Type</b>	<b>Task Group</b>	<b>Subject</b>	<b>Handler</b>	<b>Assigned By</b>	<b>Completed On</b>	<b>Created On</b>	<b>Done?</b>
No results.									

## Claim Documents

\*SJG4950B (1704810644SG)  
[SLB9412H]  
TP  
FAST TRACK LIMO SERVICE  
Jan 17 2019 9:00AM  
[LION CITY RENTALS PTE LTD]  
GREEN STAR SPRAY PAINTING

Upload Documents		Upload Photos		Compose New Letter		Upload Video		Upload Audio		View <input type="button" value="View in Browser"/>	
<b>Photos/Images</b>										3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)						Thumbnail	Print		
1	25/01/19 14:06	General View						 Load JPG	<input checked="" type="checkbox"/>		
2	25/01/19 14:06	General View						 Load JPG	<input checked="" type="checkbox"/>		
3	25/01/19 14:06	General View						 Load JPG	<input checked="" type="checkbox"/>		
4	25/01/19 14:06	General View						 Load JPG	<input checked="" type="checkbox"/>		
5	25/01/19 14:06	General View						 Load JPG	<input checked="" type="checkbox"/>		
6	25/01/19 14:06	General View						 Load JPG	<input checked="" type="checkbox"/>		
7	25/01/19 14:06	General View						 Load JPG	<input checked="" type="checkbox"/>		
8	25/01/19 14:06	General View						 Load JPG	<input checked="" type="checkbox"/>		
9	25/01/19 14:06	General View						 Load JPG	<input checked="" type="checkbox"/>		
10	25/01/19 14:06	General View						 Load JPG	<input checked="" type="checkbox"/>		
11	25/01/19 14:06	General View						 Load JPG	<input checked="" type="checkbox"/>		
12	25/01/19 14:06	General View						 Load JPG	<input checked="" type="checkbox"/>		
13	25/01/19 14:06	General View						 Load JPG	<input checked="" type="checkbox"/>		
14	25/01/19 14:06	General View						 Load JPG	<input checked="" type="checkbox"/>		
15	25/01/19 14:06	General View						 Load JPG	<input checked="" type="checkbox"/>		
16	25/01/19 14:06	General View						 Load JPG	<input checked="" type="checkbox"/>		
17	25/01/19 14:06	General View						 Load JPG	<input checked="" type="checkbox"/>		
18	25/01/19 14:06	General View						 Load JPG	<input checked="" type="checkbox"/>		
19	25/01/19 14:06	General View						 Load JPG	<input checked="" type="checkbox"/>		
20	25/01/19 14:06	General View						 Load JPG	<input checked="" type="checkbox"/>		
21	25/01/19 14:06	General View						 Load JPG	<input checked="" type="checkbox"/>		
22	25/01/19 14:06	General View						 Load JPG	<input checked="" type="checkbox"/>		
23	25/01/19 14:06	General View						 Load JPG	<input checked="" type="checkbox"/>		
24	25/01/19 14:06	General View						 Load JPG	<input checked="" type="checkbox"/>		
25	25/01/19 14:06	General View						 Load JPG	<input checked="" type="checkbox"/>		
26	25/01/19 14:06	General View						 Load JPG	<input checked="" type="checkbox"/>		
27	25/01/19 14:06	General View						 Load JPG	<input checked="" type="checkbox"/>		
28	25/01/19 14:06	General View						 Load JPG	<input checked="" type="checkbox"/>		
29	25/01/19 14:06	General View						 Load JPG	<input checked="" type="checkbox"/>		
30	25/01/19 14:06	General View						 Load JPG	<input checked="" type="checkbox"/>		
31	25/01/19 14:06	General View						 Load JPG	<input checked="" type="checkbox"/>		
32	25/01/19 14:06	General View						 Load JPG	<input checked="" type="checkbox"/>		
33	25/01/19 14:06	General View						 Load JPG	<input checked="" type="checkbox"/>		
34	25/01/19 14:06	General View						 Load JPG	<input checked="" type="checkbox"/>		
35	25/01/19 14:06	General View						 Load JPG	<input checked="" type="checkbox"/>		
36	25/01/19 14:06	General View						 Load JPG	<input checked="" type="checkbox"/>		
37	25/01/19 14:06	General View						 Load JPG	<input checked="" type="checkbox"/>		

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
38	25/01/19 14:06	General View		<input checked="" type="checkbox"/>
39	25/01/19 14:06	General View		<input checked="" type="checkbox"/>
40	25/01/19 14:06	General View		<input checked="" type="checkbox"/>
41	25/01/19 14:06	General View		<input checked="" type="checkbox"/>
42	25/01/19 14:06	General View		<input checked="" type="checkbox"/>
43	25/01/19 14:06	General View		<input checked="" type="checkbox"/>
44	25/01/19 14:06	General View		<input checked="" type="checkbox"/>
45	25/01/19 14:06	General View		<input checked="" type="checkbox"/>
46	25/01/19 14:06	General View		<input checked="" type="checkbox"/>
47	25/01/19 14:06	General View		<input checked="" type="checkbox"/>
48	25/01/19 14:06	General View		<input checked="" type="checkbox"/>
49	25/01/19 14:06	General View		<input checked="" type="checkbox"/>
50	25/01/19 14:06	General View		<input checked="" type="checkbox"/>
51	25/01/19 14:06	General View		<input checked="" type="checkbox"/>
52	25/01/19 14:06	General View		<input checked="" type="checkbox"/>
53	25/01/19 14:06	General View		<input checked="" type="checkbox"/>
54	25/01/19 14:06	General View		<input checked="" type="checkbox"/>
55	25/01/19 14:06	General View		<input checked="" type="checkbox"/>
56	25/01/19 14:06	General View		<input checked="" type="checkbox"/>
57	25/01/19 14:06	General View		<input checked="" type="checkbox"/>
58	25/01/19 14:06	General View		<input checked="" type="checkbox"/>
59	25/01/19 14:06	General View		<input checked="" type="checkbox"/>
60	25/01/19 14:06	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
61	25/01/19 14:06	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
62	25/01/19 14:06	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
63	25/01/19 14:06	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
64	25/01/19 14:06	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
65	25/01/19 14:06	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
66	25/01/19 14:06	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
67	25/01/19 14:06	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
68	25/01/19 14:06	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
69	25/01/19 14:06	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
70	25/01/19 14:06	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
71	25/01/19 14:06	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
72	25/01/19 14:06	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
73	25/01/19 14:06	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
74	25/01/19 14:06	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
75	25/01/19 14:06	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
76	25/01/19 14:06	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
77	25/01/19 14:06	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
78	25/01/19 14:06	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
79	25/01/19 14:06	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
80	25/01/19 14:06	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
81	25/01/19 14:06	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
82	25/01/19 14:06	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
83	25/01/19 14:06	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
84	25/01/19 14:06	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
85	25/01/19 14:06	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
86	25/01/19 14:06	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
87	25/01/19 14:06	Photographs of Damaged Parts		<input checked="" type="checkbox"/>

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
88	25/01/19 14:06	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
89	25/01/19 14:06	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
90	25/01/19 14:06	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
91	25/01/19 14:06	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
92	25/01/19 14:06	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
93	25/01/19 14:06	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
94	25/01/19 14:06	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
95	25/01/19 14:06	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
96	25/01/19 14:06	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
97	25/01/19 14:06	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
98	25/01/19 14:06	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
99	25/01/19 14:06	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
100	25/01/19 14:06	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
101	25/01/19 14:06	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
102	25/01/19 14:06	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
103	25/01/19 14:06	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
104	25/01/19 14:06	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
105	25/01/19 14:06	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
106	25/01/19 14:06	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
107	25/01/19 14:06	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
108	25/01/19 14:06	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
109	25/01/19 14:06	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
110	25/01/19 14:06	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
111	25/01/19 14:06	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
112	25/01/19 14:06	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
113	25/01/19 14:06	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
114	25/01/19 14:06	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
115	25/01/19 14:06	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
116	25/01/19 14:06	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
117	25/01/19 14:06	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
118	25/01/19 14:06	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
119	25/01/19 14:06	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
120	25/01/19 14:06	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
121	25/01/19 14:06	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
122	25/01/19 14:06	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
123	25/01/19 14:06	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
124	25/01/19 14:06	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
125	25/01/19 14:06	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
126	25/01/19 14:06	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
127	25/01/19 14:06	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
128	25/01/19 14:06	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
129	25/01/19 14:06	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	23/01/19 12:50	OI GIA REPORT	 Load PDF	<input checked="" type="checkbox"/>

## Documents Checklist

<b>DOCUMENTS CHECKLIST</b>	<input type="button" value="Reset"/> <input type="button" value="Save"/> <input type="button" value="Print"/>
----------------------------	---

There are no document checklists configured.

**Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)**

**Show Remarks To:**  Handling Insurer

Note: Remarks are private unless you show it to other parties.

## LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

### VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CS3/AIG19001419/BCD3E2

**Date:** 31/01/2019

#### REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.

Policy No:

**Claimant Vehicle No :** SJG4950B

**Insured Vehicle No :** SLB9412H

Date of Loss: 17/01/2019

Nature of Claim: TP

Claim No: 1704810644SG

#### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SJG4950B**

Make & Model: TOYOTA WISH, 1.8 X (A)

Engine No: 1ZZ3099776

Reg. Date: 01/07/2008 (Man. Year: 2008)

Chassis No: ZNE100409240

Colour: Grey

Odometer: 254996 km

Engine Capacity: 1794 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

#### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

#### CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Bridgestone 2 mm	Rear Left Side:	Bridgestone 4 mm
Front Right Side:	Bridgestone 2 mm	Rear Right Side:	Bridgestone 4 mm

*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Nett Amount (S\$)</b>	<b>0.00</b>	<b>0.00</b>	<b>0.00</b>	

#### INSPECTION

Date of Assignment: 22/01/2019

Date Inspected: 22/01/2019 Inspected At:

GREEN STAR SPRAY PAINTING (HQ)  
BLK 3011 BEDOK NORTH AVENUE 4  
#01-2004 BEDOK INDUSTRIAL PARK E  
Singapore 489977

Estimated Period of Repair: 9.0 days

**Adjuster:** Lim Teow Guan

**Manager:** CELINE FONG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Dented	0.00 F	*- F
2	1		*REAR BUMPER SIDE RETAINER	Necessary	0.00 F	*- F
3	2		*REAR BUMPER DAMPER	Dented	0.00 F	*- F
4	1		*REAR BUMPER REFLECTOR	Broken	0.00 F	*- F
5	1		*REVERSE SENSOR	Cut	0.00 F	*- F
6	1		*REAR END PANEL	Buckled	0.00 F	*- F
7	1		*REAR END PANEL TOP GARNISH	Dislodged	0.00 F	*- F
8	1		*REAR LH TAILLAMP	Cracked	0.00 F	*- F
9	1		*REAR RH TAILLAMP	Cracked	0.00 F	*- F
10	1		*TAILGATE	Dented	0.00 F	*- F
11	1		*TAILGATE EMBLEM	Necessary	0.00 F	*- F
12	1		*TAILGATE LAMP	Cut	0.00 F	*- F
13	1		*TAILGATE GLASS MOULDING	Necessary	0.00 F	*- F
14	1		*TAILGATE GLASS SEALANT	Necessary	0.00 F	*- F
15	1		*TAILGATE LOCK	Bent	0.00 F	*- F
16	1		*TAILGATE RUBBER	Necessary	0.00 F	*- F
17	1		*REAR EXHAUST PIPE	Bent	0.00 F	*- F
18	2		*REAR EXHAUST MOUNTING	Distorted	0.00 F	*- F
19	1		*REAR EXHAUST HEAT SHIELD	Dented	0.00 F	*- F
20	1		*REAR LH FENDER	Repair	0.00 F	*- F
21	1		*FRT BUMPER	Broken	0.00 F	*- F
22	1		*FRT BUMPER CLIPS	Necessary	0.00 F	*- F
23	1		*FRT BUMPER SIDE RETAINER	Necessary	0.00 F	*- F
24	1		*FRT BUMPER REINFORCEMENT	Dented	0.00 F	*- F
25	1		*FRT BUMPER GRILLE	Broken	0.00 F	*- F
26	1		*FRT GRILLE	Broken	0.00 F	*- F
27	1		*FRT GRILLE EMBLEM	Necessary	0.00 F	*- F
28	1		*FRT GRILLE CHROME MOULDING	Dented	0.00 F	*- F
29	1		*FRT SUPPORT PANEL	Dented	0.00 F	*- F
30	1		*FRT LH HEADLAMP ASSY	Cracked	0.00 F	*- F
31	1		*FRT RH HEADLAMP ASSY	Cracked	0.00 F	*- F
32	1		*BONNET	Dented	0.00 F	*- F
33	1		*BONNET EMBLEM	Necessary	0.00 F	*- F
34	1		*BONNET MOULDING	Dented	0.00 F	*- F
35	1		*AIR CON CONDENSER	Dented	0.00 F	*- F
36	2		*HEADLAMP SUPPORT BRACKET	Bent	0.00 F	*- F
37	1		*TAILGATE INNER BOARD	Cracked	0.00 F	*- F
<b>Total Parts (\$\$)</b>					<b>0.00</b>	<b>0.00</b>

F=Franchise part.

Report was unsubmitted during this print-out.
---

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.
---

< END OF ESTIMATES >