

22/03/2002

ASS. REC. BY:

REF:

CS/AIG/9001425/Gcd3d

Special Instruction:

Survivor:

Gao Qiang

ASSIGNMENT (Office)

From (Person):

Chin Lee Ying

of

AIG

Date/Time:

22/11/19 @ 11:07 am

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLE 5085D

Insured:

SKW 3306Y

at Workshop m/s

Eclipse Auto

Tel:

8128 8789

of

155 Kaki Bukit Ave 1 # Level 1

Policy No:

2100435340

Claim No:

1695273646SG

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

12/01/2019

CA / REV / REP. / REV 24 HRS

(up)

H.O.D. Endorsement:

Date/Time:

11:33am @ 22/1/19

Person Contacted:

Frankie

Vehicle IN/OUT

Date/Time

Action/Instruction (X) Estimate

SLE 5085D - CC3/EQF/7012352/M/1/06/392

JVA. 21/6/19

SKW 3306Y - X

Dismantle: 23/1/2019

After repair: 25/1/2019

108/11/13

Surrey

REF:

A161

09 534  
C-2022

## ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: \_\_\_\_\_

at Workshop m/s

of \_\_\_\_\_

Insured: \_\_\_\_\_

Policy No. \_\_\_\_\_

Claims No. \_\_\_\_\_

Sum Insured: \_\_\_\_\_

Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.

Bal. or Market Value: \_\_\_\_\_

IDAC Accident Rpt: \_\_\_\_\_

Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_

Consistent? : Yes or No

Est. Repairs: \_\_\_\_\_

days

Res.: Yes or No

Lum Sum: \_\_\_\_\_

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_

Person Contacted: \_\_\_\_\_

Vehicle: IN / OUT

Veh No: \_\_\_\_\_

Yr Regn: \_\_\_\_\_

Type: ☒ M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: \_\_\_\_\_

Colour: \_\_\_\_\_

Sp. Reading: \_\_\_\_\_

Eng/No: \_\_\_\_\_

C/No: \_\_\_\_\_

Gen. Cond: ☒ Good / Fair / Poor / BurntSteering: ☒ In order / Jammed / Leaked / Burnt orBrake: ☒ In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD / A/Rim or

Tyre Size: F: \_\_\_\_\_

R: \_\_\_\_\_

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. \_\_\_\_\_

mm

R/Bal. \_\_\_\_\_

mm

L/Bal. \_\_\_\_\_

mm

L/Bal. \_\_\_\_\_

mm

D.O.A. \_\_\_\_\_

D.O.I. \_\_\_\_\_

Survey held at \_\_\_\_\_

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

MV - 22000

PV - 18,464

NV - 3536

RECEIVED 31 JAN 2019.

Date/Time, File Pass to?

☐

: Preli. Report

☐

: Final Report

1)

Date/Time, File Return to?

2)

Days Of Repair: \_\_\_\_\_

Resurvey No. of Trip: \_\_\_\_\_

Add Fee:

☐

: Site Insp (\$)

☐

: Interview (\$)

☐

: Tech Invs (\$)

☐

: Weekend (\$)

Survey Fee: \_\_\_\_\_

Transportation: \_\_\_\_\_

) \$ + RS. \$ SI

) Photos

) Others

TOTAL




180
10
190

Report Format: \_\_\_\_\_

Lump Sum / I.B.I. (\$) \_\_\_\_\_

- PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURE...

From: Chin, Lee-Ying  
To: assignments, Admin A  
Cc: Fong, Andy-SY  
Sent: 22/1/2019 11:07:17 AM

Attachments:  [SLE 5085D FORM1.pdf](#)  [SLE5085D GIA.PDF](#)  
 [FORM3 SLE 5085D.PDF](#)

---

Hi LKK,

Kindly assist to survey, vehicle in workshop.

Thanks.

Best Regards

Lee Ying, Chin

AIG

Claims | AIG Asia Pacific Insurance Pte. Ltd.

78 Shenton Way #08-16 Singapore 079120

Tel +(65) 6419 1947

[Lee-Ying.Chin@aig.com](mailto:Lee-Ying.Chin@aig.com) | [www.aig.sg](http://www.aig.sg)

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

VEHICLE CLAIMS SPECIALIST PTE LTD  
UEN 201802773H

Date: 21st January 2019

Your ref: SKW 3306Y

BY EMAIL ONLY

Our ref: VCS/SLE 5085D/EA/PD

**To: AIG ASIA PACIFIC INSURANCE PTE LTD**

Attn: Motor Claims Dept

Dear Sirs,

**CORRESPONDANCE PURSUANT TO PARAGRAPH 2.9 OF THE PRE-ACTION  
PROTOCOL FOR NIMA CASES.**

We refer to your email dated 21st January 2019.

Please note that the said vehicle can be inspected at:

ECLIPSE AUTO PTE LTD

155 KAKI BUKIT AVE 1

LEVEL 1

SINGAPORE 416012

Contact No: 81288789

**Please call for to arrange for an appointment before conducting the pre-repair inspection.**

Please note that the vehicle will be available for pre-repair inspection within the next 2 days excluding any intervening Saturday, Sunday and/or Public Holiday, the said workshop will commence repairs thereafter without further notice or reference to you. All our client's right are expressly reserved.

**PLEASE REPLY BY EMAIL ONLY : VCSSG01@GMAIL.COM**

**DO NOT REPLY BY FAX**

Yours faithfully

**VCS**

Vehicle Claims Specialist Pte Ltd

[> Back to OneMotoring](#)

## Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	0953H
Vehicle Details	
Vehicle No.:	SLE5085D
Vehicle to be Exported:	No
Intended Deregistration Date:	23 Jan 2019
Vehicle Make:	TOYOTA
Vehicle Model:	PICNIC AUTO W/O ROOF RACK
Primary Colour:	Silver
Manufacturing Year:	2007
Engine No.:	1AZ5637827
Chassis No.:	JTEGH23B500024080
Maximum Power Output:	110.0 kW (147 bhp)
Open Market Value:	\$24,702.00
Original Registration Date:	31 Jul 2007
First Registration Date:	31 Jul 2007
Transfer Count:	2
Actual ARF Paid:	\$27,173.00
Intended PARF Rebate Details	
PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	30 Jul 2022
COE Category:	E - Open Category
COE Period(Years):	5
PQP Paid:	\$26,237.00
COE Rebate Amount:	\$18,464.00
<b>Total Rebate Amount:</b>	<b>\$18,464.00</b>
Message	
Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 23 Jan 2019

OK

**► Picnic Used Vehicle List (19 vehicles)**

Car Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Company	Availabi
<b>Toyota Picnic 2.0A (COE till 05/2022)</b>	<b>\$22,800</b>	<b>\$6,800 /yr</b>	<b>19-Jun-2007</b>	<b>1,998 cc</b>	<b>-</b>	<b>Boeki Auto &amp; Marine</b>	<b>Availal</b>
Trade In All Available, Interested Please Call For Viewing, Viewing By Appointment Only. Office No. - 65549390 BOEKI - 82180500							
<b>Toyota Picnic 2.0A (COE till 11/2022)</b>	<b>\$23,800</b>	<b>\$6,170 /yr</b>	<b>18-Jan-2008</b>	<b>1,998 cc</b>	<b>128,000 km</b>	<b>Boeki Auto &amp; Marine</b>	<b>Availal</b>
High Loan And Trade In All Available, Interested Please Call For Viewing, Viewing By Appointment Only. Office No. - 65549390 Boeki - 82180500							
<b>Toyota Picnic 2.0A (COE till 05/2022)</b>	<b>\$26,800</b>	<b>\$8,040 /yr</b>	<b>24-May-2007</b>	<b>1,998 cc</b>	<b>-</b>	<b>Classic Credit Pte Ltd</b>	<b>Availal</b>
\$600+ Low Monthly. Best Condition. Very Well Maintained. Up To 90% Flexible Loan. We Provide Lowest Interest Rate. Flexible Loan And Hi Trade In Are Available. Package With Unrivaed Warranty Comple... Office No. - 68412076 / 68481203 / 68414849 Hui - 93705799   Roland - 97479331   Mr Chen - 90044461							
<b>Toyota Picnic 2.0A (COE till 04/2022)</b>	<b>\$27,800</b>	<b>\$8,530 /yr</b>	<b>27-Apr-2007</b>	<b>1,998 cc</b>	<b>-</b>	<b>GV Credit Pte Ltd</b>	<b>Availal</b>
2.88% Per Annum Lowest Interest At \$688 Monthly For Toyota Picnic. \$0 Admin Fees For All GV Purchase. 2 Years Warranty For Engine And Gearbox. Add Ons Available. Office No. - 63443344 Mave - 90099586							
<b>Toyota Picnic 2.0A (New 5-yr COE)</b>	<b>\$35,666</b>	<b>\$7,130 /yr</b>	<b>14-Jan-2009</b>	<b>1,998 cc</b>	<b>112,108 km</b>	<b>Creative Auto</b>	<b>Availal</b>
Drive With Assurance! Cars Are Selling At The Most Reasonable Price With A Peace Of Mind! STA/VICOM Inspection Welcome! Flexible Bank/ House Loan Easy Approval, Top Up \$3k, Low Monthly Installment,... Office No. - - Andychev - 93392128   Tony Chia - 97460421   Terence Leow - 90290899							
<b>Toyota Picnic 2.0A (New 5-yr COE)</b>	<b>\$36,888</b>	<b>\$7,370 /yr</b>	<b>23-Dec-2008</b>	<b>1,998 cc</b>	<b>113,000 km</b>	<b>JDM Cars</b>	<b>Availal</b>
2 Years Warranty Engine And Gearbox! 100% Loan Approval! Bank And In House Loan Available! Trade In Welcome! Priced Lowest In The Market Yet Comes With Accessories! Well Maintained, Excellent Conditio... Office No. - 62994111 John - 90105163   Patrick Wong - 93865066   Yang - 92981269   Paul Cheok - 90666676							
<b>Toyota Picnic 2.0 (New 5-yr COE)</b>	<b>\$36,888</b>	<b>\$7,370 /yr</b>	<b>09-Jan-2009</b>	<b>1,998 cc</b>	<b>-</b>	<b>JDM Cars</b>	<b>Availal</b>
2 Years Warranty Engine And Gearbox! 100% Loan Approval! Bank And In House Loan Available! Trade In Welcome! Priced Lowest In The Market Yet Comes With Accessories! Well Maintained, Excellent Conditio... Office No. - 62994111 Patrick Wong - 93865066   Yang - 92981269   John - 90105163   Paul Cheok - 90666676							
<b>Toyota Picnic 2.0A (COE till 01/2024)</b>	<b>\$37,800</b>	<b>\$7,610 /yr</b>	<b>12-Jan-2009</b>	<b>1,998 cc</b>	<b>75,103 km</b>	<b>Rexy Motor Trading Company</b>	<b>Availal</b>
One Meticulous Owner. Super Low Mileage 7500km Per Year Driven. Always Sheltered And Hardly Driven, Previous Owner Second Car. Car I Tip-top Alike Brand New Condition. Comfortable And Spacious With A... Office No. - 64680082 Desmond - 97323670   Yeo - 97482688   Wayne - 93210015   David Koh - 94551891							
<b>Toyota Picnic 2.0A (New 5-yr COE)</b>	<b>\$39,800</b>	<b>\$7,960 /yr</b>	<b>14-Jan-2009</b>	<b>1,998 cc</b>	<b>120,000 km</b>	<b>Car House Pte Ltd</b>	<b>Availal</b>

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT	
Date Of Report	14/01/2019 17:11
Date Of Accident	12/01/2019 09:20
Exact Location Of Accident	BISHAN ST 22 TURNING TO MARYMOUNT ROAD
Country/State of Loss	SINGAPORE
DETAILS OF OWN VEHICLE	
Vehicle Registration Number	SLE5085D
Insured/Policyholder	
Name Of Registered Owner	DREAM LEASING PTE LTD
Co Reg No	201420013Z
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-81288789
Alternative Phone No	OFFICE-67483762
Vehicle Particulars	
Manufacturer	TOYOTA
Model	PICNIC-2.0 (A)
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE HIRE
Insurance Company	
Name of Insurance Company	EQ INSURANCE COMPANY LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	YES
Policy Number	DMCFHQ18-000142
Cover Note Number	
Driver	
Name of Driver	LUM MUN WAI SHAUN
NRIC No	S9506939H
Date Of Birth	04/03/1995
Occupation	OUTDOOR
Date Of Driving Pass	14/09/2017
Driving Experience	1 YEAR AND 3 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-98308944
Fax Number	
Contact Number	
EEmail Address	JOHNCENA.SHAUN@GMAIL.COM



Address	BLK 246 BISHAN ST 22 #10-338
Postcode	570246
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRED
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

#### Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

REFER TO THE ATTACHED REPORT.

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SKW3306Y
Vehicle Make/Model/Colour	NISSAN
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	ALICIA TOH GUEK GEOK
NRIC/Passport Number	S8241362F
Contact Number	83835428
Address	BLK 273A BISHAN ST 24 #32-106
Postcode	571273
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	



## Sketch Plan

### SKETCH PLAN

#### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
- (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature

Date & Time:

14/1/19

4:35 PM

GUANC SketchPlanForm\_V3

Driver's Signature  
(If driver is not the policyholder)

Date & Time: 14 Jan 2019

16:36 hrs



Reporting Centre Personnel's Signature


Name:

NRIC/FIN No.:

# Sketch Plan #2

A - Pickic SLE 5085D  
B - Nissan SKW 3306Y

## SKETCH PLAN



## DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On the morning of 12 January 2019, Saturday at 0922 hours, I was travelling down Bishan Street 22, making a right turn onto Marymount Road, traffic was slow as the green light appeared, I was travelling at about 10-15 km/h to follow up with traffic. Suddenly I felt an impact on the back, where the other driver (SKW 3306Y) has hit the vehicle at the back (SLE 5085D).

## DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature  
Date & Time: 14/1/19  
4.36pm  
CAREC Sketch Plan #2

Driver's Signature  
(If driver is not the policyholder)  
Date & Time: 14/1/19  
4.36pm

Reporting Centre Personnel's Signature  
Name:  
NRC/FIN No.:



Condition (CON)

(01) Bent (2) Denied (3) Distorted (4) Cracked (5) Cut (6) Scratched  
(07) Deformed (08) Shifted (09) Buckled (10) Broken (11) Necessary  
(12) Missing (13) Turn (14) Unconfirmed (15) Not Working

MOTORCAR (Rear)

Assessment

(1) Replace (✓) (2) Repair (X) (3) Check (0)  
(4) Not Consistent (NC)

Vehicle No:

SLE 5085D

Rear Portion

NAC	INC	Item	CON	AC	Qty
1137	993626	Rear Number Plate			
1138	993627	Rear Number Plate Base			
1139	993630	Rear Number Plate Garnish			
1140	993632	Rear Number Plate Lamp			
1141	992958	Rear Bumper	DD	✓	
1142	993085	Rear Bumper Upper			
1143	993017	Rear Bumper Lower			
1144	993054	Rear Bumper Side			
1145	993103	Rear Bumper Tow Cover			
1146	992341	Rear Bumper Clips	NEC	✓	
1147	992976	Rear Bumper Bracket			
1148	993068	Rear Bumper Side Retainer	BR	✓	2
1149	993045	Rear Bumper Reinforcement			
1150	992970	Rear Bumper Beam			
1151	993077	Rear Bumper Sponge			
1152	992999	Rear Bumper Damper			
1153	993040	Rear Bumper Protector			
1154	993036	Rear Bumper Pad			
1155	993026	Rear Bumper Moulding			
1156	993044	Rear Bumper Reflector			
1157	993023	Rear Bumper Lower Spoiler			
1158	994023	Reverse Sensor	BR	✓	
1159	993327	Rear End Panel	DD	✓	
1160	993339	Rear End Panel Top Garnish	RA	✓	
1161	993333	Rear End Panel Inner Trim			
1162	990333	Boot Compartment Inner Trim			
1163	993851	Rear LH Taillamp			
1164	993853	Rear LH Taillamp Garnish			
1165	993859	Rear LH Taillamp Panel			
1166	995116	Rear RH Taillamp			
1167	993853	Rear RH Taillamp Garnish			
1168	993859	Rear RH Taillamp Panel			
1169	993554	Rear Apron Panel			
1170	992895	Bootlid			
1171	991328	Bootlid Emblem			
1172	990356	Bootlid Handle			
1173	995250	Bootlid Moulding			
1174	990376	Bootlid Reflector			
1175	995222	Bootlid Lamp LH			
1176	992899	Bootlid Lamp RH			
1177	995243	Bootlid Lock	BT	✓	
1178	990377	Bootlid Rubber			
1179	990382	Bootlid Hinge			
1180	993877	Bootlid Spoiler			
1181	994543	Tailgate	DD	✓	
1182	991328	Tailgate Emblem	NEC	✓	3
1183	994643	Tailgate Outer Handle			
1184	994640	Tailgate Moulding			
1185	994545	Tailgate Garnish Trim board	BR	✓	
1186	994648	Tailgate Reflector			
1187	994549	Tailgate Lamp			
1188	994646	Tailgate Protector			
1189	994676	Tailgate Wiper Arm			
1190	994677	Tailgate Wiper Blade			
1191	994679	Tailgate Wiper Nozzle			
1192	994555	Tailgate Wiper Motor			
1193	994602	Tailgate Glass			
1194	994606	Tailgate Glass Rubber			
1195	994604	Tailgate Glass Moulding	NEC	✓	
1196	994607	Tailgate Glass Sealant	NEC	✓	
1197	994629	Tailgate Lock	BT	✓	
1198	994651	Tailgate Rubber	DD	✓	
1199	994611	Tailgate Hinge			
1200	994594	Tailgate Damper			

NAC	INC	Item	CON	AC	Qty
1202	993784	Spare Tyre Board			
1203	994328	Spare Tyre Panel			
1204	995065	Spare Tyre			
1205	994326	Spare Tyre Lock Screw			
1206	993787	Spare Tyre Cover			
1207	995323	Triangle Breakdown Sign			
1208	990507	CD Changer Assy			
1209	990164	Antenna			
1210	990534	Centre Exhaust Pipe Assy			
1211	990532	Centre Exhaust Mounting			
1212	993364	Rear Exhaust Pipe			
1213	993357	Rear Exhaust Chrome Pipe			
1214	993361	Rear Exhaust Mounting			
1215	993358	Rear Exhaust Heat Shield			
1216	995223	Rear LH Chassis Member			
1217	993165	Rear RH Chassis Member			
1218	993436	Rear LH Fender			
1219	993449	Rear LH Fender Protector			
1220	993420	Rear LH Fender Inner Panel			
1221	993431	Rear LH Fender Inner Trim			
1222	993415	Rear LH Fender Inner Garnish			
1223	993425	Rear LH Fender Inner Shield			
1224	993621	Rear LH Mudflap			
1225	993933	Rear LH Wheel Rim			
1226	994025	Rear LH Rim Cover			
1227	995065	Rear LH Tyre			
1228	993456	Rear RH Fender			
1229	993450	Rear RH Fender Protector			
1230	993420	Rear RH Fender Inner Panel			
1231	993431	Rear RH Fender Inner Trim			
1232	993415	Rear RH Fender Inner Garnish			
1233	993425	Rear RH Fender Inner Shield			
1234	993622	Rear RH Mudflap			
1235	993934	Rear RH Wheel Rim			
1236	994025	Rear RH Rim Cover			
1237	995065	Rear RH Tyre			
1238	995162	Rear Fender Extension Panel LH			
1239	993401	Rear Fender Extension Panel RH			
1240	993430	Rear Fender Inner Top Garnish			
1241	993673	Rear Fender 1/4 Glass			
1242	993452	Rear Fender 1/4 Glass Rubber			
1243	993453	Rear Fender 1/4 Glass Sealant			
1244	993949	Rear Windscreen Glass			
1245	993976	Rear Windscreen Rubber			
1246	993961	Rear Windscreen Moulding			
1247	993955	Rear Windscreen Sealant			
1248	994729	Third Brake Light			
1249	993385	Rear Fender Air Grille			
1250	992167	Fuel Lid			
1251	992168	Fuel Neck			
1252	992179	Fuel Tank			
1253	992184	Fuel Tank Bracket			
1254	992191	Fuel Tank Float			
1255	990247	Sticker			

30/11/2019

## ...CLAIM SUBFOLDER...(Pending for Survey Report)

PRI



































## CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	14 Jan 2019 <a href="#">Edit Reg</a>		22 Jan 2019 00:00 <a href="#">Edit Adj Rpt</a>	<b>S\$0.00</b> <a href="#">Edit Estimates</a>	<b>S\$0.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b> <span style="float: right;">[Created by adjuster]</span>									
Insured:	<b>WONG CHEE CHUNG (HUANG ZHIZHONG)</b> , ID: S8006446B								
Main Claimant:	<b>DREAM LEASING PTE LTD</b> , Co. Reg. No.: 201420013Z								
Vehicle Reg. No.:	<b>SLE5085D</b>	Date of Loss:	12/01/2019 09:00 - :59 [137 Months and 12 Days From LTA Reg Date (Man Yr)]						
Claim Type:	<b>TP / 1695273646SG</b>	Policy/Cover Note No.:	2100435340 (Comprehensive)						
Vehicle Reg. No. (Insured):	<b>SKW3306Y</b>	Policy No. (Claimant):							
		Excess:							
Repairer:	<b>Eclipse Auto Pte Ltd (HQ)</b> 155 Kaki Bukit Avenue 1, Shun Li Industrial Park #01-01, 416012 Kaki Bukit - Tel:								
Handling Insurer:	<b>AIG Asia Pacific Insurance Pte. Ltd. (Express)</b> - Tel: 65-6419-3000 ... [Handled by <b>Chan, Kian-Meng</b> ] Kianmeng.Chan1@aig.com								
Adjuster:	<b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [Handled by <b>XING GUO QIANG</b> ] ... [Final Rpt due 31/01/2019]								
<b>ASSOCIATED MAIL RECEIVED</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Compose Case Mail</a></span>									
<ul style="list-style-type: none"> <li>AIG_SG (23/01/2019): Request To Upload TP GIA Report</li> </ul>									
<b>ALL ASSOCIATED TASKS</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a></span>									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## Claim Documents

**\*SLE5085D (1695273646SG)**  
**[SKW3306Y]**  
**TP**  
**DREAM LEASING PTE LTD**  
**Jan 12 2019 9:00AM**  
**[WONG CHEE CHUNG (HUANG ZHIZHONG)]**  
**Eclipse Auto Pte Ltd**

<a href="#">Upload Documents</a>		<a href="#">Upload Photos</a>	<a href="#">Compose New Letter</a>	<a href="#">Upload Video</a>	<a href="#">Upload Audio</a>	<b>View</b> <a href="#">View in Browser</a>	
<b>Assessment Reports</b>						1 per page	<input checked="" type="checkbox"/>
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)		Thumbnail	Print		
1	23/01/19 13:25	<b>Accident Statement</b> From: SC - Reg. No: SKW3306Y, Claimant: WONG CHEE CHUNG (HUANG ZHIZHONG)		 Load HTM			
<b>Photos/Images</b>						3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print		
1	25/01/19 11:18	General View		 Load JPG	<input checked="" type="checkbox"/>		
2	25/01/19 11:18	General View		 Load JPG	<input checked="" type="checkbox"/>		
3	25/01/19 11:18	General View		 Load JPG	<input checked="" type="checkbox"/>		
4	25/01/19 11:18	General View		 Load JPG	<input checked="" type="checkbox"/>		
5	25/01/19 11:18	General View		 Load JPG	<input checked="" type="checkbox"/>		
6	25/01/19 11:18	General View		 Load JPG	<input checked="" type="checkbox"/>		
7	25/01/19 11:18	General View		 Load JPG	<input checked="" type="checkbox"/>		
8	25/01/19 11:18	General View		 Load JPG	<input checked="" type="checkbox"/>		
9	25/01/19 11:18	General View		 Load JPG	<input checked="" type="checkbox"/>		
10	25/01/19 11:18	General View		 Load JPG	<input checked="" type="checkbox"/>		
11	25/01/19 11:18	General View		 Load JPG	<input checked="" type="checkbox"/>		
12	25/01/19 11:18	General View		 Load JPG	<input checked="" type="checkbox"/>		
13	25/01/19 11:18	General View		 Load JPG	<input checked="" type="checkbox"/>		
14	25/01/19 11:18	General View		 Load JPG	<input checked="" type="checkbox"/>		
15	25/01/19 11:18	General View		 Load JPG	<input checked="" type="checkbox"/>		
16	25/01/19 11:18	General View		 Load JPG	<input checked="" type="checkbox"/>		
17	25/01/19 11:18	General View		 Load JPG	<input checked="" type="checkbox"/>		
18	25/01/19 11:18	General View		 Load JPG	<input checked="" type="checkbox"/>		
19	25/01/19 11:18	General View		 Load JPG	<input checked="" type="checkbox"/>		
20	25/01/19 11:18	General View		 Load JPG	<input checked="" type="checkbox"/>		
21	25/01/19 11:18	General View		 Load JPG	<input checked="" type="checkbox"/>		
22	25/01/19 11:18	General View		 Load JPG	<input checked="" type="checkbox"/>		
23	25/01/19 11:18	General View		 Load JPG	<input checked="" type="checkbox"/>		
24	25/01/19 11:18	General View		 Load JPG	<input checked="" type="checkbox"/>		
25	25/01/19 11:18	General View		 Load JPG	<input checked="" type="checkbox"/>		
26	25/01/19 11:18	General View		 Load JPG	<input checked="" type="checkbox"/>		
27	25/01/19 11:20	Photographs of Damaged Parts		 Load JPG	<input checked="" type="checkbox"/>		
28	25/01/19 11:20	Photographs of Damaged Parts		 Load JPG	<input checked="" type="checkbox"/>		
29	25/01/19 11:20	Photographs of Damaged Parts		 Load JPG	<input checked="" type="checkbox"/>		
30	25/01/19 11:20	Photographs of Damaged Parts		 Load JPG	<input checked="" type="checkbox"/>		
31	25/01/19 11:20	Photographs of Damaged Parts		 Load JPG	<input checked="" type="checkbox"/>		
32	25/01/19 11:20	Photographs of Damaged Parts		 Load JPG	<input checked="" type="checkbox"/>		
33	25/01/19 11:20	Photographs of Damaged Parts		 Load JPG	<input checked="" type="checkbox"/>		

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
34	25/01/19 11:20	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
35	25/01/19 11:20	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
36	25/01/19 11:20	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
37	25/01/19 11:20	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
38	25/01/19 11:20	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
39	25/01/19 11:20	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
40	25/01/19 11:20	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
41	25/01/19 11:20	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
42	25/01/19 11:20	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
43	25/01/19 11:20	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
44	25/01/19 11:20	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
45	25/01/19 11:20	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
46	25/01/19 11:20	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>

## Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
<b>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</b> <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>			
<b>Show Remarks To:</b> <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AIG19001425/GCD3E2

Date: 31/01/2019

## REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.

Policy No: 2100435340

Claimant Vehicle  
No : SLE5085D

Insured Vehicle No : SKW3306Y

Date of Loss: 12/01/2019

Nature of Claim: TP

Claim No: 1695273646SG

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No: SLE5085D

Make &amp; Model: TOYOTA PICNIC, 2.0 (A)

Engine No: 1AZ5637827

Reg. Date: 31/07/2007 (Man. Year: 2007)

Chassis No: JTEGH23B500024080

Colour: Silver

Odometer: 264500 km

Engine Capacity: 1998 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

## CONDITION OF TYRES

Front Tyre Size:	215/60 R16	Rear Tyre Size:	215/60 R16
Front Left Side:	Haida 5 mm	Rear Left Side:	Haida 5 mm
Front Right Side:	Haida 5 mm	Rear Right Side:	Haida 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Nett Amount (S\$)</b>	<b>0.00</b>	<b>0.00</b>	<b>0.00</b>	

## INSPECTION

Date of Assignment: 22/01/2019

Date Inspected: 22/01/2019 Inspected At:

Eclipse Auto Pte Ltd (HQ)  
155 Kaki Bukit Avenue 1, Shun Li  
Industrial Park #01-01  
Singapore 416012

Estimated Period of Repair: 6.0 days

Adjuster: XING GUO QIANG

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.



## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Dented	0.00 F	*- F
2	1		*REAR BUMPER CLIPS	Necessary	0.00 F	*- F
3	2		*REAR BUMPER SIDE RETAINER	Broken	0.00 F	*- F
4	1		*REVERSE SENSOR	Broken	0.00 F	*- F
5	1		*REAR END PANEL	Dented	0.00 F	*- F
6	1		*REAR END PANEL TOP GARNISH	Cracked	0.00 F	*- F
7	1		*BOOTLID LOCK	Bent	0.00 F	*- F
8	1		*TAILGATE	Dented	0.00 F	*- F
9	3		*TAILGATE EMBLEM	Necessary	0.00 F	*- F
10	1		*TAILGATE TRIM BOARD	Broken	0.00 F	*- F
11	1		*TAILGATE GLASS MOULDING	Necessary	0.00 F	*- F
12	1		*TAILGATE GLASS SEALANT	Necessary	0.00 F	*- F
13	1		*TAILGATE LOCK	Bent	0.00 F	*- F
14	1		*TAILGATE RUBBER	Dented	0.00 F	*- F

F=Franchise part.

<b>Total Parts (\$\$)</b>	<b>0.00</b>	<b>0.00</b>
---------------------------	-------------	-------------

Report was unsubmitted during this print-out.
---

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.
---

< END OF ESTIMATES >