

22/03/2002

ASS. REC. BY:

REF: CS3/ALG/19001428/Gcd302 Special Instruction:

Surveyor:

GUD (Diane)

ASSIGNMENT (Office)

From (Person):

Chin Lee Ying

of

ALG

Date/Time:

22/1/19 @ 11-09am

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLU 2949Y

Insured:

SLU 4774T

at Workshop m/s

Power Autocare

Tel:

81812212 / 9177 8876

of

1 Kaki Bukit Ave 6 # 02-11

Policy No:

2100501792

Claim No:

815969894SG

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

19/01/2019

CA / REV / REP. / REV 24 HRS

lup

H.O.D. Endorsement:

Date/Time:

11-12am @ 22/1/19

Person Contacted:

Gary

Vehicle: IN/OUT

Date/Time

Action/Instruction (X) Estimate

SLU 2949Y - X

SLU 4774T - X

(S&P 1/13)

Surveyor

PMS
Karl

REF:

ALG

1987G

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s

Power Auto Care

of _____

Insured: _____

Policy No. _____

Claims No. _____


Sum Insured: _____

Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rpt: _____

Consistent? : Yes or No

GIA / PR Seen: _____

Consistent? : Yes or No

Est. Repairs: _____

10

days

Res.: _____

Yes or No

Lum Sum: _____

20

%

3 Val.: _____

Yes or No

CA / REV / REP. / 24 HRS

Date: _____

Person Contacted: _____

Vehicle: IN / OUT

Veh No: _____

SLU 29497

Yr Regn: _____

28 Nov 2017

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: _____

Honda Civic GT C.C. 1996

Colour

Red

A/C: Insured / Std / NI / NA

Sp. Reading

T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: _____

SHHEK 2790 FU 701366

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: _____

F: _____

235/35 8R19

R: _____

11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. _____

6

mm

R/Bal. _____

6

mm

L/Bal. _____

6

mm

L/Bal. _____

6

mm

D.O.A. _____

D.O.I. _____

22-01-19

Survey held at

w/s

1223opm

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

RECEIVED 31 JAN 2019

Date/Time, File Pass to?

☐

Preli. Report

1)

☐

Final Report

Date/Time, File Return to?

2)

Days Of Repair: _____

10

Resurvey No. of Trip: _____

-

Survey Fee: _____

Transportation: _____

S + RS, SI

Photos

Others

TOTAL

Add Fee:

☐

Site Insp (\$ _____)

☐

Interview (\$ _____)

☐

Tech. Invs (\$ _____)

☐

Weekend (\$ _____)

Report Format: _____

DAR.

Lump Sum / I.B.I. (\$) _____

180
10
190

- PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURE...

From: Chin, Lee-Ying
To: assignments, Admin A
Cc: Fong, Andy-SY
Sent: 22/1/2019 11:09:04 AM
Attachments:  [tmp6596.tif](#)

Hi LKK,

Kindly assist to survey, vehicle in workshop.

Thanks.

Best Regards

Lee Ying, Chin

AIG

Claims | AIG Asia Pacific Insurance Pte. Ltd.

78 Shenton Way #08-16 Singapore 079120

Tel +(65) 6419 1947

Lee-Ying.Chin@aig.com | www.aig.sg

From: natalie_ng@rssolomon.com [mailto:natalie_ng@rssolomon.com]

Sent: Monday, January 21, 2019 1:07 PM

To: Hor, Yinrul; pearlyn_goh@rssolomon.com

Cc: Fong, Andy-SY; Chin, Lee-Ying; Kaur, Baljit; Abu Kassim, Noor Mariesa; Azlan, Syazairdina; Chan, Yoke Shi; Lim, Sheng Yang; Md Ishak, Mohd Imran; Mithoosingh, Aashweenjeetkaur; natalie_ng@rssolomon.com

Subject: RE: PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SLL4774T AND TP ON DOA

Dear Ms Hor,

We thank you for your email of even date.

We write to inform that our client will be appointing his Independent Surveyors.

In this respect, please arrange your Surveyors to contact Mr. Gary of Power Autocare at mobile no. 81812212 for a pre-repair survey of our client's vehicle located at 1 Kaki Bukit Avenue 6 #02-11 Autobay @ Kaki Bukit Singapore 417883.

Best Regards,

Natalie Ng

For and On Behalf of

R. S. Solomon LLC

Advocates & Solicitors

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

Our Ref. : RSS/1901-7036(PAC) (PD)

Your Ref. :

W: Natalie Ng/Pearlyn Goh

E: natalie_ng@rssolomon.com/pearlyn_goh@rssolomon.com

21 January 2019



R. S. SOLOMON LLC

Advocates & Solicitors | Commissioner for Oaths

By FAX: 6835 7416 & PDX: 8181

AIG Asia Pacific Insurance Pte Ltd

No. 78 Shenton Way

#07-16 Lippo Centre

Singapore 079120

Attn: Motor Claims Dept

Dear Sirs,

PRE-REPAIR SURVEY

ACCIDENT INVOLVING SLU2949Y & SLL4774T & OTHERS ON 19TH JANUARY 2019 AT ABOUT 1345HRS

We act for the owner ("our Client") of vehicle no. SLU2949Y.

2. We hereby notify you of a road traffic accident on 19th January 2019 at about 1345 hours along Pan Island Expressway near Changi Thomson Exit involving our Client's vehicle and vehicle registration no. SLL4774T driven by your insured/insured's driver. A copy of our Client's Singapore Accident Statement is enclosed.

3. As a result of the accident, our Client's vehicle has been damaged. Before our Client proceeds to repair the damaged vehicle, please let us know within 2 working days upon receipt of this notice whether you would like to conduct a pre-repair survey of the vehicle. If we do not receive any reply from you within the stipulated timeline, our Client shall proceed to repair his vehicle without further reference to you.

Yours faithfully,

R. S. SOLOMON LLC
Advocates & Solicitors

Encl.

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	1987G
Vehicle Details	
Vehicle No.:	SLU2949Y
Vehicle to be Exported:	No
Intended Deregistration Date:	23 Jan 2019
Vehicle Make:	HONDA
Vehicle Model:	CIVIC GT TYPE R 2.0 M
Primary Colour:	Red
Manufacturing Year:	2015
Engine No.:	K20C11001465
Chassis No.:	SHHFK2790FU701366
Maximum Power Output:	228.0 kW (305 bhp)
Open Market Value:	\$41,007.00
Original Registration Date:	28 Nov 2017
First Registration Date:	28 Nov 2017
Transfer Count:	0
Actual ARF Paid:	\$49,410.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	27 Nov 2027
PARF Rebate Amount:	\$37,057.00
Intended COE Rebate Details	
COE Expiry Date:	27 Nov 2027
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$57,390.00
COE Rebate Amount:	\$50,758.00
Total Rebate Amount:	\$87,815.00

The information contained herein is correct as at 23 Jan 2019

OK

MBHA19009216 / BH Auto Services Pte Ltd - Sin Ming
 ENTRY DATE & TIME: 10/01/2019 16:31
 SUBMITTED BY: Kelvin Lim Khan Hong

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT	
Date Of Report	19/01/2019 16:31
Date Of Accident	19/01/2019 13:45
Exact Location Of Accident	PIE (TUAS) TO PIE CHANGI THOMSON EXIT AREA
Country/State of Loss	SINGAPORE
DETAILS OF OWN VEHICLE	
Vehicle Registration Number	SLU2949Y
Insured/Policyholder	
Name Of Registered Owner	SHENG SHAOMING
NRIC No	S8511987G
Email Address	UBERSHAO@GMAIL.COM
Mobile Phone No	(LOCAL) +65-97210011
Alternative Phone No	OFFICE-97210011
Vehicle Particulars	
Manufacturer	HONDA
Model	CIVIC-2.0 TYPE-R (M)
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	REPORTING ONLY
Vehicle Category	PRIVATE CAR
Insurance Company	
Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	GA295538/1
Cover Note Number	
Driver	
Name of Driver	SHENG SHAOMING
NRIC No	S8511987G
Date Of Birth	04/04/1985
Occupation	INDOOR
Date Of Driving Pass	22/02/2007
Driving Experience	11 YEARS AND 10 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-97210011
Fax Number	
Contact Number	OFFICE-97210011
Email Address	UBERSHAO@GMAIL.COM

Address 99 CLUNY PARK ROAD #03-03 SINGAPORE 257496.
 Postcode
 Was driver an employee of the Insured's Company NO
 If No, Relationship of the Driver with the Insured OWNER
 Vehicle Registration Number of Driver's Own Vehicle -
 -
 Insurance Company of Driver's Own Vehicle -
 -
 -

General Information of the Accident

Type Of Accident CHAIN COLLISION
 Weather Conditions CLEAR
 Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
 Number of vehicles (including own vehicle) involved in the accident 5
 Was any body injured in the Accident? NO
 Was any injured conveyed to hospital by ambulance? NO
 Was any other material or property damaged? YES
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. YES
 Number of Passengers (Including Driver) 1

Details of Police Action

Was the accident reported to the police? NO
 If Yes, Please state which Police Station
 Was notice of intended Prosecution given? NO
 If Yes, against whom?

Circumstances of Accident

PLEASE REFER ACCIDENT STATEMENT.

Attachment(s)

Are accident photos available for attachment? YES
 Was there any video captured by Car Camera? YES
 Remarks/ Reasons: FILE TO BIG
 Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SLL4774T
 Vehicle Make/Model/Colour *Mercedes benz C180*
 Details Of Properties
 Vehicle Category PRIVATE CAR
 Name of Driver
 NRIC/Passport Number
 Contact Number
 Address
 Postcode
 Insurance Company Name
 Nature Of Damage
 No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number SMA3391S
Vehicle Make/Model/Colour
Details Of Properties
Vehicle Category PRIVATE CAR
Name of Driver
NRIC/Passport Number
Contact Number
Address
Postcode
Insurance Company Name
Nature Of Damage
No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 3

Vehicle Registration Number SKX6626Z
Vehicle Make/Model/Colour
Details Of Properties
Vehicle Category PRIVATE CAR
Name of Driver
NRIC/Passport Number
Contact Number
Address
Postcode
Insurance Company Name
Nature Of Damage
No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 4

Vehicle Registration Number SLZ8709H
Vehicle Make/Model/Colour
Details Of Properties
Vehicle Category PRIVATE CAR
Name of Driver
NRIC/Passport Number
Contact Number
Address
Postcode
Insurance Company Name
Nature Of Damage
No. Of Passenger (Including Driver)

Accident Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodging of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforementioned.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [Form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the making of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages), and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes, and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims
- (e) the information so collected under (a) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders



Policyholder's Signature
Date & Time


Driver's Signature
(If driver is not the policyholder)
Date & Time


Reporting Centre Personnel's Signature
Name
NRIC / IIN No

Accident Sketch Plan

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

ON THE 19 JAN 2019 I WAS DRIVING ON THE PIE (CHANGI). THE CAR IN FRONT OF ME SL28709H SUDDENTLY BRAKED SO I JAM BRAKED IN REACTION TO THIS. THE CAR BEHIND ME (SLU4774T) ALSO JAM BRAKED BUT HE KNOCKED INTO ME AND I KNOCKED THE CAR IN FRONT OF ME (SL28709H). ROUGH TIME OF ACCIDENT: 13.5 HRS.

DECLARATION

I/We declare the foregoing particulars are true in every respect


 Policyholder's Signature
 Date & Time:

Driver's Signature
 (If driver is not the policyholder)
 Date & Time


 Reporting Centre Personnel's Signature
 Name:
 NRIC/ID No:

$$1 \leq f_{\text{max}}/f_{\text{min}} \leq 10^3$$

30/1/2019

PAC	INC	Item	Qty
1071	993205	Purge Box	
1072	994041	Relay Box	
1073	995053	Wiper Washer Tank	
1074	995052	Wiper Washer Tank Motor	
1075	990159	Alternator Assy	
1076	990160	Alternator Belt	
1077	992688	Power Steering Pump	
1078	992669	Power Steering Belt	
1079	994431	Power Steering Cooler Pipe	
1080	992692	Power Steering Hose	
1081	990010	ABS Pump Control Unit	
1082	990427	Brake Master Pump Assy	
1083	990403	Brake Booster Pump Assy	
1084	991005	Engine Top Cover	
1085	991011	Engine Under Cover	
1086	990946	Engine Mounting	
1087	990949	Engine Mounting Frt	
1088	990950	Engine Mounting LH	
1089	990952	Engine Mounting RH	
1090	990951	Engine Mounting Rear	
1091	992234	Gear Box Mounting	
1092	991520	Frt LH Chassis Member	
1093	991520	Frt RH Chassis Member	
1094	990728	Frt Vertical Cross Member	
1095	991863	Frt Lower Cross Member	
1096	995070	Frt LH Fender	
1097	995072	Frt LH Fender Inner Panel	
1098	995147	Frt LH Fender Lamp	
1099	995148	Frt LH Fender Protector	
1100	991740	Frt LH Fender Inner Shield	
1101	995179	Frt LH Mudflap	
1102	995170	Frt LH Wheel Rim	
1103	994025	Frt LH Rim Cover	
1104	995065	Frt LH Tyre	
1105	995071	Frt RH Fender	
1106	991739	Frt RH Fender Inner Panel	
1107	991744	Frt RH Fender Lamp	
1108	991752	Frt RH Fender Protector	
1109	991740	Frt RH Fender Inner Shield	
1110	991834	Frt RH Mudflap	
1111	992087	Frt RH Wheel Rim	
1112	994025	Frt RH Rim Cover	
1113	995065	Frt RH Tyre	
1114	992093	Frt Windscreen Glass	
1115	992117	Frt Windscreen Rubber	
1116	992108	Frt Windscreen Moulding	
1117	992096	Frt Windscreen Sealant	
1118	991019	FRT Bucket	
1119	991020	ERP Unit	
1120	992140	Frt Wiper Arm	
1121	992142	Frt Wiper Blade	
1122	995045	Wiper Panel Garnish	
1123	991126	Firewall Panel	
1124	990753	Dashboard Assy	
1125	992282	Glove Box Cover	
1126	992281	Glove Box Compartment	
1127	994453	Steering Wheel Airbag	
1128	994455	Steering Wheel Airbag Sensor	
1129	990749	Dashboard Airbag	
1130	990750	Dashboard Airbag Sensor	
1131	990029	Airbag Control Unit	
1132	990264	Frt Driver Seat	
1133	991600	Frt RH Seat Belt Assy	
1134	991299	Frt Passenger Seat	
1135	995143	Frt LH Seat Belt Assy	
1136	990747	Trailer	

Condition (CON)

(01) Bent (2) Denied (3) Distorted (4) Cracked (5) Cut (6) Scratched
(07) Deformed (08) Shifted (09) Buckled (10) Broken (11) Necessary
(12) Missing (13) Torn (14) Unconfirmed (15) Not Working

MOTORCAR (Rear)

(1) Replace (✓) (2) Repair (X) (3) Check (C)
(4) Not Consistent (NC)

Vehicle No:

SLU 2949Y (282)

Rear Portion

NAC	INC	Item	CON	AC	Qty
1137	993626	Rear Number Plate			
1138	993627	Rear Number Plate Base			
1139	993630	Rear Number Plate Garnish			
1140	993632	Rear Number Plate Lamp			
1141	992958	Rear Bumper	DU	✓	
1142	993085	Rear Bumper Upper			
1143	993017	Rear Bumper Lower			
1144	993054	Rear Bumper Side			
1145	993103	Rear Bumper Tow Cover			
1146	992341	Rear Bumper Clips	NEC	✓	
1147	992976	Rear Bumper Bracket			
1148	993068	Rear Bumper Side Retainer	BR	✓	2
1149	993045	Rear Bumper Reinforcement			
1150	992970	Rear Bumper Beam			
1151	993077	Rear Bumper Sponge			
1152	992999	Rear Bumper Damper			
1153	993040	Rear Bumper Protector			
1154	993036	Rear Bumper Pad			
1155	993026	Rear Bumper Moulding			
1156	993044	Rear Bumper Reflector	BR	✓	
1157	993023	Rear Bumper Lower Spoiler	BR	✓	
1158	994023	Reverse Sensor	BR	✓	
1159	993327	Rear End Panel		R	
1160	993339	Rear End Panel Top Garnish			
1161	993333	Rear End Panel Inner Trim			
1162	990333	Boot Compartment Inner Trim			
1163	993851	Rear LH Taillamp			
1164	993853	Rear LH Taillamp Garnish			
1165	993859	Rear LH Taillamp Panel			
1166	995116	Rear RH Taillamp			
1167	993853	Rear RH Taillamp Garnish			
1168	993859	Rear RH Taillamp Panel			
1169	993554	Rear Apron Panel			
1170	992895	Bootlid			
1171	991328	Bootlid Emblem			
1172	990356	Bootlid Handle			
1173	995250	Bootlid Moulding			
1174	990376	Bootlid Reflector			
1175	995222	Bootlid Lamp LH			
1176	992899	Bootlid Lamp RH			
1177	995243	Bootlid Lock			
1178	990377	Bootlid Rubber	CRU	✓	
1179	990382	Bootlid Hinge			
1180	993877	Bootlid Spoiler			
1181	994543	Tailgate			
1182	991328	Tailgate Emblem			
1183	994643	Tailgate Outer Handle			
1184	994640	Tailgate Moulding			
1185	994545	Tailgate Garnish	BR	✓	
1186	994648	Tailgate Reflector			
1187	994549	Tailgate Lamp			
1188	994646	Tailgate Protector			
1189	994676	Tailgate Wiper Arm			
1190	994677	Tailgate Wiper Blade			
1191	994679	Tailgate Wiper Nozzle			
1192	994555	Tailgate Wiper Motor			
1193	994602	Tailgate Glass			
1194	994606	Tailgate Glass Rubber			
1195	994604	Tailgate Glass Moulding			
1196	994607	Tailgate Glass Sealant			
1197	994629	Tailgate Lock			
1198	994651	Tailgate Rubber			
1199	994611	Tailgate Hinge			
1200	994594	Tailgate Damper			

NAC	INC	Item	CON	AC	Qty
1202	993784	Spare Tyre Board			
1203	994328	Spare Tyre Panel			
1204	995065	Spare Tyre			
1205	994326	Spare Tyre Lock Screw			
1206	993787	Spare Tyre Cover			
1207	995323	Triangle Breakdown Sign			
1208	990507	CD Changer Assy			
1209	990164	Antenna			
1210	990534	Centre Exhaust Pipe Assy			
1211	990532	Centre Exhaust Mounting			
1212	993364	Rear Exhaust Pipe		?	
1213	993357	Rear Exhaust Chrome Pipe	BT	✓	
1214	993361	Rear Exhaust Mounting			
1215	993358	Rear Exhaust Heat Shield			
1216	995223	Rear LH Chassis Member			
1217	993165	Rear RH Chassis Member			
1218	993436	Rear LH Fender			
1219	993449	Rear LH Fender Protector			
1220	993420	Rear LH Fender Inner Panel			
1221	993431	Rear LH Fender Inner Trim			
1222	993415	Rear LH Fender Inner Garnish			
1223	993425	Rear LH Fender Inner Shield			
1224	993621	Rear LH Mudflap			
1225	993933	Rear LH Wheel Rim			
1226	994025	Rear LH Rim Cover			
1227	995065	Rear LH Tyre			
1228	993456	Rear RH Fender			
1229	993450	Rear RH Fender Protector			
1230	993420	Rear RH Fender Inner Panel			
1231	993431	Rear RH Fender Inner Trim			
1232	993415	Rear RH Fender Inner Garnish			
1233	993425	Rear RH Fender Inner Shield			
1234	993622	Rear RH Mudflap			
1235	993934	Rear RH Wheel Rim			
1236	994025	Rear RH Rim Cover			
1237	995065	Rear RH Tyre			
1238	995162	Rear Fender Extension Panel LH			
1239	993401	Rear Fender Extension Panel RH			
1240	993430	Rear Fender Inner Top Garnish			
1241	993673	Rear Fender 1/4 Glass			
1242	993452	Rear Fender 1/4 Glass Rubber			
1243	993453	Rear Fender 1/4 Glass Sealant			
1244	993949	Rear Windscreen Glass			
1245	993976	Rear Windscreen Rubber			
1246	993961	Rear Windscreen Moulding			
1247	993955	Rear Windscreen Sealant			
1248	994729	Third Brake Light			
1249	993385	Rear Fender Air Grille			
1250	992167	Fuel Lid			
1251	992168	Fuel Neck			
1252	992179	Fuel Tank			
1253	992184	Fuel Tank Bracket			
1254	992191	Fuel Tank Float			
1255	990247	Sticker			

...CLAIM SUBFOLDER...(Pending for Survey Report)

PRI

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	22 Jan 2019 Edit Reg		22 Jan 2019 00:00 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured: -, Co. Reg. No.: -									
Main Claimant: SHENG SHAOMING , ID: S8511987G									
Vehicle Reg. No.: SLU2949Y		Date of Loss: 19/01/2019 13:00 - :59 [13 Months and 22 Days From LTA Reg Date (Man Yr)]							
Claim Type: TP / 8115969894SG		Policy/Cover Note No.: 2100501792							
Vehicle Reg. No. (Insured): SLL4774T		Policy No. (Claimant):							
		Excess:							
Repairer: Power Autocare (HQ) 1 Kaki Bukit Ave 6, #02-11 Kai Bukit @ Autobay, 417883 Kaki Bukit - Tel:									
Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Lee, Ming-Yao] MingYao.Lee@aig.com									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Final Rpt due 31/01/2019]									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
- AIG_SG (23/01/2019): Request To Upload TP GIA Report - AIG_SG (23/01/2019): No Policy Found									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SLU2949Y (8115969894SG)
[SLL4774T]
TP
SHENG SHAOMING
Jan 19 2019 1:00PM
[-]
Power Autocare

Upload Documents			Upload Photos			Compose New Letter			Upload Video			Upload Audio			View		View in Browser	
Photos/Images															3 per page		☒	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)														Thumbnail	Print	
1	25/01/19 10:30	General View														Load JPG	☒	
2	25/01/19 10:30	General View														Load JPG	☒	
3	25/01/19 10:30	General View														Load JPG	☒	
4	25/01/19 10:30	General View														Load JPG	☒	
5	25/01/19 10:30	General View														Load JPG	☒	
6	25/01/19 10:30	General View														Load JPG	☒	
7	25/01/19 10:30	General View														Load JPG	☒	
8	25/01/19 10:30	General View														Load JPG	☒	
9	25/01/19 10:30	General View														Load JPG	☒	
10	25/01/19 10:30	General View														Load JPG	☒	
11	25/01/19 10:30	General View														Load JPG	☒	
12	25/01/19 10:30	General View														Load JPG	☒	
13	25/01/19 10:30	General View														Load JPG	☒	
14	25/01/19 10:30	General View														Load JPG	☒	
15	25/01/19 10:30	General View														Load JPG	☒	
16	25/01/19 10:30	General View														Load JPG	☒	
17	25/01/19 10:30	General View														Load JPG	☒	
18	25/01/19 10:30	General View														Load JPG	☒	
19	25/01/19 10:30	General View														Load JPG	☒	
20	25/01/19 10:30	General View														Load JPG	☒	
21	25/01/19 10:30	General View														Load JPG	☒	
22	25/01/19 10:30	General View														Load JPG	☒	
23	25/01/19 10:30	General View														Load JPG	☒	
24	25/01/19 10:30	General View														Load JPG	☒	
25	25/01/19 10:30	General View														Load JPG	☒	
26	25/01/19 10:30	General View														Load JPG	☒	
27	25/01/19 10:30	General View														Load JPG	☒	
28	25/01/19 10:30	General View														Load JPG	☒	
29	25/01/19 10:30	General View														Load JPG	☒	
30	25/01/19 10:30	General View														Load JPG	☒	
31	25/01/19 10:30	General View														Load JPG	☒	
32	25/01/19 10:30	General View														Load JPG	☒	
33	25/01/19 10:30	General View														Load JPG	☒	
34	25/01/19 10:30	General View														Load JPG	☒	
35	25/01/19 10:30	General View														Load JPG	☒	
36	25/01/19 10:30	General View														Load JPG	☒	
37	25/01/19 10:30	General View														Load JPG	☒	

Photos/Images			3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
38	25/01/19 10:30	General View	 Load JPG	☒
39	25/01/19 10:30	General View	 Load JPG	☒
40	25/01/19 10:30	General View	 Load JPG	☒
41	25/01/19 10:30	General View	 Load JPG	☒
42	25/01/19 10:30	General View	 Load JPG	☒

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)
Show Remarks To: ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AIG19001428/GCD3E2

Date: 31/01/2019

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.

Policy No: 2100501792

Claimant Vehicle No : SLU2949Y

Insured Vehicle No : SLL4774T

Date of Loss: 19/01/2019

Nature of Claim: TP

Claim No: 8115969894SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SLU2949Y

Make & Model: HONDA CIVIC, 2.0 TYPE-R (M)

Engine No: K20C11001465

Reg. Date: 28/11/2017 (Man. Year: 2015)

Chassis No: SHHFK2790FU701366

Colour: Red

Odometer: 0 km

Engine Capacity: 1996 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification:

No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 235/35Z R19

Rear Tyre Size: 235/35Z R19

Front Left Side: Bridgestone 6 mm

Rear Left Side: Bridgestone 6 mm

Front Right Side: Bridgestone 6 mm

Rear Right Side: Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 22/01/2019

Date Inspected: 22/01/2019 Inspected At:

Power Autocare (HQ)
1 Kaki Bukit Ave 6, #02-11 Kai Bukit @
Autobay
Singapore 417883

Estimated Period of Repair: 10.0 days

Adjuster: XING GUO QIANG

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT NUMBER PLATE	Broken	0.00 F	*- F
2	1		*FRT NUMBER PLATE BASE	Broken	0.00 F	*- F
3	1		*FRT NUMBER PLATE GARNISH	Cut	0.00 F	*- F
4	1		*FRT BUMPER	Dented	0.00 F	*- F
5	1		*FRT BUMPER CLIPS	Necessary	0.00 F	*- F
6	1		*FRT BUMPER SIDE RETAINER	Broken	0.00 F	*- F
7	1		*FRT BUMPER GRILLE	Distorted	0.00 F	*- F
8	1		*FRT BUMPER SENSOR	Broken	0.00 F	*- F
9	1		*FRT LH BUMPER FOG LAMP COVER	* Check	0.00 F	*- F
10	1		*FRT RH BUMPER FOG LAMP COVER	* Check	0.00 F	*- F
11	1		*FRT LH BUMPER FOG LAMP	* Check	0.00 F	*- F
12	1		*FRT RH BUMPER FOG LAMP	* Check	0.00 F	*- F
13	1		*FRT GRILLE	Broken	0.00 F	*- F
14	1		*FRT GRILLE EMBLEM	Cut	0.00 F	*- F
15	1		*FRT SUPPORT PANEL	Bent	0.00 F	*- F
16	1		*FRT SUPPORT PANEL TOP GARNISH COVER	Cut	0.00 F	*- F
17	1		*FRT LH HEADLAMP ASSY	Broken	0.00 F	*- F
18	1		*FRT RH HEADLAMP ASSY	Broken	0.00 F	*- F
19	1		*BONNET	Dented	0.00 F	*- F
20	1		*BONNET LOCK	Bent	0.00 F	*- F
21	2		*BONNET HINGE	Bent	0.00 F	*- F
22	1		*BONNET RUBBER	Torn	0.00 F	*- F
23	1		*AIR CON CONDENSER	* Check	0.00 F	*- F
24	1		*RADIATOR	* Check	0.00 F	*- F
25	1		*RADIATOR FAN ASSY	* Check	0.00 F	*- F
26	1		*REAR BUMPER	Dented	0.00 F	*- F
27	1		*REAR BUMPER CLIPS	Necessary	0.00 F	*- F
28	2		*REAR BUMPER SIDE RETAINER	Broken	0.00 F	*- F
29	1		*REAR BUMPER REFLECTOR	Broken	0.00 F	*- F
30	1		*REAR BUMPER LOWER SPOILER	Broken	0.00 F	*- F
31	1		*REVERSE SENSOR	Broken	0.00 F	*- F
32	1		*REAR END PANEL	Repair	0.00 F	*- F
33	1		*BOOTLID RUBBER	Crumpled	0.00 F	*- F
34	1		*TAILGATE GARNISH	Broken	0.00 F	*- F
35	1		*REAR EXHAUST PIPE	* Check	0.00 F	*- F
36	1		*REAR EXHAUST CHROME PIPE	Bent	0.00 F	*- F
37	1		*BONNET INSULATOR	Crumpled	0.00 F	*- F

F=Franchise part.

Total Parts (S\$)	0.00	0.00
--------------------------	-------------	-------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >