

INS. CASE OWNER:

CC 6, Mb 1900 1446, Uoasg

LKK: IDAC:

MARINS

ASSIGNMENT

DOI: 22/11/19

Date / Time: 22/11/19

Registered in Merimen: 22/11/19

Pre-assign / CCU / FTE



Insured Vehicle No.: SMG 2210  
Name of Insured: Atlantic Supplies & Trading pte  
Insured Tel No.: HP:  
Excess Sec II :SS D.O.A: 12/01/19  
Is driver the owner? (YES / NO) Nature of Accident:

Claim No.:  
Policy No.:  
Make / Model :  
Place of Accident :

If NO, Driver Name / Age:

Driver Tel No.: (V/L: YES / NO)

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability: % Final? Yes / No

FBB 1524 P



INSRS: WSP: BHH  
Tel:  
Liability:  
RMKS:



INSRS: WSP:  
Tel:  
Liability:  
RMKS:



INSRS: WSP:  
Tel:  
Liability:  
RMKS:



INSRS: WSP:  
Tel:  
Liability:  
RMKS:

Date/Time

Date/Time	STAGE	DATE / PIC
22/11/19	Non-Reporting ltr (1st):	
	Non-Reporting ltr (2nd):	
	Non-Reporting ltr (Final):	
18/11/19	Notification ltr (if non-pickup):	
	Call OE: LORNA 18/11/19	VIC-OL
	After call ltr to OE: LORNA 20/11/19	
20/11/19	Documentation Check List:	Handler Typist
	Notification ltr (if non-pickup)	<input type="checkbox"/>
	After call ltr to OE:	<input checked="" type="checkbox"/>
	Authorisation To Act:	<input checked="" type="checkbox"/>
	Release Voucher:	<input checked="" type="checkbox"/>
	Final Repair Bill:	<input checked="" type="checkbox"/>
	Car Rental Invoice:	<input type="checkbox"/>
	Towing Invoice:	<input type="checkbox"/>
	LTA / GIA :	<input checked="" type="checkbox"/>
	Medical Bill:	<input type="checkbox"/>
	PIR:	<input type="checkbox"/>
	Mandate/Reject Instruction:	<input type="checkbox"/>
	LOD	<input checked="" type="checkbox"/>
	Payment Breakdown Form:	<input type="checkbox"/>
	Post-Repair Photos:	<input type="checkbox"/>
	Others:	<input type="checkbox"/>

PRELIMINARY ADVICE Date/Time: Sent By:

FINALIZATION Date/Time: Confirm with: Confirm by: OKs

Repair Cost: SS 2,090 ( 5 days) Reduction: 55 % Email  Call

FINAL SETTLEMENT Date/Time: 21.10.19 Confirm with: RAYMOND Email  Call

Final Liability: 100% % 50 (Agreed / Assessed) BOLA S/N No.: 720

Repair Cost: SS 1,996.50

Loss of Rental (LOR): - SS - ( days)

Loss of Use (LOU): +100.00 SS 50.00 (5 30 x 5 days)

Loss of Income (LOI): - SS - (5 x days)

LOR only  LOU only  LOR + LOU  LOR + LOI  [Tick only one]

GIA/LTA Search +200 SS 200

- 1) Claim status: Normal/Reject/Private Settle
- 2) Report Format: TP
- 3) Survey fee: 300

Total: +2,295.50 SS 1,448.75 Global Sum SS: 1,150

FINAL PAYMENT Date/Time: 21.10.19 Confirm with: RAYMOND Email  Call

Payee 1: SS 1,150.00 Name 1: BAY HOOK HIRE CO PTE LTD

Payee 2: Name 2:

Payee 3: Name 3:

ASS. REC. BY: MD/16/1

REG. ALB

**ASSIGNMENT**

From: \_\_\_\_\_ Date: \_\_\_\_\_  
 Estimated Cost: \_\_\_\_\_  
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV  
 To inspect Vehicle No: FBB1524P  
 at Workshop n/s: SM/M  
 of: SMG 2 2110  
 Insured: \_\_\_\_\_  
 Policy No: \_\_\_\_\_  
 Claims No: \_\_\_\_\_  
 Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_  
 (Client's Record)  
 Make of Veh: \_\_\_\_\_

(Policy Condition)  
 Remark: The veh had commenced its repair at the time of inspection.  

<input checked="" type="checkbox"/>	N/S	O/S
<input checked="" type="checkbox"/>		

  
 Bal. or Market Value: 5500  
 IDAC Accident Rpt: \_\_\_\_\_ Consistant? : Yes or No  
 GIA / PR Seen: \_\_\_\_\_ Consistant? : Yes or No  
 Est. Repairs: 5 days Res: Yes or No  
 Lum Sum: 20 % 3 Val: Yes or No  
 CA / REV / REP. / 24 HRS 9 3557  
 Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_  
 Vehicle: IN / OUT 5-15-2024

Veh No: FBB1524P Tr Regn: 12 04  
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /  
 Truck / Trailer or \_\_\_\_\_  
 Make: PIAGGIO Vespa cc 198  
 Colour: Blue A/C: Insured / Std / Nil / NA  
 Sp. Reading: 9655 TRadio: Insured / Std / Nil / NA  
 Eng No: \_\_\_\_\_  
 Chassis: ZAPM3120000021477  
 Gen. Cond: Good / Fair / Poor / Burnt  
 Steering: Order / Jammed / Leaked / Burnt or \_\_\_\_\_  
 Brake: Order / Jammed / Leaked / Burnt or \_\_\_\_\_  
 Mod: Nil / S/Rim / STD A/Rim or \_\_\_\_\_  
 Tyre Size: F: 120-70-12  
 R: 130-70-12  
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  
 TOYO / YOKO or \_\_\_\_\_  

Front	<u>6</u>	Rear	<u>6</u>
R/Bal.	mm	R/Bal.	mm
L/Bal.	mm	L/Bal.	mm
D.O.A.	<u>12/1/19</u>	D.O.I.	<u>22/1/19</u>

  
 Survey held at \_\_\_\_\_  
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or  
Rear, n/s Body.  
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
31-3-2024	Call #2050 confirmed with Raymond. agree 50%
	(RED: # 2050 55%)

Date/Time, File Pass to?  : Prel. Report  
 : Final Report

1) \_\_\_\_\_  
 Date/Time, File Return to? \_\_\_\_\_

2) \_\_\_\_\_

Report Format : \_\_\_\_\_  
 Lump Sum / I.B.I: (\$ \_\_\_\_\_)

Days Of Repair: \_\_\_\_\_  
 Resurvey No. of Trip: \_\_\_\_\_

Add Fee:  Site Insp (\$ \_\_\_\_\_)  
 Interview (\$ \_\_\_\_\_)  
 Tech. Invs (\$ \_\_\_\_\_)  
 Weekend (\$ \_\_\_\_\_)

Survey Fee: \_\_\_\_\_  
 Transportation: \_\_\_\_\_  
 Photo: \_\_\_\_\_  
 Others: \_\_\_\_\_  
 TOTAL: \_\_\_\_\_



**QUOTATION**

NO. : 33516

Customer :

AIG ASIA PACIFIC INSURANCE PTE LTD  
CHARTIS BUILDING  
78 SHENTON WAY  
#07-16  
SINGAPORE 079120

DATE : 21/01/2019  
CLAIM NO. : 11245  
POLICY NO. :  
FROM : RAYMOND

VEHICLE NO. : FBB1524P  
MAKE/MODEL : PIAG / GT200

*not added  
2/5/2019  
5 days  
the whole after repair*

(Page 1 of 2)

S/N	Description	Action	Qty	Unit Price	Amount
1	ALIGNMENT BODY P/N: 29561	REPLACE	1.00	\$350.00	350.00
2	ALIGNMENT HANDLE	REPLACE	1.00	\$150.00	150.00 X
3	BALANCER HANDLE LH&RH SILVER P/N: 48159	REPLACE	1.00	\$38.00	38.00
4	BEADING WINDSHIELD LH P/N: 26854	REPLACE	1.00	\$42.00	42.00
5	BEADING WINDSHIELD RH P/N: 30066	REPLACE	1.00	\$42.00	42.00 X
6	COVER CRANKCASE P/N: 44492	REPLACE	1.00	\$432.00	432.00
7	FRONT HANDLEBARS COVER	REPLACE	1.00	\$165.00	165.00 X
8	GLOVE BOX	REPLACE	1.00	\$550.00	550.00
9	LABOUR P/N: 06766 - FOR DISMANTLING AND ASSEMBLING OF PARTS QUOTED.	Supply/Install	8.00	\$35.00	280.00
10	LAMP SIGNAL FRONT LH P/N: 44167	REPLACE	1.00	\$58.00	58.00
11	LEVER BRAKE P/N: 27992	REPLACE	1.00	\$35.00	35.00
12	METER IU (12V) NEW MODEL P/N: 34351	REPLACE	1.00	\$200.00	200.00 X
13	MIRROR SET P/N: 54888	REPLACE	1.00	\$223.00	223.00 X



S/N	Description	Action	Qty	Unit Price	Amount	Amount
14	REFERENCIA	REPLACE	1.00	\$789.00	789.00	789.00 X
15	RUBBER MAINSTAND P/N: 41222	REPLACE	1.00	\$7.00	7.00	7.00 ✓
16	RUBBER MAINSTAND P/N: 41222	REPLACE	1.00	\$7.00	7.00	7.00 ✓
17	RUBBER MAINSTAND P/N: 47482	REPLACE	1.00	\$7.00	7.00	7.00 ✓
18	SPRAY PAINT REAR BOX	Spray	1.00	\$130.00	130.00	130.00 ✓
19	SPRAY PAINTING WHOLE BIKE	Spray	1.00	\$580.00	580.00	580.00 ✓
20	STAND MAIN P/N: 29604	REPLACE	1.00	\$120.00	120.00	120.00 ✓
21	STICKER IU METER (MATTE BLACK) P/N: 55545	REPLACE	1.00	\$15.00	15.00	15.00 ✓
22	STICKER NUMBER PLATE FRONT (BLACK) STRAIGHT P/N: 32921	REPLACE	1.00	\$12.00	12.00	12.00 ✓
23	WINDSHIELD	REPLACE	1.00	\$330.00	330.00	330.00 ✓
<b>SUB TOTAL</b>						<b>\$4,562.00</b>
<b>GST @ 7 %</b>						<b>\$319.34</b>
<b>GRAND TOTAL</b>						<b>\$4,881.34</b>

**50% deposit required before ordering of parts.**

Validity: 30 days

For & on Behalf of  
**BAN HOCK HIN CO PTE LTD**

Acknowledge & Accepted By



RAYMOND

1626

This quotation is sent via email / LAN-Fax and will bear a computer generated signature.





**QUOTATION**

Customer :

NO. : 33516

- Rev. 1

AIG ASIA PACIFIC INSURANCE PTE LTD  
CHARTIS BUILDING  
78 SHENTON WAY  
#07-16  
SINGAPORE 079120

DATE : 21/01/2019

CLAIM NO. : 11245

POLICY NO. :

FROM : RAYMOND

VEHICLE NO. : FBB1524P  
MAKE/MODEL : PIAG / GT200

(Page 1 of 2)

S/N	Description	Action	Qty	Unit Price	Amount
1	ALIGNMENT BODY P/N: 29561	REPLACE	1.00	\$320.00	320.00
2	BALANCER HANDLE LH&RH SILVER P/N: 48159	REPLACE	1.00	\$38.00	34.20
				Disc %: 10.00	
3	BEADING WINDSHIELD LH P/N: 26854	REPLACE	1.00	\$42.00	37.80
				Disc %: 10.00	
4	COVER CRANKCASE P/N: 44492	REPLACE	1.00	\$432.00	388.80
				Disc %: 10.00	
5	GLOVE BOX	REPLACE	1.00	\$550.00	495.00
				Disc %: 10.00	
6	LABOUR P/N: 06766 - FOR DISMANTLING AND ASSEMBLING OF PARTS QUOTED.	Supply/Install	1.00	\$250.00	250.00
7	LAMP SIGNAL FRONT LH P/N: 44167	REPLACE	1.00	\$58.00	58.00
8	LEVER BRAKE P/N: 27992	REPLACE	1.00	\$35.00	31.50
				Disc %: 10.00	
9	RUBBER MAINSTAND P/N: 41222	REPLACE	1.00	\$7.00	6.30
				Disc %: 10.00	
10	RUBBER MAINSTAND P/N: 41222	REPLACE	1.00	\$7.00	6.30
				Disc %: 10.00	
11	RUBBER MAINSTAND P/N: 47482	REPLACE	1.00	\$7.00	6.30
				Disc %: 10.00	
12	SPRAY PAINT REAR BOX	Spray	1.00	\$120.00	120.00
13	SPRAY PAINTING WHOLE BIKE	Spray	1.00	\$400.00	400.00



*bizSAFE<sub>3</sub>*



<u>S/N</u>	<u>Description</u>	<u>Action</u>	<u>Qty</u>	<u>Unit Price</u>	<u>Amount</u>
14	STAND MAIN P/N: 29604	REPLACE	1.00	\$120.00	108.00
				Disc %: 10.00	
15	STICKER NUMBER PLATE FRONT (BLACK) STRAIGHT P/N: 32921	REPLACE	1.00	\$10.00	10.00
16	WINDSHIELD	REPLACE	1.00	\$330.00	297.00
				Disc %: 10.00	
SUB TOTAL					\$2,569.20
GST @ 7 %					\$179.84
<b>GRAND TOTAL</b>					<b>\$2,749.04</b>

50% deposit required before ordering of parts.

Validity: 30 days

4/5 2050

For & on Behalf of  
**BAN HOCK HIN CO PTE LTD**

Acknowledge & Accepted By



**RAYMOND**

This quotation is sent via email / LAN-Fax and will bear a computer generated signature.



*bizSAFE<sub>3</sub>*



> [Back to OneMotoring](#)

## Enquire PARF/COE Rebate for Registered Vehicle

<b>Vehicle Owner Particulars</b>	
Owner ID Type:	Singapore NRIC
Owner ID:	9355F
<b>Vehicle Details</b>	
Vehicle No.:	FBB1524P
Vehicle to be Exported:	No
Intended Deregistration Date:	23 Jan 2019
Vehicle Make:	PIAGGIO
Vehicle Model:	VESPA GT200A
Primary Colour:	Blue
Manufacturing Year:	2004
Engine No.:	M312M20902
Chassis No.:	ZAPM3120000021477
Maximum Power Output:	-
Open Market Value:	\$3,257.00
Original Registration Date:	16 Dec 2004
First Registration Date:	16 Dec 2004
Transfer Count:	2
Actual ARF Paid:	\$489.00
<b>Intended PARF Rebate Details</b>	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
<b>Intended COE Rebate Details</b>	
COE Expiry Date:	31 Mar 2024
COE Category:	D - Motorcycle
COE Period(Years):	10
PQP Paid:	\$2,474.00
COE Rebate Amount:	\$1,283.00
<b>Total Rebate Amount:</b>	<b>\$1,283.00</b>
<b>Message</b>	

The information contained herein is correct as at 23 Jan 2019

OK

Listing Type	Paid Ad
Brand	Vespa (/listing/usedbike/brand/vespa/)
Model	Vespa GT200A (/listing/usedbike/model/vespa-gt200a/)
Engine Capacity	198cc
Classification	2B
Registration Date	15/11/2006
COE Expiry Date	14/11/2026 (7 years 9 months left)
Mileage	72000km
No. of owners	2
Type of Vehicle	Scooters (/listing/usedbikes/listing/?bike_type=4)

**Price: <sup>SGD</sup>\$6950**

#### DETAILS

Great scooter. Very stylish. Well maintained. I use it everyday to go to work and even long trips within Singapore. New tyres and new battery. I am a private owner.

#### Accessories

Box

#### SIMILAR BIKES

[VIEW ALL \(/LISTING/USEDBIKES/LISTING/\)](#)



Vespa GT200A



Vespa GT200A

[\(/listing/usedbike/vespa-vespa-gt200a/10148/\)](/listing/usedbike/vespa-vespa-gt200a/10148/)

[\(/listing/usedbike/vespa-vespa-gt200a/9884/\)](/listing/usedbike/vespa-vespa-gt200a/9884/)

**Enquire Transfer Fee**

<b>Vehicle Details</b>			
Vehicle No. :	FBB1524P		
Vehicle Type :	P01 - Passenger Scooter		
Vehicle Attachment 1 :	No Attachment		
Vehicle Scheme :	Normal		
Vehicle Make :	PIAGGIO		
Vehicle Model :	VESPA GT200A		
Chassis No. :	ZAPM3120000021477		
Propellant :	Petrol		
Engine No. :	M312M20902		
Engine Capacity :	198 cc		
Maximum Power Output :	-		
Maximum Laden Weight :	-		
Unladen Weight :	138 kg		
Year Of Manufacture :	2004		
Original Registration Date :	16 Dec 2004		
Lifespan Expiry Date :	-		
COE Category :	D - Motorcycle		
PQP Paid :	\$2,474.00		
COE Expiry Date :	31 Mar 2024		
Road Tax Expiry Date :	15 Dec 2019		
Inspection Due Date :	15 Dec 2019		
Intended Transfer Date :	23 Jan 2019		
CO2 Emission :	-		
CO Emission :	-		
HC Emission :	-		
NOx Emission :	-		
PM Emission :	-		
Late renewal fee(s) will be imposed if road tax / lay up has expired. Please use Enquire Road Tax Payable for fee(s) payable.			
Road tax, including Over Payment (if any), of a vehicle will follow the vehicle to the new registered owner when its ownership is being transferred.			
<b>Amount Payable</b>			
	<b>Amount Before GST (S\$)</b>	<b>GST Amount (S\$)</b>	<b>Amount After GST (S\$)</b>
Transfer Fee :	25.00	-	25.00
<b>Total Amount Payable :</b>			<b>25.00</b>

You may print this page for reference.

OK

Print

### ...CLAIM SUBFOLDER...(Pending for Survey Report)

Fastlane

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	15 Jan 2019 <a href="#">Edit Reg</a>		22 Jan 2019 00:00 <a href="#">Edit Adj Rpt</a>	<b>\$92,050.00</b> <a href="#">Edit Estimates</a>	<b>\$92,050.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b>		[Created by adjuster]							
Insured:	<b>ATLANTIC SUPPLIES AND TRADING PTE LTD</b> , Co. Reg. No.: 51112211F								
Main Claimant:	<b>TAN YEW MENG</b> , ID: 58339355F								
Vehicle Reg. No.:	<b>FBB1524P</b>	Date of Loss:	12/01/2019 00:00 - :59 [168 Months and 27 Days From LTA Reg Date (Man Yr)]						
Claim Type:	<b>TP / 6788417395SG</b>	Policy/Cover Note No.:	(Comprehensive) Coverage: 26/12/2018 - 25/12/2019						
Vehicle Reg. No. (Insured):	<b>SMG2211D</b>	Policy No. (Claimant):	PNMC2017-00001745						
Excess:									
Repairer:	<b>Ban Hock Hin Co. Pte Ltd (HQ)</b> No. 6 Defu Lane 4, 539410 Defu Lane - Tel: 62816520								
Handling Insurer:	<b>AIG Asia Pacific Insurance Pte. Ltd. (Express)</b> - Tel: 65-6419-3000 ... [Handled by <b>MdNoor, Norsiah</b> ] Norsiah.MdNoor@aig.com								
Claimant's Insurer:	<b>FWD Singapore Pte. Ltd. (HQ)</b> - Tel: 6727 5700								
Adjuster:	<b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [Handled by <b>MARCUS CHUA</b> ] ... [Final Rpt due 31/01/2019]								
<b>ASSOCIATED MAIL RECEIVED</b>			<a href="#">View All</a>	<a href="#">Compose Case Mail</a>					
• AIG_SG (23/01/2019): TP GIA REPORT									
<b>ALL ASSOCIATED TASKS</b>			<a href="#">View All</a>	<a href="#">Search Tasks</a>					
			<a href="#">Create New Task</a>	<a href="#">Complete</a>					
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## Claim Documents

\*FBB1524P (6788417395SG)  
[SMG2211D]  
TP  
TAN YEW MENG  
Jan 12 2019 12:00AM  
[ATLANTIC SUPPLIES AND TRADING PTE LTD]  
Ban Hock Hin Co. Pte Ltd

Upload Documents		Upload Photos		Compose New Letter		Upload Video		Upload Audio		View <input type="button" value="View in Browser"/>	
<b>Letters/Correspondences</b>										1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)						Thumbnail	Print		
1	{Draft}	Third Party Express Settlement - Payment Breakdown							Edit		
<b>Photos/Images</b>										3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)						Thumbnail	Print		
1	22/01/19 18:35	General View							Load JPG	<input checked="" type="checkbox"/>	
2	22/01/19 18:35	General View							Load JPG	<input checked="" type="checkbox"/>	
3	22/01/19 18:35	General View							Load JPG	<input checked="" type="checkbox"/>	
4	22/01/19 18:35	General View							Load JPG	<input checked="" type="checkbox"/>	
5	22/01/19 18:35	General View							Load JPG	<input checked="" type="checkbox"/>	
6	22/01/19 18:35	General View							Load JPG	<input checked="" type="checkbox"/>	
7	22/01/19 18:35	General View							Load JPG	<input checked="" type="checkbox"/>	
8	22/01/19 18:35	General View							Load JPG	<input checked="" type="checkbox"/>	
9	22/01/19 18:35	General View							Load JPG	<input checked="" type="checkbox"/>	
10	22/01/19 18:35	General View							Load JPG	<input checked="" type="checkbox"/>	
11	22/01/19 18:35	General View							Load JPG	<input checked="" type="checkbox"/>	
12	22/01/19 18:35	General View							Load JPG	<input checked="" type="checkbox"/>	
13	22/01/19 18:35	General View							Load JPG	<input checked="" type="checkbox"/>	
14	22/01/19 18:35	General View							Load JPG	<input checked="" type="checkbox"/>	
15	22/01/19 18:35	General View							Load JPG	<input checked="" type="checkbox"/>	
16	22/01/19 18:35	General View							Load JPG	<input checked="" type="checkbox"/>	
17	22/01/19 18:35	General View							Load JPG	<input checked="" type="checkbox"/>	
18	22/01/19 18:35	General View							Load JPG	<input checked="" type="checkbox"/>	
19	22/01/19 18:35	General View							Load JPG	<input checked="" type="checkbox"/>	
20	22/01/19 18:35	General View							Load JPG	<input checked="" type="checkbox"/>	
21	22/01/19 18:35	General View							Load JPG	<input checked="" type="checkbox"/>	
22	22/01/19 18:35	General View							Load JPG	<input checked="" type="checkbox"/>	
23	22/01/19 18:35	General View							Load JPG	<input checked="" type="checkbox"/>	
24	22/01/19 18:35	General View							Load JPG	<input checked="" type="checkbox"/>	
25	22/01/19 18:35	General View							Load JPG	<input checked="" type="checkbox"/>	
26	22/01/19 18:35	General View							Load JPG	<input checked="" type="checkbox"/>	
27	22/01/19 18:35	General View							Load JPG	<input checked="" type="checkbox"/>	
28	22/01/19 18:35	General View							Load JPG	<input checked="" type="checkbox"/>	
29	22/01/19 18:35	General View							Load JPG	<input checked="" type="checkbox"/>	
30	22/01/19 18:35	General View							Load JPG	<input checked="" type="checkbox"/>	
31	22/01/19 18:35	General View							Load JPG	<input checked="" type="checkbox"/>	
32	22/01/19 18:35	General View							Load JPG	<input checked="" type="checkbox"/>	
33	22/01/19 18:35	General View							Load JPG	<input checked="" type="checkbox"/>	
34	22/01/19 18:35	General View							Load JPG	<input checked="" type="checkbox"/>	
35	22/01/19 18:35	General View							Load JPG	<input checked="" type="checkbox"/>	
36	22/01/19 18:35	General View							Load JPG	<input checked="" type="checkbox"/>	
37	22/01/19 18:35	General View							Load JPG	<input checked="" type="checkbox"/>	
38	22/01/19 18:35	General View							Load JPG	<input checked="" type="checkbox"/>	
39	22/01/19 18:35	General View							Load JPG	<input checked="" type="checkbox"/>	
40	22/01/19 18:35	General View							Load JPG	<input checked="" type="checkbox"/>	

Letters/Correspondences			1 per page	<input checked="" type="checkbox"/>	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
					<input checked="" type="checkbox"/>
41	22/01/19 18:35	General View		Load JPG	<input checked="" type="checkbox"/>
42	22/01/19 18:35	General View		Load JPG	<input checked="" type="checkbox"/>
43	22/01/19 18:35	General View		Load JPG	<input checked="" type="checkbox"/>
44	22/01/19 18:35	General View		Load JPG	<input checked="" type="checkbox"/>
45	22/01/19 18:35	General View		Load JPG	<input checked="" type="checkbox"/>
46	22/01/19 18:35	General View		Load JPG	<input checked="" type="checkbox"/>
47	22/01/19 18:35	General View		Load JPG	<input checked="" type="checkbox"/>
48	22/01/19 18:35	General View		Load JPG	<input checked="" type="checkbox"/>
49	22/01/19 18:35	General View		Load JPG	<input checked="" type="checkbox"/>
50	22/01/19 18:35	General View		Load JPG	<input checked="" type="checkbox"/>
51	22/01/19 18:35	General View		Load JPG	<input checked="" type="checkbox"/>
52	22/01/19 18:35	General View		Load JPG	<input checked="" type="checkbox"/>
53	22/01/19 18:35	General View		Load JPG	<input checked="" type="checkbox"/>
54	22/01/19 18:35	General View		Load JPG	<input checked="" type="checkbox"/>
55	22/01/19 18:35	General View		Load JPG	<input checked="" type="checkbox"/>
56	22/01/19 18:35	General View		Load JPG	<input checked="" type="checkbox"/>
57	22/01/19 18:35	General View		Load JPG	<input checked="" type="checkbox"/>
58	22/01/19 18:35	General View		Load JPG	<input checked="" type="checkbox"/>
59	22/01/19 18:35	General View		Load JPG	<input checked="" type="checkbox"/>
60	22/01/19 18:35	General View		Load JPG	<input checked="" type="checkbox"/>
61	22/01/19 18:35	General View		Load JPG	<input checked="" type="checkbox"/>
62	22/01/19 18:35	General View		Load JPG	<input checked="" type="checkbox"/>
63	22/01/19 18:35	General View		Load JPG	<input checked="" type="checkbox"/>
64	22/01/19 18:35	General View		Load JPG	<input checked="" type="checkbox"/>
65	22/01/19 18:35	General View		Load JPG	<input checked="" type="checkbox"/>
66	22/01/19 18:35	General View		Load JPG	<input checked="" type="checkbox"/>
67	22/01/19 18:35	General View		Load JPG	<input checked="" type="checkbox"/>
68	22/01/19 18:35	General View		Load JPG	<input checked="" type="checkbox"/>
69	22/01/19 18:35	General View		Load JPG	<input checked="" type="checkbox"/>
70	22/01/19 18:35	General View		Load JPG	<input checked="" type="checkbox"/>
71	22/01/19 18:35	General View		Load JPG	<input checked="" type="checkbox"/>
72	22/01/19 18:35	General View		Load JPG	<input checked="" type="checkbox"/>
73	22/01/19 18:35	General View		Load JPG	<input checked="" type="checkbox"/>
74	22/01/19 18:35	General View		Load JPG	<input checked="" type="checkbox"/>
75	22/01/19 18:35	General View		Load JPG	<input checked="" type="checkbox"/>
76	22/01/19 18:35	General View		Load JPG	<input checked="" type="checkbox"/>
77	22/01/19 18:35	General View		Load JPG	<input checked="" type="checkbox"/>
78	22/01/19 18:35	General View		Load JPG	<input checked="" type="checkbox"/>
79	22/01/19 18:35	General View		Load JPG	<input checked="" type="checkbox"/>
80	22/01/19 18:35	General View		Load JPG	<input checked="" type="checkbox"/>
81	22/01/19 18:35	General View		Load JPG	<input checked="" type="checkbox"/>
82	22/01/19 18:35	General View		Load JPG	<input checked="" type="checkbox"/>
83	26/07/19 16:50	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
84	26/07/19 16:50	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
85	26/07/19 16:50	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
86	26/07/19 16:50	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
87	26/07/19 16:50	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
88	26/07/19 16:50	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
89	26/07/19 16:50	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
90	26/07/19 16:50	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
91	26/07/19 16:50	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
92	26/07/19 16:50	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
93	26/07/19 16:50	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
94	26/07/19 16:50	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
95	26/07/19 16:50	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>

Letters/Correspondences			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
96	26/07/19 16:50	Reinspection Photo		<input checked="" type="checkbox"/>
97	26/07/19 16:50	Reinspection Photo		<input checked="" type="checkbox"/>

  

Documentation			1 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	23/01/19 11:59	TP ESTIMATE + TP GIA REPORT		<input type="checkbox"/>
2	24/01/19 09:46	TP ESTIMATE - MARKED		<input type="checkbox"/>
3	14/11/19 10:16	WORKSHOP INVOICE		<input type="checkbox"/>
4	14/11/19 10:16	AUTHORISATION TO ACT FORM		<input type="checkbox"/>
5	14/11/19 10:16	Release Voucher		<input type="checkbox"/>
6	14/11/19 10:16	GIA SEARCH		<input type="checkbox"/>
7	14/11/19 10:16	LOD		<input type="checkbox"/>
8	14/11/19 10:16	LETTER TO OI		<input type="checkbox"/>

  

No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	23/01/19 10:48	OI GIA REPORT		<input type="checkbox"/>

### Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
<b>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</b> <div style="border: 1px solid black; height: 40px; width: 100%;"></div>			
<b>Show Remarks To:</b> <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			



## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607199R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG19001446/UEA3Q2

Date: 14/11/2019

## REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No:  
**Claimant**  
**Vehicle No :** FBB1524P **Insured Vehicle No :** SMG2211D  
**Date of Loss:** 12/01/2019 **Nature of Claim:** TP **Claim No:** 6788417395SG

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No: **FBB1524P**  
 Make & Model: PIAGGIO VESPA GT200A, 198cc Engine No: M312M20902  
 Reg. Date: 16/12/2004 (Man. Year: 2004) Chassis No: ZAPM3120000021477  
 Colour: Blue Odometer: 9655 km  
 Engine Capacity: 198 cc  
 Market Value/New Car Price: N/A  
 Sum Insured (S\$): **Market Value/New Car Price**

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

## CONDITION OF TYRES

Front Tyre Size: 120-70-12 Rear Tyre Size: 130-70-12  
 Front Left Side: Michelin 6 mm Rear Left Side: Michelin 6 mm  
 Front Right Side: 0 mm Rear Right Side: 0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,072.00	1,479.20	1,592.80	51.85
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,490.00	1,090.00	400.00	26.85
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>4,562.00</b>	<b>2,569.20</b>	<b>1,992.80</b>	<b>43.68</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>2,050.00</b>		
(S\$)	4,562.00	2,050.00	2,512.00	55.06
<b>+ GST 7.00/7.00% (S\$)</b>	319.34	143.50	175.84	55.06
<b>Nett Amount (S\$)</b>	<b>4,881.34</b>	<b>2,193.50</b>	<b>2,687.84</b>	<b>55.06</b>
<b>+ Loss of Use (5.0 x S\$20.00/day) (S\$)</b>		100.00		
(S\$)		2,293.50		
<b>Liab Amount (50.00%) (S\$)</b>		<b>1,146.75</b>		
<b>+ Doc/Search Fee (S\$)</b>		2.00		
<b>Nett Liability (S\$)</b>		<b>1,148.75</b>		
<b>Global Sum Settlement (S\$)</b>		<b>1,150.00</b>		

## INSPECTION

Date of Assignment: 22/01/2019  
 Date Inspected: 22/01/2019 Inspected At:

Ban Hock Hin Co. Pte Ltd (HQ)  
No. 6 Defu Lane 4  
Singapore 539410

Estimated Period of Repair: 5.0 days

---

**Adjuster:** MARCUS CHUA

**Manager:** Asher Sng Rong Yi

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BALANCER HANDLE LH & RH SILVER	Scratched	38.00 F	*38.00 FL
2	1		*BEADING WINDSHIELD LH	Cut	42.00 F	*42.00 FL
3	1		*BEADING WINDSHIELD RH	Not Necessary	42.00 F	*- FL
4	1		*COVER CRANKCASE	Cut	432.00 F	*432.00 FL
5	1		*FRONT HANDLEBARS COVER	Not Necessary	165.00 F	*- FL
6	1		*GLOVE BOX	Cut	550.00 F	*550.00 FL
7	1		*LAMP SIGNAL FRONT LH	Cracked	58.00 FS	*58.00 FS
8	1		*LEVER BRAKE	Scratched	35.00 F	*35.00 FL
9	1		*MTER IU (12V) NEW MODEL	Serviceable	200.00 F	*- FL
10	1		*SET MIRROR	Serviceable	223.00 F	*- FL
11	1		*REFERENCIA	Not Necessary	789.00 F	*- FL
12	1		*RUBBER MAINSTAND	Necessary	7.00 F	*7.00 FL
13	1		*RUBBER MAINSTAND	Necessary	7.00 F	*7.00 FL
14	1		*RUBBER MAINSTAND	Necessary	7.00 F	*7.00 FL
15	1		*STAND MAIN	Cut / Bent	120.00 F	*120.00 FL
16	1		*STICKER IU METER (MATTE BLACK)	Not Necessary	15.00 F	*- FL
17	1		*STICKER NUMBER PLATE FRONT (BLACK) STRAIGHT	Necessary	12.00 FS	*10.00 FS
18	1		*WINDSHIELD	Cut	330.00 F	*330.00 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>3,072.00</b>	<b>1,636.00</b>
<b>- List Item Discount on L Items 0.00/10.00% (\$\$)</b>	<b>0.00</b>	<b>156.80</b>
<b>Total Parts (\$\$)</b>	<b>3,072.00</b>	<b>1,479.20</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	ALIGNMENT BODY )	New	350.00	320.00
2	ALIGNMENT HANDLE )	New	150.00	0.00
3	LABOUR-FOR DISMANTLING AND ASSEMBLING OF PARTS QUOTED	New	280.00	250.00
4	SPRAY PAINT REAR BOX	New	130.00	120.00
5	SPRAY PAINTING WHOLE BIKE	New	580.00	400.00
<b>Gross Labour Cost (S\$)</b>			<b>1,490.00</b>	<b>1,090.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >