

ASS. REC. BY:

REF CS3/AIG19001466/Gcd37 Special Instruction

Supervisor

ASSIGNMENT (Office)

From (Person): chin lee ying

of AIG

Date/Time: 22/1/19 @ 2pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SJ2 6468P

Insured:

SDB 99884

at Workshop m/s

Prestige Auto

Tel:

90210057

of

Blk 3023A Ubi Rd 1 #01-64

Policy No:

2100279760

Claim No:

180073998686

Sum Insured:

Excess:

Make of Veh:
(Client's Record)

D.O.A.

19/01/2019

23/1/19

H.O.D. Endorsement:

CA / REV / REP. / REV 24 HRS

(up)

Date/Time:

3:17pm @ 22/1/19

Person Contacted:

Mr chong

Vehicle IN OUT

Date/Time	Action/Instruction (X)	Estimate
	SJ2 6468P - X	
	SDB 99884 - CS3/AIG13017669/Ap92-1	Jua: 30/8/13
	After repair: 28/1/2019.	

PAS
Khal.

REF: A19

ASSIGNMENT

From: _____ Date: 23/1/19

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SJZ 6468P

at Workshop n/s: Prestige Auto

of Blk 3023A Ubi Rd 1 #01-64

Insured: _____

Policy No: _____

Claims No: _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: Mr chong @ 9021 0057

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 86 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS lup

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SJZ 6468P Yr Regn: Sep / 10

Type: M/Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: Toyota wellfire 3.5 C.C. 3456

Colour: Black A/C: Insured / Std / NI / NA

Sp. Reading: 153181 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: 66H 20803 1574

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD / A/Rim or

Tyre Size: F: 235/50R18

R: 11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front	Rear
R/Bal. <u>6</u> mm	R/Bal. <u>6</u> mm
L/Bal. <u>6</u> mm	L/Bal. <u>6</u> mm

D.O.A. _____ D.O.I. 23-01-19

Survey held at w/s 11:50

Des. of Damages: Front / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	\$7000 - \$8000
	MV - 55000
	PV - 32910
	NV - 22090

RECEIVED 31 JAN 2019

Date/Time, File Pass to? : Preli. Report

1) : Final Report

Date/Time, File Return to? _____

Days Of Repair: 6

Resurvey No. of Trip: 1

Survey Fee:	<u>19</u>
Transportation:	
S + RS	
SI	
Photos	
Others	
TOTAL	<u>19</u>

Add Fee: Site Insp (\$)

Interview (\$)

Tech. Invs (\$)

Weekend (\$)

Report Format: DAR.

Lump Sum / I.B.I: (\$)

- PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURE...

From: Chin, Lee-Ying
To: assignments, Admin A
Cc: Fong, Andy-SY
Sent: 22/1/2019 2:00:05 PM
Attachments:  190154.pdf

Hi LKK,

Kindly assist to survey.

Thanks.

Best Regards

Lee Ying, Chin

AIG

Claims | AIG Asia Pacific Insurance Pte. Ltd.

78 Shenton Way #08-16 Singapore 079120

Tel +(65) 6419 1947

Lee-Ying.Chin@aig.com | www.aig.sg

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

- PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SDB9988H AND SJZ6468P ON 19/01/...

From: Chin, Lee-Ying
To: assignments, Admin A
Cc:
Sent: 22/1/2019 2:38:32 PM

Hi LKK,

FYI.

Thanks.

Best Regards

Lee Ying, Chin
AIG
Claims | AIG Asia Pacific Insurance Pte. Ltd.
78 Shenton Way #08-16 Singapore 079120
Tel +(65) 6419 1947
Lee-Ying.Chin@aig.com | www.aig.sg

From: Chin, Lee-Ying

Sent: Tuesday, January 22, 2019 2:00 PM

To: assignments; Admin A

Cc: Fong, Andy-SY

Subject: AIGENCRYPT - PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SDB9988H AND SJZ6468P ON 19/01/2019 CL/190154/T/PA 1800739986SG003

Hi LKK,

Kindly assist to survey.

Thanks.

Best Regards

Lee Ying, Chin
AIG
Claims | AIG Asia Pacific Insurance Pte. Ltd.
78 Shenton Way #08-16 Singapore 079120
Tel +(65) 6419 1947
Lee-Ying.Chin@aig.com | www.aig.sg

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

From: info@catherinelimllc.com

To: Yinnul.Hor@aig.com

Cc: Andy-SY.Fong@aig.com, Lee-Ying.Chin@aig.com, Baljit.Kaur@aig.com, NoorMariesa.AbuKassim@aig.com, Syazairdina.Azlan@aig.com, yokeshi.chan@aig.com, ShengYang.Lim@aig.com, Imran.Ishak@aig.com, Aashweenjeetka

Subject: RE: PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SDB9988H AND SJZ6468P ON 19/01/2019 CL/190154/T/PA 1800739986SG003

Date: Tue, 22 Jan 2019 06:34:11 +0000

Dear Sir (Without Prejudice)

Please be informed that our client's vehicle is at the following address:

Prestige Auto
3023A Ubi Road 1
#01-64
Singapore 408717

9021 0057 for Chong

Regards:

Sally Goh

Catherine Lim LLC

20 Bayview Road #03-01

Central Square

Singapore 059765

Email: info@catherinelimllc.com

From: Hor, Yinnul [<mailto:Yinnul.Hor@aig.com>]

Sent: Tuesday, January 22, 2019 12:52 PM

To: Sally

Cc: Fong, Andy-SY; Chin, Lee-Ying; Kaur, Baljit; Abu Kassim, Noor Mariesa; Azlan, Syazairdina; Chan, Yoke Shi; Lim, Sheng Yang; Md Ishak, Mohd Imran; Mithoosingh, Aashweenjeetkaur

Subject: RE: PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SDB9988H AND SJZ6468P ON 19/01/2019 CL/190154/T/PA 1800739986SG003

[Redacted]

This is a secure, encrypted message. To read it, open the attachment.

这是安全加密信息。如要阅读此信息，请开启附件。

นี่คือการรักษาความปลอดภัยข้อความที่เข้ารหัสลับ เพื่ออ่านบน
โมบายล์โฟนของคุณ

이것은 안전하고 암호화된 메시지입니다. 그것을 읽으려
면 첨부 파일을 엽니다.

Ini adalah pesan, aman terenkripsi. Untuk membacanya,
membuka attachment.

[Click here](#) by 2019-01-29 12:52 +08 to read your message.
After that, open the attachment.

[More info](#)

Disclaimer: This email and its content are confidential and intended solely for the use of the
addressee. Please notify the sender if you have received this email in error or simply delete it.

Secured by Proofpoint Encryption. Copyright © 2009-2017 Proofpoint, Inc. All rights
reserved.

CATHERINE LIM LLC

林 ADVOCATES & SOLICITORS
翠 NOTARY PUBLIC - 公证官
玲 COMMISSIONER FOR OATHS - 宣誓官
律
師 CATHERINE C.L.LIM
馆 DIRECTOR
LL.B (HONS) SINGAPORE - 法律系 - 律師
M.B.A. (BUSINESS LAW) - 商业系 - 碩士

20 Havelock Road #03-01
Central Square Singapore 059765
UEN No. 201310922K

Tel: (65) 6438 5500
Fax: (65) 6438 0111
www.catherinelimllc.com
Email: info@catherinelimllc.com
CATHERINE LIM LLC is a law corporation
with limited liability

Your Ref: SDB 9988H
Our Ref: CL/190154/T/PA.sg

22 January 2019

AIG Asia Pacific Insurance Pte Ltd
AIG Building
78 Shenton Way
#07-16
Singapore 079120
Attn: Motor Claims Department

via fax: 6415 3727 & By Hand

Tan Chin Liat
12 Robin Lane
Singapore 258242

CERTIFICATE OF POSTING
(Please be informed that all supporting documents
have been forwarded to your insurer.)

Dear Sir

**RE: NOTICE TO CONDUCT PRE-REPAIR INSPECTION WITHIN 2 WORKING DAYS PURSUANT TO
PRE-ACTION PROTOCOL FOR NON-INJURY MOTOR ACCIDENT CLAIMS (NIMA)**

**ACCIDENT INVOLVING SJZ 6468P / SDB 9988H ON 19.01.2019 AT TRAFFIC CROSS JUNCTION AT
STEVEN ROAD**

We are instructed by **Pok Fern Ming** to notify you of a road traffic accident involving our client's vehicle No. SJZ 6468P and vehicle No. SDB 9988H driven by you at the material time. A copy of the Singapore Accident Statement and/or Police Report is enclosed.

As a result of the accident, our client's motor vehicle has been damaged. Before our client proceed to repair the damaged motor vehicle, please let us know within **2 working days** of your receipt of this notice whether you/your insurer would like to conduct a pre-repair survey of the motor vehicle. If we do not receive any reply from you/your insurer within the stipulated timeline, our client shall proceed to repair the vehicle without further reference to you.

Please let us know your appointed surveyor.

Venue: Prestige Auto
191 Tanjong Katong Road
Singapore 436993

Chong Hp: 9021 0057 Fax: 6842 3217

Yours faithfully



cc: clients

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	21/01/2019 11:28
Date Of Accident	19/01/2019 15:30
Exact Location Of Accident	TRAFFIC CROSS JUNCTION AT STEVEN ROAD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SJZ6468P
Insured/Policyholder	
Name Of Registered Owner	POK FERN MING
NRIC No	S7902069I
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-96343193
Alternative Phone No	HOME-96343193

Vehicle Particulars

Manufacturer	TOYOTA
Model	VELLFIRE 3.5Z PLATINUM A
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	SOMPO INSURANCE SINGAPORE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	D18MTPV01015160
Cover Note Number	

Driver

Name of Driver	KEE HONG HENG
NRIC No	S8041069G
Date Of Birth	11/12/1980
Occupation	INDOOR
Date Of Driving Pass	31/07/1999
Driving Experience	19 YEARS AND 5 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-97744440
Fax Number	
Contact Number	
EEmail Address	NOEMAIL

Address 18 PHOENIX GARDEN SINGAPORE 668285
 Postcode
 Was driver an employee of the Insured's Company NO
 If No, Relationship of the Driver with the Insured SPOUSE
 Vehicle Registration Number of Driver's Own Vehicle -
 -
 -
 Insurance Company of Driver's Own Vehicle -
 -
 -

General information of the Accident

Type Of Accident COLLISION - CROSS JUNCTION
 Weather Conditions CLEAR
 Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
 Number of vehicles (including own vehicle) involved in the accident 2
 Was any body injured in the Accident? YES
 Was any injured conveyed to hospital by ambulance? NO
 Was any other material or property damaged? YES
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
 Number of Passengers (Including Driver) 6
 Passenger 1 NAME: : POK FERN MING
 GENDER: : FEMALE
 Passenger 2 NAME: : NIECE
 GENDER: : FEMALE
 Passenger 3 NAME: : NIECE
 GENDER: : FEMALE
 Passenger 4 NAME: : NEPHEW
 GENDER: : MALE
 Passenger 5 NAME: : SON
 GENDER: : MALE

Details of Police Action

Was the accident reported to the police? YES
 If Yes, Please state which Police Station
 Police Station Name KEBUN BARU NEIGHBOURHOOD POLICE POST
 Police Station Address ROAD: BLK 111 ANG MO KIO AVENUE 4 , POSTCODE: 560111 ,
 COUNTRY: SINGAPORE
 Police Station Contact TEL NO: 1800-4589999 - FAX NO: 64574454
 Was notice of intended Prosecution given? NO
 If Yes, against whom?

Circumstances of Accident

REFER TO POLICE REPORT/ SKETCH PLAN

Attachment(s)

Are accident photos available for attachment? YES
 Was there any video captured by Car Camera? YES

Was there any audio recorded?

NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SDB9988H
Vehicle Make/Model/Colour MERCEDES
Details Of Properties
Vehicle Category PRIVATE CAR
Name of Driver TAN CHIN LIAT
NRIC/Passport Number S0219455D
Contact Number 96362861
Address
Postcode
Insurance Company Name
Nature Of Damage
No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1


Name POK FERN MING
Approximate Age
Injuries Sustain
Injured person in which vehicle? SJZ6468P
Were seat belts worn?
Was this injured conveyed to hospital by ambulance? NO
Address
Postcode

DETAILS OF INJURED PERSON 2

Name KEE HONG HENG
Approximate Age
Injuries Sustain
Injured person in which vehicle? SJZ6468P
Were seat belts worn?
Was this injured conveyed to hospital by ambulance? NO
Address
Postcode

Sketch Plan Pg. 3

SKETCH PLAN




DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

My hubby was waiting for the green light to drive off. Once, in the traffic light turned green, he started to move off. The other party beat the red light and crashed onto our car's front bumper.


<p>Important: You have been advised by the workshop that in the event that you wish to claim against your own policy (OD CLAIM), There is a FOURTEEN (14) DAYS CLAUSE WHEREBY MUST BE MADE within the stipulated time frame from the day of the occurrence.</p>	<input type="checkbox"/>	- Reporting Only
	<input type="checkbox"/>	- Claim OD
	<input type="checkbox"/>	- Claim TP
	<input checked="" type="checkbox"/>	- Claim OD (TP) at other workshop

DECLARATION

I/WE declare the foregoing particulars are true in every respect.


 Policyholder's signature
 Date & Time 10:50am
 21/1/2019


 Driver's Signature
 (if driver not the policyholder)
 Date & Time 10:50am
 21/1/2019


 Reporting Centre Personnel's Signature
 Name:
 Nric/Fin No.


SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My Insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all Insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



 Policyholder's Signature
 Date & Time:



 Driver's Signature
 (If driver is not the policyholder)
 Date & Time:



 Reporting Officer's Signature
 Name:
 NRIC/IN No.:



**SINGAPORE
POLICE FORCE**



T/20190121/2118

Police Station Of Origin:
Kebun Baru NPP
111 Ang Mo Kio Avenue 4 SINGAPORE
560111
Tel No: 1800-4589999

1 of 3

Report No. T/20190121/2118

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 21/01/2019 16:26		Vide Report No.:		Station Diary No.: 19	
Informant's Particulars					
Name of Informant: KEE HONG HENG			Address: 18 PHOENIX GARDEN SINGAPORE 668285		
ID Type / ID No.: NRIC NO / S8041069G			Contact No.: Home/Office: Mobile: 97744440		
Nationality: SINGAPORE CITIZEN.			Email:		
Sex: Male	Age: 38	Date of Birth: 11/12/1980	Type of Informant: Driver		
Race: Chinese			Language:		Institution / School Name:
Occupation: SELF-EMPLOYED			Driving Licence Information: Class: 3		Date of Expiry:

General Information of the Accident				
Type of Accident:	Injury Others	Drink Drive: No	Date/Time of Accident: 19/01/2019 15:00	Type of Location: X-Junction
Location: Junction of Road 1 and Road 2 STEVENS ROAD BUKIT TIMAH ROAD Road beside The Equatorial Condominium				
Weather: Clear		Road Surface: Dry	Road Speed Limit:	
Traffic Flow:		Traffic Control:	Traffic Volume: Moderate	
Type of Collision: Between Moving Vehicles - Head To Side				Anyone conveyed by ambulance: No

Details of Vehicle Involved						
Vehicle No.	Type	Make	Model	Color	Condition	No. of Passengers
SDB9988H	Car				Slightly Damaged	0
SJZ8468P	Car				Seriously Damaged	5

Details of Person Involved	
Any Pedestrian Involved: No	
No. of Pedestrians Injured: NIL	Use of Pedestrian Crossing: NA

POLICE REPORT Pg. 2



**SINGAPORE
POLICE FORCE**



T/20190121/2118

Police Station Of Origin:
Kebun Baru NPP
111 Ang Mo Kio Avenue 4 SINGAPORE
560111
Tel No: 1800-4589999

2 of 3

Report No. T/20190121/2118

CONTINUATION OF REPORT

Driver			
Name	KEE HONG HENG	ID No.	S8041069G
Related Vehicle	SJZ6468P (Car)	Contact No.	97744440
Hospital/Clinic	LIGHTHOUSE CLINIC AND SURGERY	Class of Driving Licence & Expiry Date	Class: 3 Date of Expiry: NIL
Date Treatment	21/01/2019	Date Discharge	21/01/2019
No. of Days granted Medical Leave	07	Degree of Injury	Slight
Passenger			
Name	Pok Fern Ming	ID No.	S7908069I
Related Vehicle	SJZ6468P (Car)	Contact No.	96343193
Hospital/Clinic	LIGHTHOUSE CLINIC AND SURGERY	Class of Driving Licence & Expiry Date	Class: 3 Date of Expiry: NIL
Date Treatment	21/01/2019	Date Discharge	21/01/2019
No. of Days granted Medical Leave	07	Degree of Injury	Slight

Brief Details.

On 19/01/2019, at around 1500hrs to 1530hrs, I was at the junction between Stevens Road and Bukit Timah Road. When the green light came on, I drove forward. However, at that point in time, another vehicle (SDB9988H) suddenly drove pass my vehicle from Bukit Timah Road, when that side of the road should have stopped. As the vehicle drove pass my vehicle, it hit on the front of my vehicle, which caused the entire front bumper to come off. The impact also caused me to sprain my right shoulder and my neck, and also caused my wife to have bruises on her right leg.

After the collision, I immediately turned left to go after the other party. After I turn, the other party's vehicle is already coming to a stop. I stopped my vehicle behind his, and alighted to check on the damages done, as well as to exchange particulars.

I believe that he had dashed past the red light, as at the junction, I have the right of way, as the traffic light for the road I was on is green. I have the dashcam video record of the accident.

POLICE REPORT Pg. 3



**SINGAPORE
POLICE FORCE**



T/20190121/2118

Police Station Of Origin:
Kebun Baru NPP
111 Ang Mo Kio Avenue 4 SINGAPORE
560111
Tel No: 1800-4589999



3 of 3
Report No. T/20190121/2118

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report: F / Sgt 2 KOH JIA JUN 	Signature Of Informant: 
Signature Of Interpreter: Not applicable	Date/Time: 21/01/2019 16:26
Officer In Charge Of Case: TP / AEIT / Staff Sgt WONG SIEU LUI Contact No.: 65476151	Classification Of Case: 

Authentication Stamp
NP168

> [Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	2069I
Vehicle Details	
Vehicle No.:	SJZ6468P
Vehicle to be Exported:	No
Intended Deregistration Date:	25 Jan 2019
Vehicle Make:	TOYOTA
Vehicle Model:	VELLFIRE 3.5Z PLATINUM A
Primary Colour:	Black
Manufacturing Year:	2010
Engine No.:	2GR0720554
Chassis No.:	GGH208031574
Maximum Power Output:	206.0 kW (276 bhp)
Open Market Value:	\$46,716.00
Original Registration Date:	14 Sep 2010
First Registration Date:	14 Sep 2010
Transfer Count:	2
Actual ARF Paid:	\$46,716.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	13 Sep 2020
PARF Rebate Amount:	\$25,693.00
Intended COE Rebate Details	
COE Expiry Date:	13 Sep 2020
COE Category:	B - Car (1601cc & above)
COE Period(Years):	10
QP Paid:	\$44,129.00
COE Rebate Amount:	\$7,217.00
Total Rebate Amount:	\$32,910.00

The information contained herein is correct as at 25 Jan 2019

OK

500+ dealers competed to buy my car!

Sell ur Car for More Cash
Highest Price or Get \$100 Free
Get Paid Now, Handover Later

SELL YOUR CAR

Toyota Vellfire Price Range Depreciation 2010 Vehicle Type

Advanced Search

Home » Used Cars » Nordad » Toyota Vellfire 3.5A Z

Resources

- Car Buying
- Car Selling
- Car Ownership
- Car Aftermarket
- On The Move
- Lifestyle

Car Tyres



Toyota Vellfire 3.5A Z

Overview Financial Insurance Accessories Similar Research Photos Map

PREMIUM AD

Add to Shortlist Add to Compare Add a Note Report Error More Actions Share

Car Details

Price	\$52,000	
Depreciation	\$21,070 /yr	View models with similar depreciation
Reg Date	25-Jun-2010	(1yr 4mths 25days COE left)
Manufactured	2010	
Mileage	-	
Transmission	Auto	
Engine Cap	3,456 cc	
Road Tax	\$3,100 /yr	
Power	206.0 kW (276 bhp)	
Curb Weight	1,970 kg	
Features	Smooth And Reliable 3.5L V6 Dual VVT-i Engine, Producing 276 Bhp And 340Nm Torque, Coupled With 6 Speed Auto Transmission, Auto Headlights And Wipers.	
Accessories	Stock Condition.	
Description	Well Maintained. Service Regularly. Accident Free. PI Model. Sheltered Parking. Viewing By Appointment Only.	
COE	\$38,000	
OMV	\$45,005	
ARF	\$45,005	
Dereg Value	\$30,073 as of today (change)	
No. of Owners	2	
Type of Veh	MPV	
Category	PARF Car, Premium Ad Car	
Availability	Available	PREMIUM AD



Seller Information

Company	Nordad	» dealer's pricelist	» 4 vehs sold 6 vehs available
Address	1557 Keppel Road #02-18A Search cars nearby this location		
Location	Cantonment Central		
Office No	63544555 / 63379200		
Contact Person(s)	Chris	90686124	
	Ken	91868878	

Useful Services



Afraid of lemons? Request to have this car evaluated professionally.

Vehicle Evaluation



Find out the market value for your car. Get a free Car Valuation.

Free Valuation

Add to Shortlist Add to Compare Add a Note

Posted on: 12-Jan-2019 | Last Updated on: 12-Jan-2019
Tags: Toyota Vellfire, toyota vellfire, 2010 Toyota Vellfire, 2010 toyota vellfire, Toyota, Vellfire, vellfire, Used Toyota

Upfront Payment [View Internal Info](#)

Transfer Fee \$25

Complete

...CLAIM SUBFOLDER...(Pending for Survey Report)

PRI

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	21 Jan 2019 Edit Reg		22 Jan 2019 00:00 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by adjuster]

Insured:	Tan Chin Liat , ID: S0219455D		
Main Claimant:	POK FERN MING , ID: S7902069I		
Vehicle Reg. No.:	SJZ6468P	Date of Loss:	19/01/2019 15:00 - :59 [100 Months and 5 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 1800739986SG	Policy/Cover Note No.:	2100279760 (Comprehensive) Coverage: 21/11/2018 - 20/11/2019
Vehicle Reg. No. (Insured):	SDB9988H	Policy No. (Claimant):	
		Excess:	
Repairer:	Prestige Auto () 191 Tanjong Katong Road, 436993 Katong - Tel: 90210057/62574781		
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Tan, Bennie-WZ - 6419 1718] Bennie-WZ.Tan@aig.com		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Final Rpt due 31/01/2019]		
Claimant's Solicitor:	CATHERINE LIM LLC - Tel: 6438 5500		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

- AIG_SG (23/01/2019): **Request To Upload TP GIA Report**

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SJZ6468P (1800739986SG)**
[SDB9988H]
TP
POK FERN MING
Jan 19 2019 3:00PM
[Tan Chin Liat]
Prestige Auto

Upload Documents Upload Photos Compose New Letter Upload Video Upload Audio			View View in Browser ▼	
Video			1 per page ▼ <input checked="" type="checkbox"/>	
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	25/01/19 14:44	TP Video - Accident	Load MP4	<input type="checkbox"/>
Assessment Reports			1 per page ▼ <input checked="" type="checkbox"/>	
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	23/01/19 16:21	Accident Statement From:OD - Reg. No: SDB9988H, Claimant: TAN CHIN LIAT	Load HTM	<input type="checkbox"/>
Photos/Images			3 per page ▼ <input checked="" type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	24/01/19 09:42	General View	Load JPG	<input checked="" type="checkbox"/>
2	24/01/19 09:42	General View	Load JPG	<input checked="" type="checkbox"/>
3	24/01/19 09:42	General View	Load JPG	<input checked="" type="checkbox"/>
4	24/01/19 09:42	General View	Load JPG	<input checked="" type="checkbox"/>
5	24/01/19 09:42	General View	Load JPG	<input checked="" type="checkbox"/>
6	24/01/19 09:42	General View	Load JPG	<input checked="" type="checkbox"/>
7	24/01/19 09:42	General View	Load JPG	<input checked="" type="checkbox"/>
8	24/01/19 09:42	General View	Load JPG	<input checked="" type="checkbox"/>
9	24/01/19 09:42	General View	Load JPG	<input checked="" type="checkbox"/>
10	24/01/19 09:42	General View	Load JPG	<input checked="" type="checkbox"/>
11	24/01/19 09:42	General View	Load JPG	<input checked="" type="checkbox"/>
12	24/01/19 09:42	General View	Load JPG	<input checked="" type="checkbox"/>
13	24/01/19 09:42	General View	Load JPG	<input checked="" type="checkbox"/>
14	24/01/19 09:42	General View	Load JPG	<input checked="" type="checkbox"/>
15	24/01/19 09:42	General View	Load JPG	<input checked="" type="checkbox"/>
16	24/01/19 09:42	General View	Load JPG	<input checked="" type="checkbox"/>
17	24/01/19 09:42	General View	Load JPG	<input checked="" type="checkbox"/>
18	24/01/19 09:42	General View	Load JPG	<input checked="" type="checkbox"/>
19	24/01/19 09:42	General View	Load JPG	<input checked="" type="checkbox"/>
20	24/01/19 09:42	General View	Load JPG	<input checked="" type="checkbox"/>
21	24/01/19 09:42	General View	Load JPG	<input checked="" type="checkbox"/>
22	24/01/19 09:42	General View	Load JPG	<input checked="" type="checkbox"/>
23	24/01/19 09:42	General View	Load JPG	<input checked="" type="checkbox"/>
24	24/01/19 09:42	General View	Load JPG	<input checked="" type="checkbox"/>
25	24/01/19 09:42	General View	Load JPG	<input checked="" type="checkbox"/>
26	24/01/19 09:42	General View	Load JPG	<input checked="" type="checkbox"/>
27	24/01/19 09:42	General View	Load JPG	<input checked="" type="checkbox"/>
28	24/01/19 09:42	General View	Load JPG	<input checked="" type="checkbox"/>

Video			1 per page	<input checked="" type="checkbox"/>	
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)		Thumbnail	Print
29	24/01/19 09:42	General View	1	Load JPG	<input checked="" type="checkbox"/>
30	24/01/19 09:42	General View	1	Load JPG	<input checked="" type="checkbox"/>
31	24/01/19 09:42	General View	1	Load JPG	<input checked="" type="checkbox"/>
32	24/01/19 09:42	General View	1	Load JPG	<input checked="" type="checkbox"/>
33	24/01/19 09:42	General View	1	Load JPG	<input checked="" type="checkbox"/>
34	24/01/19 09:42	General View	1	Load JPG	<input checked="" type="checkbox"/>
35	24/01/19 09:42	General View	1	Load JPG	<input checked="" type="checkbox"/>
36	24/01/19 09:42	General View	1	Load JPG	<input checked="" type="checkbox"/>
37	24/01/19 09:42	General View	1	Load JPG	<input checked="" type="checkbox"/>
38	24/01/19 09:42	General View	1	Load JPG	<input checked="" type="checkbox"/>
39	24/01/19 09:42	General View	1	Load JPG	<input checked="" type="checkbox"/>
40	24/01/19 09:42	General View	1	Load JPG	<input checked="" type="checkbox"/>
41	24/01/19 09:42	General View	1	Load JPG	<input checked="" type="checkbox"/>
42	24/01/19 09:42	General View	1	Load JPG	<input checked="" type="checkbox"/>
43	24/01/19 09:42	General View	1	Load JPG	<input checked="" type="checkbox"/>
44	24/01/19 09:42	General View	1	Load JPG	<input checked="" type="checkbox"/>
45	24/01/19 09:42	General View	1	Load JPG	<input checked="" type="checkbox"/>
46	24/01/19 09:42	General View	1	Load JPG	<input checked="" type="checkbox"/>
47	24/01/19 09:42	General View	1	Load JPG	<input checked="" type="checkbox"/>
48	24/01/19 09:42	General View	1	Load JPG	<input checked="" type="checkbox"/>
49	24/01/19 09:42	General View	1	Load JPG	<input checked="" type="checkbox"/>
50	24/01/19 09:42	General View	1	Load JPG	<input checked="" type="checkbox"/>
51	24/01/19 09:42	General View	1	Load JPG	<input checked="" type="checkbox"/>
52	24/01/19 09:42	General View	1	Load JPG	<input checked="" type="checkbox"/>
53	24/01/19 09:42	General View	1	Load JPG	<input checked="" type="checkbox"/>
54	24/01/19 09:42	General View	1	Load JPG	<input checked="" type="checkbox"/>
55	24/01/19 09:42	General View	1	Load JPG	<input checked="" type="checkbox"/>
56	24/01/19 09:42	General View	1	Load JPG	<input checked="" type="checkbox"/>
57	24/01/19 09:42	General View	1	Load JPG	<input checked="" type="checkbox"/>
58	24/01/19 09:42	General View	1	Load JPG	<input checked="" type="checkbox"/>
59	24/01/19 09:42	General View	1	Load JPG	<input checked="" type="checkbox"/>
60	24/01/19 09:43	Odometer Reading	1	Load JPG	<input checked="" type="checkbox"/>
61	24/01/19 09:43	Chassis Number	1	Load JPG	<input checked="" type="checkbox"/>
62	28/01/19 16:10	Photo After Spray	1	Load JPG	<input checked="" type="checkbox"/>
63	28/01/19 16:10	Photo After Spray	1	Load JPG	<input checked="" type="checkbox"/>
64	28/01/19 16:10	Photo After Spray	1	Load JPG	<input checked="" type="checkbox"/>
65	28/01/19 16:10	Photo After Spray	1	Load JPG	<input checked="" type="checkbox"/>
66	28/01/19 16:10	Photo After Spray	1	Load JPG	<input checked="" type="checkbox"/>
67	28/01/19 16:10	Photo After Spray	1	Load JPG	<input checked="" type="checkbox"/>
68	28/01/19 16:10	Photo After Spray	1	Load JPG	<input checked="" type="checkbox"/>
69	28/01/19 16:10	Photo After Spray	1	Load JPG	<input checked="" type="checkbox"/>
70	28/01/19 16:10	Photo After Spray	1	Load JPG	<input checked="" type="checkbox"/>
71	28/01/19 16:10	Photo After Spray	1	Load JPG	<input checked="" type="checkbox"/>
72	28/01/19 16:10	Photo After Spray	1	Load JPG	<input checked="" type="checkbox"/>
73	28/01/19 16:10	Photo After Spray	1	Load JPG	<input checked="" type="checkbox"/>
74	28/01/19 16:10	Photo After Spray	1	Load JPG	<input checked="" type="checkbox"/>
75	28/01/19 16:10	Photo After Spray	1	Load JPG	<input checked="" type="checkbox"/>
76	28/01/19 16:10	Photo After Spray	1	Load JPG	<input checked="" type="checkbox"/>

Video			1 per page ▼	✓
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
77	28/01/19 16:10	Photo After Spray	Load JPG	✓
78	28/01/19 16:10	Photo After Spray	Load JPG	✓
79	28/01/19 16:10	Photo After Spray	Load JPG	✓
80	28/01/19 16:10	Photo After Spray	Load JPG	✓
81	28/01/19 16:10	Photo After Spray	Load JPG	✓
82	28/01/19 16:10	Photo After Spray	Load JPG	✓
83	28/01/19 16:10	Photo After Spray	Load JPG	✓
84	28/01/19 16:10	Photo After Spray	Load JPG	✓
85	28/01/19 16:10	Photo After Spray	Load JPG	✓
86	28/01/19 16:10	Photo After Spray	Load JPG	✓

Documents Checklist

DOCUMENTS CHECKLIST

Reset Save Print

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AIG19001466/GCD3S2
Date: 01/02/2019

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100279760
Claimant Vehicle No : SJZ6468P **Insured Vehicle No :** SDB9988H
 Date of Loss: 19/01/2019 Nature of Claim: TP Claim No: 1800739986SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SJZ6468P**
 Make & Model: TOYOTA VELLFIRE, 3.5 Z (A) Engine No: 2GR0720554
 Reg. Date: 14/09/2010 (Man. Year: 2010) Chassis No: GGH208031574
 Colour: Black Odometer: 153181 km
 Engine Capacity: 3456 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Good Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 235/50R18 Rear Tyre Size: 235/50R18
 Front Left Side: Yokohama 6 mm Rear Left Side: Yokohama 6 mm
 Front Right Side: Yokohama 6 mm Rear Right Side: Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 22/01/2019
 Date Inspected: 23/01/2019 Inspected At: BLK 3023A UBI RD 1 #01-64
 Estimated Period of Repair: 6.0 days Repairer: Prestige Auto

Adjuster: XING GUO QIANG

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT BUMPER	Broken	0.00 F	*-F
2	1		*FRT BUMPER CLIPS	Necessary	0.00 F	*-F
3	2		*FRT BUMPER SIDE RETAINER	Broken	0.00 F	*-F
4	1		*FRT BUMPER REINFORCEMENT	Buckled	0.00 F	*-F
5	1		*FRT BUMPER SPONGE	Broken	0.00 F	*-F
6	1		*FRT BUMPER GRILLE	Broken	0.00 F	*-F
7	2		*FRT BUMPER SENSOR	Broken	0.00 F	*-F
8	1		*FRT RH BUMPER FOG LAMP	Broken	0.00 F	*-F
9	1		*FRT GRILLE	Broken	0.00 F	*-F
10	1		*FRT GRILLE EMBLEM	Necessary	0.00 F	*-F
11	1		*FRT SUPPORT PANEL	Repair	0.00 F	*-F
12	1		*FRT SUPPORT PANEL TOP GARNISH COVER	Broken	0.00 F	*-F
13	1		*FRT LH HEADLAMP ASSY	Broken	0.00 F	*-F
14	1		*FRT RH HEADLAMP ASSY	Broken	0.00 F	*-F
15	1		*BONNET	Repair	0.00 F	*-F
16	2		*BONNET HINGE	Bent	0.00 F	*-F
17	1		*BONNET STUD PLATE	Bent	0.00 F	*-F
18	1		*FRONT RH AIR DEFLECTOR	Broken	0.00 F	*-F
19	2		*HEADLAMP GARNISH	Broken	0.00 F	*-F
20	1		*WIPER WASHER TANK	Crushed	0.00 F	*-F
21	1		*FRT LH FENDER	Repair	0.00 F	*-F
22	1		*FRT LH FENDER INNER SHIELD	Torn	0.00 F	*-F
23	1		*FRT RH FENDER	Repair	0.00 F	*-F
24	1		*FRT RH FENDER INNER SHIELD	Torn	0.00 F	*-F

F=Franchise part.

Total Parts (\$\$)	0.00	0.00
---------------------------	-------------	-------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >