

2/03/2002

ASS. REC. BY:

REF:

es/MSG19001468/Jt dsk

Special Instruction:

Surveyor:

Meinen

ASSIGNMENT (Office)

From (Person):

Jasmine Lok

of

MSG

Date/Time:

22/1/19 @ 4:09pm

Estimated Cost:

Bill to:

OD ☒ TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No.:

GBC 5110T

Insured:

SLC 9774H

at Workshop m/s

Carz Auto

Tel:

64931924

of

No-61 Woodlands Ind. Park - 9 #04-04

Policy No:

1000691854

Claim No:

214530

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

18/01/2019

CA / REV / REP. / REV 24 HRS

wp'

23/01/19

H.O.D. Endorsement:

Date/Time:

4:41pm @ 22/1/19

Person Contacted:

Celebra

Vehicle:

IN/OUT

Date/Time

Action/Instruction

(

✓)

Estimate

GBC 5110T-

SLC 9774H - X

24/1/19 @ 2:32pm verified to Jasmine Lok via Meinen.

Surgeon Hwee Jie


REF: MS16

# ASSIGNMENT

From: \_\_\_\_\_ Date: 23/01/2019  
 Estimated Cost: \_\_\_\_\_  
 OD ☒ TP / WS / TP RES / OD RES / EVA / INV / MV  
 To Inspect Vehicle No: GBC 5110T  
 at Workshop m/s: Carz Auto  
 of No. 61 woodlands Ind. Park E9 #04-  
 Insured: 04  
 Policy No: \_\_\_\_\_  
 Claims No: \_\_\_\_\_  
 Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_  
 (Client's Record)  
 Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: \_\_\_\_\_  
 IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No  
 GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No  
 Est. Repairs: \_\_\_\_\_ days Res.: Yes or No  
 Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS <sup>up</sup>

Vehicle: IN / OUT

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Veh No: GBC 5110T Yr Regn: 24 Oct 2012  
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /  
 Truck / Trailer or  
 Make: Nissan NV 200 C.C: 1461  
 Colour: Silver A/C: Insured / Std / NI / NA  
 Sp. Reading: 214227 T/Radio: Insured / Std / NI / NA  
 Eng/No: \_\_\_\_\_  
 Ch No: VSKYBAM20U0038809  
 Gen. Cond: Good / Fair / Poor / Burnt  
 Steering: Order / Jammed / Leaked / Burnt or  
 Brake: Order / Jammed / Leaked / Burnt or  
 Modi: Nil / S/Rim / STD A/Rim or  
 Tyre Size: F: 175/70R14  
 R: \_\_\_\_\_

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  
 TOYO / YOKO or

Front		Rear	
R/Bal.	<u>7</u> mm	R/Bal.	<u>7</u> mm
L/Bal.	<u>7</u> mm	L/Bal.	<u>7</u> mm
D.O.A.	<u>18/1/19</u>	D.O.I.	<u>23/1/19</u>

Survey held at Carz Auto

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	<u>Hwee Jie</u>
	<u>MV - \$29,000</u>
	<u>PV - \$22,205</u>
	<u>NV - \$6,795</u>
	<u>Pls. check repair margin</u>
	<u>RECEIVED 9 JAN 2019</u>
<u>29/1/19</u>	<u>Confirmed L/s \$4,900/- with 7 days of repair.</u>
	<u>(Red: 493830! 50%)</u>

Date/Time, File Pass to? ☐ : Preli. Report

11/29/11 Typist ☒ : Final Report

Date/Time, File Return to?

2)

Days Of Repair: 7

Resurvey No. of Trip: 2

Add Fee: ☐ : Site Insp (\$)  
☐ : Interview (\$)  
☐ : Tech. Invs (\$)  
☐ : Weekend (\$)

Survey Fee:

Transportation:

) \$ + RS. SI

) Photos

) Others

) ..

TOTAL

Report Format :

Lump Sum / I.B.I. (\$

TP  
4900/-

<u>150</u>
<u>10</u>
<u>160</u>

## ...CLAIM SUBFOLDER...(New Assignment)

### CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	22 Jan 2019 10:45		22 Jan 2019 16:09 <a href="#">Assign</a>				<b>New Assignment</b> <a href="#">Cancel Case</a>

<a href="#">Main</a>	<a href="#">Reference</a>	<a href="#">Claim Details</a>	<a href="#">Documents</a>	<a href="#">Show All</a>
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

### CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	TOKYO CENTURY LEASING (SINGAPORE) PTE LTD, Co. Reg. No.: 197901535G		
Main Claimant:	LEE KIM TAH (PTE) LTD, Co. Reg. No.: 196800499G		
Vehicle Reg. No.:	GBC5110T	Date of Loss:	18/01/2019 00:00 - :59 [74 Months and 25 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP	Policy/Cover Note No.:	1000691854 (Comprehensive) Coverage: 01/06/2018 - 31/05/2019
Vehicle Reg. No. (Insured):	SLC9774H	Policy No. (Claimant):	
		Excess:	
Repairer:	Carz Auto Services Pte Ltd - Woodlands (HQ) NO 61, WOODLANDS INDUSTRIAL PARK E9, #04-04 E9 PREMIUM SINGAPORE 757047, 757047 Woodlands - Tel:		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Jasmine Lok Kheng Kwei - 6594 2550]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 23/01/2019]		
Driver/Custodian (Insured):	YEO CHIN HSIUNG (), NRIC: S8032834F		
Adj Asg. Remarks:	on WP. TP Pre-Repair Survey. TP selected LKK to be SJE. Liability : 100% Contact : Ms Cecilia Chong @ 6493 1924		

### ASSOCIATED MAIL RECEIVED

[View All](#)

[Compose Case Mail](#)

There are no mail for this case.

### ALL ASSOCIATED TASKS

[View All](#)

[Search Tasks](#)

[Create New Task](#)

[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

**Note: This document has not been finalised.****LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.  
4 Shenton Way  
#21-01 SGX Centre 2  
Singapore 068807

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Jasmine Lok Kheng Kwei

Date: 24 Jan 2019

**Preliminary Advice**

Insured Vehicle No	: SLC9774H	Accident Date	: 18/01/2019
TP Vehicle No	: GBC5110T	Assignment Date	: 22/01/2019
Make	: NISSAN NV200	Est. Duration of Repair	: 5.00
Date of Inspection	: 23/01/2019		
Inspection At	: CARZ AUTO SERVICES PTE LTD - WOODLANDS (HQ) NO 61, WOODLANDS INDUSTRIAL PARK E9, #04-04 E9 PREMIUM SINGAPORE 757047 SINGAPORE 757047		

**Point of Impact / General Description of Damages**

The vehicle sustained impact / damages rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	9,838.80
Revised Amount	:S\$	4,948.64
Check Items (Estimated)	:S\$	2,702.09
Total	:S\$	7,650.73

Lump Sum Repair	:S\$	
-----------------	------	--

**Total Loss Consideration**

New for Old Value	:S\$	
Pre-Accident Value	:S\$	
COE / PARF Rebate	:S\$	
Salvage Value	:S\$	
Margin for Repair	:S\$	

**Remarks**

- ( ) The vehicle is economical/not economical for repair.
- ( X ) The above survey was conducted on a 'without prejudice' basis.

> Back to OneMotoring

## Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	0499G
Vehicle Details	
Vehicle No.:	GBC5110T
Vehicle to be Exported:	No
Intended Deregistration Date:	24 Jan 2019
Vehicle Make:	NISSAN
Vehicle Model:	NV200 1.5L MT ABS AIRBAG 2WD 6DR
Primary Colour:	Grey
Manufacturing Year:	2012
Engine No.:	K9KF276D126904
Chassis No.:	VSKYBAM20U0038809
Maximum Power Output:	-
Open Market Value:	\$22,455.00
Original Registration Date:	24 Oct 2012
First Registration Date:	24 Oct 2012
Transfer Count:	0
Actual ARF Paid:	\$1,123.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	23 Oct 2022
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
QP Paid:	\$59,334.00
COE Rebate Amount:	\$22,221.00
<b>Total Rebate Amount:</b>	<b>\$22,221.00</b>

The information contained herein is correct as at 24 Jan 2019

OK



**Post an Advertisement**  
Sell it yourself! Advertise it at just  
**\$58 until it's SOLD!**

[Post an Ad](#) [Advertiser Login](#) [Ways of Selling](#)

Jun 2017 Land Rover Discovery Sport Diesel 2.0A SE



10 Years Servicing Package &  
Warranty Until Jun/2020 By  
Wearnes. Like New!  
Auto Zoom Enterprise [StarAd](#)



Browse by Category ▼

Sort by Date Posted ▼ 20 results/page ▼

1 vehicles

NISSAN NV200

Advanced Search:

	Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
<b>Search Selection</b>	NISSAN NV200		Any	Any	2012	Any	Any	Any	Available
	Nissan NV200 1.5M		\$29,800	\$8,110 /yr	28-Sep-2012	1,461 cc	-	Van	Available
	<b>Fuel Type: Diesel</b> Please Call To Arrange For Viewing, Thanks.								
	Posted: 09-Jan-2019    Tags: 2012 Nissan NV200, 2012 nissan nv200, Nissan NV200, nissan nv200, Nissan, NV200, nv200, Used Nissan								

Save this search criteria, to get email alerts whenever a match is found.

	Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
--	------	-------	-------	--------------	----------	---------	---------	----------	--------

For old advertisements, view [Expired ads](#)

20 results/page

[Home](#) | [New Cars](#) | [Used Cars](#) | [Sell My Car](#) | [Directory](#) | [Products](#) | [Insurance](#) | [Article](#) | [Forum](#) | [Resources](#)

sgCarMart is the number one car classifieds for parallel import cars, Toyota, Honda, Nissan, Mitsubishi & BMW. There are plenty of cars for sale, from vans, trucks, sedan cars, luxury cars, sports cars or stationwagons, SUV, MPV, hatchback, to COE cars & OPC cars. You can also buy from a car auction, look up car loans, financial services, low mileage cars, car brands, carpark rates & car insurance. Find buy used NISSAN NV200, NISSAN NV200 Singapore, used NISSAN NV200 Singapore, used NISSAN NV200, used vehicles Singapore or even buy used NISSAN NV200 Singapore. We have new car dealers comprising parallel importers, authorised car dealers, and used car dealers on our site. Find new car price lists, new car launches and new car promotions. Visit our partner sites for job openings for Singapore jobs, real estate properties for sale, mover, car performance parts, car discussion, forum discussion, commercial vehicle leasing & COE results.

All prices and other information displayed on sgCarMart.com are gathered from sources and based on algorithms that are believed by sgCarMart.com to be reliable, but no assurance can be given that this information is accurate, complete or current. sgCarMart.com does not assume any responsibility for errors or omissions or warrant the accuracy of this information.

**Follow sgCarMart.com**

[About Us](#) | [Careers](#) | [Contact Us](#) | [Sitemap](#) | [Terms of Service](#) | [Privacy Policy](#) | [Personal Data Protection Statement](#)

©2004-2019 sgCarMart. All rights reserved.

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

Date Of Report	18/01/2019 15:25
Date Of Accident	18/01/2019 09:15
Exact Location Of Accident	JALAN BOON LAY
Country/State of Loss	SINGAPORE

Vehicle Registration Number	GBC5110T
-----------------------------	----------

#### Insured/Policyholder

Name Of Registered Owner	LEE KIM TAH (PTE) LTD
Co Reg No	196800499G
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-67453318

#### Vehicle Particulars

Manufacturer	NISSAN
Model	NV200-1.5 L ABS AIRBAG 2WD 6DR EURO 5 (M)
Exact Purpose for which vehicle was being used at time of accident	COMMERCIAL
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	COMMERCIAL VEHICLE

#### Insurance Company

Name of Insurance Company	MS FIRST CAPITAL INSURANCE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	D-1809165MCVP
Cover Note Number	

#### Driver

Name of Driver	TEO LEONG SENG
NRIC No	S1153617D
Date Of Birth	05/02/1956
Occupation	OUTDOOR
Date Of Driving Pass	01/03/1978
Driving Experience	40 YEARS AND 10 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-96330503
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address BLK 221A JURONG EAST STREET 21  
#05-881  
Postcode 601221  
Was driver an employee of the Insured's Company YES  
If No, Relationship of the Driver with the Insured  
Vehicle Registration Number of Driver's Own Vehicle -  
-  
-  
Insurance Company of Driver's Own Vehicle -  
-  
-

#### General Information of the Accident

Type Of Accident COLLISION - HEAD TO REAR  
Weather Conditions CLEAR  
Road Surface DRY

#### Other Information

Was any foreign vehicle involved in this accident? NO  
Number of vehicles (including own vehicle) involved in the accident 2  
Was any body injured in the Accident? NO  
Was any injured conveyed to hospital by ambulance? NO  
Was any other material or property damaged? YES  
I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO  
Number of Passengers (Including Driver) 1

#### Details of Police Action

Was the accident reported to the police? NO  
If Yes, Please state which Police Station  
Was notice of intended Prosecution given? NO  
If Yes, against whom?

#### Circumstances of Accident

On 18/1/2019 at about 9:15am I was travelling to Jalan Boon Lay Road. I was stop when waiting all the vehicle drive along jalan Boon Lay Road. Suddenly, I heard a loud bang from behind. When I realised, there was vehicle B collided my vehicle.

#### Attachment(s)

Are accident photos available for attachment? YES  
Was there any video captured by Car Camera? NO  
Was there any audio recorded?

Vehicle Registration Number

Vehicle Make/Model/Colour

Details Of Properties

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)



**SKETCH PLAN**

**IMPORTANT NOTICE**

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.




Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

SKETCH PLAN



Vehicle A: GBC5110T.

Vehicle B: SLC9774H

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 18/1/2019 at about 9:15a.m. I was travelling to Jalan Boon Lay Road. I was stop when waiting all the vehicle drive along Jalan Boon Lay Road. Suddenly, I heard a loud bang from behind. When I realised, there was Vehicle B collided my vehicle.

DECLARATION

I/We declare the foregoing particulars are true in every respect.



Policyholder's Signature  
Date & Time:

*[Handwritten Signature]*

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

*[Handwritten Signature]*

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:



# CARZ AUTO SERVICES PTE LTD

UEN/ GST 201409457D

61 WOODLANDS IND PARK E9 (E9 PREMIUM)

#04-04 Singapore 757047

Tel: 65 6493 1924

Fax: 65 6493 1928

## VEHICLE REPAIR ESTIMATE

Insurance Company: MSIG Insurance (Singapore) Pte Ltd

Address: 4 Shenton Way #21-01 SGX Centre 2 Singapore 068807

Telephone: 6827 7660

Fax: 6225 6371

Email: [claims@sg.msig-asia.com](mailto:claims@sg.msig-asia.com)

Make/ Model : NISSAN NV200

Date: 19-01-19

Chassis No : VSKYBAM20UOO38809

Vehicle No: GBC 5110 T

Date/Time of Accident : 18-01-19 9:15

### Materials Cost/ Spare Parts Cost

#### TO BE COMPLETED BY SERVICE ADVISOR

ITEMS	PARTS DESCRIPTION	QTY	LIST PRICE \$	PARTS DISCOUNT	FINAL PRICE \$
1	REAR DOOR LH <b>BUL</b>	1	<del>\$ 1150.13</del> <b>1,391.30</b>	10%	<del>\$ 1035.12</del> <b>1,252.17</b>
2	REAR DOOR INNER TRIM LH <b>NN</b>	1	\$ 205.80	10%	\$ 185.22
3	DOOR LOGO LH <b>NEC</b>	1	\$ 80.90	10%	\$ 72.81
4	REAR DOOR NV200 EMBLEM LH <b>NEC</b>	1	\$ 79.90	10%	\$ 71.91
5	REAR DOOR GLASS INNER SEAL LH <b>NEC</b>	1	\$ 45.90	10%	\$ 41.31
6	REAR DOOR HINGE LH <b>NN</b>	2	\$ 231.20	10%	\$ 208.08
7	REAR DOOR INNER LOWER LOCK LH	1	\$ 145.90	10%	\$ 131.31
8	REAR DOOR LOWER CATCH LOCK LH <b>SVC</b>	1	\$ 88.20	10%	\$ 79.38
9	REAR DOOR FRAME WEATHERSTRIP <b>CUT</b>	1	\$ 110.70	10%	\$ 99.63
10	REAR DOOR TOP LOCK LH <b>SVC</b>	1	\$ 155.10	10%	\$ 139.59
11	REAR DOOR RH <b>BUL</b>	1	\$ 980.90	10%	\$ 882.81
12	REAR DOOR DCI EMBLEM RH <b>NEC</b>	1	\$ 80.90	10%	\$ 72.81
13	REAR DOOR SEAL RH <b>DEF</b>	1	\$ 58.90	10%	\$ 53.01
14	REAR DOOR HINGE RH <b>NN</b>	2	\$ 231.20	10%	\$ 208.08
15	REAR DOOR LOWER LOCK RH <b>SVC</b>	1	\$ 145.90	10%	\$ 131.31
16	REAR DOOR TOP LOCK RH	1	\$ 155.10	10%	\$ 139.59
17	REAR DOOR GLASS INNER SEAL RH <b>NEC</b>	1	\$ 45.90	10%	\$ 41.31
18	REAR DOOR INNER TRIM RH <b>NN</b>	1	\$ 181.60	10%	\$ 163.44
19	REAR DOOR INNER SIDE HANDLE RH <b>NN</b>	1	\$ 115.70	10%	\$ 104.13
20	REAR BUMPER <b>DEF</b>	1	\$ 649.80	10%	\$ 584.82
21	REAR BUMPER SIDE RETAINER <b>NN</b>	2	\$ 96.40	10%	\$ 86.76
22	REAR BUMPER REFLECTOR <b>CRA</b>	2	\$ 131.80	10%	\$ 118.62
23	REAR BUMPER SPONGE <b>CRA</b>	2	\$ 177.00	10%	\$ 159.30
24	REAR TAIL LAMP <b>NN</b>	2	\$ 564.20	10%	\$ 507.78
25	REAR END PANEL <b>DD</b>	1	<del>\$ 250.28</del> <b>288.90</b>	10%	<del>\$ 225.25</del> <b>260.01</b>
26	REAR END PANEL INNER <b>BUL</b>	1	<del>\$ 485.59</del> <b>598.40</b>	10%	<del>\$ 436.53</del> <b>538.56</b>
27	REAR END PANEL TOP GARNISH <b>DEF</b>	1	<del>\$ 64.11</del> <b>110.30</b>	10%	<del>\$ 57.69</del> <b>99.27</b>
28	REAR END CORNER PANEL <b>NN</b>	2	\$ 284.20	10%	\$ 255.78

SPECIAL ITEMS	PARTS DESCRIPTION	QTY	PRICE \$	FINAL PRICE \$
1	REAR DOOR 70KM/H STICKER LH	1	\$ 15.00	\$ 15.00
2	REAR DOOR GLASS SEALANT LH <b>NEC</b>	1	\$ 50.00	\$ 50.00
3	REAR DOOR 6 PAX STICKER RH	1	\$ 15.00	\$ 15.00

4	REAR DOOR GLASS SEALANT RH	NEC	1	\$	50.00		\$	50.00	/
5	REAR NUMBER PLATE	NN	1	\$	40.00		\$	40.00	X
6	REAR BUMPER CLIP	NEC	10	\$	40.00		\$	30 40.00	X
7	REAR END TOP GARNISH CLIP	NN	5	\$	20.00		\$	20.00	/
8	REAR REVERSE SENSOR	Shorted	1	\$	280.00		\$	200 280.00	/
<b>Total Special Items Cost</b>							\$	7,198.80	

### Labour Works/ Panel Beating Related Works

Job Scope	Quotation
TO RENEW DAMAGED PARTS, REPLACED AND REALIGNED HYDRAULIC, ALIGNED ALL PARTS	\$ 700 1,000.00
	850

### Spray Painting

Job Scope	Quotation
TO RESPRAY AFFECTED AREAS	\$ 650 1,000.00
	700

### Others Cost (Accident Repair Related Expenses)

Job Scope	Quotation
TO REMOVE & REFIX REAR WINDSCREEN	\$ 100.00
TO REPLACE REAR WINDSCREEN	\$ 100.00
TO REMOVE/ REFIT WIRING CHECKS	\$ 30 60.00
TO REMOVE/ REPLACE REAR SILENCER BOX	\$ 80.00
TO REMOVE/ REPLACE REVERSE SENSORS	\$ 30 100.00
TO REMOVE AND REPLACE NEW DOOR MECHANISM LH	\$ 50 100.00
TO REMOVE AND REPLACE NEW DOOR MECHANISM RH	\$ 50 100.00
<b>Total Others Cost</b>	\$ 640.00
<b>GRAND TOTAL</b>	\$ 9,838.80

CARZ AUTO SERVICES PTE LTD

Person Incharge: Ms Cecilia Chong  
Job Title: Operations Executive  
Direct Contact: 65 9023 6692  
Email: cecilia@carzauto.com.sg

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

*[Signature]*  
25/1/19  
Huee Jie-LKK  
23/1/19  
L/s ~~days~~ 7days  
*[Signature]*

Total - \$4900

### ...CLAIM SUBFOLDER...(Pending for Survey Report)




































CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	22 Jan 2019 10:45		22 Jan 2019 16:09 <a href="#">Edit Adj Rpt</a>	<b>S\$4,900.00</b> <a href="#">Edit Estimates</a>	<b>S\$4,900.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>






































  

Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b> <span style="float: right;">[Created by insurer]</span>									
Insured: <b>TOKYO CENTURY LEASING (SINGAPORE) PTE LTD</b> , Co. Reg. No.: 197901535G									
Main Claimant: <b>LEE KIM TAH (PTE) LTD</b> , Co. Reg. No.: 196800499G									
Vehicle Reg. No.:	<b>GBC5110T</b>	Date of Loss:	18/01/2019 09:00 - :59 [74 Months and 25 Days From LTA Reg Date (Man Yr)]						
Claim Type:	<b>TP / 224530</b>	Policy/Cover Note No.:	1000691854 (Comprehensive) Coverage: 01/06/2018 - 31/05/2019						
Vehicle Reg. No. (Insured):	<b>SLC9774H</b>	Policy No. (Claimant):							
		Excess:	S\$0.00						
Repairster:	<b>Carz Auto Services Pte Ltd - Woodlands (HQ)</b> NO 61, WOODLANDS INDUSTRIAL PARK E9, #04-04 E9 PREMIUM SINGAPORE 757047, 757047 Woodlands - Tel:								
Handling Insurer:	<b>MSIG Insurance (Singapore) Pte. Ltd. (HQ)</b> - Tel: +65 6827 7888 ... [Handled by <b>Jasmine Lok Kheng Kwei</b> - 6594 2550]								
Adjuster:	<b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [Handled by <b>ONG HWEE JIE</b> ] ... [Final Rpt due 21/02/2019]								
Driver/Custodian (Insured):	YEO CHIN HSIUNG (), NRIC: S8032834F								
Adj Asg. Remarks:	on WP. TP Pre-Repair Survey. TP selected LKK to be SJE. Liability : 100% Contact : Ms Cecilia Chong @ 6493 1924								
<b>ASSOCIATED MAIL RECEIVED</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Compose Case Mail</a></span>									
There are no mail for this case.									
<b>ALL ASSOCIATED TASKS</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a></span>									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## Claim Documents

\*GBC5110T (224530)  
[SLC9774H]  
TP  
LEE KIM TAH (PTE) LTD  
Jan 18 2019 9:00AM  
[TOKYO CENTURY LEASING (SINGAPORE) PTE LTD]  
Carz Auto Services Pte Ltd - Woodlands

Upload Documents		Upload Photos		Compose New Letter		View		View in Browser	
Assessment Reports						1 per page		<input checked="" type="checkbox"/>	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)				Thumbnail		Print	
1	24/01/19 14:32	Adjuster Immediate Advice				 Load HTM		<input checked="" type="checkbox"/>	
Photos/Images						3 per page		<input checked="" type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)				Thumbnail		Print	
1	24/01/19 11:03	General View				 Load JPG		<input checked="" type="checkbox"/>	
2	24/01/19 11:03	General View				 Load JPG		<input checked="" type="checkbox"/>	
3	24/01/19 11:03	General View				 Load JPG		<input checked="" type="checkbox"/>	
4	24/01/19 11:03	General View				 Load JPG		<input checked="" type="checkbox"/>	
5	24/01/19 11:03	General View				 Load JPG		<input checked="" type="checkbox"/>	
6	24/01/19 11:03	General View				 Load JPG		<input checked="" type="checkbox"/>	
7	24/01/19 11:03	General View				 Load JPG		<input checked="" type="checkbox"/>	
8	24/01/19 11:03	General View				 Load JPG		<input checked="" type="checkbox"/>	
9	24/01/19 11:03	General View				 Load JPG		<input checked="" type="checkbox"/>	
10	24/01/19 11:03	General View				 Load JPG		<input checked="" type="checkbox"/>	
11	24/01/19 11:03	General View				 Load JPG		<input checked="" type="checkbox"/>	
12	24/01/19 11:03	General View				 Load JPG		<input checked="" type="checkbox"/>	
13	24/01/19 11:03	General View				 Load JPG		<input checked="" type="checkbox"/>	
14	24/01/19 11:03	General View				 Load JPG		<input checked="" type="checkbox"/>	
15	24/01/19 11:03	General View				 Load JPG		<input checked="" type="checkbox"/>	
16	24/01/19 11:03	General View				 Load JPG		<input checked="" type="checkbox"/>	
17	24/01/19 11:03	General View				 Load JPG		<input checked="" type="checkbox"/>	
18	24/01/19 11:03	General View				 Load JPG		<input checked="" type="checkbox"/>	
19	24/01/19 11:03	General View				 Load JPG		<input checked="" type="checkbox"/>	
20	24/01/19 11:03	General View				 Load JPG		<input checked="" type="checkbox"/>	
21	24/01/19 11:03	General View				 Load JPG		<input checked="" type="checkbox"/>	
22	24/01/19 11:03	General View				 Load JPG		<input checked="" type="checkbox"/>	
23	24/01/19 11:03	General View				 Load JPG		<input checked="" type="checkbox"/>	
24	24/01/19 11:03	General View				 Load JPG		<input checked="" type="checkbox"/>	
25	24/01/19 11:03	General View				 Load JPG		<input checked="" type="checkbox"/>	
26	24/01/19 11:03	General View				 Load JPG		<input checked="" type="checkbox"/>	
27	24/01/19 11:03	General View				 Load JPG		<input checked="" type="checkbox"/>	
28	25/01/19 10:04	Dismantled Parts				 Load JPG		<input checked="" type="checkbox"/>	
29	25/01/19 10:04	Dismantled Parts				 Load JPG		<input checked="" type="checkbox"/>	
30	25/01/19 10:04	Dismantled Parts				 Load JPG		<input checked="" type="checkbox"/>	
31	25/01/19 10:04	Dismantled Parts				 Load JPG		<input checked="" type="checkbox"/>	
32	25/01/19 10:04	Dismantled Parts				 Load JPG		<input checked="" type="checkbox"/>	
33	25/01/19 10:04	Dismantled Parts				 Load JPG		<input checked="" type="checkbox"/>	
34	25/01/19 10:04	Dismantled Parts				 Load JPG		<input checked="" type="checkbox"/>	

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
				<input checked="" type="checkbox"/>
35	25/01/19 10:04	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
36	25/01/19 10:04	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
37	25/01/19 10:04	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
38	25/01/19 10:04	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
39	25/01/19 10:04	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
40	25/01/19 10:04	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
41	25/01/19 10:04	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
42	25/01/19 10:04	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
43	25/01/19 10:04	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
44	25/01/19 10:04	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
45	25/01/19 10:04	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
46	25/01/19 10:04	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
47	25/01/19 10:04	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
48	25/01/19 10:04	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
49	25/01/19 10:04	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
50	25/01/19 10:04	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
51	25/01/19 10:04	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
52	25/01/19 10:04	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
53	25/01/19 10:04	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
54	25/01/19 10:04	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
55	25/01/19 10:04	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
56	25/01/19 10:04	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
57	25/01/19 10:04	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
58	29/01/19 09:02	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
59	29/01/19 09:02	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
60	29/01/19 09:02	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
61	29/01/19 09:02	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
62	29/01/19 09:02	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
63	29/01/19 09:02	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
64	29/01/19 09:02	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
65	29/01/19 09:02	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
66	29/01/19 09:02	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
67	29/01/19 09:02	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	21/01/19 19:07	TP EST BILL	 Load PDF	
2	21/01/19 19:22	E-FILE REPORT (SLC9774H)	 Load PDF	
3	21/01/19 19:22	E-FILE REPORT (GBC5110T)	 Load PDF	
4	22/01/19 11:02	TP SELECTED LKK TO BE SJE	 Load PDF	

## Documents Checklist

<b>DOCUMENTS CHECKLIST</b> <span>Reset</span> <span>Save</span> <span>Print</span>
There are no document checklists configured.
<b>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</b> <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>

Show Remarks To: ☐ Handling Insurer  
Note: Remarks are private unless you show it to other parties.



## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG19001468/JTD3E2

Date: 29/01/2019

## REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: 1000691854

Claimant Vehicle No : GBC5110T

Insured Vehicle No : SLC9774H

Date of Loss: 18/01/2019

Nature of Claim: TP

Claim No: 224530

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No: GBC5110T

Make & Model: NISSAN NV200, 1.5 L ABS AIRBAG 2WD 6DR  
EURO 5 (M)

Engine No: K9KF276D126904

Reg. Date: 24/10/2012 (Man. Year: 2012)

Chassis No: VSKYBAM20U0038809

Colour: Silver

Odometer: 214227 km

Engine Capacity: 1461 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

## CONDITION OF TYRES

Front Tyre Size: 175/70 R14

Rear Tyre Size: 175/70 R14

Front Left Side: Yokohama 7 mm

Rear Left Side: Yokohama 7 mm

Front Right Side: Yokohama 7 mm

Rear Right Side: Yokohama 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,198.80	4,312.44	2,886.36	40.10
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,640.00	1,810.00	830.00	31.44
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>9,838.80</b>	<b>6,122.44</b>	<b>3,716.36</b>	<b>37.77</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>4,900.00</b>		
(S\$)	9,838.80	4,900.00	4,938.80	50.20
+ GST 7.00/7.00% (S\$)	688.72	343.00	345.72	50.20
<b>Nett Amount (S\$)</b>	<b>10,527.52</b>	<b>5,243.00</b>	<b>5,284.52</b>	<b>50.20</b>

## INSPECTION

Date of Assignment: 22/01/2019

Date Inspected: 23/01/2019 Inspected At:

Carz Auto Services Pte Ltd - Woodlands  
(HQ)  
NO 61, WOODLANDS INDUSTRIAL  
PARK E9, #04-04 E9 PREMIUM  
SINGAPORE 757047  
Singapore 757047

Estimated Period of Repair: 7.0 days

---

**Adjuster:** ONG HWEE JIE

**Manager:** DENISE TAY KWEE CHENG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

## Reference

<b>Part Source:</b>	(Last Synchronised: 29 Jan 2019)	
<b>Parts:</b>	N/A	NISSAN NV200 1.5 L ABS AIRBAG 2WD 6DR EURO 5 (M) (Model not available in database)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for GBC5110T)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR DOOR LH	Buckled	1,391.30 FL	*1,150.00 FL
2	1		*REAR DOOR INNER TRIM LH	Not Necessary	205.80 FL	*- FL
3	1		*DOOR LOGO LH	Necessary	80.90 FL	*80.90 FL
4	1		*REAR DOOR NV200 EMBLEM LH	Necessary	79.90 FL	*79.90 FL
5	1		*REAR DOOR GLASS INNER SEAL LH	Necessary	45.90 FL	*45.90 FL
6	2		*REAR DOOR HINGE LH	Not Necessary	231.20 FL	*- FL
7	1		*REAR DOOR INNER LOWER LOCK LH	Serviceable	145.90 FL	*- FL
8	1		*REAR DOOR LOWER CATCH LOCK LH	Serviceable	88.20 FL	*- FL
9	1		*REAR DOOR FRAME WEATHERSTRIP	Cut	110.70 FL	*110.70 FL
10	1		*REAR DOOR TOP LOCK LH	Serviceable	155.10 FL	*- FL
11	1		*REAR DOOR RH	Buckled	980.90 FL	*980.90 FL
12	1		*REAR DOOR DCI EMBLEM RH	Necessary	80.90 FL	*80.90 FL
13	1		*REAR DOOR SEAL RH	Deformed	58.90 FL	*58.90 FL
14	2		*REAR DOOR HINGE RH	Not Necessary	231.20 FL	*- FL
15	1		*REAR DOOR LOWER LOCK RH	Serviceable	145.90 FL	*- FL
16	1		*REAR DOOR TOP LOCK RH	Serviceable	155.10 FL	*- FL
17	1		*REAR DOOR GLASS INNER SEAL RH	Necessary	45.90 FL	*45.90 FL
18	1		*REAR DOOR INNER TRIM RH	Not Necessary	181.60 FL	*- FL
19	1		*REAR DOOR INNER SIDE HANDLE RH	Not Necessary	115.70 FL	*- FL
20	1		*REAR BUMPER	Deformed	649.80 FL	*649.80 FL
21	2		*REAR BUMPER SIDE RETAINER	Not Necessary	96.40 FL	*- FL
22	2		*REAR BUMPER REFLECTOR	Cracked	131.80 FL	*131.80 FL
23	2		*REAR BUMPER SPONGE	Cracked	177.00 FL	*177.00 FL
24	2		*REAR TAIL LAMP	Not Necessary	564.20 FL	*- FL
25	1		*REAR END PANEL	Dented	288.90 FL	*250.00 FL
26	1		*REAR END PANEL INNER	Buckled	598.40 FL	*485.00 FL
27	1		*REAR END PANEL TOP GARNISH	Deformed	110.30 FL	*64.00 FL
28	2		*REAR END CORNER PANEL	Not Necessary	284.20 FL	*- FL
29	1		*REAR DOOR 70KM/H STICKER LH	Necessary	15.00 FS	*15.00 FS
30	1		*REAR DOOR GLASS SEALANT LH	Necessary	50.00 FS	*50.00 FS
31	1		*REAR DOOR 6 PAX STICKER RH	Necessary	15.00 FS	*15.00 FS
32	1		*REAR DOOR GLASS SEALANT RH	Necessary	50.00 FS	*50.00 FS
33	1		*REAR NUMBER PLATE	Not Necessary	40.00 FS	*- FS
34	10		*REAR BUMPER CLIP	Necessary	40.00 FS	*30.00 FS
35	5		*REAR END TOP GARNISH CLIP	Not Necessary	20.00 FS	*- FS
36	1		*REAR REVERSE SENSOR	Shorted	280.00 FS	*200.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>7,942.00</b>	<b>4,751.60</b>
<b>- List Item Discount on L Items 10.00/10.00% (\$\$)</b>	<b>743.20</b>	<b>439.16</b>

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
				Total Parts (S\$)	7,198.80	4,312.44

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO RENEW DAMAGED PARTS, REPLACED AND REALIGNED HYDRAULIC, ALIGNED ALL PARTS	New	1,000.00	850.00
2	TO RESPRAY AFFECTED AREAS	New	1,000.00	700.00
3	TO REMOVE & REFIX REAR WINDSCREEN	New	100.00	100.00
4	TO REPLACE REAR WINDSCREEN	New	100.00	0.00
5	TO REMOVE / REFIT WIRING CHECKS	New	60.00	30.00
6	TO REMOVE / REPLACE REAR SILENCER BOX	New	80.00	0.00
7	TO REMOVE / REPLACE REVERSE SENSORS	New	100.00	30.00
8	TO REMOVE AND REPLACE NEW DOOR MECHANISM LH	New	100.00	50.00
9	TO REMOVE AND REPLACE NEW DOOR MECHANISM RH	New	100.00	50.00
Gross Labour Cost (S\$)			<b>2,640.00</b>	<b>1,810.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >