

22/03/2019

ASS. REC. BY:

REF

CS3/MSG18017624/Gtd3.1

Special Instructions:

Survivor
Member

From person:

Chhia Nyuk Pui

ASSIGNMENT (Office)

MS16

Date/Time

23/01/2019

Estimated Cost:

Bill to:

OD TP WS / TP RES / OD RES / EVA / INV / MV / CS

To inspect Vehicle No:

FBL 7951Y

Insured:

FQ 7655D

at Workshop in/s

ong Motor

Tel:

8380 2233

of

No. 464 Macpherson Rd

Policy No:

MSD/VMS/18-38270

Claim No:

MSC/v/18-001273

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A

17/09/18

CA / REV / REP. / REV 24 HRS

(up)

28/09/18

Date/Time:

5:04pm 27/1/18

Person Contacted:

Jaeky

H.O.D. Endorsement:

Vehicle IN/OUT

Date/Time	Action/Instruction (X) Estimate	Do Not Finalize
	FBL 7951Y - NA/INC18017058/r3	DOA: 17/9/18
	FQ 7655D - NA/INC18017058/r3	DOA: 17/9/18
	Diamond: 2/10/2018	
	Advise the margin repair value. Submit.	
	\$4950, 5 days.	\$4800, 5 days
		Cred: 3400, 44%



18/4 file pass to typist

17/4/2019

MV: 90001
LTA 57471-
Net LTA: 3253

Indicate in report.



RECEIVED 18 APR 2019



PR'S
Xnd.

REF: MSIG

64746

ASSIGNMENT

From:

Date:

28/9/18

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

FBL 7951Y

at Workshop m/s

Ong Motor

of

No. 164 Macpherson Rd

Insured:

Policy No:

Claims No:

Sum Insured:

Excess:


(Client's Record)

Make of Veh:

jaeky @ 8380 2233

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

3

days

Res.:

Yes or No

Lum Sum:

20

%

3 Val.:

Yes or No

CA / REV / REP. / 24 HRS 'wp'

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

FBL 7951Y

Yr Regn:

15 Mar 2017

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Yamaha XABRE

Colour:

Black

Sp. Reading:

Eng/No:

C/No:

MH 3R63710 (1K02432)

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mod: N/S / Rim / STD A/Rim or

Tyre Size:

F:

110/70-17

R:

130/70-17

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

IRC

Front

Rear

R/Bal:

5

mm

R/Bal:

5

mm

L/Bal:

5

mm

L/Bal:

mm

D.O.A.

D.O.I.

28-09-18

Survey held at

w/s

5pm

Des. of Damages: Frt / Rear / O/S / U/S / UIC / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

\$2000 - \$3000

MV: \$9000

cdg: 5747

mt: 3253

Date/Time: File Pass to?



: Prel. Report

1)



: Final Report

Date/Time: File Return to?

2)

Days Of Repair:

3

Resurvey No. of Trip:

1

Survey Fee:

Transportation:

\$ - RS. \$

Photos

Others

Add Fee:



Site Insp (\$



Interview (\$



Tech. Invs (\$



Weekend (\$

Report Format :

PRQ

Lump Sum / I.B.I. (\$

TOTAL

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	17 Sep 2018		27 Sep 2018 09:35 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS									
Insured:	KENNEDY KWOK JUN AN , ID: S9632237B, Tel: +6584484520, Email: NOEMAIL [Created by insurer]								
Main Claimant:	LIM AI GEOK , ID: S1406474E								
Vehicle Reg. No.:	FBL7951Y	Date of Loss:	17/09/2018 02:00 - :59 [18 Months and 2 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / MSC/V/18-001273	Policy/Cover Note No.:	MSD/VMS/18-382170 (TP, Fire & Theft) Coverage: 24/04/2018 - 23/04/2019						
Vehicle Reg. No. (Insured):	FQ7655D	Policy No. (Claimant):	Excess:						
Repairer:	Ong Motor Trading (MACPHERSON RD) No. 464 Macpherson Road, 368182 Macpherson - Tel:								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Chhia Nyuk Pui - 6594 2521]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Final Rpt due 25/01/2019]								
Driver/Custodian (Insured):	KENNEDY KWOK JUN AN (22 / Male), NRIC: S9632237B, Tel: +6584484520								
Adj Asg. Remarks:	SURVEY DISAGREE ON SJE - ASSIGN LKK. LIABILITY:50%/50% CONTACT: JACKY SIAH 8380 2233								
ASSOCIATED MAIL RECEIVED									
<ul style="list-style-type: none"> MSIG_SG (23/01/2019): Report Send Back Alerts - FBL7951Y (TP) 			View All	Compose Case Mail					
ALL ASSOCIATED TASKS									
Due Date	Priority	Type	Task Group	Subject	Handler	View All	Search Tasks	Create New Task	Complete
						Assigned By	Completed On	Created On	Done?
No results.									

Catherine Chong (LKK Auto)

From: Denise Tay (LKKAuto) <denisetay@lkkauto.com>
Sent: Wednesday, 23 January, 2019 10:23 AM
To: assignments
Subject: FW: Your ref: AS.182293.sl. Our ref: MSC/V/18-001273 (OIV: FQ7655D)

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Chhia Nyuk Pui <NyukPui_Chhia@sg.msig-asia.com>
Sent: Wednesday, 23 January 2019 9:57 AM
To: Veron Chen (LKKAuto) <veronchen@lkkauto.com>; SUR <sur@lkkauto.com>; Shiau Chan (LKKAuto) <siewsc@lkkauto.com>
Subject: FW: Your ref: AS.182293.sl. Our ref: MSC/V/18-001273 (OIV: FQ7655D)

Dear LKK

Please do a paper re for us and advise us the margin repair value.

We have sent back via Merimen.

Thanks!

Chhia Nyuk Pui
Senior Executive, Claims Services
Direct line +65 6594 2521 | Direct fax +65 6643 1349 | nyukpui_chhia@sg.msig-asia.com

From: Chhia Nyuk Pui
Sent: Wednesday, 23 January, 2019 9:51 AM
To: 'Roy' <roy@chiaarul.com>; 'info@chiaarul.com' <info@chiaarul.com>
Subject: Your ref: AS.182293.sl. Our ref: MSC/V/18-001273 (OIV: FQ7655D)

Dear Sir/Madam

Without Prejudice
Save as to Costs

We refer to your letter dated 28.11.18

We are looking into the claim and shall come back to you soon.

Thank you.


Please note that by submitting this claim to us, you are deemed to have agreed to us collecting, using, disclosing and processing your personal data for the purpose of assessing your claim. This may include disclosing and sharing your personal data with our service providers and/or with other insurers in the general insurance industry, including the General Insurance Association of Singapore, for the proper processing, handling and/or dealing with your claim, which includes investigating the said claim, and complying with applicable laws (collectively, "the Purpose"). We may also need to disclose or share your personal data with service providers who are sited outside Singapore for the Purpose.

Chhia Nyuk Pui

Senior Executive, Claims Services

Direct line +65 6594 2521 | Direct fax +65 6643 1349 | nyukpui_chhia@sg.msig-asia.com




MSIG Insurance (Singapore) Pte. Ltd. 16 Raffles Quay, #24-01 Hong Leong Building, Singapore 048581 | Tel +65 6220 9644 | Fax +65 6225 6371 | Co. Reg. No. 200412212G | www.msig.com.sg | Follow us on  [@MSIG_SG](https://www.facebook.com/MSIG_SG)

A member of **MS&AD** INSURANCE GROUP

CHIA S ARUL LLC
ADVOCATES & SOLICITORS
UEN 201330709H

ARULCHELVAN S



Our Ref : AS.182293.sl
Your Ref : To be advised 18-001273

28 NOV 2018

MSIG INSURANCE (S) PTE LTD
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

BY PDX

KENNEDY KWOK JUN AN
297 Bukit Batok Street 22
#08-38 Singapore 650297

BY CERTIFICATE OF POSTING

Dear Sirs,

NAME OF CLAIMANT: LIM AI GEOK
ADDRESS OF CLAIMANT: C/O MOTO 51 PTE LTD
2 KAKI BUKIT AVENUE 2
#01-17 KAKI BUKIT AUTOHUB
SINGAPORE 417921

ACCIDENT INVOLVING FBL 7951Y & FQ 7655D ALONG BKE TOWARDS PIE ON 17 SEPTEMBER 2018

We are instructed by the abovenamed to claim damages against you in connection with a road traffic accident on 17 September 2018 at about 2:50p.m. along BKE towards PIE involving our client's vehicle registration FBL 7951Y and vehicle registration number FQ 7655D owned by you at all material time.

We are instructed that the accident was caused by the negligent driving and/or management of the vehicle. As a result of the accident, our client's vehicle was damaged and our client has been put to loss and expense, particulars of which are as follows:

a)	Costs of Repair	S\$ 7,700.00
b)	Costs (inclusive of GST)	S\$ 1,500.00
c)	Survey Report Fee	S\$ 725.00
d)	Towing fee	S\$ 70.00
e)	GIA Report Fee	S\$ 29.00
f)	Loss of Use (20 days x S\$50)	S\$ 1,000.00
g)	LTA Search Fee	S\$ 7.49
	Total	S\$ 11,031.49

A copy of each of the following supporting documents is enclosed.

- a) A copy of our client's GIA report and police report;
- b) A copy of your insured rider GIA report and police report;
- c) A copy of the survey report, invoice and photographs of our client's motor vehicle;
- d) A copy of our client's proforma tax invoice ;
- e) A copy of the Towing receipt; and
- f) A copy of the LTA search.

Please note that if you are insured and you wish to claim under your insurance policy, you should immediately pass this letter and all the enclosed documents to your insurer.

Please note that you or your insurer should send to us an acknowledgement of receipt of this letter within 14 days of your receipt of this letter, failing which our client will have no alternative but to commence proceedings against you without further notice to you or your insurer.

Please also note that if you have a counterclaim against our client arising out of the accident, you are also required to send to us a letter giving full particulars of the counterclaim together with all relevant supporting documents within 8 weeks of your receipt of this letter.

Yours faithfully,

MR ARULCHELVAN S

Enclosure(s)

Law Firm Search Details

Law Firm Case No.: FBL7951Y

Current Owner Details

Owner ID: S9632237B

Registered Address Type: HDB / HUDC

Registered Block/House No.: 297

Registered Street Name: BUKIT BATOK STREET 22

Registered Unit No.: # 08 - 38

Registered Building Name: -

Registered Postal Code: 650297

Current Vehicle Details

Vehicle No.: FQ7655D

Make Description/Model: YAMAHA / YZF-R15

Insurance Company Name: MSIG INSURANCE (SINGAPORE) PTE LTD



BIKEBULANCE

9D, Yuan Ching Road #03-38 S(618546)
Tel: 6425-5333 96080928
Email: bikebulance@yahoo.com
MOTORCYCLE/SCOOTER Haulage Company

☐ DELIVERY ORDER
☐ CASH SALE
☐ INVOICE

CHK/S:

mudo 57

NO : 16164

RE :

DATE: 19/9/18.

ITEM	QTY	DESCRIPTION	UNIT PRICE	AMOUNT
1		Towing FBL 795T	\$	\$ 70
2		Boat by - LK - washup	\$	\$
3			\$	\$
4			\$	\$
5			\$	\$
Total			\$	\$ 70

50% of quoted Price or min \$20 (which ever is higher) is liable for cancellation of booking (Not For Contract Basis)

注意: 本公司對所拖的電單車, 在拖運中如有任何損壞, 一概由車主自行負責

NOTE: Vehicle is hauled at owner's risk. The Company accepts no responsibility for damages or other misdemeanor to your vehicle whilst being towed

YM2E ☐ YM3C ☐ GY2E ☐ GBB2K ☒ GZ2320T ☐ GBB4376E ☐ Other ☐

E & O E

Issued By

Customer's Signature & Chop

Bikebulance Is The Solution To Your Motorcycle / Scooter Conveying Needs (Local & West Malaysia)

MOTO 51 PTE LTD

Kaki Bukit Autohub, 2 Kaki Bukit Ave 2, #01-18
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : moto51@n51.com.sg
Company Reg. No. : 201536417C

18220621

LIM AI GEOK
BLK 259 BOON LAY DRIVE #12-523
SINGAPORE 640259

Contact : 97122384

TAX INVOICE

Date : 29/10/2018

Date in : 17/09/2018

Vehicle Num. : FBL7951Y

Make/Model : YAMAHA XABRE TFX150-2017

Chassis/Eng# : MH3RG3710HK024327/G3G8E0030352

Accident Date : 17/09/2018

Claim No : CLM13314

Reference : SEPT-06/2018

Policy No. : 5088593378-01 (14/03/2019)

LUMP SUM REPAIR BILL

AS PER SURVEYOR REPORT

REF : CAS/18-10/043 DATED 20/09/2018

BY CONSTANT APPRAISER SERVICES

Amount S\$

7,700.00

E. & O.E. Sub S\$: 7,700.00

Total Amount S\$: 7,700.00



for MOTO 51 PTE LTD

TAX INVOICE

Our Ref No: GR-18-147917
Date of Request: 25/09/2018

Your Ref No: WALK IN LEONG

MOTO 51 PTE LTD
2 KAKI BUKIT AVENUE 2, #01-17, KAKI BUKIT AUTOHUB
SINGAPORE 417921

Dear Sir/Madam,

Your Vehicle No: FBL7951Y
Date of Accident: 17/09/2018
Place of Accident: BKE
Involving Vehicle No: FQ7655D

DESCRIPTION	AMOUNT (S\$)
E-File Search Fee (Public)	
GST Amount	14.02
Total Amount Due (GST Inclusive)	0.98
	15.00

Thank You.

This is a computer generated document and requires no signature.

For GIARMC Official use:

Date:

☐ GIRO ☒ Cash ☐ Cheque



RECORDS MANAGEMENT CENTRE

GENERAL INSURANCE ASSOCIATION OF SINGAPORE
RECORDS MANAGEMENT CENTRE

6 Raffles Quay #18-00, Singapore 048580
Phone: +65 6224 0010 Fax: +65 6224 0030
Operating Hours: Monday to Friday 9am to 5pm
GST Registration No: M400017735

TAX INVOICE

Our Ref No: GR-18-147918
Date of Request: 25/09/2018

Your Ref No: WALK IN LEONG

MOTO 51 PTE LTD
2 KAKI BUKIT AVENUE 2, #01-17, KAKI BUKIT AUTOHUB
SINGAPORE 417921

Dear Sir/Madam,

Date of Accident: 17/09/2018
Vehicle No: FBL7951Y
Place of Accident: BKE TWDS PIE
Involving Vehicle No: FQ7655D

With reference to your application for the accident report, we have attached the following accident reports as requested:

DOCUMENTS	ACCIDENT LOCATION	PER DOC (S\$)	QTY	AMOUNT (S\$)
FQ7655D	BKE TWDS PIE	14.00	1	13.08
GST Amount				0.92
Total Amount Due (GST Inclusive)				14.00

The images provided to you are taken from the original reports forwarded to the centre by the members of the General Insurance Association of Singapore and we take no responsibility for their accuracy or contents and shall be under no liability whatsoever for any loss or damage arising out of or in connection with the reports or their images.

Thank You.

This is a computer generated document and requires no signature.

For GIARMC Official use:

Date:

☐ GIRO ☒ Cash ☐ Cheque

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	19/09/2018 14:34
Date Of Accident	17/09/2018 02:00
Exact Location Of Accident	BKE TWDS PIE
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	FBL7951Y
Insured/Policyholder	
Name Of Registered Owner	LIM AI GEOK
NRIC No	S1406474E
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-97122384
Alternative Phone No	OTHERS-97122384

Vehicle Particulars

Manufacturer	YAMAHA
Model	XABRE TFX150
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	MOTORCYCLE

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	NO
Policy Number	5088593378-01
Cover Note Number	

Driver

Name of Driver	TAY YU HENG
NRIC No	S9633335H
Date Of Birth	19/09/1996
Occupation	OUTDOOR
Date Of Driving Pass	11/01/2017
Driving Experience	1 YEAR AND 8 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-97122384
Fax Number	
Contact Number	

Address	BLK 259 BOON LAY DRIVE #12-523
Postcode	640259
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	CHILDREN
Vehicle Registration Number of Driver's Own Vehicle	- - -
Insurance Company of Driver's Own Vehicle	- - -

General Information of the Accident

Type Of Accident	SIDE SWIPE
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	JURONG WEST NPC
Police Station Address	ROAD: 700 CORPORATION ROAD , POSTCODE: 649818 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: - FAX NO:
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

PLS REFER TO THE POLICE REPORT: T/20180918/2001

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	FQ7655D
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	MOTORCYCLE
Name of Driver	KENNEDY KOWK JUN AN
NRIC/Passport Number	S9632237B
Contact Number	
Address	
Postcode	

No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name

TAY YU HENG

Approximate Age

Injuries Sustain

LEFT LEG,RIGHT WRIST & LEFT ELBOW

Injured person in which vehicle?

FBL7951Y

Were seat belts worn?

Was this injured conveyed to hospital by ambulance?

NO

Address

Postcode

Accident Sketch Plan

SKETCH PLAN


IMPORTANT NOTICE


1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:


Driver's Signature
(If driver is not the policyholder)
Date & Time: 19/09/18


 19/09/18
Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Accident Sketch Plan

SKETCH PLAN

A-FBL7951Y

B-FQ7655D




DESCRIBE CIRCUMSTANCES OF THE ACCIDENT


Pls refer to the police report: 5/20180918/2001

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:


Driver's Signature
(If driver is not the policyholder)
Date & Time: 19/09/18

 19/09/18
Reporting Centre Personnel's Signature
Name:
NRIC/FIN No:

Individual Statement



SINGAPORE
POLICE FORCE



T/20180918/2001

Police Station Of Origin:
Jurong West N.P.C
700 Corporation Road SINGAPORE 649818
Tel No: 1800-2689999

2 of 3

Report No. T/20180918/2001

CONTINUATION OF REPORT

Brief Details.

On 17/9/2018 at around 0200hrs, i was riding my bike(FBL7951Y) along BKE towards PIE. I was riding on the second left most lane. While on my left there was another rider however, i do not remember what is the plate number however, the model of the bike is Yamaha R15, black color with the rider namely: Keanedy Kowk Jun An, S9632237B.

Ahead of the rider was a vehicle going to make a stop as it flashes hazard light, the rider then make a lane change towards his right side without signaling before hand. As a resulted, the other rider crash along the left side of my bike. I then lost my balance and fell towards the left of my bike. Passerby then stop on the road to help me out. Both of us then exchange our particulars. After that, i then make a check on my bike and discovered that the gear, hand guard and mirror was damaged. There's ambulance on scene.

On the same date at round 0600hrs, i went to Ng Teng Fong to seek treatment and i was given medical leave from 17/9/2018 to 24/9/2018. I sustained injuries on left leg, cuts on my right wrist and left elbow.

[> Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:	Singapore NRIC
Owner ID:	6474E

Vehicle Details

Vehicle No.:	FBL7951Y
Vehicle to be Exported:	No
Intended Deregistration Date:	17 Apr 2019
Vehicle Make:	YAMAHA
Vehicle Model:	XABRE TFX150
Primary Colour:	Grey
Manufacturing Year:	2017
Engine No.:	G3G8E0030352
Chassis No.:	MH3RG3710HK024327
Maximum Power Output:	-
Open Market Value:	\$2,727.00
Original Registration Date:	15 Mar 2017
First Registration Date:	15 Mar 2017
Transfer Count:	0
Actual ARF Paid:	\$410.00

Intended PARF Rebate Details

PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00

Intended COE Rebate Details

COE Expiry Date:	14 Mar 2027
COE Category:	D - Motorcycle
COE Period(Years):	10
QP Paid:	\$6,801.00
COE Rebate Amount:	\$5,375.00
Total Rebate Amount:	\$5,375.00

The information contained herein is correct as at 17 Apr 2019

OK

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Owner ID Type:	Singapore NRIC
Owner ID:	6474E
Vehicle No.:	FBL7951Y
Vehicle to be Exported:	No
Intended Deregistration Date:	01 Oct 2018
Vehicle Make:	YAMAHA
Vehicle Model:	XABRE TFX150
Primary Colour:	Grey
Manufacturing Year:	2017
Engine No.:	G3G8E0030352
Chassis No.:	MH3RG3710HK024327
Maximum Power Output:	-
Open Market Value:	\$2,727.00
Original Registration Date:	15 Mar 2017
First Registration Date:	15 Mar 2017
Transfer Count:	0
Actual ARF Paid:	\$410.00
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
COE Expiry Date:	14 Mar 2027
COE Category:	D - Motorcycle
COE Period(Years):	10
QP Paid:	\$6,801.00
COE Rebate Amount:	\$5,747.00
Total Rebate Amount:	\$5,747.00

The information contained herein is correct as at 01 Oct 2018

OK

Home (2) > Motorbikes (categories/motorbikes-108)
 > Motorbikes for Sale (categories/motorbikes-108/motorbikes-for-sale-1592)
 > Class 2B (categories/motorbikes-108/motorbikes-for-sale-1592/class-2b-1595)



Yamaha xabre

43 Likes Chat Make Offer

6 months ago by
anthonytang (/anthonytang/)

S\$9,000

43 Likes

Used

In Class 2B (categories/class-2b-1595)

Yamaha xabre
 Reg March 2017
 Current mileage (106xx), very
 Low mileage for going 2
 read more

Make

Yamaha

Type

Road Bike

Share This Listing



(https://www.facebook.com/sharer/sharer.php?
 u=https://sg.carousell.com/p/yamaha-xabre-
 193299783/)

Public Comments

stylomarc 6 months ago (/stylomarc/)
 Price -

Be the first to write a public comment. Ask
 a question or @mention a friend to check
 this out!

Post a New Comment

Insurance

Insure this vehicle with AXA.
 Premiums start from S\$206.28

BUY AXA
 INSURANCE
 NOW

Getting This

Meet The Seller



anthonytang
 (/anthonytang/)
 joined 4 years ago.
 Verified

Reviews 5.0 ★★★★★ (12)



carmelgrc 5.0 ★
 (/carmelgrc) Great seller
 to deal with! Item
 delivered as descr...read
 more
 4 months ago



calista2 (/calista2) Great 5.0 ★
 seller to deal with!
 Prompt delivery! Item
 d...read more
 8 months ago



mrshank5353 0.0 ★
 (/mrshank5353) Nice
 and friendly seller.
 Thanks fr the item.
 Chee...read more
 10 months ago

Read All Reviews

YOU MAY ALSO LIKE

Home 17 > Motorbikes (categories/motorbikes-106) > Motorbikes for Sale (categories/motorbikes-106/motorbikes-for-sale-1392)
> Class 2B (categories/motorbikes-106/motorbikes-for-sale-1392/class-2b-1395)



Share This Listing



(https://www.facebook.com/sharer/sharer.php?u=https://sg.carousell.com/p/yamaha-2018-xabre-tfx-150-reserved-218091901/) 218

Yamaha 2018 XABRE TFX 150 (Reserved)

30 Chat Make Offer

- 1 month ago by addie_7478 (/addie_7478)
- \$58,300
- 30 Likes
- Used
- In Class 2B (categories/class-2b-1595)
- Selling November 2018 XABRE TFX 150 in very-very low mileage interested and keen
- Make Yamaha
- Type Road Bike

Insurance
Secure this vehicle with AXA
Premiums start from S\$206.28

BUY AXA
INSURANCE
NOW

Getting This

- Meet-up
- Caltex (https://www.google.com/maps/pla

Meet The Seller

addie_7478 (/addie_7478)
Joined 4 years ago
Verified

Reviews 5.0 ★★★★★ (10)

Read All Reviews

YOU MAY ALSO LIKE

<p>(/yamaha-sniper-for-sale-222488797/)</p> <p>2018 yamaha sniper-150-222488797</p> <p>218091901/218091901</p> <p>Yamaha Sniper F... R15 V2</p> <p>\$50 \$59,000</p> <p>Yamaha Sniper 150 F... R15 V2 FULL CASH</p> <p>Used</p> <p>(/yamaha-sniper-for-sale-222488797/)</p> <p>2018 yamaha sniper-150-222488797</p> <p>218091901/218091901</p>	<p>(/yamaha-sniper-150-222515787/)</p> <p>2018 yamaha sniper-150-222515787</p> <p>218091901/218091901</p> <p>Yamaha Sniper 1... R15 V2</p> <p>\$51,000</p> <p>Hi My Brother Hi Sate...</p> <p>Used</p> <p>(/yamaha-sniper-150-222515787/)</p> <p>2018 yamaha sniper-150-222515787</p> <p>218091901/218091901</p>	<p>(/yamaha-sniper-150-222515787/)</p> <p>2018 yamaha sniper-150-222515787</p> <p>218091901/218091901</p> <p>Yamaha Sniper 1... R15 V2</p> <p>\$51,000</p> <p>Hi My Brother Hi Sate...</p> <p>Used</p> <p>(/yamaha-sniper-150-222515787/)</p> <p>2018 yamaha sniper-150-222515787</p> <p>218091901/218091901</p>	<p>(/yamaha-sniper-150-222515787/)</p> <p>2018 yamaha sniper-150-222515787</p> <p>218091901/218091901</p> <p>Yamaha Sniper 1... R15 V2</p> <p>\$51,000</p> <p>Hi My Brother Hi Sate...</p> <p>Used</p> <p>(/yamaha-sniper-150-222515787/)</p> <p>2018 yamaha sniper-150-222515787</p> <p>218091901/218091901</p>	<p>(/yamaha-sniper-150-222515787/)</p> <p>2018 yamaha sniper-150-222515787</p> <p>218091901/218091901</p> <p>Yamaha Sniper 1... R15 V2</p> <p>\$51,000</p> <p>Hi My Brother Hi Sate...</p> <p>Used</p> <p>(/yamaha-sniper-150-222515787/)</p> <p>2018 yamaha sniper-150-222515787</p> <p>218091901/218091901</p>	<p>(/yamaha-sniper-150-222515787/)</p> <p>2018 yamaha sniper-150-222515787</p> <p>218091901/218091901</p> <p>Yamaha Sniper 1... R15 V2</p> <p>\$51,000</p> <p>Hi My Brother Hi Sate...</p> <p>Used</p> <p>(/yamaha-sniper-150-222515787/)</p> <p>2018 yamaha sniper-150-222515787</p> <p>218091901/218091901</p>
<p>(/yamaha-sniper-150-222515787/)</p> <p>2018 yamaha sniper-150-222515787</p> <p>218091901/218091901</p> <p>Yamaha Sniper 1... R15 V2</p> <p>\$51,000</p> <p>Hi My Brother Hi Sate...</p> <p>Used</p> <p>(/yamaha-sniper-150-222515787/)</p> <p>2018 yamaha sniper-150-222515787</p> <p>218091901/218091901</p>	<p>(/yamaha-sniper-150-222515787/)</p> <p>2018 yamaha sniper-150-222515787</p> <p>218091901/218091901</p> <p>Yamaha Sniper 1... R15 V2</p> <p>\$51,000</p> <p>Hi My Brother Hi Sate...</p> <p>Used</p> <p>(/yamaha-sniper-150-222515787/)</p> <p>2018 yamaha sniper-150-222515787</p> <p>218091901/218091901</p>	<p>(/yamaha-sniper-150-222515787/)</p> <p>2018 yamaha sniper-150-222515787</p> <p>218091901/218091901</p> <p>Yamaha Sniper 1... R15 V2</p> <p>\$51,000</p> <p>Hi My Brother Hi Sate...</p> <p>Used</p> <p>(/yamaha-sniper-150-222515787/)</p> <p>2018 yamaha sniper-150-222515787</p> <p>218091901/218091901</p>	<p>(/yamaha-sniper-150-222515787/)</p> <p>2018 yamaha sniper-150-222515787</p> <p>218091901/218091901</p> <p>Yamaha Sniper 1... R15 V2</p> <p>\$51,000</p> <p>Hi My Brother Hi Sate...</p> <p>Used</p> <p>(/yamaha-sniper-150-222515787/)</p> <p>2018 yamaha sniper-150-222515787</p> <p>218091901/218091901</p>	<p>(/yamaha-sniper-150-222515787/)</p> <p>2018 yamaha sniper-150-222515787</p> <p>218091901/218091901</p> <p>Yamaha Sniper 1... R15 V2</p> <p>\$51,000</p> <p>Hi My Brother Hi Sate...</p> <p>Used</p> <p>(/yamaha-sniper-150-222515787/)</p> <p>2018 yamaha sniper-150-222515787</p> <p>218091901/218091901</p>	<p>(/yamaha-sniper-150-222515787/)</p> <p>2018 yamaha sniper-150-222515787</p> <p>218091901/218091901</p> <p>Yamaha Sniper 1... R15 V2</p> <p>\$51,000</p> <p>Hi My Brother Hi Sate...</p> <p>Used</p> <p>(/yamaha-sniper-150-222515787/)</p> <p>2018 yamaha sniper-150-222515787</p> <p>218091901/218091901</p>

Constant Appraiser Services

Qualified Automobile Accident Damage Appraisers/Loss Adjusters
Blk 2 Rivervale Link, #09-02 Singapore 545040
Tel/Fax: 6886 1106 Mobile: 9007 5234
Email: constant_as@yahoo.com.sg
RCB No. 53138015K

INVOICE

To: Lim Ai Geok
c/o 2 Kaki Bukit Ave 2
#01-17 Kaki Bukit Autohub
Singapore 417921

Date : 19/10/2018

Invoice No : IV18-10043/CAS

Particulars	Amount
Fee For Services Rendered In Respect Of: Surveying, Adjusting, and Re-inspection Of Accident Damaged Vehicle FBL 7951Y (Inclusive Of Photographs And Transport Charges) Our reference : CAS/18-10/043	\$725.00
Total	\$725.00

E. & O.E

Constant Appraiser Services



Cheque Should Be Crossed And Made Payment To 'Constant Appraiser Services'

Constant Appraiser Services

Qualified Automobile Accident Damage Appraisers/Loss Adjusters
Blk 2 Rivervale Link, #09-02 Singapore 545040
Tel/Fax: 6886 1106 Mobile: 9007 5234
Email: constant_as@yahoo.com.sg
RCB No. 53138015K

Automobile Inspection Report

To: Lim Ai Geok
c/o 2 Kaki Bukit Ave 2
#01-17 Kaki Bukit Autohub
Singapore 417921

Date : 19/10/2018

Reference No : CAS/18-10/043

General Information

Registration No. : FBL 7951Y
Accident Date : 17/09/2018

Particulars of Damaged Vehicle

Colour	: Black	Make & Model	: Yamaha Xabre TFX150
Engine Capacity	: 150 cc	Pre-Accident Condition	: Good
Mileage (KM)	: -	Engine No.	: G3G8E0030352
Chassis No.	: MH3RG3710HK024327	Steering	: Affected
Registration Date	: 15/03/2017	Brake	: In Order

Tyre Condition

	Size	Make	Balance
Front Tyre	110/70R17	IRC	90%
Rear Tyre	130/70R17	IRC	80%

Inspection

Repairer : Moto 51 Pte Ltd
2 Kaki Bukit Ave 2, #01-17 Kaki Bukit Autohub, Singapore 417921

Adjustment And Recommendation Cost Of Repair

Repairer's Estimate : \$10,831.70
Revised Amount : \$7,700.00
Less Excess : -
Nett Total : \$7,700.00

Remarks

- (A) Survey was done on 20/09/2018
- (B) Re-survey was done on 01/10/2018
- (C) Re-survey after repair was done on 10/10/2018
- (D) The survey was conducted entirely on WITHOUT PREJUDICE basis.
- (E) We have NOT given any instruction to authorize the repair of the vehicle.

NOTE: The revised estimate was made from a visual inspection. Should there be any discrepancy or unseen damage/item in this survey, kindly notified the company within 7 (seven) days from the date hereof. Otherwise, the revised amount shall be deemed to be valid.

Constant Appraiser Services

Vehicle No : FBL 7951Y

Our ref : CAS/18-10/043

Adjustment On Repair Costs And Replacement Of Parts:

S/No	Qty	Descriptions	Assessed Condition	Estimate by Workshop (\$)	Revised Amount (\$)
<u>PARTS REPLACEMENT - LIST ITEMS</u>					
1	1pc	Brake pedal	Serviceable	65.00	-
2	1pc	Front brake caliper	Serviceable	221.00	-
3	1pc	Front brake disc	Bent/Warped	460.00	460.00
4	2pcs	Front footrest bracket R/L @ \$115.00	N/S Bent	230.00	115.00
5	2pcs	Front footrest R/L @ \$45.00	N/S Broken	90.00	45.00
6	2pcs	Front fork assy R/L @ \$680.00 490	Bent/Twisted	1,360.00	1,360.00
7	1pc	Front fork bottom bracket	Bent	280.00	280.00
8	1pc	Front fork top bracket	Bent	350.00	350.00
9	1pc	Front mudguard	Broken	118.00	118.00
10	1pc	Front no plate holder	Twisted	46.00	46.00
11	2pcs	Front side bottom cover R/L @ \$179.00 N/S	Grazed/Broken	358.00	358.00
12	2pcs	Front signal lamp R/L @ \$95.00 N/S	Grazed/Broken	190.00	190.00
13	1pc	Front wheel rim	Dented/Warped	680.00	680.00
14	1pc	Front wheel rim shaft	Bent	85.00	85.00
15	2pcs	Fuel tank side cover emblem R/L @ \$35.00	Necessary	70.00	70.00
16	2pcs	Fuel tank side cover R/L @ \$298.00 CH - 1/2	Grazed/Broken	596.00	596.00
17	1pc	Fuel tank top cover	Broken	145.00	145.00
18	1pc	Handle bar	Bent	128.00	128.00
19	1pc	Headlamp assy	Mounting Broken	185.00	185.00
20	1pc	Headlamp bracket	Bent	95.00	95.00
21	1pc	Headlamp cowling	Grazed	145.00	145.00
22	1pc	Meter assy	Damaged	465.00	465.00
23	1pc	Meter cover front	Grazed	88.00	88.00
24	1pc	Rear exhaust muffler	Repair	650.00	-
25	1pc	Rear exhaust muffler protector	Grazed	95.00	95.00
26	2pcs	Rear footrest bracket R/L @ \$115.00	N/S Bent	230.00	115.00
27	2pcs	Rear footrest R/L @ \$45.00	N/S Grazed	90.00	45.00
28	2pcs	Rear side board R/L @ \$179.00 N/S	Grazed/Broken	358.00	358.00
29	2pcs	Rear signal lamp R/L @ \$95.00	Grazed/Bent	190.00	190.00
Less 10%				8,063.00	6,807.00
				(806.30)	(680.70)
Sub total				7,256.70	6,126.30

Constant Appraiser Services

Vehicle No : FBL 7951Y

Our ref : CAS/18-10/043

S/No	Qty	Descriptions	Assessed Condition	Estimate by Workshop (\$)	Revised Amount (\$)
<u>PARTS REPLACEMENT - SPECIAL NETT ITEMS</u>					
1	1set	Body sticker set	Necessary	180.00	120180.00 ✓
2	1set	Brake & clutch lever set LH	Grazed	260.00	260.00 70 ✓
3	2pcs	Fork oil seal R/L @ \$35.00	Necessary	70.00	70.00 ✓
4	1pc	Front no plate	Grazed	20.00	20.00 ✓
5	1pc	Front tyre	Serviceable	280.00	-
6	1pc	Front wheel rim bearing	Necessary	65.00	65.00 ✓
7	1set	Handle bar balancer set LH	Grazed	80.00	80.00 40 ✓
8	1set	Handle bar grip set	Grazed/Torn	65.00	65.00 X N/A
9	1set	Mirror set	Grazed/Broken	280.00	280.00 X N/A
10	1pc	Rear box	Dented/Grazed	680.00	680.00 550 ✓
11	1pc	Rear box bracket	Bent/Twisted	160.00	160.00 X N/A
12	1pc	Rear no plate	Serviceable	30.00	-
13	1pc	Steering cone/bearing	Necessary	95.00	95.00 X N/A
<u>LABOUR & MISC. CHARGES</u>			Sub total	9,521.70	8,081.30 995 ✓
1		To remove, reinstall electrical wiring harness, check lighting. (to FR)		60.00	30.00 ✓
2		To re-spray painting on the change bodyparts, repair portion, and where consistent to the accident		400.00	300.00 200 ✓
13		To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident		500.00	400.00 300 ✓
4		To Straighten body frame to the original position		350.00	250.00 200 ✓
Grand total				10,831.70	9,061.30 780 ✓
Recommended cost of lump sum repair (To its pre-accident condition)					7,700.00

P- 3645.90

M- 995

L- 730

5370.90

L/S- 4296.72

= 4300 ✓

4 days

6181.4

20% 4980

5 Days

MV- 8500

PV- 5375

NV- 3125

Constant Appraiser Services

Vehicle No : FBL 7951Y

Our ref : CAS/18-10/043

Adjustment/Recommendations

We have thoroughly inspected each and every item on the estimate against the physical damage found on the vehicle and we have listed the breakdown of our finding and our recommendation.

The repairer has agreed to undertake the job at a lump sum of **\$7,700.00** on a contractual basis. Under normal circumstances, the repair period would be about **12 (Twelve)** working days.

Yours faithfully,

Constant Appraiser Services



Lim Yong Tian (Sebastian)
Licensed Appraiser
Adv. Dip. In Mechanical Engineering (AUS)
MSAAA

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	17 Sep 2018		27 Sep 2018 09:35 Edit Adj Rpt	S\$4,300.00 Edit Estimates	S\$4,300.00 View Rpt		Pending for Survey Report Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	KENNEDY KWOK JUN AN, ID: S9632237B, Tel: +6584484520, Email: NOEMAIL		
Main Claimant:	LIM AI GEOK, ID: S1406474E		
Vehicle Reg. No.:	FBL7951Y	Date of Loss:	17/09/2018 02:00 - :59 [18 Months and 2 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / MSC/V/18-001273	Policy/Cover Note No.:	MSD/VMS/18-382170 (TP, Fire & Theft) Coverage: 24/04/2018 - 23/04/2019
Vehicle Reg. No. (Insured):	FQ7655D	Policy No. (Claimant):	
		Excess:	
Repairer:	Ong Motor Trading (MACPHERSON RD) No. 464 Macpherson Road, 368182 Macpherson - Tel:		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Chhia Nyuk Pui - 6594 2521]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Final Rpt due 25/01/2019]		
Driver/Custodian (Insured):	KENNEDY KWOK JUN AN (22 / Male), NRIC: S9632237B, Tel: +6584484520 Email: NOEMAIL		
Adj Asg. Remarks:	SURVEY DISAGREE ON SJE - ASSIGN LKK. LIABILITY: 50%/50% CONTACT: JACKY SIAH 8380 2233		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

- MSIG_SG (23/01/2019): Report Send Back Alerts - FBL7951Y (TP)

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
----------	----------	------	------------	---------	---------	-------------	--------------	------------	-------

No results.

Claim Documents




***FBL7951Y (MSC/V/18-001273)**
[FQ7655D]
TP
LIM AI GEOK
Sep 17 2018 2:00AM
[KENNEDY KWOK JUN AN]
Ong Motor Trading

Upload Documents Upload Photos Compose New Letter

View View in Browser ▾

Assessment Reports


































1 per page ▾ ☒

No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	26/09/18 16:41	Accident Statement From:SC - Reg. No: FQ7655D, Claimant: KENNEDY KWOK JUN AN	 Load HTM	<input type="checkbox"/>
2	26/09/18 16:41	Addendum Sheet From:SC - Reg. No: FQ7655D, Claimant: KENNEDY KWOK JUN AN	 Load TIF	<input type="checkbox"/>
3	26/09/18 16:41	Accident Statement Addm. #1 From:SC - Reg. No: FQ7655D, Claimant: KENNEDY KWOK JUN AN	 Load HTM	<input type="checkbox"/>

Photos/Images

3 per page ▾ ☒

No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	03/10/18 11:57	General View	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
2	03/10/18 11:57	General View	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
3	03/10/18 11:57	General View	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
4	03/10/18 11:57	General View	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
5	03/10/18 11:57	General View	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
6	03/10/18 11:57	General View	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
7	03/10/18 11:57	General View	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
8	03/10/18 11:57	General View	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
9	03/10/18 11:57	General View	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
10	03/10/18 11:57	General View	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
11	03/10/18 11:57	General View	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
12	03/10/18 11:57	General View	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
13	03/10/18 11:57	General View	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
14	03/10/18 11:57	General View	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
15	03/10/18 11:57	General View	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
16	03/10/18 11:57	General View	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
17	03/10/18 11:57	General View	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
18	03/10/18 11:57	General View	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
19	03/10/18 11:57	General View	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
20	03/10/18 11:57	General View	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
21	03/10/18 11:57	General View	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
22	03/10/18 11:57	General View	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
23	03/10/18 11:57	General View	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
24	03/10/18 11:57	General View	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
25	03/10/18 11:57	General View	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
26	03/10/18 11:57	General View	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
27	03/10/18 11:57	General View	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
28	03/10/18 11:57	General View	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
29	03/10/18 11:57	General View	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>

Assessment Reports			1 per page ▾	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
30	03/10/18 11:57	General View	 Load JPG	<input checked="" type="checkbox"/>
31	03/10/18 11:57	General View	 Load JPG	<input checked="" type="checkbox"/>
32	03/10/18 11:57	General View	 Load JPG	<input checked="" type="checkbox"/>
33	03/10/18 11:57	General View	 Load JPG	<input checked="" type="checkbox"/>
34	03/10/18 11:57	General View	 Load JPG	<input checked="" type="checkbox"/>
35	03/10/18 11:57	General View	 Load JPG	<input checked="" type="checkbox"/>
36	03/10/18 11:57	General View	 Load JPG	<input checked="" type="checkbox"/>
37	03/10/18 11:57	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
38	03/10/18 11:57	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
39	03/10/18 11:57	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
40	03/10/18 11:57	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
41	03/10/18 11:57	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
42	03/10/18 11:57	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
43	03/10/18 11:57	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
44	03/10/18 11:57	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
45	03/10/18 11:57	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
46	03/10/18 11:57	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
47	03/10/18 11:57	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
48	03/10/18 11:57	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
49	03/10/18 11:57	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
50	03/10/18 11:57	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
51	03/10/18 11:57	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
52	03/10/18 11:57	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
53	03/10/18 11:57	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
54	03/10/18 11:57	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page ▾	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	26/09/18 16:41	FBL7951Y TP E-FILE REPORT From: SC - Reg. No: FQ7655D, Claimant: KENNEDY KWOK JUN AN	 Load PDF	
2	26/09/18 16:46	EMAIL FROM TP TO ARRANGE SURVEY	 Load PDF	
3	26/09/18 16:46	SURVEY DISAGREE ON SJE - ASSIGN LKK	 Load PDF	
4	03/12/18 16:23	LOD & SUPPORTING DOCUMENTS	 Load PDF	
5	03/12/18 16:23	SURVEY REPORT	 Load PDF	
6	03/12/18 16:25	SURVEY PHOTOS PART 1	 Load PDF	
7	03/12/18 16:25	SURVEY PHOTOS PART 2	 Load PDF	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	18/04/19 14:06	PRS INVOICE	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST		Reset	Save	Print
There are no document checklists configured.				
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)				
Show Remarks To: <input type="checkbox"/> Handling Insurer Note: Remarks are private unless you show it to other parties.				

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/MSG18017624/GTD3S2-1

Date: 18/04/2019

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd. Policy No: MSD/VMS/18-382170
 Claimant Vehicle No: FBL7951Y Insured Vehicle No: FQ7655D
 Date of Loss: 17/09/2018 Nature of Claim: TP Claim No: MSC/V/18-001273

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: FBL7951Y
 Make & Model: YAMAHA XABRE, 150cc TFX150 Engine No: G3G8E0030352
 Reg. Date: 15/03/2017 (Man. Year: 2017) Chassis No: MH3RG3710HK024327
 Colour: Black Odometer: 0 km
 Engine Capacity: 150 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Good Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 110/70-17 Rear Tyre Size: 130/70-17
 Front Left Side: IRC 5 mm Rear Left Side: IRC 5 mm
 Front Right Side: 0 mm Rear Right Side: 0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	9,521.70	4,625.90	4,895.80	51.42
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,310.00	730.00	580.00	44.27
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	10,831.70	5,355.90	5,475.80	50.55
Approved Total (Overridden) (S\$)		4,300.00		
Nett Amount (S\$)	10,831.70	4,300.00	6,531.70	60.30

INSPECTION

Date of Assignment: 27/09/2018
 Date Inspected: 28/09/2018 Inspected At: Ong Motor Trading (MACPHERSON RD)
 Singapore 368182
 Estimated Period of Repair: 5.0 days

Adjuster: XING GUO QIANG

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

MARKET VALUE: \$9,000.00

LTA: \$5,747.00

NETT VALUE: \$3,253.00

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 18 Apr 2019)	
Parts:	N/A	YAMAHA XABRE 150cc TFX150 (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for FBL7951Y)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BRAKE PEDAL	Serviceable	65.00 FL	*- FL
2	1		*FRONT BRAKE CALIPER	Serviceable	221.00 FL	*- FL
3	1		*FRONT BRAKE DISC	Bent / Warped	460.00 FL	*360.00 FL
4	1		*FRONT FOOTREST BRACKET R/L	N/s Bent	230.00 FL	*115.00 FL
5	1		*FRONT FOOTREST R/L	N/s Broken	90.00 FL	*45.00 FL
6	2		*FRONT FORK ASSY R/L	Bent / Twisted	1,360.00 FL	*980.00 FL
7	1		*FRONT FORK BOTTOM BRACKET	Bent	280.00 FL	*280.00 FL
8	1		*FRONT FORK TOP BRACKET	Not Necessary	350.00 FL	*- FL
9	1		*FRONT MUDGUARD	Broken	118.00 FL	*118.00 FL
10	1		*FRONT NO PLATE HOLDER	Twisted	46.00 FL	*46.00 FL
11	1		*FRONT SIDE BOTTOM COVER R/L	N/s Grazed / Broken	358.00 FL	*179.00 FL
12	1		*FRONT SIGNAL LAMP R/L	N/s Grazed / Broken	190.00 FL	*95.00 FL
13	1		*FRONT WHEEL RIM	Dented / Warped	680.00 FL	*365.00 FL
14	1		*FRONT WHEEL RIM SHAFT	Bent	85.00 FL	*85.00 FL
15	1		*FUEL TANK SIDE COVER EMBLEM R/L	N/s Necessary/O/s Not Necessary	70.00 FL	*35.00 FL
16	1		*FUEL TANK SIDE COVER R/L	N/s Cut / O/s Not Necessary	596.00 FL	*298.00 FL
17	1		*FUEL TANK TOP COVER	Not Necessary	145.00 FL	*- FL
18	1		*HANDLE BAR	Bent	128.00 FL	*128.00 FL
19	1		*HEADLAMP ASSY	Not Necessary	185.00 FL	*- FL
20	1		*HEADLAMP BRACKET	Not Necessary	95.00 FL	*- FL
21	1		*HEADLAMP COWLING	Grazed	145.00 FL	*145.00 FL
22	1		*METER ASSY	Damaged	465.00 FL	*465.00 FL
23	1		*METER COVER FRONT	Grazed	88.00 FL	*88.00 FL
24	1		*REAR EXHAUST MUFFLER	Repair	650.00 FL	*- FL
25	1		*REAR EXHAUST MUFFLER PROTECTOR	Grazed	95.00 FL	*95.00 FL
26	2		*REAR FOOTREST BRACKET R/L	Not Necessary	230.00 FL	*- FL
27	2		*REAR FOOTREST R/L	Not Necessary	90.00 FL	*- FL
28	1		*REAR SIDE BOARD R/L	N/s Grazed / Broken	358.00 FL	*179.00 FL
29	2		*REAR SIGNAL LAMP R/L	Not Necessary	190.00 FL	*- FL
30	1		*SET BODY STICKER	Necessary	180.00 FS	*120.00 FS
31	1		*BRAKE & CLUTCH LEVER LH	Grazed	260.00 FS	*70.00 FS
32	2		*FORK OIL SEAL R/L	Necessary	70.00 FS	*70.00 FS
33	1		*FRONT NO PLATE	Grazed	20.00 FS	*20.00 FS
34	1		*FRONT TYRE	Serviceable	280.00 FS	*- FS
35	1		*FRONT WHEEL WITH BEARING	Necessary	65.00 FS	*65.00 FS
36	1		*HANDLE BAR BALANCER LH	Grazed	80.00 FS	*40.00 FS
37	1		*SET HANDLE BAR GRIP	Not Necessary	65.00 FS	*- FS
38	1		*SET MIRROR	Not Necessary	280.00 FS	*- FS
39	1		*REAR BOX	Dented / Grazed	680.00 FS	*550.00 FS
40	1		*REAR BOX BRACKET	Not Necessary	160.00 FS	*- FS
41	1		*REAR NO PLATE	Serviceable	30.00 FS	*- FS
42	1		*STEERING CONE / BEARING	Not Necessary	95.00 FS	*- FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
F=Franchise part. S=SpcNett. L=ListItemDisc.						
Sub Total (\$\$)					10,328.00	5,036.00
- List Item Discount on L Items 10.00/10.00% (\$\$)					806.30	410.10
Total Parts (\$\$)					9,521.70	4,625.90

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE, REINSTALL ELECTRICAL WIRING HARNESS, CHECK LIGHTING. (TO FR)	New	60.00	30.00
2	TO RE-SPRAY PAINTING ON THE CHANGE BODYPARTS, REPAIR PORTION, AND WHERE CONSISTENT TO THE ACCIDENT.	New	400.00	200.00
3	TO PROVIDE LABOUR, WORKMANSHIP TO CHANGE THE ABOVE DAMAGED BODYPARTS, REPAIR, RE-CONSTRUCT AND RE-ALIGN BODY STRUCTURE, BODY ALIGNMENTS AND DAMAGED CONSISTENT TO THE ACCIDENT.	New	500.00	300.00
4	TO STRAIGHTEN BODY FRAME TO THE ORIGINAL POSITION.	New	350.00	200.00
Gross Labour Cost (S\$)			1,310.00	730.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >