

REF: NTUC

NS/PNC19001488/Jsd32

Hwee Jie

## ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

at Workshop m/s

of:

Insured:

GT 7102E

Policy No:

5098801850

010418 - 310319

Claims No:

MT/1028485-002

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / FR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lump Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

TIB1155M

Yr Regn: 21 Jun 2001

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Mercedes 04056

C.C. 11967.

Colour:

Multi Colour

A/C: Insured / Std / NI / NA

Sp. Reading

191265

T/Radio: Insured / Std / NI / NA

Eng/No:

-

C.No:

WER61232321098209

Gen. Cond: Good / Fair / Poor / BurntSteering: Order / Jammed / Leaked / Burnt orBrake: Order / Jammed / Leaked / Burnt orModi: Nil / SKM / STD A/Rim or

Tyre Size:

F: 275/70R22.5

R: -

(0)

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Firenze

Front

Rear

R/Bal.

7

mm

R/Bal.

7/7

mm

L/Bal.

7

mm

L/Bal.

7/7

mm

D.O.A.

17/1/19

D.O.I.

22/1/19

Survey held at

Surt

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision:

Date / Time

Action / Instruction

TIB 1155M - CC3/17614020805 / Kike3w2

GT 7102E - X

DPA: 05/11/2014

RECEIVED 31 JAN 2019

Date/Time. File Pass to?

☐

Preli. Report

1)

☐

Final Report

Date/Time. File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

) S + PG SI

) Photos

) Others

) :

TOTAL

Report Format :

Lump Sum / I.B.I. (\$) :

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech Invs (\$

☐

Weekend (\$

**TP Claims against NTUC Income: Follow-Through Survey**

Date: 31/01/2019

| S/No | Income Reference | Claimant (Owner / Taxi Company) | Claimant Vehicle No. | Income Vehicle No. | Date of Accident | Time of Accident | Estimate    | Tentative repair cost |
|------|------------------|---------------------------------|----------------------|--------------------|------------------|------------------|-------------|-----------------------|
| 1    | MT/1028485-002   | SMRT BUSED LTD                  | TIB 1155M            | GT 7102E           | 17/1/2019        | 15:55            | \$ 2,631.92 | \$ 1,700.00           |

eBaoTech

GeneralClaim

Hello, NAC\_PAYA\_UBT\_800601

[Change Language](#)[Change Password](#)[Log Out](#)[My Desktop](#)[Notice of Loss](#)

## Policy Query

Policy No.  Date of Accident   
Vehicle No. (For Motor)  Certificate Number

| Select                | Policy No. | Certificate Number | Policyholder Name                       | Policyholder NRIC | Product | Cover Type                   | Vehicle No. | Insured Object | Commence Date | Expiry Date |
|-----------------------|------------|--------------------|---|-------------------|---------|------------------------------|-------------|----------------|---------------|-------------|
| <input type="radio"/> | 5098801850 |                    | EAST ASIA<br>TRANSPORTATION<br>SERVICES | 29267600W         | GCV     | Third Party,<br>Fire & Theft | GT7102E     | GT7102E        | 01/04/2018    | 31/03/2019  |

## Shirley Hiew (LKK Auto)

---

**From:** Catherine Lee Sau Chan (Auto Svcs/Ext Biz Svcs/AR & SC/ARC (Buses)/AR(Buses))  
<catherineleesc@smrt.com.sg>  
**Sent:** Thursday, 31 January 2019 12:03 PM  
**To:** Shirley Hiew (LKK Auto); Hwee Jie (LKK Auto); SUR; Admin A  
**Cc:** Koo Yew Chung (Auto Svcs/Ext Biz Svcs/AR & SC); AutoSvs-ARC (Bus)  
**Subject:** RE: Finalisation - TIB1155M (BUS/01/19/7020) - NTUC

Hi Shirley,

Hwee Jie already finalised the case with me this morning.

Thank you

Best Regards  
Catherine Lee  
SMRT Automotive Services Pte Ltd  
(Accident Repair Centre)  
DID: 6866 2669 Fax: 6368 5592  
[catherineleesc@smrt.com.sg](mailto:catherineleesc@smrt.com.sg)



---

**From:** Shirley Hiew (LKK Auto) [mailto:ShirleyHiew@lkkauto.com]  
**Sent:** 31 January 2019 12:00  
**To:** Catherine Lee Sau Chan (Auto Svcs/Ext Biz Svcs/AR & SC/ARC (Buses)/AR(Buses))  
<catherineleesc@smrt.com.sg>; Hwee Jie (LKK Auto) <hweejie@lkkauto.com>; SUR <sur@lkkauto.com>; Admin A  
<admin-a@lkkauto.com>  
**Cc:** Koo Yew Chung (Auto Svcs/Ext Biz Svcs/AR & SC) <YewChung@smrt.com.sg>; AutoSvs-ARC (Bus) <AutoSvs-  
ARCBus@smrt.com.sg>  
**Subject:** RE: Finalisation - TIB1155M (BUS/01/19/7020) - NTUC

Dear Catherine,

Confirmed lump sum \$1,700, 3 days.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email: [Sur@lkkauto.com](mailto:Sur@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Catherine Lee Sau Chan (Auto Svcs/Ext Biz Svcs/AR & SC/ARC (Buses)/AR(Buses))  
[mailto:catherineleesc@smrt.com.sg]  
**Sent:** Tuesday, 29 January 2019 6:20 PM

**To:** [hweejie@lkkauto.com](mailto:hweejie@lkkauto.com); SUR <[sur@lkkauto.com](mailto:sur@lkkauto.com)>; Admin A <[admin-a@lkkauto.com](mailto:admin-a@lkkauto.com)>

**Cc:** Koo Yew Chung (Auto Svcs/Ext Biz Svcs/AR & SC) <[YewChung@smrt.com.sg](mailto:YewChung@smrt.com.sg)>; AutoSvs-ARC (Bus) <[AutoSvs-ARCBus@smrt.com.sg](mailto:AutoSvs-ARCBus@smrt.com.sg)>

**Subject:** Finalisation - TIB1155M (BUS/01/19/7020) - NTUC

Hi Hwee Jie,

Attached herewith our copy of the bus repair estimate for the case.

Our finalised amount is \$1.700/- @ 3 working days under lump sum repair. Attached after repair photos for your perusal.

Please confirm the COR by return email ASAP.

Thank you

Best Regards  
Catherine Lee  
SMRT Automotive Services Pte Ltd  
(Accident Repair Centre)  
DID: 6866 2669 Fax: 6368 5592  
[catherineleesc@smrt.com.sg](mailto:catherineleesc@smrt.com.sg)



Moving People, Enhancing Lives

**SINGAPORE ACCIDENT STATEMENT**

**IMPORTANT NOTICE**

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

**ACCIDENT STATEMENT**

|                            |  |
|----------------------------|--|
| Date Of Report             | 22/01/2019 11:15                             |
| Date Of Accident           | 17/01/2019 15:55                             |
| Exact Location Of Accident | WOODLANDS AVENUE 1 - BS: 46349 (AFT BLK 353) |
| Country/State of Loss      | SINGAPORE                                    |

**DETAILS OF OWN VEHICLE**

|                             |                |
|-----------------------------|----------------|
| Vehicle Registration Number | TIB1155M       |
| <b>Insured/Policyholder</b> |                |
| Name Of Registered Owner    | SMRT BUSES LTD |
| Co Reg No                   | 198202292D     |
| Email Address               | NOEMAIL        |
| Mobile Phone No             |                |
| Alternative Phone No        | OFFICE-NOPHONE |

**Vehicle Particulars**

|              |                  |
|--------------|------------------|
| Manufacturer | MERCEDES-BENZ    |
| Model        | 0405G-12.0 D (A) |

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY  
Vehicle Category BUS

**Insurance Company**

|                           |                                |
|---------------------------|--------------------------------|
| Name of Insurance Company | MS FIRST CAPITAL INSURANCE LTD |
| Type Of Coverage          | THIRD PARTY                    |
| Fleet Policy              | YES                            |
| Policy Number             | D-18090224MFBP                 |
| Cover Note Number         |                                |

**Driver**

|                      |  |
|----------------------|--|
| Name of Driver       | BUS CAPTAIN NAME WANG XIAOMING BUS CAPTAIN NAMEW |
| NRIC No              | G2006475M  |
| Date Of Birth        | 21/08/1981                                       |
| Occupation           | OUTDOOR  |
| Date Of Driving Pass | 16/04/2012                                       |
| Driving Experience   | 6 YEARS AND 9 MONTHS                             |
| Gender               | MALE   |
| Mobile Number        | (LOCAL) +65-80000000                             |
| Fax Number           |  |
| Contact Number       |  |
| Email Address        | NOEMAIL  |

|   |           |
|---|-----------|
| Address   | NOADDRESS |
| Postcode  |           |
| Was driver an employee of the Insured's Company     | YES       |
| If No, Relationship of the Driver with the Insured  |           |
| Vehicle Registration Number of Driver's Own Vehicle | -         |
|   | -         |
|   | -         |
| Insurance Company of Driver's Own Vehicle           | -         |
|   | -         |
|   | -         |

#### General Information of the Accident

|                    |            |
|--------------------|------------|
| Type Of Accident   | SIDE SWIPE |
| Weather Conditions | CLEAR      |
| Road Surface       | DRY        |

#### Other Information

|   |     |
|---|-----|
| Was any foreign vehicle involved in this accident?  | NO  |
| Number of vehicles (including own vehicle) involved in the accident                         | 2   |
| Was any body injured in the Accident?   | NO  |
| Was any injured conveyed to hospital by ambulance?  | NO  |
| Was any other material or property damaged?   | YES |
| I have been approached by unknown person(s) soliciting/offering accident claims assistance. | NO  |
| Number of Passengers (Including Driver)   | 10  |

#### Details of Police Action

|   |    |
|---|----|
| Was the accident reported to the police?  | NO |
| If Yes, Please state which Police Station |    |
| Was notice of intended Prosecution given? | NO |
| If Yes, against whom?                     |    |

#### Circumstances of Accident

While my bus was in stationary position at bus stop 46349 along Woodlands Avenue 1 conducting pas activity, suddenly i felt an impact on the rear of my bus. When i checked the mirror, i saw a van (GT7102E) stuck in between the right rear portion of my bus and another pte car (SLF2112Z) that was on the right lane. The van had collided onto the right rear portion of my bus. No injuries reported.

#### Attachment(s)

|   |  |
|---|--|
| Are accident photos available for attachment? | NOT AVAILABLE DUE TO CIRCUMSTANCES OF ACCIDENT |
| Was there any video captured by Car Camera?   | YES  |
| Remarks/ Reasons:                             | PENDING DOWNLOAD                               |
| Was there any audio recorded?                 | NO   |

#### DETAILS OF OTHER VEHICLE PROPERTY 1

|                             |  |
|-----------------------------|--|
| Vehicle Registration Number | GT7102                                 |
| Vehicle Make/Model/Colour   |  |
| Details Of Properties       |  |
| Vehicle Category            | BUS                                    |
| Name of Driver              |  |
| NRIC/Passport Number        |  |
| Contact Number              |  |
| Address                     |  |
| Postcode                    |  |
| Insurance Company Name      | NTUC INCOME INSURANCE CO-OPERATIVE LTD |
| Nature Of Damage            |  |

No. Of Passenger (Including Driver) \*



**SKETCH PLAN**

**IMPORTANT NOTICE**

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "**Personal Information**") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "**Insurers**"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "**Purposes**").
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims. \*
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature  
Date & Time:


王小明

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:



Reporting Centre Personnel's Signature  
Name: BALQISH  
NRIC/FIN No.: S8340325Z

© 2006 The Authors  
Journal compilation © 2006 Blackwell Publishing Ltd

[illegible]

TELETYPE



王小明

Reporting Centre Personnel's Signature  
Name: BALQISH  
NRIC/FIN No: S8340325Z

> [Back to OneMotoring](#)

## Enquire Transfer Fee

|  |  |                     |                           |
|--|--|---------------------|---------------------------|
| Vehicle Details  |  |                     |                           |
| Vehicle No. :  | TIB1155M                                 |                     |                           |
| Vehicle Type :   | H20 - Public Transport Bus/Coach/Minibus |                     |                           |
| Vehicle Attachment 1 :   | Air-Conditioned                          |                     |                           |
| Vehicle Scheme :   | OmniBus (SMRT Non ARF-exempted)          |                     |                           |
| Vehicle Make :   | MERCEDES BENZ                            |                     |                           |
| Vehicle Model :  | O4O5G AUTO                               |                     |                           |
| Chassis No. :  | WEB61232321098208                        |                     |                           |
| Propellant :   | Diesel                                   |                     |                           |
| Engine No. :   | 44797720081132                           |                     |                           |
| Engine Capacity :  | 11967 cc                                 |                     |                           |
| Maximum Power Output :   | -  |                     |                           |
| Maximum Laden Weight :   | 24000 kg                                 |                     |                           |
| Unladen Weight :   | 16060 kg                                 |                     |                           |
| Year Of Manufacture :  | 2000                                     |                     |                           |
| Original Registration Date :   | 21 Jun 2001                              |                     |                           |
| Lifespan Expiry Date :   | 20 Jun 2019                              |                     |                           |
| Road Tax Expiry Date :   | 20 Jun 2019                              |                     |                           |
| Inspection Due Date :  | 20 Dec 2019                              |                     |                           |
| Intended Transfer Date :   | 31 Jan 2019                              |                     |                           |
| CO2 Emission :   | -  |                     |                           |
| CO Emission :  | -  |                     |                           |
| HC Emission :  | -  |                     |                           |
| NOx Emission :   | -  |                     |                           |
| PM Emission :  | -  |                     |                           |
| Late renewal fee(s) will be imposed if road tax / lay up has expired. Please use Enquire Road Tax Payable for fee(s) payable.                        |  |                     |                           |
| Road tax, including Over Payment (if any), of a vehicle will follow the vehicle to the new registered owner when its ownership is being transferred. |  |                     |                           |
| Amount Payable   |  |                     |                           |
|  | Amount Before GST<br>(S\$)               | GST Amount<br>(S\$) | Amount After GST<br>(S\$) |
| Transfer Fee :   | 25.00                                    | -                   | 25.00                     |
| Total Amount Payable :   |  |                     | 25.00                     |

You may print this page for reference.

OK

Print



## SMRT Accident Vehicle Repair Estimates

|   |
|---|
| <b>SMRT Automotive Services Pte Ltd</b>           |
| 60 Woodlands Industrial Park E4, Singapore 757705 |
| FAX Number : 63685592                             |
| Estimator Telephone Number : 68662623             |
| Accident Reporting Number : 68662672              |



Date Generated : 22/01/2019

User ID : GohKK2

### Section A - Accident Details

|                                    |  |
|------------------------------------|--|
| Registration Number                | TIB1155M   |
| Case Reference Number              | BUS/01/19/7020   |
| Registration Date                  | 21/6/2001  |
| Company Type                       | SMRT Buses Ltd   |
| Make                               | MERCEDES   |
| Model                              | MERCEDES 0405G   |
| Name of Driver                     | Wang Xiaoming  |
| Type of Accident                   | Side Swipe   |
| Accident Date and Time             | 17/1/2019 3:55 PM  |
| Accident Reported Date and Time    | 17/1/2019 4:45 PM  |
| Is Surveyor Required?              | Yes  |
| Survey by                          |  |
| Vehicle is Towed Back?             | No   |
| Towed Back Date and Time           |  |
| Replacement Vehicle issued?        | No   |
| Job Card Number                    |  |
| Special Instruction to ARC, if any | TIB1155M - RIGHT REAR PORTION<br>GT7102E (TP) - LEFT PORTION |
| Prepared Date and Time             | 22/1/2019 10:54 AM   |
| Chassis Number                     | WEB61232321098208  |
| Mileage                            |  |
| Work Shop                          |  |
| Repair Completion Date and Time    |  |

### Section B - Summary of Repair Estimates

| Summary of Repair Estimates  |   |   |
|------------------------------|---|---|
|                              | Quotation from ARC  | Adjusted by Surveyor, if applicable   |
| Total Labour Cost            | \$1,590.00  | \$0.00  |
| Total Spray Cost             | \$616.00  | \$0.00  |
| Total Spare Part Cost        | \$425.92  | \$0.00  |
| Total Other Cost             | \$0.00  | \$0.00  |
| <b>TOTAL COST</b>            | <b>\$2,631.92</b>   | <b>\$0.00</b>   |
| Lump Sum Total               | \$2,650.00  | \$0.00  |
| Number of Repair Days        | 4.0   |   |
| Prepared / Adjusted By       | Kok Khoo Goh  |   |
| ARC / Surveyor Sign Off Date | 22/01/2019 10:59 AM   |   |
| Signature                    |  |  |
| Remarks                      |   |   |

### Section C - Quotation and Accident Invoice Details

|                  |  |                |  |
|------------------|--|----------------|--|
| Quotation Number |  | Invoice Number |  |
| Quotation Date   |  | Invoice Date   |  |
| Invoice Amount   |  | Prepared Date  |  |



## SMRT Accident Vehicle Repair Estimates

Shirley

|   |
|---|
| SMRT Automotive Services Pte Ltd                  |
| 60 Woodlands Industrial Park E4, Singapore 757705 |
| FAX Number : 63685592                             |
| Estimator Telephone Number : 68662623             |
| Accident Reporting Number : 68662672              |

Date Generated : 29/01/2019



User ID : CatherineLee

### Section A - Accident Details

|                                    |  |
|------------------------------------|--|
| Registration Number                | TIB1155M   |
| Case Reference Number              | BUS/01/19/7020   |
| Registration Date                  | 21/6/2001  |
| Company Type                       | SMRT Buses Ltd   |
| Make                               | MERCEDES   |
| Model                              | MERCEDES 0405G   |
| Name of Driver                     | Wang Xiaoming  |
| Type of Accident                   | Side Swipe   |
| Accident Date and Time             | 17/1/2019 3:55 PM  |
| Accident Reported Date and Time    | 17/1/2019 4:45 PM  |
| Is Surveyor Required?              | Yes  |
| Survey by                          |  |
| Vehicle is Towed Back?             | No   |
| Towed Back Date and Time           |  |
| Replacement Vehicle issued?        | No   |
| Job Card Number                    | 24069828   |
| Special Instruction to ARC, if any | TIB1155M - RIGHT REAR PORTION<br>GT7102E (TP) - LEFT PORTION |
| Prepared Date and Time             | 22/1/2019 10:54 AM   |
| Chassis Number                     | WEE6123232108208   |
| Mileage                            |  |
| Work Shop                          |  |
| Repair Completion Date and Time    |  |

Finalized - Hwee Jie

### Section B - Summary of Repair Estimates

| Summary of Repair Estimates  |   |   |
|------------------------------|---|---|
|                              | Quotation from ARC  | Adjusted by Surveyor, if applicable   |
| Total Labour Cost            | \$1,590.00  | \$1,060.00  |
| Total Spray Cost             | \$616.00  | \$528.00  |
| Total Spare Part Cost        | \$425.92  | \$425.92  |
| Total Other Cost             | \$0.00  | (\$317.60)  |
| TOTAL COST                   | \$2,631.92  | \$1,696.32  |
| Lump Sum Total               | \$2,650.00  | \$1,700.00  |
| Number of Repair Days        | 4.0   | 3.0   |
| Prepared / Adjusted By       | Kok Khoo Goh  | Hwee Jie  |
| ARC / Surveyor Sign Off Date | 22/01/2019 10:59 AM   | 22/01/2019 4:49 PM  |
| Signature                    |  |  |
| Remarks                      |   |   |

### Section C - Quotation and Accident Invoice Details

|                  |  |                |  |
|------------------|--|----------------|--|
| Quotation Number |  | Invoice Number |  |
| Quotation Date   |  | Invoice Date   |  |
| Invoice Amount   |  | Prepared Date  |  |



# SMRT Accident Vehicle Repair Estimates

|   |
|---|
| SMRT Automotive Services Pte Ltd                  |
| 60 Woodlands Industrial Park E4, Singapore 757705 |
| FAX Number : 63685592                             |
| Estimator Telephone Number : 68662623             |
| Accident Reporting Number : 68662672              |

Date Generated : 29/01/2019

User ID : CatherineLee

## Section D - Details of Repair Estimates

### Part 1 - Labour Works

| Job Scope  | Quotation from AR | Adjusted by Surveyor, if applicable |
|--|-------------------|-------------------------------------|
| TO REMOVE & INSTALL ALL ABOVE ITEMS : REPAIR REAR ENGINE DOOR PANEL : REAR ENGINE DOOR STRUC | \$1,590.00        | \$1,060.00                          |
| Total Labour   | \$1,590.00        | \$1,060.00                          |

### Part 2 - Spray Painting & Panel Beating Related Works

| Job Scope   | Quotation from ARC | Adjusted by Surveyor, if applicable |
|---|--------------------|-------------------------------------|
| PROVIDE LABOUR AND MATERIAL TO PUTTY AND RESPRAY ABOVE REPAIR ITEMS | \$616.00           | \$528.00                            |
| Total Spray Painting & Panel Beating                                | \$616.00           | \$528.00                            |

### Part 3 - Other Costs - Accident and Accident Repair Related Expense

| Job Scope                       | Quotation from ARC | Adjusted by Surveyor, if applicable |
|---------------------------------|--------------------|-------------------------------------|
| Lump Sum Adjustment by Surveyor | \$0.00             | (\$317.60)                          |
| Total Other Costs               | \$0.00             | (\$317.60)                          |

### Part 4 - Spare Parts / Material Usage

| Part Number | Portion | Stock Number | Part Name                             | Quantity | List Price (\$) | Discount (%) | Final Price (\$) | Estimator Approved | Surveyor Approved |
|-------------|---------|--------------|---------------------------------------|----------|-----------------|--------------|------------------|--------------------|-------------------|
| 6008174     | BODY RH | 4009851012   | BUMPER REAR RH FOR MB C405G HABIT BUS | 1.00     | \$591.56        | 10.00        | \$532.40         | Replace            | Replace           |
| Total       |         |              |                                       |          | \$591.56        |              | \$532.40         |                    |                   |

### Added Spare Parts / Material Usage After Surveyor Signed off

| Part Number | Portion | Stock Number | Part Name | Quantity | List Price \$ | Discount (%) | Final Price (\$) | ARC Check | Surveyor Check |
|-------------|---------|--------------|-----------|----------|---------------|--------------|------------------|-----------|----------------|
| Total       |         |              |           |          |               |              |                  |           |                |

2797.56

\$1060  
+ \$ 528  
\$ 532.4

\$2120.4  
- 20%

\$1696.32

L/s Total - \$1700/3days



## National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



NTUC INCOME INSURANCE CO-OPERATIVE LTD Ref: NS/INC19001488/Jsd3s2

73 BRAS BASAH ROAD

#05-01 NTUC TRADE UNION HOUSESINGAPORE Date: 31-01-2019

189556



Code: INC4

### 1. Policy Particulars :- THIRD PARTY CLAIM

|              |                |                |            |
|--------------|----------------|----------------|------------|
| Insured Veh. | GT 7102E       | Veh. Inspected | TIB 1155M  |
| Policy No.   | 5098801850     | Coverage (\$)  | 0.00       |
| Claim No.    | MT/1028485-002 | Excess (\$)    | 0.00       |
| Assign From  |                | Assign Date    | 22/01/2019 |

### 2. Vehicle Particulars & Condition

|              |                     |              |              |
|--------------|---------------------|--------------|--------------|
| Make & Model | MERCEDES BENZ O4O5G | c.c          | 11967        |
| Engine No.   | HIDDEN              | Year of Reg. | 2001         |
| Chassis No.  | WEB61232321098208   | Colour       | MULTI COLOUR |
| Odometer     | 191265              | Steering     | IN ORDER     |
| Brakes       | IN ORDER            | Modification | SPORTS RIM   |
| General      | GOOD                |              |              |

### 3. Conditions of Tyres

|                | Size             | Make    | Balance |
|----------------|------------------|---------|---------|
| R/H Front Tyre | 275/70 R22.5     | FIRENZA | 7 mm    |
| L/H Front Tyre | 275/70 R22.5     | FIRENZA | 7 mm    |
| R/H Rear Tyre  | 275/70 R22.5 (D) | FIRENZA | 7/7 mm  |
| L/H Rear Tyre  | 275/70 R22.5 (D) | FIRENZA | 7/7 mm  |

### 4. Description of Damages

|  |
|--|
| THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.<br>DAMAGES SEE DETAILS. |
|--|

### 5. General Information

|                |  |                 |            |
|----------------|--|-----------------|------------|
| Accident Date  | 17/01/2019   | Inspection Date | 22/01/2019 |
| Survey held at | SMRT AUTOMOTIVE SERVICES PTE LTD<br>60 WOODLANDS INDUSTRIAL PARK E4 SINGAPORE 757705 |                 |            |

### 5a. Remarks

|  |
|--|
| A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.<br>B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. |
|--|

### 5b. Estimate Days of Repair

|                                     |                |
|-------------------------------------|----------------|
| ESTIMATED NORMAL PERIOD FOR REPAIR: | 3 Working Days |
|-------------------------------------|----------------|



# National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:1 of 1

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. TIB 1155M

| Qty   | Description of Parts  | Condition | Estimate By Workshop (\$) | Our Adjusted (\$) |
|---|---|-----------|---------------------------|-------------------|
| 1   | <b>REPLACEMENT OF PARTS</b>   | DEFORMED  |                           |                   |
|   | BUMPER: REAR RH, FOR MB O405G HABIT BUS   |           | 591.56                    | 591.56            |
|   | LESS 10% DISCOUNT   |           | -                         | -59.16            |
|   |   |           | 591.56                    | 532.40            |
|   | <b>LABOUR</b>   |           |                           |                   |
|   | TO REMOVE & INSTALL ALL ABOVE ITEMS: REPAIR REAR ENGINE DOOR PANEL, REPAIR ENGINE DOOR STRUC. |           | 1,590.00                  | 1,060.00          |
|   | PROVIDE LABOUR AND MATERIAL TO PUTTY AND RESPRAY ABOVE REPAIR ITEMS.                          |           | 616.00                    | 528.00            |
|   |   |           | 2,206.00                  | 1,588.00          |
| <b>GRAND TOTAL</b>  |   |           | <b>2,797.56</b>           | <b>2,120.40</b>   |
| <b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)</b> |   |           |                           | <b>1,700.00</b>   |

Report Ref No. NS/INC19001488/Jsd3s2

ONG HWEE JIE

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons), B.Bus, MBA, PEng, PE,  
MInstAEA, MASME, MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.