

Hwee Jie

REF: NTUC NS/INC19001459 / Jgd352

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To inspect Vehicle No: _____
 at Workshop m/s _____
 of _____
 Insured: **688 7829X**
 Policy No: **5093484993 -01 05082018**
 Claims No: **M1/1028475-002**
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

Veh No: **SG5752T** Yr Regn: **27 Apr 2016**
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or _____
 Make: **Man A95** C.C. **10518**
 Colour: **Multi colour** A/C Insured / Std / NI / NA
 Sp Reading: **199171** T/Radio: Insured / Std / NI / NA
 Eng/No: **-**
 C/No: **WMAA952Z667003188**
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: In order / Jammed / Leaked / Burnt or
 Brake: In order / Jammed / Leaked / Burnt or
 Modi: Nil / STD A/Rim or
 Tyre Size: F: **275/70 R22.5**
 R: **-**

(Policy Condition)
 Remark: The veh had commenced its repair at the time of inspection.

<input checked="" type="radio"/>	
N/S	O/S

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or **Continental**

Bal. or Market Value: _____
 IDAC Accident Rpt: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: **3** days Res.: Yes or No
 Lum Sum: _____ % 3 Val.: Yes or No

Front		Rear	
R/Bal.	7 mm	R/Bal.	7/7 mm
L/Bal.	7 mm	L/Bal.	7/7 mm
D.O.A.	18/1/19	D.O.I.	22/1/19

CA / REV / REP: / 24 HRS
 Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Survey held at **Smart**
 Des. of Damages: Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	Hwee Jie finalised final fig @ 6189.75, 3 days. (Red to 1405.75, 12%)
	RECEIVED 20 FEB 2019

Date/Time, File Pass to? : Preli. Report
 : Final Report

Days Of Repair: **3**
 Resurvey No. of Trip: **1**

Date/Time, File Return to?
3)

Add Fee: Site Insp (\$)
 Interview (\$)
 Tech. Invs (\$)
 Weekend (\$)

Report Format: **TP**
 Lump Sum / I.B.I: (\$) **6189.75**

Survey Fee:	
Transportation:	
1) S-PS	
2) Photos	
3) Other	
TOTAL	

TP Claims against NTUC Income: Follow-Through Survey

Date 19/2/2019

S/No	Income Reference	Claimant (Owner / Taxi Company)	Claimant Vehicle No.	Income Vehicle No.
1	MT/1031465-002	COMFORT TRANSPORTATION PTE LTD	SHA 7323Y	SJS 3321K
2	MT/1018247-002	SMRT BUSES LTD	SMB 5073S	SJN 7756P
3	MT/1031666-002	COMFORT TRANSPORTATION PTE LTD	SHD 7299T	SGN 3392S
4	MT/1028475-002	SMRT BUSES LTD	SG 5752T	GBB 7829X
5	MT/1026811-002	SMRT TAXIS PTE LTD	SHB 452Z	SCL 4054U
6	MT/1030640-002	COMFORT TRANSPORTATION PTE LTD	SHA 7852L	SJM 3601J
7	MT/1031254-002	COMFORT TRANSPORTATION PTE LTD	SH 7181Y	SGW 2882D
8	MT/1031376-002	CITYCAB PTE LTD	SHC 7931G	SBU 8888T

eBaoTech

GeneralClaim

Hello, NAC_PAYA_UBI_800601

Change Language Change Password Log Out

My Desktop
Notice of Loss

Policy Query

Policy No.

Vehicle No. (For Motor)

Date of Accident

Certificate Number

Search

Select	Policy No.	Certificate Number	Policyholder Name	Policyholder NRIC	Product	Cover Type	Vehicle No.	Insured Object	Commence Date	Expiry Date
<input checked="" type="radio"/>	5093484993-01		CHARTWORTH ENTERPRISE SINGAPORE PTE LTD	198302426K	GFT	Preferred Workshop Plan	GBB7829X	GBB7829X	05/08/2018	

Continue

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	21/01/2019 16:41
Date Of Accident	18/01/2019 11:00
Exact Location Of Accident	ALONG SLIP ROAD TPE (PIE) TWDS TAMPINES AVE 12
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SG5752T
Insured/Policyholder	
Name Of Registered Owner	SMRT BUSES LTD
Co Reg No	198202292D
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-NOPHONE

Vehicle Particulars

Manufacturer	MAN
Model	A95-10.5 D (A)

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY

Vehicle Category BUS

Insurance Company

Name of Insurance Company	MS FIRST CAPITAL INSURANCE LTD
Type Of Coverage	THIRD PARTY
Fleet Policy	YES
Policy Number	D-18090224MFBP
Cover Note Number	

Driver

Name of Driver	BUS CAPTAIN NAME KANTHA SWAMY S/O PALANIAPPAN BU
NRIC No	S7803798I
Date Of Birth	17/02/1978
Occupation	OUTDOOR
Date Of Driving Pass	18/07/2006
Driving Experience	12 YEARS AND 6 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-80000000
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address NOADDRESS

Postcode

Was driver an employee of the Insured's Company YES

If No, Relationship of the Driver with the Insured

Vehicle Registration Number of Driver's Own Vehicle -

Insurance Company of Driver's Own Vehicle -

General Information of the Accident

Type Of Accident SIDE SWIPE

Weather Conditions CLEAR

Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO

Number of vehicles (including own vehicle) involved in the accident 2

Was any body injured in the Accident? NO

Was any injured conveyed to hospital by ambulance? NO

Was any other material or property damaged? YES

I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO

Number of Passengers (Including Driver) 10

Details of Police Action

Was the accident reported to the police? NO

If Yes, Please state which Police Station

Was notice of intended Prosecution given? NO

If Yes, against whom?

Circumstances of Accident

While travelling along the slip road of TPE (PIE) towards Tampines Ave 12, a lorry that was from the leftmost lanes of the highway skidded and swirled uncontrollably towards my direction, then it's right rear portion collided onto the left front portion of my bus. When I saw the lorry skidded, I managed to brake gently on time before the lorry collided onto my bus. There were no injuries reported.

Attachment(s)

Are accident photos available for attachment? NOT AVAILABLE DUE TO CIRCUMSTANCES OF ACCIDENT

Was there any video captured by Car Camera? YES

Remarks/ Reasons: PENDING DOWNLOAD

Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number GBB7829X

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category COMMERCIAL VEHICLE

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name NTUC INCOME INSURANCE CO-OPERATIVE LTD

Nature Of Damage

No. Of Passenger (Including Driver) *

SKETCH PLAN

IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation**.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims;
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time

Driver's Signature
(If driver is not the policyholder)
Date & Time



Reporting Centre Personnel's Signature
Name: BALQISH
NRIC/FIN No.: S8340325Z

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	2292D
Vehicle Details	
Vehicle No.:	SG5752T
Vehicle to be Exported:	No
Intended Deregistration Date:	20 Feb 2019
Vehicle Make:	MAN
Vehicle Model:	A95
Primary Colour:	Multi-Colour
Manufacturing Year:	2015
Engine No.:	50343152214320
Chassis No.:	WMAA95ZZ6G7003188
Maximum Power Output:	-
Open Market Value:	\$596,095.00
Original Registration Date:	27 Apr 2016
First Registration Date:	27 Apr 2016
Transfer Count:	1
Actual ARF Paid:	\$0.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Rebate Amount:	\$0.00
Total Rebate Amount:	\$0.00

The information contained herein is correct as at 20 Feb 2019

OK



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 22/01/2019

User ID : GohKK2

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REMOVE & INSTALL ALL REPLACE ITEMS - REPAIR FRONT PORTION	\$4,600.00 1325	
Total Labour	\$1,590.00	

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
PROVIDE LABOUR AND MATERIAL TO PUTTY AND RESPRAY ABOVE REPAIR ITEMS	\$616.00 528	
Total Spray Painting & Panel Beating	\$616.00	

Part 3 - Other Costs - Accident and Accident Repair Related Expense

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Other Costs		

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
4008315	INTERIOR	G20.05.01.03	SCREEN LOWER (A95)	1.00	\$4,107.50	0.00	\$4,107.50	Replace /	CRA 3696-23
			ACTIVATOR	1.00	\$80.00	0.00	\$80.00	Replace /	NEC
4008314			SEALANT SIKAFLEX	10.00	\$37.00	370	\$370.00	Replace /	NEC
4008313			PRIMER	1.00	\$80.00	0.00	\$80.00	Replace /	NEC
			IU BRACKET	1.00	\$35.00	0.00	\$35.00	Replace /	NEC
			STICKER SMRT	1.00	\$35.00	75	\$35.00	Replace /	NEC
			N/S HEADLAMP COVER	1.00	\$975.00	10.00	\$877.50	Replace /	CRA X 24
Total					\$5,349.50		\$5,585.00		

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
Total									

7929.50

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Hwee Jie - LKK
22/1/19
P/P 3days
as -
Photo before paint.

[Signature]
23/1/19






SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd	
60 Woodlands Industrial Park E4, Singapore 757705	
FAX Number : 63685592	
Estimator Telephone Number : 68662523	
Accident Reporting Number : 68662572	

Date Generated : 14/02/2019

User ID : CatherineLee

Section A - Accident Details	
Registration Number	SG5752T
Case Reference Number	BUS/D1/19/1051
Registration Date	17/8/2016
Company Type	SMRT Buses Ltd
Make	MAN
Model	A95
Name of Driver	Kantha Swamy S/O Palaniappan
Type of Accident	Side Swipe
Accident Date and Time	18/1/2019 11:00 AM
Accident Reported Date and Time	18/1/2019 1:45 PM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	24099923
Special Instruction to ARC, if any	SG5752T - LEFT FRONT PORTION GBB7829X (TP) - RIGHT CENTRE PORTION. INSURED WITH NTUC
Prepared Date and Time	22/1/2019 10:15 AM
Chassis Number	WMAA95Z26G7003188
Mileage	
Work Shop	
Repair Completion Date and Time	



Section B - Summary of Repair Estimates		
Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$1,590.00	\$1,325.00
Total Spray Cost	\$616.00	\$528.00
Total Spare Part Cost	\$4,336.75	\$4,336.75
Total Other Cost	\$0.00	\$0.00
TOTAL COST	\$6,542.75	\$6,189.75
Lump Sum Total	\$0.00	\$0.00
Number of Repair Days	4.0	3.0
Prepared / Adjusted By	Kok Khoon Goh	HWEE JIE
ARC / Surveyor Sign Off Date		23/01/2019 2:33 PM
Signature		
Remarks		

Section C - Quotation and Accident Invoice Details			
Quotation Number		Invoice Number	
Quotation Date		Invoice Date	
Invoice Amount		Prepared Date	



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 14/02/2019

User ID : CatherineLee

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REMOVE & INSTALL ALL REPLACE ITEMS ; REPAIR FRONT PORTION	\$1,590.00	\$1,325.00
Total Labour	\$1,590.00	\$1,325.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
PROVIDE LABOUR AND MATERIAL TO PUTTY AND RESPRAY ABOVE REPAIR ITEMS	\$616.00	\$528.00
Total Spray Painting & Panel Beating	\$616.00	\$528.00

Part 3 - Other Costs - Accident and Accident Repair Related Expense

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Other Costs		

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
4006314			SEALANT SIKAFLEX	10.00	\$37.00	0.00	\$370.00	Replace	Replace
			STICKER SMRT	1.00	\$75.00	0.00	\$75.00	Replace	Replace
			N/S HEADLAMP COVER	1.00	\$975.00	100.00	\$0.00	Repair	Repair
4006313			PRIMER	1.00	\$80.00	0.00	\$80.00	Replace	Replace
4006315			ACTIVATOR	1.00	\$80.00	0.00	\$80.00	Replace	Replace
			IU BRACKET	1.00	\$35.00	0.00	\$35.00	Replace	Replace
	INTERIOR	G20.05.01.03	SCREEN LOWER (A95)	1.00	\$4,107.50	10.00	\$3,696.75	Replace	Replace
Total					\$5,389.50		\$4,336.75		

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
Total									

\$ 1325
 + \$ 528
 \$ 4336.75

 Total - \$ 6189.75



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



NTUC INCOME INSURANCE CO-OPERATIVE LTD Ref: NS/INC19001489/Jqd3s2	
73 BRAS BASAH ROAD #05-01 NTUC TRADE UNION HOUSESINGAPORE 189556	Date: 20-02-2019
	Code: INC4



1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	GBB 7829X	Veh. Inspected	SG 5752T
Policy No.	5093484993-01	Coverage (\$)	0.00
Claim No.	MT/1028475-002	Excess (\$)	0.00
Assign From		Assign Date	22/01/2019

2. Vehicle Particulars & Condition

Make & Model	MAN A95	c.c	10518
Engine No.	HIDDEN	Year of Reg.	2016
Chassis No.	WMAA95ZZ6G7003188	Colour	MULTI COLOUR
Odometer	199171	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	275/70 R22.5	CONTINENTAL	7 mm
L/H Front Tyre	275/70 R22.5	CONTINENTAL	7 mm
R/H Rear Tyre	275/70 R22.5 (D)	CONTINENTAL	7/7 mm
L/H Rear Tyre	275/70 R22.5 (D)	CONTINENTAL	7/7 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION. DAMAGES SEE DETAILS.

5. General Information

Accident Date	18/01/2019	Inspection Date	22/01/2019
Survey held at	SMRT AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4 SINGAPORE 757705		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	3 Working Days
-------------------------------------	----------------



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SG 5752T

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	N/S HEADLAMP COVER	SERVICEABLE	975.00	-
			975.00	-
SPECIAL NETT ITEMS				
1	SCREEN LOWER (A95) (SN)	CRACKED	4,107.50	3,696.75
1	ACTIVATOR (SN)	NECESSARY	80.00	80.00
10	SEALANT SIKAFLEX @ \$37.00 (SN)	NECESSARY	370.00	370.00
1	PRIMER (SN)	NECESSARY	80.00	80.00
1	IU BRACKET (SN)	NECESSARY	35.00	35.00
1	STICKER SMRT (SN)	NECESSARY	75.00	75.00
			4,747.50	4,336.75
LABOUR				
	TO REMOVE & INSTALL ALL REPLACE ITEMS; REPAIR FRONT PORTION.		1,590.00	1,325.00
	PROVIDE LABOUR AND MATERIAL TO PUTTY AND RESPRAY ABOVE REPAIR ITEMS.		616.00	528.00
			2,206.00	1,853.00
GRAND TOTAL			7,928.50	6,189.75
RECOMMENDED COST OF REPAIRS (CONFIRMED)				6,189.75

Report Ref No. NS/INC19001489/Jqd3s2

ONG HWEE JIE
Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons), B.Bus, MBA, PEng, PE,
MInstAEA, MASME, MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.