






SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 22/01/2019

User ID : GohKK2

Section A - Accident Details	
Registration Number	SG5752T
Case Reference Number	BUS/01/19/1051
Registration Date	17/8/2016
Company Type	SMRT Buses Ltd
Make	MAN
Model	A95
Name of Driver	Kantha Swamy S/O Palaniappan
Type of Accident	Side Swipe
Accident Date and Time	18/1/2019 11:00 AM
Accident Reported Date and Time	18/1/2019 1:45 PM
Is Surveyor Required?	No
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	
Special Instruction to ARC, if any	SG5752T - LEFT FRONT PORTION GBB7829X (TP) - RIGHT CENTRE PORTION. INSURED WITH NTUC
Prepared Date and Time	22/1/2019 10:15 AM
Chassis Number	WMAA95ZZ6G7003188
Mileage	
Work Shop	
Repair Completion Date and Time	



Section B - Summary of Repair Estimates		
Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$1,590.00	\$0.00
Total Spray Cost	\$616.00	\$0.00
Total Spare Part Cost	\$5,585.00	\$0.00
Total Other Cost	\$0.00	\$0.00
TOTAL COST	\$7,791.00	\$0.00
Lump Sum Total	\$0.00	\$0.00
Number of Repair Days	4.0	
Prepared / Adjusted By	Kok Khoon Goh	
ARC / Surveyor Sign Off Date		
Signature		*
Remarks		

Section C - Quotation and Accident Invoice Details			
Quotation Number		Invoice Number	
Quotation Date		Invoice Date	
Invoice Amount		Prepared Date	



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 22/01/2019

User ID : GohKK2

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REMOVE & INSTALL ALL REPLACE ITEMS ; REPAIR FRONT PORTION	\$1,590.00 1325	
Total Labour	\$1,590.00	

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
PROVIDE LABOUR AND MATERIAL TO PUTTY AND RESPRAY ABOVE REPAIR ITEMS	\$616.00 528 /	
Total Spray Painting & Panel Beating	\$616.00	

Part 3 - Other Costs - Accident and Accident Repair Related Expense

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Other Costs		

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
	INTERIOR	G20.05.01.03	SCREEN LOWER (A95)	1.00	\$4,107.50	0.00	\$4,107.50	Replace /	CRA
4006315			ACTIVATOR	1.00	\$80.00	0.00	\$80.00	Replace /	NEC
4006314			SEALANT SIKAFLEX	10.00	\$37.00	0.00	\$370.00	Replace /	NEC
4006313			PRIMER	1.00	\$80.00	0.00	\$80.00	Replace /	NEC
			IU BRACKET	1.00	\$35.00	0.00	\$35.00	Replace /	NEC
			STICKER SMRT	1.00	\$35.00	0.00	\$35.00	Replace /	NEC
			N/S HEADLAMP COVER	1.00	\$975.00	10.00	\$877.50	Replace /	NEC
Total					\$5,349.50		\$5,585.00		CRA X

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
Total									

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

[Signature]
23/1/19
Hwee Jie - LKK
22/1/19
P/P 3days
as -
Photo before paint.