

ASS. REC. BY:

REF: CS/CTI19001516/Jsd307 Special Instruction:

Survey of
Mainmen

the file
Irene Tay

ASSIGNMENT (Office)

From (Person): of CTF Date/Time: 23/1/19 @ 2:48pm

Estimated Cost: Bill to:

OD TP/WS/TP RES / OD RES / EVA / INV / MV ? CS

To Inspect Vehicle No: SLG 1095R Insured: YL3090K

at Workshop m/s World Auto Tel: 63621776

of No. 1Kranji loop

Policy No: DMCVSN30003819044 Claim No: YL3090K

Sum Insured: Excess:

Make of Veh:
(Client's Record)

D.O.A. 18/1/19

CA / REV / REP. / REV 24 HRS lup

21/1/19

H.O.D. Endorsement:

Date/Time: 2:59pm @ 23/1/19 Person Contacted: Anee

Vehicle IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	SLG 1095R-X
	YL3090K-X

Hwee Jia

REF: CTF

ASSIGNMENT

From: _____ Date: **24/1/2019**

Estimated Cost: _____

OD WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: **SLG1095R**

at Workshop m/s: **World Auto**

of: **No. 1 Krnji loop**

Insured: _____

Policy No: _____

Claims No: _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: **The veh had commenced its repair at the time of inspection.**

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS **up**

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: **SLG 1095R** Yr Regn: **21 Sep 2016**

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: **Honda Vezel** c.c. **1496**

Colour: **Black** A/C: **Insured / Std / NI / NA**

Sp. Reading: **159615** T/Radio: **Insured / Std / NI / NA**

Eng/No: _____

C/No: **RU31208141**

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: **Nil** / S/Rim / STD A/Rim or

Tyre Size: F: **215/60 R16**

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or **Giti**

Front		Rear	
R/Bal. 6	mm	R/Bal. 6	mm
L/Bal. 6	mm	L/Bal. 6	mm
D.O.A. 18/1/19		D.O.I. 24/1/19	

Survey held at **World Auto**

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

<input checked="" type="checkbox"/>	N/S	O/S

Date / Time	Action / Instruction
	MV - \$69,000
	PV - \$41,720
	NV - \$27,280

7/3/19 Confirmed PIP \$1705/- with 3 days of repair.
(\$2,377.40 Red - 58%)

RECEIVED 07 MAR 2019

Date/Time, File Pass to? : Preli. Report

1) **07/03/19 Typist** : Final Report

Date/Time, File Return to?

Days Of Repair: **3**

Resurvey No. of Trip: **1**

Survey Fee:	220
Transportation	
S + RS SI	
Photos	
Others	
TOTAL	220

Add Fee: Site Insp (\$)

Interview (\$)

Tech Invs (\$)

Weekend (\$)

Report Format :

Lum Sum / I.B.I: (\$) **1,705/- PA**

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	23 Jan 2019		23 Jan 2019 15:04 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:			
Main Claimant:	LCRF PTE LTD		
Vehicle Reg. No.:	SLG1095R	Date of Loss:	18/01/2019 10:00 - :59
Claim Type:	TP / YL3090K	Policy/Cover Note No.:	DMCVSN30003819044
Vehicle Reg. No. (Insured):	YL3090K	Policy No. (Claimant):	
		Excess:	S\$0.00
Repairer:	World Auto Pte Ltd - Kranji (HQ) No 1 Kranji Loop, 739535 Kranji - Tel: 63621776		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Irene Tay Hui Ping - 638986192]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 01/02/2019]		
Adj Asg. Remarks:	PLEASE SURVEY AND REVERT		

ASSOCIATED MAIL RECEIVED

[View All](#)

[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)

[Search Tasks](#)

[Create New Task](#)

[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Nivitha (LKK Auto)

From: Irene Tay <irene.tay@sg.cntaiping.com>
Sent: Wednesday, 23 January 2019 2:48 PM
To: ainee31@worldauto.com.sg
Cc: 'Daniel Tan'; kana@worldauto.com.sg; assignments; Admin A
Subject: RE: Request for Third Party Motor Claim Survey (SLG1095R) DOA: 18-01-2019

WITHOUT PREJUDICE

Dear Sir/Mdm,

We refer to the above matter and our telephone conversation a moment ago.

We will appoint LKK to conduct PRS.

Aside to LKK;

Please assist to liaise with World Auto Pte Ltd.

Thank you.

Regards,

Irene Tay
Executive
Claims Department (Motor Division)

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road #16-00 Springleaf Tower Singapore 079909
Direct (65) 6389 6192
Fax (65) 62247478/62247175
Email: claimsdept@sg.cntaiping.com
www.sg.cntaiping.com



Disclaimer :

This message is confidential; its contents do not constitute a commitment by China Taiping Insurance (Singapore) Pte. Ltd. except where provided for in a written agreement between you and China Taiping Insurance (Singapore) Pte. Ltd. Any unauthorized disclosure, use or dissemination, either in whole or partial, is prohibited. If you are not the intended recipient of the message, please notify the sender immediately.

From: ainee31@worldauto.com.sg [mailto:ainee31@worldauto.com.sg]
Sent: Wednesday, 23 January, 2019 11:25 AM
To: Irene Tay <irene.tay@sg.cntaiping.com>
Cc: 'Daniel Tan' <worldautopl@yahoo.com.sg>; kana@worldauto.com.sg; Claims Dept of CTI

<claimsdept@sg.cntaiping.com>

Subject: RE: Request for Third Party Motor Claim Survey (SLG1095R) DOA: 18-01-2019

Dear Irene

Here is the attachment please do a necessary follow up

Ainee
Thanks and Rgds,
World Auto Pte Ltd
Kranji: 63621776
Fax: 63631250

From: ainee31@worldauto.com.sg <ainee31@worldauto.com.sg>

Sent: Wednesday, January 23, 2019 8:56 AM

To: 'claimsdept@sg.cntaiping.com' <claimsdept@sg.cntaiping.com>; 'Irene Tay' <irene.tay@sg.cntaiping.com>; 'lucas.lee@sg.cntaiping.com' <lucas.lee@sg.cntaiping.com>

Cc: 'Daniel Tan' <worldautopl@yahoo.com.sg>; 'kana@worldauto.com.sg' <kana@worldauto.com.sg>

Subject: Request for Third Party Motor Claim Survey (SLG1095R) DOA: 18-01-2019

Good afternoon,

We would like to request for a Third Party Motor Claim Survey, details as follow;

Our Vehicle: SLG1095R
Your Insured: YL3090K
DOA: 18-01-2019

Our vehicle is currently in the workshop, address as follow;

World Auto Pte Ltd
No.1, Kranji Loop
Singapore 739535

Please response immediately upon receiving this request, send us your list of Loss Adjustor for our choice within 48 hours.

Kindly note that should you fail to response to us within the above stipulated timeline, we may, at our discretion, appoint our own Loss Adjustor to perform this PRI.

Ainee
Thanks and Rgds,
World Auto Pte Ltd
Kranji: 63621776
Fax: 63631250

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>

~~Att.~~
China Taipei

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT	
Date Of Report	19/01/2019 09:29
Date Of Accident	18/01/2019 10:40
Exact Location Of Accident	UPPER SERANGOON RD
Country/State of Loss	SINGAPORE
DETAILS OF OWN VEHICLE	
Vehicle Registration Number	SLG1095R
Insured/Policyholder	
Name Of Registered Owner	LCRF PTE LTD
Co Reg No	201624597K
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-62414992
Vehicle Particulars	
Manufacturer	HONDA
Model	VEZEL-1.5 HYBRID (A)
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE HIRE
Insurance Company	
Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	YES
Policy Number	999995144
Cover Note Number	
Driver	
Name of Driver	SEE HAO JIE
NRIC No	S8741915J
Date Of Birth	03/12/1987
Occupation	OUTDOOR
Date Of Driving Pass	16/11/2015
Driving Experience	3 YEARS AND 2 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-96870976
Fax Number	
Contact Number	
EMail Address	NOEMAIL

Address	NOADDRESS
Postcode	
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	PAID DRIVER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - CHANGE/CROSS LANE
Weather Conditions	CLEAR
Road Surface	WET

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	4
Passenger 1	NAME: : UNKNOWN GENDER: : MALE
Passenger 2	NAME: : UNKNOWN GENDER: : MALE
Passenger 3	NAME: : UNKNOWN GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes,Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes,against whom?	

Circumstances of Accident

PLEASE SEE ATTACHED SKETCH

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	VIDEO OVERWRITTEN
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	YL3090K
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	
NRIC/Passport Number	

Contact Number

Address

Postcode


Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

Sketch Plan

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 18 Jan 2019, at approximately 1040hrs, I was driving vehicle A, SLG 1045R, on upper serangoon Road where I was involved in a hit & run accident with vehicle B, YL3090K.

While travelling along upper Serangoon Road heading down south towards Woodleigh station, I was on the right lane when vehicle B filtered into my lane without signalling his intentions. I sounded my horn to warn him of my presence, but it fell on deaf ears and the incident occurred.

After the incident, I managed to contact the company of vehicle B, Sindhua Hock Kee Trading. After a couple of hours, the company got back to me and asked for me to proceed the claim on them.

DECLARATION

I/We declare the foregoing particulars are true in every respect.



Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Sketch Plan #2

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process
2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated; or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Sketch Plan #3

Land Transport Authority
 AUTO TRANSMISSION VEHICLE ONLY
VOCATIONAL LICENCE
 Licence No: S8741915J
 Name: SEE HAO JIE
 Please visit www.lta.gov.sg to check the status of this vocational licence




REPUBLIC OF SINGAPORE
 IDENTITY CARD NO. **S8741915J**



Name: SEE HAO JIE
 施豪杰
 Race: CHINESE
 Date of birth: 03-12-1967
 Country/Place of birth: SINGAPORE
 Sex: M
 S8741915J




REPUBLIC OF SINGAPORE DRIVING LICENCE
 Licence No: S8741915J
 Name: SEE HAO JIE
 Date of birth: 03 Dec 1967
 Expiry Date: 12 Feb 2018
 002772863E

This card is not transferable and is the property of the Land Transport Authority (LTA). It must be surrendered to LTA on request. If found, please return to LTA, 10 Sin Ming Drive, Singapore 575701.

Type	Description	Issue Date
13	PRIVATE HIRE CAR VL	21/05/2018



5814015



NRIC No: S8741915J



Date of issue: 28-09-2017
 APT BLK 804C WOODLANDS DRIVE 02 #10-48
 SINGAPORE 733884
 NRIC No: S8741915J Date: 05/07/2018
 www.lta.gov.sg

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASSIES

Class	Description	EFFECTIVE DATE
Class 3A	Motor cars without clutch pedals (Auto) with unladen weight <= 3000kg with <= 7 passengers, exclusive of driver; and other motor vehicles without clutch pedals with unladen weight <= 2500kg	16 Nov 2015

HP 426A



WORLD AUTO PTE LTD

47 Jalan Pemimpin #01-02/03
 Halcyon 2, S'pore 577200
 Tel No. : 6451 3933 Fax No. : 6455 7576
 E-Mail : worldaut@singnet.com.sg
 Website : www.worldauto.com.sg
 Tax Reg. No. : 200006765-H Buss. Reg. No. : 200006765H

CHINA TAIPING INSURANCE PTE LTD
 3 ANSON ROAD
 #16-00 SPRINGLEAF TOWER 079909

Attention : Motor Claim Department
 Contact : 6389 6111

Estimate : ES190040

Date : 23/01/2019
 Vehicle Num. : SLG 1095R (LCR)
 Make/Model : HONDA VEZEL HYBRID
 Chassis/Eng# :
 Accident Date : 18/01/2019
 Claim No. :
 Reference :
 Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

LIST ITEMS :				
1.	1	FRONT FENDER LH <i>DD</i>		550.00 ✓
2.	1	FRONT FENDER HYBRID EMBLEM LH <i>NEC</i>	50	89.00 ✓
3.	1	FRONT WHEEL ARCH MOULDING LH <i>SCR</i>		250.00 ✓
4.	1	FRONT DOOR - LH <i>Repair</i>		1,500.00 X
5.	1	FRONT BUMPER RETAINER LH <i>NN</i>		89.00 X
List TotalS\$:				2,478.00
20.00% Discount S\$:				495.60
				<hr/>
				1,982.40

SPECIAL NETT ITEMS :				
1.	1	FRONT WHEEL ARCH MOULDING CLIPS <i>NEC</i>	15	40.00 ✓
Special Nett Total S\$:				40.00

LABOUR :					
TO APPLY RUSTPROOFING/ TUFFCOATING TREATMENT TO REPLACED PARTS.				30	180.00 ✓
TRANSFER DOOR MECHANISM					180.00 X
REMOVE ACCIDENT DAMAGED PARTS IN ORDER TO FACILITATE 1, REPAIRS INCLUDING PANEL BEAT, CUT / WELD, STRAIGHTEN CHASSIS WHERE NECESSARY AND REPLACE ABOVE PARTS				500	900.00 ✓
PUTTY AND SPRAY PAINT ALL AFFECTED AREAS (INNER/OUTER)				480	800.00 ✓
Labour Total S\$:					2,060.00

E. & O.E. Total S\$: 4,082.40

[Handwritten Signature]
28/1/19

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

Total - \$1705

Hwee Jie -LKK
 24/1/19
 P/P 3days
 Photo before paint

for WORLD AUTO PTE LTD

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	23 Jan 2019		23 Jan 2019 15:04 Edit Adj Rpt	S\$1,705.00 Edit Estimates	S\$1,705.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS		[Created by insurer]							
Insured:	-, Co. Reg. No.: -								
Main Claimant:	LCRF PTE LTD								
Vehicle Reg. No.:	SLG1095R	Date of Loss:	18/01/2019 10:00 - :59 [27 Months and 28 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / YL3090K	Policy/Cover Note No.:	DMCVSN30003819044						
Vehicle Reg. No. (Insured):	YL3090K	Policy No. (Claimant):							
		Excess:	S\$0.00						
Repairer:	World Auto Pte Ltd - Kranji (HQ) No 1 Kranji Loop, 739535 Kranji - Tel: 63621776								
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Irene Tay Hui Ping - 638986192]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ONG HWEE JIE] ... [Final Rpt due 01/02/2019]								
Adj Asg. Remarks:	PLEASE SURVEY AND REVERT								
ASSOCIATED MAIL RECEIVED		View All Compose Case Mail							
There are no mail for this case.									
ALL ASSOCIATED TASKS <input type="checkbox"/>		View All Search Tasks Create New Task Complete							
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SLG1095R (YL3090K)**
[YL3090K]
TP
LCRF PTE LTD
Jan 18 2019 10:00AM
[-]
World Auto Pte Ltd - Kranji

Upload Documents		Upload Photos		Compose New Letter		View View in Browser <input type="button" value="v"/>		
Photos/Images							3 per page <input type="button" value="v"/>	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print			
1	25/01/19 10:16	General View		Load JPG	<input checked="" type="checkbox"/>			
2	25/01/19 10:16	General View		Load JPG	<input checked="" type="checkbox"/>			
3	25/01/19 10:16	General View		Load JPG	<input checked="" type="checkbox"/>			
4	25/01/19 10:16	General View		Load JPG	<input checked="" type="checkbox"/>			
5	25/01/19 10:16	General View		Load JPG	<input checked="" type="checkbox"/>			
6	25/01/19 10:16	General View		Load JPG	<input checked="" type="checkbox"/>			
7	25/01/19 10:16	General View		Load JPG	<input checked="" type="checkbox"/>			
8	25/01/19 10:16	General View		Load JPG	<input checked="" type="checkbox"/>			
9	25/01/19 10:16	General View		Load JPG	<input checked="" type="checkbox"/>			
10	25/01/19 10:16	General View		Load JPG	<input checked="" type="checkbox"/>			
11	25/01/19 10:16	General View		Load JPG	<input checked="" type="checkbox"/>			
12	25/01/19 10:16	General View		Load JPG	<input checked="" type="checkbox"/>			
13	25/01/19 10:16	General View		Load JPG	<input checked="" type="checkbox"/>			
14	25/01/19 10:16	General View		Load JPG	<input checked="" type="checkbox"/>			
15	20/02/19 09:28	Replacement Part Photo		Load JPG	<input checked="" type="checkbox"/>			
16	20/02/19 09:28	Replacement Part Photo		Load JPG	<input checked="" type="checkbox"/>			
17	20/02/19 09:28	Replacement Part Photo		Load JPG	<input checked="" type="checkbox"/>			
18	20/02/19 09:28	Replacement Part Photo		Load JPG	<input checked="" type="checkbox"/>			

Documents Checklist

DOCUMENTS CHECKLIST		Reset	Save	Print
There are no document checklists configured.				
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)				
<div style="border: 1px solid black; width: 100%; height: 100%;"></div>				
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>				

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI19001516/JSD3E2

Date: 08/03/2019

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSN30003819044
Claimant Vehicle No :	SLG1095R	Insured Vehicle No :	YL3090K
Date of Loss:	18/01/2019	Nature of Claim:	TP
		Claim No:	YL3090K

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLG1095R	Engine No:	LEB5908152
Make & Model:	HONDA VEZEL, 1.5 HYBRID (A)	Chassis No:	RU31208141
Reg. Date:	21/09/2016 (Man. Year: 2016)	Odometer:	159615 km
Colour:	Black		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/60 R16	Rear Tyre Size:	215/60 R16
Front Left Side:	Giti 6 mm	Rear Left Side:	Giti 6 mm
Front Right Side:	Giti 6 mm	Rear Right Side:	Giti 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,022.40	695.00	1,327.40	65.63
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,060.00	1,010.00	1,050.00	50.97
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	4,082.40	1,705.00	2,377.40	58.24
+ GST 7.00/7.00% (S\$)	285.77	119.35	166.42	58.24
Nett Amount (S\$)	4,368.17	1,824.35	2,543.82	58.24

INSPECTION

Date of Assignment:	23/01/2019	Inspected At:	World Auto Pte Ltd - Kranji (HQ)
Date Inspected:	24/01/2019		No 1 Kranji Loop
			Singapore 739535
Estimated Period of Repair:	3.0 days		

Adjuster: ONG HWEE JIE

Manager: Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference	
Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 08 Mar 2019)
Parts: M1-SUV	HONDA VEZEL 1.5 HYBRID (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SLG1095R)	
Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT FENDER LH	Dented	550.00 FL	*550.00 FL
2	1		*FRONT FENDER HYBRID EMBLEM LH	Necessary	89.00 FL	*50.00 FL
3	1		*FRONT WHEEL ARCH MOULDING LH	Scratched	250.00 FL	*250.00 FL
4	1		*FRONT DOOR - LH	Repair	1,500.00 FL	*- FL
5	1		*FRONT BUMPER RETAINER LH	Not Necessary	89.00 FL	*- FL
6	1		*FRONT WHEEL ARCH MOULDING CLIPS	Necessary	40.00 FS	*15.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	2,518.00	865.00
- List Item Discount on L Items 20.00/20.00% (S\$)	495.60	170.00
Total Parts (S\$)	2,022.40	695.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO APPLY RUSTPROOFING / TUFFCOATING TREATMENT TO REPLACED PARTS	New	180.00	30.00
2	TRANSFER DOOR MECHANISM	New	180.00	0.00
3	REMOVE ACCIDENT DAMAGED PARTS IN ORDER TO FACILITATE 1, REPAIRS INCLUDING PANEL BEAT, CUT / WELD, STRAIGHTEN CHASSIS WHERE NECESSARY AND REPLACE ABOVE PARTS	New	900.00	500.00
4	PUTTY AND SPRAY PAINT ALL AFFECTED AREAS (INNER/OUTER)	New	800.00	480.00
Gross Labour Cost (S\$)			2,060.00	1,010.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >