



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AXA INSURANCE PTE LTD

Ref : CC4/ASM19001529/Kpa3q2

8 SHENTON WAY #24-01
AXA TOWERSINGAPORE 068811

Date : 16-04-2020



ATTN:PETER

Code : ASM

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	EG 37Z	Veh. Inspected	SLN 8738L
Policy No.	CN030411	Coverage (\$)	0.00
Claim No.	S9M01BBM	Excess (\$)	0.00
Assign From		Assign Date	23/01/2019

2. Vehicle Particulars & Condition

Make & Model	B.M.W. 523I (A)	c.c	2497
Engine No.	HIDDEN	Year of Reg.	2011
Chassis No.	WBAFP32040C866963	Colour	METALLIC PEARL WHITE
Odometer	107544	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	245/40 R19	CONTINENTAL	4 mm
L/H Front Tyre	245/40 R19	CONTINENTAL	4 mm
R/H Rear Tyre	275/35Z R19	CONTINENTAL	3 mm
L/H Rear Tyre	275/35Z R19	CONTINENTAL	3 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR & FRONT PORTION. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	21/01/2019	Inspection Date	23/01/2019
Survey held at	LAI HUAT (MENG KEE) MOTOR PTE LTD 160 SIN MING DRIVE #04-01/02 SIN MING AUTOCITY SINGAPORE 575722		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	6 Working Days
-------------------------------------	----------------