

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	23/01/2019 17:02
Date Of Accident	14/01/2019 19:45
Exact Location Of Accident	BLK 799 YISHUN RING ROAD OPEN SPACE CARPARK
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	S2970CD
-----------------------------	---------

Insured/Policyholder

Name Of Registered Owner	EMBASSY OF THE REPUBLIC OF INDONESIA
Co Reg No	S67DP0029F
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-67377422

Vehicle Particulars

Manufacturer	TOYOTA
Model	ALPHARD MR CVT
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	REPORTING ONLY
Vehicle Category	COMMERCIAL VEHICLE

Insurance Company

Name of Insurance Company	MSIG INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	A27797952MCY
Cover Note Number	

Driver

Name of Driver	AHMAD SHAFIQ BIN TALIB
NRIC No	S8628639D
Date Of Birth	01/10/1986
Occupation	OUTDOOR
Date Of Driving Pass	14/03/2013
Driving Experience	5 YEARS AND 10 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-91093749
Fax Number	
Contact Number	OFFICE-91093749
Email Address	NOEMAIL

Address	BLK 139 YISHUN RING ROAD #05-108
Postcode	760139
Was driver an employee of the Insured's Company	YES
If No, Relationship of the Driver with the Insured	
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	HIT AND RUN / VANDALISM / DAMAGED WHILST PARKED
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	0

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	YISHUN SOUTH NEIGHBOURHOOD POLICE CENTRE
Police Station Address	ROAD: 32 YISHUN ST 81 , POSTCODE: 768456 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: 1800-8522999 - FAX NO: 68522239
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO POLICE REPORT - T/20190114/2171.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	UNKNOWN
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	

No. Of Passenger (Including Driver)

Accident Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Accident Sketch Plan

SKETCH PLAN

Alle drei Fahrer King
Rund um die 3000
ca. 100 km/h

A: 5297000
B: Unklarheit

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Refer to police report - 7/20190114/2171.

[A large diagonal line is drawn across the remaining lines of this section.]

DECLARATION

I/We declare the foregoing particulars are true in every respect:

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Police Report



**SINGAPORE
POLICE FORCE**



T/20190114/2171

Police Station Of Origin:
Yishun South N.P.C
32 Yishun Street 81 SINGAPORE 768456
Tel No: 1800-8522999

1 of 3

Report No. T/20190114/2171

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 14/01/2019 23:15	Vide Report No.:	Station Diary No.: 122
--	------------------	---------------------------

Informant's Particulars

Name of Informant: AHMAD SHAFIQ BIN TALIB			Address: APT BLK 139 YISHUN RING ROAD #05-108 SINGAPORE 760139		
ID Type / ID No.: NRIC NO / S8628639D			Contact No.: Home/Office: Mobile: 91093749		
Nationality: SINGAPORE CITIZEN			Email:		
Sex: Male	Age: 32	Date of Birth: 01/10/1986	Type of Informant: Driver		
Race: Malay			Language:		Institution / School Name:
Occupation: Driver			Driving Licence Information: Class: 2B,3 Date of Expiry:		

General Information of the Accident

Type of Accident:	Non-Injury Hit and Run	Drink Drive: No	Date/Time of Accident: 14/01/2019 21:45	Type of Location: Car Park
Location: Along Road 1 YISHUN RING ROAD				
Car Park of Blk 799 YISHUN RING ROAD				
Weather: Clear	Road Surface: Dry		Road Speed Limit:	
Traffic Flow:	Traffic Control:		Traffic Volume:	
Type of Collision: Moving Vehicle Against - Parked Vehicle	Anyone conveyed by ambulance: No			

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
S2970CD	Car	TOYOTA	ALPHARD	Black	Slightly Damaged	0

Police Report



**SINGAPORE
POLICE FORCE**



T/20190114/2171

Police Station Of Origin:
Yishun South N.P.C
32 Yishun Street 81 SINGAPORE 768456
Tel No: 1800-8522999

2 of 3

Report No. T/20190114/2171

CONTINUATION OF REPORT

Brief Details.

On the 14/01/2019 at about 7:45pm, I parked my vehicle S2970CD at Lot number 2 at the carpark of Blk 799 Yishun Ring Road. At about 9:45pm, when I came back to drive the car off, I discovered that the right side bumper of my vehicle was damaged and came out. The right side of the bumper is dented and scratch marks can be seen.

I am driving this vehicle for an Indonesian Diplomat. There is no in-built camera in my car. When I parked my vehicle there was a car on the left side(still there) and an empty handicap lot on the right side of my vehicle.

Police Report



**SINGAPORE
POLICE FORCE**



T/20190114/2171

Police Station Of Origin:
Yishun South N.P.C
32 Yishun Street 81 SINGAPORE 768456
Tel No: 1800-8522999

3 of 3

Report No. T/20190114/2171

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report:
L/
Sr Staff Sgt MOHAMAD FAIZAL BIN SIKEN

Signature Of Informant:

Signature Of Interpreter:
Not applicable

Date/Time:
14/01/2019 23:15

Officer In Charge Of Case:
TP / HRT /
Sr Staff Sgt IRMAN BIN MOHAMAD SAID
Contact No.: 65476145

Classification Of Case:

Authentication Stamp
NP168

Signature:



Police Report



**SINGAPORE
POLICE FORCE**



L/20190114/2137

1 of 2

POLICE REPORT (NP299)

Report No. L/20190114/2137

Police Station Of Origin
Yishun South N.P.C
32 Yishun Street 81 SINGAPORE 768456
Tel No: 1800-8522999

Date/Time Report Made 14/01/2019 23:24		Vide Report No. T/20190114/2171		Station Diary No. 127	
Name Of Informant AHMAD SHAFIQ BIN TALIB		Address APT BLK 139 YISHUN RING ROAD #05-108 SINGAPORE 760139			
ID Type / ID No. NRIC NO / S8628639D		Contact No. Home/Office Mobile 91093749			
Nationality SINGAPORE CITIZEN		Email Address			
Occupation Driver		Sex Male	Age 32	Date of Birth 01/10/1986	Race Malay
Institution/School Name		Language			
Date/Time Of Incident 14/01/2019 19:45 - 14/01/2019 21:45		Location Of Incident APT BLK 799 YISHUN RING ROAD KHATIB VALE SINGAPORE 760799			

Brief details.

On the 14/01/2019 at about 7:45pm, I parked my vehicle S2970CD at Lot number 2 at the carpark of Blk 799 Yishun Ring Road. At about 9:45pm, when I came back to drive the car off, I discovered that the right side bumper of my vehicle was damaged and came out. The right side of the bumper is dented and scratch marks can be seen.

I am driving this vehicle for an Indonesian Diplomat. There is no in-built camera in my car. When I parked

Signature Of Officer Recording The Report: L / Sr Staff Sgt MOHAMAD FAIZAL BIN SIKEN		Signature Of Informant:	
Signature Of Interpreter: Not applicable		Date/Time: 14/01/2019 23:24	
Officer In-Charge Of Case: L / Woodlands Police Divisional Investigation Branch / Insp NG MEIQI, JOLENE Contact No.: 64660000		Classification Of Case:	

Authentication Stamp



Police Report



**SINGAPORE
POLICE FORCE**



L/20190114/2137

2 of 2

POLICE REPORT (NP299)

CONTINUATION OF REPORT

Report No. L/20190114/2137

my vehicle there was a car on the left side(still there) and an empty handicap lot on the right side of my vehicle.

Signature Of Officer Recording The Report:

L / Sr Staff Sgt MOHAMAD FAIZAL BIN SIKEN

Signature Of Interpreter:
Not applicable

Officer In-Charge Of Case:
L / Woodlands Police Divisional Investigation Branch /
Insp NG MEIQI, JOLENE
Contact No.: 64660000

Authentication Stamp

Signature Of Informant:

Date/Time:
14/01/2019 23:24

Classification Of Case:



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo

