

ASS. REC. BY:

REP

CS/CTI/1901552/Ksd3 9/1

Report of Instruction

Surveyor

Kenneth

ASSIGNMENT (Office)

Meimen

Irene Tay

From (Person)

of

CTI

Date/Time

23/1/19 @ 3:25pm

Estimated Cost:

Bill to:

OD / (TP) WS / TP RES / OD RES / EVA / INV / MV7 CS

To Inspect Vehicle No:

SKA 7703Z

Insured:

YN1776T

at Workshop in/s

Ah Lim Motor

Tel:

64831244

of

10 Amk Ind. Park 2A #01-09

Policy No:

DMERSN 3022/518000

Claim No:

SNM19D200395C02

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A

18/1/2019

CA / REV / REP. / REV 24 HRS

hup

H.O.D. Endorsement:

Date/Time:

4:47pm @ 23/1/19

Person Contacted:

Zila

Vehicle IN / OUT

Date/Time

Action/Instruction

(✓)

Estimate

SKA 7703Z - X

YN1776T - CS/CTI/18014096/Ksd3n2

D.O.A: 30/7/18

30/4

LI Reg 81550k. Confirmed

(\$ 2,497.00 Red - 62%)

ASS. REC. BY:

REF: C121

Kenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____


Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Soon: _____ Consistent? : Yes or No

Est. Repairs: 04 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SKA 77038 Yr Regn: 03/11

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or AI MPV

Make: Honda Stream c.c. 1799

Colour: M. Grey AC: Insured / Std / NI / NA

Sp. Reading: 158816 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: THMRN08609C20049

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 205/65R15

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Continued

Front: _____ Rear: _____

R/Bal: 8 mm R/Bal: 8 mm

L/Bal: 8 mm L/Bal: 8 mm

D.O.A. 18/1/19 D.O.I. 23/1/19

Survey held at: _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

24/1 File pass to Car

RECEIVED 30 APR 2012

Date/Time, File Pass to?

30/04/19

1) Type: 4

Date/Time, File Return to?

2)

☐ : Prelim. Report☒ : Final Report

Days Of Repair: 4

Resurvey No. of Trip: 1

Survey Fee:

Transportation:

S - RS - SI

Fixtures

Others

TOTAL

Add Fee: ☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech Invs (\$)☐ : Weekend (\$)

Report Format :

Lump Sum / I.B.I: (\$ 1,550 / H/S)

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	23 Jan 2019		23 Jan 2019 15:25 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:			
Main Claimant:	WONG YIN MUN		
Vehicle Reg. No.:	SKA7703Z	Date of Loss:	18/01/2019 15:00 - :59
Claim Type:	TP / SNM19D200395C02	Policy/Cover Note No.:	DMCV5N30221518000
Vehicle Reg. No. (Insured):	YN1776T	Policy No. (Claimant):	
		Excess:	S\$0.00
Repairer:	Ah Lim Motor Company (AMK) 10 Ang Mo Kio Industrial Park 2A, #01-09 AMK Autopoint, 568047 Ang Mo Kio - Tel: 6483 1244		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Irene Tay Hui Ping - 638986192]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 01/02/2019]		
Adj Asg. Remarks:	PLEASE SURVEY AND REVERT		

ASSOCIATED MAIL RECEIVED

[View All](#)

[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)

[Search Tasks](#)

[Create New Task](#)

[Complete](#)

Due Date Priority Type Task Group Subject Handler Assigned By Completed On Created On Done?

No results.

Nivitha (LKK Auto)

From: Irene Tay <irene.tay@sg.cntaiping.com>
Sent: Wednesday, 23 January 2019 3:18 PM
To: zila@ahlimmotor.com.sg
Cc: assignments; Admin A
Subject: CTP REF NO. SNM19D200395 - TP / OUR CLIENT SKA7703Z DOA: 18/01/2019
POLICY NO. MT/00293418/02 YOUR INSURED YN1776T
Attachments: 7703.pdf; 7703 - DIRECT.pdf

WITHOUT PREJUDICE

Dear Sir/Mdm,

We refer to the above matter and our telephone conversation a moment ago.

We will appoint LKK to conduct PRS.

Aside to LKK;

Please assist to liaise with Ah Lim Motor.

Thank you.

Regards,

Irene Tay
Executive
Claims Department (Motor Division)

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road #16-00 Springleaf Tower Singapore 079909 Direct (65) 6389 6192
Fax (65) 62247478/62247175
Email: claimsdept@sg.cntaiping.com
www.sg.cntaiping.com

Disclaimer :

This message is confidential; its contents do not constitute a commitment by China Taiping Insurance (Singapore) Pte. Ltd. except where provided for in a written agreement between you and China Taiping Insurance (Singapore) Pte. Ltd. Any unauthorized disclosure, use or dissemination, either in whole or partial, is prohibited. If you are not the intended recipient of the message, please notify the sender immediately.

-----Original Message-----

From: zila [mailto:zila@ahlimmotor.com.sg]
Sent: Tuesday, 22 January, 2019 4:12 PM
To: Irene Tay <irene.tay@sg.cntaiping.com>
Subject: Fwd: TP / OUR CLIENT SKA7703Z DOA: 18/01/2019 POLICY NO. MT/00293418/02 YOUR INSURED YN1776T

Hi Irene,

Please kindly arrange survey.

Note: Vehicle is not in. – To be arrange

Thanks.

Best Regards,

Zila
Ah Lim Motor
Tel: 64831244 Fax: 64836170

----- Forwarded Message -----

Subject: TP / OUR CLIENT SKA7703Z DOA: 18/01/2019 POLICY NO.
MT/00293418/02 YOUR INSURED YN1776T
Date: Tue, 22 Jan 2019 10:29:30 +0800
From: zila <zila@ahlimmotor.com.sg>
To: CLAIMSDEPT@SG.CNTAIPING.COM, ANGIE.FOO@SG.CNTAIPING.COM

Hi Claims Dept,

Please kindly arrange survey.
Note: Vehicle is not in. – To be arrange

Thanks.

--
Best Regards,

Zila
Ah Lim Motor
Tel: 64831244 Fax: 64836170

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC
Owner ID: 3533Z

Vehicle Details

Vehicle No.: SKA7703Z
Vehicle to be Exported: No
Intended Deregistration Date: 19 Jan 2019
Vehicle Make: HONDA
Vehicle Model: STREAM 1.8L AT
Primary Colour: Grey
Manufacturing Year: 2009
Engine No.: R18A13850491
Chassis No.: JHMRN68609C200491
Maximum Power Output: 103.0 kW (138 bhp)
Open Market Value: \$25,394.00
Original Registration Date: 30 Mar 2011
First Registration Date: 30 Mar 2011
Transfer Count: 1
Actual ARF Paid: \$25,394.00

Intended PARF Rebate Details

PARF Eligibility: Yes
PARF Eligibility Expiry Date: 29 Mar 2021
PARF Rebate Amount: \$15,236.00

Intended COE Rebate Details

COE Expiry Date: 29 Mar 2021
COE Category: B - Car (1601cc & above)
COE Period(Years): 10
QP Paid: \$62,000.00
COE Rebate Amount: \$13,599.00
Total Rebate Amount: \$28,835.00

The information contained herein is correct as at 19 Jan 2019

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	19/01/2019 11:10
Date Of Accident	18/01/2019 15:10
Exact Location Of Accident	JERVOIS RD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKA7703Z
Insured/Policyholder	
Name Of Registered Owner	WONG YIN MUN
NRIC No	S7773533Z
Email Address	WGYIUN@GMAIL.COM
Mobile Phone No	(LOCAL) +65-94883504
Alternative Phone No	OTHERS-94883504

Vehicle Particulars

Manufacturer	HONDA
Model	STREAM-1.8 L (A)
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	DIRECT ASIA INSURANCE (SINGAPORE) PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	MT/00293418/02
Cover Note Number	30/03/2018 - 29/03/2019

Driver

Name of Driver	WONG YIN MUN
NRIC No	S7773533Z
Date Of Birth	15/11/1977
Occupation	INDOOR
Date Of Driving Pass	16/01/2003
Driving Experience	16 YEARS AND 0 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-94883504
Fax Number	
Contact Number	OTHERS-94883504
Email Address	WGYIUN@GMAIL.COM


SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:



Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Sketch Plan Pg. 3



Contact us at
 Hotline: (65) 6532 2888
 E-mail: CustomerService@DirectAsia.com

YOUR POLICY SCHEDULE

This document forms part of your contract with us and should be read together with your Certificate of Insurance and your Policy Details. Do let us know if any of the details shown here need to be amended or updated.

Car Insurance

Policy number	: MT/00293418/02
Period of cover	: Policy begins 30/03/2018 00:00 and runs until 29/03/2019 23:59
Premium	: S\$ 860.17 (inclusive of GST)
Own Damage Excess	: S\$ 100.00 (before any applicable GST)
Windscreen Excess	: S\$ 100.00 (before any applicable GST)
Vehicle Details	
Vehicle Registration	: SKA7703Z
Make and model	: Honda Stream 1.8 T (A)
Year of registration	: 2011
Finance company / Hire purchase	:
Is your car modified? (Modifications are according to LTA guidelines)	: No
Chassis number	
	: JHMRN68609C200491
Car usage	: Private Use + Commuting to work
Policyholder	
Policyholder	: Wong, Yin Mun
Mailing Address	: 7 FERNVALE CLOSE, 11-13 LUSH ACRES, Singapore 797488
E-mail Address	: wgyiun@gmail.com
Mobile Number	: 94883504
No Claims Discount (NCD)	: 50%
Main Driver Details	
Main Driver	: Wong, Yin Mun
Date of Birth	: 15/11/1977
Marital Status	: Married
Gender	: Male
Occupation	: Professionals (doctor, lawyer, consultant, etc)
Certificate of Merit	: Yes
Years of valid driving licence	: > 5
Important Note: This policy does not cover drivers below the age of 30 and drivers who hold a valid driving licence of less than 2 years with the exception of the named drivers above.	
Young and/ or Inexperienced Driver (YIED): refers to any driver who is below the age of 30 or holds a driving licence for less than 2 years.	

Direct Asia Insurance (Singapore) Pte Ltd
 88 South Bridge Road Singapore 058716
 www.DirectAsia.com

Copyright © 2008/2016

AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlimmc@singnet.com.sg
GST:M9-0009639-E RCB NO:06470300B

SURVEYOR COPY

M/S : WONG YIN MUN
7 FERNVALE CLOSE
#11-13
SINGAPORE 797488

Estimate No: MC1900076
Date: 22 Jan 2019
Policy No: MT/00293418/02
Veh Reg No: SKA7703Z
Make/Model: HONDA STREAM 1.8L
AT

ATTN:

Your Ref No: SKA7703Z
Claim Type: Third Party - China
Accident Date: 18/01/2019
TP Veh Reg No: YN1776T

LKK
1:30pm

Not Notmark
11/12/87
Muney After Point

4 days

Estimate Repair Cost to Vehicle No :SKA7703Z

Description	Quantity	List Price	Amount
		SS	SS
SPARE PARTS			
1 REAR WINDSCREEN MOULDING	1 PC	65.00	—
2 TAILGATE	1 PC	903.00	—
3 TAILGATE HINGE LH & RH	2 PC	93.60	X
4 TAILGATE EMBLEM	1 PC	21.90	—
5 TAILGATE STREAM LOGO	1 PC	31.60	—
6 TAILGATE NO PLATE GARNISH	1 PC	162.80	X
7 TAILGATE NO PLATE LAMP LH & RH	2 PC	65.60	X
8 TAILGATE WIPER ARM	1 PC	45.00	—
9 TAILGATE WIPER BLADE	1 PC	41.30	—
10 TAILGATE WIPER MOTOR	1 PC	255.30	X
11 TAILGATE TRIMBOARD	1 PC	141.00	X
12 TAILGATE INNER LOCK	1 PC	109.40	X
13 TAILAMP LH & RH	2 PC	705.00	—
		2,640.50	
		Less 20%	528.10
			2,112.40
Special Nett			
14 NUMBER PLATE	1 PC	35.00	X
15 INNER SEAL	1 PC	20.00	—
16 WINDSCREEN SEALANT	1 PC	40.00	—
17 REAR WINDSCREEN SOLAR FILM	1 PC	200.00	150.00
		295.00	295.00
LABOUR			
18 TO DISCONNECT AND CHECK ELECTRICAL WIRING, WIRE SOCKETS AND ETC. TO REMOVE AND REINSTALL DAMAGED ELECTRICAL UNITS, TEST AND RECTIFY FOR PROPER FUNCTIONING.	1 PC	40.00	20.00
19 TO REMOVE AND REINSTALL/REPLACE FRONT/REAR WINDSCREEN.	1 PC	120.00	—
20 TO REMOVE AND REINSTALL CUSHIONS, SEATS, BACKREST, INNER TRIM, GARNISH, ROOF LINING OR UPHOLSTERY TO FACILITATE REPAIRS.	1 PC	80.00	X
21 TO DISMANTLE ALL DAMAGED PARTS, TO CUT & WELD, TO KNOCK & REPAIR REAR BUMPER, END PANEL INNER PANELS AND AFFECTED AREAS. TO REFIT LISTED PARTS BACK SAME.	1 PC	700.00	200.00
22 TO SPRAY TAILGATE, REAR BUMPER, END PANEL.	1 PC	700.00	250.00
		1,640.00	1,640.00

LKK Auto Consultants hereby notify the Repairer of the following:

- To rectify before/after spray painting
- To display damaged part(s) during survey
- Parts prices are subject to confirmation
- Third party survey is on a "without prejudice" basis
- No illegal modification work is allowed
- Supplementary work/ items must be approved by the insurance company

Acknowledged by Repairer: *cl sum*
Signature: _____
Date: _____



AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlmmc@singnet.com.sg
GST:M9-0009639-E RCB NO.06470300B

SURVEYOR COPY

M/S : WONG YIN MUN
7 FERNVALE CLOSE
#11-13
SINGAPORE 797488

Estimate No: MC1900076
Date: 22 Jan 2019
Policy No: MT/00293418/02
Veh Reg No: SKA7703Z
Make/Model: HONDA STREAM 1.8L
AT

ATTN:

Your Ref No: SKA7703Z
Claim Type: Third Party
Accident Date: 18/01/2019
TP Veh Reg No: YN1776T

Estimate Repair Cost to Vehicle No :SKA7703Z

Description	Quantity	List Price	Amount
		S\$	S\$
		Total	S\$ 4,047.40
		Add GST @ 7%	283.32
		Total Amount Payable	S\$ 4,330.72

TOTAL: SINGAPORE DOLLAR FOUR THOUSAND THREE HUNDRED THIRTY AND CENTS SEVENTY TWO ONLY

Please arrange this vehicle to be surveyed soonest possible.

Thank You

For AH LIM MOTOR COMPANY



AUTHORISED SIGNATURE

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	23 Jan 2019		23 Jan 2019 15:25 Edit Adj Rpt	S\$1,550.00 Edit Estimates	S\$1,550.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by Insurer]									
Insured:	ID: -								
Main Claimant:	WONG YIN MUN								
Vehicle Reg. No.:	SKA7703Z	Date of Loss:	18/01/2019 15:00 - :59 [93 Months and 19 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / SNM19D200395C02	Policy/Cover Note No.:	DMCV5N30221518000						
Vehicle Reg. No. (Insured):	YN1776T	Policy No. (Claimant):							
		Excess:	S\$0.00						
Reparer:	Ah Lim Motor Company (AMK) 10 Ang Mo Kio Industrial Park 2A, #01-09 AMK Autopoint, 568047 Ang Mo Kio - Tel: 6483 1244								
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Irene Tay Hui Ping - 638986192]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KENNETH KONG] ... [Final Rpt due 01/02/2019]								
Adj Asg. Remarks:	PLEASE SURVEY AND REVERT								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SKA7703Z (SNM19D200395C02)
[YN1776T]
TP
WONG YIN MUN
Jan 18 2019 3:00PM
[-]
Ah Lim Motor Company

Upload Documents

Upload Photos

Compose New Letter

View

View in Browser

Photos/Images

3 per page

No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	30/04/19 11:11	General View		 Load JPG	<input checked="" type="checkbox"/>
2	30/04/19 11:11	General View		 Load JPG	<input checked="" type="checkbox"/>
3	30/04/19 11:11	General View		 Load JPG	<input checked="" type="checkbox"/>
4	30/04/19 11:11	General View		 Load JPG	<input checked="" type="checkbox"/>
5	30/04/19 11:11	General View		 Load JPG	<input checked="" type="checkbox"/>
6	30/04/19 11:11	General View		 Load JPG	<input checked="" type="checkbox"/>
7	30/04/19 11:11	General View		 Load JPG	<input checked="" type="checkbox"/>
8	30/04/19 11:11	General View		 Load JPG	<input checked="" type="checkbox"/>
9	30/04/19 11:11	General View		 Load JPG	<input checked="" type="checkbox"/>
10	30/04/19 11:11	General View		 Load JPG	<input checked="" type="checkbox"/>
11	30/04/19 11:12	Reinspection Photo		 Load JPG	<input checked="" type="checkbox"/>
12	30/04/19 11:12	Reinspection Photo		 Load JPG	<input checked="" type="checkbox"/>
13	30/04/19 11:12	Reinspection Photo		 Load JPG	<input checked="" type="checkbox"/>

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

LKK Auto Consultants Pte Ltd

(Co. Reg. No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CT119001552/KSD3Q2

Date: 06/05/2019

REFERENCE

Handling Insurer: China Taiping Insurance
(Singapore) Pte. Ltd.

Policy No: DMCVSN30221518000

Claimant Vehicle
No: SKA7703ZInsured Vehicle
No: YN1776T

Date of Loss: 18/01/2019

Nature of Claim: TP

Claim
No: SNM19D200395C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SKA7703Z

Make & Model: HONDA STREAM, 1.8 (A)

Reg. Date: 30/03/2011 (Man. Year: 2009)

Colour: Metallic Grey

Engine Capacity: 1799 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

Engine No: R18A13850491

Chassis No: JHMRN68609C200491

Odometer: 158816 km

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/65 R15

Front Left Side: Continental 8 mm

Front Right Side: Continental 8 mm

Rear Tyre Size: 205/65 R15

Rear Left Side: Continental 8 mm

Rear Right Side: Continental 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,407.40	1,378.24	1,029.16	42.75
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,640.00	590.00	1,050.00	64.02
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	4,047.40	1,968.24	2,079.16	51.37
Approved Total (Overridden) (S\$)		1,550.00		
(S\$)	4,047.40	1,550.00	2,497.40	61.70
+ GST 7.00/7.00% (S\$)	283.32	108.50	174.82	61.70
Nett Amount (S\$)	4,330.72	1,658.50	2,672.22	61.70

INSPECTION

Date of Assignment: 23/01/2019

Date Inspected: 23/01/2019 Inspected At:

Ah Lim Motor Company (AMK)
10 Ang Mo Kio Industrial Park 2A, #01-09
AMK Autopoint
Singapore 568047

Estimated Period of Repair: 4.0 days

Adjuster: KENNETH KONG**Manager:** Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 06 May 2019)
Parts: M1-MPV	HONDA STREAM 1.8 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SKA7703Z)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR WINDSCREEN MOULDING	Necessary	65.00 FL	*65.00 FL
2	1		*TAILGATE	Bent	903.00 FL	*903.00 FL
3	2		*TAILGATE HINGE LH & RH	Repair	93.60 FL	*- FL
4	1		*TAILGATE EMBLEM	Necessary	21.90 FL	*21.90 FL
5	1		*TAILGATE STREAM LOGO	Necessary	31.60 FL	*31.60 FL
6	1		*TAILGATE NO PLATE GARNISH	Serviceable	162.80 FL	*- FL
7	2		*TAILGATE NO PLATE LAMP LH & RH	Serviceable	65.60 FL	*- FL
8	1		*TAILGATE WIPER ARM	Broken	45.00 FL	*45.00 FL
9	1		*TAILGATE WIPER BLADE	Missing	41.30 FL	*41.30 FL
10	1		*TAILGATE WIPER MOTOR	Serviceable	255.30 FL	*- FL
11	1		*TAILGATE TRIMBOARD	Serviceable	141.00 FL	*- FL
12	1		*TAILGATE INNER LOCK	Repair	109.40 FL	*- FL
13	1		*TAILAMP LH & RH	O/S Cracked	705.00 FL	*352.50 FL
14	1		*NUMBER PLATE	Serviceable	35.00 FS	*- FS
15	1		*INNER SEAL	Necessary	20.00 FS	*20.00 FS
16	1		*WINDSCREEN SEALANT	Necessary	40.00 FS	*40.00 FS
17	1		*REAR WINDSCREEN SOLAR FILM	Necessary	200.00 FS	*150.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	2,935.50	1,670.30
- List Item Discount on L Items 20.00/20.00% (\$\$)	528.10	292.06
Total Parts (\$\$)	2,407.40	1,378.24

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO DISCONNECT AND CHECK ELECTRICAL WIRING ,WIRE SOCKETS AND ETC .TO REMOVE AND REINSTALL DAMAGED ELECTRICAL UNITS ,TEST AND RECTIFY FOR PROPER FUNCTIONING	New	40.00	20.00
2	TO REMOVE AND REINSTALL /REPLACE FRONT /REAR WINDSCREEN	New	120.00	120.00
3	TO REMOVE AND REINSTALL CUSHIONS ,SEATS ,BACKREST ,INNER TRIM ,GARNISH ,ROOF LINING OR UPHOLSTERY TO FACILITATE REPAIRS	New	80.00	0.00
4	TO DISMANTLE ALL DAMAGED PARTS .TO CUT & WELD .TO KNOCK & REPAIR REAR BUMPER,END PANEL INNER PANELS AND AFFECTED AREAS .TO REFIT LISTED PARTS BACK SAME	New	700.00	200.00
5	TO SPRAY TAILGATE ,REAR BUMPER,END PANEL	New	700.00	250.00
Gross Labour Cost (S\$)			1,640.00	590.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >