

DJS CASE OWNER:

CC 6/MG 1900

1566, Aja39

LKK:
IDAC:

ASSIGNMENT

DOI:

21/1/19

Date / Time:

21/1/19

Registered in Merimen:

23/1/19

Pre-assign / CCU / FTE



Insured Vehicle No.:

SLH 71922

Name of Insured:

HO LMC (OWN, BROWN)

Insured Tel No.:

HP:

Excess Sec II :SS

D.O.A: 18/1/19

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

Driver Tel No.:

(V/L: YES/NO)

Claim No.:

Policy No.:

Make / Model:

Place of Accident:

TPV

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability: % Final ? Yes / No

SYM 1016 L

SLH 71922

SGJ 6762J



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date / Time

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

255-19 301

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice

LTA / GIA :

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost: S\$

days) Reduction:

%

Email

Call

FINAL SETTLEMENT

Date/Time:

Confirm with:

Email

Call

Final Liability:

%

(Agreed / Assessed)

BOLA S/N No.: 28

If NO or B 28, Ass. Lia:

Repair Cost:

S\$

4,387.44

Loss of Rental (LOR):

S\$

-

days)

Loss of Use (LOU):

S\$

366 (560 x 6)

days)

Loss of Income (LOI):

S\$

-

(\$

x

days)

LOR only ☐ LOU only ☐LOR + LOU ☐LOR + LOI ☐

[Tick only one]

GIA/LTA Search

S\$

7.45

Medical:

S\$

-

Disbursement:

S\$

-

Legal Cost

S\$

-

Total:

S\$

4,754.45

Global Sum S\$:

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

S\$

4,754.45

Name 1:

MG SOLUTION PTE LTD

Payee 2: (Strike if N.A.)

S\$

-

Name 2:

-

Payee 3: (Strike if N.A.)

S\$

-

Name 3:

-

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:


Adrian.

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To inspect Vehicle No: _____
 at Workshop m/s _____
 of _____
 Insured: _____
 Policy No: _____
 Claims No: _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
 repair at the time of inspection.



Bal. or Market Value: _____
 IDAC Accident Rpt: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: 4 days Res.: Yes or No
 Lum Sum: _____ % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SG56762J Yr Regn: 2006 July
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or

Make: Toyota AHis cc 1558
 Colour: Black A/C: Insured / Std / Nil / NA
 Sp. Reading: 307695 T/Radio: Insured / Std / Nil / NA
 Eng/No: _____

C/No: MROS3ZEC107127302Gen. Cond: Good / Fair / Poor / BurntSteering: Inorder / Jammed / Leaked / Burnt orBrake: Inorder / Jammed / Leaked / Burnt orModi: Nil / S/Rip / STD A/Rim orTyre Size: F: 185/65R14R: 185/65R14

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 06 mm R/Bal. 06 mmL/Bal. 06 mm L/Bal. 06 mmD.O.A. _____ D.O.I. 21/01/19.Survey held at MG Solution.Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	<u>TP AIG.</u>
	<u>COE Expiry: 30/06/21.</u>
	<u>MV: 16K</u>
	<u>PV: 11.3K</u>
	<u>Nett: 4.7K.</u>
	<u>L/S \$4,100 R(\$3,859.03/48%)</u>

Date/Time, File Pass to?

Date/Time, File Return to?

1) _____
 2) _____
 3) _____
 4) _____
 5) _____
 6) _____
 Prel. Report: _____
 Final Report: _____

Part Prices Check:

IN

OUT

Survey Fee:

Basic & Add.

_ S + RS, _ SI

Photos

Others

TOTAL

Date:

MG SOLUTION PTE LTD

23 Kaki Bukit Avenue 4 (South Wing) #02-03 Singapore 415933

Tel: (+65) 6243 1373 | Fax: (+65) 6243 1376

Reg. No: 201427944N

Email : mg3solution@gmail.com

TO : AIG DATE : 18/01/2019
ATTENTION : MOTOR CLAIMS DEPT JOB TYPE : T/P CLAIM
ESTIMATE REPORT :

VEHICLE DETAILS

VEHICLE NO : SGJ6762J
MODEL : TOYOTA COROLLA ALTIS 1.6 A Joy
CHASSIS NO

ACCIDENT DETAILS DATE : 18-Jan-19
TIME : 07:07HRS

THIRD PARTY REQUESTOR / CONTACT : JACK LI

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	BOOTLID Buckled	1	\$ 847.60	\$ 847.60 ✓
2	BOOTLID LOGO }	1	\$ 54.20	\$ 54.20 ✓
3	BOOTLID '1.6' EMBLEM }	1	\$ 58.00	\$ 58.00 ✓
4	BOOTLID 'E' EMBLEM }	1	\$ 45.50	\$ 45.50 ✓
5	BOOTLID 'WT-I' EMBLEM }	1	\$ 65.40	\$ 65.40 ✓
6	BOOTLID 'COROLLA' EMBLEM }	1	\$ 58.60	\$ 58.60 ✓
7	BOOTLID 'ALTIS' EMBLEM }	1	\$ 65.20	\$ 65.20 ✓
8	BOOTLID TOP LOCK Buckled	1	\$ 124.00	\$ 124.00 ✓
9	BOOTLID LOWER CATCH New	1	\$ 87.00	\$ 87.00 ✓
10	BOOTLID WEATHER STRIP New	1	\$ 157.00	\$ 157.00 ✓
11	REAR BUMPER Deformed	1	\$ 650.20	\$ 650.20 425.90 ✓
12	REAR BUMPER SIDE RETAINER New	2	\$ 62.50	\$ 125.00 64 ✓
13	REAR BUMPER BRACKET Deformed	1	\$ 88.50	\$ 88.50 43.20 ✓
14	TAIL LAMP RH Cracked	2	\$ 467.50	\$ 935.00 579. ✓
15	TAIL LAMP PANEL RH Buckled	1	\$ 581.50	\$ 581.50 381.20 ✓
16	TAIL LAMP LOWER PANEL RH Deformed	2	\$ 95.00	\$ 190.00 95 ✓
17	REAR END PANEL Deformed	1	\$ 768.00	\$ 768.00 ✓
18	REAR END PANEL TOP GARNISH Deformed	1	\$ 146.00	\$ 146.00 ✓

19	REAR FLOOR PANEL TOP BOARD <i>tan</i>	1	\$ 168.00	\$ 168.00	✓
----	---------------------------------------	---	-----------	-----------	---

4145.80
3109.35

TOTAL PRICE \$ 5,214.70
LESS 25% \$ 1,303.68
SUB TOTAL PRICE \$ 3,911.03

SPECIAL NETT ITEMS

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT	
1	REAR NUMBER PLATE <i>gill an</i>	1	\$ 50.00	\$ 50.00	✓
2	BOOTLID SEALANT <i>not an</i>	1	\$ 80.00	\$ 80.00	✓
3	REAR BUMPER CLIPS <i>an</i>	1	\$ 20.00	\$ 20.00	✓
4	TAILLAMP PANEL SEALANT RH <i>2</i>	1	\$ 80.00	\$ 80.00	+
5	TAILLAMP LOWER PANEL RIVET <i>1 an</i>	1	\$ 25.00	\$ 25.00	+
6	TAILLAMP LOWER PANEL SEALANT RH	1	\$ 80.00	\$ 80.00	+
7	REAR END PANEL INSULATION SEAL <i>an</i>	1	\$ 150.00	\$ 150.00	60.
8	REAR END PANEL TOP GARNISH CLIPS <i>an</i>	6	\$ 5.50	\$ 33.00	10
9	REVERSE SENSOR <i>2nd</i>	1	\$ 220.00	\$ 220.00	200.

290

TOTAL \$ 688.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING

1	PANEL BEATING, REMOVING AND REPLACING PARTS	\$ 1,400.00	800	
2	SPRAY PAINTING TO AFFECTED AREA	\$ 1,200.00	800	
3	TUFF COAT	\$ 180.00	60	
4	TO CONDUCT WATER LEAKAGE TEST	\$ 250.00	x	
5	WIRING CHECK	\$ 150.00	30	
6	TRANSFER BOOTLID MECHANISM	\$ 100.00	50	
7	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	\$ 80.00	50	

1790

TOTAL \$3,360.00

ESTIMATE REPORT

TOTAL PARTS COST : \$ 4,599.03

Adrian Lij total 389.35
4/3 21/01/19. 4/5: 4.1K
06 Aug.

TOTAL LABOUR COST : \$ 3,360.00
TOTAL REPAIR COST : \$ 7,959.03

APPROVED DETAILS

SURVEYOR :

CONTACT NO :

FAX :

PART BY PART / LUMP SUM :

NO OF DAYS :

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

> Back to OneMotoring


Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	8414H
Vehicle Details	
Vehicle No.:	SGJ6762J
Vehicle to be Exported:	Yes
Intended Deregistration Date:	22 Jan 2019
Vehicle Make:	TOYOTA
Vehicle Model:	COROLLA ALTIS 1.6 AUTO
Primary Colour:	Silver
Manufacturing Year:	2006
Engine No.:	3ZZ4590599
Chassis No.:	MR053ZEC107127302
Maximum Power Output:	81.0 kW (108 bhp)
Open Market Value:	\$15,950.00
Original Registration Date:	18 Jul 2006
First Registration Date:	18 Jul 2006
Transfer Count:	0
Actual ARF Paid:	\$17,545.00
Intended PARF Vehicle Details	
PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	30 Jun 2021
COE Category:	A - Car (1600cc & below)
COE Period(Years):	5
PQP Paid:	\$23,227.00
COE Rebate Amount:	\$11,329.00
Total Rebate Amount:	\$11,329.00
Remarks	

Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 22 Jan 2019


OK



page 17, column 1



Ken Garage Pte Ltd



Ken Garage Pte Ltd



Fig. 2. 2006 Toyota Corolla, 2006 Toyota Corolla, Toyota Corolla, Toyota Corolla, Toyota Corolla, Corolla, Corolla, Used



End out meet



Tag: 2006 Toyota Corolla, 2006 toyota corolla, Toyota Corolla, toyota corolla, Toyota, Corolla, corolla, Used



Singapore Automobile.com



Hamilton Autohub Pte Ltd



Tags: 2006 Toyota Corolla, 2008 Toyota Corolla, Toyota Corolla, toyota corolla, Toyota Corolla, Corolla, corolla, Used



Tags: 2007 Toyota Corolla, 2007 Toyota corolla, Toyota Corolla, toyota corolla, Toyota, Corolla, corolla, Used



Prem Roy Motorings





MG SOLUTION PTE LTD

23 Kaki Bukit Ave 4, AAS Kaki Bukit Centre #02-03 Singapore 415933

Tel: 6243 1373 Fax: 6243 1376

(GST Reg. No. 201427944N)

Date : 17/04/2019
Your Ref : SLH7192Z
To : **AIG ASIA PACIFIC INSURANCE PTE LTD**
Attn : Motor Claims Department

Dear Sir/Mdm,

**RE: ACCIDENT INVOLVING VEHICLE SGJ6762J & SLH7192Z ON 18/01/2019 AT
ALONG TPE TOWARDS PIE AFTER KPE EXIT.**

We refer to the above matter.

Attached copies of the following for your kind perusal:

- 1) Proforma Bill No.198125 @ S\$4,387.00 (Inclusive Of 7% GST)
- 2) Loss of Use @ S\$1,200.00 (6 Days x S\$200)
- 3) LTA Search @ S\$7.45
- 4) Authorisation to Act
- 5) GIA Report

Hope the above is in order and kindly let us have your confirmation soon.

Tax invoice will be issue upon amount finalized.

Thank You.

Yours faithfully,



Sharon Chia

HP: 9188 6931

E-mail: mg3solution@gmail.com



MG SOLUTION PTE LTD

23 Kaki Bukit Ave 4, AAS Kaki Bukit Centre #02-03 Singapore 415933

Tel: 6243 1373 Fax: 6243 1376

(GST Reg. No. 20-1427944-N)

PROFORMA BILL

Bill To:

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-12 AIG BUILDING

SINGAPORE 079120

Bill No : 198125

Date : 17-April-2019


Vehicle Number : *SGJ 6762J*

ATTN : MOTOR CLAIMS DEPARTMENT

QTY	CLAIM	AMOUNT
1	To carried out accident repair as per surveyor's recommendation (Lump Sum)	\$ 4,100.00
BEFORE GST		4,100.00
7% GST		287.00
TOTAL		\$ 4,387.00

Tax Invoice will be issue upon amount finalised.

Please note that our above offer and any settlement arising from the above offer are made on a without prejudice basis with sole intention of resolving the matter amicably without parties resorting to legal proceeding. Terms of such settlement should also not be disclosed in any other related matter(s) in respect of the accident. No reference shall be made to this offer or any settlement arising from this offer in any other related matters.



Co's stamp & Authorised Signature

MG SOLUTION PTE LTD
23 Kaki Bukit Ave 4 (South Wing) #02-03B
Vicom Inspection Centre, Singapore 415933
Tel: 6243 1373 Fax: 6243 1376
GST Reg. No. : 201427944N

MOTOR CLAIM DISCHARGE

INSURED: TAN CHOON GIM
CAR/LORRY/CYCLE: REG NO: SGJ 6762J POLICY NO: -
ACCIDENT CLAIM NO: -
C
C

I / We confirm that I / we have taken delivery of Car / Lorry / Motor Cycle

Registered No. SGJ 6762J from the repairers,
Messrs MG Solution Pte Ltd
C
C

And that all repairs necessary as a result of an accident in which the said vehicle was Involved on or
about the 18 day of 01 2019 have been completed to my / our satisfaction, and that
I / we have no further claim on the above company in Respect thereof.

Date: Signature: x 
C
C

Co's Stamp: NRIC No:

21/01/2019 - PRI

Vehicle In - 21/01/2019

Vehicle Out - 26/01/2019

LOA - 6 days x \$200
= \$1,200

LETTER OF AUTHORITY

Name : TAN CHOON GIN

Address : BLK 445A FERNVALE ROAD
#26-409 S(791445)

Contact No : _____

TO: ~~ALG~~ ASIA PACIFIC INSURANCE PTE LTD

Dear Sirs,


ACCIDENT INVOLVING SGT 6762J AND SLH 7192Z ON 18/01/2019
AT/ALONG TPE towards PIE after KPE exit

I/We, Tan Choon Gin, am/are the registered owner of
motor car no. SGT 6762J

Please note that I have assigned all compensations monies due to me/us in the above said accident
to **M/S MG SOLUTION PTE LTD.**

I/We, hereby authorize you to release all compensation monies pertaining to the above-mentioned
accident to **M/S MG SOLUTION PTE LTD** and forward your settlement cheque to **M/S MG SOLUTION**
PTE LTD whom I had authorized to collect the said compensation monies.

Thank you



Signature of Claimant



Witness By



Provided always that this discharge of claim for damages relating to the damage to my vehicle shall not prejudice or affect my further claim for general and special damages for my personal injuries sustained in the same accident.

RELEASE VOUCHER
(AIG Asia Pacific – EXPRESS THIRD PARTY CLAIM)

We/I, _____ ("the workshop") hereby confirm that we/I have reached an agreement with the appointed surveyor of AIG Asia Pacific Insurance Pte. Ltd. _____ ("name of surveyor") with respect to the amount claimed for S\$ _____ (repair costs), S\$ _____ (loss of use/rental) S\$ _____ (search fees) for vehicle no. _____ that was damaged pursuant to the accident which occurred on _____ (date) along _____ (location) involving vehicle no/s _____.

This is pursuant to the inspection conducted on _____ (date) at "the workshop".

We/I confirm that we/I are/am authorized by the owner _____ ("third party claimant") of vehicle no. _____ to make the claim as set out in the above paragraph and we/I have full authority to settle the matter on his/her behalf in a manner that we/I deem fit. We/I enclose herein the letter of authority given by "the third party claimant".

We/I further confirm that we/I will indemnify AIG Asia Pacific Insurance Pte. Ltd for all damages, loss and/or expense that they will or have already incurred in the event that "the third party claimant" after the above said agreement lodges a further claim against the former for any loss and expenses suffered pertaining to costs of repairs and/or rental and/or loss of use pursuant to the damage to _____ (vehicle no.) as a result of the accident.

We/I confirm that the agreement reached above is in full and final settlement of any claim of "the third party claimant" pursuant to the accident and that further this settlement is reached on a without prejudice and without admission of liability basis.

This agreement is subject to the application of Singapore law and the Singapore Courts have exclusive jurisdiction over any disputes arising out of the same.

Dated this _____ day of _____ (month) 20____ (year)

Signed by AIG appointed surveyor

Chopped & Signed by "the workshop"





Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 67414108

Our Ref CC6/AIG19001566/Aja3

25 MAY 2019

HO LIK KOON EDWIN (HE LIQUN EDWIN)
BLK 325B SENGKANG EASTWAY
#12-651, SINGAPORE 542325

Dear Sir/Madam,

ACCIDENT INVOLVING SLH 7192Z AND SGJ 6762J ON 18/01/19

We refer to the above accident where we are acting for AIG Asia Pacific Insurance Pte Ltd to resolve the claim against you and/or your authorized driver under the Auto Insurance policy taken up with them.

Based on the accident report and accident scenario, liability is down against us. We will therefore proceed to negotiate for an amicable settlement with the Third Party.

Should you however wish to further discuss on the matter prior to our negotiations and settlement, please contact us within 7 days from the date of this letter.

Please note that your No-Claim Discount (NCD)(if any) will be affected and reduced by 30% (20% for commercial vehicles) upon next renewal due to this Third Party claim. However, if your policy has a NCD protector feature, it will be deemed utilized for this claim and your NCD will be protected.

Please call us if you have further queries.

Yours faithfully,

Joy Irene
Case Handler

DID: 6841 2409

FAX: 6741 4108

Email: joyirene@lkkauto.com

c.c. AIG Asia Pacific Insurance Pte Ltd
(Motor Claims Dept)

Provided always that this discharge of my claim for damages relating to the damage to my vehicle shall not prejudice or affect my further claim for general and special damages for my personal injuries sustained in the same accident.

AUTHORIZATION TO ACT
(AIG Asia Pacific – EXPRESS THIRD PARTY CLAIM)

I, Tan Choon Gin ("the third party claimant")
of BLK 445A Fernvale Road #26-409 S (791445) (address),
owner of SGJ 6762J (vehicle no.) hereby authorize
MG Solution Pte Ltd
("the workshop") to act for me with respect to my claim for repair costs and/or
rental and/or loss of use ("claim") for my vehicle no. SGJ 6762J that was
damaged pursuant to the accident which occurred on 18/01/2019 (date) along
TPE towards PIE after KPE Exit (location)
involving vehicle no/s SLH 7192 Z ("the accident").

I further authorize the workshop to settle the above mentioned claim in a
manner that they deem fit and the workshop is further authorized to receive
payment further to settlement of my claim with payment cheque/s being made in
favour of the workshop.

I further acknowledge that any settlement the workshop may reach on my
behalf is on a without prejudice and without admission of liability basis insofar
as the driver/owner/insurers of the other vehicle/s is concerned.

Date this 18 day of 01 (month) 20 19 (year)

x [Signature]
Signed by "the third party claimant"

[Stamp: MG SOLUTION PTE LTD]
Signed by "the workshop"

RELEASE VOUCHER
(AIG Asia Pacific - Express Third Party Claim)

"We/I, MG SOLUTION PTE LTD ("the workshop") hereby confirm that we/I have reached an agreement with the appointed surveyor of AIG Asia Pacific Insurance Pte Ltd LKK AUTO CONSULTANTS PTE LTD (name of surveyor) with respect to the amount claimed for S\$4,387.00 (Repair Cost), S\$360.00 (Loss of Use/Rental) S\$7.45 (Disbursement) for vehicle no. SGJ 6762J that was damaged pursuant to the accident which occurred on 18/01/2019 (date) along TPE TOWARDS CHANGI (location) involving vehicle no/s SLH 7192Z. This is pursuant to the inspection conducted on 21/01/2019 (date) at "the workshop".

We/I confirm that we/I are/am authorized by the owner TAN CHOON GIN ("the third party claimant") of vehicle no. SGJ 6762J make the claim as set out in the above paragraph and we/I have full authority to settle the matter on his/her behalf in a manner that we/I deem fit. We/I enclose herein the letter of authority given by "the third party claimant".

We/I further confirm that we/I will indemnify AIG Asia Pacific Insurance Pte Ltd for all damages, loss and/or expense that they will or have already incurred in the event that "the third party claimant" after the above said agreement lodges a further claim against the former for any loss and expenses suffered pertaining to costs of repairs and/or rental and/or loss of use pursuant to the damage to SGJ 6762J (vehicle no.) as a result of the accident.

We/I confirm that the agreement reached above is in full and final settlement of any claim of "the third party claimant" pursuant to the accident and that further this settlement is reached on a without prejudice and without admission of liability basis.

This agreement is subject to the application of Singapore law and the Singapore Courts have exclusive jurisdiction over any dispute arising out of the same.

Dated this 10 (day) of 06 (month) **2019** (year)



Signed by appointed surveyor



Signed by "the workshop" (with chop)

*Provided always that this discharge of my claim for damages relating to the damage to my vehicle shall not prejudice or affect my further claim for general and special damages for my personal injuries sustained in the same accident.



MG SOLUTION PTE LTD

23 Kaki Bukit Ave 4, AAS Kaki Bukit Centre #02-03 Singapore 415933

Tel: 6243 1373 Fax: 6243 1376

(GST Reg. No. 20-1427944-N)

TAX INVOICE

Bill To:

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-12 AIG BUILDING

SINGAPORE 079120

INVOICE No : TI 199127

PB No : 198125

Date : 06-June-2019

ATTN : MOTOR CLAIMS DEPARTMENT

Vehicle Number : SGJ 6762J

QTY	DESCRIPTION	AMOUNT
1	To carried out accident repair as per surveyor's recommendation (Lump Sum)	\$ 4,100.00
BEFORE GST		4,100.00
7% GST		287.00
TOTAL		\$ 4,387.00

Cheque should be made payable to MG Solution Pte Ltd



Co's stamp & Authorised Signature



Land Transport Authority
10 Sin Ming Drive
Singapore 575701
GST Registration No. : M4-0006529-2

Print Date/Time : 18 Jan 2019 / 12:09:58

Receipt Date/Time : 18 Jan 2019 / 12:09:58

Tax Invoice/Receipt

Receipt No. : ITNET-00000-190118-001217

Previous Receipt No. :

S/N Item Description/
Business Transaction Reference
No.

Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
-------------------------------	------------------------	------------------------------

Result of Insurance Enquiry - SLH7192Z

As at 18 Jan 2019/07:07:00

Insurance Co: AIG ASIA PACIFIC INSURANCE PTE. LTD.

1 Insurance Enquiry - SLH7192Z

Enquiry Fee

20190118120827476462

7.00	0.49	7.49
------	------	------

Sub-Total	7.00	0.49	7.49
-----------	------	------	------

Total Before Rounding	7.00	0.49	7.49
-----------------------	------	------	------

Rounding Difference			0.04
---------------------	--	--	------

Total Amount Payable			7.45
----------------------	--	--	------

Paid By

20190118120909608	Direct Debit: eNETS Debit (Internet Banking)	7.45
-------------------	---	------

Total		7.45
-------	--	------

Cash Change		0.00
-------------	--	------

Tendered Amount		7.45
-----------------	--	------

Excess Refundable Amount		0.00
--------------------------	--	------

THANK YOU AND HAVE A NICE DAY!

Please ensure that all payments to the Authority are good and promptly settled by the payment service provider / financial institution. Otherwise, the transaction and receipt is considered void and late fee may apply.

...CLAIM SUBFOLDER...(Pending for Survey Report)

Fastlane

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	23 Jan 2019 Edit Reg		21 Jan 2019 00:00 Edit Adj Rpt	S\$4,100.00 Edit Estimates	S\$4,100.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured:	HO LIK KOON, EDWIN (HE LIQUN, EDWIN) , ID: S7440060D								
Main Claimant:	TAN CHOON GIN , ID: S6808414H								
Vehicle Reg. No.:	SGJ6762J	Date of Loss:	18/01/2019 06:00 - :59 [150 Months From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 1890878782SG	Policy/Cover Note No.:	2100491314 (Comprehensive)						
Vehicle Reg. No. (Insured):	SLH7192Z	Policy No. (Claimant):	10680409						
		Excess:							
Repairer:	MG Solution Pte Ltd (HQ) 23 Kaki Bukit Avenue 4 #02-03B, VICOM Inspection Centre, 415933 Kaki Bukit - Tel: 91886931								
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by MdNoor, Norsiah] Norsiah.MdNoor@aig.com								
Claimant's Insurer:	Aviva Ltd (HQ) - Tel: (65) 6827 9966								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ADRIAN LING] ... [Final Rpt due 01/02/2019]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
<ul style="list-style-type: none"> AIG_SG (24/01/2019): Request to upload TP GIA Report 									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SGJ6762J (1890878782SG)
[SLH7192Z]

TP

TAN CHOON GIN

Jan 18 2019 6:00AM

[HO LIK KOON, EDWIN (HE LIQUN, EDWIN)]
MG Solution Pte Ltd

Upload Documents			Upload Photos			Compose New Letter			Upload Video			Upload Audio			View			View in Browser		
Letters/Correspondences															1 per page			<input checked="" type="checkbox"/>		
No	Finalized On		LKK Auto Consultants Pte Ltd (HQ)												Thumbnail			Print		
1	(Draft)		Third Party Express Settlement – Payment Breakdown															Edit		
Photos/Images															3 per page			<input checked="" type="checkbox"/>		
No	Relabel/Reorder		LKK Auto Consultants Pte Ltd (HQ)												Thumbnail			Print		
1	10/04/19 00:18		General View															Load JPG <input checked="" type="checkbox"/>		
2	10/04/19 00:18		General View															Load JPG <input checked="" type="checkbox"/>		
3	10/04/19 00:18		General View															Load JPG <input checked="" type="checkbox"/>		
4	10/04/19 00:18		General View															Load JPG <input checked="" type="checkbox"/>		
5	10/04/19 00:18		General View															Load JPG <input checked="" type="checkbox"/>		
6	10/04/19 00:18		General View															Load JPG <input checked="" type="checkbox"/>		
7	10/04/19 00:18		General View															Load JPG <input checked="" type="checkbox"/>		
8	10/04/19 00:18		General View															Load JPG <input checked="" type="checkbox"/>		
9	10/04/19 00:18		General View															Load JPG <input checked="" type="checkbox"/>		
10	10/04/19 00:18		General View															Load JPG <input checked="" type="checkbox"/>		
11	10/04/19 00:18		General View															Load JPG <input checked="" type="checkbox"/>		
12	10/04/19 00:18		General View															Load JPG <input checked="" type="checkbox"/>		
13	10/04/19 00:18		General View															Load JPG <input checked="" type="checkbox"/>		
14	10/04/19 00:18		General View															Load JPG <input checked="" type="checkbox"/>		
15	10/04/19 00:18		General View															Load JPG <input checked="" type="checkbox"/>		
16	10/04/19 00:18		General View															Load JPG <input checked="" type="checkbox"/>		
17	10/04/19 00:18		General View															Load JPG <input checked="" type="checkbox"/>		
18	10/04/19 00:18		General View															Load JPG <input checked="" type="checkbox"/>		
19	10/04/19 00:18		General View															Load JPG <input checked="" type="checkbox"/>		
20	10/04/19 00:18		General View															Load JPG <input checked="" type="checkbox"/>		
21	10/04/19 00:18		General View															Load JPG <input checked="" type="checkbox"/>		
22	10/04/19 00:18		General View															Load JPG <input checked="" type="checkbox"/>		
23	10/04/19 00:18		General View															Load JPG <input checked="" type="checkbox"/>		
24	10/04/19 00:18		General View															Load JPG <input checked="" type="checkbox"/>		
25	10/04/19 00:18		Reinspection Photo															Load JPG <input checked="" type="checkbox"/>		
26	10/04/19 00:18		Reinspection Photo															Load JPG <input checked="" type="checkbox"/>		
27	10/04/19 00:18		Reinspection Photo															Load JPG <input checked="" type="checkbox"/>		
28	10/04/19 00:18		Reinspection Photo															Load JPG <input checked="" type="checkbox"/>		
29	10/04/19 00:18		Reinspection Photo															Load JPG <input checked="" type="checkbox"/>		
30	10/04/19 00:18		Reinspection Photo															Load JPG <input checked="" type="checkbox"/>		
31	10/04/19 00:18		Reinspection Photo															Load JPG <input checked="" type="checkbox"/>		
32	10/04/19 00:18		Reinspection Photo															Load JPG <input checked="" type="checkbox"/>		
33	10/04/19 00:18		Reinspection Photo															Load JPG <input checked="" type="checkbox"/>		
34	10/04/19 00:18		Reinspection Photo															Load JPG <input checked="" type="checkbox"/>		

Letters/Correspondences			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
				<input checked="" type="checkbox"/>
35	10/04/19 00:18	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
36	10/04/19 00:18	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
37	10/04/19 00:18	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
38	10/04/19 00:18	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
39	10/04/19 00:18	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
40	10/04/19 00:18	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
41	10/04/19 00:18	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
42	10/04/19 00:18	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
43	10/04/19 00:18	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
44	10/04/19 00:18	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
45	10/04/19 00:18	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
46	10/04/19 00:18	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
47	10/04/19 00:18	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
48	10/04/19 00:18	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	24/01/19 09:55	TP GIA REPORT	Load PDF	
2	19/06/19 09:15	WORKSHOP INVOICE	Load PDF	
3	19/06/19 09:15	AUTHORISATION TO ACT FORM	Load PDF	
4	19/06/19 09:15	Release Voucher	Load PDF	
5	19/06/19 09:15	LTA SEARCH	Load PDF	
6	19/06/19 09:15	LETTER TO OI	Load PDF	
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	24/01/19 08:53	OI GIA REPORT	Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 100px; width: 100%;"></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SLH7192Z (Insd veh)	Model:	TOYOTA COROLLA ALTIS
	SGJ6762J (TP veh)		1.6 (A)
Date of Accident:	18/01/2019		

Global Sum Settlement	:	<input type="checkbox"/> Yes	<input checked="" type="checkbox"/> No	
Repair Estimate	: \$	8,569.65		
Final Repair Cost	: \$	4,387.00		
Loss of Use	: \$	360.00		
		6.00 days at \$60.00 per day		
Rental (if any)	: \$	0.00		
		days		
LTA / GIA Search Fee	: \$	7.45		
Others:	: \$	0.00		
	: \$			
Final Settlement Sum	: \$	4,754.45		

Is Third Party Workshop GIA Registered? ☐ YES ☒ NO (Kindly indicate below)

A) For Non GIA Registered Workshop: Agreed Liability ____ 100 ____ (%)

B) For GIA Registered Workshop: BOLA Applicable: Yes/ No BOLA Scenario No: ____

BOLA Liability: ____ (%) Assessed Liability (*): ____ 0 ____ (%)

** Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.*

Remarks _____

Payment Instruction: Payee's Breakdown			
1)	MG Solution Pte Ltd	: \$	4,754.45
2)		: \$	
3)		: \$	

JOANNE LEE KHANG MIN

19 Jun
2019

LKK Auto Consultants Pte Ltd

Date

Please attach all the supporting documents to the form.
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG19001566/AJA3Q2

Date: 19/06/2019

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100491314
 Claimant Vehicle No: SGJ6762J Insured Vehicle No: SLH7192Z
 Date of Loss: 18/01/2019 Nature of Claim: TP Claim No: 1890878782SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SGJ6762J**
 Make & Model: TOYOTA COROLLA ALTIS, 1.6 (A) Engine No: 3ZZ4590599
 Reg. Date: 18/07/2006 (Man. Year: 2006) Chassis No: MR053ZEC107127302
 Colour: Black Odometer: 307695 km
 Engine Capacity: 1598 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 185/65 R14 Rear Tyre Size: 185/65 R14
 Front Left Side: Toyo 6 mm Rear Left Side: Toyo 6 mm
 Front Right Side: Toyo 6 mm Rear Right Side: Toyo 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,649.02	3,399.35	1,249.67	26.88
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,360.00	1,790.00	1,570.00	46.73
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	8,009.02	5,189.35	2,819.67	35.21
Approved Total (Overridden) (S\$)		4,100.00		
(S\$)	8,009.02	4,100.00	3,909.02	48.81
+ GST 7.00/7.00% (S\$)	560.63	287.00	273.63	48.81
Nett Amount (S\$)	8,569.65	4,387.00	4,182.65	48.81
+ Loss of Use (6.0 x S\$60.00/day) (S\$)		360.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		4,754.45		

INSPECTION

Date of Assignment: 21/01/2019
 Date Inspected: 21/01/2019 Inspected At: MG Solution Pte Ltd (HQ)
 23 Kaki Bukit Avenue 4 #02-03B, VICOM

Inspection Centre
Singapore 415933

Estimated Period of Repair: 6.0 days

Adjuster: ADRIAN LING

Manager: Joy Irene Bascao

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOOTLID	Buckled	847.60 FL	*847.60 FL
2	1		*BOOTLID LOGO	Necessary	54.20 FL	*54.20 FL
3	1		*BOOTLID 1.6 EMBLEM	Necessary	58.00 FL	*58.00 FL
4	1		*BOOTLID E EMBLEM	Necessary	45.50 FL	*45.50 FL
5	1		*BOOTLID WT-I EMBLEM	Necessary	65.40 FL	*65.40 FL
6	1		*BOOTLID COROLLA EMBLEM	Necessary	58.60 FL	*58.60 FL
7	1		*BOOTLID ALTIS EMBLEM	Necessary	65.20 FL	*65.20 FL
8	1		*BOOTLID TOP LOCK	Damaged	124.00 FL	*124.00 FL
9	1		*BOOTLID LOWER CATCH	Not Necessary	87.00 FL	*- FL
10	1		*BOOTLID WEATHER STRIP	Cut	157.00 FL	*157.00 FL
11	1		*REAR BUMPER	Deformed	650.20 FL	*425.90 FL
12	2		*REAR BUMPER SIDE RETAINER	Necessary	125.00 FL	*64.00 FL
13	1		*REAR BUMPER BRACKET	Dented	88.50 FL	*43.20 FL
14	2		*TAIL LAMP	Cracked	935.00 FL	*579.00 FL
15	1		*TAILLAMP PANEL RH	Buckled	581.50 FL	*381.20 FL
16	2		*TAILLAMP LOWER PANEL RH	Dented (1 PCS ONLY)	190.00 FL	*95.00 FL
17	1		*REAR END PANEL	Dented	768.00 FL	*768.00 FL
18	1		*REAR END PANEL TOP GARNISH	Deformed	146.00 FL	*146.00 FL
19	1		*REAR FLOOR PANEL TOP BOARD	Torn	168.00 FL	*168.00 FL
20	1		*REAR NUMBER PLATE	Not Necessary	50.00 FS	*- FS
21	1		*BOOTLID SEALANT	Not Necessary	80.00 FS	*- FS
22	1		*REAR BUMPER CLIPS	Necessary	20.00 FS	*20.00 FS
23	1		*TAILLAMP PANEL SEALANT RH	Not Necessary	80.00 FS	*- FS
24	1		*TAILLAMP LOWER PANEL RIVET	Not Necessary	25.00 FS	*- FS
25	1		*TAILLAMP LOWER PANEL SEALANT RH	Not Necessary	80.00 FS	*- FS
26	1		*REAR END PANEL INSULATION SEAL	Necessary	150.00 FS	*60.00 FS
27	1		*REAR END PANEL TOP GARNISH CLIPS (6PCS)	Necessary	33.00 FS	*10.00 FS
28	1		*REVERSE SENSOR	Damaged	220.00 FS	*200.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	5,952.70	4,435.80
- List Item Discount on L Items 25.00/25.00% (\$\$)	1,303.68	1,036.45
Total Parts (\$\$)	4,649.02	3,399.35

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING ,REMOVING AND REPLACING PARTS	New	1,400.00	800.00
2	SPRAY PAINTING TO AFFECTED AREA	New	1,200.00	800.00
3	TUFF COAT	New	180.00	60.00
4	TO CONDUCT WATER LEAKAGE TEST	New	250.00	0.00
5	WIRING CHECK	New	150.00	30.00
6	TRANFER BOOTLID MECHANISM	New	100.00	50.00
7	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	New	80.00	50.00
Gross Labour Cost (\$\$)			3,360.00	1,790.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >