

REF: CS3/ASM1900021/Bsd3-1

From (Person): Xin Yi of Seahong Date/Time: 23/1/19 @ 10:48am
Estimated Cost: _____

L/S: \$ 17,100.00

ASSIGNMENT OBJECTS

Total Factor

Cluster

Surveyors: SCL Appraiser Plc Ltd

Workshop: Motor Intel

OD/TP Re-inspection / Evaluation

To inspect Vehicle No: SKH 763B Insured: XF 1931X

at Workshop m/s Motor Intel Tel: 88383318

13 kaki Bukit Road 4 #01-20

Policy No. _____ Claim No. 19. 26242 PD-0

Site Number: _____

Make of Veh: _____ D.O.B. 26/12/2018

Client's Record

Date/Time: _____ Person Contacted: _____ Vehicle IN / OUT _____

Date/Time: Confirmed with Final Fig days (Red S / %; Original 12 days)

Date/Time: 14/03/19 Submit Final Fig 88,250/-, 6 days (Red S 88,250/- 52 %; Original 12 days)

Date/Time	Action/Instruction
-----------	--------------------

SK117R38-ES3/ASMIN000021/Rcho2

DATE: 26/12/2018

XF 1431 X - CS3/ASM 19000121 / Bcbx2

Date: 26/12/2018

Para(1) : Parts found not replaced (To highlight R or UB, LR, Etc)

Para(2) : Comments on consistency of damages (Parts Not Consistent : NC)
--

RECEIVED 14 MAR 2019

Para(3) : Nett Value

Market Value :

Salvage Value: _____

Nett Value :

Inspected/
Evaluated by:

Fee Charged:

Basic & Add

Transport

Photos

Others

Total

Date: _____

190

150

1) Date/Time _____ File Pass to _____

2) Date/Time _____ File Return to _____

3) Date/Time _____ File Pass to _____

4) Date/Time _____ File Return to _____

5) Date/Time _____ File Pass to _____

6) Date/Time _____ File Return to _____

227002/2019

ASS. REC. BY:

REF: CS3/ASM19000021/Bche2

Special Instruction:

Survivor:

Mr. Lim

ASSIGNMENT (Office)

Smart claim

From (Person):

Owen Kingan

of

AEM

Date/Time: 02012019 1043am

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SKH 783B

Insured:

XE 1931X

nt Workshop m/s

Major Intelligence

Tel:

of

13 Kaki Bukit Rd 4 #01-20

Policy No:

Claim No:

S8M0182W

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 26.12.2018

CA / REV / REP. / REV 24 HRS 'wp'

H.O.D. Endorsement:

Date/Time: 02012019 1043am

Person Contacted:

Wilson

Vehicle IN / OUT

Date/Time	Action/Instruction (X) Estimate
	SKH 783B - CTE/NUH15002139/Apo3g1
	XE 1931X - X
	Dismantle: 3/1/2019.

DA 030215

PRS

REF: ASM(AXA)

Smart claim

ASSIGNMENT

From:

Date: 02/01/2019

Estimated Cost:

OD / TI / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

SKH 783B

at Workshop mis

Motor Intelligence

of

13 Kaki Bukit Rd 4 #01-20

Insured:

Bartley Biz Centre

Policy No:

Claims No:

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

6

days

Res:

Yes or No

Lum Sum:

%

3 Val:

Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SKH 783B

Yr Regn:

1/11/2012

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

MERCEDES BEAZ

C.C 1796

Colour:

GREY

A/C

Insured / Std / NI / NA

Sp. Reading:

185643

T/Radio:

Insured / Std / NI / NA

Eng/No:

27186030471274

C/No:

WDD2120472A639759

Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: Nil / SRim / STD A/Rim or

Tyre Size:

F: 245/40/18

R: 265/35/18

DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal:

6

mm

R/Bal:

6

mm

L/Bal:

6

mm

L/Bal:

6

mm

D.O.A:

26/12/2018

D.O.I:

2/1/19 @ 07:15pm

Survey held at

Motor Intelligence

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Range 8,000/- - 9,000/-

MV 77,000/-

PV 66,745/-

NV 10,255/-

3/1/2019

Tee Luv

Date/Time, File Pass to?

☐

Prel. Report

1)

☐

Final Report

Date/Time, File Return to?

2)

Days Of Repair:

6

Resurvey No. of Trip:

1

Survey Fee:

100

Transportation:

) S + RS. \$1

) Fees

) Fees

) Fees

TOTAL

100

Report Format :

PRS

Lump Sum / I.B.I. (\$))

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Insp (\$

☐

Weekend (\$

Nivitha (LKK Auto)

From: Xin Yi <xinyi@seahong.com.sg>
Sent: Wednesday, 23 January 2019 10:48 AM
To: 'Admin-D (LKKAuto)'
Cc: 'Chee Kiong'; samson@seahong.com.sg; amanda@seahong.com.sg; sharon@seahong.com.sg
Subject: SKH 783B [Our file ref: 19.26242 PD-O]
Attachments: TPPD Litigation LOD TAN SWEE KANG.pdf; XE1931X INSD GIA.PDF; SKH783B TP GIA.PDF

Dear Catherine,

CLAIMANT :	TAN SWEE KANG @ TAN SWEE KAY
VEHICLE NUMBER :	SKH 783B
ALLEGED ACCIDENT DATE :	26 DECEMBER 2018
AXA VEHICLE NUMBER :	XE 1931X

We act for AXA Insurance Pte Ltd for the above matter.

We understand that you were engaged to survey the claimant's vehicle.

The claimant has issued their LOD and their surveyor's report is attached. A copy is enclosed.

Please let us hear from you on the following; -

- a. If you have conducted post-repair inspection already, please let us have your survey report urgently.
- b. If you have not conducted post-repair inspection, please let us arrange for inspection with the claimant's solicitor and let us have your survey report in due course.

May we hear from you on the above soonest.

Thanks & Best Regards

Heng Xinyi

(Secretary to Mr Tan Chee Kiong)

Seah Ong & Partners LLP

36 Robinson Road

#12-03 City House

Singapore 068877

Tel: 6536 5369

Fax: 6536 5811

This message is intended for the recipient named above. It may contain confidential or privileged information. If you are not the intended recipient, please notify the sender immediately by replying to this message and then delete it from your system. Do not read, copy, use or circulate this communication. Thank you.

Disclaimer: Internet communications are not secure. While every reasonable effort has been made to ensure that this communication has not been tampered with, Seah Ong & Partners LLP cannot be responsible for alterations made to the contents of this message without its express consent. If you wish to receive a hard copy of this message for comparison or should you require any other form of confirmation of the contents of this message, please contact the sender. Opinions, conclusions and other information in this message that do not relate to the official business of the company shall be understood as neither given nor endorsed by Seah Ong & Partners LLP.

PDX Intercompany Exchange Pte Ltd



010808613386
FROM Allister Lim & Thrumurgan
PDX Box No. 8144

AL&T
ADVOCATES AND SOLICITORS

Your Ref: XE 1931 X
Our Ref: AL.INS.2019.13055(PDPI).jw

60130579

16 January 2019

WITHOUT PREJUDICE

AXA INSURANCE PTE LTD

8 Shenton Way
#24-01 AXA Tower
Singapore 068811
Attention: Motor Claims Department



CHUAN LIM CONSTRUCTION PTE LTD
20 Senoko Drive
Singapore 758207

NATARAJAN PRABU
c/o CHUAN LIM CONSTRUCTION PTE LTD
20 Senoko Drive
Singapore 758207

CERTIFICATE OF POSTING



Dear Sirs,

CLAIMANT: TAN SWEE KANG @ TAN SWEE KAY
ACCIDENT INVOLVING SKH 783 B & XE 1931 X ALONG PIE TOWARDS TUAS
(BEFORE TOA PAYOH EXIT) ON 26 DECEMBER 2018 AT ABOUT 1430 HOURS

We act for **TAN SWEE KANG @ TAN SWEE KAY**, who was the owner of motor vehicle no. **SKH 783 B**.

We are instructed by the above named to claim damages against you/your insured in connection with a road traffic accident **ALONG PIE TOWARDS TUAS (BEFORE TOA PAYOH EXIT)** involving our client's vehicle registration number **SKH 783 B** and vehicle registration number **XE 1931 X** driven by your insured/you at the material time.

We are instructed that the accident was caused by your insured's/your negligence in the driving and/or management of your insured's/your vehicle. As a result of the accident, our client's vehicle was damaged and our client has been put to loss and expense, particulars of which are as follows: -

01. Cost of Repair	\$18,297.00
02. Pre-repair inspection days (\$150 x 2days)	\$ 300.00
03. Loss of Rental	\$ 2,520.00
03. Survey report fees	\$ 986.00
04. LTA search fees	\$ 36.49
05. Cost Contribution (at this stage) (inclusive of GST)	\$ 1,070.00
06. Incidentals (at this stage) (inclusive of GST)	\$ 107.00
	<u>\$23,316.49</u>

ALLISTER LIM & THRUMURGAN

111 North Bridge Road, #11-04 Peninsula Plaza, Singapore 179098 UEN & GST Reg. No.: 53130941W
Tel: 6438 3303 Fax: 6438 1211 (Not for service of court documents) Email: mail@alt.sg

We enclose herewith copies of all the supporting documents as follows: -

- (a) GIA report lodged by driver of motor vehicle SKH 783 B / XE 1931 X;
- (b) LTA Search of motor vehicle no. XE 1931 X;
- (c) Certificate of insurance;
- (d) Rental Invoice and agreement;
- (e) Surveyor's invoice & report with photographs depicting the damages to motor vehicle SKH 783 B.

The demand herein is in respect of our client's claim for damages pertaining to his motor vehicle and any settlement following or subsequent to this demand shall not prejudice our client's claim in respect of damages and consequential loss in relation to his personal injuries.

Please also note that if you are insured and you wish to claim under your insurance policy, you should immediately pass this letter and all the enclosed documents to your insurer.

Please note that you or your insurer should send to us an acknowledgement of receipt of this letter within 14 days of your receipt of this letter, failing which our client will have no alternative but to commence proceedings against you without further notice to you or your insurer. Our client's claim herein is quantified based on supporting documents in our file. Until a settlement is reached, all negotiations are conducted on the basis that the damages quantified herein are subject to revision if so instructed by our client.

Please also note that if you have a counterclaim against our client arising out of the accident, you are also required to send to us a letter giving full particulars of the counterclaim together with all relevant supporting documents within 8 weeks of your receipt of this letter.

Please note that this demand is made without prejudice to our client's right to claim for personal injury damages arising out of the same accident.

Yours faithfully



ALLISTER LIM

encls

Enquire Vehicle & Owner Information (Vehicle No. XE1931X As At 26 Dec 2018 / 14:30:00)**Law Firm Search Details**

Search Reason: Insurance claim in relation to traffic accident
Law Firm Case No.: ALINS.2018.5KH783B

Current Owner Details

Owner ID Type: Company
Owner ID: 199600684W
Owner Name: CHUAN LIM CONSTRUCTION PTE LTD
Registered Address Type: Private Residential (Condo Apt or House) / Shopping / Office Complexes
Registered Block/House No.: 20
Registered Street Name: SENOKO DRIVE
Registered Unit No.: -
Registered Building Name: -
Registered Postal Code: 758207

Current Vehicle Details

Vehicle No.: XE1931X
Make Description/Model: SCANIA / P360CB6X4MHZ
Insurance Company Name: AXA INSURANCE PTE LTD



Thank you

Lim Wee Sing Allister has successfully logged out.
Your last login date and time was 27 Dec 2018, 12:55:35.

To return to ONE.MOTORING, please click [here](#)

For security reasons, please **CLEAR YOUR CACHE** after each session.

Session Transaction History

LN#	Asset Type	Asset ID	Asset Owner ID	Transaction Type	Transac
1	Vehicle	XE1931X		18.19 Enquire Veh Owner Info (Others) by Law Firm	7.49



**GENERAL INSURANCE ASSOCIATION OF SINGAPORE
RECORDS MANAGEMENT CENTRE**

8 Raffles Quay #18-00, Singapore 048580
Phone: +65 6224 0010 Fax: +65 6224 0030
Operating Hours: Monday to Friday 9am to 5pm
GST Registration No: M400017735

TAX INVOICE

Our Ref No: GR-19-009034

Date of Request: 16/01/2019

Your Ref No: ALINS.2019.13055(PDP1)JW

ALLISTER LIM & THIRUMURUGAN
111 North Bridge Road #11-04
Peninsula Plaza
Singapore 179098

Dear Sir/Madam,

Date of Accident: 26/12/2018

Vehicle No: SKH783B

Place of Accident: PIE TOWARDS TUAS (BEFORE TOA PAYOH EXIT)

Involving Vehicle No: XE1931X

With reference to your application for the accident report, we have attached the following accident reports as requested:

DOCUMENTS	ACCIDENT LOCATION	PER DOC (S\$)	QTY	AMOUNT (S\$)
XE1931X	PIE TOWARDS TUAS (BEFORE TOA PAYOH EXIT)	14.00	1	13.08
GST Amount				0.92
Total Amount Due (GST Inclusive)				14.00

The images provided to you are taken from the original reports forwarded to the centre by the members of the General Insurance Association of Singapore and we take no responsibility for their accuracy or contents and shall be under no liability whatsoever for any loss or damage arising out of or in connection with the reports or their images.

Thank You,

This is a computer generated document and requires no signature.

For GIARMC Official use:

Date:

☒ GIRO ☐ Cash ☐ Cheque

高GAO

Express Towing Services



5:30 PM

You Call, We Tow - Fast . Secured . Reliable

Blk 27 Marine Crescent Villes 10-01 Singapore 440027 Co. Reg. No. 53152603L HP: 900 900 92 Email: jim.koh@hotmail.com Website: <http://www.gaoexpress towing.sg>

CASH SALE/WORK ORDER

No. 156699

Date: 26-12-18

寶號

Messrs: INDL Cash

車號

Vehicle No SKH 783B 車型 Model No: E 250

時間(日/夜)

Time (day/night): Contact No:

由

Location: Tan Payah Stadium

到

To: INDL

Cash \$: 100 其他 Others:

經手人

Authorised By: Jim Tow Truck Driver Name: 9983 rookly

注意本公司對所拖之車輛,在進行中如有任何損失或破壞,一概由車主自行負責。
Note: Vehicle is towed at owner's risk. The company accepts no responsibility for damages or other misdemeanour to your vehicle whilst being towed.

- ☐ Jump Start/Changing of battery
- ☐ Tyre Replacement
- ☐ Accident/Breakdown
- ☐ Multi/Basement
- ☐ With Load/Cargo Box
- ☐ King Dolly
- ☐ Transport Charge
- ☐ Low Body Kit
- ☐ Door Opening Service
- ☐ Crane Up/Winch Out
- ☐ Collect Doc/Key
- ☐ Repo
- ☐ Woodlands and Tuas Checkpoint

ST

Address: 394 Yishun Avenue 6 #02-1090

Mobile: 90252583

Website: WWW.FB.COM/SECARRENTAL

Email: se.carrental@yahoo.com

Bill To: TAN SWEE KANG

Mobile: NIL

Invoice #: A107

Address: 15 WOO MON CHEW ROAD

Fax: NIL

Invoice Date: 10/1/2019

Email: NTL

Owner Vehicle: SKH783 B

Invoice For: RA No.107

Item #	Model	Vehicle No.	Rental Rate DAILY	From	To	Subtotal
1	TOYOTA CAMRY	SLU8175B	\$ 180.00	26/12/2018	9/1/2019	\$ 2,520.00
					TOTAL:	\$ 2,520.00

SE CAR RENTAL:



Signature & Company Stamp

Make all checks payable to SE CAR RENTAL.

SE CAR RENTAL

394 Yishun Avenue 6 #02-1090 S(760394)

Tel: 9025 2583 Fax: 6841 3390

RA No: 0107

VEHICLE HIRING AGREEMENT

Workshop: MIA

HIRER'S PARTICULARS

Name (as in IC): Tan Swee Kang
 NRIC/Passport No: S1844528 Z Date of Birth: 03-12-1946
 Address: 15, Woo Man Chew Rd Age: 58
 S(15)
 Name & Address of Employer: 455066
 Occupation: _____ Driving Exp: _____
 Driving Licence No: _____ Passed Date: _____
 D/L Type: Local/Int/Other: _____
 Tel(O): _____ (R): _____ HP: _____

DRIVER'S PARTICULARS

Name (as in IC): Lim Chee Son
 NRIC/Passport No: S1819437 F Date of Birth: 25-2-1946
 Address: 15, Woo Man Chew Rd Age: 58
 S(15)
 Occupation: _____ Driving Exp: _____ Yrs
 Driving Licence No: _____ Passed/Expiry Date: 20-1-1970
 D/L Type: Local/Int/Other: _____ Contact No: _____


Hirer's Own Vehicle No: SKH783 Replace Veh No: SL481578
 Loan Vehicle No: SLU 8175 B VR No: _____
 Make & Model: T Camry 2.5 A Auto/Manual Group: _____
CHARGES S cts
 Daily 14 day @ \$ 180/- Per day 2520/-
 Weekly/Monthly week @ \$ _____ Per week/Monthly _____
 Others _____
 CDW/PAI @ \$ _____ Per day/Monthly _____
 Delivery/Collection Svc _____
 GST _____
 OR No: _____ (A) SUB-TOTAL 2520/-
 Petrol Level: OUT E 1.6 1.2 0.8 F
 Surcharge IN _____
 First _____ km FREE per day GST _____
 Excess mileage is chargeable at _____ cents per km TOTAL CHARGES 2520/-

Security Deposit: \$ _____ Bank: _____
 CASH/NETS/VISA/MC/AMEX/CHQ No: _____
 Expiry Date: _____ Card ID No: _____
 Name as in Card: _____

NON WAIVER EXCESS (Subject to GST): \$ _____
ACCESSORIES CHECK
☐ IU ☐ STD Tools ☐ Hub Cap ☐ Radio / CD Cartridge
☐ Jack ☐ Tyre Opener ☐ Petrol Cap ☐ Spare Tyre

Hirer's Signature: _____ Additional Driver's Signature: _____

SINGAPORE Use Only



I have read and agree to the terms and condition on both sides of this agreement. If I have presented a charge/credit card for payment, I agree that all amounts payable under this agreement and for parking and traffic infringements may be billed to that account and my signature above will be considered to have been made on the charge/credit card voucher. All information I have been given SE CAR RENTAL in connection with this agreement is true.

IMPORTANT

- The Hirer and the authorized driver must be over 23 years of age and under 55 years and be holding valid driving licenses and have a minimum of 2 years regular and qualified driving experience. Failure to observe stipulation may return all damages costs to be borne by the Hirer/the Authorized Driver.
- All vehicles are supplied with petrol and should be returned with petrol level likewise. A service charge of \$5 on top of a petrol surcharge is payable by the hirer should he fail to return the vehicle at the appropriate petrol level.
- No refund for early return of vehicle. The hirer shall be liable for additional charges for any late return at the rate shown per hour per day, inclusive of CDW and/or PAI where applicable. Any returns after our operation hours will be charged as a full day rental.
- Use of the vehicle for illegal purpose (For instance: in connection with theft, drug peddling or trafficking, smuggling), is strictly prohibited.
- Vehicle strictly for Singapore use only and may not be driven out of Singapore without prior written consent of SE CAR RENTAL. The hirer is liable for a penalty fee of \$200 in addition to the appropriate insurance top up in the case of non-disclosure of Malaysia usage.
- The hirer and/or driver shall be responsible for all damages or losses howsoever caused, all traffic violations, fines and penalties imposed on the vehicle for whatsoever reason in respect of or in connection with its use or operation.
- The hirer and/or driver shall be responsible for all claims, damages, losses, increased insurance premiums, non-waiver excess and cost expense (including

- legal costs on a full indemnity basis), whatsoever and howsoever brought against, suffered or incurred by you in respect of the vehicle or the use or the operation of the vehicle. Full excess amount have to be paid immediately in the event of an accident. The owner reserve the right not to replace a replacement vehicle if an accident occurred. Any damage to the car will be repair at our authorized workshop.
- Smoke or permit smoking and transport of pets in the vehicle are not allowed. Any offensive smell e.g. cigarette, durian or pet's smell, the hirer and/or driver shall bear the cost of removing the offensive smell or pet's fair between \$200 - \$400.
- The Hirer agrees that a punctured tyre, empty petrol tank, loss of vehicle's key or locked keys inside of vehicle, by itself, does not constitute a breakdown and that in the event the owner's 24-Hours Emergency Service is called upon to respond to such occurrence, the Hirer shall bear the cost of such response at \$50.00 per trip.
- In case of accident, the hirer shall report to rental office immediately. An accident report must be made within 24 hours. Failure to comply, the hirer will have to borne all liability from all parties claim. Full excess amount have to be paid immediately in the event of an accident.
- The hirer/Driver also have the responsibility to ensure that the radiator water level in the car is sufficient and do not drive when the vehicle is stalled and does not have sufficient water. Any damage to the engine will be bear by the hirer/driver.
- All customers' data will be kept strictly confidential and is solely used for the purpose of completing the sales transactions and other relating matters.
- I understand and agree to the personal data collection statement.

Date Out	Time Out	Mileage	Check By	Remarks
26/12/2018	1645 Hrs			

Return Of Vehicle: The Hirer Driver is Required To Sign In The Column "Signature Of Hirer Driver Failing Which The Day And Time Inserted Below Shall Be Deemed To Be The Day And Time The Vehicle is Returned To SE CAR RENTAL And The Same Shall Be Accepted As Conclusive Evidence Of The Same And Shall Not Be Challenged Or Questioned On Any Account Whatsoever. And I had cleared my belonging items from the rental vehicle (cashcard, parking coupons, etc)"


Date In	Time In	Mileage	Check By	Remarks
09/01/2019	2130 Hrs			

Hirer's/Driver Signature

Hirer's/Driver Signature



Motor Intel Automo Pte. Ltd.
Regn & GST No. : 201732961N
Bartley Biz Centre, 13 Kaki Bukit Road 4, #01-20
Singapore 417807
Phone: 6281 0087/Fax: 6281 0187/Mobile: 9150 1587
Email: sales@mia.com.sg

Customer: TAN SWEE KANG C/O MOTOR INTEL AUTOMO PTE LTD			Tax Invoice No: PERFORMA INVOICE		Date: 11/Jan/2019	
Contact Details: 15 WOO MON CHEW ROAD SINGAPORE 455066			Make and Model: MERCEDEA BENZ E250		Mode/Terms of Payment: Due upon receipt	
			Mileage: 185643		Chasis/Car Plate No: SKH 783 B WDD2120472A639759	
S/No:	Product	Description	Qty	Unit	Priced (SGD)	Amount (SGD)
1	COST OF REPAIR	LUMP SUM REPAIR OF ACCIDENT PORTION	1	JOB	17100.00	17100.00
					Sub Total (SGD)	17100.00
					GST 7%	1197.00
					Total (SGD)	18297.00
Amount in words: DOLLARS EIGHTEEN THOUSAND TWO HUNDRED AND NINETY SEVEN ONLY.						
Declaration: We declare that this Tax Invoice shows the actual price of the goods described and that all particulars are true and correct.			<div>For Motor Intel Automo Pte. Ltd.  Authorized Signatory</div>			
Remarks :			Receiver Chop & Sign			

CL APPRAISER PTE LTD

24 Peshurst Place, Singapore 556440
Email: clappraiser@yahoo.com Hp: 9068 8689 Fax: 6452 9783
Reg No: 201000228E

INVOICE

Tan Swee Kang
C/o: Motor Intel Automo Pte Ltd
13 Kaki Bukit Road 4, #01-20
Bartley Biz Centre, Singapore 417807

Invoice No: CL/190032
Ref No: MIA/12/1819/TP
Date: 09 January 2019

DESCRIPTION	AMOUNT
OUR SERVICE FEE CHARGES:	
<ul style="list-style-type: none">SURVEY INSPECTION FOR VEHICLE NO. <u>SKH 783 B</u>RESURVEY INSPECTIONDIGITAL PHOTOGRAPHS SERVICES (INCLUSIVE OF STORAGE AND SUBMISSION OF DIGITAL PHOTOGRAPHS)TRANSPORTATION	
GRAND TOTAL	SS986.00

E & O E

All cheque payment should be "Crossed" and made payable to "CL APPRAISER PTE LTD"

We shall be grateful if you could forward our payment at your early convenience.



CL Appraiser Pte Ltd

CL APPRAISER PTE LTD

24 Peshurst Place, Singapore 556440
Email: clappraiser@yahoo.com Hp: 9068 8689 Fax: 6452 9783
Reg No: 201000228E

VEHICLE INSPECTION REPORT

To: Tan Swee Kang
C/o: Motor Intel Automo Pte Ltd
13 Kaki Bukit Road 4, #01-20
Bartley Biz Centre, Singapore 417807

Date : 09 January 2019
Our ref : MIA/12/1819/TP

Accident Date : 26 December 2018
Inspection Date : 27 December 2018
Repairer Name : Motor Intel Automo Pte Ltd
13 Kaki Bukit Road 4, #01-20
Bartley Biz Centre, Singapore 417807

Type of Survey : Third Party

PARTICULARS OF VEHICLE

Registration No : SKH 783 B
Make / Model : Mercedes Benz E250
Chassis No : WDD2120472A639759
Engine No : 27186030471274

Year / Capacity : 2012 / 1796 cc
Colour : Grey
Mileage : 185643

CONDITION OF TYRES

	Make	Size	Thread Balance	Rim
Front Nearside	: Bridgestone	245/40 R18	5 mm	Sport
Front Offside	: Bridgestone	245/40 R18	5 mm	Sport
Rear Nearside	: Bridgestone	245/40 R18	5 mm	Sport
Rear Offside	: Bridgestone	245/40 R18	5 mm	Sport

GENERAL DESCRIPTION OF DAMAGE VEHICLE

The impact damages sustained on the vehicle at the time of inspection is on the o/s portion.
(Details refer to the photographs attached)

Enclosed number of photographs: **91** copies

REMARKS

This inspection was conducted entirely on a "**WITHOUT PREJUDICE**" basis
and we have not given authorization and instruction to the repairer to proceed with the repair

RECOMMENDATIONS

We have thoroughly inspected each and every item on the estimate against the physical damage found on the vehicle and we have listed the breakdown of our finding and our recommendation.

The repairer has agreed to undertake the job at a **Lump Sum of \$ 17,100.00** on a contractual basis.

Under normal circumstances, the repair period would be about 12 (Twelve) working days.

ECL APPRAISER PTE LTD

Vehicle Registration No: SKH 783 B

Our Ref No: MIA/12/1819/TP

Qty	Description	Conditions	Repairer's Estimate	Revised Amount
-----	-------------	------------	---------------------	----------------

SPARE PARTS - LIST ITEMS

1	Rear windscreen repair kit	Necessary	\$ 195.00	\$ 195.00	NECV
1	Rear o/s taillamp	Intact	\$ 843.00		
1	Rear bumper	Damage	\$ 2,094.00	\$ 2,094.00	CUTV
1	Rear bumper clip (1 set)	Necessary	\$ 80.00	\$ 80.00	NECV
1	Rear bumper o/s side retainer	Necessary	\$ 48.00	\$ 48.00	NECV
1	Rear o/s fender	Damage	\$ 2,185.00	\$ 2,185.00	DDV
1	Rear o/s fender inner shield	Damage	\$ 186.00	\$ 186.00	CUTV
1	Rear o/s wheel rim	Damage	\$ 1,200.00	\$ 1,200.00	CUTV
1	Rear o/s wheel hub	Damage	\$ 316.00	\$ 316.00	NNX
1	Rear o/s wheel bearing	Necessary	\$ 115.00	\$ 115.00	NECV
1	Rear o/s shock absorber	Damage	\$ 520.00	\$ 520.00	NNX
1	Rear o/s knuckle arm	Damage	\$ 1,265.00	\$ 1,265.00	} NNX
1	Rear o/s lower arm	Damage	\$ 520.00	\$ 520.00	
1	Rear o/s stay arm	Damage	\$ 608.00	\$ 608.00	
1	Rear o/s trailing arm	Damage	\$ 440.00	\$ 440.00	
1	O/s centre pillar	Repair	\$ 1,380.00		
1	O/s rocker panel outer garnish	Damage	\$ 655.00	\$ 655.00	NNX ✓
1	Rear o/s door	Damage	\$ 2,235.00	\$ 2,235.00	DDV
1	Rear o/s door outer chrome moulding	Intact	\$ 175.00		
1	Rear o/s door lock	Damage	\$ 445.00	\$ 445.00	NNX
1	Rear o/s door chrome protector	Damage	\$ 160.00	\$ 160.00	DDV ✓
1	Rear o/s door weatherstrip	Necessary	\$ 280.00	\$ 280.00	NNX
1	Rear o/s door lower rubber seal	Necessary	\$ 185.00	\$ 185.00	DDV
1	Front o/s door	Damage	\$ 2,235.00	\$ 2,235.00	DDV
1	Front o/s door glass chrome moulding	Intact	\$ 175.00		
1	Front o/s door lock	Damage	\$ 435.00	\$ 435.00	NNX
1	Front o/s door chrome protector	Damage	\$ 165.00	\$ 165.00	NNX
1	Front o/s door regulator	Damage	\$ 650.00	\$ 650.00	NNX
1	Front o/s door regulator motor	Damage	\$ 590.00	\$ 590.00	NNX
1	Front o/s door side mirror	Damage	\$ 758.00	\$ 758.00	DDV
1	Front o/s door weatherstrip	Necessary	\$ 295.00	\$ 295.00	NECV
1	Front o/s door lower rubber seal	Necessary	\$ 190.00	\$ 190.00	NECV
			\$ 21,623.00	\$ 19,050.00	
			Less 10%	\$ 2,162.30	\$ 1,905.00
Total Cost - List Items			\$ 19,460.70	\$ 17,145.00	

ECL APPRAISER PTE LTD

Vehicle Registration No: SKH 783 B

Our Ref No: MIA/12/1819/TP

Qty	Description	Conditions	Repairer's Estimate	Revised Amount
List Items Total c/f			\$ 19,460.70	\$ 17,145.00

SPECIAL NETT ITEMS

1	Rear o/s fender inner shield clip (1 set)	Necessary	\$ 45.00	\$ 45.00	NEW
1	Rear o/s tyre (Depreciation)	Damage	\$ 550.00	\$ 275.00	MAX
Total Cost - Special Nett items			\$ 595.00	\$ 320.00	

Total cost of parts

\$ 20,055.70 \$ 17,465.00

ECL APPRAISER PTE LTD

Vehicle Registration No: SKH 783 B

Our Ref No: MIA/12/1819/TP

S/No	Description	Repairer's Estimate	Revised Amount
	Total cost of parts c/f	\$ 20,055.70	\$ 17,465.00

LABOUR

1	To remove, refit, replaced damaged lamps and check up rear electrical wiring	\$ 80.00	\$ 50.00 ✓
2	To remove and refit inner garnishes, inner trim to assist repair.	\$ 150.00	\$ 120.00 ✓
3	To remove and refit rear reverse sensor.	\$ 150.00	\$ 120.00 ✓
4	To remove and refit fuel tank assembly with all attachments, pipe and hoses.	\$ 150.00	\$ 120.00
5	To remove and refit rear undercarriage.	\$ 400.00	\$ 300.00 ✓
6	To conduct wheel alignment.	\$ 150.00	\$ 120.00 ✓
7	To remove and refit rear windscreen glass.	\$ 180.00	\$ 120.00 ✓
8	To remove and refit doors complete fittings and replace damaged parts, transfer all fittings to new door.	\$ 300.00	\$ 240.00 ✓
9	To apply undercoating on repaired and replaced panel.	\$ 180.00	\$ 120.00 ✓
10	To provide labour charges, workmanship to dismantle above damaged parts, repair including cut and weld ; re-align body structure and damaged consistent to the accident.	\$ 1,600.00	\$ 1,250.00 ✓
11	To respray painting include polishing and waxing on the changed body parts, repaired portions where consistent to the accident.	\$ 1,500.00	\$ 1,320.00 ✓

Repair days 6 **GRAND TOTAL**

\$ 24,895.70 \$ 21,345.00

Val 13/3/12

C L APPRAISER PTE LTD

Vehicle Registration No: SKH 783 B

Our Ref No: MLA/12/1819/TP

The repairer has agreed to undertake the repair under a Lump Sum Basis. We have further adjusted the amount to a **Lump Sum Repair Contract of : S 17,100.00**

By accepting to carry out the repairs on a contract lump sum basis, the repairer has the discretion to replace the damaged parts with used, reconditioned or new parts, or to repair it to a roadworthy condition.

Note: The revised estimate was made from a visual inspection. Should there be any discrepancy or unseen damage / item in this survey, kindly notified the company within seven (7) from the date hereof. Otherwise, the revised amount shall be deem to be vaild.

Disclaimer

The rates and assessment of damages as stated in this report is to be used solely for legal proceedings in relation to the surveyed vehicle and the accident in which the surveyed vehicle was involved in. The rates and assessment of damages must not be used in any circumstances for comparison with other vehicle and/or other accident in other legal proceedings.

C L APPRAISER PTE LTD



Cheong K. H
Automotive Appraiser

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT	
Date Of Report	27/12/2018 12:55
Date Of Accident	26/12/2018 14:30
Exact Location Of Accident	PIE TOWARDS TUAS (BEFORE TOA PAYOH EXIT)
Country/State of Loss	SINGAPORE
DETAILS OF OWN VEHICLE	
Vehicle Registration Number	SKH783B
Insured/Policyholder	
Name Of Registered Owner	TAN SWEE KANG
NRIC No	S1844528Z
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-98155418
Alternative Phone No	OFFICE-98155418
Vehicle Particulars	
Manufacturer	MERCEDES-BENZ
Model	E 250 BLUEEFFICIENCY
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR
Insurance Company	
Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5075045925-03 PREMIUM
Cover Note Number	
Driver	
Name of Driver	LIM CHEE SON @LIM CHEE SONG
NRIC No	S1819437F
Date Of Birth	25/02/1945
Occupation	INDOOR
Date Of Driving Pass	20/01/1970
Driving Experience	48 YEARS AND 11 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-98155418
Fax Number	
Contact Number	
E-Mail Address	NOEMAIL

Address	15 WOO MON CHEW ROAD
Postcode	455066
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	SPOUSE
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	SIDE SWIPE
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : TAN SWEE KANG @TAN SWEE KAY GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO SKETCH PLAN ATTACHED

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	XE1931X
Vehicle Make/Model/Colour	SCANIA P360CB6X4MHZ
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

SKETCH PLAN

IMPORTANT NOTICE


1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application to interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)
I understand, acknowledge, agree and consent that:
 - (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purposes of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
 - (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
 - (c) my Personal Information may/can be disclosed by any of the insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes
 - (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection investigation and management in present and all future claims.
 - (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

X mk
Policyholder's Signature
Date & Time

X huf
Driver's Signature
(If driver is not the policyholder)
Date & Time
27 DEC 2010

IDAC KAKI
23 Kaki Bukit
Singapore 41000
Tel: 67416697 Fax: 67416698
Email: idac@idac.com.sg
Reporting Centre Personnel's Signature
Name:
NRIC/IN No:

SKETCH PLAN



VEH A → SKH 7839
Mercedes E 200

VEH B → XE1931X

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 26/12/2018 at about 1430hrs, I was traveling along PIE towards Jernang Bafers just before the exit on the lane 3. Traffic was moderate. Out of sudden, vehicle B XE1931X drove into my lane 3 from lane 2 from the rear and hit my vehicle A right rear portion to the right front portion. The impact was so huge that his vehicle B and my vehicle A was stuck together in my lane 3. His vehicle also pushed my vehicle A to be slightly out of the lane due to the accident impact. Vehicle B alighted and apologized and told us that he has not enough of sleep. Both me and my wife suffer injuries to our shoulder and hands.

DECLARATION

We declare the foregoing particulars are true in every respect.

x *[Signature]*
Policyholder's Signature
Date & Time

x *[Signature]*
Driver's Signature
(If driver is not the policyholder)
Date & Time

IDAC KAT

23 Kaki Bukit
Singapore 417
Tel: 67416697 Fax:
Email: vockb@idac.gov.sg

Reporting Centre Personnel's Signature
Name:
NRIC/PIN No:

27 DEC 2018

Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report 27/12/2018 12:55
Date Of Accident 26/12/2018 14:30
Exact Location Of Accident PIE TOWARDS TUAS (BEFORE TOA PAYOH EXIT)
Country/State of Loss SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number SKH783B
☒ Insured/Policyholder
Name Of Registered Owner TAN SWEE KANG
NRIC No S1844528Z
Email Address NOEMAIL
Mobile Phone No (LOCAL) +65-98155418
Alternative Phone No OFFICE-98155418
Vehicle Particulars
Manufacturer MERCEDES-BENZ
Model E 250 BLUEEFFICIENCY

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY

Vehicle Category PRIVATE CAR

Insurance Company

☒ Name of Insurance Company NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage COMPREHENSIVE
Fleet Policy NO
Policy Number 5075045925-03 PREMIUM

Cover Note Number

Driver

Name of Driver LIM CHEE SON @LIM CHEE SONG
NRIC No S1819437F
Date Of Birth 25/02/1945
Occupation INDOOR
Date Of Driving Pass 20/01/1970
Driving Experience 48 YEARS AND 11 MONTHS
Gender MALE
Mobile Number (LOCAL) +65-98155418
Fax Number
Contact Number
Email Address NOEMAIL

Address 15 WOO MON-CHEW ROAD
Postcode 455066
Was driver an employee of the Insured's Company NO
If No, Relationship of the Driver with the Insured SPOUSE
Vehicle Registration Number of Driver's Own Vehicle -
Insurance Company of Driver's Own Vehicle -

General Information of the Accident

Type Of Accident SIDE SWIPE
Weather Conditions CLEAR
Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
Number of vehicles (including own vehicle) involved in the accident 2
Was any body injured in the Accident? NO
Was any injured conveyed to hospital by ambulance? NO
Was any other material or property damaged? YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
Number of Passengers (Including Driver) 2
Passenger 1
NAME: TAN SWEE KANG @TAN SWEE KAY
GENDER: FEMALE

Details of Police Action

Was the accident reported to the police? NO
If Yes, Please state which Police Station
Was notice of intended Prosecution given? NO
If Yes, against whom?

Circumstances of Accident

REFER TO SKETCH PLAN ATTACHED

Attachment(s)

Are accident photos available for attachment? YES
Was there any video captured by Car Camera? NO
Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number XE1931X
Vehicle Make/Model/Colour SCANIA P360CB6X4MHZ
Details Of Properties
Vehicle Category COMMERCIAL VEHICLE
Name of Driver
NRIC/Passport Number
Contact Number
Address
Postcode
Insurance Company Name
Nature Of Damage
No. Of Passenger (Including Driver)

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorized Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purposes of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes").
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes;
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims;
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated; or
 - (ii) for complying with requirements under any regulations, laws or court orders.


Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

27 DEC 2010

IDAC KAKI
23 Kaki Bukit
Singapore 41508
Tel: 67416697 Fax: 67416698
Email: feedback@idac.gov.sg
Reporting Centre Personnel's Signature
Name:
NRIC/PIN No.:

SKETCH PLAN



VEH1 → SKH 7839
Mercedes B 200

VEH3 → XE1931X

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 26/12/2018 at about 1430hrs, I was travelling along PIE towards Jooi direction just before Toa Payoh on the lane 3. Traffic was moderate. Out of sudden, vehicle 3 XE1931X drove into my lane 3 from lane 2 from the rear and hit my vehicle A right rear portion to the right front portion. The impact was so huge that his vehicle B and my vehicle A was stuck together in my lane 3. His vehicle also pushed my vehicle A to be slightly out of the lane due to the accident impact. Vehicle B alighted and apologised and told us that he has not enough of sleep. Both me and my wife suffer injuries to our shoulder and hands.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

x *[Signature]*
Policyholder's Signature
Date & Time:

x *[Signature]*
Driver's Signature
(If driver is not the policyholder)
Date & Time:

27 DEC 2018

23 Kaki Bukit
Singapore 41
Tel: 67416697 F
Email: vackh@ps.com.sg
Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:



Certificate of Insurance

MOTOR VEHICLES (THIRD PARTY RISKS AND COMPENSATION) ACT (CHAPTER 189)
MOTOR VEHICLES (THIRD PARTY RISKS AND COMPENSATION) RULES, 1960
ROAD TRANSPORT ACT, 1987 (MALAYSIA)
MOTOR VEHICLES (THIRD PARTY RISKS) RULES, 1959 (MALAYSIA)

Certificate Number: 5075045925-03

Cover : drive PREMIUM

- | | |
|--|---------------------|
| 1. Index mark and Registration Number of Vehicle | : SKH7838 |
| Chassis Number | : WDD212D472A639759 |
| 2. Name of Policyholder | : TAN SWEE KANG |
| 3. Effective Date of Insurance | : 01 Nov 2018 |
| 4. Expiry Date of Insurance | : 31 Oct 2019 |

5. Persons or Classes of Persons entitled to drive#

(a) The Policyholder.

(b) Any other person who is driving on the Policyholder's order or with his/her permission.

Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle.

6. Limitations as to Use#

(a) Use for social domestic and pleasure purposes and in connection with the Policyholder's business or profession.

This Policy does not cover

(a) Use for hire or reward.

(b) Use for racing, pace-making, reliability trial or speed-testing.

(c) Use for the carriage of goods (other than samples) in connection with any trade or business.

(d) Use for any purpose in connection with the Motor Trade.

* Limitations rendered inoperative by Section 8 of the Motor Vehicle (Third Party Risks and Compensation) Act (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

EXCESS (SECTION 1)	: S\$600
EXCESS (SECTION 2)	: N/A
WINDSCREEN EXCESS	: S\$100
ADDITIONAL EXCESS	: N/A
UNNAMED DRIVER EXCESS	: PLEASE REFER OVERLEAF
REPAIR AT OWNER'S PREFERRED WORKSHOP	: YES
INSURE WITH COE	: YES
NCD PROTECTION	: NO
TRANSPORT ALLOWANCE	: NO
EXCESS WAIVER	: NO
PRIMARY DRIVER	: TAN SWEE KANG @ TAN SWEE KAY
NAMED DRIVER (1)	: LIM CHEE SON @ LIM CHEE SONG
NAMED DRIVER (2)	: N/A
HIRE PURCHASE COMPANY	: TAI THONG LEE TRADING PTE LTD
SUM INSURED	: MARKET VALUE OF INSURED VEHICLE AT TIME OF LOSS

I/We hereby Certify that the Policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia)

Agency : TAI THONG LEE TRADING PTE LTD (00000612744)

Date of issue : 01 Oct 2018 10:24 hrs

For NTUC INCOME INSURANCE CO-OPERATIVE LIMITED

Countersigned By:

Authorised Officer

Chief Executive

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT	
Date Of Report	27/12/2018 10:55
Date Of Accident	26/12/2018 14:30
Exact Location Of Accident	WOODSVILLE FLYOVER AFTER EXIT 15A TOWARDS TUAS
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE	
Vehicle Registration Number	XE1931X
Insured/Policyholder	
Name Of Registered Owner	CHUAN LIM CONSTRUCTION PTE LTD
Co Reg No	199600684W
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-65710615

Vehicle Particulars	
Manufacturer	SCANIA
Model	P360CB6X4MHZ-12.7 D (M)
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	REPORTING ONLY
Vehicle Category	COMMERCIAL VEHICLE

Insurance Company	
Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	YES
Policy Number	GA364468
Cover Note Number	

Driver	
Name of Driver	NATARAJAN PRABU
NRIC No	G8269917T
Date Of Birth	10/06/1980
Occupation	OUTDOOR
Date Of Driving Pass	04/05/2012
Driving Experience	6 YEARS AND 7 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-93438240
Fax Number	
Contact Number	
EMail Address	NOEMAIL

Address	C/O CHUAN LIM CONSTRUCTION PTE LTD, 20 SENOKO DRIVE
Postcode	
Was driver an employee of the Insured's Company	YES
If No, Relationship of the Driver with the Insured	
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - CHANGE/CROSS LANE
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER SKETCH PLAN

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SKH783B
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	LIM CHEE SON@LIM CHEE SONG
NRIC/Passport Number	S1819437F
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.




Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/PIN No.:

Sketch Plan #2

SKETCH PLAN



Veh A: XE1931X

Veh B: SKH 783B

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I was travelling towards TWS via PIE at Woodsville flyover. I was travelling in lane 2 suddenly a car from lane 1 dash left side of my truck.

DECLARATION

I/We declare the following particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/ID No.:

Accident Photo



Accident Photo



Accident Photo



Accident Photo





Your Ref: 19.26242PD-0

Date: 15th Mar 2019

Our Ref: CS3/ASM19000021/Bsd3e2-1

M/s AXA Insurance Pte Ltd
C/O: Seah Ong & Partners LLP
36 Robinson Road
#12-03 City House
Singapore 068877
(The Motor Claims Department)

Dear Sir / Madam,

EVALUATION REPORT (PAPER SURVEY) OF ACCIDENT VEHICLE NO: SKH 783B
INSURED VEHICLE: XE 1931X
ACCIDENT DATE: 26/12/2018

We thank you for your instruction on 23/01/2019.

We acknowledge receipt of the following documents:-

- a) Automobile Inspection Report of SKH 783B from M/s S C L Appraiser Pte Ltd.
- b) Final Repair Bill of SKH 783B from M/s Motor Intel Automo Pte Ltd.
- c) Singapore Accident Statement of Vehicle SKH 783B and XE 1931X.
- d) Colour damaged vehicle photographs of SKH 783B.

Pre-Repair Inspection Date : 02/01/2019 at M/s Motor Intel Automo Pte Ltd, 13 Kaki Bukit Road 4 @ Bartley Biz Centre #01-20, Singapore 417807.

Based on the documents received from you, we have evaluated the damages of the vehicle and have the following comments:-

1. Information Recorded: -

Registration Number	: SKH 783B
Make & Model	: Mercedes Benz E250 Blueefficiency
Year of Registration	: 2012
Chassis Number	: WDD2120472A639759
Engine Capacity	: 1796 cc
2. We recommend that the repairs of the entire damage require about 6 (Six) working days to complete.
3. We hereby provide our recommendations on the cost of repair to the damaged vehicle as stated in the following page.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKH 783B

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	REAR WINDSCREEN REPAIR KIT	NECESSARY	195.00	195.00
1	REAR O/S TAILLAMP	INTACT	843.00	-
1	REAR BUMPER	CUT	2,094.00	1,318.07
1	SET REAR BUMPER CLIP	NECESSARY	80.00	80.00
1	REAR BUMPER O/S SIDE RETAINER	NECESSARY	48.00	48.00
1	REAR O/S FENDER	DENTED	2,185.00	1,954.00
1	REAR O/S FENDER INNER SHIELD	CUT	186.00	186.00
1	REAR O/S WHEEL RIM	CUT	1,200.00	1,000.00
1	REAR O/S WHEEL HUB	NOT NECESSARY	316.00	-
1	REAR O/S WHEEL BEARING	NECESSARY	115.00	115.00
1	REAR O/S SHOCK ABSORBER	NOT NECESSARY	520.00	-
1	REAR O/S KNUCKLE ARM	NOT NECESSARY	1,265.00	-
1	REAR O/S LOWER ARM	NOT NECESSARY	520.00	-
1	REAR O/S STAY ARM	NOT NECESSARY	608.00	-
1	REAR O/S TRAILING ARM	NOT NECESSARY	440.00	-
1	O/S CENTRE PILLAR	TO REPAIR SEE LABOUR	1,380.00	-
1	O/S ROCKER PANEL OUTER GARNISH	CRACKED	655.00	655.00
1	REAR O/S DOOR	TO REPAIR SEE LABOUR	2,235.00	-
1	REAR O/S DOOR OUTER CHROME MOULDING	INTACT	175.00	-
1	REAR O/S DOOR LOCK	NOT NECESSARY	445.00	-
1	REAR O/S DOOR CHROME PROTECTOR	DENTED	160.00	160.00
1	REAR O/S DOOR WEATHERSTRIP	NOT NECESSARY	280.00	-
1	REAR O/S DOOR LOWER RUBBER SEAL	NOT NECESSARY	185.00	-
1	FRONT O/S DOOR	DENTED	2,235.00	1,955.00
1	FRONT O/S DOOR GLASS CHROME MOULDING	INTACT	175.00	-
1	FRONT O/S DOOR LOCK	NOT NECESSARY	435.00	-
1	FRONT O/S DOOR CHROME PROTECTOR	NOT NECESSARY	165.00	-
1	FRONT O/S DOOR REGULATOR	NOT NECESSARY	650.00	-
1	FRONT O/S DOOR REGULATOR MOTOR	NOT NECESSARY	590.00	-
1	FRONT O/S DOOR SIDE MIRROR	BROKEN	758.00	758.00
1	FRONT O/S DOOR WEATHERSTRIP	NECESSARY	295.00	295.00
1	FRONT O/S DOOR LOWER RUBBER SEAL	NECESSARY	190.00	190.00

Report Ref No. CS3/ASM19000021/Bsd3e2-1



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LESS 10% DISCOUNT		-2,162.30	-890.91
			19,460.70	8,018.16
	SPECIAL NETT ITEMS			
1	SET REAR O/S FENDER INNER SHIELD CLIP (SN)	NECESSARY	45.00	25.00
1	REAR O/S TYRE (SN)	NOT NECESSARY	550.00	-
			595.00	25.00
	LABOUR			
	TO REMOVE, REFIT, REPLACED DAMAGED LAMPS AND CHECK UP REAR ELECTRICAL WIRING.		80.00	50.00
	TO REMOVE AND REFIT INNER GARNISHES, INNER TRIM TO ASSIST REPAIR.		150.00	80.00
	TO REMOVE AND REFIT REAR REVERSE SENSOR.		150.00	60.00
	TO REMOVE AND REFIT FUEL TANK ASSEMBLY WITH ALL ATTACHMENTS, PIPE AND HOSES.		150.00	120.00
	TO REMOVE AND REFIT REAR UNDERCARRIAGE.		400.00	80.00
	TO CONDUCT WHEEL ALIGNMENT.		150.00	60.00
	TO REMOVE AND REFIT REAR WINDSCREEN GLASS.		180.00	80.00
	TO REMOVE AND REFIT DOORS COMPLETE FITTINGS AND REPLACE DAMAGED PARTS, TRANSFER ALL FITTINGS TO NEW DOOR.		300.00	100.00
	TO APPLY UNDERCOATING ON REPAIRED AND REPLACED PANEL.		180.00	60.00
	TO PROVIDE LABOUR CHARGES, WORKMANSHIP TO DISMANTLE ABOVE DAMAGED PARTS, REPAIR INCLUDING CUT AND WELD; RE-ALIGN BODY STRUCTURE AND DAMAGED CONSISTENT TO THE ACCIDENT. INCLUSIVE OF THE REPAIR OF O/S CENTRE PILLAR AND REAR O/S DOOR.		1,600.00	800.00
	TO RESPRAY PAINTING INCLUDE POLISHING AND WAXING ON THE CHANGED BODY PARTS, REPAIRED PORTIONS WHERE CONSISTENT TO THE ACCIDENT.		1,500.00	800.00
			4,840.00	2,290.00
GRAND TOTAL			24,895.70	10,333.16

RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			8,250.00
---	--	--	-----------------

Report Ref No. CS3/ASM19000021/Bsd3e2-1

LIM TEOW GUAN

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.