

<<

Service Request Details

ClaimS9M01BIB

ReferenceCS/ASM19001580/Ztd3s2✎

Loss DateJanuary 21, 2019

Report DateJan 22, 2019 4:00:00 PM

Request DateJanuary 23, 2019

Due Date

Vendor NameLKK AUTO CONSULTANTS PTE LTD (OD)

Type of LossOwn Damage

ServicesFire

Actions

Next StepWait for: Approve invoice

Add Invoice

Vehicle Information

Incident VehicleSGG7507P

Registration #

MakeMERCEDES

ModelS280L

Service Address

Block 1005 Bukit Merah Lane 2, , 159761

Primary Contact/Insured

ONG BEE LUAN IVY

991 BUKIT TIMAH ROAD, #07-08

MAPLEWOODS, 589630, Singapore

IVYBEEG@YAHOO.COM

Claim Handler

TAN Jas

6568804844

jas.tan@axa.com.sg

Additional Instructions

SHL- FIRE INVESTIGATION OD XS NIL

Messages	Invoices	History	Documents	Assessment	Metrics	Notes
Document TypeDocument SubType						
+ Upload Documents						
NAME	TYPE	SUB-TYPE	AUTHOR	DATE UPLOADED		
📄 Accident Statement	Reports & Statement		Merimen			
📄 LKKInvoice1[4].pdf	Invoice	Surveyor/ Assessor expense	LKK AUTO CONSULTANTS PTE LTD (OD)	March 28, 2019		
📄 TOTAL LOSS REPORT.pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (OD)	March 28, 2019		
📄 SCDF FIRE REPORT INVOICE.pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (OD)	March 28, 2019		
📄 LTA REBATE.pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (OD)	March 28, 2019		
📄 GIA RPT.pdf	Reports & Statement	GIA Report	LKK AUTO CONSULTANTS PTE LTD (OD)	March 28, 2019		

NAME	TYPE	SUB-TYPE	AUTHOR	DATE UPLOADED
 PRR_Holland Dr.pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (OD)	March 8, 2019
 investigation.pdf	Reports & Statement	Investigator / Adjustor Report	LKK AUTO CONSULTANTS PTE LTD (OD)	February 1, 2019
 Full page photo.pdf	Evidence	Photos	LKK AUTO CONSULTANTS PTE LTD (OD)	January 25, 2019
 PRELI ADVISED SGG 7507P.pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (OD)	January 25, 2019
 OD SHL - EMAIL.pdf	Letters and Correspondence	Workshop	RATAN BHOSALE Pragati	January 23, 2019