

ASS. REC. BY:

REF

CS3/ICS19001581/71cd3

Special Instruction

Surveyor

Taufik

ASSIGNMENT (Office)

From (Person)

Memmen

Desmond Lee

ed

ICS

Date/Time:

24/1/19 @ 10:39am

Estimated Cost:

Bill to:

OD (TP) WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SJU 2122P

Insured:

SGO 4523P

at Workshop m/s:

28 Auto Works

Tel:

9362 8159

of

Blk 1002 Bukit Merah Lane 3 #01-83

Policy No:

Claim No:

Sum Insured:

Excess:

Make of Veh:

D.O.A:

20/01/2018

(Client's Record)

CA / REV / REP. / REV 24 HRS

upl

H.O.D. Endorsement:

Date/Time:

11:30am @ 24/1/19

Person Contacted:

Roger

Vehicle

IN/OUT

Date/Time	Action/Instruction (X) Estimate	
	SJU 2122P - NBA / ICS19001347 / Y	Don: 20/01/2019
	SGO 4523P - NBA / ICS19001347 / Y	Don: 20/01/2019
	Diamond: 25/1/2019	

Tayfikh

REF:

ECICS

VEHICLE

From _____ Date: _____
 Estimated Cost: _____
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To inspect Vehicle No: _____
 at Workshop no's _____
 of _____
 Insured _____
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S
	X

Bal. or Market Value: _____
 IDAC Accident Report: _____ Consistent?: Yes or No
 GIA / PR Seen: _____ Consistent?: Yes or No
 Est. Repairs: 5 days Res.: Yes or No
 Lump Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Vehicle: SS42122P Yr/Reg: 2016 Reg.
 Type: Motor / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or _____
 Make: Mazda 5 Yr: 1998
 Colour: Silver A/C: Insured / Std / NI / NA
 Sp. Reading: 35629 T/Ratio: Insured / Std / NI / NA
 Eng/No: JM6CW107160/24048
 C/No: _____
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: In order / Jammed / Leaked / Burnt or
 Brake: In order / Jammed / Leaked / Burnt or
 Mortl: Nil / S/Rim / STD A/Rim or
 Tyre Size: F: 205/55R16
 R: _____
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or _____
 Front _____ Rear _____
 R/Bal. 6 mm R/Bal. 6 mm
 L/Bal. 6 mm L/Bal. 6 mm
 D.O.A. _____ D.O.I. 24/1/19C/pw
 Survey held at: 28 Haverks
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Rep: large 4K-5K

11/2/19

1002 BM Line 3 #01-83

Date/Time File Pass to?

☐ : Preli. Report
☐ : Final Report

11

Date/Time File Return to?

12

Report Format: PRS

Lump Sum / I.B. / I.S.

Days Of Repair: 5

Resurvey No. of Trip: 1

Add Fee: ☐ Site Insp (\$)
☐ Interview (\$)
☐ Tech. Insp (\$)
☐ Wash and (\$)

Survey Fee:

Interpretation:

1. S-R

2. Photo

3. Video

TOTAL

100
100
10
210

Nivitha (LKK Auto)

From: Desmond Lee Ker Wen (ECICS, Claims) <Desmond_Lee@ecics.com.sg>
Sent: Thursday, 24 January 2019 10:39 AM
To: Pearlyn Goh; SUR; assignments
Cc: ECICS Claims; Natalie Ng; Janice Goh Siew Geok (ECICS, Claims)
Subject: RE: PRE-REPAIR SURVEY - ACCIDENT INVOLVING SJU2122P & SGQ4523P ON 20TH JANUARY 2018 AT ABOUT 2145HRS [1901-7044]

Dear Catherine

Please assist to get back for the PRI.

Best regards

Desmond Lee

Senior Associate | Claims



DID (65) 6303 0167

Tel (65) 6337 4779

Email Desmond_Lee@ecics.com.sg Web www.ecics.com.sg

Address 10 Eunos Road 8, Singapore Post Centre, #09-04A, Singapore 408600.

From: Desmond Lee Ker Wen (ECICS, Claims)
Sent: Tuesday, 22 January 2019 5:03 PM
To: 'Pearlyn Goh'; SUR
Cc: ECICS Claims; 'Natalie Ng'; Janice Goh Siew Geok (ECICS, Claims)
Subject: RE: PRE-REPAIR SURVEY - ACCIDENT INVOLVING SJU2122P & SGQ4523P ON 20TH JANUARY 2018 AT ABOUT 2145HRS [1901-7044]

Dear Pearlyn

In this respect, we will appoint LKK for the survey,

Dear LKK

Kindy assist with the survey.

Best regards

Desmond Lee

Senior Associate | Claims



DID (65) 6303 0167

Tel (65) 6337 4779

Email Desmond_Lee@ecics.com.sg Web www.ecics.com.sg

Address 10 Eunos Road 8, Singapore Post Centre, #09-04A, Singapore 408600.

From: Pearlyn Goh [mailto:pearlyn_goh@rssolomon.com]

Sent: Tuesday, 22 January 2019 4:25 PM

To: Desmond Lee Ker Wen (ECICS, Claims)

Cc: ECICS Claims; Natalie Ng; Janice Goh Siew Geok (ECICS, Claims)

Subject: Re: PRE-REPAIR SURVEY - ACCIDENT INVOLVING SJU2122P & SGQ4523P ON 20TH JANUARY 2018 AT ABOUT 2145HRS [1901-7044]

Dear Desmond,

We refer to your email of even date.

We write to inform that our clients will be appointing their independent surveyors.

In this respect, please arrange your Surveyors to contact Mr. Roger of 28 Auto Werks Pte Ltd at mobile No. 93628159 for a pre-repair survey of our clients' vehicle located at Blk 1002 Bukit Merah Lane 3 #01-83 Singapore 159719.

Thank you and Best Regards,

Pearlyn Goh

Sent for and On behalf of

R. S. SOLOMON LLC

On Tue, Jan 22, 2019 at 4:18 PM Desmond Lee Ker Wen (ECICS, Claims) <Desmond.Lee@ecics.com.sg> wrote:

Without prejudice

Dear Pearlyn

Thank you for your email.

We intend to conduct a pre-repair survey of the damage to your client's vehicle jointly with your client's workshop.

We propose to use one of the motor surveyors named in the list below to conduct the joint pre-repair survey as a single joint expert:

1. LKK
2. JP knight
3. Formteam
4. Appraisal Associates
5. Autoprobe
6. Raleigh

Please let us know within two (2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert.

Thank you.

Best regards

Desmond Lee

Senior Associate | Claims



DID (65) 6303 0167

Tel (65) 6337 4779

Email Desmond.Lee@ecics.com.sg Web www.ecics.com.sg

Address 10 Eunos Road 8, Singapore Post Centre, #09-04A, Singapore 408600.

From: Pearlyn Goh [mailto:pearlyn_goh@rssolomon.com]

Sent: Tuesday, 22 January 2019 3:15 PM

To: Desmond Lee Ker Wen (ECICS, Claims)

Cc: Natalie Ng

Subject: RE: PRE-REPAIR SURVEY - ACCIDENT INVOLVING SJU2122P & SGQ4523P ON 20TH JANUARY 2018 AT ABOUT 2145HRS [1901-7044]

Dear Sirs,

We act for the owner ('our client') of vehicle no. SJU2122P.

Our client's vehicle was involved in the aforesaid accident with your insured's vehicle no. SGQ4523P at the material time. As a result, our client's vehicle was damaged and before our client proceed to repair his vehicle, please let us know within 2 working days upon receipt of this notice whether you intend to conduct a pre-repair survey of our client's vehicle within the stipulated timeline, our client will proceed to repair his vehicle without further reference to you.

Please see below, the following documents for your necessary action:-

1. Our letter of even date;
2. GIA report lodged by our client's driver.

Let us hear from you soonest.

Thank you and Best Regards,

Pearlyn Goh

Sent for and On behalf of

R. S. SOLOMON LLC

Advocates & Solicitors

This message may contain privileged and confidential information and is only intended for use by the addressee. No representation, warranty, guarantee or undertaking expressed or implied is made by ECICS Limited; as to the fairness, accuracy or completeness of any information, projections or opinions contained in this message. Any unauthorized disclosure, use or dissemination either in whole or in part is prohibited. If you are not the addressee indicated in this message (or responsible for delivery of the message to such person), you may not copy or deliver this message to anyone. In such case, you should destroy this message and kindly notify the sender by reply email. Opinions contained herein are the personal opinions of the sender and do not necessarily represent the views of ECICS Limited.

[> Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	4850F
Vehicle Details	
Vehicle No.:	SJU2122P
Vehicle to be Exported:	No
Intended Deregistration Date:	30 Jan 2019
Vehicle Make:	MAZDA
Vehicle Model:	MAZDA5 5-DOOR WAGON 2.0L SP6EAT SUNROOF
Primary Colour:	Silver
Manufacturing Year:	2016
Engine No.:	PE10355037
Chassis No.:	JM6CW1071G0124048
Maximum Power Output:	111.0 kW (148 bhp)
Open Market Value:	\$20,747.00
Original Registration Date:	30 Aug 2016
First Registration Date:	30 Aug 2016
Transfer Count:	0
Actual ARF Paid:	\$21,046.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	29 Aug 2026
PARF Rebate Amount:	\$15,784.00
Intended COE Rebate Details	
COE Expiry Date:	29 Aug 2026
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$56,500.00
COE Rebate Amount:	\$42,830.00
Total Rebate Amount:	\$58,614.00

The information contained herein is correct as at 30 Jan 2019

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	21/01/2019 18:35
Date Of Accident	20/01/2019 21:45
Exact Location Of Accident	BETWEEN WOODLANDS AVENUE 12/WOODLANDS LANE
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SJU2122P
Insured/Policyholder	
Name Of Registered Owner	LIM BAK LENG
NRIC No	S1754850F
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-97977120
Alternative Phone No	OTHERS-97866756

Vehicle Particulars

Manufacturer	MAZDA
Model	5
Exact Purpose for which vehicle was being used at time of accident	GOING HOME AFTER DINNER
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	LONPAC INSURANCE BHD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	Z18VP05019971
Cover Note Number	

Driver

Name of Driver	MAX LIM WEI JIE
NRIC No	S9821906D
Date Of Birth	09/07/1998
Occupation	INDOOR
Date Of Driving Pass	05/12/2017
Driving Experience	1 YEAR AND 1 MONTH
Gender	MALE
Mobile Number	(LOCAL) +65-97977120
Fax Number	
Contact Number	OTHERS-97866756
Email Address	NOEMAIL

Address	BLK 787D WOODLANDS CRESCENT #08-20
Postcode	734787
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	CHILDREN
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	7
Passenger 1	NAME: : PASSENGER GENDER: : FEMALE
Passenger 2	NAME: : PASSENGER GENDER: : FEMALE
Passenger 3	NAME: : PASSENGER GENDER: : FEMALE
Passenger 4	NAME: : PASSENGER GENDER: : MALE
Passenger 5	NAME: : PASSENGER GENDER: : MALE
Passenger 6	NAME: : PASSENGER GENDER: : MALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

PLEASE REFER TO SKETCH PLAN

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO

Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SGQ4523J
Vehicle Make/Model/Colour	SUZUKI SWIFT
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	GREGORY RICHARD PEREIRA
NRIC/Passport Number	S9613694C
Contact Number	90214149
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	3
Passenger 1	NAME: : GENDER: :
Passenger 2	NAME: : GENDER: :

Accident Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodging of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (a) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/ID No.:


Accident Sketch Plan

SKETCH PLAN

BETWEEN WOODLOROS AVE 12 / WOODLOROS LANE

A) SJU 2122F

B) 54Q 7523J



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Saw amber light at Traffic junction brake and then the car crashed into the back of my vehicle.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature

Date & Time:

Driver's Signature

(If driver is not the policyholder)

Date & Time:

Reporting Centre Personnel's Signature

Name:

NRIC/ID No.:

...CLAIM SUBFOLDER...(Pending for Survey Report)

Midnight Accident

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	12 Feb 2019 08:49 Edit Reg		24 Jan 2019 00:00 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured: -, Co. Reg. No.: -, Email: EMAIL@EMAIL.COM									
Main Claimant: *									
Vehicle Reg. No.: SJU2122P		Date of Loss: 20/01/2018 00:00 - :59 [16 Months and 21 Days From LTA Reg Date (Man Yr)]							
Claim Type: TP / DMPC1900018H/JG		Policy/Cover Note No.: MPC18A00113600							
Vehicle Reg. No. (Insured): SGQ4523J		Policy No. (Claimant):							
		Excess:							
Repairer: 28 Auto Werks Pte Ltd (HQ) BLK 1002 BUKIT MERAH LANE 3 #01-83, 159719 Bukit Merah - Tel:									
Handling Insurer: ECICS Limited (HQ) - Tel: 63374779 /6303 0178 ... [Handled by Janice Goh - 6303 0182]									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD TAUFIKH BIN HAMID] ... [Final Rpt due 04/02/2019]									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents






































*SJU2122P (DMPC1900018H/JG)
[SGQ4523J]



































TP

Jan 20 2018 12:00AM

[-]

28 Auto Werks Pte Ltd

Upload Documents			Upload Photos			Compose New Letter			View		View in Browser	
Photos/Images									3 per page		<input checked="" type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)								Thumbnail	Print	
1	30/01/19 11:36	General View								Load JPG	<input checked="" type="checkbox"/>	
2	30/01/19 11:36	General View								Load JPG	<input checked="" type="checkbox"/>	
3	30/01/19 11:36	General View								Load JPG	<input checked="" type="checkbox"/>	
4	30/01/19 11:36	General View								Load JPG	<input checked="" type="checkbox"/>	
5	30/01/19 11:36	General View								Load JPG	<input checked="" type="checkbox"/>	
6	30/01/19 11:36	General View								Load JPG	<input checked="" type="checkbox"/>	
7	30/01/19 11:36	General View								Load JPG	<input checked="" type="checkbox"/>	
8	30/01/19 11:36	General View								Load JPG	<input checked="" type="checkbox"/>	
9	30/01/19 11:36	General View								Load JPG	<input checked="" type="checkbox"/>	
10	30/01/19 11:36	General View								Load JPG	<input checked="" type="checkbox"/>	
11	30/01/19 11:36	General View								Load JPG	<input checked="" type="checkbox"/>	
12	30/01/19 11:36	General View								Load JPG	<input checked="" type="checkbox"/>	
13	30/01/19 11:36	General View								Load JPG	<input checked="" type="checkbox"/>	
14	30/01/19 11:36	General View								Load JPG	<input checked="" type="checkbox"/>	
15	30/01/19 11:36	General View								Load JPG	<input checked="" type="checkbox"/>	
16	30/01/19 11:36	General View								Load JPG	<input checked="" type="checkbox"/>	
17	30/01/19 11:36	General View								Load JPG	<input checked="" type="checkbox"/>	
18	30/01/19 11:36	General View								Load JPG	<input checked="" type="checkbox"/>	
19	30/01/19 11:36	General View								Load JPG	<input checked="" type="checkbox"/>	
20	30/01/19 11:36	General View								Load JPG	<input checked="" type="checkbox"/>	
21	30/01/19 11:36	General View								Load JPG	<input checked="" type="checkbox"/>	
22	30/01/19 11:36	General View								Load JPG	<input checked="" type="checkbox"/>	
23	30/01/19 11:36	General View								Load JPG	<input checked="" type="checkbox"/>	
24	30/01/19 11:36	General View								Load JPG	<input checked="" type="checkbox"/>	
25	30/01/19 11:36	General View								Load JPG	<input checked="" type="checkbox"/>	
26	30/01/19 11:36	General View								Load JPG	<input checked="" type="checkbox"/>	
27	30/01/19 11:36	General View								Load JPG	<input checked="" type="checkbox"/>	
28	30/01/19 11:36	General View								Load JPG	<input checked="" type="checkbox"/>	
29	30/01/19 11:36	General View								Load JPG	<input checked="" type="checkbox"/>	
30	30/01/19 11:36	General View								Load JPG	<input checked="" type="checkbox"/>	
31	30/01/19 11:36	General View								Load JPG	<input checked="" type="checkbox"/>	
32	30/01/19 11:36	General View								Load JPG	<input checked="" type="checkbox"/>	
33	30/01/19 11:36	General View								Load JPG	<input checked="" type="checkbox"/>	
34	30/01/19 11:36	General View								Load JPG	<input checked="" type="checkbox"/>	
35	30/01/19 11:36	General View								Load JPG	<input checked="" type="checkbox"/>	
36	30/01/19 11:36	General View								Load JPG	<input checked="" type="checkbox"/>	
37	30/01/19 11:36	General View								Load JPG	<input checked="" type="checkbox"/>	

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
38	30/01/19 11:36	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
39	30/01/19 11:36	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
40	30/01/19 11:36	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
41	30/01/19 11:36	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
42	30/01/19 11:36	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
43	30/01/19 11:36	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
44	30/01/19 11:36	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
45	30/01/19 11:36	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
46	30/01/19 11:36	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
47	30/01/19 11:36	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
48	30/01/19 11:36	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
49	30/01/19 11:36	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
50	30/01/19 11:36	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
51	30/01/19 11:36	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
52	30/01/19 11:36	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
53	30/01/19 11:36	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
54	30/01/19 11:36	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
55	30/01/19 11:36	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
56	30/01/19 11:36	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
57	30/01/19 11:36	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
58	30/01/19 11:36	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
59	30/01/19 11:36	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
60	30/01/19 11:36	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
61	30/01/19 11:36	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
62	30/01/19 11:36	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
63	30/01/19 11:36	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
64	30/01/19 11:36	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
65	30/01/19 11:36	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
66	30/01/19 11:36	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
67	30/01/19 11:36	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
68	30/01/19 11:36	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
69	30/01/19 11:36	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
70	30/01/19 11:36	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
71	30/01/19 11:36	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>

Documents Checklist

DOCUMENTS CHECKLIST		Reset	Save	Print
There are no document checklists configured.				
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>				
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>				

LKK Auto Consultants Pte Ltd (Co. Reg No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/ICS19001581/T1CD3E2

Date: 12/02/2019

REFERENCE

Handling Insurer: ECICS Limited Policy No: MPC18A00113600

Claimant Vehicle No: SJU2122P Insured Vehicle No: SGQ4523J

Date of Loss: 20/01/2018 Nature of Claim: TP Claim No: DMPC1900018H/JG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SJU2122P

Make & Model: MAZDA 2, 1.5 R (A)

Reg. Date: 30/08/2016 (Man. Year: 2016)

Colour: Silver

Engine Capacity: 1998 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

Engine No: PE10355037

Chassis No: JM6CW1071G0124048

Odometer: 35629 km

CONDITION OF VEHICLE AT THE TIME OF SURVEYGeneral Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:CONDITION OF TYRES

Front Tyre Size: 205/55 R16

Front Left Side: Pirelli 6 mm

Front Right Side: Pirelli 6 mm

Rear Tyre Size: 205/55 R16

Rear Left Side: Pirelli 6 mm

Rear Right Side: Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 24/01/2019

Date Inspected: 24/01/2019 Inspected At:

28 Auto Werks Pte Ltd (HQ)
BLK 1002 BUKIT MERAH LANE 3 #01-83
Singapore 159719

Estimated Period of Repair: 5.0 days

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$4,000.00 - \$5,000.00

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 12 Feb 2019)
Parts: 143	MAZDA 2 1.5 R (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJU2122P)
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >