

ASS. REP. BY:

REF:

CS/CTI19001592/Utd3

n2

Special Instruction

Surveyor:

ASSIGNMENT (Office)

From (Person):

Chong Boon gen

of

CTI

Date/Time:

21/1/19 @ 10:49am

Estimated Cost:

Bill to:

OD / ~~TP~~ WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

GU 7500J

Insured:

GBJ 228J

at Workshop m/s

Torque 5

Tel:

8131 6518

of

8 kaki Bukit Ave 4 #01-49 premier

Policy No:

DMCVSN1629901802

Claim No:

Sum Insured:

DMCVSN1838651800

Excess:

Make of Veh:

D.O.A.

21/01/2019

(Client's Record)

CA / REV / REP. / REV 24 HRS / up

H.O.D. Endorsement:

Date/Time:

11:20am @ 21/1/19

Person Contacted:

Lucas

Vehicle IN/OUT

Date/Time

Action/Instruction (✓) Estimate

GU 7500J - NA/CTI19001450/r3

DOA: 21/01/2019

GBJ 228J - NA/CTI19001450/r3

DOA: 21/01/2019

ASSIGNMENT

From: Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: 6475007

at Workshop m/s Torque 5

of

Insured:

Policy No.

Claims No.

Sum Insured: Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt: Consistent?: Yes or No

GIA / PR Seen: Consistent?: Yes or No

Est. Repairs: 4 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes- or No

CA / REV / REP. / 24 HRS 4100R

Date: Person Contacted: Vehicle: IN / OUT

Veh No: 6475007 Yr Regn: 61 01

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or Cam

Make: Nissan Cabstar c.o 3157

Colour: Silver A/C: Insured / Std / NI / NA

Sp. Reading: 514346 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: JN1SF4F-2320844/90

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 195 R15 OH754

R: 155 R12

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Condor

Front Rear

R/Bal. 6 mm R/Bal. 6/6 mm

L/Bal. 0 mm L/Bal. 6/6 mm

D.O.A. 21/1/19 D.O.I. 25/1/19

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Reap

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	LTAB71 31-3-2019 2nd plus
22/1/19	confirmed m/s \$2100 with Lucas. (Red. (4150 38', 75%))
	RECEIVED 22 FEB 2019

Date/Time, File Pass to? 22/1 Typist

Date/Time, File Return to?

2)

Report Format :

Lump Sum / I.B.I: (\$ 2100)

Days Of Repair: 4

Resurvey No. of Trip:

Add Fee:

Site Insp (\$)

Interview (\$)

Tech. Invs (\$)

Weekend (\$)

Survey Fee:

Transportation:

S + RS, SI

Photos

Others

TOTAL

220

Nivitha (LKK Auto)

From: Mei Kwan (LKKAuto) <Meikwan@lkkauto.com>
Sent: Thursday, 24 January 2019 10:49 AM
To: assignments
Subject: FW: Accident involving GU7500J & GBJ228J on 21/01/2019 (PRE-REPAIR SURVEY REQUEST)
Attachments: image026.wmz; image030.emz; Accident involving GU7500J & GBJ228J on 21/01/2019 (PRE-REPAIR SURVEY REQ... (560 KB)

NEW CASE

From: Chong Boon Sen <boonsen.chong@sg.cntaiping.com>
Sent: Thursday, 24 January, 2019 10:47 AM
To: Torque 5 Assessment <assessment@torque5.com>
Cc: claims@torque5.com; Admin A <admin-a@lkkauto.com>
Subject: RE: Accident involving GU7500J & GBJ228J on 21/01/2019 (PRE-REPAIR SURVEY REQUEST)

Without Prejudice

Dear Sir,

Will appoint.

Dear Ikk,

Pls pri.

Regards,

Chong Boon Sen

Claims Executive

Claims

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #16-00 Springleaf Tower

Singapore 079909

Co. Reg. No. 200208384E

DID: 63896171

Fax: 62247175

Email: boonsen.chong@sg.cntaiping.com

Website: www.sg.cntaiping.com

Disclaimer :

This message is confidential; its contents do not constitute a commitment by China Taiping Insurance (Singapore) Pte. Ltd. except where provided for in a written agreement between you and China Taiping Insurance (Singapore) Pte. Ltd. Any unauthorized disclosure, use or dissemination, either in whole or partial, is prohibited. If you are not the intended recipient of the message, please notify the sender immediately.

From: Torque 5 Assessment [<mailto:assessment@torque5.com>]
Sent: Thursday, 24 January, 2019 10:29 AM
To: Chong Boon Sen <boonsen.chong@sg.cntaiping.com>
Cc: 'Torque 5 Assessment' <assessment@torque5.com>; claims@torque5.com
Subject: RE: Accident involving GU7500J & GBJ228J on 21/01/2019 (PRE-REPAIR SURVEY REQUEST)

Dear Boon Sen ,



We are agreeable Marcus Chua to PRS this vehicle , please kindly arrange.

Thank you.

Warmest Regards,

Lucas Chow

Assessor | Motor Claims Department

Hotline (65) 6452 4457 | Fax (65) 6452 4584

Mobile (65) 8131 6518

Email lucas.chow@torque5.com

Address 8 Kaki Bukit Ave 4, #01-49/50/51/52/53/54
Premier @ KB, Singapore 415875

www.torque5.com



From: Chong Boon Sen [<mailto:boonsen.chong@sg.cntaiping.com>]

Sent: Thursday, January 24, 2019 9:12 AM

To: Torque 5 Assessment

Cc: sam.chang@torque5.com; claims@torque5.com

Subject: RE: Accident involving GU7500J & GBJ228J on 21/01/2019 (PRE-REPAIR SURVEY REQUEST)



Without Prejudice

Dear Sirs

We intend to conduct a pre-repair survey of the damage to your client's vehicle jointly with your client/your motor workshop. We propose to use one of the following motor surveyors to conduct the joint pre-repair survey as a single joint expert.

ADRIAN LING
Kelvin Ang
SEE CHEW SENG
MOHD FADHILAH BIN OSMAN
XING QUO QIANG
KENNETH KONG
SIMON HO
CHUA WEIJIE
MARCUS CHUA
HENRY NG

Please let us know within two(2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert.

You may select one of the listed motor surveyors and we will bear the cost of the pre-repair survey carried out by the single joint expert.

Thank you.

Regards,

Chong Boon Sen

Claims Executive
Claims

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #16-00 Springleaf Tower

Singapore 079909

Co. Reg. No. 200208384E

DID: 63896171

Fax: 62247175

Email: boonsen.chong@sg.cntaiping.com

Website: www.sg.cntaiping.com

Disclaimer :

This message is confidential; its contents do not constitute a commitment by China Taiping Insurance (Singapore) Pte. Ltd. except where provided for in a written agreement between you and China Taiping Insurance (Singapore) Pte. Ltd. Any unauthorized disclosure, use or dissemination, either in whole or partial, is prohibited. If you are not the intended recipient of the message, please notify the sender immediately.

From: Torque 5 Assessment [<mailto:assessment@torque5.com>]

Sent: Tuesday, 22 January, 2019 3:38 PM

To: Chong Boon Sen <boonsen.chong@sg.cntaiping.com>; Claims Dept of CTI <claimsdept@sg.cntaiping.com>;

Elaine Cheong <elaine.cheong@sg.cntaiping.com>

Cc: assessment@torque5.com; sam.chang@torque5.com; claims@torque5.com

Subject: Accident involving GU7500J & GBJ228J on 21/01/2019 (PRE-REPAIR SURVEY REQUEST)

Without Prejudice

Dear Sir/ Mdm,

We refer to the above matter.

We represent our client, Data Clean Asia Pte Ltd , to notify you of the aforesaid accident involving our client's vehicle GU 7500 J and your insured's vehicle GBJ 228 J on 21/01/2019.

Please find enclosed our client's GIA report for your necessary action.

This serves as a **NOTICE** that we are claiming against GBJ 228 J for damages, costs and disbursements.

Please let us know within **2 working days** from today, your client's and your intention to conduct a pre-repair survey of our client's vehicle, along with your list of at least **ten (10) motor surveyors**.

If we do not receive any reply from you within the stipulated timeline, we shall proceed to appoint our own surveyor and proceed with the necessary repair for our client's vehicle without further reference to your insured or you.

Premises for the Pre-repair inspection: 8 Kaki Bukit Ave 4 #01-49, Premier @ Kaki Bukit Singapore 415875

Contact Person: Lucas (8131 6518)

Contact Email: assessment@torque5.com

VEH IN (Date & Time) : 25/01/2019 11.00AM CUSTOMER WILL BE WAITING

PRS ARRANGEMENT (Date & Time) : 22/01/2019 03.37PM

PRS ACKNOWLEDGEMENT

Appointed Surveyor
(Name & Signature) :

Date & Time of Inspection :

Kindly cc a copy of this letter to your insured for his/her acknowledgement.

We look forward to hearing from you soon.

To avoid incurrence of any unnecessary cost on both our end, kindly confirm liability status within 7 days from this to minimize time wastage and incurrence of any unnecessary cost(s) on both our end, we seek your kind advice, within 7 days working days, on liability status for subject claim. If we do not hear from you within the stipulated period, we shall proceed with the purchase of your insured GIA



report and this cost or any other cost incurred for confirmation of liability status shall be included in our LOD for reimbursement purpose.

Warmest Regards,

Heng Lee Yi

Administrative Assistant | Motor Claims Department

Hotline (65) 6452 4457 | Fax (65) 6452 4584

Address 8 Kaki Bukit Ave 4, #01-49/50/51/52/53/54
Premier @ KB, Singapore 415875





This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type:	Company
Owner ID:	4100R

Vehicle Details

Vehicle No.:	GU7500J
Vehicle to be Exported:	Yes
Intended Deregistration Date:	22 Jan 2019
Vehicle Make:	NISSAN
Vehicle Model:	CABSTAR
Primary Colour:	Silver
Manufacturing Year:	2001
Engine No.:	QD32153245
Chassis No.:	JN15F4F23Z0844190
Maximum Power Output:	-
Open Market Value:	\$19,159.00
Original Registration Date:	06 Jun 2001
First Registration Date:	06 Jun 2001
Transfer Count:	4
Actual ARF Paid:	\$958.00

Intended PARF Rebate Details

PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00

Intended COE Rebate Details

COE Expiry Date:	31 Mar 2019
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
PQP Paid:	\$3,733.00
COE Rebate Amount:	\$71.00
Total Rebate Amount:	\$71.00

The information contained herein is correct as at 22 Jan 2019

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT	
Date Of Report	22/01/2019 15:29
Date Of Accident	21/01/2019 18:30
Exact Location Of Accident	KALLANG PUDDING ROAD
Country/State of Loss	SINGAPORE
DETAILS OF OWN VEHICLE	
Vehicle Registration Number	GU7500J
Insured/Policyholder	
Name Of Registered Owner	DATA CLEAN ASIA PTE LTD
Co Reg No	200504100R
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-67485377
Vehicle Particulars	
Manufacturer	NISSAN
Model	CABSTAR
Exact Purpose for which vehicle was being used at time of accident	COMMERCIAL USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	COMMERCIAL VEHICLE
Insurance Company	
Name of Insurance Company	CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	NO
Policy Number	DMCVSN1629901802
Cover Note Number	
Driver Particulars	
Name of Driver	MUHAMMED HENDRY BIN MOHD NOOR
NRIC No	S8204619D
Date Of Birth	25/02/1982
Occupation	OUTDOOR
Date Of Driving Pass	25/02/2014
Driving Experience	4 YEARS AND 10 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-84976643
Fax Number	
Contact Number	
EMail Address	NOEMAIL

Address	BLK 424D YISHUN AVE 11 #05-322
Postcode	764424
Was driver an employee of the Insured's Company	YES
If No, Relationship of the Driver with the Insured	
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	4
Passenger 1	NAME: : JANI GENDER: : MALE
Passenger 2	NAME: : AMIRUL GENDER: : MALE
Passenger 3	NAME: : DEVINDRAN GENDER: : MALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

PLS REFER TO THE ATTACHED STATEMENT.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GBJ228J
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	
NRIC/Passport Number	

ACCIDENT STATEMENT

ACCIDENT DATE: (21 / 01 / 19) (DD/MM/YYYY), TIME: (18 : 30) (HH:MM)
LOCATION: Kallang Pudding Road

1. DETAILS OF VEHICLE

a) VEHICLE NUMBER: GU7500J
b) INSURANCE COMPANY: CHIAI Taiping
c) POLICY NUMBER: DMCVSN 1629901802
d) POLICY TYPE: (COMPREHENSIVE / THIRD PARTY / THIRD PARTY FIRE & THEFT)
e) MAKE & MODEL: MITSUBISHI CABSTAR
f) TYPE: (SALOON / COUPE / MPV / VAN / CORRY / MOTORCYCLE / OTHERS)
g) VEHICLE CATEGORY: (PRIVATE / COMMERCIAL / MOTORCYCLE)
h) PURPOSE OF USING AT ACCIDENT TIME:
i) ARE YOU CLAIMING UNDER YOUR OWN INSURANCE (YES/NO)
IF NO, PLEASE STATE THIRD PARTY CLAIM / REPORTING ONLY

2. INSURED / POLICY HOLDER

a) NAME: DATA CLEAN ASIA PTE LTD (MALE / FEMALE)
b) NRIC/FIN/PASSPORT: 200504100R CONTACT: 6748 5377
c) ADDRESS: 246 Macpherson Road #05-02 Betime Building
S(248578)

* CONTINUE TO 3.d IF DRIVER ALSO POLICY HOLDER

DRIVER

a) NAME: Muhammed Hendry Bin Mohd Nour (MALE / FEMALE)
b) NRIC/FIN/PASSPORT: S82046190 CONTACT: 8497 6643
c) ADDRESS: Blk 424D Vishun Ave 11 #05-322 S(764424)

* d) DATE OF BIRTH: (25 / 02 / 1982) (DD/MM/YYYY)

e) OCCUPATION: (INDOOR / OUTDOOR)

f) YEARS OF DRIVING EXPERIENCE: 3

g) WAS DRIVER AN EMPLOYEE OF THE INSURED'S COMPANY? (YES / NO)
IF NO, RELATIONSHIP OF THE DRIVER WITH INSURED: Employer

5. a) WEATHER CONDITION: (CLEAR) RAINING / OTHERS

b) ROAD SURFACE: (DRY) WET / OTHERS

6. WAS ANYBODY INJURED (YES / NO)

7. a) REPORTED TO POLICE (YES / NO)

IF YES, PLEASE STATE WHICH POLICE STATION:

Bedok South NPC

8. THIRD PARTY VEHICLE

a) VEHICLE NUMBER: G1BJ 228J MODEL:
b) DRIVER'S NAME: CONTACT:
c) NRIC/FIN/PASSPORT: CONTACT:

9. THIRD PARTY VEHICLE

a) VEHICLE NUMBER: MODEL:
b) DRIVER'S NAME: CONTACT:
c) NRIC/FIN/PASSPORT: CONTACT:

* No of passenger
(Including driver)
(04)

Passenger 1: Jani (M)

11 2: Amirul (M)

11 3: ~~Devindran~~ (M)

Devindran

* No of passenger
(Including driver)
()

* No of passenger
(Including driver)
()

KK
25, 51 Ubi Ave 1
S(408933)

Email = REPORTING@TOPQUE5.COM
Fax = 6452 4584

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

22nd Jan 2019
1204hrs

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On the stated date and time, I vehicle 'A' was travelling on the stated venue. I was travelling straight in my lane awaiting for traffic to clear before I proceed to turn left. while waiting, suddenly vehicle 'B' collided onto my vehicle rear portion. I wish to state that my vehicle was stationary upon the impact.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

22nd Jan 2019
1200hrs



Torque5 Pte Ltd

No.8 Kaki Bukit Ave 4, Premier @ Kaki Bukit, #01-50 Singapore 415875
Tel: +65 6452 4457 | Fax: +65 6452 4584 | Email: enquiry@torque5.com
Co. & GST Reg. No.: 201313221G

ESTIMATION REPORT

Vehicle No : GU7500J
Make & Model : NISSAN,CABSTAR,JN1SF4F23Z0844190
Year of : 2001
Manufacture

Estimation No. : E19010032
DOA : 22/01/2019

No	Description	Qty	U/P	Amt
Section: List Items				
1	Rear chassis panel Tailgate lower panel	1.00	315.00	0.00
2	Rear chassis stepwell	1.00	180.00	0.00
3	Rear body panel bracket (LH)	1.00	293.00	293.00
4	Rear body panel bracket (RH)	1.00	293.00	293.00

495
346.5

Amt	S\$ 586.00
Discount (30.00%)	S\$ 175.80
Subtotal	S\$ 410.20

Section: Nett Items				
5	Tail lamp (LH)	1.00	277.20	277.20
6	Tail lamp (RH)	1.00	277.20	277.20
7	Rear body panel bracket rubber stopper (LH)	1.00	89.40	89.40
8	Rear body panel bracket rubber stopper (RH)	1.00	89.40	89.40
9	License lamp (LH)	1.00	64.00	64.00
10	License lamp (RH)	1.00	64.00	64.00
11	Number plate bracket	1.00	89.00	89.00

499
445.1

Amt	S\$ 950.20
Discount (10.00%)	S\$ 95.02
Subtotal	S\$ 855.18

Section: Special Nett Items				
12	Rear body end panel	1.00	180.00	180.00
13	Rear body end panel hinge	3.00	300.00	900.00
14	Rear body floor panel	1.00	2,200.00	2,200.00
15	Rear body floor panel side hinge (LH)	1.00	300.00	300.00
16	Rear body floor panel side hinge (RH)	1.00	300.00	300.00

Continue on next page...

Nett Actual
L/S \$ 2100 25/1/19
4 day. Mr. Ph. Atthayz



Vehicle No : GU7500J
Make & Model : NISSAN,CABSTAR,JN1SF4F23Z0844190
Year of Manufacture : 2001

DOA : 22/01/2019

Amt	S\$ 5,025.00
Discount (0.00%)	S\$ 0.00
Subtotal	S\$ 5,025.00

24	To check wiring & lighting system	1.00	60.00	60.00
25	To supply undercoating / anti rust on affected areas	1.00	80.00	80.00
26	To repair, replace & realign damaged areas	1.00	1,200.00	1,200.00
27	To spray painting on affected areas	1.00	800.00	800.00
28	To R&R spare wheel assy	1.00	120.00	120.00

Amt	S\$ 2,260.00
Discount (0.00%)	S\$ 0.00
Subtotal	S\$ 2,260.00

List Items Subtotal	S\$ 410.20
Nett Items Subtotal	S\$ 855.18
Special Nett Items	S\$
Subtotal	5,025.00
Labour Items Subtotal	S\$
	2,260.00
Total	S\$

PAGE 2 OF 2

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI19001592/UTD3N2

Date: 26/02/2019

REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd.

Policy No:

Claimant Vehicle No : GU7500J

Insured Vehicle No : GBJ228J

Date of Loss: 21/01/2019

Nature of Claim: TP

Claim No: N/A

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: GU7500J

Make & Model: NISSAN CABSTAR, 2.0 (M)

Reg. Date: 06/06/2001 (Man. Year: 2001)

Colour: Silver

Engine Capacity: 3153 cc

Market Value/New Car

Price: N/A

Sum Insured (S\$): Market Value/New Car Price

Engine No: QD32153245

Chassis No: JN1SF4F23Z0844190

Odometer: 514346 km

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes

Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195R15

Rear Tyre Size:

155R12 (D)

Front Left Side: Othsu 6 mm

Rear Left Side:

Condor 6/6 mm

Front Right Side: Othsu 6 mm

Rear Right Side:

Condor 6/6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	6,636.88	1,169.60	5,467.28	82.38
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,260.00	1,530.00	730.00	32.30
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	8,896.88	2,699.60	6,197.28	69.66
Approved Total (Overridden) (S\$)		2,100.00		
(S\$)	8,896.88	2,100.00	6,796.88	76.40
+ GST 7.00/7.00% (S\$)	622.78	147.00	475.78	76.40
Nett Amount (S\$)	9,519.66	2,247.00	7,272.66	76.40

INSPECTION

Date of Assignment: 22/02/2019

Date Inspected: 25/01/2019 Inspected At:

Torque 5 Bodyworks Pte Ltd (Kaki Bukit)

8 Kaki Bukit Ave 4, #01-

49/50/51/52/53/54 Premier @ Kaki Bukit

Singapore 415875

Estimated Period of Repair: 4.0 days

Adjuster: MARCUS CHUA

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 26 Feb 2019)	
Parts:	N/A	NISSAN CABSTAR 2.0 (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GU7500J)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR TAILGATE LOWER PANEL	Bent	315.00 FL	*315.00 FL
2	1		*REAR CHASSIS STEPWELL	Bent	180.00 FL	*180.00 FL
3	1		*REAR BODY PANEL BRACKET LH	Repair	293.00 FL	*- FL
4	1		*REAR BODY PANEL BRACKET RH	Repair	293.00 FL	*- FL
5	1		*TAIL LAMP (LH)	Broken	277.20 FN	*205.00 FN
6	1		*TAIL LAMP (RH)	Broken	277.20 FN	*205.00 FN
7	1		*REAR BODY PANEL BRACKET RUBBER STOPPER (LH)	Not Necessary	89.40 FN	*- FN
8	1		*REAR BODY PANEL BRACKET RUBBER STOPPER (RH)	Not Necessary	89.40 FN	*- FN
9	1		*LICENSE LAMP (LH)	Not Necessary	64.00 FN	*- FN
10	1		*LICENSE LAMP (RH)	Not Necessary	64.00 FN	*- FN
11	1		*NUMBER PLATE BRACKET	Bent	89.00 FN	*89.00 FN
12	1		*REAR BODY END PANEL	Bent	180.00 FS	*180.00 FS
13	3		*REAR BODY END PANEL HINGE	Repair	900.00 FS	*- FS
14	1		*REAR BODY FLOOR PANEL	Repair	2,200.00 FS	*- FS
15	1		*REAR BODY FLOOR PANEL SIDE HINGE (LH)	Repair	300.00 FS	*- FS
16	1		*REAR BODY FLOOR PANEL SIDE HINGE (RH)	Repair	300.00 FS	*- FS
17	2		*REAR BODY END PANEL LOCK	Repair	600.00 FS	*- FS
18	1		*REAR BODY END PANEL STICKER-DATA CLEAN ASIA PTE LTD	Necessary	160.00 FS	*160.00 FS
19	1		*REAR BODY END PANEL STICKER-70KM/H	Necessary	90.00 FS	*10.00 FS
20	1		*REAR BODY END PANEL STICKER-6 PAX	Necessary	90.00 FS	*10.00 FS
21	1		*REAR BODY END PANEL STICKER-STA	Not Necessary	80.00 FS	*- FS
22	1		*REAR BODY END PANEL STICKER-LTA INSPECTION	Not Necessary	80.00 FS	*- FS
23	1		*REAR NUMBER PLATE & CASING	Broken	45.00 FS	*14.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc. N=NettItemDisc.

Sub Total (\$\$)	7,056.20	1,368.00
- List Item Discount on L Items 30.00/30.00% (\$\$)	324.30	148.50
- Nett Item Discount on N Items 10.00/10.00% (\$\$)	95.02	49.90

Total Parts (\$\$) 6,636.88 1,169.60

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK WIRING & LIGHTING SYSTEM	New	60.00	30.00
2	TO SUPPLY UNDERCOATING/ANTI RUST ON AFFECTED AREAS	New	80.00	50.00
3	TO REPAIR,REPLACE & REALIGN DAMAGED AREAS	New	1,200.00	750.00
4	TO SPRAY PAINTING ON AFFECTED AREAS	New	800.00	700.00
5	TO R&R SPARE WHEEL ASSY	New	120.00	0.00
Gross Labour Cost (S\$)			2,260.00	1,530.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >