

ASS. REC. BY:

REF: es/CT#19001595/Dvd3/n2

Special Instruction:

Surveyor:

ASSIGNMENT (Office)

From (Person): Chang Boon Sen of CTI Date/Time: 24/1/19 @ 9:36am

Estimated Cost: \_\_\_\_\_ Bill to: \_\_\_\_\_

OD (TP) / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SH7099C Insured: GBG 481SD

at Workshop m/s Chunni Motor Tel: 65425119

of Amk Autopoint #01-05-06

Policy No: \_\_\_\_\_ Claim No: \_\_\_\_\_

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

Make of Veh: \_\_\_\_\_ D.O.A. 19/01/2019  
(Client's Record)

CA / REV / REP. / REV 24 HRS <sup>up</sup> H.O.D. Endorsement: 25/01/2019

Date/Time: 10:4am @ 24/1/19 Person Contacted: Jynn Vehicle IN/OUT

Date/Time	Action/Instruction	Estimate
	SH7099C-NS/INC17020762/Klvbn2	D.O.A: 29/10/2017
	GBG481SD-X	

REF:

ASSIGNMENT

CBE May 2025

From: \_\_\_\_\_ Date: \_\_\_\_\_  
 Estimated Cost: \_\_\_\_\_  
 OD / TP / WS / TP RES / OD RES / EVA / INV / MY  
 To inspect Vehicle No: \_\_\_\_\_  
 at Workshop m/s \_\_\_\_\_  
 of \_\_\_\_\_  
 Insured: \_\_\_\_\_  
 Policy No: \_\_\_\_\_  
 Claims No: \_\_\_\_\_  
 Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_  
 (Client's Record)  
 Make of Veh: \_\_\_\_\_  
 (Policy Condition)  
 Remark: The veh had commenced its repair at the time of inspection.  
 Bal. or Market Value: \_\_\_\_\_  
 IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No  
 GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No  
 Est. Repairs: 9 days Res.: Yes or No  
 Lum Sum: 20 % 3 Val: Yes or No  
 CA / REV / REP. / 24 HRS  
 Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_ Vehicle: IN / OUT

<input checked="" type="checkbox"/>	<input type="checkbox"/>
N/S	O/S
<input type="checkbox"/>	<input type="checkbox"/>

Veh No: SH 7099C Yr Regn: 2017 May  
 Type: M.Car / M.Cycle / Bus / Van / Lorry /  Prime Mover /  
 Truck / Trailer or \_\_\_\_\_  
 Make: Toyota Prius c.c. .1798  
 Colour: Blue A/C: Insured / Std / NI / NA  
 Sp. Reading: 218688 TRadio: Insured / Std / NI / NA  
 Eng/No: 2ZR3041902  
 C/No: JTDKB3FU103556766  
 Gen. Cond:  Good / Fair / Poor / Burnt  
 Steering:  In order / Jammed / Leaked / Burnt or  
 Brake:  In order / Jammed / Leaked / Burnt or  
 Modi:  Nil / S/Rim / STD A/Rim or  
 Tyre Size: F: 195/65 R 15  
 R: - - -  
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  
 TOYO / YOKO or Wastlake  
 Front Rear  
 R/Bal. S mm R/Bal. S mm  
 L/Bal. S mm L/Bal. S mm  
 D.O.A. 19/01/2019 D.O.I. 25/01/2019  
 Survey held at Chunni AMC  
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or  
N/S Front & N/S Body  
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction  
China Teiping GBG 4815D  
01/03/19 Jnanju 1/5 12150/- with 9 days of rev (Real 7020.68, 379)

RECEIVED 9 MAR 2019

5/3 check with handler, no policy or claim. Just submit the report.

Date/Time, File Pass to?  : Preli. Report  
 : Final Report  
 Days Of Repair: 9  
 Resurvey No. of Trip: 2  
 Survey Fee: \_\_\_\_\_  
 Transportation: \_\_\_\_\_  
 Add Fee:  Site Insp (\$)  S + RS (\$)  Photos  Glass  
 Interview (\$)  Tech. Invs (\$)   
 Weekend (\$)   
 Report Format: merimen  
 Lump Sum / I.B.I: (\$) 12,150/-  
 TOTAL 220

### ...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	(Not Notified)		01 Mar 2019 11:36 <a href="#">Edit Adj Rpt</a>				<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

[Main](#)
[Reference](#)
[Claim Details](#)
[Documents](#)
[Show All](#)

CLAIM SUBFOLDER DETAILS		[Created by insurer]	
Insured:			
Main Claimant:	<b>COMFORT TRANSPORTATION PTE LTD</b>		
Vehicle Reg. No.:	<b>SH7099C</b>	Date of Loss:	19/01/2019 00:00 - :59
Claim Type:	<b>TP</b>	Policy/Cover Note No.:	
Vehicle Reg. No. (Insured):	<b>GBG4815D</b>	Policy No. (Claimant):	
		Excess:	S\$0.00
Repairer:	<b>Chunni Motor Pte Ltd (HQ)</b> 10 Ang Mo Kio Industrial Park 2A, #03-19 AMK Autopoint, 568047 Ang Mo Kio - Tel:		
Handling Insurer:	<b>China Taiping Insurance (Singapore) Pte. Ltd. (HQ)</b> - Tel: 6389 6111 ... [Handled by <b>Chong Boon Sen</b> ]		
Adjuster:	<b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [Handled by <b>BRYAN TANI</b> ] ... <b>[Final Rpt due 12/03/2019]</b>		
<b>ASSOCIATED MAIL RECEIVED</b>		<a href="#">View All</a>	<a href="#">Compose Case Mail</a>
There are no mail for this case.			
<b>ALL ASSOCIATED TASKS</b>		<a href="#">View All</a>	<a href="#">Search Tasks</a>
		<a href="#">Create New Task</a>	<a href="#">Complete</a>
Due Date	Priority	Type	Task Group
			Subject
			Handler
			Assigned By
			Completed On
			Created On
			Done?
No results.			

## Veron Chen (LKKAuto)

---

**From:** Chong Boon Sen <boonsen.chong@sg.cntaiping.com>  
**Sent:** Friday, 1 March 2019 11:37 AM  
**To:** Veron Chen (LKKAuto)  
**Cc:** SUR; Chunni Motor  
**Subject:** RE: REQUEST PRI : ACCIDENT INVOLVING VEH sh7099c & gbg4815d on 19.1.19

Dear Ikk,

Done.

Regards,

**Chong Boon Sen**

Claims Executive

Claims

**China Taiping Insurance (Singapore) Pte. Ltd.**

3 Anson Road #16-00 Springleaf Tower

Singapore 079909

Co. Reg. No. 200208384E

DID: 63896171

Fax: 62247175

Email: boonsen.chong@sg.cntaiping.com

Website: www.sg.cntaiping.com

*Disclaimer :*

*This message is confidential; its contents do not constitute a commitment by China Taiping Insurance (Singapore) Pte. Ltd. except where provided for in a written agreement between you and China Taiping Insurance (Singapore) Pte. Ltd. Any unauthorized disclosure, use or dissemination, either in whole or partial, is prohibited. If you are not the intended recipient of the message, please notify the sender immediately.*

---

**From:** Veron Chen (LKKAuto) [mailto:veronchen@lkkauto.com]  
**Sent:** Friday, 1 March, 2019 11:28 AM  
**To:** Chong Boon Sen <boonsen.chong@sg.cntaiping.com>  
**Cc:** SUR <sur@lkkauto.com>; Chunni Motor <chunnimotor@gmail.com>  
**Subject:** RE: REQUEST PRI : ACCIDENT INVOLVING VEH sh7099c & gbg4815d on 19.1.19

Dear Boon Sen,

GIA attached.

Best Regards,

**Veron Chen** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

**From:** Chong Boon Sen <[boonsen.chong@sg.cntaiping.com](mailto:boonsen.chong@sg.cntaiping.com)>  
**Sent:** Friday, 1 March 2019 11:21 AM  
**To:** Veron Chen (LKKAuto) <[veronchen@lkkauto.com](mailto:veronchen@lkkauto.com)>  
**Cc:** SUR <[sur@lkkauto.com](mailto:sur@lkkauto.com)>; Chunni Motor <[chunnimotor@gmail.com](mailto:chunnimotor@gmail.com)>  
**Subject:** RE: REQUEST PRI : ACCIDENT INVOLVING VEH sh7099c & gbg4815d on 19.1.19

Dear Chunni,

Kindly confirm your client: sh7099c and provide third party report for us to merimen.

Regards,

**Chong Boon Sen**

Claims Executive  
Claims

**China Taiping Insurance (Singapore) Pte. Ltd.**

3 Anson Road #16-00 Springleaf Tower  
Singapore 079909  
Co. Reg. No. 200208384E  
DID: 63896171  
Fax: 62247175  
Email: [boonsen.chong@sg.cntaiping.com](mailto:boonsen.chong@sg.cntaiping.com)  
Website: [www.sg.cntaiping.com](http://www.sg.cntaiping.com)

*Disclaimer :*

*This message is confidential; its contents do not constitute a commitment by China Taiping Insurance (Singapore) Pte. Ltd. except where provided for in a written agreement between you and China Taiping Insurance (Singapore) Pte. Ltd. Any unauthorized disclosure, use or dissemination, either in whole or partial, is prohibited. If you are not the intended recipient of the message, please notify the sender immediately.*

---

**From:** Veron Chen (LKKAuto) [<mailto:veronchen@lkkauto.com>]  
**Sent:** Friday, 1 March, 2019 11:18 AM  
**To:** Chong Boon Sen <[boonsen.chong@sg.cntaiping.com](mailto:boonsen.chong@sg.cntaiping.com)>  
**Cc:** SUR <[sur@lkkauto.com](mailto:sur@lkkauto.com)>  
**Subject:** RE: REQUEST PRI : ACCIDENT INVOLVING VEH sh7099c & gbg4815d on 19.1.19

Dear Boon Sen,

Kindly create claim in merimen.

**Workshop Details:**

**CHUNNI MOTOR WORK PTE LTD  
BLK 10 ANG MO KIO IND. PARK 2A,  
#03-19 AMK AUTOPOINT  
SINGAPORE 568047.**

Best Regards,

**Veron Chen** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email :[sur@lkkauto.com](mailto:sur@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

**From:** Admin-D (LKKAuto)  
**Sent:** Thursday, 24 January 2019 10:30 AM  
**To:** 'Chong Boon Sen' <[boonsen.chong@sg.cntaiping.com](mailto:boonsen.chong@sg.cntaiping.com)>; assignments <[assignments@lkkauto.com](mailto:assignments@lkkauto.com)>  
**Cc:** SUR <[sur@lkkauto.com](mailto:sur@lkkauto.com)>  
**Subject:** RE: REQUEST PRI : ACCIDENT INVOLVING VEH sh7099c & gbg4815d on 19.1.19

Dear Sir/Mdm,

Thank you for the assignment.

BEST REGARDS,

**G.Nivitha** | Admin

**LKK Auto Consultants Pte Ltd**

Phone: 6841-1972 | email: [assignments@lkkauto.com](mailto:assignments@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Chong Boon Sen <[boonsen.chong@sg.cntaiping.com](mailto:boonsen.chong@sg.cntaiping.com)>  
**Sent:** Thursday, 24 January 2019 9:26 AM  
**To:** Chunnimotor <[chunnimotor@gmail.com](mailto:chunnimotor@gmail.com)>  
**Cc:** Admin A <[admin-a@lkkauto.com](mailto:admin-a@lkkauto.com)>  
**Subject:** RE: REQUEST PRI : ACCIDENT INVOLVING VEH sh7099c & gbg4815d on 19.1.19

Without Prejudice

Dear Sir,

We will appoint LKK accordingly.

Dear LKK,

Pls pri.

Regards,

**Chong Boon Sen**

Claims Executive

Claims

**China Taiping Insurance (Singapore) Pte. Ltd.**

3 Anson Road #16-00 Springleaf Tower

Singapore 079909

Co. Reg. No. 200208384E

DID: 63896171

Fax: 62247175

Email: [boonsen.chong@sg.cntaiping.com](mailto:boonsen.chong@sg.cntaiping.com)

Website: [www.sg.cntaiping.com](http://www.sg.cntaiping.com)

*Disclaimer :*

*This message is confidential; its contents do not constitute a commitment by China Taiping Insurance (Singapore) Pte. Ltd. except where provided for in a written agreement between you and China Taiping Insurance (Singapore) Pte. Ltd. Any unauthorized disclosure, use or dissemination, either in whole or partial, is prohibited. If you are not the intended recipient of the message, please notify the sender immediately.*

**From:** Chunni Motor [mailto:chunnimotor@gmail.com]  
**Sent:** Thursday, 24 January, 2019 9:21 AM  
**To:** Chong Boon Sen <boonsen.chong@sg.cntaiping.com>  
**Subject:** Re: REQUEST PRI : ACCIDENT INVOLVING VEH sh7099c & gbg4815d on 19.1.19

Dear Sir,

We appoint Henry Ng

Thank you

Regards,  
Chunni Motor Work P/L

On Thu, Jan 24, 2019 at 9:10 AM Chong Boon Sen <boonsen.chong@sg.cntaiping.com> wrote:

**Without Prejudice**

Dear Sirs

We intend to conduct a pre-repair survey of the damage to your client's vehicle jointly with your client/your motor workshop. We propose to use one of the following motor surveyors to conduct the joint pre-repair survey as a single joint expert.

ADRIAN LING
Kelvin Ang
SEE CHEW SENG
MOHD FADHILAH BIN OSMAN
XING QUO QIANG
KENNETH KONG
SIMON HO
CHUA WEIJIE
MARCUS CHUA
HENRY NG

Please let us know within two(2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert.

You may select one of the listed motor surveyors and we will bear the cost of the pre-repair survey carried out by the single joint expert.

Thank you.

Regards,

**Chong Boon Sen**

Claims Executive

Claims

**China Taiping Insurance (Singapore) Pte. Ltd.**

3 Anson Road #16-00 Springleaf Tower

Singapore 079909

Co. Reg. No. 200208384E

DID: 63896171

Fax: 62247175

Email: [boonsen.chong@sg.cntaiping.com](mailto:boonsen.chong@sg.cntaiping.com)

Website: [www.sg.cntaiping.com](http://www.sg.cntaiping.com)

*Disclaimer :*

*This message is confidential; its contents do not constitute a commitment by China Taiping Insurance (Singapore) Pte. Ltd. except where provided for in a written agreement between you and China Taiping Insurance (Singapore) Pte. Ltd. Any unauthorized disclosure, use or dissemination, either in whole or partial, is prohibited. If you are not the intended recipient of the message, please notify the sender immediately.*

---

This email has been scanned by the Symantec Email Security.cloud service.  
For more information please visit <http://www.symanteccloud.com>

---



---

This email has been checked for viruses by AVG antivirus software.  
[www.avg.com](http://www.avg.com)

---

---

This email has been scanned by the Symantec Email Security.cloud service.  
For more information please visit <http://www.symanteccloud.com>

---

## Nivitha (LKK Auto)

---

**From:** Shu Pei (LKKAuto) <shupe@lkkauto.com>  
**Sent:** Thursday, 24 January 2019 9:36 AM  
**To:** assignments  
**Subject:** FW: REQUEST PRI : ACCIDENT INVOLVING VEH sh7099c & gbg4815d on 19.1.19

Best Regards,

Shu Pei | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366-0055 | email: [shupe@lkkauto.com](mailto:shupe@lkkauto.com) | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Chong Boon Sen <boonsen.chong@sg.cntaiping.com>  
**Sent:** Thursday, 24 January 2019 9:26 AM  
**To:** Chunni Motor <chunnimotor@gmail.com>  
**Cc:** Admin A <admin-a@lkkauto.com>  
**Subject:** RE: REQUEST PRI : ACCIDENT INVOLVING VEH sh7099c & gbg4815d on 19.1.19

Without Prejudice

Dear Sir,

We will appoint LKK accordingly.

Dear LKK,

Pls pri.

Regards,

**Chong Boon Sen**

Claims Executive

Claims

**China Taiping Insurance (Singapore) Pte. Ltd.**

3 Anson Road #16-00 Springleaf Tower

Singapore 079909

Co. Reg. No. 200208384E

DID: 63896171

Fax: 62247175

Email: [boonsen.chong@sg.cntaiping.com](mailto:boonsen.chong@sg.cntaiping.com)

Website: [www.sg.cntaiping.com](http://www.sg.cntaiping.com)

*Disclaimer :*

*This message is confidential; its contents do not constitute a commitment by China Taiping Insurance (Singapore) Pte. Ltd. except where provided for in a written agreement between you and China Taiping Insurance (Singapore) Pte. Ltd. Any unauthorized disclosure, use or dissemination, either in whole or partial, is prohibited. If you are not the intended recipient of the message, please notify the sender immediately.*

**From:** Chunni Motor [<mailto:chunnimotor@gmail.com>]

**Sent:** Thursday, 24 January, 2019 9:21 AM

To: Chong Boon Sen <boonsen.chong@sg.cntaiping.com>

Subject: Re: REQUEST PRI : ACCIDENT INVOLVING VEH sh7099c & gbg4815d on 19.1.19

Dear Sir,

We appoint Henry Ng

Thank you

Regards,  
Chunni Motor Work P/L

On Thu, Jan 24, 2019 at 9:10 AM Chong Boon Sen <boonsen.chong@sg.cntaiping.com> wrote:

**Without Prejudice**

Dear Sirs

We intend to conduct a pre-repair survey of the damage to your client's vehicle jointly with your client/your motor workshop. We propose to use one of the following motor surveyors to conduct the joint pre-repair survey as a single joint expert.

ADRIAN LING
Kelvin Ang
SEE CHEW SENG
MOHD FADHILAH BIN OSMAN
XING QUO QIANG
KENNETH KONG
SIMON HO
CHUA WEIJIE
MARCUS CHUA
HENRY NG

Please let us know within two(2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert.

You may select one of the listed motor surveyors and we will bear the cost of the pre-repair survey carried out by the single joint expert.

Thank you.

Regards,

**Chong Boon Sen**

Claims Executive

Claims

**China Taiping Insurance (Singapore) Pte. Ltd.**

3 Anson Road #16-00 Springleaf Tower

Singapore 079909

Co. Reg. No. 200208384E

DID: 63896171

Fax: 62247175

Email: [boonsen.chong@sg.cntaiping.com](mailto:boonsen.chong@sg.cntaiping.com)

Website: [www.sg.cntaiping.com](http://www.sg.cntaiping.com)

*Disclaimer :*

*This message is confidential; its contents do not constitute a commitment by China Taiping Insurance (Singapore) Pte. Ltd. except where provided for in a written agreement between you and China Taiping Insurance (Singapore) Pte. Ltd. Any unauthorized disclosure, use or dissemination, either in whole or partial, is prohibited. If you are not the intended recipient of the message, please notify the sender immediately.*

---

This email has been scanned by the Symantec Email Security.cloud service.  
For more information please visit <http://www.symanteccloud.com>

---

MCD612009285 / ComionDeiGro Engineering Pte Ltd - Loyang  
 ENTRY DATE & TIME: 21/01/2019 08:30  
 SUBMITTED BY: Catherine Per May Juan

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorized Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	21/01/2019 08:30
Date Of Accident	19/01/2019 23:55
Exact Location Of Accident	KRAMAT RD > CUPPAGE PLAZA
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SH7099C
<b>Insured/Policyholder</b>	
Name Of Registered Owner	COMFORT TRANSPORTATION PTE LTD
Co Reg No	199303821R
Email Address	FLEETSAFETY@CDGTAXI.COM.SG
Mobile Phone No	
Alternative Phone No	OFFICE-65508768
<b>Vehicle Particulars</b>	
Manufacturer	TOYOTA
Model	PRIUS
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	TAXI
<b>Insurance Company</b>	
Name of Insurance Company	MS FIRST CAPITAL INSURANCE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	YES
Policy Number	D-18088936MFSH
Cover Note Number	
<b>Driver</b>	
Name of Driver	KOH SOON SIAN
NRIC No	S0090492I
Date Of Birth	11/03/1954
Occupation	OUTDOOR
Date Of Driving Pass	01/01/1974
Driving Experience	45 YEARS AND 0 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-86845940
Fax Number	
Contact Number	
E-Mail Address	NOEMAIL

Address 523 05-346 BEDOK NORTH STREET 3  
 Postcode 460523  
 Was driver an employee of the Insured's Company NO  
 If No, Relationship of the Driver with the Insured OTHER - TAXI DRIVER  
 Vehicle Registration Number of Driver's Own Vehicle -  
 -  
 -  
 Insurance Company of Driver's Own Vehicle -  
 -  
 -

**General Information of the Accident**

Type Of Accident SIDE SWIPE  
 Weather Conditions CLEAR  
 Road Surface DRY

**Other Information**

Was any foreign vehicle involved in this accident? NO  
 Number of vehicles (including own vehicle) involved in the accident 2  
 Was any body injured in the Accident? NO  
 Was any injured conveyed to hospital by ambulance? NO  
 Was any other material or property damaged? YES  
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO  
 Number of Passengers (Including Driver) 1

**Details of Police Action**

Was the accident reported to the police? NO  
 If Yes, Please state which Police Station  
 Was notice of intended Prosecution given? NO  
 If Yes, against whom?

**Circumstances of Accident**

SEE ATTACH.

**Attachment(s)**

Are accident photos available for attachment? YES  
 Was there any video captured by Car Camera? YES  
 Remarks/ Reasons: -  
 Was there any audio recorded? NO

**DETAILS OF OTHER VEHICLE PROPERTY 1**

Vehicle Registration Number GBG4815D  
 Vehicle Make/Model/Colour  
 Details Of Properties  
 Vehicle Category COMMERCIAL VEHICLE  
 Name of Driver YANG XIUQIANG  
 NRIC/Passport Number G6234702W  
 Contact Number  
 Address  
 Postcode  
 Insurance Company Name  
 Nature Of Damage FRT RHT  
 No. Of Passenger (Including Driver)

**IMPORTANT NOTICE**

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mailed packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

COMFORT TRANSPORTATION PTE LTD  
CO. REG. NO. 199303821R


Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:



SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 19/1/19 at about 23.00 hrs while in I Veh A was driving straight ahead on the right lane Veh B from the left lane suddenly filtered to my lane after noticing a parked vehicle ahead of his vehicle along his left lane and collided on the whole portion of my moving vehicle.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

COMFORT TRANSPORTATION PTE LTD  
CO. REG. NO. 199303821R

Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

**REPAIR ESTIMATE**

China Taiping

VEHICLE NO: SH 7099C

DATE : 21.01.2019

MAKE :

TEL NO : 6542 5119

MODEL : TOYOTA PRIUS

FAX NO : 6542 6039

110 survey by UKF

PARTS DESCRIPTION	QTY	UNIT PRICE	AMOUNT
FRONT BUMPER COVER <i>distorted</i>			S 499.90 ✓
UNIT ASSY, HEADLAMP, LH (LED) <i>broken mounting</i>			S 3,455.00 ✓
FENDER SUB-ASSY, FRONT LH <i>Distorted</i>			S 945.30 ✓
FRONT FENDER SHIELD, LH <i>svc</i>			S 196.60 X
FRONT FENDER SHIELD CLIP <i>HL</i>			S 3.80 X
FRONT FENDER HYBRID EMBLEM, LH <i>Necl 1st</i>			S 53.50 ✓
PANEL SUB-ASSY, FRONT DOOR, LH <i>Distorted</i>			S 1,264.00 ✓
MIRROR ASSY, OUTER REAR VIEW, LH <i>crack cover</i>			S 1,390.10 ✓
FRONT WHEEL RIM (LH) <i>distorted</i>			S 1,555.10 ✓ ✓
FRONT WHEEL HUB CAP (LH) <i>cut</i>			S 177.70 ✓
FRONT WHEEL HUB BEARING (LH) <i>Dist</i>			S 560.10 ✓ ✓
FRONT SHOCK ABSORBER (LH) <i>distorted</i>			S 401.80 ✓ ✓
ABSORBER TOP MOUNTING, LH <i>HL</i>			S 196.20 X
FRONT SUSPENSION LOWER ARM (LH) <i>distorted</i>			S 637.50 ✓ ✓
FRONT DRIVE SHAFT (LH) <i>distorted</i>			S 1,310.10 ✓ ✓
RACK & PINION ASSY <i>Dist</i>			S 1,634.90 ✓ ✓
BAR, STABILIZER <i>distorted</i>			S 360.00 ✓ ✓
LINK ASSY, FRONT STABILIZER, LH <i>distorted</i>			S 199.00 ✓ ✓
KNUCKLE, STEERING, LH <i>distorted</i>			S 562.30 ✓ ✓
HUB SUB-ASSY, FRONT AXLE, RH / LH <i>HL</i>			S 549.70 ✓ X
END SUB-ASSY, TIE ROD, LH <i>distorted</i>			S 158.10 ✓ ✓
ENGINE UNDER COVER <i>HL</i>			S 457.20 X
ENGINE CROSS MEMBER <i>distorted</i>			S 2,531.70 ✓ ✓
SUB TOTAL			S 19,099.60
LESS 20% <i>25%</i>			S 3,819.92
DISCOUNTED TOTAL			S 15,279.68
FRONT DOOR COMFORT LOGO <i>HL</i>			S 75.00 NETT ✓
REAR DOOR COMFORT & APPS STICKER <i>HL</i>			S 80.00 NETT ✓
FRONT TYRE (LH) <i>svc</i>			S 216.00 NETT X
TOTAL			S 371.00

17696.10  
13272.07

155.00

NETT ✓  
NETT ✓  
NETT X

SH 7099C

PARTS DESCRIPTION	QTY	UNIT PRICE	AMOUNT
<b>LABOUR CHARGE</b>			
Panel Beating			\$ 850.00 600/-
Spray Painting Charge			\$ 1,200.00 700/-
Wiring Charge			\$ 50.00 30/-
Tuff Kote			\$ 100.00 40/-
Transfer of Door			\$ 120.00 60/-
Remove/Refix Undercarriage (FRT)			\$ 200.00 150/-
FRT Wheel Alignment			\$ 120.00 60/-
Re-set Frt ABS System			\$ 200.00
Re-set Frt Power Window System			\$ 200.00 } 180/-
Diagnosis & Resetting To Erase Fault Code			\$ 480.00
<b>TOTAL LABOUR</b>			\$ 3,520.00
<b>ESTIMATE TOTAL</b>			\$ 19,170.68

1820.00

15247.07

4512150/-

25/01/2019 e 0930am  
 not Antinuel  
 2/ same  
 9 days.  
 Ryan  
 LKK Auto

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
 Signature:  
 Date:

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

NAME  
ADDRESS

Home Tel.:

VIN:

Registration: SH 7099 C

Technician:

Mileage: 218690

Time Printed 25.1.19 10:54 AM

TOYOTA PRIUS

Front : Left

Actual	BEFORE	Specified Range
0°24'		-1°20' 0°10'
6°13'		2°25' 3°55'
7°12'		-0°06' 0°06'
20°20'		11°50' 13°20'
20°43'		10°30' 13°30'

Camber  
Caster  
Toe  
SAI  
Included Angle  
Turning Angle Diff.

Front : Right

Actual	BEFORE	Specified Range
2°15'		-1°20' 0°10'
6°17'		2°25' 3°55'
0°00'		-0°06' 0°06'
8°57'		11°50' 13°20'
11°13'		10°30' 13°30'

Front

Cross Camber  
Cross Caster  
Cross SAI  
Total Toe  
Cross Turn Diff.

Actual	BEFORE	Specified Range
-1°52'		-0°45' 0°45'
-0°04'		-0°45' 0°45'
11°22'		-0°45' 0°45'
7°12'		-0°12' 0°12'

Rear : Left

Actual	BEFORE	Specified Range
-1°28'		-2°00' -1°00'
0°38'		0°02' 0°17'

Camber  
Toe

Rear : Right

Actual	BEFORE	Specified Range
-1°33'		-2°00' -1°00'
-0°23'		0°02' 0°17'

Rear

Cross Camber  
Total Toe  
Thrust Angle

Actual	BEFORE	Specified Range
0°05'		-0°30' 0°30'
0°15'		0°03' 0°33'
0°31'		

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI19001595/DVD3N2

Date: 05/03/2019

## REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	
Claimant Vehicle No :	SH7099C	Insured Vehicle No :	GBG4815D
Date of Loss:	19/01/2019	Nature of Claim:	TP
		Claim No:	N/A

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No:	SH7099C	Engine No:	2ZRS041902
Make & Model:	TOYOTA PRIUS, 1.5 (A)	Chassis No:	JTDKB3FU103556766
Reg. Date:	25/05/2017 (Man. Year: 2017)	Odometer:	218688 km
Colour:	Blue		
Engine Capacity:	1798 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

## CONDITION OF TYRES

Front Tyre Size:	195/65R15	Rear Tyre Size:	195/65R15
Front Left Side:	West Lake 5 mm	Rear Left Side:	West Lake 5 mm
Front Right Side:	West Lake 5 mm	Rear Right Side:	West Lake 5 mm

The above values represent the remaining tyre treads depth

## COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %	
Parts	15,650.68	13,427.07	2,223.61	14.21	
Miscellaneous Items	0.00	0.00	0.00		
Labour	3,520.00	1,820.00	1,700.00	48.30	
Paintwork Labour	0.00	0.00	0.00		
Towing	0.00	0.00	0.00		
<b>Calculated Gross Total (\$\$)</b>	<b>19,170.68</b>	<b>15,247.07</b>	<b>3,923.61</b>	<b>20.47</b>	
<b>Approved Total (Overridden) (\$\$)</b>		<b>12,150.00</b>			
	(\$\$)	19,170.68	12,150.00	7,020.68	36.62
	+ GST 7.00/7.00% (\$\$)	1,341.95	850.50	491.45	36.62
	<b>Nett Amount (\$\$)</b>	<b>20,512.63</b>	<b>13,000.50</b>	<b>7,512.13</b>	<b>36.62</b>

## INSPECTION

Date of Assignment: 01/03/2019

Date Inspected: 25/01/2019 Inspected At:

Chunni Motor Pte Ltd (HQ)  
10 Ang Mo Kio Industrial Park 2A, #03-19 AMK Autopoint  
Singapore 568047

Estimated Period of Repair: 9.0 days

Adjuster: BRYAN TANI

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our

*knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b> MRM-SG	Version: 1.0 (Last Synchronised: 05 Mar 2019)
<b>Parts:</b> 144	TOYOTA PRIUS 1.5 (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b> Repairer's	(Price-denominated Standard List)
<b>Print Code:</b> (Unsubmitted, no print-code for SH7099C)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
<b>Further Info:</b> Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER COVER	Distorted	499.90 FL	*499.90 FL
2	1		*UNIT ASSY,HEADLAMP LH (LED)	Mounting Broken	3,455.00 FL	*3,455.00 FL
3	1		*FENDER SUB-ASSY,FRONT LH	Dented	945.30 FL	*945.30 FL
4	1		*FRONT FENDER SHIELD LH	Serviceable	196.60 FL	*- FL
5	1		*FRONT FENDER SHIELD CLIP	Not Necessary	3.80 FL	*- FL
6	1		*FRONT FENDER HYBRID EMBLEM,LH	Necessary/Bent	53.50 FL	*53.50 FL
7	1		*PANEL SUB-ASSY,FRONT DOOR,LH	Dented	1,264.00 FL	*1,264.00 FL
8	1		*MIRROR ASSY,OUTER REAR VIEW,LH	Cover Cracked	1,390.10 FL	*1,390.10 FL
9	1		*FRONT WHEEL RIM (LH)	Distorted	1,555.10 FL	*1,555.10 FL
10	1		*FRONT WHEEL HUB CAP (LH)	Cut	177.70 FL	*177.70 FL
11	1		*FRONT WHEEL HUB BEARING (LH)	Damaged	560.10 FL	*560.10 FL
12	1		*FRONT SHOCK ABSORBER (LH)	Distorted	401.80 FL	*401.80 FL
13	1		*ABSORBER TOP MOUNTING,LH	Not Necessary	196.20 FL	*- FL
14	1		*FRONT SUSPENSION LOWER ARM (LH)	Distorted	637.50 FL	*637.50 FL
15	1		*FRONT DRIVE SHAFT (LH)	Distorted	1,310.10 FL	*1,310.10 FL
16	1		*RACK & PINION ASSY	Damaged	1,634.90 FL	*1,634.90 FL
17	1		*BAR,STABILIZER	Distorted	360.00 FL	*360.00 FL
18	1		*LINK ASSY,FRONT STABILIZER,LH	Distorted	199.00 FL	*199.00 FL
19	2		*HUB SUB-ASSY,FRONT AXLE,RH/LH	Not Necessary	549.70 FL	*- FL
20	1		*END SUB-ASSY,TIE ROD,LH	Distorted	158.10 FL	*158.10 FL
21	1		*ENGINE UNDER COVER	Not Necessary	457.20 FL	*- FL
22	1		*ENGINE CROSS MEMBER	Distorted	2,531.70 FL	*2,531.70 FL
23	1		*FRONT DOOR COMFORT LOGO	Necessary	75.00 FS	*75.00 FS
24	1		*REAR DOOR COMFORT & APPS STICKER	Necessary	80.00 FS	*80.00 FS
25	1		*FRONT TYRE (LH)	Serviceable	216.00 FS	*- FS
26	1		*KNUCKLE STEERING,LH	Distorted	562.30 FL	*562.30 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>19,470.60</b>	<b>17,851.10</b>
- List Item Discount on L Items 20.00/25.00% (\$\$)	3,819.92	4,424.03
<b>Total Parts (\$\$)</b>	<b>15,650.68</b>	<b>13,427.07</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	PANEL BEATING	New	850.00	600.00
2	SPRAY PAINTING CHARGE	New	1,200.00	700.00
3	WIRING CHARGE	New	50.00	30.00
4	TUFF KOTE	New	100.00	40.00
5	TRANSFER OF DOOR	New	120.00	60.00
6	REMOVE/REFIX UNDERCARRIAGE (FRT)	New	200.00	150.00
7	FRT WHEEL ALIGNMENT	New	120.00	60.00
8	DIAGNOSTIC & RESETTING TO ERASE FAULT CODE }	New	480.00	180.00
9	RE-SET FRT ABS SYSTEM }	New	200.00	0.00
10	RE-SET FRT POWER WINDOW SYSTEM }	New	200.00	0.00
<b>Gross Labour Cost (S\$)</b>			<b>3,520.00</b>	<b>1,820.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >