

INCL CASE OWNER: Sathya | CC 3 / AIG1900 (613), E+63 9/ | LKK: 4/11/19
IDAC: 4/11/19

Surveyor: Steve | **ASSIGNMENT** | 2/13/2019 | Date / Time: 4/11/19
Registered in Merimen: 4/11/19

Pre-assign / CCU / FTE: GBE 25064
Insured Vehicle No.: GBE 25064 | Claim No.: 483456270556
Name of Insured: MISS SUNSHINE PILL | Policy No.: 120007286
Insured Tel No.: HP: 14/1/19 | Make / Model: WROVEN
Excess Sec II :SS: D.O.A: 14/1/19 | Place of Accident: OPMIE RD SMP RD TO EUP
Is driver the owner? (YES / NO) : (NO) | Nature of Accident: TP
If NO, Driver Name / Age: PERFORMANCE MOTOR KILLOWAN | OH GIA REPORT: YES / NO : TP GIA REPORT: YES / NO
Driver Tel No.: SKH2994H | (V/L YDS / NO) : YDS | Insured Liability: % | Final ? Yes / No: Final

INSRS: performance | INSRS: performance | INSRS: performance | INSRS: performance
WSP: performance | WSP: performance | WSP: performance | WSP: performance
Tel: performance | Tel: performance | Tel: performance | Tel: performance
Liability: performance | Liability: performance | Liability: performance | Liability: performance
RMKS: performance | RMKS: performance | RMKS: performance | RMKS: performance

Date / Time	STAGE	DATE / PIC
<u>4/11/19</u>	Non-Reporting Itr (1st)	
<u>pk</u>	Non-Reporting Itr (2nd)	
<u>1</u>	Non-Reporting Itr (Final)	
	Notification Itr (if non-pickup)	
	Call OI:	
	After call Itr to OI:	
	Documentation Check List: Handler Typist	
	Notification Itr (if non-pickup)	<input checked="" type="checkbox"/>
	After call Itr to OI:	<input checked="" type="checkbox"/>
	Authorisation To Act:	<input checked="" type="checkbox"/>
	Release Voucher:	<input checked="" type="checkbox"/>
	Final Repair Bill:	<input checked="" type="checkbox"/>
	Car Rental Invoice:	<input type="checkbox"/>
	Towing Invoice:	<input type="checkbox"/>
	LTA / GIA:	<input checked="" type="checkbox"/>
	Medical Bill:	<input type="checkbox"/>
	PIR:	<input type="checkbox"/>
	Mandate/Reject Instruction:	<input type="checkbox"/>
	LOD:	<input type="checkbox"/>
	Payment Breakdown Form:	<input type="checkbox"/>
	Post-Repair Photos:	<input type="checkbox"/>
	Others:	<input type="checkbox"/>

PRELIMINARY ADVICE Date/Time: 25/3/2019 | Sent By: LSP

FINALIZATION Date/Time: 25/3/2019 | Confirm with: LSP | Confirm by: LSP

Repair Cost: SS 3,558.40 (3 days) Reduction: 13.58 % | Email: ☒ | Call: ☐

FINAL SETTLEMENT Date/Time: 31/5/2019 | Confirm with: LSP | Email: ☒ | Call: ☐

Final Liability: % 100 (Agreed / Assessed) BOLA S/N No.: 15 | If NO or B 28, Ass. Lia: OLD change lane and collided into TP.

Repair Cost: (w/65%) SS 3,786.07 | **COPY SENT 27/6/19**

Loss of Rental (LOR): SS - (1 days) | 1) Claim status: Normal/Reject/Private Settle

Loss of Use (LOU): SS 180.00 (5 x 3 days) | 2) Report format: TP

Loss of Income (LOI): SS - (5 x 3 days) | 3) Survey fee: 4320.00

LOR only ☐ LOU only ☒ LOR + LOU ☐ LOR + LOI ☐ [Tick only one]

GIA/LTA Search: SS 2.00 | Total: SS 3,968.07 | Global Sum SS: SS 3,968.07

Medical: SS - | FINAL PAYMENT Date/Time: 31/5/2019 | Confirm with: LSP | Email: ☐ | Call: ☐

Disbursement: SS - (e.g. Tow/ Independent) | Payee 1: SS 3,968.07 | Name 1: Performance Motors Limited

Legal Cost: SS - | Payee 2 (Strike if N.A.): SS - | Name 2: -
Payee 3 (Strike if N.A.): SS - | Name 3: -

REF:

A/G

ASSIGNMENT

From:

Date:

21/3/19

Estimated Cost:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To inspect Vehicle No:

SKH 2999H

at Workshop m/s

Performance

of

303 Alexandria Road

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

In-hiran

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 3 days Res.: Yes or No

Lum Sum: 382 % 3 Val: Yes or No

CA / REV / REP. / 24 HRS / up

Date: Person Contacted:

Vehicle: IN / OUT

Veh No:

SKH 2999H

Yr Regn:

14/8/19

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

BMW 218

c.c.

1.5

Colour:

White

A/C: Insured / Std / NI / NA

Sp. Reading

6747

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

WBA 2M 12099 VE 51296

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

225/45 R17

R:

4

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

7

mm

R/Bal.

7

mm

L/Bal.

7

mm

L/Bal.

7

mm

D.O.A.

19/1/19

D.O.I.

21/3/19

Survey held at

Performance motor

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear LH

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

4.10.99.40

1/1/19 \$3,538.40 / 2.1/19 \$556.00 / 13.58%

Date/Time, File Pass to?

☐

Prel. Report

1)

☐

Final Report

Date/Time, File Returns to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

\$ + RS. \$

Photos

Others

TOTAL

Report Format :

Lump Sum / I.B.I: (\$)

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Invs (\$

☐

Weekend (\$



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AIG ASIA PACIFIC INSURANCE PTE LTD

Ref : CC3/AIG19001613/fb3

78 SHENTON WAY #08-16
CHARTIS BUILDING
SINGAPORE 079120

Date : 24-01-2019



Code : AIG

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	GBE 2506U	Veh. Inspected	SKH 2999H
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	24/01/2019

2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	19/01/2019	Inspection Date	
Survey held at	PERFORMANCE MOTORS LTD 303 ALEXANDRA ROAD SINGAPORE 159941		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X

103, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel: 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax: 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 430180
Tel: 63190888 (AfterSales)
Fax: 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel: 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax: 64796601 (AfterSales)
64796624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

24 JAN 2019

ESTIMATE

Estimate No. : b1 49885
Date Estimated : 24/01/2019
Prepared By : Inthiran A/L Thurasamy

Page No. : 1 of 4

- ESTIMATE REPAIR FOR -

Nikki Abdullah @Won Tien Li (Yun TianLi)
50 St Patrick's Road
#02-02

Singapore 424216

- ACCOUNT - 121

AIG Asia Pacific Insurance Pte. Ltd.
78 Shenton Way
#08-16 Chartis Building
Singapore 079120

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SKH2999H	VE51206	14/08/2018	218i-C	0

DESCRIPTION

To replace rear bumper, tail lamp left and attachments.

Painting rear bumper.

To check electrical wiring systems and lightings at the rear section for proper function.

Sundries.

3538.40

VALUE

850 1,275.00

934 1,038.00

150 177.00

480 80.00

Total Labour 1: 2,570.00

DESCRIPTION

SET MOUNTS PDC SENSOR REAR ✓ NEC

REAR BUMPER PANEL PRIMED (BASIS) ✓ OCF

REAR LH LED LIGHT ✓

(DG/SL) ADHESIVE SET K6 ✓ NEC

QTY

PRIC

VALUE

1 58.60 58.60

1 1,018.95 1,018.95

1 393.80 393.80

1 53.05 53.05

Total Parts : 1,524.40

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey

- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) allowed

- Supplementary item(s) not covered and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Labour 1: 2,570.00

Parts 1: 1,524.40

Labour 2: 0.00

Excess: 0.00

Total GST @ 7%: 286.61

Grand Total: 4,381.01

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY **

** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **

[➤ Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	5739D
Vehicle Details	
Vehicle No.:	SKH2999H
Vehicle to be Exported:	No
Intended Deregistration Date:	22 Mar 2019
Vehicle Make:	B.M.W.
Vehicle Model:	218I CONVERTIBLE LED NAV
Primary Colour:	White
Manufacturing Year:	2018
Engine No.:	30955368B38B15A
Chassis No.:	WBA2M12000VE51206
Maximum Power Output:	100.0 kW (134 bhp)
Open Market Value:	\$36,685.00
Original Registration Date:	14 Aug 2018
First Registration Date:	14 Aug 2018
Transfer Count:	0
Actual ARF Paid:	\$43,359.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	13 Aug 2028
PARF Rebate Amount:	\$32,519.00
Intended COE Rebate Details	
COE Expiry Date:	13 Aug 2028
COE Category:	E - Open - all except motorcycle
COE Period(Years):	10
QP Paid:	\$33,420.00
COE Rebate Amount:	\$31,389.00
Total Rebate Amount:	\$63,908.00

The information contained herein is correct as at 22 Mar 2019

OK

Poh Kin (LKKAUTO)

From: PBSP <pml-pbsp@simedarby.com.sg>
Sent: Friday, 31 May 2019 1:07 PM
To: Poh Kin (LKKAUTO)
Cc: Admin A
Subject: Re: RTA involving vehicle nos. SKH2999H and GBE 2506U on 19.01.2019

Dear Poh Kin

We have instructions to accept your offer of settlement.

Please proceed payment ASAP.

Thank you.

Regards,
Caroline
C/o Performance Motors Limited - Body and Paint
303 Alexandra Road Singapore 159941
DID: 6319 0174 Fax: 6479 4601

From: Poh Kin (LKKAUTO) <pohkin@lkkauto.com>
Sent: Saturday, 25 May 2019 1:27:21 PM
To: PBSP
Cc: 甯瑒 ©
Subject: RTA involving vehicle nos. SKH2999H and GBE 2506U on 19.01.2019

WITHOUT PREJUDICE
SAVE AS TO COSTS

Our Ref: CC3/AIG19001613/Efb3
Your Ref: SKH 2999H

Dear Caroline,

We refer to above matter and your letter of demand.

Towards an amicable settlement and without admission of liability to our Insured's part, we offer settlement as below:

1. Cost of Repair (w/gst)	S\$ 3,786.09
2. Loss of Use (\$60.00 x 3 days)	S\$ 180.00
3. GIA search fee	<u>S\$ 2.00</u>
	<u>S\$ 3,968.09</u>

kindly confirm acceptance on this matter.

Your prompt reply will be very much appreciated.

Poh Kin (LKKAUTO)

From: Poh Kin (LKKAUTO)
Sent: Saturday, 25 May 2019 1:27 PM
To: PBSP
Cc: Admin A
Subject: RTA involving vehicle nos. SKH2999H and GBE 2506U on 19.01.2019

Importance: High

WITHOUT PREJUDICE
SAVE AS TO COSTS

Our Ref: CC3/AIG19001613/Efb3
Your Ref: SKH 2999H

Dear Caroline,

We refer to above matter and your letter of demand.

Towards an amicable settlement and without admission of liability to our Insured's part, we offer settlement as below:

1. Cost of Repair (w/gst)	S\$ 3,786.09
2. Loss of Use (\$60.00 x 3 days)	S\$ 180.00
3. GIA search fee	S\$ 2.00
	S\$ 3,968.09

kindly confirm acceptance on this matter.

Your prompt reply will be very much appreciated.

"Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement."

Best Regards,

Poh Kin, Chong (Mr) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6841-2132 | email: pohkin@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

LKK Public Company Since 1982 *Save the Earth. Print only when necessary.*

This e-mail contain confidential and privileged material, and are for the sole use of the intended recipient. Use or distribution by an unintended recipient is prohibited, and may be a violation of law. If you believe that you received this e-mail in error, please do not read this e-mail or any attached items. Please delete the e-mail and all attachments, including any copies thereof, and inform the sender that you have deleted the e-mail, all attachments and any copies thereof. Thank you.

Poh Kin (LKKAuto)

From: Poh Kin (LKKAuto)
Sent: Tuesday, 12 February 2019 4:27 PM
To: 'PBSP'
Cc: Admin A; assignments
Subject: RE: REQUEST FOR DIRECT SETTLEMENT - SKH2999H & GBE2506U ON 19/01/2019
***LKK REF:CC3/AIG19001613/fb3

Importance: High

WITHOUT PREJUDICE

Our Ref: CC3/AIG19001613/fb3
Your Ref: SKH 2999H

Dear Caroline,

We refer to above matter.

Please be informed that basing on the accident statements submitted by both parties, the liability is clear / under BOLA (subject to BOLA guideline settlement) and shall proceed with direct settlement for the above mentioned case.

Please note that this e-mail is on without prejudice basis which does not amount to an authorisation of repair to your client's vehicle.

The final repair cost is subjected to the consistency of the damages according to the nature of the accident.

And the days of LOU/ LOR will be based on the number of days of repair as recommended by our surveyor.

In the meantime, kindly arrange TP survey ASAP.

"Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement."

Best Regards,

Poh Kin, Chong (Mr) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6841-2132 | email: pohkin@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Save the Earth. Print only when necessary.



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 67414108

Our Ref: CC3/AIG19001613/Efb3

17 MAY 2019

**KSS SUNSHINE PTE LTD
20 HOLLAND DRIVE
#07-407
SINGAPORE 271020**

Dear Sir/Madam,

**ACCIDENT INVOLVING GBE 2506U AND SKH 2999H ALONG/AT AFTER OPHIR RD
SLIP RD TO ECP (CHANGI) ON 19/01/2019**

We refer to the above accident where we are acting for AIG Asia Pacific Insurance Pte Ltd to resolve the claim against you and/or your authorized driver under the Auto Insurance policy taken up with them.

Based on the accident report and accident scenario, liability is down against us. We will therefore proceed to negotiate for an amicable settlement with the Third Party.

Should you however wish to further discuss on the matter prior to our negotiations and settlement, please contact us within 7 days from the date of this letter.

Please note that your No-Claim Discount (NCD)(if any) will be affected and reduced by 30% (20% for commercial vehicles) upon next renewal due to this Third Party claim. However, if your policy has a NCD protector feature, it will be deemed utilized for this claim and your NCD will be protected.

Please call us if you have further queries.

Yours faithfully,


Poh Kim, Chong
Case Handler
DID: 6841 2132
FAX: 6741 4108
Email: pohkin@lkkauto.com

c.c. AIG Asia Pacific Insurance Pte Ltd
(Motor Claims Dept)

AUTHORIZATION TO ACT
(AIG Asia Pacific – EXPRESS THIRD PARTY CLAIM)

I, Nikki Abdullah @ Woon Tien Li ("the third party claimant")
of 50 St Patrick's Rd #02-02 (424216) (address),
owner of SKH2999H (vehicle no.) hereby authorize
Performance Motors Ltd
("the workshop") to act for me with respect to my claim for repair costs and/or
rental and/or loss of use ("claim") for my vehicle no. SKH2999H that was
damaged pursuant to the accident which occurred on 19.1.2019 (date) along
Ophir Road (location)
involving vehicle no/s GBE 25064 ("the accident").


I further authorize the workshop to settle the above mentioned claim in a
manner that they deem fit and the workshop is further authorized to receive
payment further to settlement of my claim with payment cheque/s being made in
favour of the workshop.

I further acknowledge that any settlement the workshop may reach on my
behalf is on a without prejudice and without admission of liability basis insofar
as the driver/owner/insurers of the other vehicle/s is concerned.


Date this 24th day of January (month) 20 19 (year)



Signed by "the third party claimant"



Signed by "the workshop"





RELEASE VOUCHER
(AIG Asia Pacific – EXPRESS THIRD PARTY CLAIM)

We/I, Performance Motors Ltd ("the workshop") hereby confirm that we/I have reached an agreement with the appointed surveyor of AIG Asia Pacific Insurance Pte. Ltd. LKK AUTO CONSULTANTS PTE LTD ("name of surveyor") with respect to the amount claimed for S\$ 3786.09 (repair costs), S\$ 180.00 (loss of use/rental) S\$ 200 (search fees) for vehicle no. SKH2999H that was damaged pursuant to the accident which occurred on 19.1.2019 (date) along Uphir Road (location) involving vehicle no/s GBE25064.

This is pursuant to the inspection conducted on 21.3.2019 (date) at "the workshop".

We/I confirm that we/I are/am authorized by the owner Nikki Abdullah @ Wun Tien Li ("third party claimant") of vehicle no. SKH2999H to make the claim as set out in the above paragraph and we/I have full authority to settle the matter on his/her behalf in a manner that we/I deem fit. We/I enclose herein the letter of authority given by "the third party claimant".

We/I further confirm that we/I will indemnify AIG Asia Pacific Insurance Pte. Ltd for all damages, loss and/or expense that they will or have already incurred in the event that "the third party claimant" after the above said agreement lodges a further claim against the former for any loss and expenses suffered pertaining to costs of repairs and/or rental and/or loss of use pursuant to the damage to SKH2999H (vehicle no.) as a result of the accident.

We/I confirm that the agreement reached above is in full and final settlement of any claim of "the third party claimant" pursuant to the accident and that further this settlement is reached on a without prejudice and without admission of liability basis.

This agreement is subject to the application of Singapore law and the Singapore Courts have exclusive jurisdiction over any dispute arising out of the same.

Dated this 3rd day of June (month) 20 19 (year)



Signed by AIG appointed surveyor

PERFORMANCE MOTORS LIMITED
303 Alexandra Road
Dorby Performance Center
Singapore 119941
TEL: 63190100 (Dialer)
63190111 (Alternate)

JP

Chopped & Signed by "the workshop"

105, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449773115, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)

Poh Kin

SERVICE TAX INVOICE

Repair Order No. : B1 1347145	Page No. : 1 of 2
Date IN : 21/03/2019	Invoice Number : 2087918 / WSB
Cust. Svc. Advisor: Inthiran A/L Thurasamy	Invoice Date : 16/04/2019
	Payment Terms : 30 Days From Invoice
	Invoice By : Sharon Heng

- CUSTOMER INFORMATION -

Mdm Nikki Abdullah @Won Tien Li (Yun Tiar
50 St Patrick's Road
#02-02

Singapore 424216

- INVOICE TO - 121

AIG Asia Pacific Insurance Pte. Ltd.
78 Shenton Way
#08-16 Chartis Building
Singapore 079120

REGN. NO. SKH2999H	CHASSIS NO. VE51206	REGN. DATE 14/08/2018	MODEL 218I-C	MILEAGE 6747
-----------------------	------------------------	--------------------------	-----------------	-----------------

- - - - LABOUR 1 - - - -

To replace rear bumper and left tail lamp etc including
to remove and install body parts in order to carry out
painting job.

To respray rear bumper.

To check electrical wiring systems and lightings at the
rear section for proper function.

Sundries.

INS CLAIMS : ACCIDENT REPAIR, DIRECT SETTLEMENT.

DATE OF ACCIDENT : 19.1.2019. 3RD PARTY CAR : GBE2506U.

YOUR REF NO : NIL.

VEHICLE WAS SURVEYED BY MR STEVE CHAN FROM LKK AUTO
CONSULTANTS PTE LTD ON 21.3.2019 AT 11.45 AM.
AUTHORISED REPAIR BY MR CHONG POH KIN FROM LKK ON
12.2.2019 VIA E-MAIL.PROPOSE LOSS OF USE = \$80X3. THE AMOUNT IS SUBJECTED
TO INSURANCE COMPANY CONFIRMATION.

GIA SEARCH FEE = \$2.00.

NETT

850.00

934.00

150.00

80.00

0.00

0.00

0.00

Total Labour 1: 2,014.00

- - - - PARTS - - - -

REAR BUMPER PANEL PRIMED (LINES)

REAR LH LED LIGHT

(DG/SL) ADHESIVE SET K6

SET MOUNTS PDC SENSOR REAR

Qty	Retail Price
-----	--------------

1 1,018.95

1 393.80

1 53.05

1 58.60

NETT

1,018.95

393.80

53.05

58.60

Total Parts : 1,524.40



303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

360, Kembangan Road
East Coast Centre
Singapore 438160
Tel. 63190888 (AfterSales)
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)

SERVICE TAX INVOICE

Repair Order No. : B1 1347145	Page No. : 2 of 2
Date IN : 21/03/2019	Invoice Number : 2087918 / WSB
Cust. Svc. Advisor: Inthiran A/L Thurasamy	Invoice Date : 16/04/2019
	Payment Terms : 30 Days From Invoice
	Invoice By : Sharon Heng

Labour Charges : 1,934.00	Total Labour & Parts Charges : S\$ 3,538.40
Parts Charges : 1,524.40	Less Insurance Excess : S\$ 0.00
Lubricant/Misc : 80.00	Invoice Total Amount Exclude GST : S\$ 3,538.40
	GST @ 7% : S\$ 247.69
	Invoice Total Amount Include GST : S\$ 3,786.09

Computer generated invoice. No signature is required.	Amount Payable Include GST : S\$ 3,786.09
---	--

All amounts are in Singapore Dollars.

Work was carried out subject to the Company's Terms and Conditions of Service.

No complaints will be entertained unless reported within seven (7) days of the date of this invoice.

For credit purchases, interest @1% per month will be debited on overdue amounts.





RECORDS MANAGEMENT CENTRE

**GENERAL INSURANCE ASSOCIATION OF SINGAPORE
RECORDS MANAGEMENT CENTRE**

6 Raffles Quay #18-00, Singapore 048580
Phone: +65 6224 0010 Fax: +65 6224 0030
Operating Hours: Monday to Friday 9am to 5pm
GST Registration No: M400017735

Third Party Insurer Enquiry

Our Ref No: GR-19-011270

Date of Request: 21/01/2019

Your Ref No:

Online Purchase

Performance Motors Limited
303 Alexandra Road
Sime Darby Performance Centre
Singapore 159941

Dear Sir/Madam,

Enquiry Date 21/01/2019
Enquiry By Melanie Setiawati
TP Vehicle No. GBE2506U
Accident Date 19/01/2019

Enquiry Result

TP Vehicle No.	Insurer	Period of Insurance	Insurer Tel. No.
GBE2506U	AIG Asia Pacific Insurance Pte. Ltd.	26/10/2018-25/10/2019	65-6419-3000

Thank You.

The images provided to you are taken from the original reports forwarded to the centre by the members of the General Insurance Association of Singapore and we take no responsibility for their accuracy or contents and shall be under no liability whatsoever for any loss or damage arising out of or in connection with the reports or their images.

This is a computer generated document and requires no signature.



RECORDS MANAGEMENT CENTRE

**GENERAL INSURANCE ASSOCIATION OF SINGAPORE
RECORDS MANAGEMENT CENTRE**

6 Raffles Quay #18-00, Singapore 048580
Phone: +65 6224 0010 Fax: +65 6224 0030
Operating Hours: Monday to Friday 9am to 5pm
GST Registration No: M400017735

TAX INVOICE

Our Ref No: GR-19-011270

Date of Request: 21/01/2019

Your Ref No:

Online Purchase

Performance Motors Limited
303 Alexandra Road
Sime Darby Performance Centre
Singapore 159941

Dear Sir/Madam,

Enquiry Date 21/01/2019
Enquiry By Melanie Setiawati
TP Vehicle No. GBE2506U
Accident Date 19/01/2019

DESCRIPTION	AMOUNT (S\$)
TP Insurer Enquiry	1.87
GST Amount	0.13
Total Amount Due (GST Inclusive)	2.00

Thank You.

This is a computer generated document and requires no signature.

For GIARMC Official use:

Date:

☒ [X] GIRO ☐ [] Cash ☐ [] Cheque

...CLAIM SUBFOLDER...(Pending for Survey Report)

Express

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	21 Jan 2019 Edit Reg		21 Mar 2019 00:00 Edit Adj Rpt	S\$3,538.40 Edit Estimates	S\$3,538.40 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured:	KSS SUNSHINE PTE LTD , Co. Reg. No.: 201207285K								
Main Claimant:	NIKKI ABDULLAH @WON TIEN LI (YUN TIANLI) , ID: S7735739D								
Vehicle Reg. No.:	SKH2999H	Date of Loss:	19/01/2019 15:00 - :59 [5 Months and 5 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 4034562705SG	Policy/Cover Note No.:	1700071386 (Comprehensive)						
Vehicle Reg. No. (Insured):	GBE2506U	Policy No. (Claimant):	C0086358						
		Excess:							
Repairer:	Performance Motors Limited (Alexandra) 303 Alexandra Road, Sime Darby Performance Centre, 159941 Alexandra - Tel: 63190172/63190174								
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Syed-Yusoff, Saliha] Saliha.Syed-Yusoff@aig.com								
Claimant's Insurer:	Liberty Insurance Pte Ltd (HQ) - Tel: (65) 6221 8611								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by CHEN TSUE YEE] ... [Final Rpt due 04/02/2019]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SKH2999H (4034562705SG)**
[GBE2506U]

TP





NIKKI ABDULLAH @WON TIEN LI (YUN TIANLI)

Jan 19 2019 3:00PM

[KSS SUNSHINE PTE LTD]

Performance Motors Limited

Upload Documents Upload Photos Compose New Letter Upload Video Upload Audio			View View in Browser	
Letters/Correspondences			1 per page <input type="checkbox"/>	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	(Draft)	Third Party Express Settlement - Payment Breakdown	1 Edit	
Assessment Reports			1 per page <input type="checkbox"/>	
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	25/01/19 10:06	Accident Statement <small>From: SC - Reg. No: GBE2506U, Claimant: KSS SUNSHINE PTE LTD</small>	1 Load HTM	
Photos/Images			3 per page <input type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	22/03/19 08:47	General View	1 Load JPG	<input checked="" type="checkbox"/>
2	22/03/19 08:47	General View	1 Load JPG	<input checked="" type="checkbox"/>
3	22/03/19 08:47	General View	1 Load JPG	<input checked="" type="checkbox"/>
4	22/03/19 08:47	General View	1 Load JPG	<input checked="" type="checkbox"/>
5	22/03/19 08:47	General View	1 Load JPG	<input checked="" type="checkbox"/>
6	22/03/19 08:47	General View	1 Load JPG	<input checked="" type="checkbox"/>
7	22/03/19 08:47	General View	1 Load JPG	<input checked="" type="checkbox"/>
8	22/03/19 08:47	General View	1 Load JPG	<input checked="" type="checkbox"/>
9	22/03/19 08:47	General View	1 Load JPG	<input checked="" type="checkbox"/>
10	22/03/19 08:47	General View	1 Load JPG	<input checked="" type="checkbox"/>
11	22/03/19 08:47	General View	1 Load JPG	<input checked="" type="checkbox"/>
12	22/03/19 08:47	General View	1 Load JPG	<input checked="" type="checkbox"/>
13	22/03/19 08:47	General View	1 Load JPG	<input checked="" type="checkbox"/>
14	22/03/19 08:47	General View	1 Load JPG	<input checked="" type="checkbox"/>
15	22/03/19 08:47	General View	1 Load JPG	<input checked="" type="checkbox"/>
16	22/03/19 08:47	General View	1 Load JPG	<input checked="" type="checkbox"/>
17	22/03/19 08:47	Odometer Reading	1 Load JPG	<input checked="" type="checkbox"/>
18	22/03/19 08:47	Chassis Number	1 Load JPG	<input checked="" type="checkbox"/>
19	12/04/19 08:24	Reinspection Photo	1 Load JPG	<input checked="" type="checkbox"/>
20	12/04/19 08:24	Reinspection Photo	1 Load JPG	<input checked="" type="checkbox"/>
21	12/04/19 08:24	Reinspection Photo	1 Load JPG	<input checked="" type="checkbox"/>
22	12/04/19 08:24	Reinspection Photo	1 Load JPG	<input checked="" type="checkbox"/>
23	12/04/19 08:24	Reinspection Photo	1 Load JPG	<input checked="" type="checkbox"/>
24	12/04/19 08:24	Reinspection Photo	1 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page <input type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	24/01/19 16:16	TP ESTIMATE	1 Load PDF	
2	24/01/19 16:16	TP GIA REPORT	1 Load PDF	
3	25/03/19 10:04	TP ESTIMATE- MARKED	1 Load PDF	
4	03/06/19 11:07	LETTER TO OI	1 Load PDF	

Letters/Correspondences			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
5	10/06/19 11:08	WORKSHOP INVOICE	 Load PDF	
6	10/06/19 11:08	AUTHORISATION TO ACT FORM	 Load PDF	
7	10/06/19 11:08	Release Voucher	 Load PDF	
8	10/06/19 11:08	GIA SEARCH	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

TEAM _____

Vehicle No:	GBE2506U (Insd veh)	Model:	BMW 218i 1.5 CONVERTIBLE (A)
	SKH2999H (TP veh)		
Date of Accident:	19/01/2019		

Global Sum Settlement	:	<input type="checkbox"/> Yes	<input checked="" type="checkbox"/> No
Repair Estimate	:	\$	4,381.01
Final Repair Cost	:	\$	3,786.09
Loss of Use	:	\$	180.00
Rental (if any)	:	\$	0.00
LTA / GIA Search Fee	:	\$	2.00
Others:	:	\$	0.00
	:	\$	
Final Settlement Sum	:	\$	3,968.09

3.00 days at \$60.00 per day
days

Is Third Party Workshop GIA Registered? ☒ YES ☐ NO (Kindly indicate below)

A) For Non GIA Registered Workshop: Agreed Liability _____(%)

B) For GIA Registered Workshop: BOLA Applicable: Yes/ ~~No~~ BOLA Scenario No: 15

BOLA Liability: _____100_____(%) Assessed Liability (*): _____(%)

** Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.*

Remarks _____

Payment Instruction: Payee's Breakdown				
1)	Performance Motors Limited	:	\$	3,968.09
2)		:	\$	
3)		:	\$	

10 Jun
2019

Date _____

https://singapore.merimen.com/claims/index.cfm?fusebox=SVCdoc&fuseaction=dsp_doclt... 10/6/2019

LKK Auto Consultants Pte Ltd (Co. Reg No: 199607196R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/AIG19001613/EFB3Q2

Date: 10/06/2019

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.	Policy No: 1700071386
Claimant Vehicle No : SKH2999H	Insured Vehicle No : GBE2506U
Date of Loss: 19/01/2019	Nature of Claim: TP Claim No: 4034562705SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKH2999H	Engine No:	30955368B38B15A
Make & Model:	BMW 218i, 1.5 CONVERTIBLE (A)	Chassis No:	WBA2M12000VE51206
Reg. Date:	14/08/2018 (Man. Year: 2018)	Odometer:	6747 km
Colour:	White		
Engine Capacity:	1499 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/45 R17	Rear Tyre Size:	225/45 R17
Front Left Side:	Bridgestone 7 mm	Rear Left Side:	Bridgestone 7 mm
Front Right Side:	Bridgestone 7 mm	Rear Right Side:	Bridgestone 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,604.40	1,604.40	0.00	0.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,490.00	1,934.00	556.00	22.33
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	4,094.40	3,538.40	556.00	13.58
+ GST 7.00/7.00% (S\$)	286.61	247.69	38.92	13.58
Nett Amount (S\$)	4,381.01	3,786.09	594.92	13.58
+ Loss of Use (3.0 x S\$60.00/day) (S\$)		180.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		3,968.09		

INSPECTION

Date of Assignment:	21/03/2019	
Date Inspected:	21/03/2019 Inspected At:	Performance Motors Limited (Alexandra) 303 Alexandra Road, Sime Darby Performance Centre Singapore 159941
Estimated Period of Repair:	3.0 days	

Adjuster: CHEN TSUE YEE**Manager:** Chong Poh Kin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SUNDRIES	Necessary	80.00 FS	*80.00 FS
2	1		*SET MOUNTS PDC SENSOR REAR	Necessary	58.60 FS	*58.60 FS
3	1		*REAR BUMPER PANEL PRIMED (BASIS)	Deformed	1,018.95 FS	*1,018.95 FS
4	1		*REAR LH LED LIGHT	Broken	393.80 FS	*393.80 FS
5	1		*(DG/SL) ADHESIVE SET K6	Necessary	53.05 FS	*53.05 FS
Total Parts (S\$)					1,604.40	1,604.40

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REPLACE REAR BUMPER ,TAIL LAMP LEFT AND ATTACHMENTS	New	1,275.00	850.00
2	PAINTING REAR BUMPER	New	1,038.00	934.00
3	TO CHECK ELECTRICAL WIRING SYSTEMS AND LIGHTINGS AT THE REAR SECTION FOR PROPER FUNCTION	New	177.00	150.00
Gross Labour Cost (S\$)			2,490.00	1,934.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >